

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 18, 2022

Progress Estir 8	Progress Estimate Number 8		201218-D03 E & C Bridge, LLC			Original Contract Amount Net Change Order Amount Current Contract Amount	\$565,088.00 \$93,476.76 \$658,564.76
Approval Date							By User
March 18, 2022		Ge	enerated and Approv	ved (and should be c	onsidered Draft) a	at the Project Office Level by	lafava1
March 18, 2022		Review	ved and Approved (a	and should be consid	lered Draft) at the	Resident Engineer Level by	browns1
March 21, 2022			Review	ved and Approved a	t the Central Offic	e Controllers Office Level by	ramses1
Original Comp	letion Date	Current Completion Date Actual Completion Date % of Current Contract Ar					t Complete
December	December 1, 2021 December 1, 2021 89.80%						

	Milestones		
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	January 6, 2021	January 6, 2021	
Letting Date	December 18, 2020	December 18, 2020	
Notice to Proceed Date	February 8, 2021	February 8, 2021	
Work Began Date			

Contract Total Pay For Estimate No. 8											
	This Estimate	Previous	To Date								
201218-D03											
Total Posted Items Pay	\$104,480.00	\$486,942.26	\$591,422.26								
Gross Item Adjustments	\$0.00	\$0.00	\$0.00								
Incentive	\$0.00	\$0.00	\$0.00								
Disincentive	\$0.00	\$0.00	\$0.00								
Liquidated Damage	\$0.00	\$0.00	\$0.00								
Other Contract Adjustments	\$0.00	\$0.00	\$0.00								
,		\$486,942.26	\$591,422.26								
Contract Total Payable This Estimate:	\$104.480.00										

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3229	0020	2035000	UNCLASSIFIED EXCAVATION	CUYD	\$75.000	229	\$17,175.00
	0030	2035500	EMBANKMENT IN PLACE	CUYD	\$45.000	111	\$4,995.00
	0040	2036000	COMPACTING EMBANKMENT	CUYD	\$12.000	170	\$2,040.00
	0220	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$1,500.000	1	\$1,500.00
	0340	7034216	TYPE H BARRIER	LF	\$60.000	312	\$18,720.00
	5003	4019905		SQYD	\$95.000	360	\$34,200.00
	5004	5031010A	BRIDGE APPROACH SLAB (MAJOR)	SQYD	\$235.000	110	\$25,850.00
Project J5S32	29 - Total						\$104,480.00
Overall - Total							\$104,480.00

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	,	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3229	0030	EMBANKMENT IN PLACE	Material			-111	\$45.00	(\$4,995.00)
	0030	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user lafava1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	111	\$45.00	\$4,995.00
	0040	COMPACTING	Material			-170	\$12.00	(\$2,040.00)

Revision 4/1/2020 Page 1 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 18, 2022

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3229		EMBANKMENT						
	0040	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user lafava1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	170	\$12.00	\$2,040.00
	0340	TYPE H BARRIER	Material			-312	\$60.00	(\$18,720.00)
	0340	TYPE H BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	312	\$60.00	\$18,720.00
	5004	BRIDGE APPROACH SLAB (MAJOR)	Material			-110	\$235.00	(\$25,850.00)
	5004	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user lafava1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	110	\$235.00	\$25,850.00
Total								\$0.00

Revision 4/1/2020 Page 2 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Informati	on			
Project Number										
J5S3229	FAS S401(98)	Bridge superstructure replacement	Н	COLE	over Bois Brule Creek 2.0	mile south of Rte. E				
Γotals by J	Job Numbe	rs								
J5S3229		d Item Pay Item Adjustme		tem Pay	This Estimate \$104,480.00 \$0.00 <b>\$104,480.00</b>	Previous \$486,942.26 \$0.00 \$486,942.26	To Date \$591,422.26 \$0.00 \$591,422.26			
	Liquid	tive centive lated Damages Contract Adjusi	tments	•	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 3 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

**Exceptions (Discrepancies) This Estimate Period** 

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 2035500, Project Item Line Number 0030, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 2036000, Project Item Line Number 0040, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 1036RSDFEC42M19 - Rein Steel EC No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 7034216, Project Item Line Number 0340, Material Set Safety Barrier, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	lafava1: Tests to be entered at later date	lafava1	Overridden

Revision 4/1/2020 Page 4 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-D03	J5S3229	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$15,000.00	\$15,000.00
		0001	0020	2035000	UNCLASSIFIED EXCAVATION	229.00	0.00	229.00	CUYD	229.00	\$75.00	\$17,175.00
		0001	0030	2035500	EMBANKMENT IN PLACE	111.00	0.00	111.00	CUYD	111.00	\$45.00	\$4,995.00
		0001	0040	2036000	COMPACTING EMBANKMENT	170.00	0.00	170.00	CUYD	170.00	\$12.00	\$2,040.00
		0001	0050	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	360.00	0.00	360.00	SQYD	360.00	\$9.00	\$3,240.00
		0001	0060	4019905	MISC.OPTIONAL PAVEMENT	360.00	-360.00	0.00	SQYD	0.00	\$87.00	\$0.00
		0001	0070	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	5.00	0.00	5.00	CUYD	0.00	\$125.00	\$0.00
		0001	0080	6096041	PLACING TYPE 1 ROCK DITCH LINER	5.00	0.00	5.00	CUYD	0.00	\$100.00	\$0.00
		0001	0090	6161005	CONSTRUCTION SIGNS	890.00	0.00	890.00	SQFT	778.00	\$5.50	\$4,279.00
		0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$140.00
		0001	0110	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	2.00	\$20.00	\$40.00
		0001	0120	6161025	CHANNELIZER (TRIM LINE)	25.00	0.00	25.00	EA	10.00	\$18.00	\$180.00
		0001	0130	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	10.00	0.00	10.00	EA	10.00	\$185.00	\$1,850.00
		0001	0140	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0150	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1.00	\$0.00
		0001	0160	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$42,000.00	\$0.00
		0001	0161	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.50	\$37,533.00	\$18,766.50
		0001	0170	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0180	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,182.00	0.00	1,182.00	LF	0.00	\$0.60	\$0.00
		0001	0190	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,218.00	0.00	2,218.00	LF	0.00	\$0.60	\$0.00
		0001	0200	6207001	PAVEMENT MARKING REMOVAL	495.00	0.00	495.00	LF	0.00	\$1.50	\$0.00
		0001	0210	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	16.00	0.00	16.00	SQYD	0.00	\$35.00	\$0.00
		0001	0220	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1,500.00	\$1,500.00
		0001	0230	8059901	MISC.Misc. (Seeding - Coole Season Mixture)	1.00	0.00	1.00	LS	0.00	\$7,500.00	\$0.00
		0001	0240	8061005	ROCK DITCH CHECK	95.00	0.00	95.00	LF	0.00	\$14.50	\$0.00
		0001	0250	8061010A	TYPE B BERM	316.00	0.00	316.00	LF	0.00	\$12.00	\$0.00
		0001	0260	8061016	SEDIMENT REMOVAL	19.00	0.00	19.00	CUYD	0.00	\$1.00	\$0.00
		0001	0270	8061050	TYPE C BERM	526.00	0.00	526.00	LF	170.00	\$15.00	\$2,550.00
		0010	0280	6061060	MGS GUARDRAIL	38.00	0.00	38.00	LF	0.00	\$22.50	\$0.00
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	4.00	0.00	4.00	EA	0.00	\$2,100.00	\$0.00
		0010	0300	6061078	(REGULAR/NO CURB)  MGS EMBEDDED ANCHOR SECTION (WITH RUBRAIL)	250.00	0.00	250.00	LF	0.00	\$30.14	\$0.00
		0010	0310	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$2,900.00	\$0.00
		0070	0320	2169901	MISC.Removal of Existing Superstructure	1.00	0.00	1.00	LS	1.00	\$41,000.00	\$41,000.00
		0070	0330	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	110.00	-110.00	0.00	SQYD	0.00	\$100.00	\$0.00
		0070	0340	7034216	TYPE H BARRIER	312.00	0.00	312.00	LF	312.00	\$60.00	\$18,720.00
		0070	0350	7039905	MISC.Slab on Steel (GFRP Rebar)	463.00	0.00	463.00	SQYD	463.00	\$255.00	\$118,065.00
		0070	0360	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	0.00	20.00	SQFT	20.00	\$200.00	\$4,000.00
			0370	7110500	TEMPORARY COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	1.00	\$7,342.00	\$7,342.00
		0070	0380	7121113	(WEATHERING STEEL) FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709,	60,880.00	0.00	60,880.00	LB	60,880.00	\$2.70	\$164,376.00
		0070	0390	7123610	GRADE 50W SLAB DRAIN	26.00	0.00	26.00	EA	26.00	\$250.00	\$6,500.00
		0070	0400	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0070	0410	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$1,500.00	\$1,200.00
		0070	0410	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$1,200.00	\$9,600.00
		0001	5001	6189901	MISC.Adjust Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$4,467.00	\$4,467.00

Revision 4/1/2020 Page 5 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-D03	J5S3229	0070	5002	7049901	MISC.Fiber Reinforced Polymer Wrap	0.00	1.00	1.00	LS	1.00	\$75,746.76	\$75,746.76
		0001	5003	4019905		0.00	360.00	360.00	SQYD	360.00	\$95.00	\$34,200.00
		0070	5004	5031010A	BRIDGE APPROACH SLAB (MAJOR)	0.00	110.00	110.00	SQYD	110.00	\$235.00	\$25,850.00
	Project J	5S3229 - To	tal Value	Posted to D	ate as of Report Generated Date							\$591,422.26
201218-D03 Overall - Total Value Posted to Date as of Report Generated Date										\$591,422.26		

Revision 4/1/2020 Page 6 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5S3229

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2035000	UNCLASSIFIED EXCAVATION	3/14/22	3/16/22	229.00	CUYD		167+42.74		171+90.94		
0030	2035500	EMBANKMENT IN PLACE	3/14/22	3/16/22	111.00	CUYD		167+42.74		171+90.94		
0040	2036000	COMPACTING EMBANKMENT	3/14/22	3/16/22	170.00	CUYD		167+42.74		171+90.94		
0220	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	3/14/22	3/16/22	1.00	LS	Bridge R02501					
0340	7034216	TYPE H BARRIER	3/14/22	3/16/22	312.00	LF	Bridge R02501	163+97.00		175+07.73		
5003	4019905	MISC.	3/15/22	3/18/22	360.00	SQYD		163+97				
5004	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	3/15/22	3/18/22	110.00	SQYD		163+97				

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Po
33229	0090	October 18, 2021	778	SPECIAL 36x60 15.00 DETOUR	Canon	0.011	Rt BB EB	1.00	15	Spoolal Olgil		100.01 10 FG
				ASSEMBLY  SPECIAL 36x60 15.00 DETOUR ASSEMBLY		6.754	Rt H NB	1.00	15			
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		0.071	Rt H SB	1.00	12.5			1
				SPECIAL 36x60 15.00 DETOUR		0.129	MO 17 SB	1.00	15			
				ASSEMBLY SPECIAL 36x60 15.00 DETOUR		0.17	Rt E EB	1.00	15			
				ASSEMBLY SPECIAL 36x60 15.00 DETOUR		0.196	Offramp 54-Mo 17 NB	1.00	15			
				ASSEMBLY  CONST-5 96x48 32.00 POINT OF		0.206	Rt H SB	1.00	32			
				PRESENCE SPECIAL 36x60 15.00 DETOUR		0.285	Rt BB EB	1.00	15			
				ASSEMBLY MO4-8a 24x18 3.00 END DETOUR		0.34	Rt H SB	1.00	3			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.348	Rt E EB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.829	MO 17 SB	1.00	15			
				WO20-2 48x48 16.00 DETOUR AHEAD		0.903	Rt H NB	1.00	16			
				SPECIAL 36x60 15.00 DETOUR		0.928	MO 17 SB	1.00	15			
				ASSEMBLY SPECIAL 36x60 15.00 DETOUR		1.009	Rt H NB	1.00	15			
				ASSEMBLY SPECIAL 36x60 15.00 DETOUR		1.154	Rt H NB	1.00	15			
				ASSEMBLY SPECIAL 36x60 15.00 DETOUR		1.202	Rt E EB	1.00	15			
				ASSEMBLY R11-3a 60x30 12.50 ROAD		1.213	Rt H NB	1.00	12.5			
				CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY								
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		1.726	Rt H SB	1.00	16			
				MO4-8a 24x18 3.00 END DETOUR		1.784	Rt H NB	1.00	3			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		1.841	Rt H SB	1.00	16			
				R11-2 48x30 10.00 ROAD CLOSED		1.958	Rt H SB	1.00	10			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		115.601	Hwy 54 WB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		115.803	Hwy 54 WB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		116.093	Hwy 54 WB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		117.401	Hwy 54 WB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		119.126	Hwy 54 WB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		122.353	Hwy 54 WB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		149.496	Hwy 54 EB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		151.618	Hwy 54 EB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		154.447	Hwy 54 EB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		155.705	Hwy 54 EB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		155.851	Hwy 54 EB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		156.01	Hwy 54 EB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR		156.213	Hwy 54 EB	1.00	15			
				ASSEMBLY  SPECIAL 36x60 15.00 DETOUR ASSEMBLY		186.377	MO 17 NB	1.00	15			
				SPECIAL 36x60 15.00 DETOUR		186.61	MO 17 NB	1.00	15			
				ASSEMBLY  SPECIAL 36x60 15.00 DETOUR		186.72	MO 17 NB	1.00	15			
				ASSEMBLY SPECIAL 36x60 15.00 DETOUR		4.277	Rt BB WB	1.00	15			
				ASSEMBLY SPECIAL 36x60 15.00 DETOUR		4.309	Rt BB WB	1.00	15			
				ASSEMBLY WO20-3 48x48 16.00 ROAD		4.393	Rt H NB	1.00	16			
				CLOSED AHEAD  SPECIAL 36x60 15.00 DETOUR		4.441	Rt BB WB	1.00	15			
				ASSEMBLY								
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		4.448	Rt BB WB	1.00	15			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		4.516	Rt H NB	1.00	16			

Revision 4/1/2020 Page 7 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
5S3229	0090	October 18, 2021	778	SPECIAL 36x60 15.00 DETOUR ASSEMBLY		4.567	Rt E WB	1.00	15			15
				R11-2 48x30 10.00 ROAD CLOSED		4.646	Rt H NB	1.00	10			10
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		4.682	Rt E WB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.032	Rt H SB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.351	Rt H SB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.599	Rt E WB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.603	Rt H SB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		6.476	Rt H NB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		6.64	Rt H NB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.02	Offramp 54-Mo 17 NB	1.00	15			15
	0090 - Total											778

Revision 4/1/2020 Page 8 of 12



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3229	0030	EMBANKMENT IN PLACE	Material		8	Mar 18, 2022	SYSTEM	\$4,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user lafava1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Mar 18, 2022	SYSTEM	(\$4,995.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0030 -	Total						\$0.00	
	0040	COMPACTING EMBANKMENT	Material		8	Mar 18, 2022	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lafava1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Mar 18, 2022	SYSTEM	(\$2,040.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0040 -	Total						\$0.00	
	0090	CONSTRUCTION SIGNS	Material		4	Nov 2, 2021	SYSTEM	\$4,279.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$4,279.00)	
					5	Nov 16, 2021	SYSTEM	\$4,279.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$4,279.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0090 -	Total						\$0.00	
	0100	ADVANCED WARNING RAIL SYSTEM	Material		3	Oct 18, 2021	SYSTEM	\$140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Oct 18, 2021	SYSTEM	(\$140.00)	
					4	Nov 2, 2021	SYSTEM	\$140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$140.00)	
					5	Nov 16, 2021	SYSTEM	\$140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$140.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0100 -	Total						\$0.00	
	0110	FLAG ASSEMBLY	Material		3	Oct 18, 2021	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Oct 18, 2021	SYSTEM	(\$40.00)	
					4	Nov 2, 2021	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$40.00)	
					5	Nov 16, 2021	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$40.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3229	0110 -	Total						\$0.00	
	0120	CHANNELIZER (TRIM LINE)	Material		3	Oct 18, 2021	SYSTEM	\$144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Oct 18, 2021	SYSTEM	(\$144.00)	
					4	Nov 2, 2021	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$180.00)	
					5	Nov 16, 2021	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$180.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0120 -	Total						\$0.00	
	0130	TYPE III MOVEABLE BARRICADE WITH LIGHTS	Material		3	Oct 18, 2021	SYSTEM	\$1,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Oct 18, 2021	SYSTEM	(\$1,850.00)	
					4	Nov 2, 2021	SYSTEM	\$1,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$1,850.00)	
					5	Nov 16, 2021	SYSTEM	\$1,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$1,850.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0130 -	Total						\$0.00	
	0140	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		3	Oct 18, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Oct 18, 2021	SYSTEM	(\$5,600.00)	
					4	Nov 2, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$5,600.00)	
					5	Nov 16, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$5,600.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0140 -	0140 - Total						\$0.00	
	0270	TYPE C BERM	Material		4	Nov 2, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$2,550.00)	
					5	Nov 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$2,550.00)	



# Line Item Adjustments by Estimate

oject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Jec.	LIIIC	Description	Type	Adjustment Type		Date	By	Amount	Iveillains
3229	0270	TYPE C BERM	Material		6	Dec 1, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Dec 1, 2021	SYSTEM	(\$2,550.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0270 -	Total						\$0.00	
	0340	TYPE H BARRIER	Material		8	Mar 18, 2022	SYSTEM	\$18,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Mar 18, 2022	SYSTEM	(\$18,720.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0340 -	Total		<u></u>				\$0.00	
						D 4	OVOTEN		T: "
	0350	MISC. CONCRETE CONSTRUCTION	Material		6	Dec 1, 2021	SYSTEM	\$70,839.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Dec 1, 2021	SYSTEM	(\$70,839.00)	
					7	Mar 3, 2022	SYSTEM	\$118,065.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Mar 3, 2022	SYSTEM	(\$118,065.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0350 -	Total						\$0.00	
	0370	TEMPORARY COATING - CONCRETE BENTS AND P	Material		4	Nov 2, 2021	SYSTEM	\$7,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$7,342.00)	
					5	Nov 16, 2021	SYSTEM	\$7,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$7,342.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0370 -	Total						\$0.00	
	0380	FAB. STRUCT.LOW ALLOY			4	Nov 2, 2021	SYSTEM	(\$133,936.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		STEEL(IBM)A709,50W		- Total				(\$133,936.00)	
			Construction		Total			(\$133,936.00)	
			Construction Stockpile	Otookpiic	2	Jun 1, 2021	SYSTEM	\$133,936.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$133,936.00	
			Construction	Stockpile S	TMI - <u>Total</u>			\$133,936.00	
	0380 -	Total						\$0.00	
	0410	PLAIN NEOPRENE BEARING PAD	Construction Stockpile		4	Nov 2, 2021	SYSTEM	(\$560.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$560.00)	
			Construction	Stockpile - 1	Γotal			(\$560.00)	
			Construction Stockpile		2	Jun 1, 2021	SYSTEM	\$560.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$560.00	
			Construction Stockpile STMI - Total					\$560.00	
	0410 -	Total			1018			\$0.00	
			0 1 "				0)/0==:		
	0420	LAMINATED	Construction		4	Nov 2,	SYSTEM	(\$5,380.00)	Payment Estimate Item Adjustment generated Stockpile Transaction

Mar 22, 2022



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3229	0420	NEOPRENE BEARING PAD ASSEMBLY	Stockpile			2021			
				- Total				(\$5,380.00)	
			Construction	Stockpile - 1	Total			(\$5,380.00)	
			Construction Stockpile		2	Jun 1, 2021	SYSTEM	\$5,380.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$5,380.00	
			Construction	Stockpile S	ГМI - Total			\$5,380.00	
	0420 - Total								
	5004	BRIDGE APPROACH SLAB (MAJOR ROAD)			8	Mar 18, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lafava1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Mar 18, 2022	SYSTEM	(\$25,850.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	5004 - Total							\$0.00	
J5S3229 -	J5S3229 - Total								
Overall - Total								\$0.00	