

Pay Estimate Created Date: December 2, 2021

Progress Estimate No 11			201218-D04 Capital Paving & Cons	truction	Pay Period Start Nove , LLC Pay Period End Dece	mber 1, 2021 Net C		nt (\$32,484.70)		
Approval Date								By User		
December 2, 2021	ecember 2, 2021 Generated and Approved (and should be considered Draft) at the Project Office									
December 3, 2021			Reviewed and Ap	eviewed and Approved (and should be considered Draft) at the Resident Engineer Level by						
December 6, 2021				Revie	wed and Approved at the Ce	ntral Office Controlle	rs Office Level by	ramses1		
Original Completio	n Date	Current C	npletion Date Actual Completion Date % of Current Co				nt Contract Amount	Contract Amount Complete		
November 1, 20	21	Novem	ber 1, 2021				94.19%			
	Contract	Informational Da	tes		Milestones					
Date Description	Original	Completion Date	Current Completion	n Date	No Milestones Exist for Cor	ntract				
Acceptance Date										
Awarded Date	January 6	, 2021	January 6, 2021							
Letting Date	Decembe	r 18, 2020	December 18, 2020							
Notice to Proceed Date	March 8,	2021	March 8, 2021							
Work Began Date										

Contract Total Pay For Estimate No. 11

\$74,875.56		
	<mark>\$5,373,366.82</mark>	\$5,448,242.38
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
(\$8,277.95)	\$131,418.64	\$123,140.69
\$83,153.51	\$5,241,948.18	\$5,325,101.69
This Estimate	Previous	To Date
	This Estimate	This Estimate Previous

Contract Total Payable This Estimate: Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3319	0250	2142000	FURNISHING ROCK FILL	CUYD	\$40.000	-1.4	(\$56.00)
	0260	2143000	PLACING ROCK FILL	CUYD	\$25.000	-1.4	(\$35.00
	0270	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$6.700	-0.2	(\$1.34
	0310	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	TONS	\$46.510	124.3	\$5,781.19
	0510	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.090	248,450	\$22,360.50
	0520	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	225,491	\$22,549.10
	0540	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$6.060	1,511	\$9,156.66
	0550	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$4.570	5,120	\$23,398.40
Project J5S	3319 - Tota	al					\$83,153.51
Overall - To	otal						\$83,153.51

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3319	0270	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)			Reference Item Price Adjustment Index Adjustment Type applied is FUEL	-0.2	\$0.15	(\$0.03)
	0300	5 3/4 INCHES, BITUMINOUS PAVEMENT				-13.3	\$13.86	(\$184.34)
	0300	5 3/4 INCHES, BITUMINOUS PAVEMENT			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user webers1	13.3	\$13.86	\$184.34

Pay Estimate Created Date: December 2, 2021

	order Amoun	let Change C	Pay Period Start November 16, 2021 C tion, LLC Pay Period End December 1, 2021 N C		201218-I ctor Capital P		Estimate Number 11	ogress	
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	em Description	ine Item Des Io.		
			overridding Payment Estimate Exception 1 on the current Payment Estimate.					319	
\$37.27	\$2.69	13.86	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		Price	/INOUS PAVEMENT RE PG64-22 (BASE)		0	
\$296.94	\$2.69	110.44	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		Price	/INOUS PAVEMENT RE PG64-22 (BASE)		0	
(\$1,184,266.92	\$46.51	-25,462.63			Material	/INOUS PAVEMENT RE PG64-22 (BASE)		0	
\$1,184,266.92	\$46.51	25,462.63	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) Material Material Material Material PG64-22 (BASE) Material Material Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
\$41.23			AC Adjustment for 13.86 Tons of BB21-27 at 2.8% VAC placed on 8/13/21	Asphalt Cement Price Adjustment	Other Item Adjustment	/INOUS PAVEMENT RE PG64-22 (BASE)		0	
\$328.56			AC Adjustment for 110.44 Tons of BB21-27 at 2.8% VAC placed on 8/26/21	Asphalt Cement Price Adjustment	Other Item Adjustment	/INOUS PAVEMENT RE PG64-22 (BASE)		0	
(\$43,464.10	\$2.05	-21,202			Material	TACK COAT	330	0	
\$43,464.10	\$2.05	21,202	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		Material	TACK COAT	330	0	
(\$2,200.00	\$25.00	-88			Material	OVEN WIRE FENCE	350 WOVEN	0	
\$2,200.00	\$25.00	88	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		Material	OVEN WIRE FENCE	350 WOVEN	0	
(\$22,360.50	\$0.09	-248,450			Material	WHITE STANDARD BORNE PAVEMENT (ING PAINT, TYPE P BEADS	WATERBORN	0	
\$22,360.50	\$0.09	248,450	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.		Material	WHITE STANDARD BORNE PAVEMENT (ING PAINT, TYPE P BEADS	WATERBORN	0	
(\$4,472.10			20% Withheld until Retro-reflectivity results	Retroreflectivity Adjustment		WHITE STANDARD BORNE PAVEMENT (ING PAINT, TYPE P BEADS	WATERBORN	0	
(\$22,549.10	\$0.10	-225,491			Material	ELLOW STANDARD BORNE PAVEMENT (ING PAINT, TYPE P BEADS	WATERBORN	0	
\$22,549.10	\$0.10	225,491	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		Material	ELLOW STANDARD BORNE PAVEMENT (ING PAINT, TYPE P BEADS	WATERBORN	0	
(\$4,509.82			20% Withheld until Retro-reflectivity results	Retroreflectivity Adjustment		ELLOW STANDARD BORNE PAVEMENT (ING PAINT, TYPE P BEADS	WATERBORN	0	
(\$922.50	\$1.50	-615			Material	SILT FENCE	320	0	
\$922.50	\$1.50	615	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user webers1		Material	SILT FENCE	320	0	

Pay Estimate Created Date: December 2, 2021

Progre	ss Esti 1	mate Number 1	Contract ID Prime Contra	201218-D ctor Capital Pa		Pay Period Start November 16, 2021 (tion, LLC Pay Period End December 1, 2021	Net Change C	Order Amount	
Project Number	Line No.	Item De	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3319						overridding Payment Estimate Exception 17 on the current Payment Estimate.			
J5S3388	0860		TACK COAT	Material			-3,934	\$2.05	(\$8,064.70
	0860		TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	3,934	\$2.05	\$8,064.70
	0940	WATERBORN	TE STANDARD NE PAVEMENT PAINT, TYPE P BEADS	Material			-45,471	\$0.09	(\$4,092.39)
	0940	WATERBORN	TE STANDARD NE PAVEMENT PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	45,471	\$0.09	\$4,092.39
	0950	WATERBORN	W STANDARD NE PAVEMENT PAINT, TYPE P BEADS	Material			-42,278	\$0.10	(\$4,227.80)
	0950	WATERBORN	W STANDARD NE PAVEMENT PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	42,278	\$0.10	\$4,227.80
Total									(\$8,277.95



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J5S3232	FAS S401(47)	Resurface	B/M/ 124	BOONE	from west of Rte. 63 to Rte. DD and Rte. B and Rte. 124 in Hallsville
J5S3319	FAS S402(6)	Resurface and shoulder improvements	J/O/ UU	BOONE	from Rte. 124 to Rte. O, Rte. J to the end of state maintenance, and Rte. O to I-70 eastbound ramp
J5S3388	FAS- S402(060)	Pavement improvements	A	BOONE	from Rte. 63 to the end of state maintenance in Hartsburg

Totals by Job Numbers

J5S3232		This Estimate	Previous	To Date
	Posted Item Pay	\$0.00	\$300,616.41	\$300,616.41
	Gross Item Adjustments	\$0.00	\$15,977.07	\$15,977.07
	Gross Item Pay	\$0.00	\$316.593.48	\$316,593.48
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
J5S3319		This Estimate	Previous	To Date
	Posted Item Pay	\$83,153.51	\$4,707,546.74	\$4,790,700.25
	Gross Item Adjustments	(\$8,277.95)	\$92,261.20	\$83,983.25
	Gross Item Pay	\$74,875.56	\$4,799,807.94	\$4,874,683.50
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liguidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		·		
J5S3388		This Estimate	Previous	To Date
	Posted Item Pay	\$0.00	\$233,785.03	\$233,785.03
	Gross Item Adjustments	\$0.00	\$23,180.37	\$23,180.37
	Gross Item Pay	\$0.00	\$256,965.40	\$256,965.40
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	e ano e e a a a a a a a a a a a a a a a a a	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4010105, Project Item Line Number 0300, Material Set 401010596, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4010105, Project Item Line Number 0300, Material Set 401010596, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4013000, Project Item Line Number 0310, Material Set 401300096, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4071005, Project Item Line Number 0330, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4071005, Project Item Line Number 0330, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 4071005, Project Item Line Number 0860, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 4071005, Project Item Line Number 0860, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6072010, Project Item Line Number 0350, Material Set 607201096, Material 1043FMWWFB - Woven Wire Fence Fabric, Acceptance Action Generic 1043FMWWFB is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6206000C, Project Item Line Number 0510, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6206000C, Project Item Line Number 0510, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 6206000C, Project Item Line Number 0940, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 6206000C, Project Item Line Number 0940, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6206001C, Project Item Line Number 0520, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6206001C, Project Item Line Number 0520, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 6206001C, Project Item Line Number 0950, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 6206001C, Project Item Line Number 0950, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 8061019, Project Item Line Number 0820, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient.	Working with Contractor and Materials to resolve	webers1	Overridden
Estimate Exception Type: Item Overrun: Contract 201218-D04, Contract Project J5S3319, Project Item Line Number 0320, Contract Line Item Number 0320, Item 4020520, Minor Item.	Working on Change Order	webers1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201218-D04, Contract Project J5S3388, Project Item Line Number 0840, Contract Line Item Number 0840, Item 3107002, Minor Item.	Working on Change Order	webers1	Acknowledged



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note. Posted Q	uanuues	anu valu	es ale L	ased on R	eport Generated date and can differ from the posted amo	ount at the t	ime the Est	imate was (Generate	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-D04	J5S3232	0001	0010	2152000A	SHAPING SLOPES, CLASS II	206.00	0.00	206.00	100F	206.00	\$67.73	\$13,952.38
		0001	0020	3107002	GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)	16.00	4.00	20.00	TONS	20.00	\$15.94	\$318.80
		0001	0030	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	2,861.30	238.20	3,099.50	TONS	3,099.50	\$57.58	\$178,469.21
		0001	0040	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	146.10	18.10	164.20	TONS	164.20	\$37.95	\$6,231.39
		0001	0050	4079912	MISC.Low-Tracking or Non Tracking Tack Coat	3,116.00	-16.00	3,100.00	GAL	3,100.00	\$2.35	\$7,285.00
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
		0001	0070	6161005	CONSTRUCTION SIGNS	1,767.00	0.00	1,767.00	SQFT	658.00	\$8.00	\$5,264.00
		0001	0080	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$25.00	\$0.00
		0001	0090	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$25.00	\$0.00
		0001	0100	6161024	CHANNELIZER (TRIM LINE) WITH LIGHT	421.00	0.00	421.00	EA	0.00	\$20.00	\$0.00
		0001	0110	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$2,000.00	\$8,000.00
		0001	0120	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$8,039.92	\$8,039.92
		0001	0130	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	878.00	0.00	878.00	LF	878.00	\$3.75	\$3,292.50
		0001	0140	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE	124.00	0.00	124.00	LF	124.00	\$7.50	\$930.00
		0001	0150	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	1.00	0.00	1.00	EA	1.00	\$350.00	\$350.00
		0001	0160	6200036	LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN	20.00	0.00	20.00	EA	10.00	\$75.00	\$750.00
		0001	0170	6206000C		4,713.00	0.00	4,713.00	LF	4,713.00	\$0.55	\$2,592.15
		0001	0180	6206001C	PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	12,659.00	0.00	12,659.00	LF	12,659.00	\$0.25	\$3,164.75
		0001	0190	6221001	MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	29,838.00	463.00	30,301.00	SQYD	30,301.00	\$1.74	\$52,723.74
		0001	5001	1094000	SURFACING (3 IN. THICK OR LESS) FORCE ACCOUNT	0.00	9,252.57	9,252.57	EA	9,252.57	\$1.00	\$9,252.57
	Project J5S3232 - Total Value Posted				late as of Report Congrated Date							\$300,616.41
	J5S3319	0001	0200	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$115,000.00	\$115,000.00
		0001	0210	2063000	CLASS 3 EXCAVATION	865.00	0.00	865.00	CUYD	865.00	\$55.00	\$47,575.00
		0001	0220	2063300	CLASS 4 EXCAVATION		0.00	20.00	CUYD	20.00	\$10.00	\$200.00
						20.00						
		0001	0230	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0001	0230 0240	2065500 2079909	TEMPORARY SHORING MISC.MODIFIED LINEAR GRADING CLASS 2		0.00	1.00 2,395.90	LS STA	0.00 2,395.90	\$1.00 \$465.09	\$0.00 \$1,114,309.13
						1.00						
		0001	0240	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	1.00	0.00	2,395.90	STA	2,395.90	\$465.09	\$1,114,309.13
		0001 0001	0240 0250	2079909 2142000	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL	1.00 2,395.90 2,828.00	0.00	2,395.90 2,828.00	STA CUYD	2,395.90 2,200.00	\$465.09 \$40.00	\$1,114,309.13 \$88,000.00
		0001 0001 0001	0240 0250 0260	2079909 2142000 2143000 3040143	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL	1.00 2,395.90 2,828.00 2,828.00	0.00	2,395.90 2,828.00 2,828.00	STA CUYD CUYD SQYD	2,395.90 2,200.00 2,200.00	\$465.09 \$40.00 \$25.00	\$1,114,309.13 \$88,000.00 \$55,000.00
		0001 0001 0001 0001	0240 0250 0260 0270	2079909 2142000 2143000 3040143	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	1.00 2,395.90 2,828.00 2,828.00 29,287.00	0.00 0.00 0.00 0.00	2,395.90 2,828.00 2,828.00 29,287.00	STA CUYD CUYD SQYD	2,395.90 2,200.00 2,200.00 476.00	\$465.09 \$40.00 \$25.00 \$6.70	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20
		0001 0001 0001 0001 0001	0240 0250 0260 0270 0280	2079909 2142000 2143000 3040143 3049905	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)	1.00 2,395.90 2,828.00 2,828.00 29,287.00 214.00	0.00 0.00 0.00 0.00 0.00	2,395.90 2,828.00 2,828.00 29,287.00 214.00	STA CUYD CUYD SQYD SQYD	2,395.90 2,200.00 2,200.00 476.00 0.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00
		0001 0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290	2079909 2142000 2143000 3040143 3049905 3105002	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B)	1.00 2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00	0.00 0.00 0.00 0.00 0.00	2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00	STA CUYD CUYD SQYD SQYD TONS	2,395.90 2,200.00 2,200.00 476.00 0.00 0.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290 0300	2079909 2142000 2143000 3040143 3049905 3105002 4010105	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT	1.00 2,395.90 2,828.00 29,287.00 214.00 210.00 31.10	0.00 0.00 0.00 0.00 0.00 0.00	2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00 31.10	STA CUYD CUYD SQYD SQYD TONS SQYD	2,395.90 2,200.00 2,200.00 476.00 0.00 0.00 13.30	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00 \$0.00 \$184.34
		0001 0001 0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290 0300 0310	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	1.00 2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00 31.10 29,342.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00	2,395.90 2,828.00 29,287.00 214.00 210.00 31.10 29,342.00	STA CUYD CUYD SQYD SQYD TONS SQYD TONS	2,395.90 2,200.00 2,200.00 476.00 0.00 0.00 13.30 25,462.63	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00 \$0.00 \$184.34 \$1,184,266.92
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000 4020520	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	1.00 2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395,90 2,828,00 2,828,00 29,287,00 214,00 210,00 31,10 29,342,00 21,876,40	STA CUYD CUYD SQYD SQYD TONS SQYD TONS	2,395.90 2,200.00 2,200.00 476.00 0.00 13.30 25,462.63 25,917.72	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00 \$0.00 \$184.34 \$1,184,266.92 \$1,289,924.92
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000 4020520 4071005	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT.	1.00 2,395,90 2,828,00 2,828,00 2,828,00 214,00 210,00 31,10 29,342,00 21,876,40 21,876,40 23,405,00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00	STA CUYD CUYD SQYD SQYD TONS SQYD TONS TONS GAL	2,395.90 2,200.00 476.00 0.00 13.30 25,462.63 25,917.72 21,202.00	\$465.09 \$40.00 \$25.00 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00 \$0.00 \$184.34 \$1,184,266.92 \$1,289,924.92 \$43,464.10
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320 0330 0330	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000 4020520 4071005 5021305	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. GOINTS)	1.00 2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395,90 2,828,00 2,828,00 29,287,00 214,00 210,00 31,10 29,342,00 21,876,40 23,405,00 41,80	STA CUYD CUYD SQYD SQYD TONS SQYD TONS GAL SQYD	2,395.90 2,200.00 476.00 0.00 13.30 25,462.63 25,917.72 21,202.00 41.80	\$465.09 \$40.00 \$25.00 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00 \$0.00 \$184.34 \$1,184,266.92 \$1,289,924.92 \$1,289,924.92 \$43,464.10 \$1,639.81
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0310 0320 0330 0340	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000 4020520 4071005 5021305 6072010	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS) WOVEN WIRE FENCE	1.00 2,395.90 2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 21,876.40 23,405.00 41.80 184.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395,90 2,828,00 2,828,00 29,287,00 214,00 210,00 31,10 29,342,00 21,876,40 21,876,40 23,405,00 41,80 184,00	STA CUYD SQYD SQYD TONS SQYD TONS TONS GAL SQYD LF	2,395.90 2,200.00 476.00 0.00 13.30 25,462.63 25,917.72 21,202.00 41.80 88.00	\$465.09 \$40.00 \$25.00 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00 \$100 \$184.34 \$1,184,266.92 \$1,289,924.92 \$43,464.10 \$1,639.81 \$1,639.81 \$2,200.00
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0270 0270 0280 0300 0300 0310 0320 0330 0340 0350 0360	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000 4020520 4071005 5021305 6072010	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. OVVEN WIRE FENCE ROCK LINING	1.00 2,395,90 2,828,00 29,287,00 214,00 210,00 31,10 29,342,00 21,876,40 23,405,00 41,80 184,00 73,00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395,90 2,828,00 2,828,00 29,287,00 214,00 210,00 31,10 29,342,00 21,876,40 23,405,00 41,80 184,00 73,00	STA CUYD SQYD SQYD TONS SQYD TONS GAL SQYD LF CUYD	2,395.90 2,200.00 476.00 0.00 13.30 25,462.63 25,917.72 21,202.00 41.80 88.00 73.00	\$465.09 \$40.00 \$25.00 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$39.23 \$25.00	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00 \$100 \$184.34 \$1,184,266.92 \$1,289,924.92 \$43,464.10 \$1,639.81 \$2,200.00 \$3,650.00
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0300 0300 0330 0330 0330 0340 0360	2079909 2142000 2143000 3040143 304905 3105002 4010105 4013000 4020520 4071005 5021305 6072010 6097000 6113010	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS) WOVEN WIRE FENCE ROCK LINING FURNISHING TYPE 1 ROCK BLANKET	1.00 2,395.90 2,828.00 2,828.00 2,828.00 2,828.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00 121.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395,90 2,828,00 2,828,00 29,287,00 214,00 210,00 31,10 29,342,00 21,876,40 23,405,00 41,80 184,00 73,00 121,00	STA CUYD SQYD SQYD TONS SQYD TONS GAL SQYD LF CUYD	2,395.90 2,200.00 476.00 0.00 13.30 25,462.63 25,917.72 21,202.00 41.80 88.00 73.00	\$465.09 \$40.00 \$25.00 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00 \$50.00	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00 \$184.34 \$1,184,266.92 \$1,289,924.92 \$43,464.10 \$1,639.81 \$1,639.81 \$2,200.00 \$3,650.00
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320 0330 0330 0360 0350	2079909 2142000 2143000 3040143 304905 3105002 4010105 4013000 4020520 4071005 5021305 6072010 6097000 6113010	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. OVOVEN WIRE FENCE ROCK LINING FURNISHING TYPE 1 ROCK BLANKET PLACING TYPE 1 ROCK BLANKET TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS	1.00 2,395,90 2,828,00 2,828,00 2,828,00 214,00 2114,00 31,10 29,342,00 21,876,40 23,405,00 21,876,40 23,405,00 184,00 73,00 121,00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395,90 2,828,00 2,828,00 214,00 210,00 31,10 29,342,00 21,876,40 23,405,00 41,80 184,00 73,00 121,00	STA CUYD SQYD SQYD TONS SQYD TONS GAL SQYD CUYD CUYD	2,395.90 2,200.00 476.00 0.00 13.30 25,462.63 25,917.72 21,202.00 41.80 88.00 73.00 88.00	\$465.09 \$40.00 \$25.00 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00 \$50.00 \$25.00	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00 \$1,484.34 \$1,184,266.92 \$1,289,924.92 \$43,464.10 \$1,639.81 \$2,200.00 \$2,200.00
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0300 0300 0330 0330 0340 0350 0350 0360 0360 0360 0360	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4010105 4020520 4071005 5021305 6072010 6097000 6113010 6113030	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. OVINTS) WOVEN WIRE FENCE ROCK LINING FURNISHING TYPE 1 ROCK BLANKET PLACING TYPE 1 ROCK BLANKET PLACING TYPE 1 ROCK BLANKET	1.00 2,395.90 2,828.00 2,828.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00 121.00 121.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395,90 2,828,00 2,828,00 29,287,00 214,00 210,00 31,10 29,342,00 21,876,40 23,405,00 21,876,40 23,405,00 11,80 184,00 73,00 121,00 121,00 2,00	STA CUYD SQYD SQYD TONS SQYD TONS GAL SQYD CUYD CUYD CUYD EA	2,395.90 2,200.00 476.00 0.00 13.30 25,462.63 25,917.72 21,202.00 41.80 88.00 73.00 88.00 88.00 88.00	\$465.09 \$40.00 \$25.00 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00 \$50.00 \$25.00 \$25.00 \$25.00	\$1,114,309.13 \$88,000.00 \$55,000.00 \$3,189.20 \$0.00 \$184.34 \$1,184,266.92 \$1,289,924.92 \$43,464.10 \$1,639.81 \$2,200.00 \$3,650.00 \$2,200.00 \$2,200.00



Revision 4/1/2020

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Page 7 of 24

Total Paid / All Items / All Estimates (Including this Estimate)

I of all of All refins / All Estimates (including uns Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the bosted amount at the time the Estimate was Generated

	Project	Category	Line	ltem	teport Generated date and can differ from the posted am Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTE			
RACT	No.	Category	No.	Code	Description	Quantity	Change Order	Current Quantity	Unit	Posted Approved Qty	Unit Price	To Date (See repo generated date)			
4 J	J5S3319	0001	0430	6161010	RELOCATED SIGNS	384.00	0.00	384.00	SQFT	384.00	\$7.00	\$2,688.0			
		0001	0440	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$20.00	\$0.0			
		0001	0450	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	6.00	0.00	6.00	EA	4.00	\$155.00	\$620.0			
		0001	0460	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.0			
		0001	0470	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.			
		0001	0480	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$330,616.16	\$330,616			
		0001	0490	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	6.00	0.00	6.00	EA	0.00	\$600.00	\$0			
		0001	0500	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	42.00	0.00	42.00	LF	0.00	\$35.00	\$0.			
		0001	0510	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	248,450.00	0.00	248,450.00	LF	248,450.00	\$0.09	\$22,360			
		0001	0520	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	225,491.00	0.00	225,491.00	LF	225,491.00	\$0.10	\$22,549			
		0001	0530	6208064A	TEMPORARY RAISED PAVEMENT MARKER	125.00	0.00	125.00	EA	0.00	\$0.00	\$0			
		0001	0540	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,511.00	0.00	1,511.00	SQYD	1,511.00	\$6.06	\$9,156			
		0001	0550	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	5,120.00	0.00	5,120.00	SQYD	5,120.00	\$4.57	\$23,398.4			
		0001	0560	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,639.90	0.00	2,639.90	STA	1,821.10	\$10.00	\$18,211			
		0001	0570	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	1,200.50	0.00	1,200.50	STA	1,200.50	\$10.00	\$12,005			
		0001	0580	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$8,945.72	\$0			
		0001	0590	7034041	CLASS B-1 CONCRETE (CULVERTS)	15.00	0.00	15.00	CUYD	15.00	\$1,000.00	\$15,00			
		0001	0600	7061030	REINFORCING STEEL (CULVERTS)	3,700.00	0.00	3,700.00	LB	3,700.00	\$1.50	\$5,55			
		0001	0610	7250315A	15 IN. PIPE GROUP B	52.00	0.00	52.00	LF	52.00	\$50.00	\$2,60			
		0001	0620	7250318A	18 IN. PIPE GROUP B	256.00	0.00	256.00	LF	256.00	\$70.00	\$17,92			
	0001 0001 0001 0001	0001		0001 0630 7250324A 0001 0640 7250330A 0001 0650 7250336A	24 IN. PIPE GROUP B	42.00	0.00	42.00	LF	42.00	\$80.00	\$3,36			
			0001 0640 72			30 IN. PIPE GROUP B	42.00	0.00	42.00	LF	42.00	\$100.00	\$4,20		
					0001 0660 72		0650	7250336A	36 IN. PIPE GROUP B	88.00	0.00	88.00	LF	88.00	\$110.00
							1 0660	7250342A	42 IN. PIPE GROUP B	108.00	0.00	108.00	LF	108.00	\$130.00
		0001	0670	7250348A	48 IN. PIPE GROUP B	92.00	0.00	92.00	LF	92.00	\$150.00	\$13,80			
		0001	0680	7250415	15 IN. PIPE GROUP C	180.00	0.00	180.00	LF	180.00	\$40.00	\$7,20			
		0001	0690	7320015A	15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$150.00	\$30			
		0001	0700	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	8.00	0.00	8.00	EA	8.00	\$200.00	\$1,60			
		0001	0710	7320024A	24 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$275.00	\$55			
		0001	0720	7320030A	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,00			
		0001	0730	7320036A		4.00	0.00	4.00	EA	4.00	\$600.00	\$2,40			
		0001	0740	7320042A	42 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$850.00	\$3,40			
		0001	0750	7320048A		4.00	0.00	4.00	EA	4.00	0 \$1,000.00	\$4,000.00			
		0001	0760	7320815A	15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	10.00	0.00	10.00	EA	10.00	\$125.00	\$1,25			
		0001	0770	8051000A	SEETION SEEDING - COOL SEASON MIXTURES	34.60	0.00	34.60	ACRE	27.77	\$1,750.00	\$48,59			
		0001	0780	8061004	SEDIMENT TRAP ROCK	234.90	-133.90	101.00	CUYD	101.00	\$90.00	\$9,09			
		0001	0790	8061005	ROCK DITCH CHECK	7,047.00	-4,476.00	2,571.00	LF	2,571.00	\$8.00	\$20,56			
		0001	0800	8061006	ALTERNATE DITCH CHECK	470.00	4,200.00	4,670.00	LF	4,670.00	\$6.00	\$28,02			
		0001	0810	8061016	SEDIMENT REMOVAL	1,198.00	0.00	1,198.00	CUYD	0.00	\$5.00	\$			
		0001	0820	8061019	SILT FENCE	23,490.00	-22,875.00	615.00	LF	615.00	\$1.50	\$92			
		0040	0830	9039901	MISC.ADJUST EXISTING SIGNS	1.00	0.00	1.00	LS	1.00	\$165,000.00	\$165,00			
P	Project J	iS3319 - To	otal Value	Posted to I	Date as of Report Generated Date							\$4,790,70			
J	J5S3388	0001	0840	3107002	GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)	85.00	0.00	85.00	TONS	93.29	\$74.38	\$6,938			
		0001	0850	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	3,929.40	0.00	3,929.40	TONS	3,780.01	\$52.45	\$198,261			



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

ate and can differ from the posted amount at the time the Estimate was Generated

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
01218-D04	J5S3388	0001	0860	4071005	TACK COAT	4,726.00	0.00	4,726.00	GAL	3,934.00	\$2.05	\$8,064.70
		0001	0870	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
		0001	0880	6161005	CONSTRUCTION SIGNS	1,102.00	0.00	1,102.00	SQFT	288.00	\$8.00	\$2,304.00
		0001	0890	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	0.00	\$25.00	\$0.00
		0001	0900	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	0.00	\$20.00	\$0.00
		0001	0910	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0920	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.00
		0001	0930	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$5,895.70	\$5,895.70
		0001	0940	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	45,471.00	0.00	45,471.00	LF	45,471.00	\$0.09	\$4,092.39
		0001	0950	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	42,278.00	0.00	42,278.00	LF	42,278.00	\$0.10	\$4,227.80
		0001	0960	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	356.00	0.00	356.00	SQYD	0.00	\$22.33	\$0.00
	Project J	5S3388 - To	otal Value	Posted to D	ate as of Report Generated Date							\$233,785.02
1218-D04 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$5,325,101.68



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail. location and quantity of work.

Project: J5S3319

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0250	2142000	FURNISHING ROCK FILL	11/30/21	12/2/21	-1.40	CUYD	Calculation Error, adjusting to final quantity					
0260	2143000	PLACING ROCK FILL	11/30/21	12/2/21	-1.40	CUYD	Calculation Error, adjusting to final quantity					
0270	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	11/30/21	12/2/21	-0.20	SQYD	Rounding to Final Quantity					
0310	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	8/13/21	12/2/21	13.86	TONS	BB 21-27 placed on 8/13					
			8/26/21	12/2/21	110.44	TONS	Additional tonnage Contractor forgot to include with initial tickets from 8/26					
0510	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	11/30/21	12/2/21	248,450.00	LF	J/O/UU					
0520	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	11/30/21	12/2/21	225,491.00	LF	J/O/UU					
0540	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	11/30/21	12/2/21	1,511.00	SQYD	J/O/UU					
0550	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	11/30/21	12/2/21	5,120.00	SQYD	J/O/UU					

The information below this line are details for Construction Signs (if applicable). No Data Available



NUM Visite Visite <th>Project</th> <th>Line</th> <th>Description</th> <th>Adjustment</th> <th>Other</th> <th>Est.</th> <th>Created</th> <th>Created</th> <th>Amount</th> <th>Remarks</th>	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
Normal Construction Normal Construction Second Construction				Туре	Adjustment Type	Number	Date	Ву			
$ \left \begin{array}{c c c c c } & 1 & 2 & 2 \\ & 2 & 2 \\ \hline \\ 2 & 4 \\ \hline \\ 2 $	J5S3232	0020	OR CRUSHED STONE (B) OR	Overrun	Overrun	1		SYSTEM	\$63.76	Estimate Item Adjustment (0003) due to user webers1 overridding Payment	
$ \int A + $			CHAT			1		SYSTEM	(\$63.76)		
 						2		SYSTEM	(\$63.76)		
Problem <t< td=""><td></td><td></td><td></td><td></td><td></td><td>2</td><td></td><td>SYSTEM</td><td>\$63.76</td><td>Estimate Item Adjustment (0001) due to user webers1 overridding Payment</td></t<>						2		SYSTEM	\$63.76	Estimate Item Adjustment (0001) due to user webers1 overridding Payment	
Part of the second s						3		SYSTEM	(\$63.76)		
$ \frac{1}{\sqrt{22}} = \frac{1}{\sqrt{22}} =$						3		SYSTEM	\$63.76	Estimate Item Adjustment (0007) due to user webers1 overridding Payment	
$ \left \begin{array}{ $						4		SYSTEM	(\$63.76)		
$ \left \begin{array}{ c c c c } \hline c c c c c c c c c c c c c c c c c c $						4		SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment	
View View Second Secon						5		SYSTEM	(\$63.76)		
$ \begin{array}{ c c c c } \hline $						5		SYSTEM	\$63.76	Estimate Item Adjustment (0005) due to user webers1 overridding Payment	
Vertice 0 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td>6</td> <td></td> <td>SYSTEM</td> <td>(\$63.76)</td> <td></td>						6		SYSTEM	(\$63.76)		
$ \frac{1}{1} \left(\begin{array}{c c c c } 2221 \\ \hline \\ $						6		SYSTEM	\$63.76	Estimate Item Adjustment (0014) due to user webers1 overridding Payment	
$ \left \begin{array}{ c c c } \hline c c \\ \hline c c \hline c c \\ \hline c c \\ \hline c c \hline c c \\ \hline c c \\ \hline c c \hline c $						7		SYSTEM	(\$63.76)		
Overrun - Total Status Status <t< td=""><td></td><td></td><td></td><td></td><td></td><td>7</td><td></td><td>SYSTEM</td><td>\$63.76</td><td>Estimate Item Adjustment (0014) due to user woods6 overridding Payment</td></t<>						7		SYSTEM	\$63.76	Estimate Item Adjustment (0014) due to user woods6 overridding Payment	
0020 - Total State					Overrun - Total				\$0.00		
0030 BIT. MXTURE PG64-22 (BP-1) Material MAterial PG64-22 (BP-1) Material MAterial PAVEMENT MXTURE PG64-22 (BP-1) Material Material PG64-22 (BP-1) Material PAVEMENT MXTURE PG64-22 (BP-1) Material PAVEMENT MXTURE PG64-22 (BP-1) Material PAVEMENT MXTURE PG64-22 (BP-1) Material PAVEMENT MXTURE PG64-22 (BP-1) Material PAVEMENT MXTURE PG64-22 (BP-1) Material PAVEMENT PG64-22 (BP-1) Material PAVEMENT PG64-22 (BP-1) Material PAVEMENT PG64-22 (BP-1) Material PAVEMENT PG64-22 (BP-1) Material PAVEMENT PG64-22 (BP-1) Material PAVEMENT PG64-22 (BP-1) Material PAVEMENT PAVEMENT PG64-22 (BP-1) Material PAVEMENT PAVEMENT PG64-22 (BP-1) Material PAVEMENT PAVEMENT PAVEMENT PAVEMENT PG64-22 (BP-1) Material PAVEMENT PAVEMENT PAVEMENT PAVEMENT PG64-22 (BP-1) Material PAVEMENT PAVEMENT PAVEMENT PAVEMENT PAVEMENT PAVEMENT PG64-22 (BP-1) Material PAVEMENT PA				Overrun - T	otal						
MAXEMENT MIXTURE PG64-22 (BP-1) PAVEMENT MIXTURE PG64-22 (BP-1) Image: PG64-22 (P-1) Image: PG64-22 (P-1) Image: PG64-22 (
$ \left \begin{array}{c c c c c c c c c c c c c c c c c c c $		0030	PAVEMENT MIXTURE	Material		2		SYSTEM	\$178,469.21	Estimate Item Adjustment (0003) due to user webers1 overridding Payment	
$ \frac{1}{2021} = $			F G04-22 (BF-1)			2		SYSTEM	(\$178,469.21)		
$ \frac{1}{1} = \frac{1}{2021} = \frac{1}{2021} = \frac{1}{1} = \frac{1}{2021} = \frac{1}{1} = \frac{1}{2021} = \frac{1}{1} = \frac{1}{2021} = \frac{1}{1} $					3	3	3		SYSTEM	\$178,469.21	Estimate Item Adjustment (0009) due to user webers1 overridding Payment
Material - Total\$0.00Other Item AdjustmentACAD 202112021 2021webers1\$4,600.60 \$4,600.60AC Adjustment for BP1 19-35C 2.9% Virgin AC% 1866.37 TonsAdjustment12021 2021webers1\$2,934.85 2021AC Adjustment for BP1 21-33 2.8% Virgin AC% 1233.13 Tons includes 0.03 Tons for Rounding to Final QuantityACAD - TotalVerrun\$7,535.45Other Item Adjustment - Total\$12021 2021\$YSTEM\$(\$14,277.04)OverrunOverrun12021 2021\$YSTEM\$14,277.04 2021Reference Item Price Adjustment Index Adjustment Type applied is FUEL Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.2Jul 15, 2021\$YSTEM\$(\$14,277.04)Averaged Price Adjustment from this item on all previous payment estimates of "2.35720" is applied (if non-zero).						3		SYSTEM	(\$178,469.21)		
Other Item Adjustment ACAD 1 Jul 2, 2021 webers1 \$4,600.60 AC Adjustment for BP1 19-35C 2.9% Virgin AC% 1866.37 Tons Adjustment 1 Jul 2, 2021 webers1 \$2,934.85 AC Adjustment for BP1 21-33 2.8% Virgin AC% 1233.13 Tons includes 0.03 Tons for Rounding to Final Quantity ACAD - Total * \$7,535.45 Other Item Adjustment - Total \$YSTEM \$(\$14,277.04) Reference Item Price Adjustment Index Adjustment Type applied is FUEL Overrun Overrun Jul 2, 2021 \$YSTEM \$14,277.04 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 2 Jul 15, 2021 \$YSTEM \$(\$14,277.04) Averaged Price Adjustment form this item on all previous payment estimates of '2.35720' is applied (if non-zero).					- Total				\$0.00		
Adjustment Z021 webers1 \$2,934.85 AC Adjustment for BP1 21-33 2.8% Virgin AC% 1233.13 Tons includes 0.03 Tons for Rounding to Final Quantity ACAD - Total \$7,535.45 Other Item Adjustment - Total \$7,535.45 Overrun Overrun Jul 2, 2021 SYSTEM \$(\$14,277.04) Reference Item Price Adjustment Index Adjustment Type applied is FUEL 1 Jul 2, 2021 SYSTEM \$14,277.04 Reference Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 2 Jul 15, 2021 SYSTEM \$(\$14,277.04)				Material - To	otal				\$0.00		
ACAD - Total \$7,535.45 Other Item Adjustment - Total \$7,535.45 Overrun Overrun 1 Jul 2, 2021 2021 \$YSTEM 2021 \$YSTEM 1 Jul 2, 2021 2021 \$YSTEM \$14,277.04 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 2 Jul 15, 2021 \$YSTEM 2021 \$YSTEM \$(\$14,277.04) Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).					ACAD	1		webers1	\$4,600.60	AC Adjustment for BP1 19-35C 2.9% Virgin AC% 1866.37 Tons	
Other Item Adjustment - Total \$7,535.45 Overrun Overrun Jul 2, 2021 SYSTEM (\$14,277.04) Reference Item Price Adjustment Index Adjustment Type applied is FUEL 1 Jul 2, 2021 SYSTEM \$14,277.04 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 2 Jul 15, 2021 SYSTEM (\$14,277.04) Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).						1		webers1	\$2,934.85		
Overrun 1 Jul 2, 2021 SYSTEM ((\$14,277.04) Reference Item Price Adjustment Index Adjustment Type applied is FUEL 1 Jul 2, 2021 SYSTEM \$14,277.04 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 2 Jul 15, 2021 SYSTEM \$(\$14,277.04) Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).					ACAD - Tota	al			\$7,535.45		
1 Jul 2, 2021 SYSTEM \$14,277.04 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment 2 Jul 15, 2021 SYSTEM \$(\$14,277.04) Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).				Other Item	Adjustment -	Total			\$7,535.45		
2021 Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 2 Jul 15, 2021 SYSTEM (\$14,277.04) Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).				Overrun	Overrun	1		SYSTEM	(\$14,277.04)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
2021 of '2.35720' is applied (if non-zero).						1		SYSTEM	\$14,277.04	Estimate Item Adjustment (0002) due to user webers1 overridding Payment	
2 Jul 15, SYSTEM \$14,277.04 This adjustment offsets the original system-generated Overrun Payment						2		SYSTEM	(\$14,277.04)		
						2	Jul 15,	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5\$3232	0030	BIT. PAVEMENT MIXTURE	Overrun	Overrun		2021			Estimate Item Adjustment (0002) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 3099.500; Overrun Quantity Balance 238.20.
		PG64-22 (BP-1)			3	Aug 2, 2021	SYSTEM	(\$14,277.04)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).
					3	Aug 2, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 3099.500; Overrun Quantity Balance 238.20.
					4	Aug 16, 2021	SYSTEM	(\$14,277.04)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).
					4	Aug 16, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$14,277.04)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).
					5	Sep 2, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$14,277.04)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).
					6	Sep 16, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user webers1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$14,277.04)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).
					7	Oct 4, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woods6 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
			Price FUEL		1	Jul 2, 2021	SYSTEM	\$7,306.14	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$7,306.14	
			Price FUEL	- Total				\$7,306.14	
	0030 -	Total						\$14,841.59	
	0040	BITUMINOUS PAVEMENT MIXTURE	Material		1	Jul 2, 2021	SYSTEM	\$6,231.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	0040					Jul 2,	SYSTEM	(\$6,231.39)	
					1	2021	STOTEM	(\$0,231.39)	
					1 2		SYSTEM	\$6,231.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
						2021 Jul 15,		,	Estimate Item Adjustment (0005) due to user webers1 overridding Payment
					2	2021 Jul 15, 2021 Jul 15,	SYSTEM	\$6,231.39	Estimate Item Adjustment (0005) due to user webers1 overridding Payment
					2 2	2021 Jul 15, 2021 Jul 15, 2021 Aug 2,	SYSTEM SYSTEM	\$6,231.39 (\$6,231.39)	Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment
					2 2 3	2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM	\$6,231.39 (\$6,231.39) \$6,231.39	Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment
					2 2 3 3	2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$6,231.39 (\$6,231.39) \$6,231.39 (\$6,231.39) (\$6,231.39)	Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment
				- Total	2 2 3 3 4	2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$6,231.39 (\$6,231.39) \$6,231.39 (\$6,231.39) \$6,231.39	Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment
			Material - T		2 2 3 3 4	2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$6,231.39 (\$6,231.39) \$6,231.39 (\$6,231.39) \$6,231.39 \$6,231.39 (\$6,231.39)	Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment
			Material - T Other Item Adjustment	otal ACAD	2 2 3 3 4 4 1	2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$6,231.39 (\$6,231.39) \$6,231.39 (\$6,231.39) \$6,231.39 (\$6,231.39) (\$6,231.39) \$6,231.39	Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment
			Other Item	otal	2 2 3 3 4 4 1	2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Jul 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,231.39 (\$6,231.39) \$6,231.39 (\$6,231.39) \$6,231.39 (\$6,231.39) \$6,231.39 (\$6,231.39) \$0.00	Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. AC Adjustment for SL21-2 3.3% Virgin AC% 164.2 Tons includes 0.03 Tons
			Other Item Adjustment	otal ACAD	2 2 3 3 4 4 1	2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Jul 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,231.39 (\$6,231.39) \$6,231.39 (\$6,231.39) \$6,231.39 (\$6,231.39) \$6,231.39 (\$6,231.39) \$0.00 \$0.00 \$460.58	Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. AC Adjustment for SL21-2 3.3% Virgin AC% 164.2 Tons includes 0.03 Tons



ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
232	0040	BITUMINOUS PAVEMENT MIXTURE	Overrun	Type Overrun	1	Jul 2, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 3 on the current Payment Estimate. Material Insufficiency Quantity 164.200;
		PG64-22 (SUR			2	Jul 15, 2021	SYSTEM	(\$729.56)	Overrun Quantity Balance 18.10. Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					2	Jul 15, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 164.200; Overrun Quantity Balance 18.10.
					3	Aug 2, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					3	Aug 2, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 13 on the current Payment Estimate. Material Insufficiency Quantity 164.200; Overrun Quantity Balance 18.10.
					4	Aug 16, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					4	Aug 16, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception 26 on the current Payment Estimate. Material Insufficiency Quantity 164.200; Overrun Quantity Balance 18.10.
					5	Sep 2, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					5	Sep 2, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					6	Sep 16, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					7	Oct 4, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woods6 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal			OVOTEN	\$0.00	
			Price FUEL		1	Jul 2, 2021	SYSTEM	\$387.05	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$387.05	
			Price FUEL	- Total				\$387.05	
	0040 - 0130		Material		2	Jul 15, 2021	SYSTEM	\$847.63 \$3,292.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment
		PAVMT MARKING, 6 IN WHITE			2	Jul 15, 2021	SYSTEM	(\$3,292.50)	Estimate Exception 3 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	\$3,292.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$3,292.50)	
					4	Aug 16, 2021	SYSTEM	\$3,292.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$3,292.50)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0130 -	Total						\$0.00	
	0140	PREF THERMO PAVMT	Material		2	Jul 15, 2021	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
3232	0140	MARKING, 12 IN WHITE	Material		2	Jul 15, 2021	SYSTEM	(\$930.00)						
					3	Aug 2, 2021	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Paymen Estimate Exception 7 on the current Payment Estimate.					
					3	Aug 2, 2021	SYSTEM	(\$930.00)						
					4	Aug 16, 2021	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.					
					4	Aug 16, 2021	SYSTEM	(\$930.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0140 -	Total						\$0.00						
	0150	PREF THERMO PVMT MARK,	Material		2	Jul 15, 2021	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payme Estimate Exception 5 on the current Payment Estimate.					
		LT/RT ARROW			2	Jul 15, 2021	SYSTEM	(\$350.00)						
					3	Aug 2, 2021	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payme Estimate Exception 8 on the current Payment Estimate.					
					3	Aug 2, 2021	SYSTEM	(\$350.00)						
					4	Aug 16, 2021	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user webers1 overridding Payme Estimate Exception 13 on the current Payment Estimate.					
										4	Aug 16, 2021	SYSTEM	(\$350.00)	
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0150 -	Total						\$0.00						
	0160	PREF THERMO PVMT MARK,	Material		2	Jul 15, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payme Estimate Exception 6 on the current Payment Estimate.					
		30" WHT MIDBL			2	Jul 15, 2021	SYSTEM	(\$750.00)						
					3	Aug 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Payme Estimate Exception 9 on the current Payment Estimate.					
					3	Aug 2, 2021	SYSTEM	(\$750.00)						
					4	Aug 16, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user webers1 overridding Payme Estimate Exception 14 on the current Payment Estimate.					
					4	Aug 16, 2021	SYSTEM	(\$750.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0160 -	Total						\$0.00						
	0170	4 IN. WHITE WATERBORNE	Other Item Adjustment	REFL	2	Jul 15, 2021	webers1	(\$518.43)	20% Retroreflectivity Adjustment till Testing is Completed					
		PAVEMENT MARKING			5	Sep 2, 2021	webers1	\$129.61	5% Bonus for Retroreflectivity results					
					5	Sep 2, 2021	webers1	\$518.43	Resolves Item Adjustment from Estimate 0002					
								6400.04						
				REFL - Tota				\$129.61						
			Other Item A	REFL - Tota Adjustment -				\$129.61						
	0170 -	· Total	Other Item /											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J5S3232	0180	PAVEMENT MARKING	Other Item Adjustment	REFL	5	Sep 2, 2021	webers1	\$158.24	5% Bonus for Retroreflectivity results								
					5	Sep 2, 2021	webers1	\$632.95	Resolves Item Adjustment from Estimate 0002								
				REFL - Tota	I	1		\$158.24									
			Other Item	Adjustment -	Total			\$158.24									
	0180 -	Total						\$158.24									
	0190	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	1	Jul 2, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.								
					1	Jul 2, 2021	SYSTEM	(\$805.62)									
					2	Jul 15, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					2	Jul 15, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.								
					3	Aug 2, SYSTE	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					3	Aug 2, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 14 on the current Payment Estimate.								
					4	Aug 16, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					4	Aug 16, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user webers1 overridding Payment Estimate Exception 27 on the current Payment Estimate.								
									5	Sep 2, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
					5	Sep 2, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 18 on the current Payment Estimate.								
										6	Sep 16, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
							6	Sep 16, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user webers1 overridding Payment Estimate Exception 16 on the current Payment Estimate.						
					7	Oct 4, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					7	Oct 4, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woods6 overridding Payment Estimate Exception 19 on the current Payment Estimate.								
				Overrun - T	otal			\$0.00									
			Overrun - T	otal				\$0.00									
	0190 -	Total						\$0.00									
J5S3232	- Total							\$15,977.07									
J5S3319	0250	FURNISHING ROCK FILL	Material		3	Aug 2, 2021	SYSTEM	\$16,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					3	Aug 2, 2021	SYSTEM	(\$16,540.00)									
													4	Aug 16, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$76,040.00)									
					5	Sep 2, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					5	Sep 2, 2021	SYSTEM	(\$76,040.00)									
					6	Sep 16, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3319	0250	FURNISHING ROCK FILL	Material		6	Sep 16, 2021	SYSTEM	(\$76,040.00)	
					7	Oct 4, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$76,040.00)	
					8	Oct 18, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$76,040.00)	
					9	Nov 2, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$76,040.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0250 -	Total						\$0.00	
	0270	TYPE 1 AGGREGATE FOR BASE (4	Material		3	Aug 2, 2021	SYSTEM	\$814.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		IN. THICK)			3	Aug 2, 2021	SYSTEM	(\$814.72)	
					4	Aug 16, 2021	SYSTEM	\$3,101.43	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$3,101.43)	
					5	Sep 2, 2021	SYSTEM	\$3,101.43	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$3,101.43)	
					6	Sep 16, 2021	SYSTEM	\$3,101.43	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$3,101.43)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Price FUEL		3	Aug 2, 2021	SYSTEM	\$13.32	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Aug 16, 2021	SYSTEM	\$41.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Nov 16, 2021	SYSTEM	\$2.01	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Dec 2, 2021	SYSTEM	(\$0.03)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$56.77	
			Price FUEL	- Total				\$56.77	
								\$56.77	
	0270 -	Total							
	0270 - 0300	5 3/4 INCHES, BITUMINOUS PAVEMENT	Material		10	Nov 16, 2021	SYSTEM	\$184.34	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		5 3/4 INCHES, BITUMINOUS	Material		10		SYSTEM	\$184.34 (\$184.34)	Estimate Item Adjustment (0006) due to user webers1 overridding Payment
		5 3/4 INCHES, BITUMINOUS	Material			2021 Nov 16,			Estimate Item Adjustment (0006) due to user webers1 overridding Payment



Dec 13, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J5S3319	0300	5 3/4 INCHES,	Material	- Total				\$0.00									
		BITUMINOUS PAVEMENT	Material - To	otal				\$0.00									
			Other Item Adjustment	ACAD	10	Nov 16, 2021	webers1	\$14.23	AC Adjustment for SL21-5 VAC 3.3% at 13.3 SQYDs Plans show 1.987 Tons/CY for Surface Leveling 5.75"/36" x 13.3 SQYDs = 2.124 CUYDs x 1.987 = 4.22 Tons								
				ACAD - Tota	al			\$14.23									
			Other Item	- Adjustment -	Total			\$14.23									
			Price FUEL		10	Nov 16, 2021	SYSTEM	\$14.10	Reference Item Price Adjustment Index Adjustment Type applied is FUEL								
				- Total				\$14.10									
			Price FUEL	- Total				\$14.10									
	0300 -	Total						\$28.33									
	0310	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	Material		5	Sep 2, 2021	SYSTEM	\$196,635.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
		FG04-22 (BAS			5	Sep 2, 2021	SYSTEM	(\$196,635.91)									
					6	Sep 16, 2021	SYSTEM	\$10,595.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					6	Sep 16, 2021	SYSTEM	(\$10,595.91)									
													7	Oct 4, 2021	SYSTEM	\$425,565.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woods6 overridding Payment Estimate Exception 2 on the current Payment Estimate.
									7	Oct 4, 2021	SYSTEM	(\$425,565.10)					
					8	Oct 18, 2021	SYSTEM	\$425,565.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					8	Oct 18, 2021	SYSTEM	(\$425,565.10)									
					9	Nov 2, 2021	SYSTEM	\$666,875.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					9	Nov 2, 2021	SYSTEM	(\$666,875.73)									
					10	Nov 16, 2021	SYSTEM	\$1,178,485.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					10	Nov 16, 2021	SYSTEM	(\$1,178,485.73)									
					11	Dec 2, 2021	SYSTEM	\$1,184,266.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					11	Dec 2, 2021	SYSTEM	(\$1,184,266.92)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
			Other Item Adjustment	ACAD	3	Aug 2, 2021	webers1	\$197.88	AC Adjustment for Bit Base used on Pipe Crossings								
					4	Aug 16, 2021	webers1	\$553.26	AC adjustment for 184.13 Tons of asphalt placed between 8/2 to 8/15								
					6	Sep 16, 2021	webers1	\$32,624.56	AC Adjustment for Pay Period on Estimate 0005								
					7	Oct 4, 2021	webers1	\$26,855.67	AC Adjustment for 8922.15 Tons of BB21-27 VAC 2.8%								
					9	Nov 2, 2021	webers1	\$14,890.59	AC Adjustment for 5188.36 Tons of BB21-27 at VAC 2.8%								
					11	Dec 2, 2021	webers1	\$328.56	AC Adjustment for 110.44 Tons of BB21-27 at 2.8% VAC placed on 8/26/21								
					11	Dec 2, 2021	webers1	\$41.23	AC Adjustment for 13.86 Tons of BB21-27 at 2.8% VAC placed on 8/13/21								



Dec 13, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J5S3319	0310	BITUMINOUS PAVEMENT	Other Item Adjustment	ACAD - Tot	al			\$75,491.75															
		MIXTURE PG64-22 (BAS	Other Item	Adjustment -	Total			\$75,491.75															
			Price FUEL		3	Aug 2, 2021	SYSTEM	\$187.67	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					4	Aug 16, 2021	SYSTEM	\$495.07	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					5	Sep 2, 2021	SYSTEM	\$29,485.15	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					7	Oct 4, 2021	SYSTEM	\$21,323.22	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					9	Nov 2, 2021	SYSTEM	\$17,395.12	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					11	Dec 2, 2021	SYSTEM	\$334.21	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
				- Total				\$69,220.44															
			Price FUEL	- Total				\$69,220.44															
	0310 -	Total						\$144,712.19															
	0320	BITUMINOUS PAVEMENT MIXTURE	Material		6	Sep 16, 2021	SYSTEM	\$350,706.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.														
		PG64-22 (SUR			6	Sep 16, 2021	SYSTEM	(\$350,706.30)															
					7	Oct 4, 2021	SYSTEM	\$727,265.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate.														
																			7	Oct 4, 2021	SYSTEM	M (\$727,265.12)	
														8	Oct 18, 2021	SYSTEM	\$969,669.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					8	Oct 18, 2021	SYSTEM	(\$969,669.41)															
				- Total				\$0.00															
			Material - To					\$0.00															
			Other Item Adjustment	ACAD	6	Sep 16, 2021	webers1	\$19,803.56	AC Adjustment for Pay Period 9/2 to 9/15														
					6	Sep 16, 2021	webers1	\$5,133.64	AC Adjustment for Pay Period on Estimate 0005														
					7	Oct 4, 2021	webers1	\$26,840.31	AC Adjustment for 7565.98 Tons of SL21-5 VAC 3.3%														
					8	Oct 18, 2021	webers1	\$16,474.43	AC Adjustment for 4870.49 Tons of SL21-5 at 3.3% VAC														
					9	Nov 2, 2021 Nov 16,	webers1	\$4,004.28	AC Adjustment for 5250.89 Tons of SL21-5 at VAC 3.3%														
				ACAD - Tota		2021	weberst	\$90,017.36	AC Adjustment for 1188.04 SL21-5 VAC 3.3% and AC Adjustment for -4.22 SL21-5 VAC 3.3%														
			Other Hore	Adjustment -				\$90,017.36															
						Nex 2	OVOTEN		Deference kam Drice Adjustment Index Adjustment Time and it. Cliffi														
			Overrun	Overrun	9	Nov 2, 2021	SYSTEM	(\$151,799.54)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
				Overrun - T		Nov 16, 2021	STOTEM	(\$62,888.31) (\$214,687.85)															
			Overmun -T																				
			Overrun - T Price FUEL		6	Sep 16, 2021	SYSTEM	(\$214,687.85) \$16,844.05	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
			FUEL		7	Oct 4, 2021	SYSTEM	\$18,085.72	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					8	Oct 18,	SYSTEM	\$16,331.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														



ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
319	0320	BITUMINOUS PAVEMENT	Price FUEL	Туре	9	Nov 2, 2021	SYSTEM	\$17,607.28	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		MIXTURE PG64-22 (SUR	TOLL		10	Nov 16, 2021	SYSTEM	\$3,969.59	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$72,838.37	
			Price FUEL					\$72,838.37	
	0320 -	Total	111001022	Total				(\$51,832.12)	
	0330		Material		8	Oct 18, 2021	SYSTEM	\$28,726.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$28,726.65)	
					9	Nov 2, 2021	SYSTEM	\$40,669.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$40,669.95)	
					10	Nov 16, 2021	SYSTEM	\$43,464.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$43,464.10)	
					11	Dec 2, 2021	SYSTEM	\$43,464.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$43,464.10)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0330 -	Total						\$0.00	
	0340	CONCRETE PAVEMENT (5 3/4 IN. NON-	Material		4	Aug 16, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		REINF			4	Aug 16, 2021	SYSTEM	(\$1,639.81)	
					5	Sep 2, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$1,639.81)	
					6	Sep 16,	SYSTEM	\$1,639.81	
						2021		¢1,000101	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	2021 Sep 16, 2021	SYSTEM	(\$1,639.81)	Estimate Item Adjustment (0007) due to user webers1 overridding Payment
					6 7	Sep 16,	SYSTEM SYSTEM		Estimate Item Adjustment (0007) due to user webers1 overridding Payment
						Sep 16, 2021 Oct 4,		(\$1,639.81)	Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment
					7	Sep 16, 2021 Oct 4, 2021 Oct 4,	SYSTEM	(\$1,639.81) \$1,639.81	Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment
					7 7	Sep 16, 2021 Oct 4, 2021 Oct 4, 2021 Oct 4, 2021	SYSTEM SYSTEM	(\$1,639.81) \$1,639.81 (\$1,639.81)	Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment
				- Total	7 7 8	Sep 16, 2021 Oct 4, 2021 Oct 4, 2021 Oct 18, 2021 Oct 18,	SYSTEM SYSTEM SYSTEM	(\$1,639.81) \$1,639.81 (\$1,639.81) \$1,639.81	Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment
			Material - To		7 7 8	Sep 16, 2021 Oct 4, 2021 Oct 4, 2021 Oct 18, 2021 Oct 18,	SYSTEM SYSTEM SYSTEM	(\$1,639.81) \$1,639.81 (\$1,639.81) \$1,639.81 (\$1,639.81)	Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment
	0340 -	Total	Material - Te		7 7 8	Sep 16, 2021 Oct 4, 2021 Oct 4, 2021 Oct 18, 2021 Oct 18,	SYSTEM SYSTEM SYSTEM	(\$1,639.81) \$1,639.81 (\$1,639.81) \$1,639.81 (\$1,639.81) (\$1,639.81) \$0.00	Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment
	<mark>0340 -</mark> 0350	Total WOVEN WIRE FENCE	Material - To Material		7 7 8	Sep 16, 2021 Oct 4, 2021 Oct 4, 2021 Oct 18, 2021 Oct 18,	SYSTEM SYSTEM SYSTEM	(\$1,639.81) \$1,639.81 (\$1,639.81) \$1,639.81 (\$1,639.81) (\$1,639.81) \$0.00 \$0.00	Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3319	0350	WOVEN WIRE FENCE	Material		5	Sep 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$2,200.00)	
					6	Sep 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$2,200.00)	
					7	Oct 4, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woods6 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$2,200.00)	
					8	Oct 18, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$2,200.00)	
					9	Nov 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$2,200.00)	
					10	Nov 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$2,200.00)	
					11	Dec 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
						11	Dec 2, 2021	SYSTEM	(\$2,200.00)
				- Total				\$0.00	
	0350 -	Total	Material - T	otal				\$0.00 \$0.00	
	0360	ROCK LINING	Material		3	Aug 2, 2021	SYSTEM	\$385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$385.00)	
					4	Aug 16, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$3,650.00)	
					5	Sep 2, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$3,650.00)	
					6	Sep 16, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
									Leamate Exception 7 on the carrient raymont Leamater
					6	Sep 16, 2021	SYSTEM	(\$3,650.00)	
					6 7		SYSTEM	(\$3,650.00) \$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment Estimate Exception 6 on the current Payment Estimate.
						2021 Oct 4,			This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
S3319	0360	ROCK LINING	Material		8	Oct 18, 2021	SYSTEM	(\$3,650.00)											
					9	Nov 2, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
					9	Nov 2, 2021	SYSTEM	(\$3,650.00)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
	0360 -	Total						\$0.00											
	0510	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		11	Dec 2, 2021	SYSTEM	\$22,360.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
		MARKING			11	Dec 2, 2021	SYSTEM	(\$22,360.50)											
				- Total				\$0.00											
			Material - T	otal				\$0.00											
			Other Item Adjustment	REFL	11	Dec 2, 2021	webers1	(\$4,472.10)	20% Withheld until Retro-reflectivity results										
				REFL - Tota	l			(\$4,472.10)											
			Other Item	Adjustment -	Total			(\$4,472.10)											
	0510 -	Total						(\$4,472.10)											
	0520	4 IN. YELLOW WATERBORNE PAVEMENT	Material		11	Dec 2, 2021	SYSTEM	\$22,549.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.										
		MARKING			11	Dec 2, 2021	SYSTEM	(\$22,549.10)											
				- Total				\$0.00											
			Material - Total				\$0.00												
			Other Item Adjustment	REFL	11	Dec 2, 2021	webers1	(\$4,509.82)	20% Withheld until Retro-reflectivity results										
			REFL - Total					(\$4,509.82)											
			Other Item	Adjustment -	Total			(\$4,509.82)											
	0520 -	Total						(\$4,509.82)											
	0590	CLASS B-1 CONCRETE (CULVERTS)	Material		4	Aug 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Paymen Estimate Exception 15 on the current Payment Estimate.										
					4	Aug 16, 2021	SYSTEM	(\$15,000.00)											
				- Total				\$0.00											
			Material - T	otal				\$0.00											
	0590 -	Total						\$0.00											
	0600	REINFORCING STEEL (CULVERTS)	Material		4	Aug 16, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Paymen Estimate Exception 18 on the current Payment Estimate.										
					4	Aug 16, 2021	SYSTEM	(\$5,550.00)											
															5	Sep 2, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Paymen Estimate Exception 9 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$5,550.00)											
					6	Sep 16, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Paymen Estimate Exception 8 on the current Payment Estimate.										
					6	Sep 16, 2021	SYSTEM	(\$5,550.00)											
					7	Oct 4, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woods6 overridding Payment Estimate Exception 7 on the current Payment Estimate.										
									1 3										



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
319	0600	REINFORCING	Material			2021			
		STEEL (CULVERTS)			8	Oct 18, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$5,550.00)	
					9	Nov 2, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$5,550.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0600 -	Total						\$0.00	
	0770	SEEDING - COOL SEASON	Material		7	Oct 4, 2021	SYSTEM	\$19,162.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woods6 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		MIXTURES			7	Oct 4, 2021	SYSTEM	(\$19,162.50)	
					8	Oct 18, 2021	SYSTEM	\$30,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$30,660.00)	
					9	Nov 2, 2021	SYSTEM	\$41,632.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$41,632.50)	
					10	Nov 16, 2021	SYSTEM	\$48,597.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$48,597.50)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0770 -	Total						\$0.00	
		SEDIMENT TRAP ROCK							
	0780		Material		4	Aug 16, 2021	SYSTEM	\$6,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	0780		Material		4		SYSTEM	\$6,390.00 (\$6,390.00)	Estimate Item Adjustment (0010) due to user webers1 overridding Payment
	0780		Material	- Total		2021 Aug 16,			Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	0780		Material Material - T			2021 Aug 16,		(\$6,390.00)	Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
						2021 Aug 16,		(\$6,390.00) \$0.00	Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
		TRAP ROCK				2021 Aug 16,		(\$6,390.00) \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	0780 -	TRAP ROCK	Material - T		4	2021 Aug 16, 2021 Aug 2,	SYSTEM	(\$6,390.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	0780 -	TRAP ROCK	Material - T		3	2021 Aug 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM	(\$6,390.00) \$0.00 \$0.00 \$520.00	Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
I	0780 -	TRAP ROCK	Material - T		4 3 3 3	2021 Aug 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, Aug 16,	SYSTEM SYSTEM SYSTEM	(\$6,390.00) \$0.00 \$0.00 \$520.00 (\$520.00)	Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
I	0780 -	TRAP ROCK	Material - T		4 3 3 4	2021 Aug 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,390.00) \$0.00 \$0.00 \$520.00 (\$520.00) \$14,072.00	Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
I	0780 -	TRAP ROCK	Material - T	otal - Total	4 3 3 4	2021 Aug 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,390.00) \$0.00 \$0.00 \$520.00 (\$520.00) \$14,072.00 (\$14,072.00)	Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
I	0780 -	TRAP ROCK	Material - T	otal - Total	4 3 3 4	2021 Aug 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,390.00) \$0.00 \$0.00 \$520.00 (\$520.00) \$14,072.00 (\$14,072.00) \$0.00	Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	0780 -) 0790	TRAP ROCK	Material - T Material Material - T	otal - Total	4 3 3 4	2021 Aug 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,390.00) \$0.00 \$0.00 \$520.00 (\$520.00) \$14,072.00 (\$14,072.00) \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3319	0800	ALTERNATE	Material			2021			
		DITCH CHECK			5	Sep 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$15,000.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Overrun	Overrun	5	Sep 2, 2021	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 2500.000; Overrun Quantity Balance 2030.00.
					5	Sep 2, 2021	SYSTEM	(\$12,180.00)	
					6	Sep 16, 2021	SYSTEM	(\$12,180.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Sep 16, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$4,800.00)	
					7	Oct 4, 2021	SYSTEM	(\$16,980.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Oct 4, 2021	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	\$16,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woods6 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$8,220.00)	
				Overrun - T	otal			\$0.00	
			Overrun - 1	otal				\$0.00	
	0800 -	Total						\$0.00	
	0820	SILT FENCE	Material		5	Sep 2, 2021	SYSTEM	\$450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$450.00)	
					6	Sep 16, 2021	SYSTEM	\$607.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$607.50)	
					7	Oct 4, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woods6 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$922.50)	
					8	Oct 18, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$922.50)	
					9	Nov 2, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$922.50)	
					10	Nov 16, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 17 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks	
J5S3319	0820	SILT FENCE	Material	Туре	10	Nov 16,	SYSTEM	(\$922.50)		
						2021		(**==***)		
					11	Dec 2, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					11	Dec 2, 2021	SYSTEM	(\$922.50)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0820 -	Total						\$0.00		
J5S3319 -	Total							\$83,983.25		
J5S3388	0840	GRAVEL (A) OR CRUSHED	Overrun	Overrun	10	Nov 16, 2021	SYSTEM	(\$616.61)		
		STONE (B) OR CHAT		Overrun - To	otal			(\$616.61)		
			Overrun - T	otal				(\$616.61)		
	0840 -	Total						(\$616.61)		
	0850	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		8	Oct 18, 2021	SYSTEM	\$95,370.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					8	Oct 18, 2021	SYSTEM	(\$95,370.88)		
					9	Nov 2, 2021	SYSTEM	\$198,261.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					9	Nov 2, 2021	SYSTEM	(\$198,261.52)		
					10	Nov 16, 2021	SYSTEM	\$198,261.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					10	Nov 16, 2021	SYSTEM	(\$198,261.52)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
			Other Item Adjustment	ACAD	8	Oct 18, 2021	webers1	\$6,150.47	AC Adjustment for 1818.32 Tons of SL21-5 at 3.3% VAC	
					9	Nov 2, 2021	webers1	\$6,635.42	AC Adjustment for 1961.69 Tons of SL21-5 at VAC 3.3%	
				ACAD - Tota	al			\$12,785.89		
			Other Item / Price FUEL	Adjustment -	Total			\$12,785.89		
						8	Oct 18, 2021	SYSTEM	\$6,097.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Nov 2, 2021	SYSTEM	\$6,577.94	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
				- Total				\$12,675.13		
			Price FUEL	Total				\$12,675.13		
	0850 -	Total						\$25,461.02		
	0860	TACK COAT	Material		8	Oct 18, 2021	SYSTEM	\$3,113.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					8	Oct 18, 2021	SYSTEM	(\$3,113.95)		
					9	Nov 2, 2021	SYSTEM	\$8,064.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					9	Nov 2, 2021	SYSTEM	(\$8,064.70)		
					10	Nov 16, 2021	SYSTEM	\$8,064.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					10	Nov 16, 2021	SYSTEM	(\$8,064.70)		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J5S3388	0860	TACK COAT	Material		11	Dec 2, 2021	SYSTEM	\$8,064.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					11	Dec 2, 2021	SYSTEM	(\$8,064.70)						
				- Total				\$0.00						
			Material - Total					\$0.00						
	0860 -	Total						\$0.00						
	0940	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		10	Nov 16, 2021	SYSTEM	\$4,092.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.					
		WARKING			10	Nov 16, 2021	SYSTEM	(\$4,092.39)						
					11	Dec 2, 2021	SYSTEM	\$4,092.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.					
					11	Dec 2, 2021	SYSTEM	(\$4,092.39)						
				- Total				\$0.00						
			Material - Total					\$0.00						
			Other Item Adjustment	REFL	10	Nov 16, 2021	webers1	(\$818.48)	20% withheld until Retro-reflectivity results					
			REFL - Total					(\$818.48)						
			Other Item	Adjustment -	Total			(\$818.48)						
	0940 -	Total						(\$818.48)						
	0950	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		10	Nov 16, 2021	SYSTEM	\$4,227.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.					
					10	Nov 16, 2021	SYSTEM	(\$4,227.80)						
										11	Dec 2, 2021	SYSTEM	\$4,227.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$4,227.80)						
				- Total				\$0.00						
			Material - Total					\$0.00						
			Other Item Adjustment	REFL	10	Nov 16, 2021	webers1	(\$845.56)	20% withheld until Retro-reflectivity results					
			REFL - Total					(\$845.56)						
			Other Item Adjustment - Total					(\$845.56)						
	0950 -	Total						(\$845.56)						
J5S3388 -	Total							\$23,180.37						
Overall -	Total						\$123,140.69							