

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 16, 2021

Progress Estimate Number	Contract ID	201218-D04	Pay Period Start	December 2, 202	1 Original Contract Amo	ount\$5,685,901.14
12	Prime Contractor	Capital Paving & Construction, LLC	Pay Period En	d December 15, 2021	Net Change Order Amount Current Contract Amo	(\$177,259.97) ount \$5,508,641.17

Approval Date		By User
December 16, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	hogued1
December 16, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	oeschd1
December 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2021	November 19, 2021		97.64%

	Milestones		
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date	November 19, 2021	November 19, 2021	
Awarded Date	January 6, 2021	January 6, 2021	
Letting Date	December 18, 2020	December 18, 2020	
Notice to Proceed Date	March 8, 2021	March 8, 2021	
Work Began Date			

Contract Total Pay For Estimate No. 12				
	This Estimate	Previous	To Date	
201218-D04				
Total Posted Items Pay	\$53,298.43	\$5,325,101.69	\$5,378,400.12	
Gross Item Adjustments	\$0.00	\$123,140.69	\$123,140.69	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		\$5,448,242.38	\$5,501,540.81	
Contract Total Payable This Estimate:	\$53,298.43			

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J5S3319	0290	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$40.000	126	\$5,040.00		
	5101	1046001	VALUE ENGINEERING	L S \$48,258.430		1	\$48,258.43		
Project J5S3319	Project J5S3319 - Total								
Overall - Total	Overall - Total								

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3319	0300	5 3/4 INCHES, BITUMINOUS PAVEMENT	Material			-13.3	\$13.86	(\$184.34)
	0300	5 3/4 INCHES, BITUMINOUS PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user hogued1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	13.3	\$13.86	\$184.34
	0310	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Material			-1,462.63	\$46.51	(\$68,026.92)
	0310	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	1,462.63	\$46.51	\$68,026.92

Revision 4/1/2020 Page 1 of 25



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 16, 2021

Pay Period **Progress Estimate** December 2, 2021 Original Contract Amount\$5,685,901.14 **Contract ID** 201218-D04 Number Start Pay Period End December 15, 2021 Prime Capital Paving & Construction, Net Change Order 12 (\$177,259.97) Contractor LLĊ Amount Current Contract Amount \$5,508,641.17

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3319					Adjustment (0002) due to user hogued1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
	0330	TACK COAT	Material			-21,202	\$2.05	(\$43,464.10)
	0330	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user hogued1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	21,202	\$2.05	\$43,464.10
	0350	WOVEN WIRE FENCE	Material			-88	\$25.00	(\$2,200.00)
	0350	WOVEN WIRE FENCE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user hogued1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	88	\$25.00	\$2,200.00
	0510	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-248,450	\$0.09	(\$22,360.50)
	0510	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user hogued1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	248,450	\$0.09	\$22,360.50
	0520	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-225,491	\$0.10	(\$22,549.10)
	0520	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user hogued1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	225,491	\$0.10	\$22,549.10
	0820	SILT FENCE	Material			-615	\$1.50	(\$922.50)
	0820	SILT FENCE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user hogued1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	615	\$1.50	\$922.50
J5S3388	0860	TACK COAT	Material			-3,934	\$2.05	(\$8,064.70)
	0860	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user hogued1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	3,934	\$2.05	\$8,064.70
	0940	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-45,471	\$0.09	(\$4,092.39)
	0940	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user hogued1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	45,471	\$0.09	\$4,092.39
	0950	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material			-42,278	\$0.10	(\$4,227.80)

Revision 4/1/2020 Page 2 of 25



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 16, 2021

Progress Estimate Number	Contract ID	201218-D04	Pay Period Start	December 2, 202	1 Original Contract An	nount\$5,685,901.14
12	Prime Contractor	Capital Paving & Construction, LLC	Pay Period En	d December 15, 2021	Net Change Order Amount	(\$177,259.97)
					Current Contract Am	ount \$5,508,641.17

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3388		BEADS						
	0950	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user hogued1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	42,278	\$0.10	\$4,227.80
Total								\$0.00

Revision 4/1/2020 Page 3 of 25



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J5S3232	FAS S401(47)	Resurface	B/M/ 124	BOONE	from west of Rte. 63 to F	m west of Rte. 63 to Rte. DD and Rte. B and Rte. 124 in Hallsville					
J5S3319	FAS S402(6)	Resurface and shoulder improvements	J/O/ UU	BOONE	from Rte. 124 to Rte. O,	m Rte. 124 to Rte. O, Rte. J to the end of state maintenance, and Rte. O to I-70 eastbound ramp					
J5S3388	FAS- S402(060)	Pavement improvements	А	BOONE	from Rte. 63 to the end of	om Rte. 63 to the end of state maintenance in Hartsburg					
Totals by .	Job Number	s									
J5S3232		Item Pay Item Adjustmen	ts Gross It	em Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$300,616.41 \$15,977.07 \$316,593.48	To Date \$300,616.41 \$15,977.07 \$316,593.48				
			ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J5S3319		Posted Item Pay Gross Item Adjustments Gross Item Pay			This Estimate \$53,298.43 \$0.00 \$53,298.43	Previous \$4,790,700.25 \$83,983.25 \$4,874,683.50	To Date \$4,843,998.68 \$83,983.25 \$4,927,981.93				
			ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J5S3388	Posted Item Pay Gross Item Adjustments Gross Item Pay		This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$233,785.03 \$23,180.37 \$256,965.40	To Date \$233,785.03 \$23,180.37 \$256,965.40						
			ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 4/1/2020 Page 4 of 25



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Feriou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4010105, Project Item Line Number 0300, Material Set 401010596, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4010105, Project Item Line Number 0300, Material Set 401010596, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4013000, Project Item Line Number 0310, Material Set 401300096, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4071005, Project Item Line Number 0330, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4071005, Project Item Line Number 0330, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 4071005, Project Item Line Number 0860, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 4071005, Project Item Line Number 0860, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6072010, Project Item Line Number 0350, Material Set 607201096, Material 1043FMWWFB - Woven Wire Fence Fabric, Acceptance Action Generic 1043FMWWFB is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6206000C, Project Item Line Number 0510, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6206000C, Project Item Line Number 0510, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 6206000C, Project Item Line Number 0940, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 6206000C, Project Item Line Number 0940, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6206001C, Project Item Line Number 0520, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6206001C, Project Item Line Number 0520, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 6206001C, Project Item Line Number 0950, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 6206001C, Project Item Line Number 0950, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 8061019, Project Item Line Number 0820, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient.	Working with materials and contractor to resolve.	hogued1	Overridden
Estimate Exception Type: Item Overrun: Contract 201218-D04, Contract Project J5S3319, Project Item Line Number 0320, Contract Line Item Number 0320, Item 4020520, Minor Item.	Change order in progress	hogued1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201218-D04, Contract Project J5S3388, Project Item Line Number 0840, Contract Line Item Number 0840, Item 3107002, Minor Item.	Change order in progress	hogued1	Acknowledged

Revision 4/1/2020 Page 5 of 25



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
01218-D04	J5S3232	0001	0010	2152000A	SHAPING SLOPES, CLASS II	206.00	0.00	206.00	100F	206.00	\$67.73	\$13,952.3
		0001	0020	3107002	GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)	16.00	4.00	20.00	TONS	20.00	\$15.94	\$318.8
		0001	0030	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	2,861.30	238.20	3,099.50	TONS	3,099.50	\$57.58	\$178,469.2
		0001	0040	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	146.10	18.10	164.20	TONS	164.20	\$37.95	\$6,231.3
		0001	0050	4079912	MISC.Low-Tracking or Non Tracking Tack Coat	3,116.00	-16.00	3,100.00	GAL	3,100.00	\$2.35	\$7,285.0
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.0
		0001	0070	6161005	CONSTRUCTION SIGNS	1,767.00	0.00	1,767.00	SQFT	658.00	\$8.00	\$5,264.0
		0001	0080	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$25.00	\$0.
		0001	0090	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$25.00	\$0.0
		0001	0100	6161024	CHANNELIZER (TRIM LINE) WITH LIGHT	421.00	0.00	421.00	EA	0.00	\$20.00	\$0.0
		0001	0110	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$2,000.00	\$8,000.0
		0001	0120	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$8,039.92	\$8,039.9
		0001	0130	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	878.00	0.00	878.00	LF	878.00	\$3.75	\$3,292.5
		0001	0140	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE	124.00	0.00	124.00	LF	124.00	\$7.50	\$930.0
		0001	0150	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	1.00	\$350.00	\$350.0
		0001	0160	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	20.00	0.00	20.00	EA	10.00	\$75.00	\$750.0
		0001	0170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	4,713.00	0.00	4,713.00	LF	4,713.00	\$0.55	\$2,592.
		0001	0180	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	12,659.00	0.00	12,659.00	LF	12,659.00	\$0.25	\$3,164.
		0001	0190	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	29,838.00	463.00	30,301.00	SQYD	30,301.00	\$1.74	\$52,723.
		0001	5001	1094000	FORCE ACCOUNT	0.00	9,252.57	9,252.57	EA	9,252.57	\$1.00	\$9,252.
	Project J	S3232 - To	tal Value	e Posted to D	Date as of Report Generated Date							\$300,616.
	J5S3319	0001	0200	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$115,000.00	\$115,000.
		0001	0210	2063000	CLASS 3 EXCAVATION	865.00	0.00	865.00	CUYD	865.00	\$55.00	\$47,575.
		0001	0220	2063300	CLASS 4 EXCAVATION	20.00	0.00	20.00	CUYD	20.00	\$10.00	\$200.
		0001	0230	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.
		0001	0240	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	2,395.90	0.00	2,395.90	STA	2,395.90	\$465.09	\$1,114,309
		0001	0240 0250	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL	2,395.90 2,828.00	0.00	2,395.90 2,828.00	STA	2,395.90 2,200.00	\$465.09 \$40.00	\$1,114,309 \$88,000
		0001 0001 0001	0240 0250 0260	2079909 2142000 2143000	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL	2,395.90 2,828.00 2,828.00	0.00 0.00 0.00	2,395.90 2,828.00 2,828.00	STA CUYD CUYD	2,395.90 2,200.00 2,200.00	\$465.09 \$40.00 \$25.00	\$1,114,309 \$88,000 \$55,000
		0001 0001 0001 0001	0240 0250 0260 0270	2079909 2142000 2143000 3040143	MISC.MODIFIED LINEAR GRADING CLASS 2 FURNISHING ROCK FILL PLACING ROCK FILL TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	2,395.90 2,828.00 2,828.00 29,287.00	0.00 0.00 0.00 -28,811.00	2,395.90 2,828.00 2,828.00 476.00	STA CUYD CUYD SQYD	2,395.90 2,200.00 2,200.00 476.00	\$465.09 \$40.00 \$25.00 \$6.70	\$1,114,309 \$88,000 \$55,000 \$3,189
		0001 0001 0001 0001 0001	0240 0250 0260 0270 0280	2079909 2142000 2143000 3040143 3049905	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)	2,395.90 2,828.00 2,828.00 29,287.00 214.00	0.00 0.00 0.00 -28,811.00	2,395.90 2,828.00 2,828.00 476.00 214.00	STA CUYD CUYD SQYD SQYD	2,395.90 2,200.00 2,200.00 476.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50	\$1,114,309 \$88,000 \$55,000 \$3,189
		0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290	2079909 2142000 2143000 3040143 3049905 3105002	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)	2,395.90 2,828.00 2,828.00 29,287.00 214.00	0.00 0.00 0.00 -28,811.00 0.00	2,395.90 2,828.00 2,828.00 476.00 214.00	STA CUYD CUYD SQYD SQYD TONS	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00	\$1,114,309 \$88,000 \$55,000 \$3,189 \$0
		0001 0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290	2079909 2142000 2143000 3040143 3049905 3105002 4010105	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT	2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00 31.10	0.00 0.00 0.00 -28,811.00 0.00 0.00	2,395.90 2,828.00 2,828.00 476.00 214.00 210.00	STA CUYD CUYD SQYD SQYD TONS SQYD	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00	\$1,114,309 \$88,000 \$55,000 \$3,189 \$0 \$5,040
		0001 0001 0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290 0300	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00 31.10 29,342.00	0.00 0.00 0.00 -28,811.00 0.00 0.00 0.00	2,395.90 2,828.00 2,828.00 476.00 214.00 210.00 31.10 29,342.00	STA CUYD CUYD SQYD SQYD TONS SQYD TONS	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00 13.30 25,462.63	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51	\$1,114,309 \$88,000 \$55,000 \$3,189 \$0 \$5,040 \$184 \$1,184,266
		0001 0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290	2079909 2142000 2143000 3040143 3049905 3105002 4010105	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT	2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00 31.10	0.00 0.00 0.00 -28,811.00 0.00 0.00	2,395.90 2,828.00 2,828.00 476.00 214.00 210.00	STA CUYD CUYD SQYD SQYD TONS SQYD	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00	\$1,114,309 \$88,000 \$55,000 \$3,189 \$0 \$5,040 \$184 \$1,184,266
		0001 0001 0001 0001 0001 0001 0001	0240 0250 0260 0270 0280 0290 0300	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00 31.10 29,342.00	0.00 0.00 0.00 -28,811.00 0.00 0.00 0.00	2,395.90 2,828.00 2,828.00 476.00 214.00 210.00 31.10 29,342.00	STA CUYD CUYD SQYD SQYD TONS SQYD TONS	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00 13.30 25,462.63	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51	\$1,114,309 \$88,000 \$55,000 \$3,189 \$0 \$5,040 \$184 \$1,184,266 \$1,289,924
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000 4020520	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	2,395.90 2,828.00 2,828.00 29,287.00 214.00 31.10 29,342.00 21,876.40	0.00 0.00 0.00 -28,811.00 0.00 0.00 0.00 0.00	2,395,90 2,828,00 2,828,00 476,00 214,00 210,00 31,10 29,342,00 21,876,40	STA CUYD CUYD SQYD SQYD TONS SQYD TONS TONS	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00 13.30 25,462.63 25,917.72	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77	\$1,114,309 \$88,000 \$55,000 \$3,189 \$0 \$5,040 \$184 \$1,184,266 \$1,289,924
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000 4020520	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT.	2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40	0.00 0.00 -28,811.00 0.00 0.00 0.00 0.00 0.00	2,395,90 2,828,00 2,828,00 476,00 214,00 210,00 31,10 29,342,00 21,876,40	STA CUYD CUYD SQYD SQYD TONS SQYD TONS TONS GAL	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00 13.30 25,462.63 25,917.72 21,202.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77	\$1,114,309 \$88,000 \$55,000 \$3,189 \$0 \$5,040 \$184 \$1,184,266 \$1,289,924 \$43,464 \$1,639
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320 0330	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000 4020520 4071005 5021305	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS)	2,395,90 2,828,00 2,828,00 29,287,00 214,00 31,10 29,342,00 21,876,40 23,405,00 41,80	0.00 0.00 0.00 -28,811.00 0.00 0.00 0.00 0.00 0.00	2,395,90 2,828,00 2,828,00 476,00 214,00 210,00 31,10 29,342,00 21,876,40 23,405,00 41,80	STA CUYD CUYD SQYD SQYD TONS SQYD TONS TONS GAL SQYD	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00 13.30 25,462.63 25,917.72 21,202.00 41.80	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23	\$1,114,309. \$88,000. \$55,000. \$3,189. \$0. \$5,040. \$184. \$1,184,266. \$1,289,924. \$43,464. \$1,639. \$2,200.
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320 0330 0340	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4020520 4071005 5021305 6072010	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS)  WOVEN WIRE FENCE	2,395.90 2,828.00 2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 41.80	0.00 0.00 -28,811.00 0.00 0.00 0.00 0.00 0.00 0.00	2,395,90 2,828,00 2,828,00 476,00 214,00 210,00 31,10 29,342,00 21,876,40 41,80 184,00	STA CUYD CUYD SQYD SQYD TONS SQYD TONS TONS GAL SQYD LF	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00 13.30 25,462.63 25,917.72 21,202.00 41.80 88.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23	\$1,114,309 \$88,000 \$55,000 \$3,189 \$0 \$5,040 \$184 \$1,184,266 \$1,289,924 \$43,464 \$1,639 \$2,200 \$3,650
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0300 0310 0320 0330 0340 0350 0360	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000 4020520 4071005 5021305 6072010 6097000	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS)  WOVEN WIRE FENCE  ROCK LINING	2,395,90 2,828,00 2,828,00 29,287,00 214,00 210,00 31,10 29,342,00 21,876,40 41,80 184,00 73,00	0.00 0.00 -28,811.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395,90 2,828,00 2,828,00 476,00 214,00 210,00 31,10 29,342,00 21,876,40 41,80 184,00 73,00	STA CUYD CUYD SQYD SQYD TONS SQYD TONS GAL SQYD LF CUYD	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00 13.30 25,462.63 25,917.72 21,202.00 41.80 88.00 73.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00	\$1,114,309 \$88,000 \$55,000 \$3,189 \$0 \$5,040 \$184 \$1,184,266 \$1,289,924 \$43,464 \$1,639 \$2,200
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0300 0310 0320 0340 0350 0360	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4013000 4071005 5021305 6072010 6097000 6113010	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS)  WOVEN WIRE FENCE  ROCK LINING  FURNISHING TYPE 1 ROCK BLANKET	2,395,90 2,828,00 2,828,00 29,287,00 214,00 210,00 31,10 29,342,00 21,876,40 23,405,00 41,80 184,00 73,00 121,00	0.00 0.00 -28,811.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395,90 2,828,00 2,828,00 476,00 214,00 210,00 31,10 29,342,00 21,876,40 23,405,00 41,80 184,00 73,00 121,00	STA CUYD CUYD SQYD SQYD TONS SQYD TONS GAL SQYD LF CUYD	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00 13.30 25,462.63 25,917.72 21,202.00 41.80 88.00 73.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00 \$50.00	\$1,114,309 \$88,000 \$55,000 \$3,189 \$0 \$5,040 \$184 \$1,184,266 \$1,289,924 \$43,464 \$1,639 \$2,200 \$3,650 \$2,200
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0290 0310 0320 0330 0340 0350 0360	2079909 2142000 2143000 3040143 3049905 3105002 4010105 4020520 4071005 5021305 6072010 6097000 6113010	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS)  WOVEN WIRE FENCE  ROCK LINING  FURNISHING TYPE 1 ROCK BLANKET  PLACING TYPE 1 ROCK BLANKET	2,395,90 2,828,00 2,828,00 29,287,00 214,00 210,00 31,10 29,342,00 21,876,40 41,80 73,00 121,00	0.00 0.00 0.00 -28,811.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395,90 2,828,00 2,828,00 476,00 214,00 210,00 31,10 29,342,00 21,876,40 41,80 73,00 121,00	STA CUYD CUYD SQYD SQYD TONS SQYD TONS TONS GAL SQYD LF CUYD CUYD	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00 13.30 25,462.63 25,917.72 21,202.00 41.80 88.00 73.00 88.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00 \$50.00 \$25.00	\$1,114,309. \$88,000. \$55,000. \$3,189. \$0. \$5,040. \$184. \$1,184,266. \$1,289,924. \$43,464. \$1,639. \$2,200. \$3,650. \$2,200. \$2,200.
		0001 0001 0001 0001 0001 0001 0001 000	0240 0250 0260 0270 0280 0300 0310 0320 0330 0340 0350 0360 0370 0380	2079909 2142000 2143000 3040143 3049905 3105002 40110105 4013000 4020520 4071005 5021305 6072010 6097000 6113010 6113030 6123000A	MISC.MODIFIED LINEAR GRADING CLASS 2  FURNISHING ROCK FILL  PLACING ROCK FILL  TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)  MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)  GRAVEL (A) OR CRUSHED STONE (B)  5 3/4 INCHES, BITUMINOUS PAVEMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS)  WOVEN WIRE FENCE  ROCK LINING  FURNISHING TYPE 1 ROCK BLANKET  PLACING TYPE 1 ROCK BLANKET  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2,395,90 2,828,00 2,828,00 29,287,00 214,00 210,00 31,10 29,342,00 21,876,40 41,80 184,00 73,00 121,00 121,00 2,00	0.00 0.00 0.00 -28,811.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,395,90 2,828,00 2,828,00 476,00 214,00 210,00 31,10 29,342,00 21,876,40 41,80 184,00 73,00 121,00 121,00 2,00	STA CUYD CUYD SQYD SQYD TONS SQYD TONS TONS GAL SQYD CUYD CUYD CUYD	2,395.90 2,200.00 2,200.00 476.00 0.00 126.00 13.30 25,462.63 25,917.72 21,202.00 41.80 88.00 73.00 88.00 0.00	\$465.09 \$40.00 \$25.00 \$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00 \$50.00 \$25.00 \$1.00	\$0. \$1,114,309. \$88,000. \$55,000. \$3,189. \$0. \$5,040. \$184. \$1,184,266. \$1,289,924. \$43,464. \$1,639. \$2,200. \$3,650. \$2,200. \$2,200. \$0.

Revision 4/1/2020 Page 6 of 25



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

ract TRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
004	J5S3319	0001	0430	6161010	RELOCATED SIGNS	384.00	0.00	384.00	SQFT	384.00	\$7.00	\$2,688.0
		0001	0440	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$20.00	\$0.0
		0001	0450	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	6.00	0.00	6.00	EA	4.00	\$155.00	\$620.
		0001	0460	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.
		0001	0470	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.
		0001	0480	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$330,616.16	\$330,616
		0001	0490	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	6.00	0.00	6.00	EA	0.00	\$600.00	\$0
		0001	0500	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	42.00	0.00	42.00	LF	0.00	\$35.00	\$0.
		0001	0510	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	248,450.00	0.00	248,450.00	LF	248,450.00	\$0.09	\$22,360
		0001	0520	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	225,491.00	0.00	225,491.00	LF	225,491.00	\$0.10	\$22,549
		0001	0530	6208064A	TEMPORARY RAISED PAVEMENT MARKER	125.00	0.00	125.00	EA	0.00	\$0.00	\$0
		0001	0540	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,511.00	0.00	1,511.00	SQYD	1,511.00	\$6.06	\$9,156
		0001	0550	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	5,120.00	0.00	5,120.00	SQYD	5,120.00	\$4.57	\$23,398
		0001	0560	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,639.90	0.00	2,639.90	STA	1,821.10	\$10.00	\$18,211
		0001	0570	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	1,200.50	0.00	1,200.50	STA	1,200.50	\$10.00	\$12,005
		0001	0580	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$8,945.72	\$0
		0001	0590	7034041	CLASS B-1 CONCRETE (CULVERTS)	15.00	0.00	15.00	CUYD	15.00	\$1,000.00	\$15,000
		0001	0600	7061030	REINFORCING STEEL (CULVERTS)	3,700.00	0.00	3,700.00	LB	3,700.00	\$1.50	\$5,550
		0001	0610	7250315A	15 IN. PIPE GROUP B	52.00	0.00	52.00	LF	52.00	\$50.00	\$2,600
		0001	0620	7250318A	18 IN. PIPE GROUP B	256.00	0.00	256.00	LF	256.00	\$70.00	\$17,920
		0001	0630	7250324A	24 IN. PIPE GROUP B	42.00	0.00	42.00	LF	42.00	\$80.00	\$3,360
		0001	0640	7250330A	30 IN. PIPE GROUP B	42.00	0.00	42.00	LF	42.00	\$100.00	\$4,200
		0001	0650	7250336A	36 IN. PIPE GROUP B	88.00	0.00	88.00	LF	88.00	\$110.00	\$9,680
		0001	0660	7250342A	42 IN. PIPE GROUP B	108.00	0.00	108.00	LF	108.00	\$130.00	\$14,040
		0001	0670	7250348A	48 IN. PIPE GROUP B	92.00	0.00	92.00	LF	92.00	\$150.00	\$13,800
		0001	0680	7250415	15 IN. PIPE GROUP C	180.00	0.00	180.00	LF	180.00	\$40.00	\$7,200
		0001	0690	7320015A	15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$150.00	\$300
		0001	0700	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	8.00	0.00	8.00	EA	8.00	\$200.00	\$1,600
		0001	0710	7320024A	24 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$275.00	\$55
		0001	0720	7320030A	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000
		0001	0730	7320036A		4.00	0.00	4.00	EA	4.00	\$600.00	\$2,400
		0001	0740	7320042A	42 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$850.00	\$3,400
		0001	0750	7320048A	48 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$1,000.00	\$4,000
		0001	0760	7320815A	15 IN, OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	10.00	0.00	10.00	EA	10.00	\$125.00	\$1,250
		0001	0770	8051000A	SEEDING - COOL SEASON MIXTURES	34.60	0.00	34.60	ACRE	27.77	\$1,750.00	\$48,597
		0001	0780	8061004	SEDIMENT TRAP ROCK	234.90	-133.90	101.00	CUYD	101.00	\$90.00	\$9,090
		0001	0790	8061005	ROCK DITCH CHECK	7,047.00	-4,476.00	2,571.00	LF	2,571.00	\$8.00	\$20,568
		0001	0800	8061006	ALTERNATE DITCH CHECK	470.00	4,200.00	4,670.00	LF	4,670.00	\$6.00	\$28,020
		0001	0810	8061016	SEDIMENT REMOVAL	1,198.00	0.00	1,198.00	CUYD	0.00	\$5.00	\$0
		0001	0820	8061019	SILT FENCE	23,490.00	-22,875.00	615.00	LF	615.00	\$1.50	\$922
		0040	0830	9039901	MISC.ADJUST EXISTING SIGNS	1.00	0.00	1.00	LS	1.00	\$165,000.00	\$165,000
		0001	5101	1046001	VALUE ENGINEERING	0.00	1.00	1.00	LS	1.00	\$48,258.43	\$48,258
	Project J	S3319 - To	tal Value	Posted to D	Date as of Report Generated Date							\$4,843,998

Revision 4/1/2020 Page 7 of 25



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-D04	J5S3388	0001	0850	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	3,929.40	0.00	3,929.40	TONS	3,780.01	\$52.45	\$198,261.52
		0001	0860	4071005	TACK COAT	4,726.00	0.00	4,726.00	GAL	3,934.00	\$2.05	\$8,064.70
		0001	0870	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
		0001	0880	6161005	CONSTRUCTION SIGNS	1,102.00	0.00	1,102.00	SQFT	288.00	\$8.00	\$2,304.00
		0001	0890	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	0.00	\$25.00	\$0.00
		0001	0900	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	0.00	\$20.00	\$0.00
		0001	0910	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0920	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.00
		0001	0930	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$5,895.70	\$5,895.70
		0001	0940	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	45,471.00	0.00	45,471.00	LF	45,471.00	\$0.09	\$4,092.39
		0001	0950	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	42,278.00	0.00	42,278.00	LF	42,278.00	\$0.10	\$4,227.80
		0001	0960	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	356.00	0.00	356.00	SQYD	0.00	\$22.33	\$0.00
	Project J	5S3388 - To	tal Value	Posted to D	Date as of Report Generated Date							\$233,785.02
1218-D04 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$5,378,400.11

Revision 4/1/2020 Page 8 of 25



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### $\underline{\textbf{The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.}$

Project: J5S3319

Line Number	Item Code	Description	DWR Date	DWR Approval Date		Units	Location	From Station/ Log Mile	Offset/ Distance	Offset/ Distance	Comments
0290	3105002	GRAVEL (A) OR CRUSHED STONE (B)	12/6/21	12/16/21	126.00	TONS	Routes J/O/UU				
5101	1046001	VALUE ENGINEERING	12/6/21	12/16/21	1.00	LS	Value Engineering				

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 9 of 25



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J5S3232	0020	GRAVEL (A) OR CRUSHED STONE (B) OR	Overrun	Overrun	1	Jul 2, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
		CHAT			1	Jul 2, 2021	SYSTEM	(\$63.76)									
					2	Jul 15, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					2	Jul 15, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.								
					3	Aug 2, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					3	Aug 2, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.								
					4	Aug 16, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					4	Aug 16, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 24 on the current Payment Estimate.								
					5	Sep 2, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					5	Sep 2, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.								
					6	Sep 16, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					6	Sep 16, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
			Ov					7	Oct 4, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
						7	Oct 4, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woods6 overridding Payment Estimate Exception 16 on the current Payment Estimate.							
														Overrun - To	otal		
			Overrun - T	otal				\$0.00									
	0020 -	Total						\$0.00									
	0030	BIT. PAVEMENT MIXTURE	Material		2	Jul 15, 2021	SYSTEM	\$178,469.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
		PG64-22 (BP-1)			2	Jul 15, 2021	SYSTEM	(\$178,469.21)									
					3	Aug 2, 2021	SYSTEM	\$178,469.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					3	Aug 2, 2021	SYSTEM	(\$178,469.21)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
			Other Item Adjustment	ACAD	1	Jul 2, 2021	webers1	\$4,600.60	AC Adjustment for BP1 19-35C 2.9% Virgin AC% 1866.37 Tons								
					1	Jul 2, 2021	webers1	\$2,934.85	AC Adjustment for BP1 21-33 2.8% Virgin AC% 1233.13 Tons includes 0.03 Tons for Rounding to Final Quantity								
				ACAD - Tota	al			\$7,535.45									
			Other Item /	Adjustment -	Total			\$7,535.45									
			Overrun	Overrun	1	Jul 2, 2021	SYSTEM	(\$14,277.04)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL								
					1	Jul 2, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					2	Jul 15, 2021	SYSTEM	(\$14,277.04)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).								
					2	Jul 15,	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment								



Project   Control   Properties   Propertie	_		_							_
PAVACANTE   PROBLEM   Proposed Extraction Automated in confidence of Quantity 2016 Acts	Project	Line	Description		Adjustment				Amount	Remarks
3   Aug 2   SYSTEM   S14,277.04   Averaged Pick Adjustment from the face on an all process, pagement estimates	J5S3232	0030	PAVEMENT MIXTURE	Overrun	Overrun		2021			on the current Payment Estimate. Material Insufficiency Quantity 3099.500;
2021			PG04-22 (BP-1)			3		SYSTEM	(\$14,277.04)	
2021   2021						3		SYSTEM	\$14,277.04	Estimate Item Adjustment (0008) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 3099.500;
2021   2021						4		SYSTEM	(\$14,277.04)	
2021   SYSTEM   \$14,277.04   This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 for the Current Payment Payment Estimate Exception 1 for the Current Payment						4		SYSTEM	\$14,277.04	Estimate Item Adjustment (0014) due to user webers1 overridding Payment
2021   Estimate Item Augustment (0000) put our webers 1 overridding Payment						5		SYSTEM	(\$14,277.04)	
1						5		SYSTEM	\$14,277.04	Estimate Item Adjustment (0006) due to user webers1 overridding Payment
2021   Estimate Item Adjustment (00°5) due to user weberst overridding Payment Estimate.						6		SYSTEM	(\$14,277.04)	
2021   7   2024   5VSTEM   \$14,277.04   This adjustment the original system-generated Overrun Payment Estimate two Adjustment (0015) due to user worded overridding Payment Estimate two Adjustment (0015) due to user worded overridding Payment Estimate Exception 17 on the current Payment Estimate.    Overrun - Total						6		SYSTEM	\$14,277.04	Estimate Item Adjustment (0015) due to user webers1 overridding Payment
2021   Status   Estimate   Esti						7		SYSTEM	(\$14,277.04)	
Overrun - Total   Sum						7		SYSTEM	\$14,277.04	Estimate Item Adjustment (0015) due to user woods6 overridding Payment
Price FUEL   1					Overrun - T	otal			\$0.00	
FUEL   2021   57,306.14				Overrun - T	otal				\$0.00	
1						1		SYSTEM	\$7,306.14	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
SYSTEM   Section 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 4 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 9 o					- Total				\$7,306.14	
BITUMINOUS PAKEMENT MIXTURE PG64-22 (SUR   PAKEMENT MIXTURE PG64-22 (SUR   PAKEMENT MIXTURE PG64-22 (SUR   PG				Price FUEL	- Total				\$7,306.14	
PAVEMENT   MIXTURE   PG64-22 (SUR		0030 -	Total						\$14,841.59	
1		0040	PAVEMENT MIXTURE	Material		1		SYSTEM	\$6,231.39	Estimate Item Adjustment (0006) due to user webers1 overridding Payment
2021   Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			FG04-22 (SUK			1		SYSTEM	(\$6,231.39)	
2021						2		SYSTEM	\$6,231.39	Estimate Item Adjustment (0005) due to user webers1 overridding Payment
Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  3 Aug 2, 2021  4 Aug 16, 2021  5 YSTEM \$6,231.39  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  4 Aug 16, 2021  Total \$0.00  Material - Total \$0.00  Material - Total \$0.00  Other Item Adjustment ACAD 1 Jul 2, 2021 webers1 \$460.58  Other Item Adjustment - Total \$460.58  Other Item Adjustment - Total \$460.58  Overrun Overrun 1 Jul 2, SYSTEM (\$729.56) Reference Item Price Adjustment Index Adjustment Type applied is FUEL						2		SYSTEM	(\$6,231.39)	
4 Aug 16, 2021 \$\frac{1}{2021}\$ \$1						3		SYSTEM	\$6,231.39	Estimate Item Adjustment (0011) due to user webers1 overridding Payment
Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  4 Aug 16, 2021 \$0.00  Material - Total \$0.00  Other Item Adjustment ACAD 1 Jul 2, 2021 \$460.58  Other Item Adjustment - Total \$460.58  Other Item Adjustment - Total \$460.58  Overrun Overrun 1 Jul 2, SYSTEM (\$729.56) Reference Item Price Adjustment Index Adjustment Type applied is FUEL						3		SYSTEM	(\$6,231.39)	
- Total \$0.00    Material - Total \$0.00						4		SYSTEM	\$6,231.39	Estimate Item Adjustment (0016) due to user webers1 overridding Payment
Material - Total  Strain Strai						4		SYSTEM	(\$6,231.39)	
Other Item Adjustment  ACAD 1 Jul 2, 2021 webers1 \$460.58 AC Adjustment for SL21-2 3.3% Virgin AC% 164.2 Tons includes 0.03 Tons for Rounding to final Quantity  ACAD - Total \$460.58  Other Item Adjustment - Total \$460.58  Overrun Overrun 1 Jul 2, SYSTEM (\$729.56) Reference Item Price Adjustment Index Adjustment Type applied is FUEL									\$0.00	
Adjustment 2021 for Rounding to final Quantity  ACAD - Total \$460.58  Other Item Adjustment - Total \$460.58  Overrun Overrun 1 Jul 2, SYSTEM (\$729.56) Reference Item Price Adjustment Index Adjustment Type applied is FUEL				Material - To	otal				\$0.00	
Other Item Adjustment - Total \$460.58  Overrun Overrun 1 Jul 2, SYSTEM (\$729.56) Reference Item Price Adjustment Index Adjustment Type applied is FUEL					ACAD	1		webers1	\$460.58	
Overrun Overrun 1 Jul 2, SYSTEM (\$729.56) Reference Item Price Adjustment Index Adjustment Type applied is FUEL					ACAD - Tota	al			\$460.58	
				Other Item /	Adjustment -	Total			\$460.58	
				Overrun	Overrun	1		SYSTEM	(\$729.56)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
232	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Overrun	Overrun	1	Jul 2, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 3 on the current Payment Estimate. Material Insufficiency Quantity 164.200; Overrun Quantity Balance 18.10.
					2	Jul 15, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					2	Jul 15, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 164.200; Overrun Quantity Balance 18.10.
					3	Aug 2, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					3	Aug 2, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 13 on the current Payment Estimate. Material Insufficiency Quantity 164.200; Overrun Quantity Balance 18.10.
					4	Aug 16, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					4	Aug 16, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception 2 on the current Payment Estimate. Material Insufficiency Quantity 164.200; Overrun Quantity Balance 18.10.
					5	Sep 2, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					5	Sep 2, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					6	Sep 16, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimate of '2.35719' is applied (if non-zero).
					7	Oct 4, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woods6 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				Overrun - To	otal			\$0.00	
			Overrun - T Price FUEL	otai	1	Jul 2, 2021	SYSTEM	<b>\$0.00</b> <b>\$387.05</b>	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			I OLL	- Total		2021		\$387.05	
			Price FUEL	- Total				\$387.05	
	0040 -	Total						\$847.63	
	0130	PREF THERMO PAVMT MARKING, 6 IN	Material		2	Jul 15, 2021	SYSTEM	\$3,292.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		WHITE			2	Jul 15, 2021	SYSTEM	(\$3,292.50)	
					3	Aug 2, 2021	SYSTEM	\$3,292.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Paymen Estimate Exception 6 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$3,292.50)	
					4	Aug 16, 2021	SYSTEM	\$3,292.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user webers1 overridding Paymen Estimate Exception 11 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$3,292.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0130 -							\$0.00	
	0140	PREF THERMO PAVMT	Material		2	Jul 15, 2021	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Paymen Estimate Exception 4 on the current Payment Estimate.

## MoDOT

## Line Item Adjustments by Estimate

ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
232	0140	MARKING, 12 IN WHITE	Material		2	Jul 15, 2021	SYSTEM	(\$930.00)	
					3	Aug 2, 2021	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$930.00)	
					4	Aug 16, 2021	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$930.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0140 -	Total						\$0.00	
	0150	PREF THERMO PVMT MARK, LT/RT ARROW	Material		2	Jul 15, 2021	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		LI/RI ARROW			2	Jul 15, 2021	SYSTEM	(\$350.00)	
					3	Aug 2, 2021	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$350.00)	
					4	Aug 16, 2021	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$350.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0150 -	Total						\$0.00	
	0160	PREF THERMO PVMT MARK, 30" WHT	Material		2	Jul 15, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		MIDBL			2	Jul 15, 2021	SYSTEM	(\$750.00)	
					3	Aug 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$750.00)	
					4	Aug 16, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user webers1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$750.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0160 -	Total						\$0.00	
	0170	4 IN. WHITE WATERBORNE	Other Item Adjustment	REFL	2	Jul 15, 2021	webers1	(\$518.43)	20% Retroreflectivity Adjustment till Testing is Completed
		PAVEMENT MARKING			5	Sep 2, 2021	webers1	\$129.61	5% Bonus for Retroreflectivity results
					5	Sep 2, 2021	webers1	\$518.43	Resolves Item Adjustment from Estimate 0002
				REFL - Tota	ı			\$129.61	
			Other Item	Adjustment -	Total			\$129.61	
	0170 -	Total						\$129.61	
	0180	4 IN. YELLOW	Other Item	REFL	2	Jul 15,	webers1	(\$632.95)	20% Retroreflectivity Adjustment till Testing is Completed
		WATERBORNE	Adjustment			2021			

## MoDOT

## Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J5S3232	0180	PAVEMENT MARKING	Other Item Adjustment	REFL	5	Sep 2, 2021	webers1	\$158.24	5% Bonus for Retroreflectivity results							
					5	Sep 2, 2021	webers1	\$632.95	Resolves Item Adjustment from Estimate 0002							
				REFL - Tota	ıl			\$158.24								
			Other Item	Adjustment -	Total			\$158.24								
	0180 -	· Total						\$158.24								
	0190	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	1	Jul 2, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.							
					1	Jul 2, 2021	SYSTEM	(\$805.62)								
					2	Jul 15, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
					2	Jul 15, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
					3	Aug 2, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
					3	Aug 2, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
					4	Aug 16, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
						4	Aug 16, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user webers1 overridding Payment Estimate Exception 27 on the current Payment Estimate.						
							5	Sep 2, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
					5	Sep 2, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 18 on the current Payment Estimate.							
					6	Sep 16, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
						6	Sep 16, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user webers1 overridding Payment Estimate Exception 16 on the current Payment Estimate.						
									7	Oct 4, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
						7	Oct 4, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woods6 overridding Payment Estimate Exception 19 on the current Payment Estimate.						
				Overrun - T	otal			\$0.00								
			Overrun - T	otal				\$0.00								
	0190 -	· Total						\$0.00								
J5S3232 ·	- Total							\$15,977.07								
J5S3319	0250	FURNISHING ROCK FILL	Material		3	Aug 2, 2021	SYSTEM	\$16,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					3	Aug 2, 2021	SYSTEM	(\$16,540.00)								
				4	4	4	4					4	Aug 16, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$76,040.00)								
										5	Sep 2, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					5	Sep 2, 2021	SYSTEM	(\$76,040.00)								
				6	Sep 16, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								

## MoDOT

## Line Item Adjustments by Estimate

Process   Proc																			
ROCK FILL	Project	Line	Description		Adjustment			Amount	Remarks										
2021	J5S3319	0250		Material		6	SYSTEM	(\$76,040.00)											
2021   8						7	SYSTEM	\$76,040.00	Estimate Item Adjustment (0005) due to user woods6 overridding Payment										
2021   SYSTEM   (\$70,040 00)   2021   570,040 00   2021   570,04						7	SYSTEM	(\$76,040.00)											
2021   9   Nov 2   SYSTEM   S70,040 00   Estimate literal Agustement (DIOS) due to user veibers or veintriding Payment Estimate Exception 1 on the current Payment Estimate.						8	SYSTEM	\$76,040.00	Estimate Item Adjustment (0003) due to user webers1 overridding Payment										
2021   Estimate Item Adjustment (0005) due to user wedners overridding Payment Estimate Exception 1 on the current Payment Estimate Payment Estimate Payment						8	SYSTEM	(\$76,040.00)											
1-701a    1-70						9	SYSTEM	\$76,040.00	Estimate Item Adjustment (0005) due to user webers1 overridding Payment										
National - Total						9	SYSTEM	(\$76,040.00)											
					- Total			\$0.00											
				Material - To	otal			\$0.00											
Add   Aug 2		0250	Total																
AGGREGATE FOR BASE (4																			
3		0270	AGGREGATE FOR BASE (4	Material				\$814.72	Estimate Item Adjustment (0002) due to user webers1 overridding Payment										
2021   Estimate Item Adjustment (0002) due to user weberst overridding Payment Estimate Esterption 2 on the current Payment Estimate.								3	SYSTEM	(\$814.72)									
2021   5   Sep 2, 2021   6   Sep 16, 2021   6   Sep 16, 2021   6   Sep 16, 2021   6   Sep 16, 2021   7-total						4	SYSTEM	\$3,101.43	Estimate Item Adjustment (0002) due to user webers1 overridding Payment										
2021   Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						4	SYSTEM	(\$3,101.43)											
2021   6   Sep 16, SYSTEM   \$3,101.43   This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.						5	SYSTEM	\$3,101.43	Estimate Item Adjustment (0010) due to user webers1 overridding Payment										
2021   Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.									5	SYSTEM	(\$3,101.43)								
Note   Price																6	SYSTEM	\$3,101.43	Estimate Item Adjustment (0005) due to user webers1 overridding Payment
Material - Total  Price FUEL  3 Aug 2, 2021  4 Aug 16, 2021  10 Nov 16, 2021  11 Dec 2, 2021  Price FUEL - Total  Price FUEL - Total  Price FUEL - Total  0300 5 3/4 INCHES, BITUMINOUS PAVEMENT  10 Nov 16, 2021  10 Nov 16, 2021  11 Dec 2, 2021  11 Dec 2, 2021  12 SYSTEM SEGRET STATE										6	SYSTEM	(\$3,101.43)							
Price FUEL   3					- Total			\$0.00											
Price FUEL   3				Material - To	otal			\$0.00											
2021   10 Nov 16, 2021   11 Dec 2, 2021   12 SYSTEM   \$2.01 Reference Item Price Adjustment Index Adjustment Type applied is FUEL   11 Dec 2, 2021   \$10 D				Price	Price	Price	Price		3	SYSTEM		Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
2021  11 Dec 2, 2021  SYSTEM (\$0.03) Reference Item Price Adjustment Index Adjustment Type applied is FUEL  - Total  Price FUEL - Total  \$56.77  Price FUEL - Total  \$56.77   0300 5 3/4 INCHES, BITUMINOUS PAVEMENT  10 Nov 16, 2021  10 Nov 16, 2021  11 Dec 2, SYSTEM (\$184.34)  11 Dec 2, SYSTEM \$184.34  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  11 Dec 2, SYSTEM \$184.34  This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.  11 Dec 2, SYSTEM \$184.34  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate.						4	SYSTEM	\$41.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
- Total  Price FUEL - Total  S56.77   0270 - Total  0300										10	SYSTEM	\$2.01	Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
Price FUEL - Total  \$56.77  0270 - Total  \$56.77  0300						11	SYSTEM	(\$0.03)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
D270 - Total   S56.77					- Total			\$56.77											
Section 2020   Section 2021   Sect				Price FUEL	- Total			\$56.77											
10 Nov 16, 2021   SYSTEM   \$184.34   This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.   10 Nov 16, 2021   SYSTEM   \$184.34   This adjustment (0006) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.   10 Nov 16, 2021   SYSTEM   \$184.34   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.   11 Dec 2, SYSTEM   \$184.34   SYSTEM   \$184.3		0270	Total																
2021  11 Dec 2, 2021  \$184.34 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  11 Dec 2, SYSTEM (\$184.34)			5 3/4 INCHES, BITUMINOUS		aterial	al			10	SYSTEM		Estimate Item Adjustment (0006) due to user webers1 overridding Payment							
Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  11 Dec 2, SYSTEM (\$184.34)						10	SYSTEM	(\$184.34)											
					11	SYSTEM	\$184.34	Estimate Item Adjustment (0004) due to user webers1 overridding Payment											
					11	SYSTEM	(\$184.34)												



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks										
			Туре	Adjustment Type	Number	Date	Ву												
J5S3319	0300	5 3/4 INCHES, BITUMINOUS PAVEMENT	Material		12	Dec 16, 2021	SYSTEM	\$184.34	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hogued1 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					12	Dec 16, 2021	SYSTEM	(\$184.34)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
			Other Item Adjustment	ACAD	10	Nov 16, 2021	webers1	\$14.23	AC Adjustment for SL21-5 VAC 3.3% at 13.3 SQYDs Plans show 1.987 Tons/CY for Surface Leveling 5.75"/36" x 13.3 SQYDs = 2.124 CUYDs x 1.987 = 4.22 Tons										
				ACAD - Tota	al			\$14.23											
			Other Item	Adjustment -	Total			\$14.23											
			Price FUEL		10	Nov 16, 2021	SYSTEM	\$14.10	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
				- Total				\$14.10											
			Price FUEL	- Total				\$14.10											
	0300	- Total						\$28.33											
	0310	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	Material		5	Sep 2, 2021	SYSTEM	\$196,635.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
		PG04-22 (BAS			5	Sep 2, 2021	SYSTEM	(\$196,635.91)											
					6	Sep 16, 2021	SYSTEM	\$10,595.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
					6	Sep 16, 2021	SYSTEM	(\$10,595.91)											
					7	Oct 4, 2021	SYSTEM	\$425,565.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woods6 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					7	Oct 4, 2021	SYSTEM	(\$425,565.10)											
					8	Oct 18, 2021	SYSTEM	\$425,565.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					8	Oct 18, 2021	SYSTEM	(\$425,565.10)											
					9	Nov 2, 2021	SYSTEM	\$666,875.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					9	Nov 2, 2021	SYSTEM	(\$666,875.73)											
										10	Nov 16, 2021	SYSTEM	\$1,178,485.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					10	Nov 16, 2021	SYSTEM	(\$1,178,485.73)											
							11	Dec 2, 2021	SYSTEM	\$1,184,266.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					11	Dec 2, 2021	SYSTEM	(\$1,184,266.92)											
															12	Dec 16, 2021	SYSTEM	\$68,026.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hogued1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$68,026.92)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
			Other Item Adjustment	ACAD	3	Aug 2, 2021	webers1	\$197.88	AC Adjustment for Bit Base used on Pipe Crossings										
					4	Aug 16, 2021	webers1	\$553.26	AC adjustment for 184.13 Tons of asphalt placed between 8/2 to 8/15										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J5S3319	0310	BITUMINOUS PAVEMENT	Other Item Adjustment	ACAD	6	Sep 16, 2021	webers1	\$32,624.56	AC Adjustment for Pay Period on Estimate 0005										
		MIXTURE PG64-22 (BAS			7	Oct 4, 2021	webers1	\$26,855.67	AC Adjustment for 8922.15 Tons of BB21-27 VAC 2.8%										
					9	Nov 2, 2021	webers1	\$14,890.59	AC Adjustment for 5188.36 Tons of BB21-27 at VAC 2.8%										
					11	Dec 2, 2021	webers1	\$328.56	AC Adjustment for 110.44 Tons of BB21-27 at 2.8% VAC placed on 8/26/21										
					11	Dec 2, 2021	webers1	\$41.23	AC Adjustment for 13.86 Tons of BB21-27 at 2.8% VAC placed on 8/13/21										
				ACAD - Tota	al			\$75,491.75											
			Other Item	Adjustment -	Total			\$75,491.75											
			Price FUEL		3	Aug 2, 2021	SYSTEM	\$187.67	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
					4	Aug 16, 2021	SYSTEM	\$495.07	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
					5	Sep 2, 2021	SYSTEM	\$29,485.15	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
					7	Oct 4, 2021	SYSTEM	\$21,323.22	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
					9	Nov 2, 2021	SYSTEM	\$17,395.12	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
					11	Dec 2, 2021	SYSTEM	\$334.21	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
				- Total				\$69,220.44											
			Price FUEL	- Total				\$69,220.44											
	0310 -	Total						\$144,712.19											
	0320	BITUMINOUS PAVEMENT MIXTURE	Material		6	Sep 16, 2021	SYSTEM	\$350,706.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										
		PG64-22 (SUR						6	Sep 16, 2021	SYSTEM	(\$350,706.30)								
					7	Oct 4, 2021	SYSTEM	\$727,265.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
															7	Oct 4, 2021	SYSTEM	(\$727,265.12)	
															8	Oct 18, 2021	SYSTEM	\$969,669.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$969,669.41)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
			Other Item Adjustment	ACAD	6	Sep 16, 2021	webers1	\$19,803.56	AC Adjustment for Pay Period 9/2 to 9/15										
					6	Sep 16, 2021	webers1	\$5,133.64	AC Adjustment for Pay Period on Estimate 0005										
					7	Oct 4, 2021	webers1	\$26,840.31	AC Adjustment for 7565.98 Tons of SL21-5 VAC 3.3%										
					8	Oct 18, 2021	webers1	\$16,474.43	AC Adjustment for 4870.49 Tons of SL21-5 at 3.3% VAC										
					9	Nov 2, 2021	webers1	\$17,761.14	AC Adjustment for 5250.89 Tons of SL21-5 at VAC 3.3%										
					10	Nov 16, 2021	webers1	\$4,004.28	AC Adjustment for 1188.04 SL21-5 VAC 3.3% and AC Adjustment for -4.22 SL21-5 VAC 3.3%										
				ACAD - Tota	al			\$90,017.36											
			Other Item	Adjustment -	Total			\$90,017.36											
		_	Overrun	Overrun	9	Nov 2, 2021	SYSTEM	(\$151,799.54)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
					10	Nov 16,	SYSTEM	(\$62,888.31)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
1500040	0000	DITUMENOUS		Туре		0004			
J5S3319	0320	BITUMINOUS PAVEMENT	Overrun	Overrun - To	otal	2021		(\$214,687.85)	
		MIXTURE PG64-22 (SUR	Overrun - T					(\$214,687.85)	
			Price FUEL		6	Sep 16, 2021	SYSTEM	\$16,844.05	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Oct 4, 2021	SYSTEM	\$18,085.72	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Oct 18, 2021	SYSTEM	\$16,331.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Nov 2, 2021	SYSTEM	\$17,607.28	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Nov 16, 2021	SYSTEM	\$3,969.59	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$72,838.37	
			Price FUEL	- Total				\$72,838.37	
	0320 -	Total						(\$51,832.12)	
	0330	TACK COAT	Material		8	Oct 18, 2021	SYSTEM	\$28,726.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$28,726.65)	
					9	Nov 2, 2021	SYSTEM	\$40,669.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$40,669.95)	
					10	Nov 16, 2021	SYSTEM	\$43,464.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$43,464.10)	
					11	Dec 2, 2021	SYSTEM	\$43,464.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$43,464.10)	
					12	Dec 16, 2021	SYSTEM	\$43,464.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hogued1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$43,464.10)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0330 -	Total						\$0.00	
	0340	CONCRETE PAVEMENT (5 3/4 IN. NON-	Material		4	Aug 16, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		REINF			4	Aug 16, 2021	SYSTEM	(\$1,639.81)	
					5	Sep 2, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$1,639.81)	
					6	Sep 16, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$1,639.81)	
					7	Oct 4, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Oct 4,	SYSTEM	(\$1,639.81)	



:t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
9 (	0340	CONCRETE	Material			2021			
		PAVEMENT (5 3/4 IN. NON- REINF			8	Oct 18, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$1,639.81)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0340 -	Total						\$0.00	
•	0350	WOVEN WIRE FENCE	Material		4	Aug 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$2,200.00)	
					5	Sep 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$2,200.00)	
					6	Sep 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$2,200.00)	
					7	Oct 4, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woods6 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$2,200.00)	
					8	Oct 18, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$2,200.00)	
					9	Nov 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$2,200.00)	
					10	Nov 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$2,200.00)	
					11	Dec 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$2,200.00)	
					12	Dec 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hogued1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$2,200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0350 -	Total						\$0.00	
(	0360	ROCK LINING	NING Material		3	Aug 2, 2021	SYSTEM	\$385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$385.00)	
					4	Aug 16, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3319	0360	ROCK LINING	Material						Estimate Exception 10 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$3,650.00)	
					5	Sep 2, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$3,650.00)	
					6	Sep 16, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$3,650.00)	
					7	Oct 4, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$3,650.00)	
					8	Oct 18, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$3,650.00)	
					9	Nov 2, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$3,650.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0360 -	Total						\$0.00	
	0510	4 IN, WHITE WATERBORNE PAVEMENT MARKING	Material		11	Dec 2, 2021	SYSTEM	\$22,360.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$22,360.50)	
					12	Dec 16, 2021	SYSTEM	\$22,360.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hogued1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$22,360.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	REFL	11	Dec 2, 2021	webers1	(\$4,472.10)	20% Withheld until Retro-reflectivity results
				REFL - Tota	ıl			(\$4,472.10)	
			Other Item	Adjustment -	Total			(\$4,472.10)	
	0510 -	Total						(\$4,472.10)	
	0520	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		11	Dec 2, 2021	SYSTEM	\$22,549.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$22,549.10)	
					12	Dec 16, 2021	SYSTEM	\$22,549.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hogued1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$22,549.10)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	REFL	11	Dec 2, 2021	webers1	(\$4,509.82)	20% Withheld until Retro-reflectivity results



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J5S3319	0520	4 IN. YELLOW WATERBORNE PAVEMENT	Other Item Adjustment	REFL - Tota	1			(\$4,509.82)					
		MARKING	Other Item	Adjustment -	Total			(\$4,509.82)					
	0520	· Total						(\$4,509.82)					
	0590	CLASS B-1 CONCRETE (CULVERTS)	Material		4	Aug 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					4	Aug 16, 2021	SYSTEM	(\$15,000.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0590	· Total						\$0.00					
	0600	REINFORCING STEEL (CULVERTS)	Material		4	Aug 16, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					4	Aug 16, 2021	SYSTEM	(\$5,550.00)					
					5	Sep 2, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
					5	Sep 2, 2021	SYSTEM	(\$5,550.00)					
					6	Sep 16, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
						6	Sep 16, 2021	SYSTEM	(\$5,550.00)				
					7	Oct 4, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woods6 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
									7	Oct 4, 2021	SYSTEM	(\$5,550.00)	
							8	Oct 18, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.		
					8	Oct 18, 2021	SYSTEM	(\$5,550.00)					
							9	Nov 2, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.		
					9	Nov 2, 2021	SYSTEM	(\$5,550.00)					
				- Total				\$0.00					
			Material - To	- Total				\$0.00					
	0600	· Total						\$0.00					
	0770	SEEDING - COOL SEASON	Material		7	Oct 4, 2021	SYSTEM	\$19,162.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woods6 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
		MIXTURES			7	Oct 4, 2021	SYSTEM	(\$19,162.50)					
					8	Oct 18, 2021	SYSTEM	\$30,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					8	Oct 18, 2021	SYSTEM	(\$30,660.00)					
					9	Nov 2, 2021	SYSTEM	\$41,632.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.				
					9	Nov 2, 2021	SYSTEM	(\$41,632.50)					
					10	Nov 16, 2021	SYSTEM	\$48,597.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 14 on the current Payment Estimate.				



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
,		'	Type	Adjustment Type	Number	Date	Ву		
J5S3319	0770	SEEDING - COOL	Material	, ,	10	Nov 16, 2021	SYSTEM	(\$48,597.50)	
		SEASON MIXTURES		- Total				\$0.00	
			Material - To	otal				\$0.00	
	0770 -	Total						\$0.00	
	0780	SEDIMENT TRAP ROCK	Material		4	Aug 16, 2021	SYSTEM	\$6,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$6,390.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0780 -	Total						\$0.00	
	0790	ROCK DITCH CHECK	Material		3	Aug 2, 2021	SYSTEM	\$520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$520.00)	
					4	Aug 16, 2021	SYSTEM	\$14,072.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$14,072.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0790 -	Total						\$0.00	
	0800	ALTERNATE DITCH CHECK	Material		4	Aug 16, 2021	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$2,040.00)	
					5	Sep 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$15,000.00)	
				- Total			\$0.00		
			Material - To	otal				\$0.00	
			Overrun	Overrun	5	Sep 2, 2021	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 2500.000; Overrun Quantity Balance 2030.00.
					5	Sep 2, 2021	SYSTEM	(\$12,180.00)	
					6	Sep 16, 2021	SYSTEM	(\$12,180.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Sep 16, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$4,800.00)	
					7	Oct 4, 2021	SYSTEM	(\$16,980.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Oct 4, 2021	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	\$16,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woods6 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Oct 4,	SYSTEM	(\$8,220.00)	



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J5S3319	0800	ALTERNATE	Overrun	Type Overrun		2021			
3333319		DITCH CHECK	Overruit	Overrun - To	otal	2021		\$0.00	
			Overrun - T					\$0.00	
	0800 -	Total						\$0.00	
	0820	SILT FENCE	Material		5	Sep 2, 2021	SYSTEM	\$450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$450.00)	
					6	Sep 16, 2021	SYSTEM	\$607.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$607.50)	
					7	Oct 4, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woods6 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$922.50)	
					8	Oct 18, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$922.50)	
					9	Nov 2, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$922.50)	
					10	Nov 16, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$922.50)	
					11	Dec 2, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$922.50)	
					12	Dec 16, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hogued1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$922.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0820 -	Total						\$0.00	
J5S3319 -	<b>Total</b> 0840	GRAVEL (A)	Overrun	Overrun	10	Nov 16,	SYSTEM	\$83,983.25 (\$616.61)	
		OR CRUSHED STONE (B) OR CHAT		Overrun - T	otal	2021		(\$616.61)	
		CHAI	Overrun - T					(\$616.61)	
	0840 -	Total						(\$616.61)	
	0850	BITUMINOUS PAVEMENT MIXTURE	Material		8	Oct 18, 2021	SYSTEM	\$95,370.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		PG64-22 (SUR			8	Oct 18, 2021	SYSTEM	(\$95,370.88)	
					9	Nov 2, 2021	SYSTEM	\$198,261.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$198,261.52)	



ct L	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
388 085	0850	BITUMINOUS PAVEMENT MIXTURE	Material		10	Nov 16, 2021	SYSTEM	\$198,261.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		PG64-22 (SUR			10	Nov 16, 2021	SYSTEM	(\$198,261.52)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	8	Oct 18, 2021	webers1	\$6,150.47	AC Adjustment for 1818.32 Tons of SL21-5 at 3.3% VAC
					9	Nov 2, 2021	webers1	\$6,635.42	AC Adjustment for 1961.69 Tons of SL21-5 at VAC 3.3%
				ACAD - Tota	al			\$12,785.89	
			Other Item	Adjustment -	Total			\$12,785.89	
			Price FUEL		8	Oct 18, 2021	SYSTEM	\$6,097.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Nov 2, 2021	SYSTEM	\$6,577.94	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$12,675.13	
			Price FUEL	- Total				\$12,675.13	
0	0850 -	Total						\$25,461.02	
0	0860	TACK COAT	Material		8	Oct 18, 2021	SYSTEM	\$3,113.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$3,113.95)	
					9	Nov 2, 2021	SYSTEM	\$8,064.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$8,064.70)	
					10	Nov 16, 2021	SYSTEM	\$8,064.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$8,064.70)	
					11	Dec 2, 2021	SYSTEM	\$8,064.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$8,064.70)	
					12	Dec 16, 2021	SYSTEM	\$8,064.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hogued1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$8,064.70)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
0	0860 -	Total						\$0.00	
0	0940	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		10	Nov 16, 2021	SYSTEM	\$4,092.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$4,092.39)	
					11	Dec 2, 2021	SYSTEM	\$4,092.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					11	Dec 2,	SYSTEM	(\$4,092.39)	
						2021			
					12	2021 Dec 16, 2021	SYSTEM	\$4,092.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hogued1 overridding Payment Estimate Exception 11 on the current Payment Estimate.





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J5S3388	0940	4 IN. WHITE	Material	- Total				\$0.00				
		WATERBORNE PAVEMENT	Material - To	otal				\$0.00				
		MARKING	Other Item Adjustment	REFL	10	Nov 16, 2021	webers1	(\$818.48)	20% withheld until Retro-reflectivity results			
				REFL - Tota	ıl			(\$818.48)				
			Other Item	Adjustment -	Total			(\$818.48)				
	0940 -	Total						(\$818.48)				
	0950	4 IN. YELLOW WATERBORNE PAVEMENT	Material		10	Nov 16, 2021	SYSTEM	\$4,227.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
		MARKING			10	Nov 16, 2021	SYSTEM	(\$4,227.80)				
					11	Dec 2, 2021	SYSTEM	\$4,227.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
					11	Dec 2, 2021	SYSTEM	(\$4,227.80)				
										12	Dec 16, 2021	SYSTEM
					12	Dec 16, 2021	SYSTEM	(\$4,227.80)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
			Other Item Adjustment	REFL	10	Nov 16, 2021	webers1	(\$845.56)	20% withheld until Retro-reflectivity results			
				REFL - Tota	ıl			(\$845.56)				
			Other Item	Adjustment -	Total			(\$845.56)				
	0950 -	Total						(\$845.56)				
J5S3388 -	- Total							\$23,180.37				
Overall -	Total							\$123,140.69				