

Pay Estimate Created Date: November 2, 2021

Progress	Estimate Number	Contract ID	201218-D04		Pay Period Start	October 16, 202	1 Original Contract Amou	nt \$5,685,901.14
9			Capital Paving & Cor LLC	nstruction,	Pay Period End	November 1, 2021	Net Change Order Amount Current Contract Amou	(\$41,737.27) nt \$5,644,163.87
Approval Date								By User
November 2, 2021			Generated and /	Approved (and should be consi	dered Draft) at th	ne Project Office Level by	webers1
November 3, 2021			Reviewed and Appro	oved (and s	hould be considered	d Draft) at the Re	sident Engineer Level by	oeschd1
November 4, 2021				Reviewed a	and Approved at the	Central Office C	ontrollers Office Level by	ramses1
Original Comple	etion Date	Current C	ompletion Date	npletion Date Actual Completion Date			f Current Contract Amoun	t Complete
November 1	2021	Noven	er 1, 2021				88.44%	
	Cont	ract Informational	ates		Milesto	nes		
Date Description	n Origi	nal Completion Dat	e Current Comple	tion Date	No Milestones Exi	st for Contract		
Acceptance Date								
Awarded Date	Janua	ary 6, 2021	January 6, 2021					
Letting Date	Dece	mber 18, 2020	December 18, 20	20				
Notice to Proceed D	ate Marc	h 8, 2021	March 8, 2021					
Work Began Date								

Contract Total Pay For Estimate No. 9				
	This Estimate	Previous	To Date	
201218-D04				
Total Posted Items Pay	\$737,251.07	\$4,254,241.12	\$4,991,492.19	
Gross Item Adjustments	(\$70,932.05)	\$259,515.44	\$188,583.39	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		<mark>\$4,513,756.56</mark>	\$5,180,075.58	
Contract Total Payable This Estimate:	\$666,319.02			

Contract Total Payable This Estimate:

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J5S3319	0240	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	STA	\$465.090	134.59	\$62,596.46	
	0310	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	TONS	\$46.510	5,188.36	\$241,310.62	
	0320	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$49.770	5,250.89	\$261,336.80	
	0330	4071005	TACK COAT	GAL	\$2.050	5,826	\$11,943.30	
	0770	8051000A	SEEDING - COOL SEASON MIXTURES	ACRE	\$1,750.000	6.27	\$10,972.50	
	0830	9039901	MISC.ADJUST EXISTING SIGNS	LS	\$165,000.000	0.25	\$41,250.00	
Project J5S	319 - Total						\$629,409.68	
J5S3388	0850	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$52.450	1,961.69	\$102,890.64	
	0860	4071005	TACK COAT	GAL	\$2.050	2,415	\$4,950.75	
Project J5S	388 - Total						\$107,841.39	
Overall - Total								

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

	rajaon	literite into Estimato						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3319	0250	FURNISHING ROCK FILL	Material			-1,901	\$40.00	(\$76,040.00)
	0250	FURNISHING ROCK FILL	Material		This adjustment offsets the original system-	1,901	\$40.00	\$76,040.00

Pay Estimate Created Date: November 2, 2021

	Progre 9	ess Estimate Number	Contract ID Prime Contractor	201218-D(Capital Pa LLC)4 ving & Constr	Pay Period End 2021	Original Contr Net Change O Amount Current Contra	rder	(\$41,737.27)
Project Number	Line No.	Item De	escription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
5S3319						generated Material Payment Estimate Item Adjustment (0005) due to user webers overridding Payment Estimate Exception 1 or the current Payment Estimate	1		
	0310		US PAVEMENT 9G64-22 (BASE)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL		\$3.35	\$17,395.12
	0310		US PAVEMENT 9G64-22 (BASE)	Material			-14,338.33	\$46.51	(\$666,875.73
	0310		US PAVEMENT 9G64-22 (BASE)	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0002) due to user webers overridding Payment Estimate Exception 2 or the current Payment Estimate		\$46.51	\$666,875.73
	0310		US PAVEMENT 2G64-22 (BASE)	Other Item Adjustment	Asphalt Cement Price Adjustment	AC Adjustment for 5188.36 Tons of BB21-27 at VAC 2.8%			\$14,890.59
	0320	MIX	US PAVEMENT TURE PG64-22 ACE LEVELING)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL		\$3.35	\$17,607.28
	0320	MIX	US PAVEMENT TURE PG64-22 ACE LEVELING)	Overrun		Reference Item Price Adjustment Index Adjustment Type applied is FUEL		\$53.12	(\$151,799.54
	0320	BITUMINO	US PAVEMENT TURE PG64-22 ACE LEVELING)	Other Item Adjustment	Asphalt Cement Price Adjustment	AC Adjustment for 5250.89 Tons of SL21-5 a VAC 3.3%			\$17,761.14
	0330		TACK COAT	Material			-19,839	\$2.05	(\$40,669.95
	0330		TACK COAT	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0006) due to user webers overridding Payment Estimate Exception 4 or the current Payment Estimate	1	\$2.05	\$40,669.95
	0350	WOVE	N WIRE FENCE	Material			-88	\$25.00	(\$2,200.00
	0350	WOVE	N WIRE FENCE	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0007) due to user webers overridding Payment Estimate Exception 8 or the current Payment Estimate	1	\$25.00	\$2,200.00
	0360		ROCK LINING	Material			-73	\$50.00	(\$3,650.00
	0360		ROCK LINING	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0008) due to user webers overridding Payment Estimate Exception 9 or the current Payment Estimate	1	\$50.00	\$3,650.00
	0600	REINFO	ORCING STEEL (CULVERTS)	Material			-3,700	\$1.50	(\$5,550.00
	0600	REINFO	ORCING STEEL (CULVERTS)	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0009) due to user webers overridding Payment Estimate Exception 10 on the current Payment Estimate) 	\$1.50	\$5,550.00
	0770	SEEDING -	COOL SEASON MIXTURES	Material			-23.79	\$1,750.00	(\$41,632.50
	0770	SEEDING -	COOL SEASON MIXTURES	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0010) due to user webers1	1	\$1,750.00	\$41,632.50



Pay Estimate Created Date: November 2, 2021

	Progre 9	ss Estimate Number	Contract ID Prime Contractor	201218-D0 Capital Pa LLC)4 ving & Constr	S	Pay Period Start Pay Period Enc	October 16, 2021 November 1, 2021	Original Contr Net Change O Amount Current Contr	rder	(\$41,737.27)
Project Number	Line No.	Item De	escription	Adjustment Type	Other Item Adjustment Type				Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3319						overridd		stimate Exception [,] t Payment Estimat			
	0820		SILT FENCE	Material					-615	\$1.50	(\$922.50)
	0820		SILT FENCE	Material		genera Adju	ted Material Pa Istment (0011) Ing Payment Es	the original syster yment Estimate Ite due to user webers stimate Exception t Payment Estimat	m s1 I7	\$1.50	\$922.50
	0850	MIX	US PAVEMENT (TURE PG64-22 ACE LEVELING)	Price		Ref		ce Adjustment Inde ype applied is FUE		\$3.35	\$6,577.94
	0850	MIX	US PAVEMENT TURE PG64-22 ACE LEVELING)	Material					-3,780.01	\$52.45	(\$198,261.52)
	0850	MIX	US PAVEMENT TURE PG64-22 ACE LEVELING)	Material		genera Adju	ted Material Pa Istment (0013) g Payment Esti	the original syster yment Estimate Ite due to user webers mate Exception 3 of t Payment Estimat	m s1 on	\$52.45	\$198,261.52
	0850	MIX	US PAVEMENT TURE PG64-22 ACE LEVELING)	Other Item Adjustment	Asphalt Cement Price Adjustment	AC Adjust	ment for 1961.6	9 Tons of SL21-5 VAC 3.3			\$6,635.42
	0860		TACK COAT	Material					-3,934	\$2.05	(\$8,064.70)
	0860		TACK COAT	Material		genera Adju	ted Material Pa Istment (0014) g Payment Esti	the original system yment Estimate Ite due to user webers mate Exception 6 of t Payment Estimat	m s1 on	\$2.05	\$8,064.70
Total				·							(\$70,932.05



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J5S3232	FAS S401(47)	Resurface	B/M/ 124	BOONE	from west of Rte. 63 to Rte. DD and Rte. B and Rte. 124 in Hallsville
J5S3319	FAS S402(6)	Resurface and shoulder improvements	J/O/ UU	BOONE	from Rte. 124 to Rte. O, Rte. J to the end of state maintenance, and Rte. O to I-70 eastbound ramp
J5S3388	FAS- S402(060)	Pavement improvements	A	BOONE	from Rte. 63 to the end of state maintenance in Hartsburg

Totals by Job Numbers

J5S3232 This Estimate Previous To Date Posted Item Pay \$0.00 \$291,363.84 \$291,363.84 Gross Item Adjustments \$0.00 \$15,977.07 \$15,977.07 Gross Item Pay \$0.00 \$307,340.91 \$307,340.91
Posted Item Pay \$0.00 \$291,363.84 \$291,363.84 Gross Item Adjustments \$0.00 \$15,977.07 \$15,977.07
Gross Item Adjustments \$0.00 \$15,977.07 \$15,977.07
Incentive \$0.00 \$0.00 \$0.00
Disincentive \$0.00 \$0.00 \$0.00
Liquidated Damages \$0.00 \$0.00 \$0.00
Other Contract Adjustments \$0.00 \$0.00 \$0.00
J5S3319 This Estimate Previous To Date
Posted Item Pay \$629,409.68 \$3,862,918.52 \$4,492,328.20
Gross Item Adjustments (\$84,145.41) \$231,290.71 \$147,145.30
Gross Item Pay \$545,264.27 \$4,094,209.23 \$4,639,473.50
Incentive \$0.00 \$0.00 \$0.00
Disincentive \$0.00 \$0.00 \$0.00
Liguidated Damages \$0.00 \$0.00 \$0.00
Other Contract Adjustments \$0.00 \$0.00 \$0.00
J5S3388 This Estimate Previous To Date
Posted Item Pay \$107,841.39 \$99,958.76 \$207,800.15
Gross Item Adjustments \$13,213.36 \$12,247.66 \$25,461.02
Gross Item Pay \$121,054.75 \$112,206.42 \$233,261.17
Incentive \$0.00 \$0.00 \$0.00
Disincentive \$0.00 \$0.00 \$0.00
Liquidated Damages \$0.00 \$0.00 \$0.00
Other Contract Adjustments \$0.00 \$0.00 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Ferror			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 2142000, Project Item Line Number 0250, Material Set 214200096, Material 0214STRF - Stone for Rock Fill, Acceptance Action Generic 0214STRF is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4013000, Project Item Line Number 0310, Material Set 401300096, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 4020520, Project Item Line Number 0850, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4071005, Project Item Line Number 0330, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 4071005, Project Item Line Number 0330, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 4071005, Project Item Line Number 0860, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3388, Item 4071005, Project Item Line Number 0860, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6072010, Project Item Line Number 0350, Material Set 607201096, Material 1043FMWWFB - Woven Wire Fence Fabric, Acceptance Action Generic 1043FMWWFB is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 6097000, Project Item Line Number 0360, Material Set 609700096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 7061030, Project Item Line Number 0600, Material Set 706103096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 7061030, Project Item Line Number 0600, Material Set 706103096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 7061030, Project Item Line Number 0600, Material Set 706103096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 8051000A, Project Item Line Number 0770, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 8051000A, Project Item Line Number 0770, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 8051000A, Project Item Line Number 0770, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 8051000A, Project Item Line Number 0770, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3319, Item 8061019, Project Item Line Number 0820, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient.	Working with Materials and Contractor to resolve	webers1	Overridden
Estimate Exception Type: Item Overrun: Contract 201218-D04, Contract Project J5S3319, Project Item Line Number 0320, Contract Line Item Number 0320, Item 4020520, Minor Item.	Working on Change Order	webers1	Acknowledged



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted C	uantities	and valu	es are c	ased on R	eport Generated date and can differ from the posted amo	uni ai ine i	ime me Est	inate was	Jenerale	ea.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-D04	J5S3232	0001	0010	2152000A	SHAPING SLOPES, CLASS II	206.00	0.00	206.00	100F	206.00	\$67.73	\$13,952.38
		0001	0020	3107002	GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)	16.00	4.00	20.00	TONS	20.00	\$15.94	\$318.80
		0001	0030	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	2,861.30	238.20	3,099.50	TONS	3,099.50	\$57.58	\$178,469.21
		0001	0040	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	146.10	18.10	164.20	TONS	164.20	\$37.95	\$6,231.39
		0001	0050	4079912	MISC.Low-Tracking or Non Tracking Tack Coat	3,116.00	-16.00	3,100.00	GAL	3,100.00	\$2.35	\$7,285.00
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
		0001	0070	6161005	CONSTRUCTION SIGNS	1,767.00	0.00	1,767.00	SQFT	658.00	\$8.00	\$5,264.00
		0001	0080	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$25.00	\$0.00
		0001	0090	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$25.00	\$0.00
		0001	0100	6161024	CHANNELIZER (TRIM LINE) WITH LIGHT	421.00	0.00	421.00	EA	0.00	\$20.00	\$0.00
		0001	0110	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$2,000.00	\$8,000.00
		0001	0120	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$8,039.92	\$8,039.92
		0001	0130	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	878.00	0.00	878.00	LF	878.00	\$3.75	\$3,292.50
		0001	0140	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE	124.00	0.00	124.00	LF	124.00	\$7.50	\$930.00
		0001	0150	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	1.00	\$350.00	\$350.00
		0001	0160	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	20.00	0.00	20.00	EA	10.00	\$75.00	\$750.00
		0001	0170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	4,713.00	0.00	4,713.00	LF	4,713.00	\$0.55	\$2,592.15
		0001	0180	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	12,659.00	0.00	12,659.00	LF	12,659.00	\$0.25	\$3,164.75
		0001	0190	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	29,838.00	463.00	30,301.00	SQYD	30,301.00	\$1.74	\$52,723.74
	Project J	5S3232 - To	otal Value	Posted to D	Date as of Report Generated Date							\$291,363.84
	J5S3319	0001	0200	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$115,000.00	\$115,000.00
		0001	0210	2063000	CLASS 3 EXCAVATION	865.00	0.00	865.00	CUYD	865.00	\$55.00	\$47,575.00
		0001	0220	2063300	CLASS 4 EXCAVATION	20.00	0.00	20.00	CUYD	20.00	\$10.00	\$200.00
		0001	0230	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0001	0240	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	2,395.90	0.00	2,395.90	STA	2,309.57	\$465.09	\$1,074,157.91
		0001	0250	2142000	FURNISHING ROCK FILL	2,828.00	0.00	2,828.00	CUYD	1,901.00	\$40.00	\$76,040.00
		0001	0260	2143000								
		0001			PLACING ROCK FILL	2,828.00	0.00	2,828.00	CUYD	1,901.00	\$25.00	\$47,525.00
			0270	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)		0.00	2,828.00 29,287.00	SQYD	1,901.00 462.90	\$25.00 \$6.70	\$47,525.00
		0001	0280	3040143 3049905	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK)	2,828.00 29,287.00 214.00	0.00	29,287.00 214.00	SQYD SQYD	462.90	\$6.70 \$1.50	\$3,101.43 \$0.00
		0001		3040143 3049905 3105002	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B)	2,828.00 29,287.00	0.00	29,287.00	SQYD SQYD TONS	462.90	\$6.70	\$3,101.43 \$0.00 \$0.00
			0280	3040143 3049905 3105002 4010105	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT	2,828.00 29,287.00 214.00 210.00 31.10	0.00	29,287.00 214.00 210.00 31.10	SQYD SQYD TONS SQYD	462.90 0.00 0.00 0.00	\$6.70 \$1.50	\$3,101.43 \$0.00 \$0.00 \$0.00
		0001	0280 0290	3040143 3049905 3105002 4010105 4013000	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	2,828.00 29,287.00 214.00 210.00	0.00 0.00 0.00	29,287.00 214.00 210.00	SQYD SQYD TONS	462.90 0.00 0.00	\$6.70 \$1.50 \$40.00	\$3,101.43 \$0.00 \$0.00
		0001	0280 0290 0300	3040143 3049905 3105002 4010105	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT	2,828.00 29,287.00 214.00 210.00 31.10	0.00 0.00 0.00 0.00	29,287.00 214.00 210.00 31.10	SQYD SQYD TONS SQYD	462.90 0.00 0.00 0.00	\$6.70 \$1.50 \$40.00 \$13.86	\$3,101.43 \$0.00 \$0.00 \$0.00
		0001 0001 0001	0280 0290 0300 0310	3040143 3049905 3105002 4010105 4013000	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	2,828.00 29,287.00 214.00 210.00 31.10 29,342.00	0.00 0.00 0.00 0.00 0.00	29,287.00 214.00 210.00 31.10 29,342.00	SQYD SQYD TONS SQYD TONS	462.90 0.00 0.00 0.00 25,338.33	\$6.70 \$1.50 \$40.00 \$13.86 \$46.51	\$3,101.43 \$0.00 \$0.00 \$0.00 \$1,178,485.73
		0001 0001 0001 0001	0280 0290 0300 0310 0320	3040143 3049905 3105002 4010105 4013000 4020520	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40	0.00 0.00 0.00 0.00 0.00	29,287.00 214.00 210.00 31.10 29,342.00 21,876.40	SQYD SQYD TONS SQYD TONS TONS	462.90 0.00 0.00 25,338.33 24,733.90	\$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77	\$3,101.43 \$0.00 \$0.00 \$0.00 \$1,178,485.73 \$1,231,006.20
		0001 0001 0001 0001 0001	0280 0290 0300 0310 0320 0330	3040143 3049905 3105002 4010105 4013000 4020520 4071005	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT.	2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00	0.00 0.00 0.00 0.00 0.00 0.00	29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00	SQYD SQYD TONS SQYD TONS TONS GAL	462.90 0.00 0.00 25,338.33 24,733.90 19,839.00	\$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05	\$3,101.43 \$0.00 \$0.00 \$1,178,485.73 \$1,231,006.20 \$40,669.95
		0001 0001 0001 0001 0001 0001	0280 0290 0300 0310 0320 0330 0340	3040143 3049905 3105002 4010105 4013000 4020520 4071005 5021305	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS)	2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80	0.00 0.00 0.00 0.00 0.00 0.00	29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80	SQYD SQYD TONS SQYD TONS TONS GAL SQYD	462.90 0.00 0.00 25,338.33 24,733.90 19,839.00 41.80	\$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23	\$3,101.43 \$0.00 \$0.00 \$1,178,485.73 \$1,231,006.20 \$40,669.95 \$1,639.81
		0001 0001 0001 0001 0001 0001	0280 0290 0300 0310 0320 0330 0340	3040143 3049905 3105002 4010105 4013000 4020520 4071005 5021305 6072010	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS) WOVEN WIRE FENCE	2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00	SQYD SQYD TONS SQYD TONS GAL SQYD LF	462.90 0.00 25,338.33 24,733.90 19,839.00 41.80 88.00	\$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00	\$3,101.43 \$0.00 \$0.00 \$1,178,485.73 \$1,231,006.20 \$40,669.95 \$1,639.81 \$2,200.00
		0001 0001 0001 0001 0001 0001 0001	0280 0290 0300 0310 0320 0330 0340 0350 0360	3040143 3049905 3105002 4010105 4013000 4020520 4071005 5021305 6072010 6097000	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS) WOVEN WIRE FENCE ROCK LINING	2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00	SQYD SQYD TONS SQYD TONS GAL SQYD LF CUYD	462.90 0.00 25,338.33 24,733.90 19,839.00 41.80 88.00 73.00	\$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$39.23 \$25.00 \$50.00	\$3,101.43 \$0.00 \$0.00 \$1,178,485.73 \$1,231,006.20 \$40,669.95 \$1,639.81 \$2,200.00 \$3,650.00
		0001 0001 0001 0001 0001 0001 0001 000	0280 0290 0300 0310 0320 0330 0340 0350 0360	3040143 3049905 3105002 4010105 4013000 4020520 4020520 4071005 6021305 6072010 6097000 6113010	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS) WOVEN WIRE FENCE ROCK LINING FURNISHING TYPE 1 ROCK BLANKET	2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00 121.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00 121.00	SQYD SQYD TONS SQYD TONS GAL SQYD LF CUYD	462.90 0.00 0.00 25,338.33 24,733.90 19,839.00 41.80 88.00 73.00 0.00	\$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00 \$25.00	\$3,101.43 \$0.00 \$0.00 \$1,178,485.73 \$1,231,006.20 \$40,669.95 \$1,639.81 \$2,200.00 \$3,650.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001 000	0280 0290 0300 0310 0320 0330 0340 0350 0360 0360 0360	3040143 3049905 3105002 4010105 4013000 4020520 4071005 5021305 6072010 6097000 6113010 6113030	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS) WOVEN WIRE FENCE ROCK LINING FURNISHING TYPE 1 ROCK BLANKET PLACING TYPE 1 ROCK BLANKET	2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00 121.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00 121.00	SQYD SQYD TONS SQYD TONS GAL SQYD LF CUYD CUYD	462.90 0.00 25,338.33 24,733.90 19,839.00 41.80 88.00 73.00 0.00	\$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00 \$25.00 \$25.00	\$3,101.43 \$0.00 \$0.00 \$1,178,485.73 \$1,231,006.20 \$40,669.95 \$1,639.81 \$2,200.00 \$3,650.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001 000	0280 0290 0300 0310 0320 0330 0340 0350 0360 0360 0370 0380	3040143 3049905 3105002 4010105 4013000 4020520 4071005 5021305 6072010 6097000 6113010 6113030 6123000A	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS) WOVEN WIRE FENCE ROCK LINING FURNISHING TYPE 1 ROCK BLANKET PLACING TYPE 1 ROCK BLANKET TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00 121.00 121.00 2.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00 121.00 121.00 2.00	SQYD SQYD TONS SQYD TONS GAL SQYD LF CUYD CUYD CUYD CUYD	462.90 0.00 25,338.33 24,733.90 19,839.00 41.80 88.00 73.00 0.00 0.00	\$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$49.77 \$2.05 \$39.23 \$25.00 \$50.00 \$25.00 \$25.00 \$25.00	\$3,101.43 \$0.00 \$0.00 \$1,178,485.73 \$1,231,006.20 \$40,669.95 \$1,639.81 \$2,200.00 \$3,650.00 \$3,650.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001 000	0280 0290 0300 0310 0320 0330 0340 0350 0360 0360 0360 0380 0380	3040143 3049905 3105002 4010105 4013000 4020520 4071005 5021305 6072010 6097000 6113010 6113030 6123000A 6161005	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) MISC.TYPE 1 AGGREGATE FOR BASE (1 IN. THICK) GRAVEL (A) OR CRUSHED STONE (B) 5 3/4 INCHES, BITUMINOUS PAVEMENT BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT CONCRETE PAVEMENT (5 3/4 IN. NON-REINFORCED, 15 FT. JOINTS) WOVEN WIRE FENCE ROCK LINING FURNISHING TYPE 1 ROCK BLANKET PLACING TYPE 1 ROCK BLANKET TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS	2,828.00 29,287.00 214.00 210.00 31.10 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00 121.00 121.00 121.00 1,993.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	29,287.00 214.00 210.00 29,342.00 21,876.40 23,405.00 41.80 184.00 73.00 121.00 121.00 1,993.00	SQYD SQYD TONS SQYD TONS GAL SQYD CUYD CUYD CUYD CUYD EA SQFT	462.90 0.00 25,338.33 24,733.90 19,839.00 41.80 88.00 73.00 0.00 0.00 0.00	\$6.70 \$1.50 \$40.00 \$13.86 \$46.51 \$2.05 \$39.23 \$25.00 \$50.00 \$25.00 \$25.00 \$25.00 \$25.00 \$25.00 \$25.00	\$3,101.43 \$0.00 \$0.00 \$1,178,485.73 \$1,231,006.20 \$40,669.95 \$1,639.81 \$2,200.00 \$3,650.00 \$0.00 \$0.00 \$0.00 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at the t	ime the Es	timate was (Generate	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-D04	J5S3319	0001	0440	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$20.00	\$0.00
		0001	0450	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	6.00	0.00	6.00	EA	4.00	\$155.00	\$620.00
		0001	0460	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0470	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.00
		0001	0480	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$330,616.16	\$330,616.16
		0001	0490	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	6.00	0.00	6.00	EA	0.00	\$600.00	\$0.00
		0001	0500	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	42.00	0.00	42.00	LF	0.00	\$35.00	\$0.00
		0001	0510	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	248,450.00	0.00	248,450.00	LF	0.00	\$0.09	\$0.00
		0001	0520	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	225,491.00	0.00	225,491.00	LF	0.00	\$0.10	\$0.00
		0001	0530	6208064A	TEMPORARY RAISED PAVEMENT MARKER	125.00	0.00	125.00	EA	0.00	\$0.00	\$0.00
		0001	0540	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,511.00	0.00	1,511.00	SQYD	0.00	\$6.06	\$0.00
		0001	0550	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	5,120.00	0.00	5,120.00	SQYD	0.00	\$4.57	\$0.00
		0001	0560	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,639.90	0.00	2,639.90	STA	0.00	\$10.00	\$0.00
		0001	0570	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	1,200.50	0.00	1,200.50	STA	0.00	\$10.00	\$0.00
		0001	0580	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$8,945.72	\$0.00
		0001	0590	7034041	CLASS B-1 CONCRETE (CULVERTS)	15.00	0.00	15.00	CUYD	15.00	\$1,000.00	\$15,000.00
		0001	0600	7061030	REINFORCING STEEL (CULVERTS)	3,700.00	0.00	3,700.00	LB	3,700.00	\$1.50	\$5,550.00
		0001	0610	7250315A	15 IN. PIPE GROUP B	52.00	0.00	52.00	LF	52.00	\$50.00	\$2,600.00
		0001	0620	7250318A	18 IN. PIPE GROUP B	256.00	0.00	256.00	LF	256.00	\$70.00	\$17,920.00
		0001	0630	7250324A	24 IN. PIPE GROUP B	42.00	0.00	42.00	LF	42.00	\$80.00	\$3,360.00
		0001	0640	7250330A	30 IN. PIPE GROUP B	42.00	0.00	42.00	LF	42.00	\$100.00	\$4,200.00
		0001	0650	7250336A	36 IN. PIPE GROUP B	88.00	0.00	88.00	LF	88.00	\$110.00	\$9,680.00
				0001 0660 7250342A 0001 0670 7250348A	42 IN. PIPE GROUP B	108.00	0.00	108.00	LF	108.00	\$130.00	\$14,040.00
					7250348A	48 IN. PIPE GROUP B	92.00	0.00	92.00	LF	92.00	\$150.00
		0001 0680 7	1 0680 7250415	001 0680 7250415 15 IN. PIPE GROUP C	180.00	0.00	180.00	LF	180.00	\$40.00	\$7,200.00	
		0001	0690	7320015A	15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$150.00	\$300.00
		0001	0700	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	8.00	0.00	8.00	EA	8.00	\$200.00	\$1,600.00
		0001	0710	7320024A	24 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$275.00	\$550.00
		0001	0720	7320030A	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0730	7320036A	36 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$600.00	\$2,400.00
		0001	0740	7320042A	42 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$850.00	\$3,400.00
		0001	0750	7320048A	48 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$1,000.00	\$4,000.00
		0001	0760	7320815A	15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	10.00	0.00	10.00	EA	10.00	\$125.00	\$1,250.00
		0001	0770	8051000A	SEEDING - COOL SEASON MIXTURES	34.60	0.00	34.60	ACRE	23.79	\$1,750.00	\$41,632.50
		0001	0780	8061004	SEDIMENT TRAP ROCK	234.90	-133.90	101.00	CUYD	101.00	\$90.00	\$9,090.00
		0001	0790	8061005	ROCK DITCH CHECK	7,047.00	-4,476.00	2,571.00	LF	2,571.00	\$8.00	\$20,568.00
		0001	0800	8061006	ALTERNATE DITCH CHECK	470.00	4,200.00	4,670.00	LF	4,670.00	\$6.00	\$28,020.00
		0001	0810	8061016	SEDIMENT REMOVAL	1,198.00	0.00	1,198.00	CUYD	0.00	\$5.00	\$0.00
		0001	0820	8061019	SILT FENCE	23,490.00	-22,875.00	615.00	LF	615.00	\$1.50	\$922.50
		0040	0830	9039901	MISC.ADJUST EXISTING SIGNS	1.00	0.00	1.00	LS	0.75	\$165,000.00	\$123,750.00
	Project J J5S3388	5S3319 - To 0001	otal Value 0840	Posted to D 3107002	Date as of Report Generated Date GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)	85.00	0.00	85.00	TONS	0.00	\$74.38	\$4,492,328.20 \$0.00
	200000	0001	0850	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	3,929.40	0.00	3,929.40	TONS	3,780.01	\$52.45	\$198,261.52
		0001	0860	4071005	LEVELING) TACK COAT	4,726.00	0.00	4,726.00	GAL	3,934.00	\$2.05	\$8,064.70
		0001				.,. 20.00	0.00	.,. 20.00	5712	2,50 1.50	φ2.00	\$0,001.10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-D04	J5S3388	0001	0870	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
		0001	0880	6161005	CONSTRUCTION SIGNS	1,102.00	0.00	1,102.00	SQFT	0.00	\$8.00	\$0.00
		0001	0890	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	0.00	\$25.00	\$0.00
		0001	0900	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	0.00	\$20.00	\$0.00
		0001	0910	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	0.00	\$2,000.00	\$0.00
		0001	0920	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.00
		0001	0930	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$5,895.70	\$1,473.92
		0001	0940	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	45,471.00	0.00	45,471.00	LF	0.00	\$0.09	\$0.00
		0001	0950	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	42,278.00	0.00	42,278.00	LF	0.00	\$0.10	\$0.00
		0001	0960	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	356.00	0.00	356.00	SQYD	0.00	\$22.33	\$0.00
	Project J	5S3388 - To	otal Value	Posted to D	ate as of Report Generated Date							\$207,800.15
201218-D04 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$4,991,492.19



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval	Quantity Posted	Units	Location	From Station/	Offset/ Distance	To Station/	Offset/ Distance	Comments
				Date				Log Mile		Log Mile		
0240	2079909	MISC. GRADING	11/1/21	11/2/21	134.59	STA	Route O					
0310	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	11/1/21	11/2/21	628.93	TONS	10/22					
				11/2/21	2,139.64	TONS	10/20					
				11/2/21	2,419.79	TONS	10/21					
0320	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	11/1/21	11/2/21	447.23	TONS	10/19					
				11/2/21	1,336.51	TONS	10/27					
				11/2/21	1,612.66	TONS	10/26					
				11/2/21	1,854.49	TONS	10/22					
0330	4071005	TACK COAT	11/1/21	11/2/21	428.00	GAL	10/19					
				11/2/21	1,377.00	GAL	10/23					
				11/2/21	1,850.00	GAL	10/26					
				11/2/21	2,171.00	GAL	10/22					
0770	8051000A	SEEDING - COOL SEASON MIXTURES	11/1/21	11/2/21	6.27	ACRE	Partial Payment of 80% of Route O					
0830	9039901	MISC. HIGHWAY SIGNING	11/1/21	11/2/21	0.25	LS	Route O					

Project: J5S3388

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0850	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	11/1/21	11/2/21	81.71	TONS	10/16					
				11/2/21	1,879.98	TONS	10/18					
0860	4071005	TACK COAT	11/1/21	11/2/21	545.00	GAL	10/16					
				11/2/21	1,870.00	GAL	10/18					

<u>The information below this line are details for Construction Signs (if applicable).</u> No Data Available



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Fiojeci	LINE	Description	Туре	Adjustment Type	Number	Date	By	Amount	(Venderks
J5S3232	0020	GRAVEL (A) OR CRUSHED STONE (B) OR	Overrun	Overrun	1	Jul 2, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		CHAT			1	Jul 2, 2021	SYSTEM	(\$63.76)	
					2	Jul 15, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					2	Jul 15, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Aug 2, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	Aug 16, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Sep 2, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Sep 16, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$63.76)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Oct 4, 2021	SYSTEM	\$63.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woods6 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0020 -	Total						\$0.00	
	0030	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Material		2	Jul 15, 2021	SYSTEM	\$178,469.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 15, 2021	SYSTEM	(\$178,469.21)	
					3	Aug 2, 2021	SYSTEM	\$178,469.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$178,469.21)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Other Item Adjustment	ACAD	1	Jul 2, 2021	webers1	\$4,600.60	AC Adjustment for BP1 19-35C 2.9% Virgin AC% 1866.37 Tons
					1	Jul 2, 2021	webers1	\$2,934.85	AC Adjustment for BP1 21-33 2.8% Virgin AC% 1233.13 Tons includes 0.03 Tons for Rounding to Final Quantity
				ACAD - Tota	al			\$7,535.45	
			Other Item	Adjustment -	Total			\$7,535.45	
			Overrun	Overrun	1	Jul 2, 2021	SYSTEM	(\$14,277.04)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
						1.1.0	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment
					1	Jul 2, 2021	STOTEM	φ14,211.04	Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J5S3232	0030	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Overrun	Overrun	2	Jul 15, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 3099.500; Overrun Quantity Balance 238.20.						
					3	Aug 2, 2021	SYSTEM	(\$14,277.04)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).						
					3	Aug 2, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 3099.500; Overrun Quantity Balance 238.20.						
					4	Aug 16, 2021	SYSTEM	(\$14,277.04)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).						
					4	Aug 16, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 25 on the current Payment Estimate.						
					5	Sep 2, 2021	SYSTEM	(\$14,277.04)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).						
					5	Sep 2, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 16 on the current Payment Estimate.						
					6	Sep 16, 2021	SYSTEM	(\$14,277.04)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).						
					6	Sep 16, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user webers1 overridding Payment Estimate Exception 14 on the current Payment Estimate.						
								7	Oct 4, 2021	SYSTEM	(\$14,277.04)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35720' is applied (if non-zero).			
					7	Oct 4, 2021	SYSTEM	\$14,277.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woods6 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
				Overrun - T	otal			\$0.00							
			Overrun - T	otal				\$0.00							
			Price FUEL		1	Jul 2, 2021	SYSTEM	\$7,306.14	Reference Item Price Adjustment Index Adjustment Type applied is FUEL						
				- Total				\$7,306.14							
			Price FUEL	- Total				\$7,306.14							
	0030 -							\$14,841.59							
	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		1	Jul 2, 2021	SYSTEM	\$6,231.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					1	Jul 2, 2021	SYSTEM	(\$6,231.39)							
					2	Jul 15, 2021	SYSTEM	\$6,231.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					2	Jul 15, 2021	SYSTEM	(\$6,231.39)							
							3	Aug 2, 2021	SYSTEM	\$6,231.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					3	Aug 2, 2021	SYSTEM	(\$6,231.39)							
					4	4					4	Aug 16, 2021	SYSTEM	\$6,231.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$6,231.39)							
				- Total				\$0.00							
			Material - To					\$0.00							
			Other Item Adjustment	ACAD	1	Jul 2, 2021	webers1	\$460.58	AC Adjustment for SL21-2 3.3% Virgin AC% 164.2 Tons includes 0.03 Tons for Rounding to final Quantity						
				ACAD - Tota	al			\$460.58							
			Other Item /	Adjustment -	Total			\$460.58							



at	Line	Description	Adjustment	Other	Eat	Created	Created	Amount	Damarka
ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
32	0040	BITUMINOUS	Overrun	Overrun	1	Jul 2, 2021	SYSTEM	(\$729.56)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		MIXTURE PG64-22 (SUR			1	Jul 2, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 3 on the current Payment Estimate. Material Insufficiency Quantity 164.200; Overrun Quantity Balance 18.10.
					2	Jul 15, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					2	Jul 15, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception S on the current Payment Estimate. Material Insufficiency Quantity 164.200; Overrun Quantity Balance 18.10.
					3	Aug 2, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35719' is applied (if non-zero).
					3	Aug 2, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception on the current Payment Estimate. Material Insufficiency Quantity 164.200; Overrun Quantity Balance 18.10.
					4	Aug 16, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimate of '2.35719' is applied (if non-zero).
					4	Aug 16, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception on the current Payment Estimate. Material Insufficiency Quantity 164.200; Overrun Quantity Balance 18.10.
					5	Sep 2, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimate of '2.35719' is applied (if non-zero).
					5	Sep 2, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user webers1 overridding Paymen Estimate Exception 17 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimate of '2.35719' is applied (if non-zero).
					6	Sep 16, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user webers1 overridding Paymen Estimate Exception 15 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$729.56)	Averaged Price Adjustment from this item on all previous payment estimate of '2.35719' is applied (if non-zero).
					7	Oct 4, 2021	SYSTEM	\$729.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woods6 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
			Price FUEL		1	Jul 2, 2021	SYSTEM	\$387.05	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$387.05	
			Price FUEL	- Total				\$387.05	
	0040 -	Total						\$847.63	
	0130	PREF THERMO PAVMT	Material		2	Jul 15, 2021	SYSTEM	\$3,292.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Paymer Estimate Exception 3 on the current Payment Estimate.
		MARKING, 6 IN WHITE			2	Jul 15, 2021	SYSTEM	(\$3,292.50)	
					3	Aug 2, 2021	SYSTEM	\$3,292.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Paymen Estimate Exception 6 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$3,292.50)	
					4	Aug 16, 2021	SYSTEM	\$3,292.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user webers1 overridding Paymer Estimate Exception 11 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$3,292.50)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
3232	0140	PREF THERMO PAVMT	Material		2	Jul 15, 2021	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
		MARKING, 12 IN WHITE			2	Jul 15, 2021	SYSTEM	(\$930.00)			
					3	Aug 2, 2021	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					3	Aug 2, 2021	SYSTEM	(\$930.00)			
					4	Aug 16, 2021	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user webers1 overridding Paymen Estimate Exception 12 on the current Payment Estimate.		
					4	Aug 16, 2021	SYSTEM	(\$930.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0140 -	Total						\$0.00			
	0150	PREF THERMO PVMT MARK,	Material		2	Jul 15, 2021	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Paymer Estimate Exception 5 on the current Payment Estimate.		
		LT/RT ARROW			2	Jul 15, 2021	SYSTEM	(\$350.00)			
					3	Aug 2, 2021	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Paymen Estimate Exception 8 on the current Payment Estimate.		
					3	Aug 2, 2021	SYSTEM	(\$350.00)			
							4	Aug 16, 2021	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user webers1 overridding Paymen Estimate Exception 13 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$350.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0150 -	PREF THERMO						\$0.00			
	0150 - 0160	THERMO PVMT MARK,	Material		2	Jul 15, 2021	SYSTEM	\$0.00 \$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Paymen Estimate Exception 6 on the current Payment Estimate.		
		PREF THERMO	Material		2		SYSTEM SYSTEM		Estimate Item Adjustment (0010) due to user webers1 overridding Paymer		
		PREF THERMO PVMT MARK, 30" WHT	Material			2021 Jul 15,		\$750.00	Estimate Item Adjustment (0010) due to user webers1 overridding Paymer Estimate Exception 6 on the current Payment Estimate.		
		PREF THERMO PVMT MARK, 30" WHT	Material		2	2021 Jul 15, 2021 Aug 2,	SYSTEM	\$750.00 (\$750.00)	Estimate Item Adjustment (0010) due to user webers1 overridding Paymer Estimate Exception 6 on the current Payment Estimate.		
		PREF THERMO PVMT MARK, 30" WHT	Material		2 3	2021 Jul 15, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM	\$750.00 (\$750.00) \$750.00	Estimate Item Adjustment (0010) due to user webers1 overridding Paymer Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Paymer Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment		
		PREF THERMO PVMT MARK, 30" WHT	Material		2 3 3	2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM	\$750.00 (\$750.00) \$750.00 (\$750.00)	Estimate Item Adjustment (0010) due to user webers1 overridding Paymer Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Paymer Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user webers1 overridding Payment		
		PREF THERMO PVMT MARK, 30" WHT	Material	- Total	2 3 3 4	2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$750.00 (\$750.00) \$750.00 (\$750.00) \$750.00	Estimate Item Adjustment (0010) due to user webers1 overridding Paymer Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Paymer Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user webers1 overridding Paymert		
		PREF THERMO PVMT MARK, 30" WHT	Material		2 3 3 4	2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$750.00 (\$750.00) \$750.00 (\$750.00) \$750.00 (\$750.00)	Estimate Item Adjustment (0010) due to user webers1 overridding Paymer Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Paymer Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user webers1 overridding Payment		
		PREF THERMO PVMT MARK, 30" WHT MIDBL			2 3 3 4	2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$750.00 (\$750.00) \$750.00 (\$750.00) \$750.00 (\$750.00) \$0.00	Estimate Item Adjustment (0010) due to user webers1 overridding Paymer Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Paymer Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user webers1 overridding Payment		
	0160	PREF THERMO PVMT MARK, 30" WHT MIDBL			2 3 3 4 4	2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$750.00 (\$750.00) \$750.00 (\$750.00) \$750.00 (\$750.00) (\$750.00) \$0.00	Estimate Item Adjustment (0010) due to user webers1 overridding Paymer Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Paymer Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user webers1 overridding Payment		
	0160 -	PREF THERMO PVMT MARK, 30" WHT MIDBL	Material - To Other Item	otal	2 3 3 4 4	2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Jul 15,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$750.00 (\$750.00) \$750.00 (\$750.00) \$750.00 (\$750.00) (\$750.00) \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user webers1 overridding Paymer Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Paymer Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user webers1 overridding Paymer Estimate Exception 14 on the current Payment Estimate.		
	0160 -	PREF THERMO PVMT MARK, 30" WHT MIDBL	Material - To Other Item	otal	2 3 3 4 4 2	2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Jul 15, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$750.00 (\$750.00) \$750.00 (\$750.00) \$750.00 (\$750.00) (\$750.00) \$0.00 \$0.00 \$0.00 (\$518.43)	Estimate Item Adjustment (0010) due to user webers1 overridding Paymer Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Paymer Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user webers1 overridding Payment Estimate Item Adjustment (0020) due to user webers1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
	0160 -	PREF THERMO PVMT MARK, 30" WHT MIDBL	Material - To Other Item	otal	2 3 3 4 4 2 5 5	2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM webers1 webers1	\$750.00 (\$750.00) \$750.00 (\$750.00) \$750.00 (\$750.00) (\$750.00) \$0.00 \$0.00 (\$518.43) \$129.61	Estimate Item Adjustment (0010) due to user webers1 overridding Paymer Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Paymer Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user webers1 overridding Paymer Estimate Exception 14 on the current Payment Estimate.		



			Туре	Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J5S3232	0170 -	Total						\$129.61													
	0180	4 IN. YELLOW WATERBORNE	Other Item Adjustment	REFL	2	Jul 15, 2021	webers1	(\$632.95)	20% Retroreflectivity Adjustment till Testing is Completed												
		PAVEMENT MARKING			5	Sep 2, 2021	webers1	\$158.24	5% Bonus for Retroreflectivity results												
					5	Sep 2, 2021	webers1	\$632.95	Resolves Item Adjustment from Estimate 0002												
				REFL - Tota	I			\$158.24													
			Other Item	Adjustment -	Total			\$158.24													
	0180 -	Total						\$158.24													
	0190	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	1	Jul 2, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					1	Jul 2, 2021	SYSTEM	(\$805.62)													
					2	Jul 15, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					2	Jul 15, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
					3	Aug 2, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					3	Aug 2, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 14 on the current Payment Estimate.												
					4	Aug 16, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					4	Aug 16, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user webers1 overridding Payment Estimate Exception 27 on the current Payment Estimate.												
					5	Sep 2, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					5	Sep 2, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 18 on the current Payment Estimate.												
						6	Sep 16, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).											
					6	Sep 16, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user webers1 overridding Payment Estimate Exception 16 on the current Payment Estimate.												
									7	Oct 4, 2021	SYSTEM	(\$805.62)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					7	Oct 4, 2021	SYSTEM	\$805.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woods6 overridding Payment Estimate Exception 19 on the current Payment Estimate.												
				Overrun - To	otal			\$0.00													
			Overrun - T	otal				\$0.00													
	0190 -	Total						\$0.00													
J5S3232 - 1	Total							\$15,977.07													
J5S3319	0250	FURNISHING ROCK FILL	Material					2						3	Aug 2, 2021	SYSTEM	\$16,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
																	3	Aug 2, 2021	SYSTEM	(\$16,540.00)	
																	4	4	4	Aug 16, 2021	SYSTEM
											4	Aug 16, 2021	SYSTEM	(\$76,040.00)							
					5	Sep 2, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.												
					5	Sep 2,	SYSTEM	(\$76,040.00)													



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
3319	0250	FURNISHING	Material			2021														
		ROCK FILL			6	Sep 16, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					6	Sep 16, 2021	SYSTEM	(\$76,040.00)												
					7	Oct 4, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					7	Oct 4, 2021	SYSTEM	(\$76,040.00)												
					8	Oct 18, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					8	Oct 18, 2021	SYSTEM	(\$76,040.00)												
					9	Nov 2, 2021	SYSTEM	\$76,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					9	Nov 2, 2021	SYSTEM	(\$76,040.00)												
				- Total				\$0.00												
			Material - T	otal				\$0.00												
	0250 -	Total						\$0.00												
	0270	TYPE 1 AGGREGATE FOR BASE (4	Material		3	Aug 2, 2021	SYSTEM	\$814.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
		IN. THICK)			3	Aug 2, 2021	SYSTEM	(\$814.72)												
					4	Aug 16, 2021	SYSTEM	\$3,101.43	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					4	Aug 16, 2021	SYSTEM	(\$3,101.43)												
					5	Sep 2, 2021	SYSTEM	\$3,101.43	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					5	Sep 2, 2021	SYSTEM	(\$3,101.43)												
				6	6							6	-	6	6	6	Sep 16, 2021	SYSTEM	\$3,101.43	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$3,101.43)												
				- Total				\$0.00												
			Material - T	otal				\$0.00												
			Price FUEL		3	Aug 2, 2021	SYSTEM	\$13.32	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					4	Aug 16, 2021	SYSTEM	\$41.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
				- Total				\$54.79												
			Price FUEL	- Total				\$54.79												
	0270 -	Total						\$54.79												
	0270 - 7 0310	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	Material		5	Sep 2, 2021	SYSTEM	\$196,635.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
		PG64-22 (BAS			5	Sep 2, 2021	SYSTEM	(\$196,635.91)												
					6	Sep 16,	SYSTEM	\$10,595.91	This adjustment offsets the original system-generated Material Payment											
						2021			Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J5S3319	0310	BITUMINOUS PAVEMENT MIXTURE	Material		7	Oct 4, 2021	SYSTEM	\$425,565.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woods6 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
		PG64-22 (BAS			7	Oct 4, 2021	SYSTEM	(\$425,565.10)																	
					8	Oct 18, 2021	SYSTEM	\$425,565.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
					8	Oct 18, 2021	SYSTEM	(\$425,565.10)																	
					9	Nov 2, 2021	SYSTEM	\$666,875.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
					9	Nov 2, 2021	SYSTEM	(\$666,875.73)																	
				- Total				\$0.00																	
			Material - To	otal				\$0.00																	
			Other Item Adjustment	ACAD	3	Aug 2, 2021	webers1	\$197.88	AC Adjustment for Bit Base used on Pipe Crossings																
					4	Aug 16, 2021	webers1	\$553.26	AC adjustment for 184.13 Tons of asphalt placed between 8/2 to 8/15																
					6	Sep 16, 2021	webers1	\$32,624.56	AC Adjustment for Pay Period on Estimate 0005																
											7	Oct 4, 2021	webers1	\$26,855.67	AC Adjustment for 8922.15 Tons of BB21-27 VAC 2.8%										
					9	Nov 2, 2021	webers1	\$14,890.59	AC Adjustment for 5188.36 Tons of BB21-27 at VAC 2.8%																
				ACAD - Tota	al			\$75,121.96																	
			Other Item	Adjustment -	Total			\$75,121.96																	
			Other Item A Price FUEL	Price			3	Aug 2, 2021	SYSTEM	\$187.67	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					4	Aug 16, 2021	SYSTEM	\$495.07	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
											5	Sep 2, 2021	SYSTEM	\$29,485.15	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
										7	Oct 4, 2021	SYSTEM	\$21,323.22	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					9	Nov 2, 2021	SYSTEM	\$17,395.12	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
				- Total				\$68,886.23																	
			Price FUEL	- Total				\$68,886.23																	
	0310 -	Total						\$144,008.19																	
	0320	BITUMINOUS PAVEMENT MIXTURE	Material	Material	Material	Material	Material	Material	Material		Material	Material			Material	Material		6	Sep 16, 2021	SYSTEM	\$350,706.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
		PG64-22 (SUR			6	Sep 16, 2021	SYSTEM	(\$350,706.30)																	
			7	7	7	7 7 8	7	7													7	Oct 4, 2021	SYSTEM	\$727,265.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate.
																7	7		-	7	Oct 4, 2021	SYSTEM	(\$727,265.12)		
									8	8	Oct 18, 2021	SYSTEM	\$969,669.41	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					8	Oct 18, 2021	SYSTEM	(\$969,669.41)																	
				- Total				\$0.00																	
			Material - To	otal				\$0.00																	
			Other Item	ACAD	6	Sep 16,	webers1	\$19,803.56	AC Adjustment for Pay Period 9/2 to 9/15																
			Adjustment			2021																			



Nov 5, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J5S3319	0320	BITUMINOUS	Other Item Adjustment	ACAD	6	Sep 16, 2021	webers1	\$5,133.64	AC Adjustment for Pay Period on Estimate 0005														
		MIXTURE PG64-22 (SUR			7	Oct 4, 2021	webers1	\$26,840.31	AC Adjustment for 7565.98 Tons of SL21-5 VAC 3.3%														
					8	Oct 18, 2021	webers1	\$16,474.43	AC Adjustment for 4870.49 Tons of SL21-5 at 3.3% VAC														
					9	Nov 2, 2021	webers1	\$17,761.14	AC Adjustment for 5250.89 Tons of SL21-5 at VAC 3.3%														
				ACAD - Tot	al			\$86,013.08															
			Other Item																				
				Adjustment -				\$86,013.08															
			Overrun	Overrun		Nov 2, 2021	SYSTEM	(\$151,799.54)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
				Overrun - T	otal			(\$151,799.54)															
			Overrun - T	otal				(\$151,799.54)															
			Price FUEL		6	Sep 16, 2021	SYSTEM	\$16,844.05	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					7	Oct 4, 2021	SYSTEM	\$18,085.72	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					8	Oct 18, 2021	SYSTEM	\$16,331.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
					9	Nov 2, 2021	SYSTEM	\$17,607.28	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
				- Total				\$68,868.78															
			Price FUEL	- Total				\$68,868.78															
	0320 -	Total						\$3,082.32															
	0330	TACK COAT	T Material	Material		8	Oct 18, 2021	SYSTEM	\$28,726.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
							8	Oct 18, 2021	SYSTEM	(\$28,726.65)													
												9	Nov 2, 2021	SYSTEM	\$40,669.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.							
					9	Nov 2, 2021	SYSTEM	(\$40,669.95)															
				- Total				\$0.00															
			Material - To	otal				\$0.00															
	0330 -	Total						\$0.00															
	0340	CONCRETE PAVEMENT (5 3/4 IN. NON-	Material		4	Aug 16, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.														
		REINF			4	Aug 16, 2021	SYSTEM	(\$1,639.81)															
																			5	Sep 2, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$1,639.81)															
					6	Sep 16, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.														
					6	Sep 16, 2021	SYSTEM	(\$1,639.81)															
					7	7	Oct 4, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					7	Oct 4, 2021	SYSTEM	(\$1,639.81)															
					8	Oct 18, 2021	SYSTEM	\$1,639.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.														



Nov 5, 2021

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks											
FIOJECI	LINE	Description	Туре	Adjustment Type	Number	Date	By	Amount	IVEIIIdiks											
J5S3319	0340	CONCRETE PAVEMENT (5 3/4 IN. NON-	Material		8	Oct 18, 2021	SYSTEM	(\$1,639.81)												
		REINF		- Total				\$0.00												
			Material - To	otal				\$0.00												
	0340 -	Total						\$0.00												
	0350	WOVEN WIRE FENCE	Material		4	Aug 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
					4	Aug 16, 2021	SYSTEM	(\$2,200.00)												
					5	Sep 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.											
					5	Sep 2, 2021	SYSTEM	(\$2,200.00)												
					6	Sep 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.											
					6	Sep 16, 2021	SYSTEM	(\$2,200.00)												
						7	Oct 4, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woods6 overridding Payment Estimate Exception 5 on the current Payment Estimate.										
								7	Oct 4, 2021	SYSTEM	(\$2,200.00)									
						8	Oct 18, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.										
						8	Oct 18, 2021	SYSTEM	(\$2,200.00)											
					9	Nov 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.											
										9	Nov 2, 2021	SYSTEM	(\$2,200.00)							
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0350 -	Total						\$0.00												
	0360	ROCK LINING	Material		3	Aug 2, 2021	SYSTEM	\$385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
				3		:			3	3	3	Aug 2, 2021	SYSTEM	(\$385.00)						
						4	Aug 16, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.										
					4	Aug 16, 2021	SYSTEM	(\$3,650.00)												
										5	Sep 2, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
											5					5	Sep 2, 2021	SYSTEM	(\$3,650.00)	
												6	Sep 16, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
			6 7	6	6	Sep 16, 2021	SYSTEM	(\$3,650.00)												
				Oct 4, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment Estimate Exception 6 on the current Payment Estimate.													
				7	Oct 4, 2021	SYSTEM	(\$3,650.00)													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
5S3319	0360	ROCK LINING	Material		8	Oct 18, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.								
					8	Oct 18, 2021	SYSTEM	(\$3,650.00)									
					9	Nov 2, 2021	SYSTEM	\$3,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.								
					9	Nov 2, 2021	SYSTEM	(\$3,650.00)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0360 -	Total						\$0.00									
	0590	CLASS B-1 CONCRETE (CULVERTS)	Material		4	Aug 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.								
					4	Aug 16, 2021	SYSTEM	(\$15,000.00)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0590 -	Total						\$0.00									
	0600	REINFORCING STEEL (CULVERTS)	Material		4	Aug 16, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 18 on the current Payment Estimate.								
					4	Aug 16, 2021	SYSTEM	(\$5,550.00)									
					5	Sep 2, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.								
					5	Sep 2, 2021	SYSTEM	(\$5,550.00)									
					6	Sep 16, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.								
					6	Sep 16, 2021	SYSTEM	(\$5,550.00)									
					7	Oct 4, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woods6 overridding Payment Estimate Exception 7 on the current Payment Estimate.								
					7	Oct 4, 2021	SYSTEM	(\$5,550.00)									
					8	Oct 18, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.								
					8	Oct 18, 2021	SYSTEM	(\$5,550.00)									
													9	Nov 2, 2021	SYSTEM	\$5,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$5,550.00)									
				- Total				\$0.00									
			Material - T	otal				\$0.00									
	0600 -	Total						\$0.00									
	0770	SEEDING - COOL SEASON MIXTURES	Material		7	Oct 4, 2021	SYSTEM	\$19,162.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woods6 overridding Payment Estimate Exception 10 on the current Payment Estimate.								
		WINTONES			7	Oct 4, 2021	SYSTEM	(\$19,162.50)									
					8	Oct 18, 2021	SYSTEM	\$30,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.								
					8	Oct 18,	SYSTEM	(\$30,660.00)									



Nov 5, 2021

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J5S3319	0770	SEEDING - COOL	Material			2021			
		SEASON MIXTURES			9	Nov 2, 2021	SYSTEM	\$41,632.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$41,632.50)	
				- Total				\$0.00	
			Material - To	Material - Total					
	0770 -	- Total						\$0.00	
	0780	SEDIMENT TRAP ROCK	Material		4	Aug 16, 2021	SYSTEM	\$6,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$6,390.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0780 -	Total						\$0.00	
	0790	ROCK DITCH CHECK	Material		3	Aug 2, 2021	SYSTEM	\$520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$520.00)	
					4	Aug 16, 2021	SYSTEM	\$14,072.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$14,072.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0790 -	Total						\$0.00	
	0800	ALTERNATE DITCH CHECK	Material		4	Aug 16, 2021	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$2,040.00)	
					5	Sep 2, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$15,000.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Overrun	Overrun	5	Sep 2, 2021	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 2500.000; Overrun Quantity Balance 2030.00.
					5	Sep 2, 2021	SYSTEM	(\$12,180.00)	
					6	Sep 16, 2021	SYSTEM	(\$12,180.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Sep 16, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$4,800.00)	
					7	Oct 4, 2021	SYSTEM	(\$16,980.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Oct 4, 2021	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3319	0800	ALTERNATE DITCH CHECK	Overrun	Overrun					Estimate Exception 15 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	\$16,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woods6 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$8,220.00)	
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0800 - Total							\$0.00	
	0820	SILT FENCE	Material		5	Sep 2, 2021	SYSTEM	\$450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	Sep 2, 2021	SYSTEM	(\$450.00)	
					6	Sep 16, 2021	SYSTEM	\$607.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Sep 16, 2021	SYSTEM	(\$607.50)	
					7	Oct 4, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woods6 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Oct 4, 2021	SYSTEM	(\$922.50)	
					8	Oct 18, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$922.50)	
					9	Nov 2, 2021	SYSTEM	\$922.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$922.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0820 - Total							\$0.00	
J5S3319 -	Total							\$147,145.30	
J5S3388	0850	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		8	Oct 18, 2021	SYSTEM	\$95,370.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$95,370.88)	
					9	Nov 2, 2021	SYSTEM	\$198,261.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$198,261.52)	
				- Total		\$0.00			
			Material - To	tal		\$0.00			
			Other Item Adjustment	ACAD	8	Oct 18, 2021	webers1	\$6,150.47	AC Adjustment for 1818.32 Tons of SL21-5 at 3.3% VAC
					9	Nov 2, 2021	webers1	\$6,635.42	AC Adjustment for 1961.69 Tons of SL21-5 at VAC 3.3%
				ACAD - Tota	al			\$12,785.89	
			Other Item	Adjustment -	Total			\$12,785.89	
			Price FUEL		8	Oct 18, 2021	SYSTEM	\$6,097.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Nov 2, 2021	SYSTEM	\$6,577.94	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$12,675.13	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3388	0850	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Price FUEL	- Total				\$12,675.13	
	0850 -	Total						\$25,461.02	
	0860	TACK COAT	Material		8	Oct 18, 2021	SYSTEM	\$3,113.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$3,113.95)	
					9	Nov 2, 2021	SYSTEM	\$8,064.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$8,064.70)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0860 -	Total						\$0.00	
J5S3388 ·	Total						\$25,461.02		
Overall - Total									