

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 15, 2021

| Progress Estimate Number | Contract ID | 210122-B01 | Pay Period Start | September 2, 2021 | Original Contract Amount | \$4,940,992.78 |
|-----------------------------|---------------------|--|---------------------|--------------------|-----------------------------|----------------|
| 13 | Prime Contractor | L.F. Krupp Construction, Inc. dba Krupp | Pay Period End | September 15, 2021 | Net Change Order Amount | \$215.51 |
| | | | | | Current Contract Amount | \$4,941,208.29 |

| Approval Date | | By User |
|-----------------------|--|---------|
| September 15, 2021 | Generated and Approved (and should be considered Draft) at the Project Office Level by | buckj |
| September 20, 2021 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | vierss |
| September 21, 2021 | Reviewed and Approved at the Central Office Controllers Office Level by | ramses1 |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete |
|--------------------------|-------------------------|------------------------|---------------------------------------|
| December 15, 2021 | December 15, 2021 | | 66.30% |

| | Milestones | | |
|------------------------|--------------------------|--------------------------------|----------------------------------|
| Date Description | Original Completion Date | Current Completion Date | No Milestones Exist for Contract |
| Acceptance Date | | | |
| Awarded Date | February 3, 2021 | February 3, 2021 | |
| Letting Date | January 22, 2021 | January 22, 2021 | |
| Notice to Proceed Date | March 8, 2021 | March 8, 2021 | |
| Work Began Date | April 5, 2021 | April 5, 2021 | |

| Contract Total Pay For Estimate No. 13 | | | | | | | | | | | |
|--|----------------------------|---------------|----------------|----------------|--|--|--|--|--|--|--|
| | | This Estimate | Previous | To Date | | | | | | | |
| 210122-B01 | | | | | | | | | | | |
| | Total Posted Items Pay | \$285,052.99 | \$2,990,933.69 | \$3,275,986.68 | | | | | | | |
| | Gross Item Adjustments | \$0.00 | \$0.00 | \$0.00 | | | | | | | |
| | Incentive | \$0.00 | \$0.00 | \$0.00 | | | | | | | |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 | | | | | | | |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | | | | | | | |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 | | | | | | | |
| | • | | \$2,990,933.69 | \$3,275,986.68 | | | | | | | |
| Contract Total Pa | yable This Estimate: | \$285,052.99 | | | | | | | | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|---|------|------------|--------------------------|-----------------------------|
| J2P2215 | 0050 | 2063000 | CLASS 3 EXCAVATION | CUYD | \$13.700 | 986 | \$13,508.20 |
| | 0090 | 3040504 | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) | SQYD | \$9.100 | 1,312.9 | \$11,947.39 |
| | 0110 | 3109907 | MISC.GRAVEL (A), CR.STONE(B) OR CHAT BACKFILL | CUYD | \$48.300 | 3.4 | \$164.22 |
| | 0150 | 4039905 | MISC.OPTIONAL PAVEMENT (CITY STREETS) | SQYD | \$65.150 | 60.7 | \$3,954.61 |
| | 0170 | 5021108 | CONCRETE PAVEMENT (8 IN. NON-REINF) | SQYD | \$62.600 | 358 | \$22,410.80 |
| | 0180 | 5024008 | CONCRETE BASE (8 IN. NON-REINF) | SQYD | \$61.400 | 188.9 | \$11,598.46 |
| | 0210 | 6046015A | 15 IN. SLOTTED DRAIN | LF | \$185.000 | 45 | \$8,325.00 |
| | 0270 | 6085008 | PAVED APPROACH, 8 IN. | SQYD | \$65.150 | 604.7 | \$39,396.21 |
| | 0310 | 6091052 | CURB AND GUTTER TYPE B | LF | \$37.950 | 403 | \$15,293.85 |
| | 0320 | 6092012 | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B | LF | \$20.900 | 290 | \$6,061.00 |
| | 0630 | 7250315A | 15 IN. PIPE GROUP B | LF | \$86.750 | 445 | \$38,603.75 |
| | 0640 | 7250318A | 18 IN. PIPE GROUP B | LF | \$98.000 | 157 | \$15,386.00 |
| | 0660 | 7250324A | 24 IN. PIPE GROUP B | LF | \$119.300 | 251 | \$29,944.30 |
| | 0720 | 7261024 | 24 IN. PIPE GROUP A | LF | \$188.800 | 38 | \$7,174.40 |
| | 0770 | 7310048 | PRECAST CONCRETE MANHOLE - 48 IN. | FT | \$576.050 | 4 | \$2,304.20 |
| | 0810 | 7311030 | PRECAST CONCRETE DROP INLET 3 FT X 2 FT-6 IN. | FT | \$644.000 | 12 | \$7,728.00 |

Revision 4/1/2020 Page 1 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 15, 2021

| Progress Estimate Number | Contract ID | 210122-B01 | Pay Period Start | September 2, 2021 | Original Contract Amount | \$4,940,992.78 |
|-----------------------------|---------------------|--|---------------------|--------------------|-----------------------------|----------------|
| 13 | Prime Contractor | L.F. Krupp Construction, Inc. dba Krupp | Pay Period End | September 15, 2021 | Net Change Order Amount | \$215.51 |
| | | | | | Current Contract Amount | \$4,941,208.29 |

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount | |
|-------------------------|----------------|--------------|---|------|------------|--------------------------|-----------------------------|--|
| J2P2215 | 0820 | 7311033 | PRECAST CONCRETE DROP INLET 3 FT X 3 FT | FT | \$661.050 | 4 | \$2,644.20 | |
| | 0860 | 7319913 | MISC.3 FT X 2.5 FT MODIFIED TYPE T DROP INLET WITH SET BACK | FT | \$644.750 | 62 | \$39,974.50 | |
| | 0870 | 7319913 | MISC.5 FT X 3 FT MODIFIED TYPE T DROP INLET WITH SETBACK. | FT | \$784.900 | 11 | \$8,633.90 | |
| Project J2P2215 - Total | | | | | | | | |
| Overall - Total | | | | | | | | |

Contract Adjustments This Estimate

| | | | | 0.11 | | | | |
|-------------------|-------------|--|--------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J2P2215 | 0090 | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) | Material | | | -8,132.5 | \$9.10 | (\$74,005.75 |
| | 0090 | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. | 8,132.5 | \$9.10 | \$74,005.75 |
| | 0100 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | | -83.6 | \$11.75 | (\$982.30 |
| | 0100 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. | 83.6 | \$11.75 | \$982.30 |
| | 0110 | MISC. | Material | | | -162.7 | \$48.30 | (\$7,858.41 |
| | 0110 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. | 162.7 | \$48.30 | \$7,858.41 |
| | 0170 | CONCRETE PAVEMENT (8 IN. NON-REINF) | Material | | | -1,394.1 | \$62.60 | (\$87,270.66 |
| | 0170 | CONCRETE PAVEMENT (8 IN. NON-REINF) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 4 on the current Payment Estimate. | 1,394.1 | \$62.60 | \$87,270.66 |
| | 0180 | CONCRETE BASE (8 IN. NON-REINF) | Material | | | -2,606.8 | \$61.40 | (\$160,057.52 |
| | 0180 | CONCRETE BASE (8 IN. NON-REINF) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate. | 2,606.8 | \$61.40 | \$160,057.52 |
| | 0200 | PIPE COLLAR, TYPE A | Material | | | -4 | \$1,345.00 | (\$5,380.00 |
| | 0200 | PIPE COLLAR, TYPE A | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. | 4 | \$1,345.00 | \$5,380.00 |
| | 0260 | PAVED APPROACH, 7 IN. | Material | | | -129 | \$63.85 | (\$8,236.65 |

Revision 4/1/2020 Page 2 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 15, 2021

Pay Period Start Pay Period September 2, 2021 Amount
September 15, Net Change Order **Progress Estimate** Contract ID 210122-B01 \$4,940,992.78 Number Prime L.F. Krupp Construction, Inc. dba 13 \$215.51 Contractor End 2021 Amount **Current Contract** \$4,941,208.29 Amount

| Project lumber | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|-------------------|-------------|---|--------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| 2P2215 | 0260 | PAVED APPROACH, 7 IN. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 16 on the current Payment Estimate. | 129 | \$63.85 | \$8,236.65 |
| | 0270 | PAVED APPROACH, 8 IN. | Material | | | -3,199.7 | \$65.15 | (\$208,460.46 |
| | 0270 | PAVED APPROACH, 8 IN. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 19 on the current Payment Estimate. | 3,199.7 | \$65.15 | \$208,460.46 |
| | 0310 | CURB AND GUTTER TYPE B | Material | | | -953.5 | \$37.95 | (\$36,185.32 |
| | 0310 | CURB AND GUTTER TYPE B | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate. | 953.5 | \$37.95 | \$36,185.32 |
| | 0320 | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B | Material | | | -1,057.4 | \$20.90 | (\$22,099.66 |
| | 0320 | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 26 on the current Payment Estimate. | 1,057.4 | \$20.90 | \$22,099.66 |
| | 0330 | INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE B | Material | | | -2,105 | \$20.90 | (\$43,994.50 |
| | 0330 | INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE B | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 27 on the current Payment Estimate. | 2,105 | \$20.90 | \$43,994.50 |
| | 0340 | ROCK LINING | Material | | | -18 | \$84.00 | (\$1,512.00 |
| | 0340 | ROCK LINING | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 28 on the current Payment Estimate. | 18 | \$84.00 | \$1,512.00 |
| | 0560 | FLOWABLE BACKFILL | Material | | | -65 | \$323.00 | (\$20,995.00 |
| | 0560 | FLOWABLE BACKFILL | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. | 65 | \$323.00 | \$20,995.00 |
| | 5007 | CHANNELIZER (TRIM LINE) | Material | | | -470 | \$40.00 | (\$18,800.00 |
| | 5007 | CHANNELIZER (TRIM LINE) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment Estimate Exception 29 on the current Payment Estimate. | 470 | \$40.00 | \$18,800.00 |
| tal | | | | | | | | \$0.00 |

Revision 4/1/2020 Page 3 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | Contract Project Information | | | | | | | |
|-------------------|------------------------------|--------------------------------------|-------|--------|---|--|--|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | Location of Work | | | |
| J2P2215 | FAF-63-4 (70) | Resurface and ADA improvements | 63 | ADAIR | from Rte. 6 south junction (Illinois St.) to Patterson street in Kirksville | | | |

| Totals by Job Numbers | This Estimate | Previous | To Date | \$285,052.99 | \$2,990,933.69 | \$3,275,986.68 | \$60.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

Revision 4/1/2020 Page 4 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period | | | |
|---|-----------------------------------|---------------|------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 3040504, Project Item Line Number 0090, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 3105003, Project Item Line Number 0100, Material Set 310500396, Material 1006GBASLD - Gr B Limestone-Dolomite for Aggreg Surf, Acceptance Action Generic 1006GBASLD is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 3109907, Project Item Line Number 0110, Material Set 3109907, Material 1006GBASLD - Gr B Limestone-Dolomite for Aggreg Surf, Acceptance Action Generic 1006GBASLD is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 5021108, Project Item Line Number 0170, Material Set 502110896, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 5021108, Project Item Line Number 0170, Material Set 502110896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 5021108, Project Item Line Number 0170, Material Set 502110896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 5021108, Project Item Line Number 0170, Material Set 502110896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 5024008, Project Item Line Number 0180, Material Set 502400896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 5024008, Project Item Line Number 0180, Material Set 502400896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 5024008, Project Item Line Number 0180, Material Set 502400896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 5024008, Project Item Line Number 0180, Material Set 502400896, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 5024008, Project Item Line Number 0180, Material Set 502400896, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 5024008, Project Item Line Number 0180, Material Set 502400896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6044011, Project Item Line Number 0200, Material Set 604401196, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6044011, Project Item Line Number 0200, Material Set 604401196, Material 0604CPCR - Collar for Pipe Connection, Acceptance Action Generic 0604CPCR is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6085007, Project Item Line Number 0260, Material Set 608500796, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6085007, Project Item Line Number 0260, Material Set 608500796, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6085007, Project Item Line Number 0260, Material Set 608500796, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6085008, Project Item Line Number 0270, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6085008, Project Item Line Number 0270, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6085008, Project Item Line Number 0270, Material Set 608500896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6085008, Project Item Line Number 0270, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6091052, Project Item Line Number 0310, Material Set 609105296, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6091052, Project Item Line Number 0310, Material Set 609105296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, | No Remark was entered by Engineer | buckj | Overridden |
| | | | |

Revision 4/1/2020 Page 5 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|---|-----------------------------------|---------------|------------|
| Acceptance Action Generic 1055CMMLDST1D is insufficient. | | | |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6091052, Project Item Line Number 0310, Material Set 609105296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6092012, Project Item Line Number 0320, Material Set 609201296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6092022, Project Item Line Number 0330, Material Set 609202296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6097000, Project Item Line Number 0340, Material Set 609700096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6161025, Project Item Line Number 5007, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 6214600A, Project Item Line Number 0560, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 9031010, Project Item Line Number 1410, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 9031280, Project Item Line Number 1430, Material Set 903128096, Material 0903HSPSPI - Pipe Post for Highway Signing, Acceptance Action Generic 0903HSPSPI is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2P2215, Item 9031281, Project Item Line Number 1440, Material Set 903128196, Material 0903HSPSPI - Pipe Post for Highway Signing, Acceptance Action Generic 0903HSPSPI is insufficient. | No Remark was entered by Engineer | buckj | Overridden |

Revision 4/1/2020 Page 6 of 25



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bid Net Total Unit To

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| 210122-B01 | J2P2215 | 0001 | 0010 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 0.50 | \$213,648.00 | \$106,824.00 |
| | | 0001 | 0020 | 2029901 | MISC.REMOVE AND REINSTALL EXISTING FENCE (PARCEL 1) | 1.00 | 0.00 | 1.00 | LS | 0.50 | \$3,200.00 | \$1,600.00 |
| | | 0001 | 0030 | 2029901 | MISC.REMOVE AND REINSTALL EXISTING GUARDRAIL (PARCEL 14) | 1.00 | 0.00 | 1.00 | LS | 0.50 | \$1,200.00 | \$600.00 |
| | | 0001 | 0040 | 2029902 | MISC.TREE REMOVAL | 6.00 | 8.00 | 14.00 | EA | 14.00 | \$995.00 | \$13,930.00 |
| | | 0001 | 0050 | 2063000 | CLASS 3 EXCAVATION | 10,181.00 | 11.00 | 10,192.00 | CUYD | 9,272.00 | \$13.70 | \$127,026.40 |
| | | 0001 | 0060 | 2063500 | CULVERT CLEANOUT | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$3,040.00 | \$0.00 |
| | | 0001 | 0070 | 2072000 | LINEAR GRADING CLASS 2 | 93.70 | 0.00 | 93.70 | STA | 3.00 | \$630.00 | \$1,890.00 |
| | | 0001 | 0080 | 2101006A | SUBGRADE COMPACTION (6-INCH DEPTH) | 74.00 | 0.00 | 74.00 | 100F | 0.00 | \$235.00 | \$0.00 |
| | | 0001 | 0090 | 3040504 | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) | 10,763.00 | -121.70 | 10,641.30 | SQYD | 8,132.50 | \$9.10 | \$74,005.75 |
| | | 0001 | 0100 | 3105003 | GRAVEL (A) OR CRUSHED STONE (B) | 90.00 | 0.00 | 90.00 | SQYD | 83.60 | \$11.75 | \$982.30 |
| | | 0001 | 0110 | 3109907 | MISC.GRAVEL (A), CR.STONE(B) OR CHAT BACKFILL | 306.00 | 0.00 | 306.00 | CUYD | 306.00 | \$48.30 | \$14,779.80 |
| | | 0001 | 0120 | 4011209 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | 102.20 | -102.20 | 0.00 | TONS | 0.00 | \$150.50 | \$0.00 |
| | | 0001 | 0130 | 4013000 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | 509.60 | -509.60 | 0.00 | TONS | 0.00 | \$150.50 | \$0.00 |
| | | 0001 | 0140 | 4030103 | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) | 2,324.30 | -238.00 | 2,086.30 | TONS | 0.00 | \$123.40 | \$0.00 |
| | | 0001 | 0150 | 4039905 | MISC.OPTIONAL PAVEMENT (CITY STREETS) | 1,093.50 | 0.00 | 1,093.50 | SQYD | 920.30 | \$65.15 | \$59,957.54 |
| | | 0001 | 0160 | 4071007 | TACK COAT - LOW OR NON-TRACKING | 2,065.00 | -553.00 | 1,512.00 | GAL | 0.00 | \$5.25 | \$0.00 |
| | | 0001 | 0170 | 5021108 | CONCRETE PAVEMENT (8 IN. NON-REINF) | 1,905.40 | -30.20 | 1,875.20 | SQYD | 1,394.10 | \$62.60 | \$87,270.66 |
| | | 0001 | 0180 | 5024008 | CONCRETE BASE (8 IN. NON-REINF) | 3,379.70 | 0.00 | 3,379.70 | SQYD | 2,606.80 | \$61.40 | \$160,057.52 |
| | | 0001 | 0190 | 6039902 | WATER | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$365.00 | \$730.00 |
| | | 0001 | 0200 | 6044011 | PIPE COLLAR, TYPE A | 7.00 | 1.00 | 8.00 | EA | 4.00 | \$1,345.00 | \$5,380.00 |
| | | 0001 | 0210 | 6046015A | 15 IN. SLOTTED DRAIN | 315.00 | 0.00 | 315.00 | LF | 295.00 | \$185.00 | \$54,575.00 |
| | | 0001 | 0220 | 6049902 | MISC.ADJUSTING MANHOLES, METERS, AND VALVES | 40.00 | 0.00 | 40.00 | EA | 0.00 | \$700.00 | \$0.00 |
| | | 0001 | 0230 | 6081010 | CONCRETE CURB RAMP | 1,589.30 | 0.00 | 1,589.30 | SQYD | 0.00 | \$87.40 | \$0.00 |
| | | 0001 | 0240 | 6081012 | TRUNCATED DOMES | 871.00 | 0.00 | 871.00 | SQFT | 0.00 | \$20.00 | \$0.00 |
| | | 0001 | 0250 | 6083003 | 3 IN. CONCRETE MEDIAN STRIP | 159.10 | 0.00 | 159.10 | SQYD | 0.00 | \$128.25 | \$0.00 |
| | | 0001 | 0260 | 6085007 | PAVED APPROACH, 7 IN. | 349.20 | 0.00 | 349.20 | SQYD | 129.00 | \$63.85 | \$8,236.65 |
| | | 0001 | 0270 | 6085008 | PAVED APPROACH, 8 IN. | 2,140.00 | 1,403.70 | 3,543.70 | SQYD | 3,199.70 | \$65.15 | \$208,460.46 |
| | | 0001 | 0280 | 6089905 | MISC.REINFORCED CONCRETE SIDEWALK, 4 IN. THICK | 2,442.70 | 51.30 | 2,494.00 | SQYD | 0.00 | \$40.70 | \$0.00 |
| | | 0001 | 0290 | 6091010 | CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S | 617.00 | 0.00 | 617.00 | LF | 0.00 | \$25.85 | \$0.00 |
| | | 0001 | 0300 | 6091011 | CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S | 109.00 | 0.00 | 109.00 | LF | 0.00 | \$27.85 | \$0.00 |
| | | 0001 | 0310 | 6091052 | CURB AND GUTTER TYPE B | 2,047.00 | -606.80 | 1,440.20 | LF | 953.50 | \$37.95 | \$36,185.32 |
| | | 0001 | 0320 | 6092012 | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B | 661.00 | 782.80 | 1,443.80 | LF | 1,057.40 | \$20.90 | \$22,099.66 |
| | | 0001 | 0330 | 6092022 | INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE B | 2,747.00 | 0.00 | 2,747.00 | LF | 2,105.00 | \$20.90 | \$43,994.50 |
| | | 0001 | 0340 | 6097000 | ROCK LINING | 84.00 | 0.00 | 84.00 | CUYD | 18.00 | \$84.00 | \$1,512.00 |
| | | 0001 | 0350 | 6099903 | MISC.MODIFIED TYPE S CURB | 408.00 | 0.00 | 408.00 | LF | 0.00 | \$55.30 | \$0.00 |
| | | 0001 | 0360 | 6141022 | GRATE AND BEARING PLATE (3 FT. X 3 FT. OR 914 MM X 914 MM) | 10.00 | 0.00 | 10.00 | EA | 2.00 | \$1,150.00 | \$2,300.00 |
| | | 0001 | 0370 | 6141120 | CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM) | 32.00 | 0.00 | 32.00 | EA | 0.00 | \$435.00 | \$0.00 |
| | | 0001 | 0380 | 6143010 | MANHOLE FRAME AND COVER, TYPE 1-A | 13.00 | 0.00 | 13.00 | EA | 1.00 | \$435.00 | \$435.00 |
| | | 0001 | 0390 | 6143013 | MANHOLE FRAME AND COVER, TYPE 3 | 122.00 | 0.00 | 122.00 | EA | 0.00 | \$225.00 | \$0.00 |
| | | 0001 | 0400 | 6161005 | CONSTRUCTION SIGNS | 922.00 | 0.00 | 922.00 | SQFT | 493.00 | \$6.00 | \$2,958.00 |
| | | 0001 | 0410 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 40.00 | 0.00 | 40.00 | EA | 10.00 | \$35.00 | \$350.00 |
| | | 0001 | 0420 | 6161009 | FLAG ASSEMBLY | 32.00 | 0.00 | 32.00 | EA | 0.00 | \$20.00 | \$0.00 |
| | | 0001 | 0430 | 6161024 | CHANNELIZER (TRIM LINE) WITH LIGHT | 310.00 | -310.00 | 0.00 | EA | 0.00 | \$85.00 | \$0.00 |
| | | 0001 | 0440 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | 28.00 | 0.00 | 28.00 | EA | 22.00 | \$225.00 | \$4,950.00 |
| | | 0001 | 0450 | 6161070 | TUBULAR MARKER | 120.00 | 0.00 | 120.00 | EA | 0.00 | \$80.00 | \$0.00 |
| | | 0001 | 0460 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$5,500.00 | \$44,000.00 |
| Revision 4/1/202 | 20 | | | | | | | | | | | Page 7 of 25 |

Page 7 of 25 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| 210122-B01 | J2P2215 | | | | INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | | | | | | | |
| | | 0001 | 0470 | 6169902 | MISC.ADA COMPLIANT DETACTABLE PEDESTRIAN CHANNELIZING BARRICADE | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$125.00 | \$0.00 |
| | | 0001 | 0480 | 6181000 | MOBILIZATION | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$596,245.00 | \$0.00 |
| | | 0001 | 0481 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 0.88 | \$558,664.00 | \$493,858.98 |
| | | 0001 | 0490 | 6191000 | PAVEMENT EDGE TREATMENT | 8,382.00 | -8,382.00 | 0.00 | LF | 0.00 | \$1.20 | \$0.00 |
| | | 0001 | 0500 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 334.00 | 0.00 | 334.00 | LF | 0.00 | \$24.00 | \$0.00 |
| | | 0001 | 0510 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 35.00 | 0.00 | 35.00 | EA | 0.00 | \$320.00 | \$0.00 |
| | | 0001 | 0520 | 6205901A | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 8,973.00 | 0.00 | 8,973.00 | LF | 0.00 | \$0.25 | \$0.00 |
| | | 0001 | 0530 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 2,108.00 | 0.00 | 2,108.00 | LF | 0.00 | \$0.35 | \$0.00 |
| | | 0001 | 0540 | 6209901 | MISC.TEMPORARY PAVEMENT MARKING PAINT | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$3,500.00 | \$0.00 |
| | | 0001 | 0550 | 6209902 | MISC PREFORMED THERMOPLASTIC PAVEMENT MARKING HELMETED BIKE SYMBOL | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$250.00 | \$0.00 |
| | | 0001 | 0560 | 6214600A | FLOWABLE BACKFILL | 65.00 | 0.00 | 65.00 | CUYD | 65.00 | \$323.00 | \$20,995.00 |
| | | 0001 | 0570 | 6229905 | MISC.COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3IN. THICK OR LESS) | 3,590.00 | 0.00 | 3,590.00 | SQYD | 0.00 | \$4.90 | \$0.00 |
| | | 0001 | 0580 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$10,000.00 | \$10,000.00 |
| | | 0001 | 0590 | 7032002 | CLASS B CONCRETE (MISC) | 0.30 | 0.00 | 0.30 | CUYD | 0.00 | \$2,165.00 | \$0.00 |
| | | 0001 | 0600 | 7034041 | CLASS B-1 CONCRETE (CULVERTS) | 3.10 | 0.00 | 3.10 | CUYD | 0.00 | \$1,945.00 | \$0.00 |
| | | 0001 | 0610 | 7061000 | REINFORCING STEEL | 700.00 | 0.00 | 700.00 | LB | 0.00 | \$3.85 | \$0.00 |
| | | 0001 | 0620 | 7250312A | 12 IN. PIPE GROUP B | 5.00 | 0.00 | 5.00 | LF | 5.00 | \$80.00 | \$400.00 |
| | | 0001 | 0630 | 7250315A | 15 IN. PIPE GROUP B | 3,573.00 | 0.00 | 3,573.00 | LF | 2,991.20 | \$86.75 | \$259,486.60 |
| | | 0001 | 0640 | 7250318A | 18 IN. PIPE GROUP B | 761.00 | 0.00 | 761.00 | LF | 761.00 | \$98.00 | \$74,578.00 |
| | | 0001 | 0650 | 7250321A | 21 IN. PIPE GROUP B | 203.00 | 0.00 | 203.00 | LF | 136.00 | \$115.45 | \$15,701.20 |
| | | 0001 | 0660 | 7250324A | 24 IN. PIPE GROUP B | 1,134.00 | 0.00 | 1,134.00 | LF | 1,134.00 | \$119.30 | \$135,286.20 |
| | | 0001 | 0670 | 7250330A | 30 IN. PIPE GROUP B | 241.00 | 0.00 | 241.00 | LF | 235.00 | \$124.75 | \$29,316.25 |
| | | 0001 | 0680 | 7250336A | 36 IN. PIPE GROUP B | 243.00 | 0.00 | 243.00 | LF | 243.00 | \$146.75 | \$35,660.25 |
| | | 0001 | 0690 | 7259902 | MISC.GROUP B; 24 IN X 38 IN ELLIPTICAL PIPE | 296.00 | 0.00 | 296.00 | EA | 296.00 | \$158.85 | \$47,019.60 |
| | | 0001 | 0700 | 7261015 | 15 IN. PIPE GROUP A | 282.00 | 0.00 | 282.00 | LF | 282.00 | \$143.70 | \$40,523.40 |
| | | 0001 | 0710 | 7261018 | 18 IN. PIPE GROUP A | 45.00 | 0.00 | 45.00 | LF | 45.00 | \$166.75 | \$7,503.75 |
| | | 0001 | 0720 | 7261024 | 24 IN. PIPE GROUP A | 38.00 | 0.00 | 38.00 | LF | 38.00 | \$188.80 | \$7,174.40 |
| | | 0001 | 0730 | 7261030 | 30 IN. PIPE GROUP A | 38.00 | 0.00 | 38.00 | LF | 38.00 | \$210.30 | \$7,991.40 |
| | | 0001 | 0740 | 7269903 | MISC.3 FT X 3 FT PRECAST CONCRETE BOX CULVERT | 376.00 | 0.00 | 376.00 | LF | 376.00 | \$342.20 | \$128,667.20 |
| | | 0001 | 0750 | 7269903 | MISC.4 FT X 2 FT PRECAST CONCRETE BOX CULVERT | 338.00 | 16.00 | 354.00 | LF | 338.00 | \$420.00 | \$141,960.00 |
| | | 0001 | 0760 | 7269903 | MISC.5 FT X 4 FT PRECAST CONCRETE BOX CULVERT | 141.00 | 0.00 | 141.00 | LF | 101.00 | \$492.00 | \$49,692.00 |
| | | 0001 | 0770 | 7310048 | PRECAST CONCRETE MANHOLE - 48 IN. | 35.00 | 0.00 | 35.00 | FT | 35.00 | \$576.05 | \$20,161.75 |
| | | 0001 | 0780 | 7310060 | PRECAST CONCRETE MANHOLE - 60 IN. | 25.00 | 0.00 | 25.00 | FT | 25.00 | \$585.00 | \$14,625.00 |
| | | 0001 | 0790 | 7310072 | PRECAST CONCRETE MANHOLE - 72 IN. | 5.00 | 0.00 | 5.00 | FT | 5.00 | \$927.20 | \$4,636.00 |
| | | 0001 | 0800 | 7311022 | PRECAST CONCRETE DROP INLET 2 FT X 2 FT | 47.00 | 0.00 | 47.00 | FT | 39.00 | \$656.35 | \$25,597.65 |
| | | 0001 | 0810 | 7311030 | PRECAST CONCRETE DROP INLET 3 FT X 2 FT-6 IN. | 66.00 | 0.00 | 66.00 | FT | 49.00 | \$644.00 | \$31,556.00 |
| | | 0001 | 0820 | 7311033 | PRECAST CONCRETE DROP INLET 3 FT X 3 FT | 39.00 | 0.00 | 39.00 | FT | 36.00 | \$661.05 | \$23,797.80 |
| | | 0001 | 0830 | 7311042 | PRECAST CONCRETE DROP INLET 4 FT X 2 FT | 13.00 | 0.00 | 13.00 | FT | 10.00 | \$729.50 | \$7,295.00 |
| | | 0001 | 0840 | 7311053 | PRECAST CONCRETE DROP INLET 5 FT X 3 FT | 42.00 | 0.00 | 42.00 | FT | 42.00 | \$838.05 | \$35,198.10 |
| | | 0001 | 0850 | 7319902 | MISC.CONNECT TO EXISTING STRUCTURE | 5.00 | 0.00 | 5.00 | EA | 3.00 | \$1,705.00 | \$5,115.00 |
| | | 0001 | 0860 | 7319913 | MISC.3 FT X 2.5 FT MODIFIED TYPE T DROP INLET WITH SET BACK | 359.00 | 0.00 | 359.00 | FT | 347.00 | \$644.75 | \$223,728.25 |
| | | 0001 | 0870 | 7319913 | MISC.5 FT X 3 FT MODIFIED TYPE T DROP INLET WITH SETBACK. | 46.00 | 0.00 | 46.00 | FT | 42.00 | \$784.90 | \$32,965.80 |
| | | 0001 | 0880 | 7319913 | MISC.5 FT X 5 FT MODIFIED TYPE T DROP INLET WITH | 32.00 | 0.00 | 32.00 | FT | 32.00 | \$883.90 | \$28,284.80 |
| | | | | | SETBACK | | | | | | | |

Page 8 of 25 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 210122-B01 | J2P2215 | 0001 | 0890 | 7319913 | MISC.6 FT X 5 FT MODIFED TYPE T DROP INLET WITH SET BACK | 5.00 | 0.00 | 5.00 | FT | 5.00 | \$1,201.00 | \$6,005.00 |
| | | 0001 | 0900 | 7319913 | MISC.8 FT X 6 FT JUNCTION BOX | 5.00 | 0.00 | 5.00 | FT | 5.00 | \$1,760.00 | \$8,800.00 |
| | | 0001 | 0910 | 7319913 | MISC.PRECAST 48" MANHOLE WITH TYPE A DI TOP | 11.00 | 0.00 | 11.00 | FT | 11.00 | \$664.10 | \$7,305.10 |
| | | 0001 | 0920 | 7319913 | MISC.PRECAST 60" MANHOLE WITH TYPE A DI TOP | 43.00 | 0.00 | 43.00 | FT | 23.00 | \$978.55 | \$22,506.65 |
| | | 0001 | 0930 | 7319913 | MISC.PRECAST DROP INLET 5 FT X 5 FT | 75.00 | 0.00 | 75.00 | FT | 75.00 | \$777.65 | \$58,323.75 |
| | | 0001 | 0940 | 7319913 | MISC.PRECAST DROP INLET 6 FT X 5 FT | 23.00 | 0.00 | 23.00 | FT | 23.00 | \$1,312.75 | \$30,193.25 |
| | | 0001 | 0950 | 7319913 | MISC.PRECAST DROP INLET 7 FT X 3 FT | 9.00 | 0.00 | 9.00 | FT | 9.00 | \$871.55 | \$7,843.95 |
| | | 0001 | 0960 | 7319913 | MISC.PRECAST DROP INLET 7 FT X 5 FT | 9.00 | 0.00 | 9.00 | FT | 0.00 | \$900.00 | \$0.00 |
| | | 0001 | 0970 | 7320015A | 15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$420.00 | \$0.00 |
| | | 0001 | 0980 | 8031000A | TURF TYPE TALL FESCUE SODDING | 2,892.00 | 70.00 | 2,962.00 | SQYD | 0.00 | \$6.90 | \$0.00 |
| | | 0001 | 0990 | 8061005 | ROCK DITCH CHECK | 26.00 | 0.00 | 26.00 | LF | 0.00 | \$35.00 | \$0.00 |
| | | 0001 | 1000 | 8061006 | ALTERNATE DITCH CHECK | 12.00 | 0.00 | 12.00 | LF | 0.00 | \$18.50 | \$0.00 |
| | | 0001 | 1010 | 8061007A | CURB INLET CHECK | 173.00 | 0.00 | 173.00 | EA | 89.00 | \$145.00 | \$12,905.00 |
| | | 0001 | 1020 | 8061016 | SEDIMENT REMOVAL | 179.00 | 0.00 | 179.00 | CUYD | 0.00 | \$1.00 | \$0.00 |
| | | 0001 | 1030 | 8061019 | SILT FENCE | 200.00 | 0.00 | 200.00 | LF | 0.00 | \$4.20 | \$0.00 |
| | | 0020 | 1040 | 9019901 | MISC.ELECTRICAL SERVICE CONNECTION | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$3,000.00 | \$0.00 |
| | | 0030 | 1050 | 9020211 | SIGNAL HEAD, TYPE 1S | 32.00 | 0.00 | 32.00 | EA | 0.00 | \$364.00 | \$0.00 |
| | | 0030 | 1060 | 9020213 | SIGNAL HEAD, TYPE 3S | 16.00 | 0.00 | 16.00 | EA | 0.00 | \$730.00 | \$0.00 |
| | | 0030 | 1070 | 9020413 | SIGNAL HEAD, TYPE 3C | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$868.00 | \$0.00 |
| | | 0030 | 1080 | 9020414 | SIGNAL HEAD, TYPE 4C | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$955.00 | \$0.00 |
| | | 0030 | 1090 | 9020513 | SIGNAL HEAD, TYPE 3B | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$856.00 | \$0.00 |
| | | 0030 | 1100 | 9020514 | SIGNAL HEAD, TYPE 4B | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$983.00 | \$0.00 |
| | | 0030 | 1110 | 9020833 | SH-FLAT SHEET - SIGNAL SIGN | 363.00 | 0.00 | 363.00 | SQFT | 0.00 | \$30.00 | \$0.00 |
| | | 0030 | 1120 | 9020834 | SIGNAL SIGN, MOUNTING HARDWARE | 72.00 | 0.00 | 72.00 | EA | 0.00 | \$100.00 | \$0.00 |
| | | 0030 | 1130 | 9022708 | POST, SIGNAL 8 FT. OR 2.4 M | 16.00 | 0.00 | 16.00 | EA | 0.00 | \$627.00 | \$0.00 |
| | | 0030 | 1140 | 9024944 | DETECTOR, VEHICLE INDUCTION LOOP (2 CHANNEL - RACK MOUNTED) | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$112.00 | \$0.00 |
| | | 0030 | 1150 | 9025020 | CONDUIT, 1 IN., LOOP DETECTOR WITH TRACER WIRE | 26.00 | 0.00 | 26.00 | LF | 0.00 | \$8.00 | \$0.00 |
| | | 0030 | 1160 | 9025200 | CONDUIT, 2 IN., TRENCH WITH TRACER WIRE | 47.00 | 0.00 | 47.00 | LF | 0.00 | \$9.00 | \$0.00 |
| | | 0030 | 1170 | 9025300 | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE | 481.00 | 0.00 | 481.00 | LF | 70.00 | \$10.50 | \$735.00 |
| | | 0030 | 1180 | 9027300 | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE | 592.00 | 0.00 | 592.00 | LF | 150.00 | \$21.00 | \$3,150.00 |
| | | 0030 | 1190 | 9028100 | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET | 700.00 | 0.00 | 700.00 | LF | 0.00 | \$0.70 | \$0.00 |
| | | 0030 | 1200 | 9028208 | CABLE, 8 AWG 1 CONDUCTOR, POWER | 190.00 | 0.00 | 190.00 | LF | 0.00 | \$1.25 | \$0.00 |
| | | 0030 | 1210 | 9028302 | CABLE, 12 AWG 2 CONDUCTOR | 1,300.00 | 0.00 | 1,300.00 | LF | 0.00 | \$1.20 | \$0.00 |
| | | 0030 | 1220 | 9028308 | CABLE, 16 AWG 2 CONDUCTOR | 3,790.00 | 0.00 | 3,790.00 | LF | 0.00 | \$1.10 | \$0.00 |
| | | 0030 | 1230 | 9028310 | CABLE, 16 AWG 5 CONDUCTOR | 3,760.00 | 0.00 | 3,760.00 | LF | 0.00 | \$1.15 | \$0.00 |
| | | 0030 | 1240 | 9028311 | CABLE, 16 AWG 7 CONDUCTOR | 5,400.00 | 0.00 | 5,400.00 | LF | 0.00 | \$1.20 | \$0.00 |
| | | 0030 | 1250 | 9028500 | CABLE, LOOP DETECTOR, IN DUCT | 300.00 | 0.00 | 300.00 | LF | 0.00 | \$5.00 | \$0.00 |
| | | 0030 | 1260 | 9028510 | CABLE, LOOP DETECTOR, LEAD-IN | 100.00 | 0.00 | 100.00 | LF | 0.00 | \$1.20 | \$0.00 |
| | | 0030 | 1270 | 9028621 | POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$4,000.00 | \$0.00 |
| | | 0030 | 1280 | 9028811 | PULL BOX, PREFORMED CLASS 2 | 9.00 | 0.00 | 9.00 | EA | 1.00 | \$1,050.00 | \$1,050.00 |
| | | 0030 | 1290 | 9028812 | PULL BOX, PREFORMED CLASS 3 | 3.00 | 0.00 | 3.00 | EA | 1.00 | \$1,550.00 | \$1,550.00 |
| | | 0030 | 1300 | 9029100 | BASE, CONCRETE | 13.10 | 0.00 | 13.10 | CUYD | 0.00 | \$1,253.00 | \$0.00 |
| | | 0030 | 1310 | 9029901 | MISC.REMOVE AND REINSTALL EXISTING CABINET TO NEW | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$2,800.00 | \$0.00 |
| | | 0030 | 1320 | 9029902 | BASE MISC.ADJUSTING VIDEO DETECTION ZONE | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$500.00 | \$0.00 |
| | | 0030 | 1330 | 9029902 | MISC.CONROLLER ASSEMBLY, NEMA, TS1 | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$19,620.00 | \$0.00 |

Page 9 of 25 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|-------------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 210122-B01 | J2P2215 | 0030 | 1340 | 9029902 | MISC.DETECTOR PUSH BUTTON APS | 32.00 | 0.00 | 32.00 | EA | 0.00 | \$738.00 | \$0.00 |
| | | 0030 | 1350 | 9029902 | MISC.PEDESTRIAN PUSH BUTTON EXTENSION | 13.00 | 0.00 | 13.00 | EA | 0.00 | \$170.00 | \$0.00 |
| | | 0030 | 1360 | 9029902 | MISC.RAISE SPAN WIRE ASSEMBLY, PER SPAN | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$950.00 | \$0.00 |
| | | 0030 | 1370 | 9029902 | MISC.RELOCATE EXISTING SIGNAL POST, 8 FT OR 15' | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$900.00 | \$0.00 |
| | | 0030 | 1380 | 9029903 | MISC.CONDUIT, STEEL, 2 IN. EXTERNAL ON POST | 160.00 | 0.00 | 160.00 | LF | 0.00 | \$20.00 | \$0.00 |
| | | 0030 | 1390 | 9029903 | MISC.VIDEO CABLE, COMBINATION COAX & 6C | 1,730.00 | 0.00 | 1,730.00 | LF | 0.00 | \$3.50 | \$0.00 |
| | | 0030 | 1400 | 9029903 | MISC.VIDEO CABLE; CAT5E DIRECT BURY (GEL FILLED) | 80.00 | 0.00 | 80.00 | LF | 0.00 | \$3.00 | \$0.00 |
| | | 0040 | 1410 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | 3.70 | 0.00 | 3.70 | CUYD | 2.80 | \$2,400.00 | \$6,720.00 |
| | | 0040 | 1420 | 9031210 | STRUCTURAL STEEL POSTS | 290.00 | 0.00 | 290.00 | LB | 218.00 | \$6.00 | \$1,308.00 |
| | | 0040 | 1430 | 9031280 | 2.5 IN. PSST POST - 12 GA. | 384.00 | 0.00 | 384.00 | LF | 288.00 | \$18.00 | \$5,184.00 |
| | | 0040 | 1440 | 9031281 | POST ANCHOR FOR 2.5 IN. PSST - 7 GA. | 72.00 | 0.00 | 72.00 | LF | 54.00 | \$40.00 | \$2,160.00 |
| | | 0001 | 5001 | 6189901 | MISC.Contract Bond | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$37,581.00 | \$37,581.00 |
| | | 0001 | 5002 | 4079912 | MISC.CPEM-1 | 0.00 | 490.00 | 490.00 | GAL | 0.00 | \$20.08 | \$0.00 |
| | | 0001 | 5003 | 5029907 | MISC.Concrete Material Increase | 0.00 | 123.60 | 123.60 | CUYD | 0.00 | \$148.00 | \$0.00 |
| | | 0001 | 5004 | 1046002 | VALUE ENGINEERING | 0.00 | 10,473.27 | 10,473.27 | EA | 0.00 | \$1.00 | \$0.00 |
| | | 0001 | 5005 | 7269902 | MISC.Disposal of unused 4x2 FES and Slotted Drain | 0.00 | 1.00 | 1.00 | EA | 0.00 | \$2,349.20 | \$0.00 |
| | | 0001 | 5006 | 1094000 | FORCE ACCOUNT | 0.00 | 1.00 | 1.00 | EA | 0.00 | \$685.66 | \$0.00 |
| | | 0001 | 5007 | 6161025 | CHANNELIZER (TRIM LINE) | 0.00 | 470.00 | 470.00 | EA | 470.00 | \$40.00 | \$18,800.00 |
| | Project J | 2P2215 - To | tal Value | Posted to E | Date as of Report Generated Date | | | | | | | \$3,275,986.64 |
| 210122-B01 Ove | erall - Total | Value Pos | ted to Dat | te as of Rep | ort Generated Date | | | | | | | \$3,275,986.64 |

Revision 4/1/2020 Page 10 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J2P2215

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|--|------------------------------|---------------------|----------------------------|---------------------|----------|
| 0050 | 2063000 | CLASS 3 EXCAVATION | 9/7/21 | 9/13/21 | 48.00 | CUYD | Correction | 58+86.23 | | 2+69.90 | | |
| | | | | 9/13/21 | 138.00 | CUYD | P-112,I-112,P-111 and I-111 | 58+86.23 | | 2+69.90 | | |
| | | | 9/8/21 | 9/13/21 | 169.00 | CUYD | P-110,I-110,P-90,I-90,P-109 and I-109 | 58+86.23 | | 2+69.90 | | |
| | | | 9/9/21 | 9/14/21 | 177.00 | CUYD | P-200,I-200,P-108,I-108,P-107 and I-107 | 58+86.23 | | 2+69.90 | | |
| | | | 9/13/21 | 9/14/21 | 172.00 | CUYD | P-106,I-106,P-89,I-89,P-88 and I-88 | 58+86.23 | | 2+69.90 | | |
| | | | 9/14/21 | 9/15/21 | 142.00 | CUYD | P-87,MH-87,P-83,I-83,P-81 and I-81 | 58+86.23 | | 2+69.90 | | |
| | | | 9/15/21 | 9/15/21 | 140.00 | CUYD | P-185,I-185,P-80,I-80,P-79,I-79,P-78,I-78,P-76,I-76,P-75,I-75,P-74 and I-74 | 58+86.23 | | 2+69.90 | | |
| 0090 | 3040504 | TYPE 5 AGGREGATE FOR BASE | 9/1/21 | 9/12/21 | 659.20 | SQYD | Normal St. Rt., C.E. 75+92.49 Rt. and Concrete Base 85+70.61 Rt 86+32.61 Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/9/21 | 9/14/21 | 268.20 | SQYD | Pierce St. Rt., C.E. 76+42.54 Rt., Concrete Base 74+49.36 Rt77+36.36 Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/13/21 | 9/14/21 | -2.80 | SQYD | Curb and gutter Type B Sta. 77+33.36 Rt 79+19.36 Rt., Concrete Base Sta. 77.33.36 Rt 79+23.36 Rt. Area between C.E. 75+92.49 Rt. and C.E. 76+42.54 Rt. and Correction for C.E. 75+92.49 Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/14/21 | 9/15/21 | 43.50 | SQYD | Area between C.E. 76+42.54 Rt. and Pierce St. Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/15/21 | 9/15/21 | 344.80 | SQYD | C.E. 79+46.24 Rt. and Concrete Base and Curb and Gutter Type | 58+86.23 | | 2+69.90 | | |
| | | | | | | | Be from Sta. 79+93.11- Sta. 81+51.11 Rt. | | | | | |
| 0110 | | MISC. GRAVEL OR CR. STONE | | 9/14/21 | | CUYD | | 58+86.23 | | 2+69.90 | | |
| 0150 | 4039905 | | 9/9/21 | | | | Pierce St. Rt. | 58+86.23 | | 2+69.90 | | |
| 0170 | 5021108 | CONCRETE PAVEMENT (8 IN. NON-REINF) | 9/1/21 | | 179.20 | | C.E. 75+92.49 Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/9/21 | 9/14/21 | 45.00 | SQYD | C.E. 76+42.54 Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/13/21 | 9/14/21 | -107.00 | SQYD | Area Between C.E. 75+92.49 Rt. and C.E. 76+42.54 Rt. and correction for C.E. 75+92.49 Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/14/21 | 9/15/21 | 43.50 | SQYD | Area between C.E. 76+42.54 Rt. and Pierce St. Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/15/21 | 9/15/21 | 197.30 | SQYD | C.E. 79+46.24 Rt. | 58+86.23 | | 2+69.90 | | |
| 0180 | 5024008 | CONCRETE BASE (8 IN. NON-REINF) | 9/1/21 | 9/12/21 | 22.40 | SQYD | | 85+70.61 | | 86+32.61 | | |
| | | | 9/9/21 | 9/14/21 | 63.80 | SQYD | | Rt. 74+49.36 | | Rt. 77+36.36 | | |
| | | | | | | | | Rt. | | Rt. | | |
| | | | 9/13/21 | 9/14/21 | 21.00 | SQYD | P-90 | 58+86.23 | | 2+69.90 | | |
| | | | | 9/14/21 | 42.20 | SQYD | | 77+33.36 Rt. | | 79+23.36 Rt. | | |
| | | | 9/15/21 | 9/15/21 | 39.50 | SQYD | | 79+93.11 Rt. | | 81+51.11 Rt. | | |
| 0210 | 6046015A | 15 IN. SLOTTED DRAIN | 9/9/21 | 9/14/21 | 30.00 | LF | I-200 | 58+86.23 | | 2+69.90 | | |
| | | | 9/15/21 | 9/15/21 | 15.00 | LF | I-185 | 58+86.23 | | 2+69.90 | | |
| 0270 | 6085008 | PAVED APPROACH, 8 IN. | 9/1/21 | 9/12/21 | 457.30 | SQYD | Normal St. Rt. and C.E. 75+92.49 Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/9/21 | 9/14/21 | 98.80 | SQYD | Pierce St. Rt. and C.E.76+42.54 Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/15/21 | 9/15/21 | 48.60 | SQYD | C.E. 79+46.24 Rt. | 58+86.23 | | 2+69.90 | | |
| 0310 | 6091052 | CURB AND GUTTER TYPE B | 9/9/21 | 9/14/21 | 39.00 | LF | | 74+49.36 Rt. | | 77+36.36 Rt. | | |
| | | | 9/13/21 | 9/14/21 | 186.00 | LF | | 77+33.36 Rt. | | 79+19.36 Rt. | | |
| | | | 9/15/21 | 9/15/21 | 178.00 | LF | | 79+93.11 Rt. | | 81+51.11 Rt. | | |
| 0320 | 6092012 | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) | 9/1/21 | 9/12/21 | 207.00 | LF | Normal St. Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/9/21 | 9/14/21 | 30.00 | LF | Pierce St. Rt. | 58+86.23 | | 2+69.90 | | |
| | | | 9/15/21 | 9/15/21 | 53.00 | LF | C.E. 79+46.24 Rt. | 58+86.23 | | 2+69.90 | | |
| 0630 | 7250315A | 15 IN. PIPE CULVERT GROUP B | 9/9/21 | 9/14/21 | 101.00 | LF | P-200 and P-107 | 58+86.23 | | 2+69.90 | | |
| | | | 9/13/21 | 9/14/21 | 81.00 | LF | P-P-106 | 58+86.23 | | 2+69.90 | | |
| | | | 9/14/21 | 9/15/21 | 104.00 | LF | P-83 and P-81 | 58+86.23 | | 2+69.90 | | |
| | | | 9/15/21 | | 159.00 | | P-185,P-80,P-79,P-78,P-76,P-75 and P-74 | 58+86.23 | | 2+69.90 | | |
| 0640 | 7250318A | 18 IN. PIPE CULVERT GROUP B | 9/8/21 | 9/13/21 | 105.00 | | P-110 P-109 | 58+86.23 | | 2+69.90 | | |
| | | | 9/9/21 | | 52.00 | | P-108 | 58+86.23 | | 2+69.90 | | |
| 0660 | 72503244 | 24 IN. PIPE CULVERT GROUP B | 9/7/21 | | 138.00 | | P-112 and P-111 | 58+86.23 | | 2+69.90 | | |
| 5000 | . 2000247 | | 9/13/21 | 9/14/21 | 65.00 | | P-88 and P-89 | 58+86.23 | | 2+69.90 | | |
| | | | | 9/15/21 | 48.00 | | P-87 | 30.00.23 | | 2.09.90 | | |
| 0720 | 7261024 | 24 IN. PIPE GROUP A | | 9/13/21 | 38.00 | | P-90 | 58+86.23 | | 2+69.90 | | |
| 0770 | | PRECAST CONCRETE MANHOLE - 48 IN. | | 9/15/21 | 4.00 | | MH-87 | | | 2+69.90 | | |
| | | | | | | | | 58+86.23 | | | | |
| 0810 | | PRECAST CONC. DROP INLET 3 FT X 2 FT-6 I | | 9/15/21 | 12.00 | | I-80,I-79 and I-78 | 58+86.23 | | 2+69.90 | | |
| 0820 | | PRECAST CONCRETE DROP INLET 3 FT X 3 FT | | 9/15/21 | 4.00 | | I-76 | 58+86.23 | | 2+69.90 | | |
| 0860 | 7319913 | MISC. MANHOLES AND DROP INLETS | | 9/13/21 | 6.00 | | P-112 | 58+86.23 | | 2+69.90 | | |
| | | | | 9/13/21 | 12.00 | | I-110,I-109 | 58+86.23 | | 2+69.90 | | |
| | | | 9/9/21 | 9/14/21 | 12.00 | FT | I-108 and I-107 | 58+86.23 | | 2+69.90 | | |
| | | | 9/13/21 | 9/14/21 | 17.00 | FT | I-106,I-88 and I-89 | 58+86.23 | | 2+69.90 | | |
| | | | 9/14/21 | 9/15/21 | 9.00 | FT | I-81 and I-83 | 58+86.23 | | 2+69.90 | | |
| | | | 9/15/21 | 9/15/21 | 6.00 | FT | I-75 and I-74 | 58+86.23 | | 2+69.90 | | |
| 0870 | 7319913 | MISC. MANHOLES AND DROP INLETS | 9/7/21 | 9/13/21 | 6.00 | FT | I-111 | 58+86.23 | | 2+69.90 | | |
| 0010 | | | | | | | | | | 2+69.90 | | |

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 11 of 25



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J2P2215 | 0090 | TYPE 5 AGGREGATE FOR BASE | Material | | 5 | May 16, 2021 | SYSTEM | \$1,340.43 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 5 | May 16, 2021 | SYSTEM | (\$1,340.43) | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | \$6,219.85 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$6,219.85) | |
| | | | | | 7 | Jun 15, 2021 | SYSTEM | \$15,374.45 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 7 | Jun 15, 2021 | SYSTEM | (\$15,374.45) | |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | \$20,222.02 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | (\$20,222.02) | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | \$33,036.64 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | (\$33,036.64) | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | \$40,521.39 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$40,521.39) | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | \$49,262.85 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | (\$49,262.85) | |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | \$62,058.36 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$62,058.36) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$74,005.75 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$74,005.75) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0090 - | · Total | | | | | | \$0.00 | |
| | 0100 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | 8 | Jun 30, 2021 | SYSTEM | \$713.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | (\$713.22) | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | \$713.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | (\$713.22) | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | \$982.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$982.30) | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | \$982.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------------------|--|--------------------|-----------------------------|--------------------|---|--------------------------------|--|--|
| P2215 | 0100 | GRAVEL (A) OR CRUSHED STONE | Material | | 11 | Aug 15, 2021 | SYSTEM | (\$982.30) | |
| | | (B) | | | 12 | Sep 1, 2021 | SYSTEM | \$982.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$982.30) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$982.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$982.30) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0100 - | - Total | | | | | | \$0.00 | |
| | 0110 | MISC. GRAVEL OR CR. STONE | Material | | 7 | Jun 15, 2021 | SYSTEM | \$666.54 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 7 | Jun 15, 2021 | SYSTEM | (\$666.54) | |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | \$666.54 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | (\$666.54) | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | \$666.54 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | (\$666.54) | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | \$666.54 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$666.54) | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | \$5,689.74 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | (\$5,689.74) | |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | \$7,694.19 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | | | | | Estimate Exception of the surrent raymont Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$7,694.19) | Estimate Exception 6 on the dutant regiment Estimate. |
| | | | | | 13 | | SYSTEM | (\$7,694.19) \$7,858.41 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | | 2021 Sep 15, | | , , , | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment |
| | | | | - Total | 13 | 2021 Sep 15, 2021 Sep 15, | SYSTEM | \$7,858.41 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment |
| | | | Material - To | | 13 | 2021 Sep 15, 2021 Sep 15, | SYSTEM | \$7,858.41 (\$7,858.41) | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment |
| | 0110 - | - Total | Material - To | | 13 | 2021 Sep 15, 2021 Sep 15, | SYSTEM | \$7,858.41 (\$7,858.41) | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment |
| | 0110 - 0170 | CONCRETE PAVEMENT (8 IN. NON-REINF) | | | 13 | 2021 Sep 15, 2021 Sep 15, | SYSTEM | \$7,858.41 (\$7,858.41) \$0.00 \$0.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment |
| | | CONCRETE PAVEMENT (8 IN. | | | 13 | 2021 Sep 15, 2021 Sep 15, 2021 | SYSTEM | \$7,858.41 (\$7,858.41) \$0.00 \$0.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment |
| ı | | CONCRETE PAVEMENT (8 IN. | | | 13 | 2021 Sep 15, 2021 Sep 15, 2021 Jun 15, 2021 | SYSTEM SYSTEM SYSTEM | \$7,858.41 (\$7,858.41) \$0.00 \$0.00 \$0.00 \$13,189.82 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment |
| | | CONCRETE PAVEMENT (8 IN. | | | 13 13 7 7 | 2021 Sep 15, 2021 Sep 15, 2021 Jun 15, 2021 Jun 15, 2021 Jun 30, | SYSTEM SYSTEM SYSTEM SYSTEM | \$7,858.41 (\$7,858.41) \$0.00 \$0.00 \$13,189.82 (\$13,189.82) | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|
| J2P2215 | 0170 | CONCRETE | Material | | | | | | Estimate Exception 4 on the current Payment Estimate. |
| | | PAVEMENT (8 IN. NON-REINF) | | | 9 | Jul 15, 2021 | SYSTEM | (\$29,929.06) | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | \$33,209.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$33,209.30) | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | \$45,485.16 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | (\$45,485.16) | |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | \$64,859.86 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$64,859.86) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$87,270.66 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$87,270.66) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0170 - | Total | | | | | | \$0.00 | |
| | 0180 | CONCRETE BASE (8 IN. NON- REINF) | Material | | 3 | Apr 15, 2021 | SYSTEM | \$3,223.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 3 | Apr 15, 2021 | SYSTEM | (\$3,223.50) | |
| | | | | | 4 | May 2, 2021 | SYSTEM | \$3,223.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 4 | May 2, 2021 | SYSTEM | (\$3,223.50) | |
| | | | | | 5 | May 16, 2021 | SYSTEM | \$3,223.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 5 | May 16, 2021 | SYSTEM | (\$3,223.50) | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | \$38,417.98 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$38,417.98) | |
| | | | | | 7 | Jun 15, 2021 | SYSTEM | \$63,297.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 7 | Jun 15, 2021 | SYSTEM | (\$63,297.26) | |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | \$74,349.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | (\$74,349.26) | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | \$79,924.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | (\$79,924.38) | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | \$109,734.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$109,734.08) | |



| ect | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|
| 215 | 0180 | CONCRETE BASE (8 IN. NON- REINF) | Material | . 760 | 11 | Aug 15, 2021 | SYSTEM | \$129,707.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | (\$129,707.50) | |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | \$148,459.06 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$148,459.06) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$160,057.52 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$160,057.52) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0180 - | Total | | | | | | \$0.00 | |
| | 0190 | WATER - UTILITY ITEM | Material | | 6 | Jun 1, 2021 | SYSTEM | \$730.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$730.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0190 - | Total | | | | | | \$0.00 | |
| | 0200 | PIPE COLLAR, TYPE A | Material | | 5 | May 16, 2021 | SYSTEM | \$1,345.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 5 | May 16, 2021 | SYSTEM | (\$1,345.00) | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | \$1,345.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$1,345.00) | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | \$5,380.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$5,380.00) | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | \$5,380.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | (\$5,380.00) | |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | \$5,380.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$5,380.00) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$5,380.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$5,380.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0200 - | Total | | | | | | \$0.00 | |
| | 0260 | PAVED APPROACH, 7 IN. | Material | | 6 | Jun 1, 2021 | SYSTEM | \$3,664.99 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|------------------|---|
| J2P2215 | 0260 | PAVED APPROACH, 7 IN. | Material | | 7 | Jun 15, 2021 | SYSTEM | \$8,236.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 7 | Jun 15, 2021 | SYSTEM | (\$8,236.65) | |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | \$8,236.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | (\$8,236.65) | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | \$8,236.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | (\$8,236.65) | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | \$8,236.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$8,236.65) | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | \$8,236.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | (\$8,236.65) | |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | \$8,236.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$8,236.65) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$8,236.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$8,236.65) | |
| | | | | - Total | | | | \$0.00 | |
| | 0260 - | Total | Material - To | otal | | | | \$0.00 \$0.00 | |
| | 0270 | PAVED APPROACH, 8 IN. | Material | | 5 | May 16, 2021 | SYSTEM | \$9,596.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 5 | May 16, 2021 | SYSTEM | (\$9,596.60) | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | \$9,596.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$9,596.60) | |
| | | | | | 7 | Jun 15, 2021 | SYSTEM | \$26,327.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate. |
| | | | | | 7 | Jun 15, 2021 | SYSTEM | (\$26,327.12) | |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | \$35,428.57 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | (\$35,428.57) | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | \$82,948.98 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | (\$82,948.98) | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | \$90,975.46 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 18 on the current Payment Estimate. |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|---------|--------|--------------------------------|---------------|--------------------|--------|-----------------|---------|----------------|---|
| Froject | Line | Description | Туре | Adjustment Type | Number | Date | By | Amount | (Verillalive |
| J2P2215 | 0270 | PAVED APPROACH, 8 IN. | Material | | 10 | Aug 1, 2021 | SYSTEM | (\$90,975.46) | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | \$120,722.95 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | (\$120,722.95) | |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | \$169,064.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$169,064.25) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$208,460.46 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$208,460.46) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0270 - | Total | | | | | | \$0.00 | |
| | 0310 | CURB AND GUTTER TYPE B | Material | | 6 | Jun 1, 2021 | SYSTEM | \$2,618.55 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$2,618.55) | |
| | | | | | 7 | Jun 15, 2021 | SYSTEM | \$3,187.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | | 7 | Jun 15, 2021 | SYSTEM | (\$3,187.80) | |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | \$13,510.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | (\$13,510.20) | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | \$14,371.66 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 28 on the current Payment Estimate. |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | (\$14,371.66) | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | \$15,244.52 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$15,244.52) | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | \$16,610.72 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | (\$16,610.72) | |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | \$20,891.48 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$20,891.48) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$36,185.32 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$36,185.32) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0310 - | Total | | | | | | \$0.00 | |
| | 0320 | INTEGRAL CURB (6 IN. HEIGHT | Material | | 7 | Jun 15, 2021 | SYSTEM | \$2,110.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment |



| | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|---------|--------|--|--------------------|-----------------------------|------------------|---|---|--|--|--|
| J2P2215 | 0320 | AND UNDER) | Material | | | | | | Estimate Exception 33 on the current Payment Estimate. | |
| | | | | | 7 | Jun 15, 2021 | SYSTEM | (\$2,110.90) | | |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | \$2,737.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. | |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | (\$2,737.90) | | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | \$7,239.76 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 34 on the current Payment Estimate. | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | (\$7,239.76) | | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | \$7,239.76 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 25 on the current Payment Estimate. | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$7,239.76) | | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | \$10,980.86 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate. | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | (\$10,980.86) | | |
| | | | - Total | | 12 | Sep 1, 2021 | SYSTEM | \$16,038.66 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 26 on the current Payment Estimate. | |
| | | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$16,038.66) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$22,099.66 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 26 on the current Payment Estimate. | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$22,099.66) | | |
| | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | | | | | \$0.00 | | |
| | | · Total | | | | | | \$0.00 \$0.00 | | |
| | 0320 - | Total INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE B | Material - To | | 6 | Jun 1, 2021 | SYSTEM | \$0.00 \$0.00 \$13,605.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. | |
| | | INTEGRAL CURB (OVER 6 IN. | | | 6 | | SYSTEM | \$0.00 \$0.00 | Estimate Item Adjustment (0012) due to user buckj overridding Payment | |
| | | INTEGRAL CURB (OVER 6 IN. | | | | 2021 Jun 1, | | \$0.00 \$0.00 \$13,605.90 | Estimate Item Adjustment (0012) due to user buckj overridding Payment | |
| | | INTEGRAL CURB (OVER 6 IN. | | | 6 | Jun 1, 2021 Jun 15, | SYSTEM | \$0.00 \$0.00 \$13,605.90 (\$13,605.90) | Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment | |
| | | INTEGRAL CURB (OVER 6 IN. | | | 6 | Jun 1, 2021 Jun 15, 2021 Jun 15, | SYSTEM | \$0.00 \$0.00 \$13,605.90 (\$13,605.90) \$23,512.50 | Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment | |
| | | INTEGRAL CURB (OVER 6 IN. | | | 6 7 | Jun 1, 2021 Jun 15, 2021 Jun 15, 2021 Jun 30, | SYSTEM SYSTEM | \$0.00 \$0.00 \$13,605.90 (\$13,605.90) \$23,512.50 | Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment | |
| | | INTEGRAL CURB (OVER 6 IN. | | | 6 7 7 8 | 2021 Jun 1, 2021 Jun 15, 2021 Jun 15, 2021 Jun 30, 2021 Jun 30, | SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$13,605.90 (\$13,605.90) \$23,512.50 (\$23,512.50) \$26,898.30 | Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment | |
| | | INTEGRAL CURB (OVER 6 IN. | | | 6 7 7 8 8 8 | 2021 Jun 1, 2021 Jun 15, 2021 Jun 15, 2021 Jun 30, 2021 Jun 30, 2021 Jun 30, 2021 | SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$13,605.90 (\$13,605.90) \$23,512.50 (\$23,512.50) \$26,898.30 | Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment | |
| | | INTEGRAL CURB (OVER 6 IN. | | | 6 7 7 8 8 8 9 | 2021 Jun 1, 2021 Jun 15, 2021 Jun 15, 2021 Jun 30, 2021 Jun 30, 2021 Jul 15, 2021 Jul 15, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$13,605.90 (\$13,605.90) \$23,512.50 (\$23,512.50) \$26,898.30 (\$26,898.30) | Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment | |
| | | INTEGRAL CURB (OVER 6 IN. | | | 6 7 7 8 8 8 9 9 | 2021 Jun 1, 2021 Jun 15, 2021 Jun 30, 2021 Jun 30, 2021 Jun 30, 2021 Jul 15, 2021 Jul 15, 2021 Aug 1, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$13,605.90 (\$13,605.90) \$23,512.50 (\$23,512.50) \$26,898.30 (\$26,898.30) \$26,898.30 | Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate. | |
| | | INTEGRAL CURB (OVER 6 IN. | | | 6 7 7 8 8 9 9 10 | 2021 Jun 1, 2021 Jun 15, 2021 Jun 30, 2021 Jun 30, 2021 Jul 15, 2021 Jul 15, 2021 Aug 1, Aug 1, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$13,605.90 (\$13,605.90) \$23,512.50 (\$23,512.50) \$26,898.30 (\$26,898.30) \$26,898.30 (\$26,898.30) | Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate. | |



| oject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 2215 | 0330 | INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE B | Material | 71- | 12 | Sep 1, 2021 | SYSTEM | \$43,994.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$43,994.50) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$43,994.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$43,994.50) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0330 - | Total | | | | | | \$0.00 | |
| | 0340 | ROCK LINING | Material | | 10 | Aug 1, 2021 | SYSTEM | \$1,512.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$1,512.00) | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | \$1,512.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 26 on the current Payment Estimate. |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | (\$1,512.00) | |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | \$1,512.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 28 on the current Payment Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$1,512.00) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$1,512.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 28 on the current Payment Estimate. |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$1,512.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0340 - | Total | | | | | | \$0.00 | |
| | 0380 | MANHOLE FRAME AND COVER, TYPE 1-A | Material | | 5 | May 16, 2021 | SYSTEM | \$435.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 5 | May 16, 2021 | SYSTEM | (\$435.00) | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | \$435.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 36 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$435.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0380 - | Total | | | | | | \$0.00 | |
| | 0400 | CONSTRUCTION SIGNS | Material | | 3 | Apr 15, 2021 | SYSTEM | \$1,572.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 3 | Apr 15, 2021 | SYSTEM | (\$1,572.00) | |
| | | | | | 4 | May 2, 2021 | SYSTEM | \$1,572.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | | | 01/0==1/ | (\$4 EZO 00) | |
| | | | | | 4 | May 2, 2021 | SYSTEM | (\$1,572.00) | |
| | | | | | 5 | | SYSTEM | \$1,572.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 17 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 2P2215 | 0400 | CONSTRUCTION SIGNS | Material | | 6 | Jun 1, 2021 | SYSTEM | \$1,572.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment Estimate Exception 37 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$1,572.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | 0400 - | Total | | | | | | \$0.00 | |
| | 0410 | ADVANCED WARNING RAIL SYSTEM | Material | | 3 | Apr 15, 2021 | SYSTEM | \$350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 3 | Apr 15, 2021 | SYSTEM | (\$350.00) | |
| | | | | | 4 | May 2, 2021 | SYSTEM | \$350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 4 | May 2, 2021 | SYSTEM | (\$350.00) | |
| | | | | | 5 | May 16, 2021 | SYSTEM | \$350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 5 | May 16, 2021 | SYSTEM | (\$350.00) | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | \$350.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 38 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$350.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0410 - | Total | | | | | | \$0.00 | |
| | 0440 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | Material | | 3 | Apr 15, 2021 | SYSTEM | \$4,950.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 3 | Apr 15, 2021 | SYSTEM | (\$4,950.00) | |
| | | | | | 4 | May 2, 2021 | SYSTEM | \$4,950.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 4 | May 2, 2021 | SYSTEM | (\$4,950.00) | |
| | | | | | 5 | May 16, 2021 | SYSTEM | \$4,950.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 5 | May 16, 2021 | SYSTEM | (\$4,950.00) | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | \$4,950.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user buckj overridding Payment Estimate Exception 39 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$4,950.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0440 - | Total | | | | | | \$0.00 | |
| | 0460 | CMS W/O COMMUNICATION INTERFACE, CONT F/ | Material | | 2 | Apr 1, 2021 | SYSTEM | \$22,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | JOH 17 | | | 2 | Apr 1, 2021 | SYSTEM | (\$22,000.00) | |
| | | | | | 3 | Apr 15, 2021 | SYSTEM | \$44,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 3 | Apr 15, 2021 | SYSTEM | (\$44,000.00) | |



| 1972 | Project | Line | Description | Adjustment | Other | Est. Number | Created | Created | Amount | Remarks |
|--|---------|--------|--------------------------|---------------|--------------------|----------------|-----------------|---------|---------------|---|
| COMMONICATION Primer Common Com | | | | Туре | Adjustment Type | | Date | Ву | | |
| 4 | J2P2215 | 0460 | COMMUNICATION INTERFACE, | Material | | 4 | | SYSTEM | \$44,000.00 | Estimate Item Adjustment (0009) due to user buckj overridding Payment |
| 2021 Swy 16 Swy | | | | | | 4 | | SYSTEM | (\$44,000.00) | |
| 2021 6 | | | | | | 5 | | SYSTEM | \$44,000.00 | Estimate Item Adjustment (0012) due to user buckj overridding Payment |
| 2021 | | | | | | 5 | | SYSTEM | (\$44,000.00) | |
| Total | | | | | | 6 | | SYSTEM | \$44,000.00 | Estimate Item Adjustment (0017) due to user buckj overridding Payment |
| Material - Total | | | | | | 6 | | SYSTEM | (\$44,000.00) | |
| 10 | | | | | - Total | | | | \$0.00 | |
| 10 | | | | Material - To | otal | | | | \$0.00 | |
| BACKFILL 2021 SYSTEM Estimate Exception 20 on the current Payment Estimate. | | 0460 - | Total | | | | | | \$0.00 | |
| 11 | | 0560 | | Material | | 10 | | SYSTEM | \$18,411.00 | Estimate Item Adjustment (0014) due to user buckj overridding Payment |
| 2021 | | | | | | 10 | | SYSTEM | (\$18,411.00) | |
| 12 Sep 1, SYSTEM \$20,995.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 30 on the current Payment Estimate Estimate Exception 30 on the current Payment Estimate Estimate Exception 30 on the current Payment Estimate Estimate Estimate Exception 30 on the current Payment Estimate Estimate Estimate Exception 30 on the current Payment Estimate Estimate Estimate Exception 30 on the current Payment Estimate Estimate Item Adjustment (0010) due to user buck) overridding Payment Estimate Item Adjustment (0010) due to user buck) overridding Payment Estimate Exception 13 on the current Payment Estimate Estimate Exception 13 on the current Payment Estimate Estimate Exception 14 on the current Payment Estimate Exception 14 on the current Payme | | | | | | 11 | | SYSTEM | \$20,349.00 | Estimate Item Adjustment (0013) due to user buckj overridding Payment |
| 2021 Estimate Item Adjustment (0013) due to user buck) overridding Payment | | | | | | 11 | | SYSTEM | (\$20,349.00) | |
| 2021 13 Sep 15, SYSTEM \$20,995.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 30 on the current Payment Estimate. 13 Sep 15, SYSTEM \$0.00 | | | | | | 12 | | SYSTEM | \$20,995.00 | Estimate Item Adjustment (0013) due to user buckj overridding Payment |
| 2021 Estimate Item Adjustment (0013) due to user buckj overridding Peyment Estimate Exception 30 on the current Payment Estimate. | | | | | | 12 | | SYSTEM | (\$20,995.00) | |
| Total \$0.00 | | | | | | 13 | | SYSTEM | \$20,995.00 | Estimate Item Adjustment (0013) due to user buckj overridding Payment |
| Material - Total S0.00 | | | | | | 13 | | SYSTEM | (\$20,995.00) | |
| Secondary Control Seco | | | | | - Total | | | \$0.00 | | |
| MISC. MANHOLES Material | | | | Material - To | otal | | | | \$0.00 | |
| AND DROP INLETS 2021 Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 13 on the current Payment Estimate. | | 0560 - | Total | | | | | | \$0.00 | |
| 2021 4 May 2, SYSTEM \$58,672.25 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 13 on the current Payment Estimate. 4 May 2, SYSTEM (\$58,672.25) - Total 50.00 Material - Total | | 0860 | AND DROP | Material | | 3 | | SYSTEM | \$18,053.00 | Estimate Item Adjustment (0010) due to user buckj overridding Payment |
| Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 13 on the current Payment Estimate. 4 May 2, 2021 **Total*** **S0.00 **Material - Total** **Supplies the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. **Apr 15, 2021 **Apr 15, 2021 **SYSTEM** **SYSTEM** **SYSTEM** **SYSTEM** **SYSTEM** **SYSTEM S10,203.70 **This adjustment (0011) due to user buckj overridding Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. **Apr 15, 2021 **Apr | | | | | | 3 | | SYSTEM | (\$18,053.00) | |
| - Total - T | | | | | | 4 | | SYSTEM | \$58,672.25 | Estimate Item Adjustment (0010) due to user buckj overridding Payment |
| Material - Total \$0.00 | | | | | | 4 | | SYSTEM | (\$58,672.25) | |
| \$0.00 MISC. MANHOLES AND DROP INLETS Material 3 Apr 15, 2021 4 May 2, 2021 4 May 2, SYSTEM 4 May 2, SYSTEM 5 SYSTEM | | | | | - Total | | | | \$0.00 | |
| MISC. MANHOLES AND DROP INLETS Material 3 Apr 15, 2021 \$SYSTEM \$3,139.60 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. 3 Apr 15, 2021 \$SYSTEM \$3,139.60 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. 4 May 2, SYSTEM \$10,203.70 This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate. | | | | Material - To | otal | | | | \$0.00 | |
| AND DROP INLETS 2021 Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. 3 Apr 15, 2021 4 May 2, SYSTEM \$10,203.70 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. 4 May 2, SYSTEM (\$10,203.70) | | 0860 - | Total | | | | | | \$0.00 | |
| 2021 4 May 2, 2021 \$10,203.70 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. | | 0870 | AND DROP | Material | | 3 | | SYSTEM | \$3,139.60 | Estimate Item Adjustment (0011) due to user buckj overridding Payment |
| Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. 4 May 2, SYSTEM (\$10,203.70) | | | | | | 3 | Apr 15, 2021 | SYSTEM | (\$3,139.60) | |
| | | | | | | 4 | | SYSTEM | \$10,203.70 | Estimate Item Adjustment (0011) due to user buckj overridding Payment |
| | | | | | | 4 | | SYSTEM | (\$10,203.70) | |



| | Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks | | | | | |
|-----|---------------|---|------------------------|---------------------|----------------|--|----------------------|--|--|---|---|-----------------|--------|------------|
| | | | | Туре | Number | Date | Бу | 44.44 | | | | | | |
| 215 | 0870 | MISC. MANHOLES AND DROP | Material | - Total | | | | \$0.00 | | | | | | |
| | | INLETS | Material - T | otal | | | | \$0.00 | | | | | | |
| | 0870 - | · Total | | | | | | \$0.00 | | | | | | |
| | 0890 | MISC. MANHOLES AND DROP INLETS | Material | | 3 | Apr 15, 2021 | SYSTEM | \$6,005.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | |
| | | | | | 3 | Apr 15, 2021 | SYSTEM | (\$6,005.00) | | | | | | |
| | | | | | 4 | May 2, 2021 | SYSTEM | \$6,005.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | |
| | | | | | 4 | May 2, 2021 | SYSTEM | (\$6,005.00) | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | |
| | | | Material - T | otal | | | | \$0.00 | | | | | | |
| | 0890 - | · Total | | | | | | \$0.00 | | | | | | |
| | 0910 | MISC. MANHOLES AND DROP INLETS | Material | | 5 | May 16, 2021 | SYSTEM | \$3,984.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | | | |
| | | | | | 5 | May 16, 2021 | SYSTEM | (\$3,984.60) | | | | | | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | \$7,305.10 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user buckj overridding Payment Estimate Exception 41 on the current Payment Estimate. | | | | | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$7,305.10) | | | | | | |
| | | | | | | | | | | | 7 | Jun 15, 2021 | SYSTEM | \$7,305.10 |
| | | | | | | | | | | | | | | 7 |
| | | | | | | 8 | Jun 30, 2021 | SYSTEM | \$7,305.10 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 34 on the current Payment Estimate. | | | | |
| | | | | | | 8 | Jun 30, 2021 | SYSTEM | (\$7,305.10) | | | | | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | \$7,305.10 | This adjustment offsets the original system-generated Material Payment | | | | | |
| | | | | | | | | | Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 40 on the current Payment Estimate. | | | | | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | (\$7,305.10) | | | | | | |
| | | | | - Total | 9 | | SYSTEM | (\$7,305.10) | | | | | | |
| | | | Material - T | | 9 | | SYSTEM | , , , | | | | | | |
| | 0910 - | · Total | Material - T | | 9 | | SYSTEM | \$0.00 | | | | | | |
| | 0910 - | Total CURB INLET CHECK | Material - T | | 9 | | SYSTEM | \$0.00 \$0.00 | | | | | | |
| | | CURB INLET | | | | 2021 Jun 1, | | \$0.00 \$0.00 \$0.00 | Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user buckj overridding Payment | | | | | |
| | | CURB INLET | | | 6 | Jun 1, 2021 Jun 1, | SYSTEM | \$0.00 \$0.00 \$0.00 \$5,220.00 | Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user buckj overridding Payment | | | | | |
| | | CURB INLET | | | 6 | Jun 1, 2021 Jun 1, 2021 Jun 15, | SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 \$5,220.00 (\$5,220.00) | Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user buckj overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment | | | | | |
| | | CURB INLET | | | 6 6 7 | Jun 1, 2021 Jun 1, 2021 Jun 15, 2021 Jun 15, | SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 \$5,220.00 (\$5,220.00) \$5,220.00 | Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user buckj overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment | | | | | |
| | | CURB INLET | | otal - Total | 6 6 7 | Jun 1, 2021 Jun 1, 2021 Jun 15, 2021 Jun 15, | SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 \$5,220.00 (\$5,220.00) \$5,220.00 | Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user buckj overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment | | | | | |
| | 1010 | CURB INLET | Material | otal - Total | 6 6 7 | Jun 1, 2021 Jun 1, 2021 Jun 15, 2021 Jun 15, | SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 \$5,220.00 (\$5,220.00) \$5,220.00 (\$5,220.00) | Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user buckj overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment | | | | | |
| | 1010 | CURB INLET CHECK | Material | otal - Total | 6 6 7 | Jun 1, 2021 Jun 1, 2021 Jun 15, 2021 Jun 15, | SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$0.00 \$5,220.00 (\$5,220.00) \$5,220.00 (\$5,220.00) | Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user buckj overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment | | | | | |
| | 1010 - | CURB INLET CHECK Total PULL BOX, PREFORMED | Material Material - T | otal - Total | 6 6 7 | Jun 1, 2021 Jun 1, 2021 Jun 15, 2021 Jun 15, 2021 | SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$5,220.00 (\$5,220.00) \$5,220.00 (\$5,220.00) \$0.00 \$0.00 | Estimate Exception 40 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user buckj overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 41 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment | | | | | |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|---------|--------|-----------------------------------|---------------|--------------------|--------|-----------------|---------|--------------|---|
| | | | Туре | Adjustment Type | Number | Date | Ву | | |
| J2P2215 | 1290 | PULL BOX, PREFORMED CLASS 3 | Material | | | 2021 | | | Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 42 on the current Payment Estimate. |
| | | OLAGO 3 | | | 7 | Jun 15, 2021 | SYSTEM | (\$1,550.00) | |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | \$1,550.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. |
| | | | | | 8 | Jun 30, 2021 | SYSTEM | (\$1,550.00) | |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | \$1,550.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 41 on the current Payment Estimate. |
| | | | | | 9 | Jul 15, 2021 | SYSTEM | (\$1,550.00) | |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | \$1,550.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$1,550.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 1290 - | Total | | | | | | \$0.00 | |
| | 1410 | CONCRETE FOOTINGS, EMBEDDED | Material | | 3 | Apr 15, 2021 | SYSTEM | \$6,720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 3 | Apr 15, 2021 | SYSTEM | (\$6,720.00) | |
| | | | | | 4 | May 2, 2021 | SYSTEM | \$6,720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 4 | May 2, 2021 | SYSTEM | (\$6,720.00) | |
| | | | | | 5 | May 16, 2021 | SYSTEM | \$6,720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate. |
| | | | | | 5 | May 16, 2021 | SYSTEM | (\$6,720.00) | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | \$6,720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 44 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$6,720.00) | |
| | | | | - Total | | | \$0.00 | | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 1410 - | Total | | | | | | \$0.00 | |
| | 1420 | STRUCTURAL STEEL POSTS | Material | | 3 | Apr 15, 2021 | SYSTEM | \$1,308.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 3 | Apr 15, 2021 | SYSTEM | (\$1,308.00) | |
| | | | | | 4 | May 2, 2021 | SYSTEM | \$1,308.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 4 | May 2, 2021 | SYSTEM | (\$1,308.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 1420 - | Total | | | | | | \$0.00 | |
| | 1430 | 2.5 IN. PSST POST - 12 GA. | Material | | 3 | Apr 15, 2021 | SYSTEM | \$5,184.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 3 | Apr 15, 2021 | SYSTEM | (\$5,184.00) | |
| | | | | | 4 | May 2, | SYSTEM | \$5,184.00 | This adjustment offsets the original system-generated Material Payment |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|-----------|--------|--|---------------|--------------------|------|-----------------|---------|---------------|---|
| Project | Line | Description | Type | Adjustment Type | | Date | By | Amount | Neillains |
| J2P2215 | 1430 | 2.5 IN. PSST POST - 12 GA. | Material | | | 2021 | | | Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 4 | May 2, 2021 | SYSTEM | (\$5,184.00) | |
| | | | | | 5 | May 16, 2021 | SYSTEM | \$5,184.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | | 5 | May 16, 2021 | SYSTEM | (\$5,184.00) | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | \$5,184.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 45 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$5,184.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 1430 - | Total | | | | | | \$0.00 | |
| | 1440 | POST ANCHOR FOR 2.5 IN. PSST - 7 GA. | Material | | 3 | Apr 15, 2021 | SYSTEM | \$2,160.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 3 | Apr 15, 2021 | SYSTEM | (\$2,160.00) | |
| | | | | | 4 | May 2, 2021 | SYSTEM | \$2,160.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 4 | May 2, 2021 | SYSTEM | (\$2,160.00) | |
| | | | | | 5 | May 16, 2021 | SYSTEM | \$2,160.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | | | 5 | May 16, 2021 | SYSTEM | (\$2,160.00) | |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | \$2,160.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 46 on the current Payment Estimate. |
| | | | | | 6 | Jun 1, 2021 | SYSTEM | (\$2,160.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 1440 - | Total | | | | | | \$0.00 | |
| | 5007 | CHANNELIZER (TRIM LINE) | Material | | 10 | Aug 1, 2021 | SYSTEM | \$18,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 28 on the current Payment Estimate. |
| | | | | | 10 | Aug 1, 2021 | SYSTEM | (\$18,800.00) | |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | \$18,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | | 11 | Aug 15, 2021 | SYSTEM | (\$18,800.00) | |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | \$18,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment Estimate Exception 29 on the current Payment Estimate. |
| | | | | | 12 | Sep 1, 2021 | SYSTEM | (\$18,800.00) | |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | \$18,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment Estimate Exception 29 on the current Payment Estimate. |
| | | | | | 13 | Sep 15, 2021 | SYSTEM | (\$18,800.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 5007 - | Total | | | | | | \$0.00 | |
| J2P2215 - | Total | | | | | | | \$0.00 | |
| | | | | | | | | | |



Sep 22, 2021

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|-------|-------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------|---------|
| Overall - | Total | | | | | | | \$0.00 | |