

Pay Estimate Created Date: June 2, 2021

Progress Estimate N 4	lumber	Contract ID Prime Contracto	210122-C06 r Emery Sapp & S	Sons, Inc.	Pay Period Start Pay Period End		Initial Contract Amount Net Change Order Amount Current Contract Amount	\$1,862,575.46 \$3,534.80 \$1,866,110.26			
Approval Date								By User			
June 2, 2021	une 2, 2021				Generated and Approved (and should be considered Draft) at the Project Office Level by						
June 2, 2021		Re	eviewed and Appro	oved (and s	should be considere	ed Draft) at th	e Resident Engineer Level by	penner1			
June 3, 2021			ł	Reviewed	and Approved at th	e Central Offi	ce Controllers Office Level by	greggd1			
Original Completion	n Date	Current Con	npletion Date	Actu	al Completion Dat	% of Current Contract Amour	nount Complete				
December 1, 202	21	Decembe	er 1, 2021				38.07%				
	Contract	Informational Dat	tes		Milest	ones					
Date Description	Original	Completion Date	Current Complet	tion Date	No Milestones Ex	kist for Contra	ict				
Acceptance Date											
Awarded Date	February	3, 2021	February 3, 2021								
Letting Date											
Notice to Proceed Date	otice to Proceed Date March 8,		March 8, 2021								
Work Began Date											

Contract Total Pay For Estimate No. 4				
	This Estimate	Previous	To Date	
210122-C06				
Total Posted Items Pay	\$82,075.00	\$628,346.80	\$710,421.80	
Gross Item Adjustments	\$0.00	\$33,396.00	\$33,396.00	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		<mark>\$661,742.80</mark>	\$743,817.80	
Contract Total Payable This Estimate:	\$82,075.00			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3379	0590	5041000	CONCRETE APPROACH PAVEMENT	SQYD	\$175.000	97	\$16,975.00
	0860	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	SQYD	\$260.000	150	\$39,000.00
	0880	7034219A	TYPE D BARRIER	LF	\$120.000	217.5	\$26,100.00
Project J4P3379	- Total						\$82,075.00
Overall - Total	\$82,075.00						

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3379	0590	CONCRETE APPROACH PAVEMENT	Material	51		-97	\$175.00	(\$16,975.00)
	0590	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user domins1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	97	\$175.00	\$16,975.00
	0860	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material			-150	\$260.00	(\$39,000.00)
	0860	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user domins1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	150	\$260.00	\$39,000.00
	0870	SLAB ON STEEL	Material			-517.5	\$334.00	(\$172,845.00)



Pay Estimate Created Date: June 2, 2021

Progr	ess Est	timate Number 4	Contract ID 210122-C06 Prime Contractor Emery Sapp & Sor			s, Inc. Pay Period End June 1, 2021 Net C	nal Contract hange Order ent Contract	Amount \$	\$1,862,575.46 \$3,534.80 \$1,866,110.26	
Project Number	Line No.	Item Desc	em Description Adjustment Other Item Comments Type Adjustment Type					Line Item Adjustment Unit Price	Adjustment amount	
J4P3379	0870	SLA	B ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user domins1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	517.5	\$334.00	\$172,845.00	
	0880	TYPE	D BARRIER	Material			-217.5	\$120.00	(\$26,100.00	
	0880	TYPE	D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user domins1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	217.5	\$120.00	\$26,100.00	
Total									\$0.00	



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J4P3373	FAF 58-1(40)	Bridge replacement	58	CASS	over Big Creek, 0.1 mile east of Hilltop Rd. and 0.2 mile west of Walnut Street
J4P3379	FAF 291-1(85)	Bridge deck replacement	291	CASS	at Middle Big Creek, 1.3 miles south of Rte. 150 and 0.6 mile north of 163rd Street in Lake Winnebago

Totals by Job Numbers

73	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$0.00	\$0.00
Gross Item Adjustments	\$0.00	\$6,886.75	\$6,886.75
Gross Item Pay	\$0.00	\$6,886.75	\$6,886.75
Incentive	¢0.00	¢0.00	* 0.00
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
79	This Estimate	Previous	To Date
Posted Item Pay	\$82,075.00	\$628,346.80	\$710,421.80
Gross Item Adjustments	\$0.00	\$26,509.25	\$26,509.25
	\$82.075.00	\$654.856.05	\$736,931.05
Gross Item Pay	+,		
		* **	* **
Incentive	\$0.00	\$0.00	\$0.00
		\$0.00 \$0.00	\$0.00 \$0.00
Incentive	\$0.00		



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5031010A, Project Item Line Number 0860, Material Set 5031010A96, Material 1036RSDFEC42M25 - Rein Steel EC No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to resolve discrepancies with steel reinforcement. PAL reports have been submitted but need to be assigned to the proper line numbers with proper amounts.	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5031010A, Project Item Line Number 0860, Material Set 5031010A96, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to resolve discrepancies with steel reinforcement. PAL reports have been submitted but need to be assigned to the proper line numbers with proper amounts.	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5031010A, Project Item Line Number 0860, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Need certification from contractor for pipe.	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5031010A, Project Item Line Number 0860, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Material has been collected by the Materials Department and is being tested. Additionally waiting on 28 Day cylinder break for concrete.	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5031010A, Project Item Line Number 0860, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Material has been collected by the Materials Department and is being tested. Additionally waiting on 28 Day cylinder break for concrete.	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5031010A, Project Item Line Number 0860, Material Set 5031010A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material has been collected by the Materials Department and is being tested. Additionally waiting on 28 Day cylinder break for concrete.	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5041000, Project Item Line Numbe 0590, Material Set 504100096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	r Material has been collected by the Materials Department and is being tested. Additionally waiting on 28 Day cylinder break for concrete.	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5041000, Project Item Line Number 0590, Material Set 504100096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	 Material has been collected by the Materials Department and is being tested. Additionally waiting on 28 Day cylinder break for concrete. 	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5041000, Project Item Line Numbe 0590, Material Set 504100096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Awaiting certifications for cure.	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5041000, Project Item Line Numbe 0590, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Awaiting certification for pipe.	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5041000, Project Item Line Numbe 0590, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@ Acceptance Action Generic ReinforcingMisc is insufficient.		domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 5041000, Project Item Line Number 0590, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@ Acceptance Action Generic ReinforcingMisc is insufficient.		domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034212, Project Item Line Numbe 0870, Material Set 703421296, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	r Material has been collected by the Materials Department and is being tested. Additionally waiting on 28 Day cylinder break for concrete.	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034212, Project Item Line Numbe 0870, Material Set 703421296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	 Material has been collected by the Materials Department and is being tested. Additionally waiting on 28 Day cylinder break for concrete. 	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034212, Project Item Line Numbe 0870, Material Set 703421296, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	 Material has been collected by the Materials Department and is being tested. Additionally waiting on 28 Day cylinder break for concrete. 	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034212, Project Item Line Numbe 0870, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	r Need certifications for deck panels	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034212, Project Item Line Numbe 0870, Material Set 703421296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	r Material has been collected by the Materials Department and is being tested. Additionally waiting on 28 Day cylinder break for concrete.	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034212, Project Item Line Numbe 0870, Material Set 703421296, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	 Working with Materials to resolve discrepancies with steel reinforcement. PAL reports have been submitted but need to be assigned to the proper line numbers with proper amounts. 	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034212, Project Item Line Numbe 0870, Material Set 703421296, Material 1036RSDFEC42M25 - Rein Steel EC No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	 Working with Materials to resolve discrepancies with steel reinforcement. PAL reports have been submitted but need to be assigned to the proper line numbers with proper amounts. 	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034212, Project Item Line Numbe 0870, Material Set 703421296, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	 Working with Materials to resolve discrepancies with steel reinforcement. PAL reports have been submitted but need to be assigned to the proper line numbers with proper amounts. 	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034212, Project Item Line Numbe 0870, Material Set 703421296, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	 Working with Materials to resolve discrepancies with steel reinforcement. PAL reports have been submitted but need to be assigned to the proper line numbers with proper amounts. 	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034212, Project Item Line Numbe 0870, Material Set 703421296, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	 Working with Materials to resolve discrepancies with steel reinforcement. PAL reports have been submitted but need to be assigned to the proper line numbers with proper amounts. 	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034212, Project Item Line Numbe 0870, Material Set 703421296, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	 Working with Materials to resolve discrepancies with steel reinforcement. PAL reports have been submitted but need to be assigned to the proper line numbers with proper amounts. 	domins1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3379, Item 7034219A, Project Item Line Number 0880, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance	Material has been collected by the Materials Department and is being tested. Additionally waiting on 28 Day cylinder break	domins1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status	
Action Generic 0501CCB1.A is insufficient.	for concrete.			
Estimate Exception Type: Item Overrun: Contract 210122-C06, Contract Project J4P3379, Project Item Line Number 0660, Contract Line Item Number 0660, Item 6161031, Minor Item.	Awaiting approval of Change Order 001	domins1	Overridden	



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

loter path Am terms / Am Estimates (including units Estimate) lote: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	eport Generated date and can differ from the posted am Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTE
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
210122-C06	J4P3373	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	0.00	\$1,790.00	\$0.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$3,435.00	\$0.00
		0001	0030	2035500	EMBANKMENT IN PLACE	536.00	0.00	536.00	CUYD	0.00	\$18.00	\$0.00
		0001	0040	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	2.00	0.00	2.00	100F	0.00	\$750.00	\$0.00
		0001	0050	3040163	TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)	492.00	0.00	492.00	SQYD	0.00	\$13.50	\$0.00
		0001	0060	3102003	CRUSHED STONE (B)	185.00	0.00	185.00	SQYD	0.00	\$9.35	\$0.00
		0001	0070	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	56.00	0.00	56.00	TONS	0.00	\$250.43	\$0.0
		0001	0080	4039905	MISC.Optional Pavement; 8" Concrete/10" HMA	492.00	0.00	492.00	SQYD	0.00	\$60.73	\$0.0
		0001	0090	4071005		42.00	0.00	42.00	GAL	0.00	\$2.50	\$0.0
		0001	0100	6113020	FURNISHING TYPE 2 ROCK BLANKET	466.00	0.00	466.00	CUYD	0.00	\$26.50	\$0.0
		0001	0110	6113040	PLACING TYPE 2 ROCK BLANKET	466.00	0.00	466.00	CUYD	0.00	\$14.50	\$0.0
		0001	0120	6161005		986.00	0.00	986.00	SQFT	0.00	\$7.00	\$0.0
		0001	0130	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$85.00	\$0.0
		0001	0140	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	0.00	\$25.00	\$0.0
		0001	0150	6161010		64.00	0.00	64.00	SQFT	0.00	\$7.00	\$0.0
		0001	0160	6161031 6161098A	TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	6.00 3.00	0.00	6.00 3.00	EA	0.00	\$200.00 \$3,250.00	\$0.0 \$0.0
		0001	0180	6181000	RETAINED MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$120,000.00	\$0.0
		0001	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	980.00	0.00	980.00	LF	0.00	\$120,000.00	\$0.0
					PAINT, TYPE P BEADS							
		0001	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	980.00	0.00	980.00	LF	0.00	\$0.50	\$0.0
		0001	0210	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	418.00	0.00	418.00	SQYD	0.00	\$23.06	\$0.0
		0001	0220	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	636.00	0.00	636.00	SQYD	0.00	\$2.75	\$0.0
		0001	0230	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.
		0001	0240	8051000A	SEEDING - COOL SEASON MIXTURES	0.20	0.00	0.20	ACRE	0.00	\$6,250.00	\$0.
		0001	0250	8061016	SEDIMENT REMOVAL	4.00	0.00	4.00	CUYD	0.00	\$36.00	\$0.
		0001	0260	8061017	TEMPORARY SEEDING AND MULCHING	0.20	0.00	0.20	ACRE	0.00	\$4,975.00	\$0.
		0001	0270	8061019	SILT FENCE	328.00	0.00	328.00	LF	0.00	\$1.55	\$0.
		0001	0280	8061050	TYPE C BERM	311.00	0.00	311.00	LF	0.00	\$37.45	\$0.0
		0001	0290	8064134	TYPE 1D EROSION CONTROL BLANKET	519.00	0.00	519.00	SQYD	0.00	\$2.30	\$0.0
		0010	0300	6061060	MGS GUARDRAIL	25.00	0.00	25.00	LF	0.00	\$21.50	\$0.0
		0010	0310	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00	0.00	2.00	EA	0.00	\$2,500.00	\$0.0
		0010	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$2,376.00	\$0.0
		0040	0330	9031270A	2 IN. PSST POST - 12 GA.	51.00	0.00	51.00	LF	0.00	\$12.00	\$0.0
		0040	0340	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	18.00	0.00	18.00	LF	0.00	\$20.00	\$0.0
		0040	0350	9035069A	SHF-FLAT SHEET FLUORESCENT	18.00	0.00	18.00	SQFT	0.00	\$23.00	\$0.0
		0070	0360	2061000	CLASS 1 EXCAVATION	70.00	0.00	70.00	CUYD	0.00	\$85.00	\$0.
		0070	0370	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.00	\$40,000.00	\$0.
		0070	0380	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	130.00	0.00	130.00	SQYD	0.00	\$130.00	\$0.
		0070	0390	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	260.00	0.00	260.00	LF	0.00	\$71.00	\$0.0
		0070	0400	7021214	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	300.00	0.00	300.00	LF	0.00	\$102.00	\$0.
		0070	0410	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	0.00	\$400.00	\$0.0
		0070	0420	7026000	PRE-BORE FOR PILING	40.00	0.00	40.00	LF	0.00	\$135.00	\$0.0
		0070	0430	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	0.00	\$226.92	\$0.0
		0070	0440	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	38.20	0.00	38.20	CUYD	0.00	\$1,300.00	\$0.0



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract		Category		Item	Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTE
1.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See repor generated date)
)122-C06	J4P3373	0070	0450	7034216	TYPE H BARRIER	300.00	0.00	300.00	LF	0.00	\$100.00	\$0.0
		0070	0460	7034222	SLAB ON CONCRETE BEAM	424.00	0.00	424.00	SQYD	0.00	\$370.00	\$0.0
		0070	0470	7059903	MISC.24 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	488.00	0.00	488.00	LF	0.00	\$328.00	\$0.0
		0070	0480	7061060	REINFORCING STEEL (BRIDGES)	2,690.00	0.00	2,690.00	LB	0.00	\$1.80	\$0.
		0070	0490	7129911	MISC.GALVANIZED FABRICATED STRUCTURAL CARBON STEEL (MISC.)	540.00	0.00	540.00	LB	0.00	\$4.35	\$0.
		0070	0500	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,000.00	\$0.
		0070	0510	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	0.00	\$210.00	\$0.
		0070	0520	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	0.00	\$215.00	\$0.
		IP3373 - To			ate as of Report Generated Date							\$0.
	J4P3379	0001	0530	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$8,000.00	\$4,000
		0001	0540	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	14.00	0.00	14.00	SQFT	14.00	\$185.00	\$2,590
		0001	0550	2153000	SHAPING SLOPES, CLASS III	11.00	0.00	11.00	100F	0.00	\$600.00	\$0
		0001	0560	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	28.90	0.00	28.90	TONS	0.00	\$30.00	\$0
		0001	0570	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	181.40	0.00	181.40	TONS	0.00	\$146.21	\$0
		0001	0580	4071005	TACK COAT	171.00	0.00	171.00	GAL	0.00	\$2.50	\$0
		0001	0590	5041000	CONCRETE APPROACH PAVEMENT	128.30	0.00	128.30	SQYD	97.00	\$175.00	\$16,975
		0001	0600	6113020	FURNISHING TYPE 2 ROCK BLANKET	2,219.00	0.00	2,219.00	CUYD	0.00	\$40.50	\$0
		0001	0610	6113040	PLACING TYPE 2 ROCK BLANKET	2,219.00	0.00	2,219.00	CUYD	0.00	\$14.50	\$0
		0001	0620	6161005	CONSTRUCTION SIGNS	1,528.00	112.50	1,640.50	SQFT	1,432.00	\$7.00	\$10,024
		0001	0630	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$85.00	\$170
		0001	0640	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	0.00	\$25.00	\$0
		0001	0650	6161025	CHANNELIZER (TRIM LINE)	80.00	0.00	80.00	EA	15.00	\$22.00	\$330
		0001	0660	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	10.00	14.00	24.00	EA	24.00	\$200.00	\$4,800
		0001	0670	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	3.00	0.00	3.00	EA	3.00	\$3,250.00	\$9,750
		0001	0680	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$113,325.00	\$113,325
		0001	0690	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	52.00	0.00	52.00	LF	0.00	\$26.00	\$0
		0001	0700	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,189.00	0.00	2,189.00	LF	0.00	\$0.50	\$0
		0001	0710	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,206.00	0.00	1,206.00	LF	0.00	\$0.50	\$0
		0001	0720	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,711.00	0.00	1,711.00	SQYD	0.00	\$9.27	\$0
		0001	0730	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	3,329.00	0.00	3,329.00	SQYD	0.00	\$2.50	\$0
		0001	0740	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	8.80	0.00	8.80	STA	0.00	\$650.00	\$0
		0001	0750	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	2.20	0.00	2.20	STA	0.00	\$650.00	\$0
		0001	0760	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.00	\$3,350.00	\$0
		0001	0770	8061005	ROCK DITCH CHECK	60.00	0.00	60.00	LF	60.00	\$24.50	\$1,470
		0001	0780	8061016	SEDIMENT REMOVAL	7.00	0.00	7.00	CUYD	0.00	\$36.00	\$0
		0001	0790	8061019	SILT FENCE	370.00	-34.00	336.00	LF	336.00	\$1.55	\$520
		0001	0800	8061050	TYPE C BERM	1,115.00	0.00	1,115.00	LF	522.00	\$14.50	\$7,569
		0010	0810	6061060	MGS GUARDRAIL	1,175.00	0.00	1,175.00	LF	0.00	\$21.50	\$0
		0010	0820	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULARINO CURB)	4.00	0.00	4.00	EA	0.00	\$2,500.00	\$0
		0010	0830	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,376.00	\$0
		0040	0840	9039902	MISC.RELOCATION OF EXISTING SIGNS	2.00	0.00	2.00	EA	0.00	\$76.00	\$0
		0070	0850	2162500	REMOVAL OF EXISTING BRIDGE DECK	6,222.00	0.00	6,222.00	SQFT	6,222.00	\$11.50	\$71,553
		0070	0860	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	200.00	0.00	200.00	SQYD	150.00	\$260.00	\$39,000
		0070	0870	7034212	SLAB ON STEEL	690.00	0.00	690.00	SQYD	517.50	\$334.00	\$172,845

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note. Posted Q	uanuues	and valu	es are b	ased on R	eport Generated date and can differ from the posted am	ount at th	e ume m	e Estimate v	las Gen	erated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-C06	J4P3379	0070	0880	7034219A	TYPE D BARRIER	290.00	0.00	290.00	LF	217.50	\$120.00	\$26,100.00
		0070	0890	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	10.00	0.00	10.00	SQFT	0.00	\$200.00	\$0.00
		0070	0900	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$3,000.00	\$0.00
		0070	0910	7123610	SLAB DRAIN	26.00	0.00	26.00	EA	26.00	\$400.00	\$10,400.00
		0070	0920	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	5,400.00	0.00	5,400.00	SQFT	5,400.00	\$39.00	\$210,600.00
		0070	0930	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	5,400.00	0.00	5,400.00	SQFT	5,400.00	\$1.00	\$5,400.00
		0070	0940	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$1.00	\$0.00
		0070	0950	7125370A	FINISH FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$1.00	\$0.00
		0070	0960	7126000	NON-DESTRUCTIVE TESTING	60.00	0.00	60.00	LF	60.00	\$50.00	\$3,000.00
	Project J4	4P3379 - To	otal Value	Posted to D	Date as of Report Generated Date							\$710,421.80
210122-C06 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$710,421.80



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code		I	Description	Date Approval Posted								Fro		Offset/ Distance	To Station/	Offset/ Distance	Comments	
						Ì	Date						Lo	g	Diotanoo	Log Mile			
0590				CH PAVEMENT			5/28/21 97.00 SQYD North and south ends of the bridge 5/28/21 150.00 SQYD North and South Ends of Bridge										28 day b	yment for 75% of the material reak to pay full for full	
			APPROACH S		28/21 150.0						full	yment for 75% awaiting 28 da							
0880	7034219A	TYPE D I	BARRIER		6/1/2	1 6/2	2/21 217.5	0 L	Both side	es of bridge							Slip forn the item	barrier 8.5% 0.5" 72 deg. Thi while awaiting 28 day strengt	s is to pay 75% 1
e infor Project	mation be Line Nur		s line are de DWR Date	Total Quantity Posted Fo		applic		nformatio	n	Station	Log Mile	Location	Number	r of Ite	ms	SF Each Sig	In Special Sign	SF Each Special Sign	Total SF to F
, P3379	0620		pril 8, 2021	1382		sp Zu			PASSING		.007		1.00				Detour - 3	19.50	
						sp Z	oecial ??x?? ONE	??.00 NC	PASSING		.037		1.00				Detour - 10	19.50	
						R	11-4 60x30 LOSED TO THF	12.50 R0	AD		.067		2.00		12	2.5			
							special ??x?? ??.00 NO		PASSING		.272		1.00				Detour - 10	19.50	
						w	O20-2 48x48 HEAD	16.00 E	ETOUR		11.132	Detour North	1.00		16	6			
						sp Zi	oecial ??x?? ONE	??.00 NC	PASSING		11.298		1.00				Detour - 1	19.50	
						sp	vecial ??x?? ??.00 NO P DNE vecial ??x?? ??.00 NO P DNE /020-3 48x48 16.00 RO. LOSED AHEAD		PASSING		11.431		1.00				Detour - 3	19.50	
						sp			PASSING		11.547		1.00				Detour - 2	19.50	
						w			OAD		11.681		1.00		16	6			
						w	/020-3a 4x4 LOSED 500 FT		OAD		11.746		1.00		10	6			
						R	11-2 48x30 LOSED	10.00 RC	AD		11.841		1.00		1(0			
						sp	oecial ??x?? ONE	??.00 NC	PASSING		11.857		1.00				Detour - 3	19.50	
						sp Z	oecial ??x?? ONE	??.00 NC	PASSING		11.896		1.00				Detour - 2	19.50	
							oecial ??x?? ONE	??.00 NC	PASSING		116.464		1.00				Detour - 5	19.50	
						sp Z	oecial ??x?? ONE	??.00 NC	PASSING		13.445		1.00				Detour - 1	19.50	
						W	O20-2 48x48 HEAD	16.00 E	ETOUR		13.450		1.00		16	6			
							oecial ??x?? ONE	??.00 NC	PASSING		13.496		1.00				Detour - 6	19.50	
						sp Z(oecial ??x?? ONE	??.00 NC	PASSING		13.547		1.00				Detour - 6	19.50	
						R	11-4 60x30 LOSED TO THE	12.50 R0	AD		13.574		2.00		13	2.5			
						sp Z(Decial ??x?? ONE	??.00 NC	PASSING		13.723		1.00				Detour - 6	19.50	
							O4-8a 24x18			2	13.843		1.00		3			10.50	
						Z	ONE		PASSING		14.371	Detour South	1.00				Detour - 6	19.50	
						z	ONE		PASSING		14.779		1.00				Detour - 1	19.50	
						z	ONE		PASSING		16.445		1.00				Detour - 6	19.50	
						Z	ONE		PASSING		16.48		1.00				Detour - 1	19.50	
						Z	ONE		PASSING		160.514		1.00				Detour - 1	19.50	
						Z	ONE		PASSING		160.698		1.00				Detour - 1	19.50	
						Z	Decial ??x?? DNE				161.249		1.00				Detour - 1	19.50	
						zi	ONE				162.827		1.00				Detour - 1	19.50	
						Z	ONE ??x??				163.950		1.00				Detour - 1	19.50	
						Z	Decial ??x?? DNE				166.218		1.00				Detour - 4	19.50	
						Z	Decial ??x?? DNE				18.18		1.00				Detour - 6	19.50	
						Z	Decial ??x?? DNE Decial ??x??				18.916		1.00				Detour - 1 Detour - 2	19.50	
						Z	Decial ??x?? DNE Decial ??x??				19.571		1.00				Detour - 2 Detour - 7	19.50	
						Z	ONE		PASSING		19.754						Detour - 7	19.50	
						z	Decial ??x?? DNE Decial ??x??				19.757		1.00				Detour - 6	19.50	
						Z	Decial ??x?? DNE Decial ??x??				19.774		1.00				Detour - 3	19.50	
						Z	ONE												
						Z	Decial ??x?? DNE				19.949		1.00				Detour - 6	19.50	
						Z	Decial ??x?? DNE										Detour - 6		
						Z	Decial ??x?? DNE				22.535		1.00				Detour - 6	19.50	
						Z	ONE				23.656		1.00				Detour - 6	19.50	
						sp Zi	Decial ??x?? DNE	??.00 NC	PASSING		25.599		1.00				Detour - 7	19.50	



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

ject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Pos
879 0620		April 8, 2021	1382	ZONE								
				special ??x?? ??.00 NO PASSING ZONE		30.236		1.00		Detour - 6	19.50	19
				special ??x?? ??.00 NO PASSING ZONE		30.791		1.00		Detour - 6	19.50	1
				special ??x?? ??.00 NO PASSING ZONE		33.227		1.00		Detour - 6	19.50	1
				WO20-2 48x48 16.00 DETOUR AHEAD		34.881		1.00	16			
				special ??x?? ??.00 NO PASSING ZONE		34.928		1.00		Detour - 6	19.50	1
				special ??x?? ??.00 NO PASSING ZONE		35.171	A	1.00		Special - 1	32.00	
				special ??x?? ??.00 NO PASSING ZONE		35.318		1.00		Detour - 7	19.50	1
				special ??x?? ??.00 NO PASSING ZONE		35.593		1.00		Detour - 8	19.50	1
				special ??x?? ??.00 NO PASSING ZONE		36.154		1.00		Detour - 9	19.50	1
				special ??x?? ??.00 NO PASSING ZONE		36.246		1.00		Detour - 10	19.50	1
				R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC		36.45	С	2.00	12.5			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		36.553		1.00	16			
				WO20-3a 4x4 16.00 ROAD CLOSED 500 FT		37.013		1.00	16			
				R11-2 48x30 10.00 ROAD CLOSED		37.108		1.00	10			
				special ??x?? ??.00 NO PASSING ZONE		39.477		1.00		Detour - 1	19.50	
				special ??x?? ??.00 NO PASSING ZONE		40.896	В	1.00		Detour - 4	19.50	
				special ??x?? ??.00 NO PASSING ZONE		40.912		1.00		Detour - 5	19.50	
				MO4-8a 24x18 3.00 END DETOUR		40.929		1.00	3			
				special ??x?? ??.00 NO PASSING ZONE		5.984		1.00		Detour - 1	19.50	
					special ??x?? ??.00 NO PASSING ZONE		7.46		1.00		Detour - 1	19.50
				WO20-2 48x48 16.00 DETOUR AHEAD		8.305		1.00	16			
				special ??x?? ??.00 NO PASSING ZONE		8.386		1.00		Special - 2	32.00	
				special ??x?? ??.00 NO PASSING ZONE		8.401		1.00		Detour - 2	19.50	
				special ??x?? ??.00 NO PASSING ZONE		8.460		1.00		Detour - 3	19.50	
				R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC		8.474		2.00	12.5			
				special ??x?? ??.00 NO PASSING ZONE		9.223		1.00		Detour -1	19.50	
				R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC			163rd St.	2.00	12.5			
				R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC			MO 58 West	2.00	12.5			
	0620 - Total		1				r	1. A.	1			1



Jun 3, 2021

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4P3373	0300	MGS GUARDRAIL	Construction	Туре	2	May 3,	SYSTEM	\$344.75	Payment Estimate Item Adjustment generated Stockpile Transaction
J4F JJ7 J	0300	MGS GOARDIVAL	Stockpile		2	2021	STOTEM		
				- Total				\$344.75	
			Construction S	Stockpile STI	MI - Total			\$344.75	
	0300 -							\$344.75	
	0310	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI		2	May 3, 2021	SYSTEM	\$3,390.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$3,390.00	
			Construction S	Stockpile STI	MI - Total			\$3,390.00	
	0310 -							\$3,390.00	
	0320	TYPE A CRSHWTHY END TERMINAL	Construction Stockpile STMI		2	May 3, 2021	SYSTEM	\$3,152.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)		- Total				\$3,152.00	
			Construction Stockpile STMI - Total					\$3,152.00	
	0320 -	Total						\$3,152.00	
J4P3373 -	Total							\$6,886.75	
J4P3379	0590	CONCRETE APPROACH PAVEMENT	Material		4	Jun 2, 2021	SYSTEM	\$16,975.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user domins1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Jun 2, 2021	SYSTEM	(\$16,975.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0590 -	Total						\$0.00	
	0620	CONSTRUCTION SIGNS	Material		1	Apr 16, 2021	SYSTEM	(\$9,674.00)	
				- Total				(\$9,674.00)	
			Material - Tota					(\$9,674.00)	
			MaterialCredit		2	May 3, 2021	SYSTEM	\$9,674.00	
			- Total					\$9,674.00	
			MaterialCredit	- Total				\$9,674.00	
			Other Item MD Adjustment		1	Apr 16, 2021	domins1	\$9,674.00	Adjustment to pay for item that needs materials reporting completed.
					2	May 3, 2021	domins1	(\$9,674.00)	Adjusting for payment on last estimate, material reporting has been completed and system generated payment for item.
				MDPA - Tot	al			\$0.00	
			Other Item Adj	justment - To	otal			\$0.00	
	0620 -	Total						\$0.00	
	0630	ADVANCED WARNING RAIL SYSTEM	Material		1	Apr 16, 2021	SYSTEM	(\$170.00)	
				- Total				(\$170.00)	
			Material - Tota	d .				(\$170.00)	
			MaterialCredit		2	May 3, 2021	SYSTEM	\$170.00	
				- Total				\$170.00	
			MaterialCredit	- Total				\$170.00	
			Other Item Adjustment	MDPA		Apr 16, 2021	domins1	\$170.00	Adjustment to pay for item that needs materials reporting completed.
					2	May 3, 2021	domins1	(\$170.00) \$0.00	Adjusting for payment on last estimate, material reporting has been completed and system generated payment for item.
				MDPA - Tot	MDPA - Total				
			Other Item Adj	justment - To	otal			\$0.00	
	0630 -	Total						\$0.00	
	0650	CHANNELIZER (TRIM LINE)	Material		1	Apr 16, 2021	SYSTEM	(\$330.00)	
				- Total				(\$330.00)	



Jun 3, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3379	0650	CHANNELIZER (TRIM LINE)	Material - Tota	ıl				(\$330.00)	
			MaterialCredit		2	May 3, 2021	SYSTEM	\$330.00	
				- Total				\$330.00	
			MaterialCredit	- Total				\$330.00	
			Other Item Adjustment	MDPA		Apr 16, 2021	domins1	\$330.00	Adjustment to pay for item that needs materials reporting completed.
				MDPA - Tot	2	May 3, 2021	domins1	(\$330.00) \$0.00	Adjusting for payment on last estimate, material reporting has been completed and system generated payment for item.
			Other Item Ad	justment - To	tai			\$0.00	
	0650 -	Total						\$0.00	
	0660	TYPE III MOVEABLE BARRICADE WITH	Material		1	Apr 16, 2021	SYSTEM	(\$4,000.00)	
		LIGHTS		- Total				(\$4,000.00)	
			Material - Tota	l				(\$4,000.00)	
			MaterialCredit		2	May 3, 2021	SYSTEM	\$4,000.00	
				- Total				\$4,000.00	
			MaterialCredit	- Total				\$4,000.00	
			Other Item Adjustment	MDPA	1	Apr 16, 2021	domins1	\$2,000.00	Adjustment to pay for item that needs materials reporting completed.
					2	May 3, 2021	domins1	(\$2,000.00)	Adjusting for payment on last estimate, material reporting has been completed and system generated payment for item.
				MDDA Tot	-1			0.00	14 barricades were added to project, change order in process of being written. This item will pay for the 10 in contract.
				MDPA - Tot				\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
			Overrun	Overrun	1	Apr 16, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 20.000; Overrun Quantity Balance 10.00.
					1	Apr 16, 2021	SYSTEM	(\$2,000.00)	
					2	May 3, 2021	SYSTEM	(\$2,000.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					2	May 3, 2021	SYSTEM	(\$800.00)	
				Overrun - Total				(\$2,800.00)	
			Overrun - Tota	al				(\$2,800.00)	
	0660	Total						(\$2,800.00)	
	0670	CMS W/O COMMUNICATION	Material		1	Apr 16, 2021	SYSTEM	(\$9,750.00)	
		INTERFACE, CONT F/		- Total				(\$9,750.00)	
			Material - Tota	1				(\$9,750.00)	
			MaterialCredit		2	May 3, 2021	SYSTEM	\$9,750.00	
				- Total				\$9,750.00	
			MaterialCredit	- Total				\$9,750.00	
			Other Item Adjustment	MDPA	1	Apr 16, 2021	domins1	\$9,750.00	Adjustment to pay for item that needs materials reporting completed.
			-		2	May 3, 2021	domins1	(\$9,750.00)	Adjusting for payment on last estimate, material reporting has been completed and system generated payment for item.
				MDPA - Tot	al			\$0.00	
			Other Item Adj	justment - To	tal			\$0.00	
	06 <u>70</u> -	Total						\$0.00	
	0770	ROCK DITCH CHECK	Material		1	Apr 16, 2021	SYSTEM	(\$1,470.00)	
				- Total				(\$1,470.00)	



Jun 3, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
I4P3379	0770	ROCK DITCH	Material - Tota					(\$1,470.00)	
		CHECK	MaterialCredit		2	May 3, 2021	SYSTEM	\$1,470.00	
				- Total				\$1,470.00	
			MaterialCredit	- Total				\$1,470.00	
			Other Item Adjustment	MDPA	1	Apr 16, 2021	domins1	\$1,470.00	Adjustment to pay for item that needs materials reporting completed.
					2	May 3, 2021	domins1	(\$1,470.00)	Adjusting for payment on last estimate, material reporting has been completed and system generated payment for item.
				MDPA - Tot				\$0.00	
			Other Item Adj	justment - To	tal			\$0.00	
	0770 -	Total						\$0.00	
	0790	SILT FENCE	Material		1	Apr 16, 2021	SYSTEM	(\$520.80)	
				- Total				(\$520.80)	
			Material - Tota		_			(\$520.80)	
			MaterialCredit		2	May 3, 2021	SYSTEM	\$520.80	
				- Total				\$520.80	
			MaterialCredit	- Total				\$520.80	
			Other Item Adjustment	MDPA	1	Apr 16, 2021	domins1	\$520.80	Adjustment to pay for item that needs materials reporting completed.
					2	May 3, 2021	domins1	(\$520.80)	Adjusting for payment on last estimate, material reporting has been completed and system generated payment for item.
				MDPA - Tot	al			\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
	0790 -	Total						\$0.00	
	0800	TYPE C BERM	Material		1	Apr 16, 2021	SYSTEM	(\$2,987.00)	
				- Total				(\$2,987.00)	
			Material - Tota	I	_			(\$2,987.00)	
			MaterialCredit		2	May 3, 2021	SYSTEM	\$2,987.00	
				- Total				\$2,987.00	
			MaterialCredit	- Total				\$2,987.00	
			Other Item Adjustment	MDPA		Apr 16, 2021	domins1	\$2,987.00	Adjustment to pay for item that needs materials reporting completed.
				2021			domins1	(\$2,987.00)	Adjusting for payment on last estimate, material reporting has been completed and system generated payment for item.
				MDPA - Tot				\$0.00	
			Other Item Ad	ustment - To	ital			\$0.00	
	0800 -							\$0.00	
	0810	MGS GUARDRAIL	Construction Stockpile STMI		2	May 3, 2021	SYSTEM	\$16,225.25	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$16,225.25	
			Construction \$	Stockpile STI	VII - Total			\$16,225.25	
	0810 -	Total						\$16,225.25	
	0820	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI		2	May 3, 2021	SYSTEM	\$6,780.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(- Total				\$6,780.00	
			Construction	Stockpile STI	VII - Total			\$6,780.00	
	0820 -	Total						\$6,780.00	
	0830	TYPE A CRSHWTHY END TERMINAL	Construction Stockpile STMI		2	May 3, 2021	SYSTEM	\$6,304.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)			- Total			\$6,304.00	
			Construction	Stockpile STI	VII - Total			\$6,304.00	
	0830 -	Total						\$6,304.00	



Jun 3, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3379	0860	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		4	Jun 2, 2021	SYSTEM	\$39,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user domins1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 2, 2021	SYSTEM	(\$39,000.00)	
				- Total				\$0.00	
			Material - Tota	I				\$0.00	
	0860 -	Total						\$0.00	
	0870	SLAB ON STEEL	Material		3	May 17, 2021	SYSTEM	\$172,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user domins1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 17, 2021	SYSTEM	(\$172,845.00)	
					4	Jun 2, 2021	SYSTEM	\$172,845.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user domins1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	Jun 2, 2021	SYSTEM	(\$172,845.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0870 -	Total						\$0.00	
	0880	TYPE D BARRIER	Material		4	Jun 2, 2021	SYSTEM	\$26,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user domins1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					4	Jun 2, 2021	SYSTEM	(\$26,100.00)	
				- Total				\$0.00	
			Material - Tota	I				\$0.00	
	0880 -	Total						\$0.00	
J4P3379	I4P3379 - Total								
Overall -	Dverall - Total							\$33,396.00	