

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 18, 2021

Progress Estimate Number	Contract ID	210122-C07	Pay Period Start	October 1, 2021	Original Contract Amount	\$1,028,179.00
4	Prime Contractor	Lehman Construction, LLC	Pay Period End		Net Change Order Amount Current Contract Amount	

Approval Date		By User
October 18, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	vohsr1
October 18, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	domins1
October 19, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021		30.27%

	Milestones						
Date Description	Original Completion Date		No Milestones Exist for Contract				
Acceptance Date							
Awarded Date	February 3, 2021	February 3, 2021					
Letting Date	January 22, 2021	January 22, 2021					
Notice to Proceed Date	March 1, 2021	March 1, 2021					
Work Began Date							

Contract Total Pay For Estimate No. 4				
	This Estimate	Previous	To Date	
210122-C07				
Total Posted Items Pay	\$28,559.17	\$282,630.66	\$311,189.83	
Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustme	nts \$0.00	\$0.00	\$0.00	
_		\$282,630.66	\$311,189.83	
Contract Total Payable This Estimate:	\$28,559.17			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit Unit Price		Current Installed Qty	Current Installed Amount		
J4S3375	0090	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	CUYD	\$50.000	11	\$550.00		
	0100 6096042		PLACING TYPE 2 ROCK DITCH LINER	CUYD	\$30.000	11	\$330.00		
	0200	6181000	MOBILIZATION	LS	\$37,373.330	0.5	\$18,686.67		
	0610	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	CUYD	\$275.000	32.7	\$8,992.50		
Project J4S337	Project J4S3375 - Total								
Overall - Total	Overall - Total								

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3375	0090	FURNISHING TYPE 2 ROCK DITCH LINER	Material			-11	\$50.00	(\$550.00)
	0090	FURNISHING TYPE 2 ROCK DITCH LINER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	11	\$50.00	\$550.00
	0130	CONSTRUCTION SIGNS	Material			-391	\$6.00	(\$2,346.00)
	0130	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1	391	\$6.00	\$2,346.00

Revision 4/1/2020 Page 1 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 18, 2021

Progress Estimate Number
4

Contract ID 210122-C07 Pay Period Start October 1, 2021 Original Contract Amount \$1,028,179.00 Prime Contractor Lehman Construction, LLC Pay Period End October 15, 2021 Net Change Order Amount \$0.00 Current Contract Amount \$1,028,179.00

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
I4S3375					overridding Payment Estimate Exception 2 on the current Payment Estimate.			
	0140	ADVANCED WARNING RAIL SYSTEM	Material			-3	\$36.00	(\$108.00)
	0140	ADVANCED WARNING RAIL SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	3	\$36.00	\$108.00
	0160	CHANNELIZER (TRIM LINE)	Material			-20	\$16.00	(\$320.00)
	0160	CHANNELIZER (TRIM LINE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	20	\$16.00	\$320.00
	0170	TYPE III MOVEABLE BARRICADE WITH LIGHTS	Material			-18	\$115.00	(\$2,070.00)
	0170	BARRICADE WITH LIGHTS generated Material Payment Estimate Iter Adjustment (0001) due to user vohsr overridding Payment Estimate Exception 5 o the current Payment Estimate					\$115.00	\$2,070.00
	0180	WARNING LIGHT, TYPE B	Material			-36	\$40.00	(\$1,440.00)
	0180	WARNING LIGHT, TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	36	\$40.00	\$1,440.00
	0190	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material			-4	\$3,000.00	(\$12,000.00)
	0190	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	4	\$3,000.00	\$12,000.00
	0280	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	Material			-2	\$750.00	(\$1,500.00)
	0280	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	2	\$750.00	\$1,500.00
	0360	TYPE C BERM	Material			-276	\$45.00	(\$12,420.00)
	0360	TYPE C BERM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	276	\$45.00	\$12,420.00
	0560	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material			-181	\$85.00	(\$15,385.00)
	0560	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1	181	\$85.00	\$15,385.00

Revision 4/1/2020 Page 2 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 18, 2021

Progress Estimate Number
4 Contract ID 210122-C07 Pay Period Start October 1, 2021 Original Contract Amount \$1,028,179.00
Prime Contractor Lehman Construction, LLC Pay Period End October 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$1,028,179.00

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3375					overridding Payment Estimate Exception 8 on the current Payment Estimate.			
	0570	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	Material			-295	\$95.00	(\$28,025.00
	0570	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	295	\$95.00	\$28,025.00
	0590	PRE-BORE FOR PILING	Material			-313	\$190.00	(\$59,470.00
	0590	PRE-BORE FOR PILING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	313	\$190.00	\$59,470.00
	0600	PILE POINT REINFORCEMENT	Material			-23	\$180.00	(\$4,140.00)
	0600	PILE POINT REINFORCEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	23	\$180.00	\$4,140.00
	0610	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-112.7	\$275.00	(\$30,992.50)
	0610	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	112.7	\$275.00	\$30,992.50
Total								\$0.00

Revision 4/1/2020 Page 3 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information						
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work						
J4S3375	FAS S302(99)	Bridge replacement	PECULIAR DR	CASS	over East Creek, 1 mile	ver East Creek, 1 mile south of Main Street and 0.2 mile north of 195th Street						
Totals by J	Job Numbe	rs										
1400075												
J4S3375					This Estimate	Previous	To Date					
J4S3375	Poste	d Item Pay			This Estimate \$28,559.17	Previous \$282,630.66	To Date \$311,189.83					
J4S3375		d Item Pay Item Adjustm	ents									
J4S3375			ents Gross Iten	n Pay	\$28,559.17	\$282,630.66	\$311,189.83					
J4S3375		Item Adjustm		n Pay	\$28,559.17 \$0.00	\$282,630.66 \$0.00	\$311,189.83 \$0.00					
J4S3375	Gross	Item Adjustm		n Pay	\$28,559.17 \$0.00 \$28,559.17	\$282,630.66 \$0.00 \$282,630.66	\$311,189.83 \$0.00 \$311,189.83					
J4S3375	Incent Disino	Item Adjustm	Gross Iten	n Pay	\$28,559.17 \$0.00 \$28,559.17 \$0.00	\$282,630.66 \$0.00 \$282,630.66 \$0.00	\$311,189.83 \$0.00 \$311,189.83 \$0.00					

Revision 4/1/2020 Page 4 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 6096020, Project Item Line Number 0090, Material Set 609602096, Material 0609PDDL - Paved Drainage Material for Ditch Liner, Acceptance Action Generic 0609PDDL is insufficient.	Overrun will be paid with future change order.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 6161005, Project Item Line Number 0130, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on Traffic Control Certs from contractor.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 6161008, Project Item Line Number 0140, Material Set 616100896, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on Traffic Control Certs from contractor.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 6161025, Project Item Line Number 0160, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on Traffic Control Certs from contractor.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 6161031, Project Item Line Number 0170, Material Set 616103196, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on traffic control certs from the contractor.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 6161052, Project Item Line Number 0180, Material Set 616105296, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on traffic control certs from the contractor.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 6161099, Project Item Line Number 0190, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Waiting on traffic control certs from the contractor.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7021212, Project Item Line Number 0560, Material Set 702121296, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7021214, Project Item Line Number 0570, Material Set 702121496, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7026000, Project Item Line Number 0590, Material Set 7026000, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7027000, Project Item Line Number 0600, Material Set 702700096, Material 0702PLPT - Pile Point Reinforcement, Acceptance Action Generic 0702PLPT is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 0610, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on concrete test results.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 0610, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 0610, Material Set 703200396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 0610, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7320030A, Project Item Line Number 0280, Material Set 7320030A96, Material 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 8061050, Project Item Line Number 0360, Material Set 806105096, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden

Revision 4/1/2020 Page 5 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
10122-C07	J4S3375	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE		\$10,000.00	\$10,000.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$18,000.00	\$18,000.00
		0001	0030	2031000	CLASS A EXCAVATION	458.00	0.00	458.00	CUYD	0.00	\$8.00	\$0.00
		0001	0040	2035500	EMBANKMENT IN PLACE	1,014.00	0.00	1,014.00	CUYD	0.00	\$20.00	\$0.00
		0001	0050	2036000	COMPACTING EMBANKMENT	366.00	0.00	366.00	CUYD	0.00	\$6.00	\$0.00
		0001	0060	2063000	CLASS 3 EXCAVATION	147.00	0.00	147.00	CUYD	147.00	\$53.00	\$7,791.00
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	3,363.00	0.00	3,363.00	SQYD	0.00	\$11.00	\$0.00
		0001	0080	4039905	MISC.OPTIONAL PAVEMENT	2,647.60	0.00	2,647.60	SQYD	0.00	\$65.00	\$0.00
		0001	0090	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	18.00	0.00	18.00	CUYD	11.00	\$50.00	\$550.00
		0001	0100	6096042	PLACING TYPE 2 ROCK DITCH LINER	18.00	0.00	18.00	CUYD	11.00	\$30.00	\$330.0
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	506.00	0.00	506.00	CUYD	0.00	\$45.00	\$0.00
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	506.00	0.00	506.00	CUYD	0.00	\$15.00	\$0.00
		0001	0130	6161005	CONSTRUCTION SIGNS	391.00	0.00	391.00	SQFT	391.00	\$6.00	\$2,346.00
		0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	3.00	0.00	3.00	EA	3.00	\$36.00	\$108.00
		0001	0150	6161009	FLAG ASSEMBLY	3.00	0.00	3.00	EA	0.00	\$55.00	\$0.00
		0001	0160	6161025	CHANNELIZER (TRIM LINE)	20.00	0.00	20.00	EA	20.00	\$16.00	\$320.00
		0001	0170	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	18.00	0.00	18.00	EA	18.00	\$115.00	\$2,070.00
		0001	0180	6161052	WARNING LIGHT, TYPE B	36.00	0.00	36.00	EA	36.00	\$40.00	\$1,440.00
		0001	0190	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0001	0200	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$37,373.33	\$37,373.3
		0001	0210	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.0
		0001	0220	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	34.00	0.00	34.00	LF	0.00	\$27.00	\$0.00
		0001	0230	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,827.00	0.00	1,827.00	LF	0.00	\$0.15	\$0.0
		0001	0240	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,907.00	0.00	1,907.00	LF	0.00	\$0.16	\$0.0
		0001	0250	6240104A	SEPARATION GEOTEXTILE	665.00	0.00	665.00	SQYD	0.00	\$5.00	\$0.0
		0001	0260	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$7,100.00	\$7,100.0
		0001	0270	7250330A	30 IN. PIPE GROUP B	86.00	0.00	86.00	LF	86.00	\$110.00	\$9,460.0
		0001	0280	7320030A	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$750.00	\$1,500.0
		0001	0290	8051000A	SEEDING - COOL SEASON MIXTURES	0.60	0.00	0.60	ACRE	0.00	\$7,700.00	\$0.0
		0001	0300	8061003	SEDIMENT TRAP EXCAVATION	20.00	0.00	20.00	CUYD	0.00	\$45.00	\$0.0
		0001	0310	8061004	SEDIMENT TRAP ROCK	20.00	0.00	20.00	CUYD	0.00	\$55.00	\$0.0
		0001	0320	8061005	ROCK DITCH CHECK	64.00	0.00	64.00	LF	0.00	\$20.00	\$0.0
		0001	0330	8061016	SEDIMENT REMOVAL	20.00	0.00	20.00	CUYD	0.00	\$4.00	\$0.0
		0001	0340	8061017	TEMPORARY SEEDING AND MULCHING	0.10	0.00	0.10	ACRE		\$39,000.00	\$0.0
		0001	0350	8061019	SILT FENCE	524.00	0.00	524.00	LF	524.00	\$3.50	\$1,834.0
		0001	0360	8061050	TYPE C BERM	276.00	0.00	276.00	LF	276.00	\$45.00	\$12,420.0
		0001	0370	8064130	TYPE 3 TURF REINFORCEMENT MAT	185.00	0.00	185.00	SQYD	0.00	\$7.00	\$0.0
		0001	0380	8064140	TYPE 3B EROSION CONTROL BLANKET	2,482.00	0.00	2,482.00	SQYD	0.00	\$2.50	\$0.0
			0390	2153000	SHAPING SLOPES, CLASS III	4.00	0.00	4.00	100F	0.00	\$2,250.00	\$0.0
		0001			, .							
		0010	0400	6061010	GUARDRAIL MGS GUARDRAIL	125.00	0.00	125.00	LF	0.00	\$24.00	\$0.0
		0010	0410	6061060	MGS GUARDRAIL	225.00	0.00	225.00	LF	0.00	\$25.00	\$0.0
		0010	0420	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	325.00	0.00	325.00	LF	0.00	\$27.00	\$0.0
		0010	0430	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	3.00	0.00	3.00	EA	0.00	\$3,200.00	\$0.00
		0010	0440	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	0.00	\$720.00	\$0.00

Revision 4/1/2020 Page 6 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
)122-C07	J4S3375	0010	0450	6062204A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (NEW CONSTRUCTION ONLY)	1.00	0.00	1.00	EA	0.00	\$2,300.00	\$0.00
		0010	0460	6062303	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	1.00	0.00	1.00	EA	0.00	\$450.00	\$0.00
		0010	0470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,900.00	\$0.00
		0040	0480	9031010	CONCRETE FOOTINGS, EMBEDDED	0.30	0.00	0.30	CUYD	0.00	\$2,400.00	\$0.00
		0040	0490	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	3.00	0.00	3.00	EA	0.00	\$330.00	\$0.00
		0040	0500	9031280	2.5 IN. PSST POST - 12 GA.	36.00	0.00	36.00	LF	0.00	\$20.00	\$0.00
		0040	0510	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	9.00	0.00	9.00	LF	0.00	\$60.00	\$0.00
		0040	0520	9035004A	SH-FLAT SHEET	17.00	0.00	17.00	SQFT	0.00	\$30.00	\$0.00
		0070	0530	2061000	CLASS 1 EXCAVATION	90.00	0.00	90.00	CUYD	90.00	\$18.00	\$1,620.00
		0070	0540	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$33,000.00	\$33,000.00
		0070	0550	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	102.00	0.00	102.00	SQYD	0.00	\$190.00	\$0.0
		0070	0560	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	181.00	0.00	181.00	LF	181.00	\$85.00	\$15,385.0
		0070	0570	7021214	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	357.00	0.00	357.00	LF	295.00	\$95.00	\$28,025.0
		0070	0580	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$950.00	\$1,900.0
		0070	0590	7026000	PRE-BORE FOR PILING	313.00	0.00	313.00	LF	313.00	\$190.00	\$59,470.0
		0070	0600	7027000	PILE POINT REINFORCEMENT	23.00	0.00	23.00	EA	23.00	\$180.00	\$4,140.00
		0070	0610	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	112.70	0.00	112.70	CUYD	112.70	\$275.00	\$30,992.50
		0070	0620	7034216	TYPE H BARRIER	327.00	0.00	327.00	LF	0.00	\$80.00	\$0.0
		0070	0630	7034222	SLAB ON CONCRETE BEAM	513.00	0.00	513.00	SQYD	0.00	\$275.00	\$0.00
		0070	0640	7059903	MISC.24 IN., PRESTRESSED CONCRETE BOX BEAM	439.00	0.00	439.00	LF	0.00	\$350.00	\$0.00
		0070	0650	7061060	REINFORCING STEEL (BRIDGES)	8,010.00	0.00	8,010.00	LB	8,010.00	\$1.50	\$12,015.0
		0070	0660	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	0.00	\$525.00	\$0.0
		0070	0670	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0.00
		0070	0680	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	0.00	\$475.00	\$0.00
		0070	0690	7161002	LAMINATED NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	0.00	\$635.00	\$0.00
	Project J	4S3375 - To	tal Value	e Posted to D	late as of Report Generated Date							\$311,189.8
122-C07 Ove	rall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$311,189.83

Revision 4/1/2020 Page 7 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3375

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0090	6096020	FURN. TYPE 2 ROCK DITCH LINER	10/12/21	10/18/21	11.00	CUYD	19th St Pipe outlet, Ditch Lining	246+88.00		247+34.80		
0100	6096042	PLACING TYPE 2 ROCK DITCH LINER	10/12/21	10/18/21	11.00	CUYD	Pile outlet, Ditch lining	248+88.00		247+34.80		
0200	6181000	MOBILIZATION	10/6/21	10/18/21	0.50	LS	Peculiar Dr.	0		1		
0610	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	10/6/21	10/18/21	32.70	CUYD	Bents 2 and 3	247+35.33		248+86.88		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 8 of 13



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4S3375	0090	FURN. TYPE 2 ROCK DITCH LINER	Material		4	Oct 18, 2021	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					4	Oct 18, 2021	SYSTEM	(\$550.00)		
				- Total				\$0.00		
			Material - To	otal						
	0090 -	Total						\$0.00		
	0130	CONSTRUCTION SIGNS	Material		1	Sep 3, 2021	SYSTEM	\$2,091.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					1	Sep 3, 2021	SYSTEM	(\$2,091.00)		
					2	Sep 16, 2021	SYSTEM	\$2,091.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					2	Sep 16, 2021	SYSTEM	(\$2,091.00)		
					3	Oct 1, 2021	SYSTEM	\$2,346.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					3	Oct 1, 2021	SYSTEM	(\$2,346.00)		
					4	Oct 18, 2021	SYSTEM	\$2,346.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					4	Oct 18, 2021	SYSTEM	(\$2,346.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0130 -	· Total						\$0.00		
	0140	ADVANCED WARNING RAIL SYSTEM	Material	Material	1	Sep 3, 2021	SYSTEM	\$108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
						1	Sep 3, 2021	SYSTEM	(\$108.00)	
					2	Sep 16, 2021	SYSTEM	\$108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment	
									Estimate Exception 2 on the current Payment Estimate.	
					2	Sep 16, 2021	SYSTEM	(\$108.00)		
					2		SYSTEM	(\$108.00) \$108.00		
						2021 Oct 1,		` '	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment	
					3	2021 Oct 1, 2021 Oct 1,	SYSTEM	\$108.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment	
					3	2021 Oct 1, 2021 Oct 1, 2021 Oct 18,	SYSTEM SYSTEM	\$108.00 (\$108.00)	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment	
				- Total	3 4	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021	SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment	
			Material - To		3 4	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021	SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment	
	0140 -	·Total	Material - To		3 4	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021	SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00 (\$108.00)	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment	
	0140 -	Total CHANNELIZER (TRIM LINE)			3 4	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021	SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00 (\$108.00) \$0.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment	
		CHANNELIZER			3 4 4	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18, 2021 Oct 18, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00 (\$108.00) \$0.00 \$0.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment	
		CHANNELIZER			3 4 4 3	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18, 2021 Oct 17, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00 (\$108.00) \$0.00 \$0.00 \$320.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment	



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
3375	0160	CHANNELIZER (TRIM LINE)	Material	- Total				\$0.00		
			Material - To	otal				\$0.00		
	0160 -	Total						\$0.00		
	0170	TYPE III MOVEABLE BARRICADE WITH LIGHTS	Material		1	Sep 3, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					1	Sep 3, 2021	SYSTEM	(\$2,070.00)		
					2	Sep 16, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					2	Sep 16, 2021	SYSTEM	(\$2,070.00)		
					3	Oct 1, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					3	Oct 1, 2021	SYSTEM	(\$2,070.00)		
					4	Oct 18, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					4	Oct 18, 2021	SYSTEM	(\$2,070.00)		
				- Total				\$0.00		
			Material - To	al - Total				\$0.00		
	0170 -	Total						\$0.00		
	0180	WARNING LIGHT, TYPE B	Material		1	Sep 3, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					1	Sep 3, 2021	SYSTEM	(\$1,440.00)		
					2	Sep 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					2	Sep 16, 2021	SYSTEM	(\$1,440.00)		
						3	Oct 1, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$1,440.00)		
					4	Oct 18, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					4	Oct 18, 2021	SYSTEM	(\$1,440.00)		
				- Total				\$0.00		
			Material - Total					\$0.00		
	0180 -	Total						\$0.00		
	0190	CMS WITH COMMUNICATION INTERFACE, CONT F	Material		1	Sep 3, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
		CONTE			1	Sep 3, 2021	SYSTEM	(\$12,000.00)		
					2	Sep 16, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					2	Sep 16,	SYSTEM	(\$12,000.00)		
						2021				
					3	2021 Oct 1, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3375	0190	CMS WITH COMMUNICATION INTERFACE,	Material		4	Oct 18, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		CONT F			4	Oct 18, 2021	SYSTEM	(\$12,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0190 -	Total						\$0.00	
	0280	30 IN. GROUP B FLARED END SEC	Material	Material	3	Oct 1, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$1,500.00)	
					4	Oct 18, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					4	Oct 18, 2021	SYSTEM	(\$1,500.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0280 -	Total						\$0.00	
	0350	SILT FENCE	Material		1	Sep 3, 2021	SYSTEM	\$1,834.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					1	Sep 3, 2021	SYSTEM	(\$1,834.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0350 -	Total						\$0.00	
	0360	TYPE C BERM	Material		2	Sep 16, 2021	SYSTEM	\$12,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					2	Sep 16, 2021	SYSTEM	(\$12,420.00)	
					3	Oct 1, 2021	SYSTEM	\$12,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$12,420.00)	
					4	4	Oct 18, 2021	SYSTEM	\$12,420.00
					4	Oct 18, 2021	SYSTEM	(\$12,420.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0360 -	Total						\$0.00	
	0560	GALVANIZED STRUCTURAL STEEL PILES (12	Material		2	Sep 16, 2021	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		IN			2	Sep 16, 2021	SYSTEM	(\$15,385.00)	
					3	Oct 1, 2021	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$15,385.00)	
					4	Oct 18, 2021	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Oct 18, 2021	SYSTEM	(\$15,385.00)	
				- Total				\$0.00	



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
3375	0560	GALVANIZED STRUCTURAL STEEL PILES (12 IN	Material - To	otal				\$0.00				
	0560 -	Total						\$0.00				
	0570	GALVANIZED STRUCTURAL STEEL PILES (14	Material		3	Oct 1, 2021	SYSTEM	\$28,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
		IN			3	Oct 1, 2021	SYSTEM	(\$28,025.00)				
					4	Oct 18, 2021	SYSTEM	\$28,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					4	Oct 18, 2021	SYSTEM	(\$28,025.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0570 -	Total						\$0.00				
	0590	PRE-BORE FOR PILING	Material		1	Sep 3, 2021	SYSTEM	\$12,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					1	Sep 3, 2021	SYSTEM	(\$12,540.00)				
						2	Sep 16, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
									2	Sep 16, 2021	SYSTEM	(\$59,470.00)
					3	Oct 1, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					3	Oct 1, 2021	SYSTEM	(\$59,470.00)				
				4	4	Oct 18, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
					4	Oct 18, 2021	SYSTEM	(\$59,470.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0590 -	Total						\$0.00				
	0600	PILE POINT REINFORCEMENT	Material		2	Sep 16, 2021	SYSTEM	\$4,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					2	Sep 16, 2021	SYSTEM	(\$4,140.00)				
					3	Oct 1, 2021	SYSTEM	\$4,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
					3	Oct 1, 2021	SYSTEM	(\$4,140.00)				
					4	Oct 18, 2021	SYSTEM	\$4,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
					4	Oct 18, 2021	SYSTEM	(\$4,140.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0600 -	Total						\$0.00				
	0610	CLASS B CONCRETE (SUBSTRUCTURE)	Material		3	Oct 1, 2021	SYSTEM	\$22,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
					3	Oct 1, 2021	SYSTEM	(\$22,000.00)				





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3375	33375 0610 CLASS B CONCRETE (SUBSTRUCTURE)	Material		4	Oct 18, 2021	SYSTEM	\$30,992.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
				4	Oct 18, 2021	SYSTEM	(\$30,992.50)		
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0610 - Total								
J4S3375 -	J4S3375 - Total								
Overall -	Overall - Total								