

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 2, 2021

Progress Estimate Number	Contract ID	210122-C07	Pay Period Start	October 16, 2021	Original Contract Amount	\$1,028,179.00
5	Prime Contractor	Lehman Construction, LL0	C Pay Period End	November 1, 2021	Net Change Order Amount	\$0.00
3					Current Contract Amount	\$1,028,179.00

Approval Date		By User
November 2, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	vohsr1
November 2, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	penner1
November 3, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021		50.53%

	Contract Informational Dates									
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contrac							
Acceptance Date										
Awarded Date	February 3, 2021	February 3, 2021								
Letting Date	January 22, 2021	January 22, 2021								
Notice to Proceed Date	March 1, 2021	March 1, 2021								
Work Began Date										

Contract Total Pa	ay For Estimate No. 5				
		This Estimate	Previous	To Date	
210122-C07					
	Total Posted Items Pay	\$208,305.00	\$311,189.83	\$519,494.83	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$311,189.83	\$519,494.83	
Contract Total Pa	ayable This Estimate:	\$208.305.00			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4S3375	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	CUYD	\$45.000	506	\$22,770.00
	0120	6113040	PLACING TYPE 2 ROCK BLANKET	CUYD	\$15.000	506	\$7,590.00
	0250	6240104A	SEPARATION GEOTEXTILE	SQYD	\$5.000	665	\$3,325.00
	0640	7059903	MISC.24 IN., PRESTRESSED CONCRETE BOX BEAM	LF	\$350.000	439	\$153,650.00
	0660	7123610	SLAB DRAIN	EA	\$525.000	20	\$10,500.00
	0680	7161000	PLAIN NEOPRENE BEARING PAD	EA	\$475.000	6	\$2,850.00
	0690	7161002	LAMINATED NEOPRENE BEARING PAD	EA	\$635.000	12	\$7,620.00
Project J4S33	75 - Total						\$208,305.00
Overall - Total							\$208,305.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	<u>Adjustr</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3375	0250	SEPARATION GEOTEXTILE	Material			-665	\$5.00	(\$3,325.00)
	0250	SEPARATION GEOTEXTILE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	665	\$5.00	\$3,325.00
	0280	30 IN. OR ALLOWED SUBSTITUTE GROUP B	Material			-2	\$750.00	(\$1,500.00)

Revision 4/1/2020 Page 1 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 2, 2021

Progress Estimate Number 5 Contract ID 210122-C07 Pay Period Start October 16, 2021 Original Contract Amount \$1,028,179.00 Prime Contractor Lehman Construction, LLC Pay Period End November 1, 2021 Net Change Order Amount \$0.00 Current Contract Amount \$1,028,179.00 Prime Contract Am

ect	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
375		FLARED END SECTION						
	0280	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	2	\$750.00	\$1,500.00
	0560	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material			-181	\$85.00	(\$15,385.00
	0560	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	181	\$85.00	\$15,385.00
	0570	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	Material			-295	\$95.00	(\$28,025.00
	0570	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	295	\$95.00	\$28,025.00
	0590	PRE-BORE FOR PILING	Material			-313	\$190.00	(\$59,470.00
	0590	PRE-BORE FOR PILING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	313	\$190.00	\$59,470.00
	0600	PILE POINT REINFORCEMENT	Material			-23	\$180.00	(\$4,140.00
	0600	PILE POINT REINFORCEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	23	\$180.00	\$4,140.00
	0610	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-112.7	\$275.00	(\$30,992.50
	0610	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	112.7	\$275.00	\$30,992.50
	0640	MISC.	Material			-439	\$350.00	(\$153,650.00
	0640	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	439	\$350.00	\$153,650.00
	0660	SLAB DRAIN	Material			-20	\$525.00	(\$10,500.00
	0660	SLAB DRAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	20	\$525.00	\$10,500.00
								\$0.0

Revision 4/1/2020 Page 2 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4S3375	FAS S302(99)	Bridge replacement	PECULIAR DR	CASS	over East Creek, 1 mile	e south of Main Street and 0	.2 mile north of 195th Street
Totals by J	lob Numbe	rs					
J4S3375					This Estimate	Previous	To Date
	Poste	d Item Pay			\$208,305.00	\$311,189.83	\$519,494.83
	Gross	Item Adjustm	ents		\$0.00	\$0.00	\$0.00
			Gross Iten	n Pay	\$208,305.00	\$311,189.83	\$519,494.83
	Incent	tive			\$0.00	\$0.00	\$0.00
	Disino	entive			\$0.00	\$0.00	\$0.00
	Liquid	lated Damages	S		\$0.00	\$0.00	\$0.00
		Contract Adju			\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 3 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 6240104A, Project Item Line Number 0250, Material Set 6240104A96, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7021212, Project Item Line Number 0560, Material Set 702121296, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7021214, Project Item Line Number 0570, Material Set 702121496, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7026000, Project Item Line Number 0590, Material Set 7026000, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7027000, Project Item Line Number 0600, Material Set 702700096, Material 0702PLPT - Pile Point Reinforcement, Acceptance Action Generic 0702PLPT is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 0610, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 0610, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 0610, Material Set 703200396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 3610, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7059903, Project Item Line Number 0640, Material Set 705990396, Material 0705INCRCPSXX - Girder Nebraska Dsn Various Leng, Acceptance Action Generic 0705INCRCPSXX is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7123610, Project Item Line Number 0660, Material Set 712361096, Material 0712STDRSB - Slab Drain, Acceptance Action Generic 0712STDRSB is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7320030A, Project Item Line Number 0280, Material Set 7320030A96, Material 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden

Revision 4/1/2020 Page 4 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
10122-C07	J4S3375	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	-	\$10,000.00	\$10,000.0
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$18,000.00	\$18,000.0
		0001	0030	2031000	CLASS A EXCAVATION	458.00	0.00	458.00	CUYD	0.00	\$8.00	\$0.0
		0001	0040	2035500	EMBANKMENT IN PLACE	1,014.00	0.00	1,014.00	CUYD	0.00	\$20.00	\$0.0
		0001	0050	2036000	COMPACTING EMBANKMENT	366.00	0.00	366.00	CUYD	0.00	\$6.00	\$0.0
		0001	0060	2063000	CLASS 3 EXCAVATION	147.00	0.00	147.00	CUYD	147.00	\$53.00	\$7,791.0
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	3,363.00	0.00	3,363.00	SQYD	0.00	\$11.00	\$0.0
		0001	0080	4039905	MISC.OPTIONAL PAVEMENT	2,647.60	0.00	2,647.60	SQYD	0.00	\$65.00	\$0.0
		0001	0090	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	18.00	0.00	18.00	CUYD	11.00	\$50.00	\$550.0
		0001	0100	6096042	PLACING TYPE 2 ROCK DITCH LINER	18.00	0.00	18.00	CUYD	11.00	\$30.00	\$330.0
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	506.00	0.00	506.00	CUYD	506.00	\$45.00	\$22,770.0
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	506.00	0.00	506.00	CUYD	506.00	\$15.00	\$7,590.0
		0001	0130	6161005	CONSTRUCTION SIGNS	391.00	0.00	391.00	SQFT	391.00	\$6.00	\$2,346.0
		0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	3.00	0.00	3.00	EA	3.00	\$36.00	\$108.0
		0001	0150	6161009	FLAG ASSEMBLY	3.00	0.00	3.00	EA	0.00	\$55.00	\$0.0
		0001	0160	6161025	CHANNELIZER (TRIM LINE)	20.00	0.00	20.00	EA	20.00	\$16.00	\$320.0
		0001	0170	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	18.00	0.00	18.00	EA	18.00	\$115.00	\$2,070.0
		0001	0180	6161052	WARNING LIGHT, TYPE B	36.00	0.00	36.00	EA	36.00	\$40.00	\$1,440.0
		0001	0190	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.0
		0001	0200	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$37,373.33	\$37,373.3
		0001	0210	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.0
		0001	0220	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	34.00	0.00	34.00	LF	0.00	\$27.00	\$0.0
		0001	0230	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,827.00	0.00	1,827.00	LF	0.00	\$0.15	\$0.
		0001	0240	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,907.00	0.00	1,907.00	LF	0.00	\$0.16	\$0.
		0001	0250	6240104A	SEPARATION GEOTEXTILE	665.00	0.00	665.00	SQYD	665.00	\$5.00	\$3,325.0
		0001	0260	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$7,100.00	\$7,100.0
		0001	0270	7250330A	30 IN. PIPE GROUP B	86.00	0.00	86.00	LF	86.00	\$110.00	\$9,460.0
		0001	0280	7320030A	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END	2.00	0.00	2.00	EA	2.00	\$750.00	\$1,500.0
		0001	0290	8051000A	SECTION SEEDING - COOL SEASON MIXTURES	0.60	0.00	0.60	ACRE	0.00	\$7,700.00	\$0.0
		0001	0300	8061003	SEDIMENT TRAP EXCAVATION	20.00	0.00	20.00	CUYD	0.00	\$45.00	\$0.0
		0001	0310	8061004	SEDIMENT TRAP ROCK	20.00	0.00	20.00	CUYD	0.00	\$55.00	\$0.0
		0001	0320	8061005	ROCK DITCH CHECK	64.00	0.00	64.00	LF	0.00	\$20.00	\$0.0
		0001	0330	8061016	SEDIMENT REMOVAL	20.00	0.00	20.00	CUYD	0.00	\$4.00	\$0.0
		0001	0340	8061017	TEMPORARY SEEDING AND MULCHING	0.10	0.00	0.10	ACRE		\$39,000.00	\$0.0
		0001	0350	8061019	SILT FENCE	524.00	0.00	524.00	LF	524.00	\$3.50	\$1,834.0
		0001	0360	8061050	TYPE C BERM	276.00	0.00	276.00	LF	276.00	\$45.00	\$12,420.0
			0370	8064130	TYPE 3 TURF REINFORCEMENT MAT	185.00	0.00	185.00	SQYD	0.00	\$7.00	\$12,420.
		0001	0370	8064140	TYPE 3B EROSION CONTROL BLANKET	2,482.00	0.00		SQYD	0.00	\$2.50	\$0.
		0001						2,482.00				
		0001	0390	2153000	SHAPING SLOPES, CLASS III	4.00	0.00	4.00	100F	0.00	\$2,250.00	\$0.
		0010	0400	6061010	GUARDRAIL TYPE A	125.00	0.00	125.00	LF	0.00	\$24.00	\$0.
		0010	0410	6061060	MGS GUARDRAIL	225.00	0.00	225.00	LF	0.00	\$25.00	\$0.
		0010	0420	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	325.00	0.00	325.00	LF	0.00	\$27.00	\$0.0
		0010	0430	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	3.00	0.00	3.00	EA	0.00	\$3,200.00	\$0.0
		0010	0440	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	0.00	\$720.00	\$0.0

Revision 4/1/2020 Page 5 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0122-C07	J4S3375	0010	0450	6062204A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (NEW CONSTRUCTION ONLY)	1.00	0.00	1.00	EA	0.00	\$2,300.00	\$0.00
		0010	0460	6062303	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	1.00	0.00	1.00	EA	0.00	\$450.00	\$0.00
		0010	0470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,900.00	\$0.0
		0040	0480	9031010	CONCRETE FOOTINGS, EMBEDDED	0.30	0.00	0.30	CUYD	0.00	\$2,400.00	\$0.0
		0040	0490	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	3.00	0.00	3.00	EA	0.00	\$330.00	\$0.0
		0040	0500	9031280	2.5 IN. PSST POST - 12 GA.	36.00	0.00	36.00	LF	0.00	\$20.00	\$0.0
		0040	0510	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	9.00	0.00	9.00	LF	0.00	\$60.00	\$0.0
		0040	0520	9035004A	SH-FLAT SHEET	17.00	0.00	17.00	SQFT	0.00	\$30.00	\$0.0
		0070	0530	2061000	CLASS 1 EXCAVATION	90.00	0.00	90.00	CUYD	90.00	\$18.00	\$1,620.0
		0070	0540	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$33,000.00	\$33,000.0
		0070	0550	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	102.00	0.00	102.00	SQYD	0.00	\$190.00	\$0.0
		0070	0560	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	181.00	0.00	181.00	LF	181.00	\$85.00	\$15,385.0
		0070	0570	7021214	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	357.00	0.00	357.00	LF	295.00	\$95.00	\$28,025.0
		0070	0580	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$950.00	\$1,900.0
		0070	0590	7026000	PRE-BORE FOR PILING	313.00	0.00	313.00	LF	313.00	\$190.00	\$59,470.0
		0070	0600	7027000	PILE POINT REINFORCEMENT	23.00	0.00	23.00	EA	23.00	\$180.00	\$4,140.0
		0070	0610	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	112.70	0.00	112.70	CUYD	112.70	\$275.00	\$30,992.5
		0070	0620	7034216	TYPE H BARRIER	327.00	0.00	327.00	LF	0.00	\$80.00	\$0.0
		0070	0630	7034222	SLAB ON CONCRETE BEAM	513.00	0.00	513.00	SQYD	0.00	\$275.00	\$0.0
		0070	0640	7059903	MISC.24 IN., PRESTRESSED CONCRETE BOX BEAM	439.00	0.00	439.00	LF	439.00	\$350.00	\$153,650.0
		0070	0650	7061060	REINFORCING STEEL (BRIDGES)	8,010.00	0.00	8,010.00	LB	8,010.00	\$1.50	\$12,015.0
		0070	0660	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	20.00	\$525.00	\$10,500.0
		0070	0670	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0.0
		0070	0680	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$475.00	\$2,850.0
		0070	0690	7161002	LAMINATED NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	12.00	\$635.00	\$7,620.0
	Project J	1S3375 - To	otal Value	Posted to D	ate as of Report Generated Date							\$519,494.8

Revision 4/1/2020 Page 6 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3375

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	10/18/21	11/2/21	193.00	CUYD	South end of bridge	248+57.46		249+01.87		
				11/2/21	313.00	CUYD		246+97.48		247+92.31		
0120	6113040	PLACING TYPE 2 ROCK BLANKET	10/18/21	11/2/21	193.00	CUYD	South end of Bridge	248+57.46		249+01.87		
				11/2/21	313.00	CUYD	North End of bridge	246+97.48		247+92.31		
0250	6240104A	SEPARATION GEOTEXTILE	10/18/21	11/2/21	253.00	SQYD	South end of bridge	248+57.46		249+01.87		
				11/2/21	412.00	SQYD	North end of bridge	426+97.48		247+92.31		
0640	7059903	MISC.	10/21/21	11/2/21	439.00	LF	Peculiar Dr. over East Creek	247+35.33		248+85.79		
0660	7123610	SLAB DRAIN	10/25/21	11/2/21	20.00	EA	Peculiar Dr. Bridge	247+35.33		248+85.79		
0680	7161000	PLAIN NEOPRENE BEARING PAD	10/21/21	11/2/21	6.00	EA	Peculiar Drive bridge over East Creek.	247+35.33		248+85.79		
0690	7161002	LAMINATED NEOPRENE BEARING PAD	10/21/21	11/2/21	12.00	EA	Peculiar Dr. Bridge over East Creek	247+35.33		248+85.79		

The information below this line are details for Construction Signs (if applicable), No Data Available

Revision 4/1/2020 Page 7 of 12



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3375	0090	FURN. TYPE 2 ROCK DITCH LINER	Material		4	Oct 18, 2021	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Oct 18, 2021	SYSTEM	(\$550.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0090 -	Total						\$0.00	
	0130	CONSTRUCTION SIGNS	Material		1	Sep 3, 2021	SYSTEM	\$2,091.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Sep 3, 2021	SYSTEM	(\$2,091.00)	
					2	Sep 16, 2021	SYSTEM	\$2,091.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Sep 16, 2021	SYSTEM	(\$2,091.00)	
					3	Oct 1, 2021	SYSTEM	\$2,346.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$2,346.00)	
					4	Oct 18, 2021	SYSTEM	\$2,346.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Oct 18, 2021	SYSTEM	(\$2,346.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0130 -	Total						\$0.00	
	0140	ADVANCED WARNING RAIL SYSTEM	Material	Material	1	Sep 3, 2021	SYSTEM	\$108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Sep 3, 2021	SYSTEM	(\$108.00)	
					2	Sep 16, 2021	SYSTEM	\$108.00	This adjustment offsets the original system-generated Material Payment
									Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Sep 16, 2021	SYSTEM	(\$108.00)	
					2		SYSTEM SYSTEM	(\$108.00) \$108.00	
						2021 Oct 1,		, ,	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment
					3	2021 Oct 1, 2021 Oct 1,	SYSTEM	\$108.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment
					3	2021 Oct 1, 2021 Oct 1, 2021 Oct 18,	SYSTEM SYSTEM	\$108.00 (\$108.00)	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment
				- Total	3 4	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18,	SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment
			Material - To		3 4	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18,	SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment
	0140 -	·Total	Material - To		3 4	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18,	SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00 (\$108.00)	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment
	0140 - 0160	-Total CHANNELIZER (TRIM LINE)			3 4	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18,	SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00 (\$108.00) \$0.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment
		CHANNELIZER			3 3 4 4	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18, 2021 Oct 18, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00 (\$108.00) \$0.00 \$0.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment
		CHANNELIZER			3 4 4 3	2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18, 2021 Oct 17, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$108.00 (\$108.00) \$108.00 (\$108.00) \$0.00 \$0.00 \$320.00	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3375	0160	CHANNELIZER (TRIM LINE)	Material	- Total				\$0.00	
			Material - T	otal				\$0.00	
	0160 -							\$0.00	
	0170	TYPE III MOVEABLE BARRICADE WITH	Material		1	Sep 3, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		LIGHTS			1	Sep 3, 2021	SYSTEM	(\$2,070.00)	
					2	Sep 16, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Sep 16, 2021	SYSTEM	(\$2,070.00)	
					3	Oct 1, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$2,070.00)	
					4	Oct 18, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Oct 18, 2021	SYSTEM	(\$2,070.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0170 -	Total						\$0.00	
	0180	WARNING LIGHT, TYPE B	Material		1	Sep 3, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				1 2 2 3 3 4	1	Sep 3, 2021	SYSTEM	(\$1,440.00)	
					2	Sep 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Sep 16, 2021	SYSTEM	(\$1,440.00)	
					3	Oct 1, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$1,440.00)	
					4	Oct 18, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Oct 18, 2021	SYSTEM	(\$1,440.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0180 -	Total						\$0.00	
	0190	CMS WITH COMMUNICATION INTERFACE,	Material		1	Sep 3, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		CONT F			1	Sep 3, 2021	SYSTEM	(\$12,000.00)	
					2	Sep 16, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Sep 16, 2021	SYSTEM	(\$12,000.00)	
					3	Oct 1, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3375	0190	CMS WITH COMMUNICATION INTERFACE,	Material		4	Oct 18, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		CONT F			4	Oct 18, 2021	SYSTEM	(\$12,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0190 -	Total						\$0.00	
	0250	SEPARATION GEOTEXTILE	Material		5	Nov 2, 2021	SYSTEM	\$3,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Nov 2, 2021	SYSTEM	(\$3,325.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0250 -	Total						\$0.00	
	0280	30 IN. GROUP B FLARED END SEC	Material		3	Oct 1, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$1,500.00)	
					4	Oct 18, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					4	Oct 18, 2021	SYSTEM	(\$1,500.00)	
					5	Nov 2, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Nov 2, 2021	SYSTEM	(\$1,500.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0280 -	Total						\$0.00	
	0350	SILT FENCE	Material		1	Sep 3, 2021	SYSTEM	\$1,834.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					1	Sep 3, 2021	SYSTEM	(\$1,834.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0350 -	Total						\$0.00	
	0360	TYPE C BERM	Material		2	Sep 16, 2021	SYSTEM	\$12,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					2	Sep 16, 2021	SYSTEM	(\$12,420.00)	
					3	Oct 1, 2021	SYSTEM	\$12,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$12,420.00)	
					4	Oct 18, 2021	SYSTEM	\$12,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					4	Oct 18, 2021	SYSTEM	(\$12,420.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0360 -	Total						\$0.00	
	0560	GALVANIZED STRUCTURAL STEEL PILES (12	Material		2	Sep 16, 2021	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks			
J4S3375	0560	IN	Material	Туре	2	Sep 16,	SYSTEM	(\$15,385.00)				
					3	2021 Oct 1, 2021	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					3	Oct 1, 2021	SYSTEM	(\$15,385.00)	Estimate Exception 7 on the current Payment Estimate.			
					4	Oct 18, 2021	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment			
					4	Oct 18, 2021	SYSTEM	(\$15,385.00)	Estimate Exception 8 on the current Payment Estimate.			
					5	Nov 2, 2021	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment			
					5	Nov 2,	SYSTEM	(\$15,385.00)	Estimate Exception 2 on the current Payment Estimate.			
				Tabel		2021		\$0.00				
			Material - To	- Total				\$0.00 \$0.00				
	0560 -	Total	Wateriai - 10	otai —				\$0.00				
	0570	GALVANIZED STRUCTURAL STEEL PILES (14	Material		3	Oct 1, 2021	SYSTEM	\$28,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
		STEEL PILES (14			3	Oct 1, 2021	SYSTEM	(\$28,025.00)	Estimate Exception 6 on the editority ayment Estimate.			
					4	Oct 18, 2021	SYSTEM	\$28,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					4	Oct 18, 2021	SYSTEM	(\$28,025.00)				
					5	Nov 2, 2021	SYSTEM	\$28,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					5	Nov 2, 2021	SYSTEM	(\$28,025.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0570 -							\$0.00				
	0590	PRE-BORE FOR PILING	Material		1	Sep 3, 2021	SYSTEM	\$12,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					1	Sep 3, 2021	SYSTEM	(\$12,540.00)				
					2	Sep 16, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					2	Sep 16, 2021	SYSTEM	(\$59,470.00)				
					3	Oct 1, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					3	Oct 1, 2021	SYSTEM	(\$59,470.00)				
					4	Oct 18, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
					4	Oct 18, 2021	SYSTEM	(\$59,470.00)				
								5	Nov 2, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Nov 2, 2021	SYSTEM	(\$59,470.00)	, , , , , , , , , , , , , , , , , , , ,			
				- Total				\$0.00				
			Material - To	otal				\$0.00				



Material	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
REINFORCEMENT	4S3375	0590 -	Total						\$0.00	
2021 3		0600		Material		2		SYSTEM	\$4,140.00	Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment
2021 SYSTEM (64,140.00)						2		SYSTEM	(\$4,140.00)	
A						3		SYSTEM	\$4,140.00	Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment
2021 Editionals Item Adjustment (0013) due to user volunt overridding Payment Editionals Exception 11 on the current Payment Estimate.						3		SYSTEM	(\$4,140.00)	
2021 SYSTEM \$4,140.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 6 on the current Payment Estimate						4		SYSTEM	\$4,140.00	Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment
2021 Estimabe Exception 5 on the current Payment Estimate.						4		SYSTEM	(\$4,140.00)	
Total So.00						5		SYSTEM	\$4,140.00	Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment
Material - Total S0.00						5		SYSTEM	(\$4,140.00)	
CLASS B					- Total				\$0.00	
CLASS B CONCRETE (SUBSTRUCTURE)				Material - To	otal				\$0.00	
CONCRETE (SUBSTRUCTURE)		0600 -	Total						\$0.00	
A		0610	CONCRETE	Material		3		SYSTEM	\$22,000.00	Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment
2021 Estimate Item Adjustment (0014) due to user vohar1 overridding Payment Estimate Exception 12 on the current Payment Estimate.						3		SYSTEM	(\$22,000.00)	
2021 5 Nov 2, 2021 5 Nov						4		SYSTEM	\$30,992.50	Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment
2021 Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 5 Nov 2, 2021 \$0.00 \$0.0						4		SYSTEM	(\$30,992.50)	
-Total						5		SYSTEM	\$30,992.50	Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment
Material - Total S0.00						5		SYSTEM	(\$30,992.50)	
Nov 2, 2021 SYSTEM \$153,650.00 This adjustment offsets the original system-generated Material Payment Estimate ltem Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate. Nov 2, 2021 SYSTEM \$153,650.00 - Total					- Total					
Material Superior				Material - To	otal				\$0.00	
2021 Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.		0610 -	Total						\$0.00	
Total \$0.00		0640	MISC.	Material		5		SYSTEM	\$153,650.00	Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment
Material - Total So.00 O640 - Total SLAB DRAIN Material Solution Solution Solution Solution Solution Solution Solution Solution Material - Total Solution Solution Solution Solution Solution Solution Solution Material - Total Solution						5		SYSTEM	(\$153,650.00)	
SLAB DRAIN Material South Standard South South South Standard South Sout					- Total				\$0.00	
SLAB DRAIN Material 5 Nov 2, 2021 \$10,500.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. 7 Nov 2, 2021 \$10,500.00 \$10,50				Material - To	otal				\$0.00	
2021 Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. 5		0640 -	Total						\$0.00	
2021		0660	SLAB DRAIN	Material	rerial	5		SYSTEM	\$10,500.00	Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment
Material - Total \$0.00 0660 - Total \$0.00						5		SYSTEM	(\$10,500.00)	
0660 - Total \$0.00					- Total				\$0.00	
				Material - To	otal				\$0.00	
		0660 -	Total						\$0.00	
4\$3375 - Total \$0.00	4S3375 -	Total							\$0.00	
Overall - Total \$0.00	Overall -	Total							\$0.00	