

Pay Estimate Created Date: October 19, 2021

Progress Estimate Number 12	Contract ID 210122-C09 Pay Period Start October 1, 2021 Original Contract Amoun Prime Contractor Clarkson Construction Company Pay Period End October 15, 2021 Net Change Order Amoun Current Contract Amoun	unt (\$60,848.00)
Approval Date		By User

Approval Date		By User
October 19, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	cracrb1
October 19, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	sandis1
October 20, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021		96.66%

Contract Informational Dates Milestones

Date Description	Original Completion Date	Current Completion Date
Acceptance Date		
Awarded Date	February 3, 2021	February 3, 2021
Letting Date	January 22, 2021	January 22, 2021
Notice to Proceed Date	March 8, 2021	March 8, 2021
Work Began Date	April 23, 2021	April 23, 2021

Date Description	Original	Current	Days	Diary
	Completion	Completion	Remaining on	Charge
	Date	Date	Milestone	Days
Milestone - Calendar Time- JSP B, section 2.1, 192 Days available for completion of contract items.	October 31, 2021	October 31, 2021	11	

Contract Total Pay For Estimate No. 12

210122-C09	
	Total Posted Items Pay
	Gross Item Adjustments
	Incentive
	Disincentive
	Liquidated Damage
	Other Contract Adjustments

This Estimate	Previous	To Date
\$73,978.93	\$1,948,049.92	\$2,022,028.85
\$0.00	\$21,189.39	\$21,189.39
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
	\$1,969,239.31	\$2,043,218.24
4-4 4-4 44		

Contract Total Payable This Estimate: \$73,978.93

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4S3389	0800	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$304.760	3	\$914.28
	0130	4071005	TACK COAT	GAL	\$2.500	32	\$80.00
	0150	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	LF	\$55.000	287	\$15,785.00
	0170	6091051	CURB AND GUTTER TYPE A	LF	\$60.450	20	\$1,209.00
	0380	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$40.000	323	\$12,920.00
	0390	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	SQYD	\$2.290	85	\$194.65
	0560	6079903	MISC.(48 in.) Decorative Pedestrian Fence (Structures)	LF	\$108.000	397	\$42,876.00

 Project J4S3389 - Total
 \$73,978.93

 Overall - Total
 \$73,978.93

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	ine Item Adjustments This Estimate										
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
J4S3389	0040	COMPACTING	Material			-1,680	\$0.50	(\$840.00)			

Revision 4/1/2020 Page 1 of 31



Pay Estimate Created Date: October 19, 2021

Progress Estimate Number
12 Contract ID 210122-C09 Pay Period Start October 1, 2021 Original Contract Amount \$2,152,835.10
Prime Contractor Clarkson Construction Company Pay Period End October 15, 2021 Net Change Order Amount \$60,848.00)
Current Contract Amount \$2,091,987.10

ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
389		EMBANKMENT						
	0040	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user cracrb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,680	\$0.50	\$840.00
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-746	\$15.53	(\$11,585.38
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	746	\$15.53	\$11,585.3
	0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-41	\$31.22	(\$1,280.02
	0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user cracrb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	41	\$31.22	\$1,280.02
	0800	GRAVEL (A) OR CRUSHED STONE (B)	Material			-3	\$304.76	(\$914.28
	0800	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	3	\$304.76	\$914.28
	0120	MISC.	Material			-678	\$120.40	(\$81,631.20
	0120	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	678	\$120.40	\$81,631.20
	0130	TACK COAT	Material			-32	\$2.50	(\$80.00
	0130	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user cracrb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	32	\$2.50	\$80.00
	0150	CHAIN-LINK FENCE (RETAINING WALLS)	Overrun			-66	\$55.00	(\$3,630.00
	0150	CHAIN-LINK FENCE (RETAINING WALLS)	Material			-287	\$55.00	(\$15,785.00
	0150	CHAIN-LINK FENCE (RETAINING WALLS)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 69 on the current Payment Estimate. Material Insufficiency Quantity 287.000; Overrun Quantity Balance 66.00.	66	\$55.00	\$3,630.00
	0150	CHAIN-LINK FENCE (RETAINING WALLS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user cracrb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	287	\$55.00	\$15,785.00
	0160	MODIFIED CONCRETE GUTTER TYPE B	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-66	\$46.15	(\$3,045.90
	0160	MODIFIED CONCRETE GUTTER TYPE B	Material			-287	\$46.15	(\$13,245.05

Revision 4/1/2020 Page 2 of 31



Pay Estimate Created Date: October 19, 2021

Progress Estimate Number
12 Contract ID 210122-C09 Pay Period Start October 1, 2021 Original Contract Amount \$2,152,835.10
Prime Contractor Clarkson Construction Company Pay Period End October 15, 2021 Net Change Order Amount (\$60,848.00)
Current Contract Amount \$2,091,987.10

roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
S3389	0160	MODIFIED CONCRETE GUTTER TYPE B	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 70 on the current Payment Estimate. Material Insufficiency Quantity 287.000; Overrun Quantity Balance 66.00.	66	\$46.15	\$3,045.90
	0160	MODIFIED CONCRETE GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user cracrb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	287	\$46.15	\$13,245.05
	0170	CURB AND GUTTER TYPE A	Material			-20	\$60.45	(\$1,209.00
	0170	CURB AND GUTTER TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user cracrb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	20	\$60.45	\$1,209.00
	0180	DRAIN BASIN	Material			-2	\$5,880.25	(\$11,760.50
	0180	DRAIN BASIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user cracrb1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	2	\$5,880.25	\$11,760.50
	0190	FURNISHING TYPE 1 ROCK DITCH LINER	Material			-34	\$58.69	(\$1,995.46
	0190	FURNISHING TYPE 1 ROCK DITCH LINER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user cracrb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	34	\$58.69	\$1,995.46
	0210	FURNISHING TYPE 2 ROCK BLANKET	Material			-323	\$58.69	(\$18,956.87
	0210	FURNISHING TYPE 2 ROCK BLANKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user cracrb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	323	\$58.69	\$18,956.87
	0390	PERMANENT EROSION CONTROL GEOTEXTILE	Material			-570	\$2.29	(\$1,305.30
	0390	PERMANENT EROSION CONTROL GEOTEXTILE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user cracrb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	570	\$2.29	\$1,305.30
	0450	SILT FENCE	Material			-666	\$2.00	(\$1,332.00
	0450	SILT FENCE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user cracrb1 overridding Payment Estimate Exception 68 on the current Payment Estimate.	666	\$2.00	\$1,332.00
	0520	ANCHOR ASSEMBLY, GUARD CABLE 3-STRAND	Material			-2	\$2,712.00	(\$5,424.00
	0520	ANCHOR ASSEMBLY, GUARD CABLE 3-STRAND	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user cracrb1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	2	\$2,712.00	\$5,424.00
	0550	BRIDGE APPROACH SLAB (MINOR ROAD)	Material			-167	\$227.12	(\$37,929.04)

Revision 4/1/2020 Page 3 of 31



Pay Estimate Created Date: October 19, 2021

Progress Estimate Number
12 Contract ID 210122-C09 Pay Period Start October 1, 2021 Original Contract Amount \$2,152,835.10
Prime Contractor Clarkson Construction Company Pay Period End October 15, 2021 Net Change Order Amount \$60,848.00)
Current Contract Amount \$2,091,987.10

roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3389	0550	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user cracrb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	167	\$227.12	\$37,929.04
	0570	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material			-12	\$563.26	(\$6,759.12
	0570	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user cracrb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	12	\$563.26	\$6,759.12
	0580	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material			-33	\$513.26	(\$16,937.58
	0580	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user cracrb1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	33	\$513.26	\$16,937.58
	0640	PILE POINT REINFORCEMENT	Material			-12	\$117.33	(\$1,407.96)
	0640	PILE POINT REINFORCEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user cracrb1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	12	\$117.33	\$1,407.96
	0650	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-68.2	\$1,116.32	(\$76,133.02
	0650	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user cracrb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	68.2	\$1,116.32	\$76,133.02
	0660	TYPE D BARRIER	Material			-415	\$132.87	(\$55,141.05
	0660	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user cracrb1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	415	\$132.87	\$55,141.05
	0670	SLAB ON CONCRETE NU- GIRDER	Material			-831	\$335.02	(\$278,401.62
	0670	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user cracrb1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	831	\$335.02	\$278,401.62
	0680	SIDEWALK (BRIDGES)	Material			-2,536	\$17.22	(\$43,669.92)
	0680	SIDEWALK (BRIDGES)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user cracrb1 overridding Payment Estimate Exception 46 on the current Payment Estimate.	2,536	\$17.22	\$43,669.92
	0690	FORM LINERS	Material			-161	\$65.82	(\$10,597.02
	0690	FORM LINERS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user cracrb1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	161	\$65.82	\$10,597.02
	0700	NU 35, PRESTRESSED	Material			-931	\$289.44	(\$269,468.64)

Revision 4/1/2020 Page 4 of 31



Pay Estimate Created Date: October 19, 2021

Progress Estimate Number
12 Contract ID 210122-C09 Pay Period Start October 1, 2021 Original Contract Amount \$2,152,835.10
Prime Contractor Clarkson Construction Company Pay Period End October 15, 2021 Net Change Order Amount \$2,091,987.10

						urrent Contra		
	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
389		CONCRETE NU-GIRDER						
0)700	NU 35, PRESTRESSED CONCRETE NU-GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user cracrb1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	931	\$289.44	\$269,468.64
0)710	REINFORCING STEEL (BRIDGES)	Material			-13,150	\$1.41	(\$18,541.50)
0)710	REINFORCING STEEL (BRIDGES)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user cracrb1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	13,150	\$1.41	\$18,541.50
0)720	CONDUIT SYSTEM ON STRUCTURE	Material			-1	\$13,119.38	(\$13,119.38)
0)720	CONDUIT SYSTEM ON STRUCTURE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user cracrb1 overridding Payment Estimate Exception 55 on the current Payment Estimate.	1	\$13,119.38	\$13,119.38
0)730	VERTICAL DRAIN AT END BENTS	Material			-2	\$2,001.33	(\$4,002.66)
0)730	VERTICAL DRAIN AT END BENTS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user cracrb1 overridding Payment Estimate Exception 59 on the current Payment Estimate.	2	\$2,001.33	\$4,002.66
0)770	CONCRETE AND MASONRY PROTECTION SYSTEM	Material			-1	\$3,139.86	(\$3,139.86)
0)770	CONCRETE AND MASONRY PROTECTION SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user cracrb1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	1	\$3,139.86	\$3,139.86
0	790	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-2,434	\$72.00	(\$175,248.00)
0	790	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user cracrb1 overridding Payment Estimate Exception 60 on the current Payment Estimate.	2,434	\$72.00	\$175,248.00
0	0080	CONCRETE AND MASONRY PROTECTION SYSTEM	Material			-1	\$3,235.23	(\$3,235.23)
0	0080	CONCRETE AND MASONRY PROTECTION SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user cracrb1 overridding Payment Estimate Exception 58 on the current Payment Estimate.	1	\$3,235.23	\$3,235.23
0	0820	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-2,641	\$72.00	(\$190,152.00)
0	0820	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user cracrb1 overridding Payment Estimate Exception 64 on the current Payment Estimate.	2,641	\$72.00	\$190,152.00
5	5001	TEMPORARY LONG-TERM RUMBLE STRIPS	Material			-12	\$1,207.50	(\$14,490.00)

Revision 4/1/2020 Page 5 of 31



Pay Estimate Created Date: October 19, 2021

Progress Estimate Number	Contract ID 210122-C09	Pay Period Start October 1, 2021 Original Contract Amount \$2,152,835.10
12	Prime Contractor Clarkson Construct	tion Company Pay Period End October 15, 2021 Net Change Order Amount (\$60,848.00)
		Current Contract Amount \$2,091,987.10

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3389	5001	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user cracrb1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	12	\$1,207.50	\$14,490.00
Total								\$0.00

Revision 4/1/2020 Page 6 of 31



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information									
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J4S3389										

J4S3389	FAS S302(92)	Bridge replacement	67th St	JACKSON	at I-435 from Corrington	Avenue and 0.1 mile west of F	Richmond Avenue
Totals by .	Job Numbe	rs					
J4S3389					This Estimate	Previous	To Date
	Poste	d Item Pay			\$73,978.93	\$1,948,049.92	\$2,022,028.85
	Gross	Item Adjustm	ents		\$0.00	\$21,189.39	\$21,189.39
			Gros	s Item Pay	\$73,978.93	\$1,969,239.31	\$2,043,218.24
	Incent	tive			\$0.00	\$0.00	\$0.00
	Disino	entive			\$0.00	\$0.00	\$0.00
	Liquid	lated Damages	s		\$0.00	\$0.00	\$0.00
	Other	Contract Adju	stments	3	\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 7 of 31



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 2036000, Project Item Line Number 0040, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 3040506, Project Item Line Number 0070, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 3105002, Project Item Line Number 0080, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 4019905, Project Item Line Number 0120, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 4071005, Project Item Line Number 0130, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 4071005, Project Item Line Number 0130, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 5031011A, Project Item Line Number 0550, Material Set 5031011A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 5031011A, Project Item Line Number 0550, Material Set 5031011A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 5031011A, Project Item Line Number 0550, Material Set 5031011A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 5031011A, Project Item Line Number 0550, Material Set 5031011A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 5031011A, Project Item Line Number 0550, Material Set 5031011A96, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 5031011A, Project Item Line Number 0550, Material Set 5031011A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 5031011A, Project Item Line Number 0550, Material Set 5031011A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 5031011A, Project Item Line Number 0550, Material Set 5031011A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6064110, Project Item Line Number 0520, Material Set 606411096, Material 1040GUAAZC - Guard Cable Galv Anchor Assembly, Acceptance Action Generic 1040GUAAZC is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6071050, Project Item Line Number 0150, Material Set 607105096, Material 1043FMCLFBAC60 - Chain Link Fence Fabric Alum Coated 60", Acceptance Action Generic 1043FMCLFBAC60 is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6071102, Project Item Line Number 0160, Material Set 607110296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6071102, Project Item Line Number 0160, Material Set 607110296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6071102, Project Item Line Number 0160, Material Set 607110296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6091051, Project Item Line Number 0170, Material Set 609105196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6091051, Project Item Line Number 0170, Material Set 609105196, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6091051, Project Item Line Number 0170, Material Set 609105196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6094010, Project Item Line Number 0180, Material Set 609401096, Material 0614DFGTCV - Curved Vane Grate and Frame, Acceptance	Working with contractor and materials to resolve.	cracrb1	Overridden

Revision 4/1/2020 Page 8 of 31



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered By	Status
Action Generic 0614DFGTCV is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6096010A, Project Item Line Number 0190, Material Set 6096010A96, Material 0609PDDL - Paved Drainage Material for Ditch Liner, Acceptance Action Generic 0609PDDL is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6113020, Project Item Line Number 0210, Material Set 611302096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6162002, Project Item Line Number 5001, Material Set 616200296, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 6240103A, Project Item Line Number 0390, Material Set 6240103A96, Material 1011GXT3 - Geotextile Fabric for ErosionControl(T3), Acceptance Action Generic 1011GXT3 is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7011105, Project Item Line Number 0570, Material Set 701110596, Material 0701PLCA - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCA is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7011105, Project Item Line Number 0570, Material Set 701110596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7011105, Project Item Line Number 0570, Material Set 701110596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7011204, Project Item Line Number 0580, Material Set 701120496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7011204, Project Item Line Number 0580, Material Set 701120496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7027000, Project Item Line Number 0640, Material Set 702700096, Material 0702PLPT - Pile Point Reinforcement, Acceptance Action Generic 0702PLPT is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7032003, Project Item Line Number 0650, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7032003, Project Item Line Number 0650, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034219A, Project Item Line Number 0660, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034219A, Project Item Line Number 0660, Material Set 7034219A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034219A, Project Item Line Number 0660, Material Set 7034219A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034221, Project Item Line Number 0670, Material Set 703422196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034221, Project Item Line Number 0670, Material Set 703422196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034221, Project Item Line Number 0670, Material Set 703422196, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034221, Project Item Line Number 0670, Material Set 703422196, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034221, Project Item Line Number 0670, Material Set 703422196, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034221, Project Item Line Number 0670, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034430, Project Item Line Number 0680, Material Set 703443096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with contractor and materials to resolve.	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034430, Project Item Line Number 0680, Material Set 703443096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7034430, Project Item Line Number	No Remark was entered by Engineer	cracrb1	Overridden

Revision 4/1/2020 Page 9 of 31



Exceptions (Discrepancies) This Estimate Period

Coulomb Samura Samura (1970) Manager Samura	Exceptions (Discrepancies) This Estimate Period			
Connot CODIC CORTA in stanford. Elization Exception Type, Installicated Marketian Project J 455388 (Inem 7034620 Project Item Line Number 0000, Marketia Ser 703462006, Marke	Exceptions / Discrepencies	Explanation		Status
6000 Marchair Set 7004/60070 Marchair Set 7004/60070 Project Intentilization I				
OTO, Material Set 705602196, Material GYOSONCREPOXY - Corden Nebroaks Dan Visitions Lang, Acceptance Action Generic Policy Actions (1998) (199	0690, Material Set 703462096, Material 3099XXAS - Aesthetic Items on Project, Acceptance Action	Working with contractor and materials to resolve.	cracrb1	Overridden
### STO MARKEL SET OF 160606, Makerial 1008FRSDFLAZMS - Resiliorous Steel No. 11,1036 GT ### STO MARKEL SECRETOR Type: Insufficient Materials Project 483389, Item 701900, Project term Line Number of 10,100, Makerials 4010000, Makerial 1008SSPLAZMS - Resiliorous Steel No. 2012 GT 100, Makerials 10010000, Makerials 1000000000000000000000000000000000000	0700, Material Set 705602196, Material 0705INCRCPSXX - Girder Nebraska Dsn Various Leng,	Working with contractor and materials to resolve.	cracrb1	Overridden
0.710. Mareail Set 7001 600000, Mareant 1008/SDEP FLAZINGS - Reinforcing Steel No. 8MA25 of 60MA250 (7.010. Materials 67.01000000, Mareant 1008/SDEP FLAZINGS - Reinforcing Steel No. 8MA25 of 60MA250 (7.010. Materials 67.01000000, Mareant 1008/SDEP FLAZINGS - Reinforcing Steel No. 7MA2 of 60MA250 (7.010. Materials 67.01000000, Mareant 1008/SDEP FLAZINGS - Reinforcing Steel No. 7MA2 of 60MA250 (7.010. Materials 67.01000000, Mareant 1008/SDEP FLAZINGS - Reinforcing Steel No. 7MA2 of 60MA250 (8. Acceptance Action Genoric ReSiloseBasis is insufficient. Flatinities Exception Type: Insufficient Materials: Project 43S3380, Item 77011000, Project Item Line Number 0720. Materials 4707/500000, Materials 1008/SDEP FLAZINGS - MATERIALS - MAT	0710, Material Set 706106096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr	Working with contractor and materials to resolve.	cracrb1	Overridden
07.10 Material Set 706100506, Material 1036RSDPF142M12 - Reinforcing Steel No. 7/M22 of 610M420 (a). Acceptance Action Generic ReSidentian is insufficient. Eliminate Exception Type: Insufficient Materials: Poject J483388, Item 7071000, Project Item Line Number 07.00 Material Set 70610006, Material 1008RSDPF142M12 - Seniforcing Steel No. 5M16 of 60M420 (a). Acceptance Action Generic ReSidentian is insufficient. Exception Type: Insufficient Materials: Poject J483388, Item 70710000, Project Item Line Number 07.00 Material Set 707100006, Material 1002.0914 - Junction Boxes for Highway Lighting, Acceptance Action Generic 1002.0914 - Junction Boxes for Highway Lighting, Acceptance Action Generic 1002.0914 - Junction Boxes for Highway Lighting, Acceptance Action Generic 1002.0914 - Junction Boxes for Highway Lighting, Acceptance Action Generic 1002.0914 - Junction Boxes for Highway Lighting, Acceptance Action Generic 1002.0914 - Junction Boxes for Highway Lighting, Acceptance Action Generic 1002.0914 - Junction Boxes for Highway Lighting, Acceptance Action Generic 1002.0914 - Junction Boxes for Highway Lighting, Acceptance Action Generic 1002.0916 - Junction Boxes for Highway Lighting, Acceptance Action Generic 1002.0916 - Junction Generic 1002.0916 - Junction Generic 1002.0916 - Junction Generic 1002.0916 - Junction	0710, Material Set 706106096, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420	No Remark was entered by Engineer	cracrb1	Overridden
0710. Material Set 170/100096. Material To 1008105/PL 22M16 - Reinforcing Steel No. 5M16 Gr 60M420 (a). Acceptance Action Generia Rischelders is insufficient. Elatimate Exception Type: Insufficient Materials: Project J453389, Item 7071000, Project Item Line Number 0720. Materials Set 707100096. Materials To 1602/BHL - Juniforcine Doses for Highway Ugining Acceptance Action Generia 1002/BHL is insufficient. Elatimate Exception Type: Insufficient Materials: Project J453389, Item 7071000, Project Item Line Number 0720. Material Set 707100096. Material 10080EC - Electrical Conduit Material. Acceptance Action Generia 10080EC (COMPS) is insufficient. Elatimate Exception Type: Insufficient Materials. Project J453389, Item 7110000, Project Item Line Number 0700. Material Set 171030096. Material 10080EC COMPS is insufficient. Elatimate Exception Type: Insufficient Materials. Project J453389, Item 7110000, Project Item Line Number 0800. Material Set 711030096. Material 10080EC COMPS is insufficient. Elatimate Exception Type: Insufficient Materials. Project J453389, Item 7110000, Project Item Line Number 0800. Material Set 715001096. Material 10080EC COMPS is insufficient. Elatimate Exception Type: Insufficient Materials. Project J453389, Item 7151001, Project Item Line Number 0700. Material Set 715001096. Material 10080EC COMPS is insufficient. Elatimate Exception Type: Insufficient Materials. Project J453389, Item 7201000, Project Item Line Number 0700. Material Set 715001096. Materials Project J453389, Item 7201000, Project Item Line Number 0700. Material Set 715001096. Materials Project J453389, Item 7201000, Project Item Line Number 0700. Material Set 715001096. Materials Project J453389, Item 7201000, Project Item Line Number 0700. Material Set 715001096. Materials Project J453389, Item 7201000, Project Item Line Number 0700. Material Set 7201000096. Materials Project J453389, Item 72010000, Project Item Line Number 07000006. Materials Project J453389, Item 72010000, Project Item Line Number 07000006. Materia	0710, Material Set 706106096, Material 1036RSDFPL42M22 - Reinforcing Steel No. 7/M22 Gr 60/M420	No Remark was entered by Engineer	cracrb1	Overridden
0720. Material Set 70/100008, Material 1062/JEHL 5 unriction Boxes for Highway Lighting, Acceptance Action Generic 1058/CEC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 70/1000, Project Item Line Number 0770. Material Set 70/100008, Material 10580FC Clearing Acceptance Action Generic 1058/CEC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 710300, Project Item Line Number 0770. Material Set 71/1003008, Material 10589FCCCCMPS a insufficient Materials: Project J4S3389, Item 710300, Project Item Line Number 0770. Material Set 71/1003008, Material 10589FCCCCMPS is a insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 710300, Project Item Line Number 0700. Material Set 71/1003008, Material 10589FCCCCMPS is a insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7151001, Project Item Line Number 0703. Material Set 71/1003008, Material 10589FCCCCMPS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7151001, Project Item Line Number 0703. Material Set 71/1003008, Material 1015405FC-Set Crans Backfill in Structural Sys, Acceptance Action Generic 01589FCT is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0709. Material Set 720100008, Material 1010SGEF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0709. Material Set 720100008, Material 1010SGEF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0709. Material Set 720100008, Material 1010SGEF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0709. Material Set 720100008, Material 1010SGEF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item	0710, Material Set 706106096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420	No Remark was entered by Engineer	cracrb1	Overridden
6720, Material Set 701100096, Material 1005CC - Electrical Conduit Materials, Acceptance Action Generic 1059PCCCOMPS is insufficient. Estimate Exception Type: Insufficient Materials: Project, J4S3388, Item 7110300, Project Item Line Number 07070, Material 1059PCCCCOMPS is insufficient. Estimate Exception Type: Insufficient Materials: Project, J4S3389, Item 7110000, Project Item Line Number 0709, Material 1059PCCCCOMPS is insufficient. Estimate Exception Type: Insufficient Materials: Project, J4S3389, Item 7151001, Project Item Line Number 0709, Material Set 711000096, Material 1059PCCCCOMPS is Insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7151001, Project Item Line Number 0709, Material Set 715100196, Material 10105GPF - Select Gran Backfill for Shructural Sys, Acceptance Action Generic 1019PCCCCOMPS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0709, Material Set 720100096, Material 10105GPF - Select Gran Backfill for Shructural Sys, Acceptance Action Generic 1019CGPF insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0709, Material Set 720100096, Material 10105GPF - Select Gran Backfill for Shructural Sys, Acceptance Action Generic 10105GPF insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0709, Material Set 720100096, Material 10105GPF - Select Gran Backfill for Shructural Sys, Acceptance Action Generic 1072MSEP in Insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0709, Material Set 720100096, Material 10105GPF - Select Gran Backfill for Shructural Sys, Acceptance Action Generic 0720MSEP in Insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0709, Material Set 720100096, Material 0720MSEP - Material Set 720100096, Material 0720MSEP - Material 0720MSEP - Mate	0720, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance	Working with contractor and materials to resolve.	cracrb1	Overridden
0.770, Material Set 711030996, Material 1059PCCCCMPS - Concrete - Masonry Protective Sealer, Acceptance Action Generic 1059PCCCCMPS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7110300, Project Item Line Number 0750, Material Set 7103096, Material 0759PCCCCMPS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 715001, Project Item Line Number 0750, Material Set 71500196, Material 07150PCCCMPS - Concrete - Masonry Protective Sealer, Acceptance Action Generic 1059PCCCCMPS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0750, Material Set 71500196, Material 07150PCT - Vertical Drain at End Bents, Acceptance Action Generic 10150SGP is sufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 720100096, Material 10150SGP - Select Gran Backfill for Structural Sys, Acceptance Action Generic 10150SGP is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 72010096, Material 07150SGP is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 72010096, Material 0710SGP is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 720100096, Material 0710SGP is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 720100096, Material 0710SGP is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 720100096, Material 0710SGP is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 07100, Project Item Line Number 07	0720, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic	No Remark was entered by Engineer	cracrb1	Overridden
0800, Material Set 71(030096, Material 1059PCCCCMPs is unstificient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 721000, Project Item Line Number O790, Material Set 720100096, Material O7105CBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 10710FCBF is insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number O790, Material Set 720100096, Material Materials: Project J4S3389, Item 7201000, Project Item Line Number O790, Material Set 720100096, Material O7105CBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SCBF is insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number O790, Material Set 720100096, Material Set 720100096, Material Set 720100096, Material Set 720100096, Material Set 72010096, Mat	0770, Material Set 711030096, Material 1059PCCCCMPS - Concrete - Masonry Protective Sealer,	Working with contractor and materials to resolve.	cracrb1	Overridden
0730, Material Set 715100196, Material 0715DRVT - Vertical Drain at End Bents, Acceptance Action Generic 0715DRVT is insufficient. Estimate Exception Type: insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 72010096, Material 1016SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 720100096, Material 1011CXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011CXT4 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 720100096, Material O70075EW - MSE Wall System - Bridge Approved Design. Acceptance Action Generic 0720MSEW is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 720100096, Material O5010CB1A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0720MSEW is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 720100096, Material O5010CB1A - Concrete, Class B-1 w/Air, Acceptance Action Generic 05010CB1A is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material	0800, Material Set 711030096, Material 1059PCCCCMPS - Concrete - Masonry Protective Sealer,	Working with contractor and materials to resolve.	cracrb1	Overridden
O'790, Material Set 72010096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number O'790, Material Set 720100096, Material 1011CXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011CXT4 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number O'790, Material Set 720100096, Material O'790, Material Set 72010096, Material Set 72010096, Material O'790, Material Set 72010096, Material O'790, Material Set 72010096, Material Set 720100096, Material Set 72010096, Material Set 72010096, Material Set 720100096, Material Set 720100096, Material Set 720100096, Mater	0730, Material Set 715100196, Material 0715DRVT - Vertical Drain at End Bents, Acceptance Action	Working with contractor and materials to resolve.	cracrb1	Overridden
0790, Material Set 720100096, Material 1011CXT4 is insufficient. Action Generic 1011CXT4 is insufficient. Status of the Companies of the Compa	0790, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance	Working with contractor and materials to resolve.	cracrb1	Overridden
O'790, Material Set 720100096, Material 0720MSEW is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0790, Material Set 720100096, Material Set 7201000	0790, Material Set 720100096, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance	No Remark was entered by Engineer	cracrb1	Overridden
O790, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material 0720MSEW - MSE Wall System-Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 8061019, Project Item Line Number 0450, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient. Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item Line Number 0150, Contract Line Item Number 0150, Item 6071050, Minor Item. Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item No Remark was entered by Engineer Overridden Overridden	0790, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design,	No Remark was entered by Engineer	cracrb1	Overridden
0820, Material Set 720100096, Material 0720MSEW is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material 1011CXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 8061019, Project Item Line Number 0450, Material Set 806101996, Material 1011CXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient. Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item No Remark was entered by Engineer cracrb1 Overridden Union Number 0150, Contract Line Item Number 0150, Minor Item. Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item No Remark was entered by Engineer cracrb1 Overridden	0790, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action	No Remark was entered by Engineer	cracrb1	Overridden
0820, Material Set 720100096, Material 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material 5et 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material 5et 720100096, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 8061019, Project Item Line Number 0450, Material Set 806101996, Material Set 720100096, Material Set 806101996, Material Set 8061019996, Material Set 8061019996, M	0820, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design,	Working with contractor and materials to resolve.	cracrb1	Overridden
0820, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 7201000, Project Item Line Number 0820, Material Set 720100096, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 8061019, Project Item Line Number 0450, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient. Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item No Remark was entered by Engineer cracrb1 Overridden Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item No Remark was entered by Engineer cracrb1 Overridden	0820, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action	No Remark was entered by Engineer	cracrb1	Overridden
0820, Material Set 720100096, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3389, Item 8061019, Project Item Line Number 0450, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient. Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item Line Number 0150, Contract Line Item Number 0150, Item 6071050, Minor Item. Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item No Remark was entered by Engineer cracrb1 Overridden No Remark was entered by Engineer cracrb1 Overridden	0820, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance	No Remark was entered by Engineer	cracrb1	Overridden
0450, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient. Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item Line Number 0150, Contract Line Item Number 0150, Item 6071050, Minor Item. Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item No Remark was entered by Engineer cracrb1 Overridden Overridden	0820, Material Set 720100096, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance	No Remark was entered by Engineer	cracrb1	Overridden
Line Number 0150, Contract Line Item Number 0150, Item 6071050, Minor Item. Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item No Remark was entered by Engineer cracrb1 Overridden	0450, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2),	Working with contractor and materials to resolve.	cracrb1	Overridden
		No Remark was entered by Engineer	cracrb1	Overridden
Line Number 0100, Contract Line item Number 0100, item 007 1102, willow item.	Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item Line Number 0160, Contract Line Item Number 0160, Item 6071102, Minor Item.	No Remark was entered by Engineer	cracrb1	Overridden
Estimate Exception Type: Item Overrun: Contract 210122-C09, Contract Project J4S3389, Project Item Line Number 0030, Contract Line Item Number 0030, Item 2032000, Minor Item.		pending change order.	cracrb1	Overridden

Revision 4/1/2020 Page 10 of 31



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-C09	J4S3389	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$30,807.93	\$30,807.93
		0001	0020	2031000	CLASS A EXCAVATION	440.00	0.00	440.00	CUYD	440.00	\$22.54	\$9,917.60
		0001	0030	2032000	CLASS C EXCAVATION	1,335.00	0.00	1,335.00	CUYD	1,561.00	\$21.34	\$33,311.74
		0001	0040	2036000	COMPACTING EMBANKMENT	1,680.00	0.00	1,680.00	CUYD	1,680.00	\$0.50	\$840.00
		0001	0050	2153000	SHAPING SLOPES, CLASS III	2.00	0.00	2.00	100F	0.00	\$600.00	\$0.00
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	746.00	0.00	746.00	SQYD	746.00	\$15.53	\$11,585.38
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	41.00	0.00	41.00	SQYD	41.00	\$31.22	\$1,280.02
		0001	0800	3105002	GRAVEL (A) OR CRUSHED STONE (B)	3.00	0.00	3.00	TONS	3.00	\$304.76	\$914.28
		0001	0090	4010150	TYPE A2 SHOULDER	41.00	0.00	41.00	SQYD	0.00	\$223.22	\$0.00
		0001	0100	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	41.60	0.00	41.60	TONS	36.00	\$426.00	\$15,336.00
		0001	0110	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	24.00	0.00	24.00	TONS	21.15	\$650.00	\$13,747.50
		0001	0120	4019905	MISC.Optional Pavement	678.00	0.00	678.00	SQYD	678.00	\$120.40	\$81,631.20
		0001	0130	4071005	TACK COAT	32.00	0.00	32.00	GAL	32.00	\$2.50	\$80.00
		0001	0140	6071012A	CHAIN-LINK FENCE (60 IN.)	115.00	0.00	115.00	LF	0.00	\$60.00	\$0.00
		0001	0150	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	221.00	0.00	221.00	LF	287.00	\$55.00	\$15,785.00
		0001	0160	6071102	MODIFIED CONCRETE GUTTER TYPE B	221.00	0.00	221.00	LF	287.00	\$46.15	\$13,245.05
		0001	0170	6091051	CURB AND GUTTER TYPE A	20.00	0.00	20.00	LF	20.00	\$60.45	\$1,209.00
		0001	0180	6094010	DRAIN BASIN	2.00	0.00	2.00	EA	2.00	\$5,880.25	\$11,760.50
		0001	0190	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	34.00	0.00	34.00	CUYD	34.00	\$58.69	\$1,995.46
		0001	0200	6096041	PLACING TYPE 1 ROCK DITCH LINER	34.00	0.00	34.00	CUYD	0.00	\$36.32	\$0.00
		0001	0210	6113020	FURNISHING TYPE 2 ROCK BLANKET	323.00	0.00	323.00	CUYD	323.00	\$58.69	\$18,956.87
		0001	0220	6113040	PLACING TYPE 2 ROCK BLANKET	323.00	0.00	323.00	CUYD	323.00	\$36.28	\$11,718.44
		0001	0230	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0001	0240	6122020	REPLACEMENT SAND BARREL	20.00	0.00	20.00	EA	0.00	\$275.00	\$0.00
		0001	0250	6161005	CONSTRUCTION SIGNS	1,655.00	39.00	1,694.00	SQFT	1,694.00	\$8.00	\$13,552.00
		0001	0260	6161008	ADVANCED WARNING RAIL SYSTEM	24.00	0.00	24.00	EA	24.00	\$60.00	\$1,440.00
		0001	0270	6161009	FLAG ASSEMBLY	24.00	-24.00	0.00	EA	0.00	\$50.00	\$0.00
		0001	0280	6161025	CHANNELIZER (TRIM LINE)	500.00	-122.00	378.00	EA	378.00	\$35.00	\$13,230.00
		0001	0290	6161030	TYPE III MOVEABLE BARRICADE	63.00	-20.00	43.00	EA	43.00	\$250.00	\$10,750.00
			0300	6161040	FLASHING ARROW PANEL	5.00	1.00	6.00	EA	6.00	\$4,000.00	\$24,000.00
		0001	0310	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION	14.00	0.00	14.00	EA	14.00	\$1,500.00	\$24,000.00
		0001	0310	0101099	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	14.00	0.00	14.00	EA	14.00	\$1,500.00	\$21,000.00
		0001	0320	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	550.00	0.00	550.00	LF	550.00	\$20.24	\$11,132.00
		0001	0330	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	250.00	0.00	250.00	LF	250.00	\$22.26	\$5,565.00
		0001	0340	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$183,114.68	\$183,114.68
		0001	0350	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$250.00	\$0.00
		0001	0360	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,142.00	0.00	1,142.00	LF	0.00	\$1.08	\$0.00
		0001	0370	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,220.00	0.00	1,220.00	LF	0.00	\$1.07	\$0.00
		0001	0380	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	323.00	0.00	323.00	SQYD	323.00	\$40.00	\$12,920.00
		0001	0390	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	570.00	0.00	570.00	SQYD	570.00	\$2.29	\$1,305.30
		0001	0400	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$8,650.00	\$8,650.00
		0001	0410	8051000A	SEEDING - COOL SEASON MIXTURES	0.30	0.00	0.30	ACRE	0.00	\$9,900.00	\$0.00
		0001	0420	8061005	ROCK DITCH CHECK	140.00	0.00	140.00	LF	0.00	\$20.00	\$0.00
		0001	0430	8061007A	CURB INLET CHECK	4.00	0.00	4.00	EA	0.00	\$90.00	\$0.00
		0001	0440	8061016	SEDIMENT REMOVAL	18.00	0.00	18.00	CUYD	0.00	\$44.00	\$0.00

Revision 4/1/2020 Page 11 of 31



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-C09	J4S3389	0001	0450	8061019	SILT FENCE	904.00	0.00	904.00	LF	666.00	\$2.00	\$1,332.00
		0010	0460	6061060	MGS GUARDRAIL	613.00	0.00	613.00	LF	0.00	\$22.00	\$0.00
		0010	0470	6061067	MGS DOUBLE FACED GUARDRAIL	50.00	0.00	50.00	LF	0.00	\$32.00	\$0.00
		0010	0480	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	3.00	0.00	3.00	EA	0.00	\$2,600.00	\$0.00
		0010	0490	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	0.00	\$2,400.00	\$0.00
		0010	0500	6063016	TYPE B CRASHWORTHY END TERMINAL	2.00	0.00	2.00	EA	0.00	\$5,000.00	\$0.00
		0010	0510	6064100	MEDIAN GUARD CABLE 3 - STRAND	6,072.00	-6,072.00	0.00	LF	0.00	\$10.50	\$0.00
		0010	0520	6064110	ANCHOR ASSEMBLY, GUARD CABLE 3-STRAND	4.00	-2.00	2.00	EA	2.00	\$2,712.00	\$5,424.00
		0070	0530	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	23.00	0.00	23.00	SQFT	23.00	\$220.00	\$5,060.00
		0070	0540	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$98,565.00	\$98,565.00
		0070	0550	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	167.00	0.00	167.00	SQYD	167.00	\$227.12	\$37,929.04
		0070	0560	6079903	MISC.(48 in.) Decorative Pedestrian Fence (Structures)	413.00	0.00	413.00	LF	397.00	\$108.00	\$42,876.00
		0070	0570	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	12.00	0.00	12.00	LF	12.00	\$563.26	\$6,759.12
		0070	0580	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	33.00	0.00	33.00	LF	33.00	\$513.26	\$16,937.58
		0070	0590	7011300	VIDEO CAMERA INSPECTION	3.00	0.00	3.00	EA	3.00	\$50.00	\$150.00
		0070	0600	7011400	FOUNDATION INSPECTION HOLES	63.00	0.00	63.00	LF	63.00	\$94.00	\$5,922.00
		0070	0610	7011600	SONIC LOGGING TESTING	3.00	0.00	3.00	EA	3.00	\$1,100.00	\$3,300.00
		0070	0620	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	324.00	0.00	324.00	LF	318.27	\$82.75	\$26,336.59
		0070	0630	7026000	PRE-BORE FOR PILING	60.00	0.00	60.00	LF	60.00	\$166.74	\$10,004.40
		0070	0640	7027000	PILE POINT REINFORCEMENT	12.00	0.00	12.00	EA	12.00	\$117.33	\$1,407.96
		0070	0650	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	68.20	0.00	68.20	CUYD	68.20	\$1,116.32	\$76,133.02
		0070	0660	7034219A	TYPE D BARRIER	415.00	0.00	415.00	LF	415.00	\$132.87	\$55,141.05
		0070	0670	7034221	SLAB ON CONCRETE NU-GIRDER	831.00	0.00	831.00	SQYD	831.00	\$335.02	\$278,401.62
		0070	0680	7034430	SIDEWALK (BRIDGES)	2,536.00	0.00	2,536.00	SQFT	2,536.00	\$17.22	\$43,669.92
		0070	0690	7034620	FORM LINERS	161.00	0.00	161.00	SQYD	161.00	\$65.82	\$10,597.02
		0070	0700	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	931.00	0.00	931.00	LF	931.00	\$289.44	\$269,468.64
		0070	0710	7061060	REINFORCING STEEL (BRIDGES)	13,150.00	0.00	13,150.00	LB	13,150.00	\$1.41	\$18,541.50
		0070	0720	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	1.00	\$13,119.38	\$13,119.38
		0070	0730	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$2,001.33	\$4,002.66
		0070	0740	7161000	PLAIN NEOPRENE BEARING PAD	15.00	0.00	15.00	EA	15.00	\$187.20	\$2,808.00
		0070	0750	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	5.00	0.00	5.00	EA	5.00	\$384.24	\$1,921.20
		0070	0760	7201300	PIPE PILE SPACERS	12.00	0.00	12.00	EA	0.00	\$0.57	\$0.00
		0071	0770	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,139.86	\$3,139.86
		0071	0780	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,139.86	\$3,139.86
		0071	0790	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	2,434.00	0.00	2,434.00	SQFT	2,434.00	\$72.00	\$175,248.00
		0072	0800	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,235.23	\$3,235.23
		0072	0810	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,235.23	\$3,235.23
		0072	0820	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	2,641.00	0.00	2,641.00	SQFT	2,641.00	\$72.00	\$190,152.00
		0001	5001	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	0.00	12.00	12.00	EA	12.00	\$1,207.50	\$14,490.00
					Date as of Report Generated Date							\$2,022,028.84
210122-C09 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$2,022,028.84

Revision 4/1/2020 Page 12 of 31



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3389

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0800	3105002	GRAVEL (A) OR CRUSHED STONE (B)	10/15/21	10/19/21	3.00	TONS	Shoulder of SE corner of 67th street.	52+35	rt	52+74	rt	
0130	4071005	TACK COAT	10/15/21	10/19/21	32.00	GAL	Rt and Lt of 67th for driveways. Each limit of mainline for tie ins.	46+95		53+05		Driveway tie ins and Mainline tie ins.
0150	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	10/15/21	10/19/21	287.00	LF	On top of MSE walls on both sides of I-435.	598+87	Rt and Lt 50 foot	600+55	Rt and Lt 50 foot	Overran due to design error.
0170	6091051	CURB AND GUTTER TYPE A	10/15/21	10/19/21	20.00	LF	Each end of the Bridge.	48+75	rt	51+24	rt	10 foot prior to each drop inlet.
0380	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	10/15/21	10/19/21	323.00	SQYD	Extents of the job.	46+95		53+05		Asphalt tie in locations at extents.
0390	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	10/15/21	10/19/21	85.00	SQYD	Pipe outflows from drain basins, and rock lined ditches at MSE top of slope.	48+82		51+16		
0560	6079903	MISC. FENCING	10/15/21	10/19/21	397.00	LF	South side of the bridge.	49+06		50+94		2 panels missing at estimate time.

The information below this line are details for Construction Signs (if applicable).

No Data Available



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3389	0020	CLASS A EXCAVATION	Price FUEL		2	May 17, 2021	SYSTEM	\$53.68	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$53.68	
			Price FUEL - 1	Γotal				\$53.68	
	0020 -	· Total						\$53.68	
	0030	CLASS C EXCAVATION	Overrun	Overrun	3	Jun 3, 2021	SYSTEM	(\$4,877.98)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				Overrun - T	otal			(\$4,877.98)	
			Overrun - Tota	al				(\$4,877.98)	
			Price FUEL		2	May 17, 2021	SYSTEM	\$292.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	Jun 3, 2021	SYSTEM	\$88.08	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$380.88	
			Price FUEL - 1	Гotal				\$380.88	
	0030 -	· Total						(\$4,497.10)	
	0040	COMPACTING EMBANKMENT	Material		10	Sep 16, 2021	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user doolet1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$840.00)	
					11	Oct 4, 2021	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user cracrb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Oct 4, 2021	SYSTEM	(\$840.00)	
					12	Oct 19, 2021	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user cracrb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$840.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0040 -	· Total						\$0.00	
	0060	TYPE 5 AGGREGATE FOR BASE	Material		10	Sep 16, 2021	SYSTEM	\$11,585.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user doolet1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$11,585.38)	
					11	Oct 4, 2021	SYSTEM	\$11,585.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user cracrb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Oct 4, 2021	SYSTEM	(\$11,585.38)	
					12	Oct 19, 2021	SYSTEM	\$11,585.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$11,585.38)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
			Price FUEL		10	Sep 16, 2021	SYSTEM	\$80.57	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$80.57	
			Price FUEL - 1					\$80.57	
	0060 -	Total						\$80.57	
	0070	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		10	Sep 16, 2021	SYSTEM	\$1,280.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user doolet1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		BASE (6 IN. THICK)			10	Sep 16, 2021	SYSTEM	(\$1,280.02)	, , , , , , , , , , , , , , , , , , , ,
					11	Oct 4,	SYSTEM	\$1,280.02	This adjustment offsets the original system-generated Material Payment



oject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
ojoo:	2.110	2000.i.pud.i.	Туре	Adjustment Type	Number	Date	Ву	7 1110 1111	
S3389	0070	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material			2021			Estimate Item Adjustment (0004) due to user cracrb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		THICK)			11	Oct 4, 2021	SYSTEM	(\$1,280.02)	
					12	Oct 19, 2021	SYSTEM	\$1,280.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user cracrb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$1,280.02)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Price FUEL		10	Sep 16, 2021	SYSTEM	\$6.79	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$6.79	
			Price FUEL - 1	Гotal				\$6.79	
	0070 -	· Total						\$6.79	
	0800	GRAVEL (A) OR CRUSHED STONE (B)	Material		12	Oct 19, 2021	SYSTEM	\$914.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$914.28)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0080 -	· Total						\$0.00	
	0100	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Price FUEL		11	Oct 4, 2021	SYSTEM	\$75.30	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		(2)		- Total				\$75.30	
			Price FUEL - 1	Total				\$75.30	
		· Total						\$75.30	
	0110	BITUMINOUS PAVEMENT MIXTURE PG64-22	Price FUEL	- Total	11	Oct 4, 2021	SYSTEM	\$44.23 \$44.23	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		(BAS	Price FUEL - 1					\$44.23	
	0110 -	· Total	111001 022	Ottai				\$44.23	
	0120	MISC.	Material		10	Sep 16, 2021	SYSTEM	\$81,631.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user doolet1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$81,631.20)	,
					11	Oct 4, 2021	SYSTEM	\$81,631.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11		SYSTEM SYSTEM	\$81,631.20 (\$81,631.20)	
						2021 Oct 4,			Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment
					11	2021 Oct 4, 2021 Oct 19,	SYSTEM	(\$81,631.20)	Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment
				- Total	11 12	2021 Oct 4, 2021 Oct 19, 2021 Oct 19,	SYSTEM SYSTEM	(\$81,631.20) \$81,631.20	Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment
			Material - Tota		11 12	2021 Oct 4, 2021 Oct 19, 2021 Oct 19,	SYSTEM SYSTEM	(\$81,631.20) \$81,631.20 (\$81,631.20)	Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment
	0120 -	. Total	Material - Tota		11 12	2021 Oct 4, 2021 Oct 19, 2021 Oct 19,	SYSTEM SYSTEM	(\$81,631.20) \$81,631.20 (\$81,631.20) \$0.00	Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment
	0120 - 0130	· Total TACK COAT	Material - Tota		11 12	2021 Oct 4, 2021 Oct 19, 2021 Oct 19,	SYSTEM SYSTEM	(\$81,631.20) \$81,631.20 (\$81,631.20) \$0.00	Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment
					11 12 12	2021 Oct 4, 2021 Oct 19, 2021 Oct 19, 2021	SYSTEM SYSTEM SYSTEM	(\$81,631.20) \$81,631.20 (\$81,631.20) \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user cracrb1 overridding Payment
					11 12 12	2021 Oct 4, 2021 Oct 19, 2021 Oct 19, 2021 Oct 19, 2021 Oct 19, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$81,631.20) \$81,631.20 (\$81,631.20) \$0.00 \$0.00 \$80.00	Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user cracrb1 overridding Payment
				al - Total	11 12 12	2021 Oct 4, 2021 Oct 19, 2021 Oct 19, 2021 Oct 19, 2021 Oct 19, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$81,631.20) \$81,631.20 (\$81,631.20) \$0.00 \$0.00 \$80.00 (\$80.00)	Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user cracrb1 overridding Payment
	0130		Material	al - Total	11 12 12	2021 Oct 4, 2021 Oct 19, 2021 Oct 19, 2021 Oct 19, 2021 Oct 19, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$81,631.20) \$81,631.20 (\$81,631.20) \$0.00 \$0.00 \$80.00 (\$80.00) \$0.00	Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user cracrb1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks														
J4S3389	0150	FENCE	Material	Туре		2021			Estimate Item Adjustment (0002) due to user cracrb1 overridding Payment														
040000	0100	(RETAINING WALLS)	Material		12	Oct 19,	SYSTEM	(\$15.795.00)	Estimate Exception 17 on the current Payment Estimate.														
					12	2021	STSTEIN	(\$15,785.00)															
				- Total				\$0.00															
			Material - Tota					\$0.00															
			Overrun	Overrun	12	Oct 19, 2021	SYSTEM	\$3,630.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 69 on the current Payment Estimate. Material Insufficiency Quantity 287.000; Overrun Quantity Balance 66.00.														
					12	Oct 19, 2021	SYSTEM	(\$3,630.00)															
				Overrun - T	otal			\$0.00															
			Overrun - Tota					\$0.00															
	0150 -	Total						\$0.00															
	0160	MODIFIED CONCRETE GUTTER TYPE B	Material		5	Jul 2, 2021	SYSTEM	\$6,522.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user cracrb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
					5	Jul 2, 2021	SYSTEM	(\$6,522.52)															
					6	Jul 16, 2021	SYSTEM	\$6,522.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user cracrb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
									6	Jul 16, 2021	SYSTEM	(\$6,522.52)											
					7	Aug 2, 2021	SYSTEM	\$6,522.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user cracrb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
						7	Aug 2, 2021	SYSTEM	(\$6,522.52)														
					8	Aug 17, 2021	SYSTEM	\$13,245.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user cracrb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
						8	Aug 17, 2021	SYSTEM	(\$13,245.05)														
					9	Sep 3, 2021	SYSTEM	\$13,245.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user doolet1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
													9	Sep 3, 2021	SYSTEM	(\$13,245.05)							
												10	Sep 16, 2021	SYSTEM	\$13,245.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user doolet1 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
					10	Sep 16, 2021	SYSTEM	(\$13,245.05)															
																			11	Oct 4, 2021	SYSTEM	\$13,245.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user cracrb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
											11	Oct 4, 2021	SYSTEM	(\$13,245.05)									
						12	Oct 19, 2021	SYSTEM	\$13,245.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user cracrb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.													
					12	Oct 19, 2021	SYSTEM	(\$13,245.05)															
				- Total				\$0.00															
			Material - Tota					\$0.00															
			Overrun	Overrun	8	Aug 17, 2021	SYSTEM	\$3,045.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 43 on the current Payment Estimate. Material Insufficiency Quantity 287.000; Overrun Quantity Balance 66.00.														
					8	Aug 17, 2021	SYSTEM	(\$3,045.90)															
					9	Sep 3, 2021	SYSTEM	(\$3,045.90)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).														
						9	Sep 3,	SYSTEM	\$3,045.90	This adjustment offsets the original system-generated Overrun Payment													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4S3389	0160	MODIFIED CONCRETE GUTTER TYPE B	Overrun	Overrun		2021			Estimate Item Adjustment (0001) overridding Payment Estimate Exception 42 on the current Payment Estimate. Material Insufficiency Quantity 287.000; Overrun Quantity Balance 66.00.		
					10	Sep 16, 2021	SYSTEM	(\$3,045.90)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
					10	Sep 16, 2021	SYSTEM	\$3,045.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 65 on the current Payment Estimate. Material Insufficiency Quantity 287.000; Overrun Quantity Balance 66.00.		
					11	Oct 4, 2021	SYSTEM	(\$3,045.90)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
					11	Oct 4, 2021	SYSTEM	\$3,045.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 70 on the current Payment Estimate. Material Insufficiency Quantity 287.000; Overrun Quantity Balance 66.00.		
					12	Oct 19, 2021	SYSTEM	(\$3,045.90)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
					12	Oct 19, 2021	SYSTEM	\$3,045.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 70 on the current Payment Estimate. Material Insufficiency Quantity 287.000; Overrun Quantity Balance 66.00.		
				Overrun - To	otal			\$0.00			
	0400	Tatal	Overrun - Tota	l				\$0.00			
	0160 - 0170	CURB AND GUTTER TYPE A	Material		12	Oct 19, 2021	SYSTEM	\$0.00 \$1,209.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user cracrb1 overridding Payment		
	0170 - Total					12	Oct 19,	SYSTEM	(\$1,209.00)	Estimate Exception 21 on the current Payment Estimate.	
				- Total		2021		\$0.00			
			Material - Tota					\$0.00			
		Total						\$0.00			
	0180	DRAIN BASIN	Material		10	Sep 16, 2021	SYSTEM	\$11,760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user doolet1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
					10	Sep 16, 2021	SYSTEM	(\$11,760.50)			
					11	Oct 4, 2021	SYSTEM	\$11,760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
					11	Oct 4, 2021	SYSTEM	(\$11,760.50)			
					12	Oct 19, 2021	SYSTEM	\$11,760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user cracrb1 overridding Payment Estimate Exception 24 on the current Payment Estimate.		
					12	Oct 19, 2021	SYSTEM	(\$11,760.50)			
				- Total				\$0.00			
			Material - Tota					\$0.00			
	0180 -		Motoric		10	Son 46	CVCTENA	\$0.00	This adjustment offsets the original system represed Material Descript		
	0190	FURNISHING TYPE 1 ROCK DITCH LINER	Material		10	Sep 16, 2021	SYSTEM	\$1,995.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user doolet1 overridding Payment Estimate Exception 20 on the current Payment Estimate.		
							10	Sep 16, 2021	SYSTEM	(\$1,995.46)	
					11	Oct 4, 2021	SYSTEM	\$1,995.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user cracrb1 overridding Payment Estimate Exception 20 on the current Payment Estimate.		
					11	Oct 4, 2021	SYSTEM	(\$1,995.46)			
					12	Oct 19, 2021	SYSTEM	\$1,995.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user cracrb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.		
					12	Oct 19, 2021	SYSTEM	(\$1,995.46)			
				- Total				\$0.00			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J4S3389	0190	FURNISHING TYPE 1 ROCK DITCH LINER	Material - Tota					\$0.00				
	0190 -	Total						\$0.00				
	0210	FURNISHING TYPE 2 ROCK BLANKET	Material		6	Jul 16, 2021	SYSTEM	\$4,284.37	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user cracrb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					6	Jul 16, 2021	SYSTEM	(\$4,284.37)				
					7	Aug 2, 2021	SYSTEM	\$4,284.37	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user cracrb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					7	Aug 2, 2021	SYSTEM	(\$4,284.37)				
					8	Aug 17, 2021	SYSTEM	\$18,956.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user cracrb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					8	Aug 17, 2021	SYSTEM	(\$18,956.87)				
					9	Sep 3, 2021	SYSTEM	\$18,956.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user doolet1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					9	Sep 3, 2021	SYSTEM	(\$18,956.87)				
								10	Sep 16, 2021	SYSTEM	\$18,956.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user doolet1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
									10	Sep 16, 2021	SYSTEM	(\$18,956.87)
					11	Oct 4, 2021	SYSTEM	\$18,956.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user cracrb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.			
					11	Oct 4, 2021	SYSTEM	(\$18,956.87)				
					12	Oct 19, 2021	SYSTEM	\$18,956.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user cracrb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.			
					12	Oct 19, 2021	SYSTEM	(\$18,956.87)				
				- Total	- Total			\$0.00				
			Material - Tota					\$0.00				
	0210 -	Total						\$0.00				
	0250	CONSTRUCTION SIGNS	Overrun	Overrun	1	May 4, 2021	SYSTEM	\$312.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user cracrb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					1	May 4, 2021	SYSTEM	(\$312.00)				
					2	May 17, 2021	SYSTEM	(\$312.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
					7	Aug 2, 2021	SYSTEM	\$312.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',8.00000 - 8.00000, 'is applied (if non-zero).			
				Overrun - T	otal			\$0.00				
			Overrun - Tota	al .				\$0.00				
		Total					0145	\$0.00				
	0300	FLASHING ARROW PANEL	Overrun	Overrun		May 4, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user cracrb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					1	May 4, 2021	SYSTEM	(\$4,000.00)				
					2	May 17, 2021	SYSTEM	(\$4,000.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
					7	Aug 2, 2021	SYSTEM	\$4,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4000.00000 - 4000.00000, 'is applied (if non-zero).			
				Overrun - T	otal			\$0.00				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J4S3389	0300	FLASHING ARROW PANEL	Overrun - Tota	ıl				\$0.00						
	0300 -	Total						\$0.00						
	0320	TEMPORARY TRAFFIC BARRIER, CONT.	Material		2	May 17, 2021	SYSTEM	\$11,132.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user cracrb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
		FURN/RE			2	May 17, 2021	SYSTEM	(\$11,132.00)						
					3	Jun 3, 2021	SYSTEM	\$11,132.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user cracrb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					3	Jun 3, 2021	SYSTEM	(\$11,132.00)						
				- Total				\$0.00						
			Material - Tota					\$0.00						
	0320 -	Total						\$0.00						
	0330	TEMP. TRAFFIC BARRIER ANCHORED.,	Material		2	May 17, 2021	SYSTEM	(\$5,565.00)						
		CONT			3	Jun 3, 2021	SYSTEM	\$5,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user cracrb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					3	Jun 3, 2021	SYSTEM	(\$5,565.00)						
				- Total				(\$5,565.00)						
			Material - Tota					(\$5,565.00)						
			MaterialCredit		3	Jun 3, 2021	SYSTEM	\$5,565.00						
				- Total				\$5,565.00						
			MaterialCredit	- Total				\$5,565.00						
	0330 -	Total						\$0.00						
	0390	PERMANENT EROSION CONTROL GEOTEXTILE	Material		8	Aug 17, 2021	SYSTEM	\$1,110.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user cracrb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
		GEOTEXTILE								8	Aug 17, 2021	SYSTEM	(\$1,110.65)	
					9	Sep 3, 2021	SYSTEM	\$1,110.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user doolet1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					9	Sep 3, 2021	SYSTEM	(\$1,110.65)						
					10	Sep 16, 2021	SYSTEM	\$1,110.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user doolet1 overridding Payment Estimate Exception 23 on the current Payment Estimate.					
					10	Sep 16, 2021	SYSTEM	(\$1,110.65)						
					11	Oct 4, 2021	SYSTEM	\$1,110.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user cracrb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.					
					11	Oct 4, 2021	SYSTEM	(\$1,110.65)						
					12	Oct 19, 2021	SYSTEM	\$1,305.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user cracrb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.					
					12	Oct 19, 2021	SYSTEM	(\$1,305.30)						
				- Total				\$0.00						
			Material - Tota	I				\$0.00						
	0390 -	Total						\$0.00						
	0450	SILT FENCE	Material		3	Jun 3, 2021	SYSTEM	\$1,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 24 on the current Payment Estimate.					
					3	Jun 3, 2021	SYSTEM	(\$1,332.00)						
					4	Jun 17,	SYSTEM	\$1,332.00	This adjustment offsets the original system-generated Material Payment					



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
389	0450	SILT FENCE	Material			2021			Estimate Item Adjustment (0015) due to user cracrb1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					4	Jun 17, 2021	SYSTEM	(\$1,332.00)	
					5	Jul 2, 2021	SYSTEM	\$1,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user cracrb1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					5	Jul 2, 2021	SYSTEM	(\$1,332.00)	
					6	Jul 16, 2021	SYSTEM	\$1,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user cracrb1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					6	Jul 16, 2021	SYSTEM	(\$1,332.00)	
					7	Aug 2, 2021	SYSTEM	\$1,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					7	Aug 2, 2021	SYSTEM	(\$1,332.00)	
					8	Aug 17, 2021	SYSTEM	\$1,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user cracrb1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					8	Aug 17, 2021	SYSTEM	(\$1,332.00)	
					9	Sep 3, 2021	SYSTEM	\$1,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user doolet1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					9	Sep 3, 2021	SYSTEM	(\$1,332.00)	
					10	Sep 16, 2021	SYSTEM	\$1,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user doolet1 overridding Payment Estimate Exception 64 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$1,332.00)	
					11	Oct 4, 2021	SYSTEM	\$1,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user cracrb1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
					11	Oct 4, 2021	SYSTEM	(\$1,332.00)	
					12	Oct 19, 2021	SYSTEM	\$1,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user cracrb1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$1,332.00)	
			Material - Tota	- Total				\$0.00 \$0.00	
	0450 -	Total	Indiana i oto	<u>"</u>				\$0.00	
ľ	0460	MGS GUARDRAIL	Construction Stockpile		1	May 4, 2021	SYSTEM	\$8,312.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$8,312.50	
			Construction	Stockpile STI	MI - Total			\$8,312.50	
	0460 -	Total						\$8,312.50	
	0470	MGS DOUBLE FACED GUARDRAIL	Construction Stockpile STMI	- Total	1	May 4, 2021	SYSTEM	\$937.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		MI - Total			\$937.00 \$937.00	
	0470 -	Total	Sonstruction .	элоскрие 311	m Total			\$937.00	
	0480	MGS BRIDGE APP. TRANS SEC	Stockpile		1	May 4, 2021	SYSTEM	\$1,760.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(EXT CURB)	STMI		7	Aug 2, 2021	SYSTEM	\$3,520.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$5,280.00	
			Construction		VII - Total			\$5,280.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
J4S3389	0490	TYPE A CRASHWORTHY	Construction Stockpile	1,750	1	May 4, 2021	SYSTEM	\$4,635.00	Payment Estimate Item Adjustment generated Stockpile Transaction																		
		END TERMINAL (MASH)	STMI	- Total				\$4,635.00																			
		(WIAGIT)	Construction		MI - Total			\$4,635.00																			
	0490 -	· Total						\$4,635.00																			
	0500		Construction Stockpile		1	May 4, 2021	SYSTEM	\$6,261.42	Payment Estimate Item Adjustment generated Stockpile Transaction																		
		END TERMINAL	STMI	- Total				\$6,261.42																			
			Construction	Stockpile ST	MI - Total			\$6,261.42																			
	0500 -	· Total						\$6,261.42																			
	0520	ANCHOR ASSEMBLY, GUARD CABLE 3-	Material		1	May 4, 2021	SYSTEM	\$5,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user cracrb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
		STRAND			1	May 4, 2021	SYSTEM	(\$5,424.00)																			
					2	May 17, 2021	SYSTEM	\$5,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user cracrb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
								2	May 17, 2021	SYSTEM	(\$5,424.00)																
									3	Jun 3, 2021	SYSTEM	\$5,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user cracrb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.														
							3	Jun 3, 2021	SYSTEM	(\$5,424.00)																	
					4	Jun 17, 2021	SYSTEM	\$5,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user cracrb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
							4	Jun 17, 2021	SYSTEM	(\$5,424.00)																	
						5	Jul 2, 2021	SYSTEM	\$5,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user cracrb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																	
					5	Jul 2, 2021	SYSTEM	(\$5,424.00)																			
					6	Jul 16, 2021	SYSTEM	\$5,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
							6	Jul 16, 2021	SYSTEM	(\$5,424.00)																	
					7	Aug 2, 2021	SYSTEM	\$5,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user cracrb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
							7	Aug 2, 2021	SYSTEM	(\$5,424.00)																	
			5							5										8	Aug 17, 2021	SYSTEM	\$5,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user cracrb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
											9 1 1 1	9 11 11 1	10	8	Aug 17, 2021	SYSTEM	(\$5,424.00)										
														9 10 10 11	9 10 10 11 11	9 10	9 10	9	Sep 3, 2021	SYSTEM	\$5,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user doolet1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
																		10	10	10	9	Sep 3, 2021	SYSTEM	(\$5,424.00)			
																					10	10	10	Sep 16, 2021	SYSTEM	\$5,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user doolet1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
																							10	Sep 16, 2021	SYSTEM	(\$5,424.00)	
																									11	Oct 4, 2021	SYSTEM
																11	Oct 4, 2021	SYSTEM	(\$5,424.00)	•							
					12	Oct 19,	SYSTEM	\$5,424.00	This adjustment offsets the original system-generated Material Payment																		



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4S3389	0520	ANCHOR	Material	Туре		2021			Estimate Item Adjustment (0017) due to user cracrb1 overridding Payment
		ASSEMBLY, GUARD CABLE 3- STRAND			12	Oct 19,	SYSTEM	(\$5,424.00)	Estimate Exception 16 on the current Payment Estimate.
				- Total		2021		\$0.00	
			Material - Tota					\$0.00	
	0520 -	Total						\$0.00	
	0550	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		10	Sep 16, 2021	SYSTEM	\$37,929.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user doolet1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$37,929.04)	
					11	Oct 4, 2021	SYSTEM	\$37,929.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user cracrb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Oct 4, 2021	SYSTEM	(\$37,929.04)	
					12	Oct 19, 2021	SYSTEM	\$37,929.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user cracrb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$37,929.04)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0550 -	Total						\$0.00	
	0570	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		2	May 17, 2021	SYSTEM	(\$6,759.12)	
					3	Jun 3, 2021	SYSTEM	(\$6,759.12)	
					4	Jun 17, 2021	SYSTEM	(\$6,759.12)	
					5	Jul 2, 2021	SYSTEM	(\$6,759.12)	
					6	Jul 16, 2021	SYSTEM	(\$6,759.12)	
					7	Aug 2, 2021	SYSTEM	\$6,759.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Aug 2, 2021	SYSTEM	(\$6,759.12)	
					8	Aug 17, 2021	SYSTEM	\$6,759.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user cracrb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Aug 17, 2021	SYSTEM	(\$6,759.12)	
					9	Sep 3, 2021	SYSTEM	\$6,759.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user doolet1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Sep 3, 2021	SYSTEM	(\$6,759.12)	
					10	Sep 16, 2021	SYSTEM	\$6,759.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user doolet1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$6,759.12)	
					11	Oct 4, 2021	SYSTEM	\$6,759.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user cracrb1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					11	Oct 4, 2021	SYSTEM	(\$6,759.12)	
					12	Oct 19, 2021	SYSTEM	\$6,759.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user cracrb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$6,759.12)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J4S3389	0570	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material	- Total				(\$33,795.60)															
		(311.0 IN. DIA.)	Material - Tota	l				(\$33,795.60)															
			MaterialCredit		3	Jun 3, 2021	SYSTEM	\$6,759.12															
					4	Jun 17, 2021	SYSTEM	\$6,759.12															
					5	Jul 2, 2021	SYSTEM	\$6,759.12															
					6	Jul 16, 2021	SYSTEM	\$6,759.12															
					7	Aug 2, 2021	SYSTEM	\$6,759.12															
				- Total				\$33,795.60															
			MaterialCredit	- Total				\$33,795.60															
	0570 -	· Total						\$0.00															
	0580	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		2	May 17, 2021	SYSTEM	(\$16,937.58)															
					3	Jun 3, 2021	SYSTEM	(\$16,937.58)															
					4	Jun 17, 2021	SYSTEM	(\$16,937.58)															
					5	Jul 2, 2021	SYSTEM	(\$16,937.58)															
					6	Jul 16, 2021	SYSTEM	(\$16,937.58)															
					7	Aug 2, 2021	SYSTEM	\$16,937.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user cracrb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.														
																7	Aug 2, 2021	SYSTEM	(\$16,937.58)				
					8	Aug 17, 2021	SYSTEM	\$16,937.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user cracrb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.														
					8	Aug 17, 2021	SYSTEM	(\$16,937.58)															
					9	Sep 3, 2021	SYSTEM	\$16,937.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user doolet1 overridding Payment Estimate Exception 13 on the current Payment Estimate.														
												9	Sep 3, 2021	SYSTEM	(\$16,937.58)								
					10	Sep 16, 2021	SYSTEM	\$16,937.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user doolet1 overridding Payment Estimate Exception 28 on the current Payment Estimate.														
																			10	Sep 16, 2021	SYSTEM	(\$16,937.58)	
																						11	Oct 4, 2021
							11	Oct 4, 2021	SYSTEM	(\$16,937.58)													
										12	Oct 19, 2021	SYSTEM	\$16,937.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user cracrb1 overridding Payment Estimate Exception 32 on the current Payment Estimate.									
					12	Oct 19, 2021	SYSTEM	(\$16,937.58)															
				- Total				(\$84,687.90)															
			Material - Tota					(\$84,687.90)															
			MaterialCredit		3	Jun 3, 2021	SYSTEM	\$16,937.58															
					4	Jun 17, 2021	SYSTEM	\$16,937.58															
					5	Jul 2, 2021	SYSTEM	\$16,937.58															
					6	Jul 16,	SYSTEM	\$16,937.58															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J4S3389	0580	ROCK SOCKETS (3 FT 0 IN. DIA.)	MaterialCredit			2021											
		(3 FT O IN. DIA.)			7	Aug 2, 2021	SYSTEM	\$16,937.58									
				- Total				\$84,687.90									
			MaterialCredit	- Total				\$84,687.90									
	0580 -	Total						\$0.00									
	0620	GALVANIZED STRUCTURAL STEEL PILES (12 IN	Material		4	Jun 17, 2021	SYSTEM	\$17,154.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user cracrb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.								
		IIN			4	Jun 17, 2021	SYSTEM	(\$17,154.08)									
				- Total				\$0.00									
			Material - Tota					\$0.00									
	0620 -	Total						\$0.00									
	0640	PILE POINT REINFORCEMENT	Material		8	Aug 17, 2021	SYSTEM	\$1,407.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user cracrb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.								
					8	Aug 17, 2021	SYSTEM	(\$1,407.96)									
											9	Sep 3, 2021	SYSTEM	\$1,407.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user doolet1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
								9	Sep 3, 2021	SYSTEM	(\$1,407.96)	Zumate Zusephen 10 on the sanoth 1 synthetic					
							10	Sep 16, 2021	SYSTEM	\$1,407.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user doolet1 overridding Payment Estimate Exception 31 on the current Payment Estimate.						
									10	Sep 16, 2021	SYSTEM	(\$1,407.96)					
						11	Oct 4, 2021	SYSTEM	\$1,407.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user cracrb1 overridding Payment Estimate Exception 31 on the current Payment Estimate.							
										11	Oct 4, 2021	SYSTEM	(\$1,407.96)				
						12	Oct 19, 2021	SYSTEM	\$1,407.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user cracrb1 overridding Payment							
						12	Oct 19,	SYSTEM	(\$1,407.96)	Estimate Exception 34 on the current Payment Estimate.							
				- Total		2021		\$0.00									
			Material - Tota					\$0.00									
	0640 -	Total						\$0.00									
	0650	CLASS B CONCRETE	Material		2	May 17, 2021	SYSTEM	(\$13,172.58)									
		(SUBSTRUCTURE)			3	Jun 3, 2021	SYSTEM	\$13,172.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user cracrb1 overridding Payment Estimate Exception 16 on the current Payment Estimate.								
													3	Jun 3, 2021	SYSTEM	(\$13,172.58)	
													4	Jun 17, 2021	SYSTEM	\$13,172.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user cracrb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
									4	Jun 17, 2021	SYSTEM	(\$13,172.58)					
					5	Jul 2, 2021	SYSTEM	\$32,373.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user cracrb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.								
					5	Jul 2, 2021	SYSTEM	(\$32,373.28)									
				6		Jul 16, 2021	SYSTEM	\$32,373.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user cracrb1 overridding Payment Estimate Exception 16 on the current Payment Estimate.								
					6	Jul 16, 2021	SYSTEM	(\$32,373.28)									
							7	Aug 2,	SYSTEM	\$76,133.02	This adjustment offsets the original system-generated Material Payment						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J4S3389	0650	CLASS B CONCRETE	Material			2021			Estimate Item Adjustment (0012) due to user cracrb1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
		(SUBSTRUCTURE)			7	Aug 2, 2021	SYSTEM	(\$76,133.02)					
					8	Aug 17, 2021	SYSTEM	\$76,133.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user cracrb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					8	Aug 17, 2021	SYSTEM	(\$76,133.02)					
					9	Sep 3, 2021	SYSTEM	\$76,133.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user doolet1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					9	Sep 3, 2021	SYSTEM	(\$76,133.02)					
					10	Sep 16, 2021	SYSTEM	\$76,133.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user doolet1 overridding Payment Estimate Exception 32 on the current Payment Estimate.				
					10	Sep 16, 2021	SYSTEM	(\$76,133.02)					
					11	Oct 4, 2021	SYSTEM	\$76,133.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user cracrb1 overridding Payment Estimate Exception 32 on the current Payment Estimate.				
					11	Oct 4, 2021	SYSTEM	(\$76,133.02)					
									12	Oct 19, 2021	SYSTEM	\$76,133.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user cracrb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$76,133.02)					
			- Total				(\$13,172.58)						
			Material - Tota	ı				(\$13,172.58)					
			MaterialCredit		3	Jun 3, 2021	SYSTEM	\$13,172.58					
				- Total				\$13,172.58					
			MaterialCredit	- Total				\$13,172.58					
	0650 -	Total						\$0.00					
	0660	TYPE D BARRIER	Material		11	Oct 4, 2021	SYSTEM	\$55,141.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user cracrb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.				
					11	Oct 4, 2021	SYSTEM	(\$55,141.05)					
					12	Oct 19, 2021	SYSTEM	\$55,141.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user cracrb1 overridding Payment Estimate Exception 37 on the current Payment Estimate.				
					12	Oct 19, 2021	SYSTEM	(\$55,141.05)					
				- Total				\$0.00					
			Material - Tota	ıl				\$0.00					
	0660 -	Total SLAB ON	Construction		7	Aug 3	QVQTF14	\$0.00	Dayment Estimate Item Adjustment generated Stealer's Transaction				
	0670	CONCRETE NU- GIRDER	Construction Stockpile		7	Aug 2, 2021	SYSTEM	(\$3,107.07)	Payment Estimate Item Adjustment generated Stockpile Transaction				
				Total	10	Sep 16, 2021	SYSTEM	(\$12,446.99)	Payment Estimate Item Adjustment generated Stockpile Transaction				
			Construction	- Total	etal			(\$15,554.06)					
			Construction S	Stockpile - 10	4	Jun 17,	SYSTEM	(\$15,554.06) \$15,554.06	Payment Estimate Item Adjustment generated Stockpile Transaction				
			Stockpile STMI			2021	2. STEW		,				
				- Total				\$15,554.06					
			Construction S	Stockpile STI			21/2	\$15,554.06					
		_	Material		7	Aug 2, 2021	SYSTEM	\$55,613.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user cracrb1 overridding Payment Estimate Exception 20 on the current Payment Estimate.				
					7	Aug 2, 2021	SYSTEM	(\$55,613.32)					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3389	0670	SLAB ON CONCRETE NU- GIRDER	Material		8	Aug 17, 2021	SYSTEM	\$55,613.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user cracrb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					8	Aug 17, 2021	SYSTEM	(\$55,613.32)	
					9	Sep 3, 2021	SYSTEM	\$55,613.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user doolet1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					9	Sep 3, 2021	SYSTEM	(\$55,613.32)	
					10	Sep 16, 2021	SYSTEM	\$278,401.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user doolet1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$278,401.62)	
					11	Oct 4, 2021	SYSTEM	\$278,401.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user cracrb1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					11	Oct 4, 2021	SYSTEM	(\$278,401.62)	
					12	Oct 19, 2021	SYSTEM	\$278,401.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user cracrb1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$278,401.62)	
				- Total		2021		\$0.00	
			Material - Tota	ı				\$0.00	
	0670 -	Total						\$0.00	
	0680	SIDEWALK (BRIDGES)	Material		10	Sep 16, 2021	SYSTEM	\$35,886.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user doolet1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$35,886.48)	
					11	Oct 4, 2021	SYSTEM	\$43,669.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user cracrb1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					11	Oct 4, 2021	SYSTEM	(\$43,669.92)	
					12	Oct 19, 2021	SYSTEM	\$43,669.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user cracrb1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$43,669.92)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0680 -	Total						\$0.00	
	0690	FORM LINERS	Material		11	Oct 4, 2021	SYSTEM	\$10,597.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user cracrb1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					11	Oct 4, 2021	SYSTEM	(\$10,597.02)	
					12	Oct 19, 2021	SYSTEM	\$10,597.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user cracrb1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$10,597.02)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0690 -	Total						\$0.00	
	0700	NU 35, PRESTRESSED	Construction Stockpile		7	Aug 2, 2021	SYSTEM	(\$206,737.86)	Payment Estimate Item Adjustment generated Stockpile Transaction
		CONC NU-GIRDER		- Total				(\$206,737.86)	
			Construction	Stockpile - To	otal			(\$206,737.86)	
			Construction Stockpile		4	Jun 17, 2021	SYSTEM	\$206,737.86	Payment Estimate Item Adjustment generated Stockpile Transaction



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4S3389	0700	NU 35, PRESTRESSED	STMI	STMI - Total				\$206,737.86		
		CONC NU-GIRDER	Construction	Stockpile STI	VII - Total			\$206,737.86		
			Material		7	Aug 2, 2021	SYSTEM	\$269,468.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user cracrb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
					7	Aug 2, 2021	SYSTEM	(\$269,468.64)		
					8	Aug 17, 2021	SYSTEM	\$269,468.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user cracrb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
					8	Aug 17, 2021	SYSTEM	(\$269,468.64)		
					9	Sep 3, 2021	SYSTEM	\$269,468.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user doolet1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	
					9	Sep 3, 2021	SYSTEM	(\$269,468.64)		
					10	Sep 16, 2021	SYSTEM	\$269,468.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user doolet1 overridding Payment Estimate Exception 46 on the current Payment Estimate.	
					10	Sep 16, 2021	SYSTEM	(\$269,468.64)		
					11	Oct 4, 2021	SYSTEM	\$269,468.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user cracrb1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	
						11	Oct 4, 2021	SYSTEM	(\$269,468.64)	
					12	Oct 19, 2021	SYSTEM	\$269,468.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user cracrb1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	
					12	Oct 19, 2021	SYSTEM	(\$269,468.64)		
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
	0700 -	- Total						\$0.00		
	0710	REINFORCING STEEL (BRIDGES)			0	May 17,	SYSTEM	(\$12,183.81)		
	0710		Material		2	2021				
	0710		Material		3		SYSTEM	(\$12,183.81)		
	0710		Material			2021 Jun 3,	SYSTEM SYSTEM	(\$12,183.81) (\$12,183.81)		
	0710		Material		3	2021 Jun 3, 2021 Jun 17,				
	0710		Material		3	2021 Jun 3, 2021 Jun 17, 2021 Jul 2,	SYSTEM	(\$12,183.81)		
	0710		Material		3 4 5	2021 Jun 3, 2021 Jun 17, 2021 Jul 2, 2021 Jul 16,	SYSTEM SYSTEM	(\$12,183.81) (\$12,183.81)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user cracrb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
	0710		Material		3 4 5	2021 Jun 3, 2021 Jun 17, 2021 Jul 2, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM	(\$12,183.81) (\$12,183.81) (\$12,183.81)	Estimate Item Adjustment (0018) due to user cracrb1 overridding Payment	
	0710		Material		3 4 5 6 7	2021 Jun 3, 2021 Jun 17, 2021 Jul 2, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,183.81) (\$12,183.81) (\$12,183.81) \$12,183.81	Estimate Item Adjustment (0018) due to user cracrb1 overridding Payment	
	0710		Material		3 4 5 6 7	2021 Jun 3, 2021 Jun 17, 2021 Jul 2, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,183.81) (\$12,183.81) (\$12,183.81) \$12,183.81 (\$12,183.81)	Estimate Item Adjustment (0018) due to user cracrb1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user cracrb1 overridding Payment	
	0710		Material		3 4 5 6 7 7 8	2021 Jun 3, 2021 Jun 17, 2021 Jul 12, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 17, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,183.81) (\$12,183.81) (\$12,183.81) \$12,183.81 (\$12,183.81) \$16,687.35	Estimate Item Adjustment (0018) due to user cracrb1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user cracrb1 overridding Payment	
	0710		Material		3 4 5 6 7 7 8 8 8	2021 Jun 3, 2021 Jun 17, 2021 Jul 12, 2021 Jul 2, 2021 Aug 2, 2021 Aug 17, 2021 Aug 17, 2021 Sep 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,183.81) (\$12,183.81) (\$12,183.81) \$12,183.81 (\$12,183.81) \$16,687.35 (\$16,687.35)	Estimate Item Adjustment (0018) due to user cracrb1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user cracrb1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user doolet1 overridding Payment	
	0710		Material		3 4 5 6 7 7 8 8	2021 Jun 3, 2021 Jun 17, 2021 Jul 12, 2021 Jul 16, 2021 Aug 2, 2021 Aug 17, 2021 Aug 17, 2021 Sep 3, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,183.81) (\$12,183.81) (\$12,183.81) \$12,183.81 (\$12,183.81) \$16,687.35 (\$16,687.35)	Estimate Item Adjustment (0018) due to user cracrb1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user cracrb1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user doolet1 overridding Payment	
	0710		Material		3 4 5 6 7 7 8 8 9	2021 Jun 3, 2021 Jun 17, 2021 Jul 17, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 17, 2021 Sep 3, 2021 Sep 16,	SYSTEM	(\$12,183.81) (\$12,183.81) (\$12,183.81) (\$12,183.81) (\$12,183.81) \$16,687.35 (\$16,687.35) \$16,687.35	Estimate Item Adjustment (0018) due to user cracrb1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user cracrb1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user doolet1 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user doolet1 overridding Payment Estimate Item Adjustment (0024) due to user doolet1 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4S3389	0710	REINFORCING STEEL (BRIDGES)	Material			2021			Estimate Item Adjustment (0025) due to user cracrb1 overridding Payment Estimate Exception 52 on the current Payment Estimate.		
		OTELL (BRIDGLO)			11	Oct 4, 2021	SYSTEM	(\$18,541.50)	Estimate Exception of the sunsiti ayrion Estimate.		
					12	Oct 19, 2021	SYSTEM	\$18,541.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user cracrb1 overridding Payment Estimate Exception 51 on the current Payment Estimate.		
					12	Oct 19, 2021	SYSTEM	(\$18,541.50)			
				- Total				(\$60,919.05)			
			Material - Tota					(\$60,919.05)			
			MaterialCredit		3	Jun 3, 2021	SYSTEM	\$12,183.81			
					4	Jun 17, 2021	SYSTEM	\$12,183.81			
					5	Jul 2, 2021	SYSTEM	\$12,183.81			
					6	Jul 16, 2021	SYSTEM	\$12,183.81			
					7	Aug 2, 2021	SYSTEM	\$12,183.81			
				- Total				\$60,919.05			
			MaterialCredit	- Total				\$60,919.05			
	0710 -	· Total						\$0.00			
	0720	CONDUIT SYSTEM ON STRUCTURE	Material		10	Sep 16, 2021	SYSTEM	\$5,247.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user doolet1 overridding Payment Estimate Exception 51 on the current Payment Estimate.		
					10	Sep 16, 2021	SYSTEM	(\$5,247.75)			
					11	Oct 4, 2021	SYSTEM	\$13,119.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user cracrb1 overridding Payment Estimate Exception 56 on the current Payment Estimate.		
					11	Oct 4, 2021	SYSTEM	(\$13,119.38)			
					12	Oct 19, 2021	SYSTEM	\$13,119.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user craorb1 overridding Payment Estimate Exception 55 on the current Payment Estimate.		
					12	Oct 19, 2021	SYSTEM	(\$13,119.38)			
				- Total				\$0.00			
			Material - Tota	al				\$0.00			
	0720 -	· Total						\$0.00			
	0730	VERTICAL DRAIN AT END BENTS			9	Sep 3, 2021	SYSTEM	\$4,002.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user doolet1 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
							9	Sep 3, 2021	SYSTEM	(\$4,002.66)	
					10	Sep 16, 2021	SYSTEM	\$4,002.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user doolet1 overridding Payment Estimate Exception 55 on the current Payment Estimate.		
					10	Sep 16, 2021	SYSTEM	(\$4,002.66)			
					11	Oct 4, 2021	SYSTEM	\$4,002.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user cracrb1 overridding Payment Estimate Exception 60 on the current Payment Estimate.		
					11	Oct 4, 2021	SYSTEM	(\$4,002.66)			
					12	Oct 19, 2021	SYSTEM	\$4,002.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user cracrb1 overridding Payment Estimate Exception 59 on the current Payment Estimate.		
					12	Oct 19, 2021	SYSTEM	(\$4,002.66)			
				- Total				\$0.00			
			Material - Tota					\$0.00			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4S3389	0730 -	· Total						\$0.00													
	0770	CONCRETE AND MASONRY PROTECTION SYSTEM	Material		10	Sep 16, 2021	SYSTEM	\$3,139.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user doolet1 overridding Payment Estimate Exception 53 on the current Payment Estimate.												
					10	Sep 16, 2021	SYSTEM	(\$3,139.86)													
					11	Oct 4, 2021	SYSTEM	\$3,139.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user cracrb1 overridding Payment Estimate Exception 58 on the current Payment Estimate.												
					11	Oct 4, 2021	SYSTEM	(\$3,139.86)													
					12	Oct 19, 2021	SYSTEM	\$3,139.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user cracrb1 overridding Payment Estimate Exception 57 on the current Payment Estimate.												
					12	Oct 19, 2021	SYSTEM	(\$3,139.86)	·												
				- Total				\$0.00													
			Material - Tota	1				\$0.00													
	0770 -	· Total						\$0.00													
	0790	MECHANICALLY STABILIZED EARTH WALL SYS	Material		4	Jun 17, 2021	SYSTEM	\$140,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user cracrb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.												
					4	Jun 17, 2021	SYSTEM	(\$140,400.00)													
					5	Jul 2, 2021	SYSTEM	\$175,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user cracrb1 overridding Payment Estimate Exception 27 on the current Payment Estimate.												
					5	Jul 2, 2021	SYSTEM	(\$175,248.00)													
					6	Jul 16, 2021	SYSTEM	\$175,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user cracrb1 overridding Payment Estimate Exception 24 on the current Payment Estimate.												
					6	Jul 16, 2021	SYSTEM	(\$175,248.00)													
					7	Aug 2, 2021	SYSTEM	\$175,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user cracrb1 overridding Payment Estimate Exception 33 on the current Payment Estimate.												
					7	Aug 2, 2021	SYSTEM	(\$175,248.00)													
					8	Aug 17, 2021	SYSTEM	\$175,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user cracrb1 overridding Payment Estimate Exception 34 on the current Payment Estimate.												
					8	Aug 17, 2021	SYSTEM	(\$175,248.00)													
					9	Sep 3, 2021	SYSTEM	\$175,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user doolet1 overridding Payment Estimate Exception 33 on the current Payment Estimate.												
					9	Sep 3, 2021	SYSTEM	(\$175,248.00)													
																	10	Sep 16, 2021	SYSTEM	\$175,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user doolet1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$175,248.00)													
					11	Oct 4, 2021	SYSTEM	\$175,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user cracrb1 overridding Payment Estimate Exception 61 on the current Payment Estimate.												
					11	Oct 4, 2021	SYSTEM	(\$175,248.00)													
					1	12	Oct 19, 2021	SYSTEM	\$175,248.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user cracrb1 overridding Payment Estimate Exception 60 on the current Payment Estimate.											
					12	Oct 19, 2021	SYSTEM	(\$175,248.00)													
				- Total				\$0.00													
			Material - Tota	l e				\$0.00													



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks														
J4S3389	0790 -	Total		Туре				\$0.00															
	0800	CONCRETE AND MASONRY PROTECTION	Material		10	Sep 16, 2021	SYSTEM	\$3,235.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user doolet1 overridding Payment Estimate Exception 54 on the current Payment Estimate.														
		SYSTEM			10	Sep 16, 2021	SYSTEM	(\$3,235.23)															
					11	Oct 4, 2021	SYSTEM	\$3,235.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user cracrb1 overridding Payment Estimate Exception 59 on the current Payment Estimate.														
					11	Oct 4, 2021	SYSTEM	(\$3,235.23)															
					12	Oct 19, 2021	SYSTEM	\$3,235.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user cracrb1 overridding Payment Estimate Exception 58 on the current Payment Estimate.														
					12	Oct 19, 2021	SYSTEM	(\$3,235.23)															
				- Total				\$0.00															
			Material - Tota	ı				\$0.00															
	0800 -	Total						\$0.00															
	0820	MECHANICALLY STABILIZED	Construction Stockpile		6	Jul 16, 2021	SYSTEM	(\$25,252.49)	Payment Estimate Item Adjustment generated Stockpile Transaction														
		EARTH WALL SYS		- Total				(\$25,252.49)															
			Construction	Stockpile - To	otal			(\$25,252.49)															
			Construction Stockpile STMI	kpile	4	Jun 17, 2021	SYSTEM	\$25,252.49	Payment Estimate Item Adjustment generated Stockpile Transaction														
				- Total				\$25,252.49															
			Construction	Stockpile STI	/II - Total			\$25,252.49															
			Material		6	Jul 16, 2021	SYSTEM	\$95,076.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user cracrb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.														
					6	Jul 16, 2021	SYSTEM	(\$95,076.00)															
						7	Aug 2, 2021	SYSTEM	\$95,076.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user cracrb1 overridding Payment Estimate Exception 37 on the current Payment Estimate.													
					7	Aug 2, 2021	SYSTEM	(\$95,076.00)															
					8	Aug 17, 2021	SYSTEM	\$190,152.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user cracrb1 overridding Payment Estimate Exception 38 on the current Payment Estimate.														
						8	Aug 17, 2021	SYSTEM	(\$190,152.00)														
							9	Sep 3, 2021	SYSTEM	\$190,152.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user doolet1 overridding Payment Estimate Exception 37 on the current Payment Estimate.												
								9	Sep 3, 2021	SYSTEM	(\$190,152.00)												
														10	Sep 16, 2021	SYSTEM	\$190,152.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user doolet1 overridding Payment Estimate Exception 60 on the current Payment Estimate.					
					10	Sep 16, 2021	SYSTEM	(\$190,152.00)	·														
					11	Oct 4, 2021	SYSTEM	\$190,152.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user cracrb1 overridding Payment Estimate Exception 65 on the current Payment Estimate.														
					11	Oct 4, 2021	SYSTEM	(\$190,152.00)															
									1.			-								12	Oct 19, 2021	SYSTEM	\$190,152.00
					12	Oct 19, 2021	SYSTEM	(\$190,152.00)															
				- Total				\$0.00															
			Material - Tota					\$0.00															
	0820 -	Total						\$0.00															





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3389	5001	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		8	Aug 17, 2021	SYSTEM	\$14,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user cracrb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Aug 17, 2021	SYSTEM	(\$14,490.00)	
					9	Sep 3, 2021	SYSTEM	\$14,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user doolet1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Sep 3, 2021	SYSTEM	(\$14,490.00)	
					10	Sep 16, 2021	SYSTEM	\$14,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user doolet1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$14,490.00)	
					11	Oct 4, 2021	SYSTEM	\$14,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user cracrb1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					11	Oct 4, 2021	SYSTEM	(\$14,490.00)	
					12	Oct 19, 2021	SYSTEM	\$14,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user cracrb1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					12	Oct 19, 2021	SYSTEM	(\$14,490.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	5001 -	Total						\$0.00	
J4S3389 -	- Total							\$21,189.39	
Overall -	Total							\$21,189.39	