

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 2, 2022

| Progress Estimate Number | Contract ID | 210122-D02 | Pay Period Start December 2, 202 | 1Original Contract Amount \$5,294,709.41 |
|--------------------------|----------------|----------------------------|---------------------------------------|--|
| 14 | Prime Contract | orN.B. West Contracting Co | mpany Pay Period End February 1, 2022 | Net Change Order Amount (\$487,553.85) |
| 17 | | | | Current Contract Amount \$4,807,155.56 |

| Approval Date | | By User |
|------------------|--|---------|
| February 2, 2022 | Generated and Approved (and should be considered Draft) at the Project Office Level by | abbote1 |
| February 2, 2022 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | abbote1 |
| February 3, 2022 | Reviewed and Approved at the Central Office Controllers Office Level by | ramses1 |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete | | | | |
|--------------------------|-------------------------|------------------------|---------------------------------------|--|--|--|--|
| November 1, 2021 | November 1, 2021 | October 5, 2021 | 100.00% | | | | |

| | Contract Informational Dat | tes | Milestones |
|------------------------|----------------------------|--------------------------------|----------------------------------|
| Date Description | Original Completion Date | Current Completion Date | No Milestones Exist for Contract |
| Acceptance Date | | | |
| Awarded Date | February 3, 2021 | February 3, 2021 | |
| Letting Date | January 22, 2021 | January 22, 2021 | |
| Notice to Proceed Date | March 8, 2021 | March 8, 2021 | |
| Work Began Date | April 19, 2021 | April 19, 2021 | |

| Contract Total Pa | ay For Estimate No. 14 | | | | |
|-------------------|----------------------------|---------------|----------------|----------------|--|
| | | This Estimate | Previous | To Date | |
| 210122-D02 | | | | | |
| | Total Posted Items Pay | \$3,037.20 | \$4,804,113.69 | \$4,807,150.89 | |
| | Gross Item Adjustments | \$5,325.42 | \$185,902.70 | \$191,228.12 | |
| | Incentive | \$0.00 | \$0.00 | \$0.00 | |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 | |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 | |
| | • | | \$4,990,016.39 | \$4,998,379.01 | |
| Contract Total Pa | avable This Estimate: | \$8,362,62 | | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|-------------------------|--------------|--|------|---------------|--------------------------|-----------------------------|
| J5P3236 | 0030 | 2063300 | CLASS 4 EXCAVATION | CUYD | \$60.500 | -0.6 | (\$36.30) |
| | 0100 | 4013000 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | TONS | \$47.000 | 0.5 | \$23.50 |
| Project J5P323 | Project J5P3236 - Total | | | | | | |
| J5S3277 | 0530 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | TONS | \$50.000 | 55 | \$2,750.00 |
| Project J5S327 | 77 - Total | | | | | | \$2,750.00 |
| J5S3393 | 0790 | 6161009 | FLAG ASSEMBLY | EA | \$30.000 | 10 | \$300.00 |
| Project J5S339 | 3 - Total | | | | | | \$300.00 |
| Overall - Total | | | | | | | \$3,037.20 |

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

| Line Item | Adjusti | ments This Estimate | | | | | | |
|-------------------|-------------|---|--------------------|----------------------------------|---|------------------------|---------------------------------------|-------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J5P3236 | 0030 | CLASS 4 EXCAVATION | Overrun | | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',60.50000 - 60.50000, 'is applied (if non-zero). | 0.6 | \$60.50 | \$36.30 |
| | 0100 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | Material | | | -13,182.44 | \$47.00 | (\$619,574.68) |
| | 0100 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item | 13,182.44 | \$47.00 | \$619,574.68 |

Revision 4/1/2020 Page 1 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 2, 2022

Progress Estimate Number
14 Contract ID 210122-D02 Pay Period StartDecember 2, 2021 Original Contract Amount \$5,294,709.41
Prime Contractor N.B. West Contracting Company Pay Period End February 1, 2022 Net Change Order Amount \$4,807,155.56

| Project | Line | Item Description | Adjustment | Other Item | Comments | Adjustment | Line Item | Adjustment |
|---------|------|--|--------------------------|------------------------|---|------------|--------------------------|----------------|
| Number | No. | item Description | Type | Adjustment Type | Comments | Quantity | Adjustment Unit Price | amount |
| J5P3236 | | | | | Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | |
| | 0110 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Material | | | -8,676.4 | \$48.00 | (\$416,467.20) |
| | 0110 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 8,676.4 | \$48.00 | \$416,467.20 |
| | 0190 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | Overrun | | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',250.00000 - 250.00000, 'is applied (if non-zero). | 2 | \$250.00 | \$500.00 |
| | 5002 | MISC. | Other Item Adjustment | Left Over Materials | Material Takeover for steel delivered to job that was not used on the other box culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. | | | \$4,489.12 |
| J5S3277 | 0540 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Material | | | -296.4 | \$46.00 | (\$13,634.40) |
| | 0540 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 296.4 | \$46.00 | \$13,634.40 |
| | 0590 | CHANNELIZER (TRIM LINE) | Overrun | | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero). | 20 | \$15.00 | \$300.00 |
| Total | | | | | | | | \$5,325.42 |

Revision 4/1/2020 Page 2 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | | 2 2 | | | |
|-------------------|--|--|--------|---------|--|--|---|--|--|
| | | | | | (| Contract Project Information | | | |
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work | | |
| J5P3236 | FAF 68-1(10) | Resurface and shoulder improvements | 68/HH | PHELPS | from Rte. 8 to Rte. 19 ne | ar Salem and Rte. HH from F | Rte. 32 to the end of state maintenance | | |
| J5S3277 | FAS S401(84) | Pavement improvements | F | DENT | from Rte. 32 to Rte. E | | | | |
| J5S3393 | FAS S402(50) | Pavement Improvements | K | PHELPS | from Rte. 63 to the end o | of state maintenance | | | |
| Totals by . | Job Numbe | rs | | | | | | | |
| J5P3236 | Posted Item Pay Gross Item Adjustments Gross Item Pay | | | | This Estimate (\$12.80) \$5,025.42 \$5,012.62 | Previous \$3,497,051.14 \$124,331.20 \$3,621,382.34 | To Date \$3,497,038.34 \$129,356.62 \$3,626,394.96 | | |
| | Incentive Disincentive Liquidated Damages Other Contract Adjustments | | | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | | |
| J5S3277 | | d Item Pay Item Adjustme | | tem Pay | This Estimate \$2,750.00 \$300.00 \$3,050.00 | Previous \$338,717.71 \$13,676.95 \$352,394.66 | To Date \$341,467.71 \$13,976.95 \$355,444.66 | | |
| | Liquid | tive centive lated Damages Contract Adjus | tments | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | | |
| J5S3393 | | d Item Pay Item Adjustme | | tem Pay | This Estimate \$300.00 \$0.00 \$300.00 | Previous \$968,344.84 \$47,894.55 \$1,016,239.39 | To Date \$968,644.84 \$47,894.55 \$1,016,539.39 | | |
| | Liquio | tive centive lated Damages Contract Adjus | tments | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | | |

Revision 4/1/2020 Page 3 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|---|---------------|---------------|------------|
| Estimate Exception Type: Insufficient Materials: Project J5P3236, Item 4013000, Project Item Line Number 0100, Material Set 401300096, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient. | Waiting on QA | linkd1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3236, Item 4020520, Project Item Line Number 0110, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient. | Waiting on QA | linkd1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3277, Item 4020520, Project Item Line Number 0540, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient. | Waiting on QA | linkd1 | Overridden |

Revision 4/1/2020 Page 4 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

| Contract | Project | | es are t | | eport Generated date and can differ from the posted am Description | ount at the | Net | timate was (Total | Generat Unit | | Unit Price | Total Value POSTED |
|-------------|---------|----------|----------|--------------|---|-------------|-----------------|-----------------------|-----------------|------------------------------------|--------------|-------------------------------------|
| Nm.CONTRACT | No. | Category | No. | Item Code | Description | Quantity | Change Order | Current Quantity | Onit | Total Posted Approved Qty | Unit Price | To Date (See report generated date) |
| 210122-D02 | J5P3236 | 0001 | 0010 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | | \$105,600.00 | \$105,600.00 |
| | | 0001 | 0020 | 2063000 | CLASS 3 EXCAVATION | 234.00 | 0.00 | 234.00 | CUYD | 234.00 | \$23.10 | \$5,405.40 |
| | | 0001 | 0030 | 2063300 | CLASS 4 EXCAVATION | 670.00 | 0.00 | 670.00 | CUYD | 670.00 | \$60.50 | \$40,535.00 |
| | | 0001 | 0040 | 2079909 | MISC.MODIFIED LINEAR GRADING, CLASS II | 2,592.00 | -52.60 | 2,539.40 | STA | 2,539.40 | \$144.25 | \$366,308.45 |
| | | 0001 | 0050 | 2142000 | FURNISHING ROCK FILL | 303.00 | 15.67 | 318.67 | CUYD | 318.67 | \$26.50 | \$8,444.76 |
| | | 0001 | 0060 | 2143000 | PLACING ROCK FILL | 303.00 | 15.67 | 318.67 | CUYD | 318.67 | \$36.00 | \$11,472.12 |
| | | 0001 | 0070 | 2163500 | PARTIAL REMOVAL OF CULVERT CONCRETE | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$10,600.00 | \$10,600.00 |
| | | 0001 | 0080 | 3040143 | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | 306.00 | 0.00 | 306.00 | SQYD | 306.00 | \$8.50 | \$2,601.00 |
| | | 0001 | 0090 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 1,477.00 | -1,022.30 | 454.70 | TONS | 454.70 | \$50.00 | \$22,735.0 |
| | | 0001 | 0100 | 4013000 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | 21,398.90 | -1,916.36 | 19,482.54 | TONS | 19,482.44 | \$47.00 | \$915,674.6 |
| | | 0001 | 0110 | 4020520 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE | 25,306.60 | -3,580.20 | 21,726.40 | TONS | 21,726.40 | \$48.00 | \$1,042,867.20 |
| | | 0001 | 0120 | 4071005 | LEVELING) TACK COAT | 36,782.00 | -17,434.00 | 19,348.00 | GAL | 19,348.00 | \$1.89 | \$36,567.7 |
| | | 0001 | 0130 | 6097000 | ROCK LINING | 59.00 | 0.00 | 59.00 | CUYD | 59.00 | \$70.00 | \$4,130.0 |
| | | 0001 | 0140 | 6123000A | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$500.00 | \$1,000.00 |
| | | 0001 | 0150 | 6161005 | CONSTRUCTION SIGNS | 4,359.00 | -640.25 | 3,718.75 | SQFT | 3,718.75 | \$4.25 | \$15,804.69 |
| | | 0001 | 0160 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$100.00 | \$200.00 |
| | | 0001 | 0170 | 6161009 | FLAG ASSEMBLY | 37.00 | -7.00 | 30.00 | EA | 30.00 | \$30.00 | \$900.0 |
| | | 0001 | 0180 | 6161025 | CHANNELIZER (TRIM LINE) | 400.00 | 0.00 | 400.00 | EA | 400.00 | \$15.00 | \$6.000.0 |
| | | 0001 | 0190 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | 8.00 | 2.00 | 10.00 | EA | 10.00 | \$250.00 | \$2,500.0 |
| | | 0001 | 0200 | 6161052 | WARNING LIGHT, TYPE B | 2.00 | -2.00 | 0.00 | EA | 0.00 | \$100.00 | \$0.0 |
| | | 0001 | 0210 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR | 8.00 | -1.00 | 7.00 | EA | 7.00 | \$2,500.00 | \$17,500.0 |
| | | 0001 | 0220 | 6162004 | RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS | 8.00 | -8.00 | 0.00 | EA | 0.00 | \$100.00 | \$0.0 |
| | | 0001 | 0230 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | | \$455,000.0 |
| | | 0001 | 0240 | 6181020 | ADDITIONAL MOBILIZATION FOR SEEDING | 4.00 | -3.00 | 1.00 | EA | 1.00 | \$600.00 | \$600.0 |
| | | 0001 | 0250 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 18.00 | 18.00 | 36.00 | LF | 36.00 | \$20.00 | \$720.0 |
| | | 0001 | 0260 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 259,585.00 | 0.00 | 259,585.00 | LF | 259,585.00 | \$0.09 | \$23,362.6 |
| | | 0001 | 0270 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 229,234.00 | 0.00 | 229,234.00 | LF | 229,234.00 | \$0.10 | \$21,777.2 |
| | | 0001 | 0280 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 820.00 | 0.00 | 820.00 | SQYD | 820.00 | \$10.15 | \$8,323. |
| | | 0001 | 0290 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 631.00 | 0.00 | 631.00 | SQYD | 631.00 | \$4.50 | \$2,839.5 |
| | | 0001 | 0300 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | 2,476.20 | 0.00 | 2,476.20 | STA | 2,476.20 | \$10.00 | \$24,762.0 |
| | | 0001 | 0310 | 6261001 | BITUMINOUS CENTERLINE RUMBLE STRIP | 1,320.90 | 0.00 | 1,320.90 | STA | 1,320.90 | \$10.00 | \$13,209.0 |
| | | 0001 | 0320 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$4,500.00 | \$4,500.0 |
| | | 0001 | 0330 | 7034041 | CLASS B-1 CONCRETE (CULVERTS) | 171.00 | 0.00 | 171.00 | CUYD | 171.00 | \$1,024.50 | \$175,189.5 |
| | | 0001 | 0340 | 7039901 | MISC.Culvert Headwall Modification | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$8,300.00 | \$0.0 |
| | | 0001 | 0350 | 7061030 | REINFORCING STEEL (CULVERTS) | 25,600.00 | 0.00 | 25,600.00 | LB | 25,600.00 | \$3.30 | \$84,480.0 |
| | | 0001 | 0360 | 7250424 | 24 IN. PIPE GROUP C | 76.00 | 0.00 | 76.00 | LF | 76.00 | \$92.25 | \$7,011.0 |
| | | 0001 | 0370 | 7250430 | 30 IN. PIPE GROUP C | 8.00 | 0.00 | 8.00 | LF | 8.00 | \$207.00 | \$1,656.0 |
| | | 0001 | 0380 | 7250436 | 36 IN. PIPE GROUP C | 8.00 | 0.00 | 8.00 | LF | 8.00 | \$215.00 | \$1,720.0 |
| | | 0001 | 0390 | 7250442 | 42 IN. PIPE GROUP C | 8.00 | 0.00 | 8.00 | LF | 8.00 | \$223.00 | \$1,784.0 |
| | | 0001 | 0400 | 7250448 | 48 IN. PIPE GROUP C | 16.00 | -16.00 | 0.00 | LF | 0.00 | \$228.00 | \$0.0 |
| | | 0001 | 0410 | 7320824A | 24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$825.00 | \$1,650.0 |
| | | 0001 | 0420 | 7320830A | 30 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,095.00 | \$2,190.0 |
| | | 0001 | 0430 | 7320836A | | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,254.00 | \$2,508.0 |
| | | 0001 | 0440 | 7320842A | 42 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,639.00 | \$3,278.0 |

Revision 4/1/2020 Page 5 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

| ontract ONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POS To Date (See re generated dat |
|--------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|---|
| 2-D02 | J5P3236 | 0001 | 0450 | 7320848A | 48 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION | 4.00 | -4.00 | 0.00 | EA | 0.00 | \$1,881.00 | \$ |
| | | 0001 | 0460 | 8051000A | SEEDING - COOL SEASON MIXTURES | 59.70 | -42.20 | 17.50 | ACRE | 17.50 | \$1.00 | \$1 |
| | | 0001 | 0470 | 8061004 | SEDIMENT TRAP ROCK | 150.10 | -150.10 | 0.00 | CUYD | 0.00 | \$66.00 | 9 |
| | | 0001 | 0480 | 8061005 | ROCK DITCH CHECK | 1,001.00 | -707.00 | 294.00 | LF | 294.00 | \$15.40 | \$4,52 |
| | | 0001 | 0490 | 8061006 | ALTERNATE DITCH CHECK | 125.00 | 0.00 | 125.00 | LF | 125.00 | \$13.50 | \$1,6 |
| | | 0001 | 0500 | 8061016 | SEDIMENT REMOVAL | 1,001.00 | -1,001.00 | 0.00 | CUYD | 0.00 | \$2.00 | |
| | | 0001 | 0510 | 8061017 | TEMPORARY SEEDING AND MULCHING | 11.90 | -8.40 | 3.50 | ACRE | 3.50 | \$1.00 | |
| | | 0001 | 0520 | 8061019 | SILT FENCE | 5,003.00 | -5,003.00 | 0.00 | LF | 0.00 | \$2.35 | |
| | | 0040 | 0660 | 9039901 | MISC.Adjusting Existing Signs | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$7,500.00 | |
| | | 0070 | 0670 | 7039903 | MISC.HEADWALL MODIFICATION | 68.00 | -68.00 | 0.00 | LF | 0.00 | \$110.00 | |
| | | 0071 | 0680 | 7039903 | MISC.HEADWALL MODIFICATION | 94.00 | -94.00 | 0.00 | LF | 0.00 | \$110.00 | |
| | | 0072 | 0690 | 7039903 | MISC.HEADWALL MODIFICATION | 45.00 | 0.00 | 45.00 | LF | 45.00 | \$110.00 | \$4,9 |
| | | 0073 | 0700 | 7039903 | MISC.HEADWALL MODIFICATION | 52.00 | -52.00 | 0.00 | LF | 0.00 | \$110.00 | |
| | | 0073 | 0710 | 7040106 | FULL DEPTH REPAIR | 10.00 | -10.00 | 0.00 | SQFT | 0.00 | \$500.00 | |
| | | 0073 | 5001 | 7279901 | MISC.48" Pipe including excavation, grading, and pavement. | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$29,646.32 | \$29,6 |
| | | | 5002 | 7039901 | MISC.Headwall Modification on Box at Log Mile 29.211 Rte 68 | | | | | | | \$2,8 |
| | D | 0001 | | | _ | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$2,800.00 | |
| | J5S3277 | 0001 | 0530 | 3105002 | Oate as of Report Generated Date GRAVEL (A) OR CRUSHED STONE (B) | 270.00 | -215.00 | 55.00 | TONS | 55.00 | \$50.00 | \$3,497,0 \$2,7 |
| | 0000277 | 0001 | 0540 | 4020520 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | 6,281.60 | -1,985.20 | 4,296.40 | TONS | 4,296.40 | \$46.00 | \$197,6 |
| | | 0001 | 0550 | 4071005 | TACK COAT | 7,306.00 | -2,117.00 | 5,189.00 | GAL | 5,189.00 | \$1.89 | \$9,8 |
| | | 0001 | 0560 | 6123000A | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$500.00 | \$1,0 |
| | | 0001 | 0570 | 6161005 | CONSTRUCTION SIGNS | 1,026.00 | 0.00 | 1,026.00 | SQFT | 1,026.00 | \$4.25 | \$4,3 |
| | | 0001 | 0580 | 6161009 | FLAG ASSEMBLY | 11.00 | 0.00 | 11.00 | EA | 11.00 | \$30.00 | \$3 |
| | | 0001 | 0590 | 6161025 | CHANNELIZER (TRIM LINE) | 100.00 | 20.00 | 120.00 | EA | 120.00 | \$15.00 | \$1,8 |
| | | 0001 | 0600 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$2,500.00 | \$5,0 |
| | | 0001 | 0610 | 6162004 | TEMPORARY SHORT-TERM RUMBLE STRIPS | 4.00 | -4.00 | 0.00 | EA | 0.00 | \$100.00 | |
| | | 0001 | 0620 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$75,500.00 | \$75,5 |
| | | 0001 | 0630 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 72,568.00 | 0.00 | 72,568.00 | LF | 72,568.00 | \$0.10 | \$7,2 |
| | | 0001 | 0640 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 61,680.00 | 0.00 | 61,680.00 | LF | 61,680.00 | \$0.10 | \$6,4 |
| | | 0001 | 0650 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 2,009.00 | 453.70 | 2,462.70 | SQYD | 2,462.70 | \$12.00 | \$29,5 |
| | Project J | | otal Value | Posted to D | Date as of Report Generated Date | | | | | | | \$341, |
| | J5S3393 | 0001 | 0720 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$1,200.00 | \$1,2 |
| | | 0001 | 0730 | 2153000 | SHAPING SLOPES, CLASS III | 12.00 | 0.00 | 12.00 | 100F | 12.00 | \$1,200.00 | \$14,4 |
| | | 0001 | 0740 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 288.00 | -172.20 | 115.80 | TONS | 115.80 | \$38.00 | \$4,4 |
| | | 0001 | 0750 | 4020520 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | 12,063.00 | 725.70 | 12,788.70 | TONS | 12,788.70 | \$54.00 | \$690,5 |
| | | 0001 | 0760 | 4071005 | TACK COAT | 13,459.00 | -470.00 | 12,989.00 | GAL | 12,989.00 | \$2.00 | \$25,9 |
| | | 0001 | 0770 | 6123000A | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$500.00 | \$1,0 |
| | | 0001 | 0780 | 6161005 | CONSTRUCTION SIGNS | 1,265.00 | -117.50 | 1,147.50 | SQFT | 1,147.50 | \$4.25 | \$4,8 |
| | | 0001 | 0790 | 6161009 | FLAG ASSEMBLY | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$30.00 | \$3 |
| | | 0001 | 0800 | 6161025 | CHANNELIZER (TRIM LINE) | 100.00 | 0.00 | 100.00 | EA | 100.00 | \$15.00 | \$1,5 |
| | | 0001 | 0810 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$2,500.00 | \$5,0 |
| | | 0001 | 0820 | 6162004 | TEMPORARY SHORT-TERM RUMBLE STRIPS | 4.00 | -4.00 | 0.00 | EA | 0.00 | \$100.00 | |
| | | | 0830 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$43,500.00 | \$43,5 |
| | | | | | to the state of th | 1.00 | 5.00 | | | | , | ψ.0,0 |
| | | 0001 | 0840 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 136,879.00 | 0.00 | 136,879.00 | LF | 136,879.00 | \$0.10 | \$13,6 |

Revision 4/1/2020 Page 6 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|-------------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|------------|--|
| 210122-D02 | J5S3393 | | | | MARKING PAINT, TYPE P BEADS | | | | | | | |
| | | 0001 | 0860 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 885.00 | 0.00 | 885.00 | SQYD | 885.00 | \$6.70 | \$5,929.50 |
| | | 0001 | 0870 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 817.00 | 0.00 | 817.00 | SQYD | 817.00 | \$6.70 | \$5,473.90 |
| | | 0010 | 0880 | 6061069 | MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$3,000.00 | \$24,000.00 |
| | | 0010 | 0890 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$2,800.00 | \$22,400.00 |
| | | 0070 | 0900 | 7034600 | CURB BLOCKOUT | 375.00 | 0.00 | 375.00 | LF | 375.00 | \$248.00 | \$93,000.00 |
| | Project J | 5S3393 - To | tal Value | Posted to E | Date as of Report Generated Date | | | | | | | \$968,644.84 |
| 210122-D02 Ove | erall - Total | Value Pos | ted to Da | te as of Rep | ort Generated Date | | | | | | | \$4,807,150.86 |

Revision 4/1/2020 Page 7 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

$\underline{\textbf{The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.}$

Project: J5P3236

| Line Number | Item Code | Description | | DWR Approval Date | | Units | | | Offset/ Distance | Offset/ Distance | Comments |
|----------------|--------------|--|---------|-------------------------|-------|-------|----------------------|--------|---------------------|---------------------|-----------------------------------|
| 0030 | 2063300 | CLASS 4 EXCAVATION | 1/24/22 | 2/2/22 | -0.60 | CUYD | | 29.687 | | | Overpaid box at 29.687 by 0.6 CY. |
| 0100 | 4013000 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS | 1/24/22 | 2/2/22 | 0.50 | TONS | Precast Box Location | | | | |

Project: J5S3277

| Line Number | Item Code | Description | | DWR Approval Date | | | Location | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|---------------------------------|---------|-------------------------|-------|------|-----------------|---------------------|-------------------------------|---------------------|----------|
| 0530 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 1/24/22 | 2/2/22 | 55.00 | TONS | Rte F Driveways | | | | |

Project: J5S3393

| Line Number | Item Code | Description | | DWR Approval Date | | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|---------------|---------|-------------------------|-------|-------|--------------------|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0790 | 6161009 | FLAG ASSEMBLY | 1/24/22 | 2/2/22 | 10.00 | EΔ | Rte K on RWA signs | | | | | |

| 0790 | 6161009 FL | AG ASSEMBLY | | 1/24/22 2/2/22 | 10.00 EA Rte | K on RW | A signs | | | | | | |
|--------------------|--------------|----------------------------|------------------------------------|----------------------------------|-------------------------------|---------|--------------------|-----------------------------|-------------------------|--------------------|---------------------------------|----------------------|------------------|
| | | | e details for Construction Sign | | | | | | | | | | |
| Project J5P3236 | Line Number | DWR Date March 31, 2021 | Total Quantity Posted For DWR Date | | nformation 10.00 ROAD WORK | Station | Log Mile 39.165 | Location | Number of Items 1.00 | SF Each Sign 10 | Special Sign | SF Each Special Sign | Total SF to Post |
| 3353230 | 0150 | Walcii 31, 2021 | 70 | NEXT XX MILES | 10.00 ROAD WORK | | 39.103 | | 1.00 | 10 | | | 10 |
| | | | | CONST-8 48x36 ZONE NO PHONE | 6 12.00 WORK EZONE | | 39.051 | | 1.00 | 12 | | | 12 |
| | | | | CONST-8 48x3i ZONE NO PHONE | 6 12.00 WORK E ZONE | | 17.275 | | 1.00 | 12 | | | 12 |
| | | | | GO20-1 60x24 NEXT XX MILES | 10.00 ROAD WORK | | 17.162 | | 1.00 | 10 | | | 10 |
| | | | | GO20-2 48x24 WORK | 8.00 END ROAD | | 17.062 | | 1.00 | 8 | | | 8 |
| | | | | CONST-7-48 48x2 WORK ZONE | 24 8.00 RATE OUR | | 17.057 | | 1.00 | 8 | | | 8 |
| | | | | GO20-2 48x24 WORK | 8.00 END ROAD | | 39.306 | | 1.00 | 8 | | | 8 |
| | | | | CONST-7-48 48x2 WORK ZONE | 24 8.00 RATE OUR | | 39.278 | | 1.00 | 8 | | | 8 |
| | | May 1, 2021 | 768 | WO3-4(48) 48x44 PREPARED TO S | | | | Various | 12.00 | 16 | | | 192 |
| | | | | WO20-4 48x48 ROAD AHEAD | 16.00 ONE LANE | | | Various | 12.00 | 16 | | | 192 |
| | | | | WO20-1 48x48 ROAD/BRIDGE/R | 16.00 AMP WORK AHEAD | | | Various | 12.00 | 16 | | | 192 |
| | | | | WO20-7 48x48 (SYMBOL) WITH I | 16.00 FLAGGER FLAGS | | | Various | 12.00 | 16 | | | 192 |
| | | May 15, 2021 | 108 | WO20-1 48x48 ROAD/BRIDGE/R | 16.00 AMP WORK AHEAD | | | 37.632 -91.539 | 1.00 | 16 | | | 16 |
| | | | | | AMP WORK AHEAD | | | 37.629 -91.541 | 1.00 | 16 | | | 16 |
| | | | | CONST-8 48x3i ZONE NO PHONE | 6 12.00 WORK E ZONE | | | 37.633 -91.540 | 1.00 | 12 | | | 12 |
| | | | | CONST-8 48x30 ZONE NO PHONE | ZONE | | | 37.591 -91.545 | 1.00 | 12 | | | 12 |
| | | | | GO20-1 60x24 NEXT XX MILES | 10.00 ROAD WORK | | | 37.634 -91.540 | 1.00 | 10 | | | 10 |
| | | | | GO20-1 60x24 NEXT XX MILES | 10.00 ROAD WORK | | | 37.589 -91.545 | 1.00 | 10 | | | 10 |
| | | | | CONST-7-48 48x2 WORK ZONE | 24 8.00 RATE OUR | | | 37.588 -91.545 | 1.00 | 8 | | | 8 |
| | | | | WORK | 8.00 END ROAD | | | 37.636 -91.540 | 1.00 | 8 | | | 8 |
| | | | | WORK | 8.00 END ROAD | | | 37.595 -91.545 | 1.00 | 8 | | | 8 |
| | | | | CONST-7-48 48x2 WORK ZONE | 24 8.00 RATE OUR | | | 37.636 -91.540 | 1.00 | 8 | | | 8 |
| | 0150 - Total | | | | | | | | | | | | 952 |
| J5S3277 | 0570 | June 3, 2021 | 590 | BY QUANTITY OF | | | | various location on project | | 1 | Pilot car in use & follow 18x12 | 1.50 | 7.5 |
| | | | | WO3-4(48) 48x44 PREPARED TO S | TOP | | | various location on project | | 16 | | | 112 |
| | | | | ROAD AHEAD | 16.00 ONE LANE | | | various location on project | | 16 | | | 96 |
| | | | | FOR PILOT CAR | 8.75 PLEASE WAIT | | | various location on project | | 8.75 | | | 17.5 |
| | | | | (SYMBOL) | 16.00 FLAGGER | | | various location on project | | 16 | | | 176 |
| | | | | | AMP WORK AHEAD | | | various location on project | | 16 | | | 176 |
| | | | | GO20-4 36x18 FOLLOW ME | 4.50 PILOT CAR | | | various location on project | 1.00 | 4.5 | | | 4.5 |
| 150 | 0570 - Total | | 70 | 001107 - :: | | | 40.0 | | 4.00 | 40 | | | 589.5 |
| J5S3393 | 0780 | June 1, 2021 | 76 | CONST-8 48x30 ZONE NO PHONE | ZONE | | 13.022 | | 1.00 | 12 | | | 12 |
| | | | | NEXT XX MILES | 10.00 ROAD WORK | | 13.04 | | 1.00 | 10 | | | 10 |
| | | | | WORK | 8.00 END ROAD | | 13.040 | | 1.00 | 8 | | | 8 |
| | | | | WORK ZONE | 24 8.00 RATE OUR | | 0.026 | | 1.00 | 8 | | | 8 |
| | | | | WORK | 8.00 END ROAD | | 0.007 | | 1.00 | 8 | | | 8 |
| | | | | CONST-8 48x30 ZONE NO PHONE | ZONE | | .297 | | 1.00 | 12 | | | 12 |
| | | | | WORK ZONE | 24 8.00 RATE OUR | | 13.042 | | 1.00 | 8 | | | 8 |
| | | | | GO20-1 60x24 | 10.00 ROAD WORK | | .142 | | 1.00 | 10 | | | 10 |

Revision 4/1/2020 Page 8 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| | Line Number | | Total Quantity Posted For DWR Date | | Station | Log Mile | Location | Number of Items | SF Each Sign | Special Sign | SF Each Special Sign | Total SF to Post |
|---------|--------------|--------------|------------------------------------|---------------|---------|----------|----------|-----------------|--------------|--------------|----------------------|------------------|
| J5S3393 | 0780 | June 1, 2021 | 76 | NEXT XX MILES | | | | | | | | |
| | 0780 - Total | | | | | | | | | | | 76 |

Revision 4/1/2020 Page 9 of 25



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|-------------|---|--------------------|-----------------------------|----------------------------|--|------------------------------------|--|--|
| J5P3236 | 0030 | CLASS 4 EXCAVATION | Overrun | Overrun | 9 | Aug 16, 2021 | SYSTEM | (\$36.30) | |
| | | | | | 14 | Feb 2, 2022 | SYSTEM | \$36.30 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',60.50000 - 60.50000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - To | tal | | | | \$0.00 | |
| | 0030 - | - Total | | | | | | \$0.00 | |
| | 0050 | FURNISHING ROCK FILL | Material | | 3 | May 16, 2021 | SYSTEM | \$415.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcwhom1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 3 | May 16, 2021 | SYSTEM | (\$415.26) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Overrun | Overrun | 9 | Aug 16, 2021 | SYSTEM | (\$415.26) | |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | \$415.26 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',26.50000 - 26.50000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - To | tal | | | | \$0.00 | |
| | 0050 - | - Total | | | | | | \$0.00 | |
| | 0060 | PLACING ROCK | Overrun | Overrun | 9 | Aug 16, | SYSTEM | (\$564.12) | |
| | | FILL | | | 13 | 2021 Dec 2, 2021 | SYSTEM | \$564.12 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',36.00000 - 36.00000, 'is |
| | | | | | | | | | applied (if non-zero). |
| | | - Total | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - To | tal | | | | \$0.00 | |
| | | | | | | | 0)10==11 | \$0.00 | |
| | 0800 | | Material | | 9 | Aug 16, 2021 | SYSTEM | \$2,601.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | , | | | 9 | Aug 16, | SYSTEM | | |
| | | | | | J | 2021 | | (\$2,601.00) | |
| | | | | | 10 | 2021 Sep 2, 2021 | SYSTEM | \$2,601.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | | Sep 2, 2021 | SYSTEM | , , , | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment |
| | | | | | 10 | Sep 2, 2021 | | \$2,601.00 | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment |
| | | | | | 10 | Sep 2, 2021 Sep 2, 2021 Sep 15, | SYSTEM | \$2,601.00 (\$2,601.00) | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment |
| | | | | | 10 10 11 | Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 | SYSTEM SYSTEM | \$2,601.00 (\$2,601.00) \$2,601.00 | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment |
| | | | | | 10 10 11 | Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Oct 1, | SYSTEM SYSTEM SYSTEM | \$2,601.00 (\$2,601.00) \$2,601.00 | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment |
| | | | | | 10 10 11 11 11 | Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 | SYSTEM SYSTEM SYSTEM SYSTEM | \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment |
| | | | | | 10 10 11 11 12 | Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Oct 1, 2021 Dec 2, | SYSTEM SYSTEM SYSTEM SYSTEM | \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment |
| | | | | - Total | 10 10 11 11 12 12 13 | Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment |
| | | | Material - To | | 10 10 11 11 12 12 13 | Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment |
| | 0080 | - Total | Material - To | | 10 10 11 11 12 12 13 | Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment |
| | 0080 - 0090 | -Total GRAVEL (A) OR CRUSHED STONE (B) | Material - To | | 10 10 11 11 12 12 13 | Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment |



| Page | Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---|---------|------|---------------------|--------------------|-----------------------------|----------------|--|----------------------|--|--|
| 9 | J5P3236 | 0090 | CRUSHED STONE | Material | | 8 | | SYSTEM | \$4,400.00 | Estimate Item Adjustment (0007) due to user linkd1 overridding Payment |
| 2021 Sey 3 | | | | | | 8 | | SYSTEM | (\$4,400.00) | |
| 1 | | | | | | 9 | | SYSTEM | \$4,400.00 | Estimate Item Adjustment (0006) due to user linkd1 overridding Payment |
| 2021 SYSTEM (\$17,035.00) This adjustment offsets the original system-generated Material Payment Estimate. Secretary Payment Estimate Secretary Paymen | | | | | | 9 | | SYSTEM | (\$4,400.00) | |
| 11 Sep 15 SYSTEM Syste | | | | | | 10 | | SYSTEM | \$17,935.00 | Estimate Item Adjustment (0003) due to user linkd1 overridding Payment |
| 1 | | | | | | 10 | | SYSTEM | (\$17,935.00) | |
| 12 | | | | | | 11 | | SYSTEM | \$17,935.00 | Estimate Item Adjustment (0003) due to user linkd1 overridding Payment |
| 2021 | | | | | | 11 | | SYSTEM | (\$17,935.00) | |
| 13 | | | | | | 12 | | SYSTEM | \$22,735.00 | Estimate Item Adjustment (0003) due to user linkd1 overridding Payment |
| 2021 Estimate Item Aglustment (0009) due to user linked overridding Payment Estimate. 13 Dec 2, SYSTEM S20,735,000 | | | | | | 12 | | SYSTEM | (\$22,735.00) | |
| 2021 | | | | | | 13 | | SYSTEM | \$22,735.00 | Estimate Item Adjustment (0009) due to user linkd1 overridding Payment |
| Material - Total S0.00 | | | | | | 13 | | SYSTEM | (\$22,735.00) | |
| Name | | | | | - Total | | | | \$0.00 | |
| BITUMINOUS PAVEMENT | | | | Material - To | tal | | | | \$0.00 | |
| PAKEMENT MIXTURE PG64-22 (BAS | | | | | | | | | | |
| 7 Jul 16. 2021 8 SYSTEM \$905,146.68 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 7 Jul 16. 2021 8 Aug 2, 2021 8 Aug 2, 2021 9 Aug 16, 2021 9 Aug 16, 2021 10 Sep 2, 2021 10 Sep 2, 2021 10 Sep 2, 2021 11 Sep 15, SYSTEM \$619,551.18 10 Sep 15, SYSTEM \$619,551.18 11 Sep 15, SYSTEM \$619,551.18 12 Oct 1, SYSTEM \$619,551.18 12 Oct 1, SYSTEM \$619,551.18 13 SYSTEM \$619,551.18 14 Sep 15, SYSTEM \$619,551.18 15 SYSTEM \$619,551.18 16 Sep 15, SYSTEM \$619,551.18 17 SySTEM \$619,551.18 18 SySTEM \$619,551.18 19 SySTEM \$619,551.18 10 Sep 2, SYSTEM \$619,551.18 11 Sep 15, SYSTEM \$619,551.18 12 Oct 1, SYSTEM \$619,551.18 13 SySTEM \$619,551.18 14 Sep 15, SYSTEM \$619,551.18 15 SySTEM \$619,551.18 16 Sep 15, SYSTEM \$619,551.18 17 SySTEM \$619,551.18 18 Sep 15, SYSTEM \$619,551.18 19 SySTEM \$619,551.18 10 Sep 2, This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Exception 4 on the current Payment Estimate Estimate Estimate Estimate Estimate Estimate Estimat | | 0100 | PAVEMENT MIXTURE | Material | | | 2021 | | | Estimate Item Adjustment (0002) due to user linkd1 overridding Payment |
| Sep 2, SySTEM Sep 3, Sep 2, SySTEM Sep 3, Sep 4, Sep 3, Sep 4, Sep | | | , | | | 6 | | SYSTEM | (\$853,042.48) | |
| 8 Aug 2, 2021 8 Aug 2, 2021 8 Aug 2, 2021 8 Aug 2, 2021 9 Aug 16, 2021 9 Aug 16, 2021 10 Sep 2, 2021 10 Sep 2, 2021 11 Sep 15, 2021 11 Sep 15, 2021 2021 2021 2021 2021 2021 2021 2021 | | | | | | 7 | | SYSTEM | \$905,146.68 | Estimate Item Adjustment (0004) due to user linkd1 overridding Payment |
| Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 8 Aug 2, SYSTEM (\$905,146.68) 9 Aug 16, SYSTEM \$633,651.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 9 Aug 16, SYSTEM (\$633,651.18) 2021 10 Sep 2, SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 10 Sep 2, SYSTEM (\$619,551.18) 11 Sep 15, SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 11 Sep 15, SYSTEM (\$619,551.18) 12 Oct 1, SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 12 Oct 1, SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | 7 | | SYSTEM | (\$905,146.68) | |
| 9 Aug 16, 2021 9 Aug 16, 2021 10 Sep 2, 2021 10 Sep 2, 2021 11 Sep 15, 2021 11 Sep 15, 2021 12 Oct 1, SYSTEM (\$619,551.18) 2021 2021 2021 2021 2021 3 YSTEM (\$619,551.18) 2021 2021 3 YSTEM (\$619,551.18) 3 YSTEM (\$619,551.18) 2021 4 Sep 15, 2021 5 YSTEM (\$619,551.18) 2021 5 YSTEM (\$619,551.18) 2021 2021 2021 3 YSTEM (\$619,551.18) 2021 4 Sep 15, 2021 5 YSTEM (\$619,551.18) 2021 2021 2021 2021 2021 3 YSTEM (\$619,551.18) 2021 2021 2021 2021 2021 3 YSTEM (\$619,551.18) 2021 2 | | | | | | 8 | | SYSTEM | \$905,146.68 | Estimate Item Adjustment (0008) due to user linkd1 overridding Payment |
| Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 9 Aug 16, 2021 10 Sep 2, 2021 10 Sep 2, SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 10 Sep 2, SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 11 Sep 15, SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 12 Oct 1, SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | 8 | | SYSTEM | (\$905,146.68) | |
| 2021 10 Sep 2, 2021 10 Sep 2, 2021 10 Sep 2, 2021 10 Sep 2, 2021 11 Sep 15, 2021 12 Oct 1, 2021 | | | | | | 9 | | SYSTEM | \$633,651.18 | Estimate Item Adjustment (0007) due to user linkd1 overridding Payment |
| Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 10 Sep 2, 2021 11 Sep 15, 2021 SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 11 Sep 15, 2021 SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 12 Oct 1, 2021 SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | 9 | | SYSTEM | (\$633,651.18) | |
| 2021 System \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. System \$619,551.18 | | | | | | | 2021 | | | |
| 2021 Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 11 Sep 15, 2021 (\$619,551.18) 12 Oct 1, 2021 SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | 10 | Sep 2, | SYSTEM | \$619,551.18 | Estimate Item Adjustment (0004) due to user linkd1 overridding Payment |
| 2021 12 Oct 1, 2021 SYSTEM \$619,551.18 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 12 Oct 1, SYSTEM (\$619,551.18) | | | | | | | Sep 2, 2021 | | | Estimate Item Adjustment (0004) due to user linkd1 overridding Payment |
| 2021 Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 12 Oct 1, SYSTEM (\$619,551.18) | | | | | | 10 | Sep 2, 2021 Sep 2, 2021 Sep 15, | SYSTEM | (\$619,551.18) | Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment |
| | | | | | | 10 | Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 | SYSTEM | (\$619,551.18) \$619,551.18 | Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment |
| LVL I | | | | | | 10 11 11 | Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, | SYSTEM SYSTEM SYSTEM | (\$619,551.18) \$619,551.18 (\$619,551.18) | Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment |



| Project | Line | Description | Adjustment | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks | | |
|---------|--------|--|--------------------------|---------------------|----------------|-----------------|---------------|---|---|--------|----------------|
| | | | Туре | Type | | | · | | | | |
| J5P3236 | 0100 | BITUMINOUS PAVEMENT MIXTURE | Material | | 13 | Dec 2, 2021 | SYSTEM | \$619,551.18 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | |
| | | PG64-22 (BAS | | | 13 | Dec 2, 2021 | SYSTEM | (\$619,551.18) | | | |
| | | | | | 14 | Feb 2, 2022 | SYSTEM | \$619,574.68 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | |
| | | | | | 14 | Feb 2, 2022 | SYSTEM | (\$619,574.68) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | tal | | | | \$0.00 | | | |
| | | | Other Item Adjustment | ACAD | 5 | Jun 16, 2021 | linkd1 | \$19,266.67 | 7533.4 tons | | |
| | | | | | 6 | Jul 1, 2021 | linkd1 | \$27,151.44 | 10,616.4 tons + \$27,151.44 | | |
| | | | | | 7 | Jul 16, 2021 | linkd1 | \$3,063.89 | 1108.6 tons , 3.3% VAC , +\$3063.89 | | |
| | | | | | 9 | Aug 16, 2021 | linkd1 | \$728.33 | Line 100 223.5 tons + \$728.33 | | |
| | | | | ACAD - Tota | al | | | \$50,210.33 | | | |
| | | | Other Item A | .djustment - T | | | | \$50,210.33 | | | |
| | 0100 - | Total | | | | | | \$50,210.33 | | | |
| | 0110 | D110 BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR | Material | | 7 | Jul 16, 2021 | SYSTEM | \$611,025.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | (\$611,025.60) | | | |
| | | | | | | | | 8 | Aug 2, 2021 | SYSTEM | \$1,032,096.00 |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$1,032,096.00) | | | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$416,467.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$416,467.20) | | | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | \$416,467.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$416,467.20) | | | |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | \$416,467.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | (\$416,467.20) | | | |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | \$416,467.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | (\$416,467.20) | | | |
| | | | 14 | 14 | Feb 2, 2022 | SYSTEM | \$416,467.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | |
| | | | | | 14 | Feb 2, 2022 | SYSTEM | (\$416,467.20) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | tal | | | | \$0.00 | | | |
| | | | Other Item Adjustment | ACAD | 7 | Jul 16, 2021 | linkd1 | \$42,644.50 | 12729.70 tons, 4.00% VAC, +\$42,644.50 | | |
| | | | | ent | 8 | Aug 2, 2021 | linkd1 | \$29,387.21 | Line 110 8772.3 Tons +\$29,387.21 | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-----------------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J5P3236 | 0110 | BITUMINOUS PAVEMENT MIXTURE | Other Item Adjustment | ACAD | 9 | Aug 16, 2021 | linkd1 | \$886.38 | Line 110 224.4 tons + \$886.38 |
| | | PG64-22 (SUR | | ACAD - Tota | al | | | \$72,918.09 | |
| | | | Other Item A | djustment - T | otal | | | \$72,918.09 | |
| | 0110 - | Total | | | | | | \$72,918.09 | |
| | 0120 | TACK COAT | Material | | 5 | Jun 16, 2021 | SYSTEM | \$1,763.37 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$1,763.37) | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$3,600.45 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$3,600.45) | |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | \$22,880.34 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | (\$22,880.34) | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$34,808.13 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$34,808.13) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$35,084.07 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$35,084.07) | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$35,084.07 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$35,084.07) | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | \$35,084.07 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$35,084.07) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0120 - | Total | | | | | | \$0.00 | |
| | 0130 | ROCK LINING | Material | | 6 | Jul 1, 2021 | SYSTEM | \$1,918.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$1,918.00) | |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | \$1,918.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | (\$1,918.00) | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$1,918.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$1,918.00) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$4,130.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$4,130.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J5P3236 | 0130 - | Total | | | | | | \$0.00 | |
| | 0160 | ADVANCED WARNING RAIL SYSTEM | Material | | 2 | May 3, 2021 | SYSTEM | \$200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 2 | May 3, 2021 | SYSTEM | (\$200.00) | |
| | | | | | 3 | May 16, 2021 | SYSTEM | \$200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcwhom1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 3 | May 16, 2021 | SYSTEM | (\$200.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0160 - | Total | | | | | | \$0.00 | |
| | 0170 | FLAG ASSEMBLY | Material | | 2 | May 3, 2021 | SYSTEM | \$720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 2 | May 3, 2021 | SYSTEM | (\$720.00) | |
| | | | | | 3 | May 16, 2021 | SYSTEM | \$720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcwhom1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 3 | May 16, 2021 | SYSTEM | (\$720.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0170 - | Total | | | | | | \$0.00 | |
| | 0180 | | Material | | 2 | May 3, 2021 | SYSTEM | \$3,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 2 | May 3, 2021 | SYSTEM | (\$3,000.00) | |
| | | | | | 3 | May 16, 2021 | SYSTEM | \$3,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 3 | May 16, 2021 | SYSTEM | (\$3,000.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0180 - | Total | | | | | | \$0.00 | |
| | 0190 | TYPE III MOVEABLE BARRICADE WITH | Overrun | Overrun | 8 | Aug 2, 2021 | SYSTEM | (\$500.00) | |
| | | LIGHTS | | | 14 | Feb 2, 2022 | SYSTEM | \$500.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',250.00000 - 250.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - To | tal | | | | \$0.00 | |
| | 0190 - | Total | | | | | | \$0.00 | |
| | 0210 | CMS W/O COMMUNICATION INTERFACE, | Material | | 2 | May 3, 2021 | SYSTEM | \$10,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | CONT F/ | | | 2 | May 3, 2021 | SYSTEM | (\$10,000.00) | |
| | | | | | 3 | May 16, 2021 | SYSTEM | \$10,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcwhom1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 3 | May 16, 2021 | SYSTEM | (\$10,000.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Overrun | Overrun | 8 | Aug 2, 2021 | SYSTEM | (\$7,500.00) | |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | \$7,500.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2500.00000 - 2500.00000, |
| | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks | |
|---------|--------|---|--------------------------|---------------------|----------------|-----------------|---------------|-----------------|--|---------------|
| J5P3236 | 0210 | CMS W/O | Overrun | Type Overrun | | | | | 'is applied (if non-zero). | |
| J3F3230 | 0210 | COMMUNICATION INTERFACE, | Overruit | Overrun - To | otal | | | \$0.00 | is applied (ii flori-zero). | |
| | | CONT F/ | Overrun - To | | | | | \$0.00 | | |
| | 0210 - | Total | | | | | | \$0.00 | | |
| | 0260 | 4 IN. WHITE WATERBORNE PAVEMENT | Material | | 10 | Sep 2, 2021 | SYSTEM | \$2,271.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | |
| | | MARKING | | | 10 | Sep 2, 2021 | SYSTEM | (\$2,271.60) | | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | \$23,362.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$23,362.65) | | |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | \$23,362.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | (\$23,362.65) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | tal | | | | \$0.00 | | |
| | | | Other Item Adjustment | REFL | 12 | Oct 1, 2021 | linkd1 | \$1,168.13 | See Adjustment Sheet | |
| | | | | REFL - Tota | ı | | | \$1,168.13 | | |
| | | | Other Item A | djustment - T | otal | | | \$1,168.13 | | |
| | 0260 - | Total | | | | | | \$1,168.13 | | |
| | 0270 | 4 IN. YELLOW WATERBORNE PAVEMENT MARKING | Material | | 10 | Sep 2, 2021 | SYSTEM | \$21,777.23 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | |
| | | MARKING | | | 10 | Sep 2, 2021 | SYSTEM | (\$21,777.23) | | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | \$21,777.23 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | |
| | | | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$21,777.23) |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | \$21,777.23 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | (\$21,777.23) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | tal | | | | \$0.00 | | |
| | | | Other Item Adjustment | REFL | 12 | Oct 1, 2021 | linkd1 | \$1,120.95 | See Adjustment Worksheet | |
| | | | | REFL - Tota | | | | \$1,120.95 | | |
| | | | Other Item A | djustment - T | otal | | | \$1,120.95 | | |
| | 0270 - | | | | | | | \$1,120.95 | | |
| | 0330 | CLASS B-1 CONCRETE (CULVERTS) | Material | | 2 | May 3, 2021 | SYSTEM | \$34,320.75 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | |
| | | | | | 2 | May 3, 2021 | SYSTEM | (\$34,320.75) | | |
| | | | | | 3 | May 16, 2021 | SYSTEM | \$82,216.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcwhom1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | |
| | | | | | 3 | May 16, 2021 | SYSTEM | (\$82,216.12) | | |
| | | | | | 4 | Jun 2, 2021 | SYSTEM | \$82,216.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcwhom1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | |
| | | | | | 4 | Jun 2, 2021 | SYSTEM | (\$82,216.12) | | |
| | | | | | 5 | Jun 16, | SYSTEM | \$82,216.12 | This adjustment offsets the original system-generated Material Payment | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-----------------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|------------------|--|
| J5P3236 | 0330 | CLASS B-1 CONCRETE | Material | | | 2021 | | | Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | (CULVERTS) | | | 5 | Jun 16, 2021 | SYSTEM | (\$82,216.12) | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$82,216.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$82,216.12) | |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | \$82,216.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | (\$82,216.12) | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$82,216.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$82,216.12) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | | | | | \$0.00 | |
| | | | Other Item Adjustment | SUBI | 3 | May 17, 2021 | mcwhom1 | (\$550.00) | Aplex poured the floor in box 0.765 on Rte. HH with Non chlorinated accelerant. I talked to Eric Abbott and we decided that the box Floor would be fine to leave in place but a deduct would need to be taken. A total of 5.25 yards were poured in the floor so Eric decided that a deduct of \$550.00 would be appropriate |
| | | | | SUBI - Tota | | | | (\$550.00) | |
| | | _ | Other Item A | djustment - T | otal | | | (\$550.00) | |
| | 0330 - | | Material | | 40 | Day 0 | OVOTEN | (\$550.00) | This adjustment offsets the critical content or content Material Research |
| | 0360 | 24 IN. PIPE CULVERT GROUP C | Material | | 13 | Dec 2, 2021 | SYSTEM | \$7,011.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | (\$7,011.00) | |
| | | | Material - To | - Total | | | | \$0.00 \$0.00 | |
| | 0360 - | Total | Waterial - 10 | lai | | | | \$0.00 | |
| | 0370 | 30 IN. PIPE CULVERT GROUP C | Material | | 13 | Dec 2, 2021 | SYSTEM | \$1,656.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | (\$1,656.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0370 - | Total | | | | | | \$0.00 | |
| | 0380 | 36 IN. PIPE CULVERT GROUP C | Material | | 13 | Dec 2, 2021 | SYSTEM | \$1,720.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | (\$1,720.00) | |
| | | | Material - To | - Total | | | | \$0.00 \$0.00 | |
| | 0380 - | Total | Material - 10 | tal | | | | \$0.00 | |
| | 0390 | | Material | | 13 | Dec 2, 2021 | SYSTEM | \$1,784.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | (\$1,784.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0390 - | Total | | | | | | \$0.00 | |
| | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | | | | | | |
|---------|--------|--------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|--------------|-----------------|----------------|--------------|--|--|--------|--------------|--|--|--|--|--|--|--|---|-----------------|
| J5P3236 | 0460 | SEEDING - COOL SEASON | Material | | 12 | Oct 1, 2021 | SYSTEM | (\$17.50) | | | | | | | | | | | | | | | | | | |
| | | MIXTURES | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| | 0460 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| | 0480 | ROCK DITCH CHECK | Material | | 7 | Jul 16, 2021 | SYSTEM | \$4,527.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | (\$4,527.60) | | | | | | | | | | | | | | | | | | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$4,527.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$4,527.60) | | | | | | | | | | | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$4,527.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$4,527.60) | | | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| | 0480 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| | 0490 | ALTERNATE DITCH CHECK | Material | | 2 | May 3, 2021 | SYSTEM | \$1,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | | | | 2 | May 3, 2021 | SYSTEM | (\$1,687.50) | | | | | | | | | | | | | | | | |
| | | | | | | | | | | 3 | May 16, 2021 | SYSTEM | \$1,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcwhom1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | | | | | | | | | | 3 | May 16, 2021 | SYSTEM | (\$1,687.50) | | | | | | | | | |
| | | | | | 4 | Jun 2, 2021 | SYSTEM | \$1,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcwhom1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | | 4 | Jun 2, 2021 | SYSTEM | (\$1,687.50) | | | | | | | | | | | | | | | | | | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$1,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$1,687.50) | | | | | | | | | | | | | | | | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$1,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | | | | | | 7 | 6 | Jul 1, 2021 | SYSTEM | (\$1,687.50) | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | 7 | Jul 16, 2021 |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | (\$1,687.50) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | 8 | Aug 2, 2021 | SYSTEM | \$1,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$1,687.50) | | | | | | | | | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$1,687.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$1,687.50) | | | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| | 0490 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks |
|------------------------|-------------------|--|--------------------------|---------------------|----------------------------|---|--|--|--|
| IED | 05:5 | TEL 175 | | Type | | | , | | |
| J5P3236 | 0510 | TEMPORARY SEEDING AND MULCHING | Material | | 7 | Jul 16, 2021 | SYSTEM | \$3.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | (\$3.50) | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$3.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate. |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$3.50) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$3.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$3.50) | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$3.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate. |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$3.50) | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | \$3.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate. |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$3.50) | |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | \$3.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | (\$3.50) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0510 - | - Total | | | | | | \$0.00 | |
| | | | | | | | | | |
| | 5002 | MISC. CONCRETE CONSTRUCTION | Other Item Adjustment | MATL | 14 | Feb 2, 2022 | linkd1 | \$4,489.12 | Material Takeover for steel delivered to job that was not used on the other box culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. |
| | 5002 | | | MATL - Tota | | | linkd1 | \$4,489.12 \$4,489.12 | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was |
| | | CONSTRUCTION | Adjustment | | al | | linkd1 | \$4,489.12 \$4,489.12 | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was |
| 1503236 | 5002 - | | Adjustment | MATL - Tot | al | | linkd1 | \$4,489.12 \$4,489.12 \$4,489.12 | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was |
| J5P3236 J5S3277 | 5002 - | - Total BITUMINOUS PAVEMENT | Adjustment | MATL - Tot | al | | linkd1 | \$4,489.12 \$4,489.12 | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment |
| | 5002 - - Total | CONSTRUCTION Total BITUMINOUS | Adjustment Other Item A | MATL - Tot | al Fotal | Jun 16, 2021 Jun 16, | | \$4,489.12 \$4,489.12 \$4,489.12 \$129,356.62 | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. This adjustment offsets the original system-generated Material Payment |
| | 5002 - - Total | CONSTRUCTION Total BITUMINOUS PAVEMENT MIXTURE | Adjustment Other Item A | MATL - Tot | al Fotal | Jun 16, 2021 | SYSTEM | \$4,489.12 \$4,489.12 \$4,489.12 \$129,356.62 \$197,634.40 | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment |
| | 5002 - - Total | CONSTRUCTION Total BITUMINOUS PAVEMENT MIXTURE | Adjustment Other Item A | MATL - Tot | fotal 5 | Jun 16, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, | SYSTEM | \$4,489.12 \$4,489.12 \$4,489.12 \$129,356.62 \$197,634.40 | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment |
| | 5002 - - Total | CONSTRUCTION Total BITUMINOUS PAVEMENT MIXTURE | Adjustment Other Item A | MATL - Tot | 5 5 6 | Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, | SYSTEM SYSTEM SYSTEM | \$4,489.12 \$4,489.12 \$4,489.12 \$129,356.62 \$197,634.40 (\$197,634.40) | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment |
| | 5002 - - Total | CONSTRUCTION Total BITUMINOUS PAVEMENT MIXTURE | Adjustment Other Item A | MATL - Tot | 5 5 6 | Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 1, | SYSTEM SYSTEM SYSTEM SYSTEM | \$4,489.12 \$4,489.12 \$4,489.12 \$129,356.62 \$197,634.40 (\$197,634.40) | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |
| | 5002 - - Total | CONSTRUCTION Total BITUMINOUS PAVEMENT MIXTURE | Adjustment Other Item A | MATL - Tot | 5 5 6 7 | Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$4,489.12 \$4,489.12 \$129,356.62 \$197,634.40 (\$197,634.40) (\$197,634.40) (\$197,634.40) | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |
| | 5002 - - Total | CONSTRUCTION Total BITUMINOUS PAVEMENT MIXTURE | Adjustment Other Item A | MATL - Tot | 5 5 6 7 7 | Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$4,489.12 \$4,489.12 \$129,356.62 \$197,634.40 (\$197,634.40) \$197,634.40 (\$197,634.40) | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | 5002 - - Total | CONSTRUCTION Total BITUMINOUS PAVEMENT MIXTURE | Adjustment Other Item A | MATL - Tot | 5 5 6 7 7 | Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$4,489.12 \$4,489.12 \$4,489.12 \$129,356.62 \$197,634.40 (\$197,634.40) \$197,634.40 (\$197,634.40) (\$197,634.40) \$197,634.40 | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | 5002 - - Total | CONSTRUCTION Total BITUMINOUS PAVEMENT MIXTURE | Adjustment Other Item A | MATL - Tot | 5 5 6 7 7 8 | Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$4,489.12 \$4,489.12 \$4,489.12 \$129,356.62 \$197,634.40 (\$197,634.40) \$197,634.40 (\$197,634.40) \$197,634.40 (\$197,634.40) | culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J5S3277 | 0540 | BITUMINOUS PAVEMENT | Material | | | 2021 | | | Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | MIXTURE PG64-22 (SUR | | | 10 | Sep 2, 2021 | SYSTEM | (\$13,634.40) | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | \$13,634.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$13,634.40) | |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | \$13,634.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | (\$13,634.40) | |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | \$13,634.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | (\$13,634.40) | |
| | | | | | 14 | Feb 2, 2022 | SYSTEM | \$13,634.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 14 | Feb 2, 2022 | SYSTEM | (\$13,634.40) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Other Item Adjustment | ACAD | 5 | Jun 16, 2021 | linkd1 | \$13,318.84 | 4296.4 tons |
| | | | | ACAD - Tota | al | | | \$13,318.84 | |
| | | | Other Item A | djustment - T | otal | | | \$13,318.84 | |
| | 0540 - | Total | | | | | | \$13,318.84 | |
| | 0550 | TACK COAT | Material | | 5 | Jun 16, 2021 | SYSTEM | \$9,807.21 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$9,807.21) | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$9,807.21 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$9,807.21) | |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | \$9,807.21 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | (\$9,807.21) | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$9,807.21 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$9,807.21) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$9,807.21 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$9,807.21) | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$9,807.21 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$9,807.21) | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | \$9,807.21 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$9,807.21) | |
| | | | | - Total | | | | \$0.00 | |
| | | | | - I Ottal | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | | | |
|---------|--------|--|--------------------------|-----------------------------|-----------------|-----------------|-----------------|----------------|--|---|--|--|--|--|--|--|--|----|----|----------------|--------|--------------|--|
| J5S3277 | 0550 | TACK COAT | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0550 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0570 | CONSTRUCTION SIGNS | Overrun | Overrun | 8 | Aug 2, 2021 | SYSTEM | (\$1,531.06) | | | | | | | | | | | | | | | |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | \$1,531.06 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4.25000 - 4.25000, 'is applied (if non-zero). | | | | | | | | | | | | | | |
| | | | | Overrun - T | otal | | | \$0.00 | | | | | | | | | | | | | | | |
| | | | Overrun - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0570 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0590 | CHANNELIZER (TRIM LINE) | Overrun | Overrun | 8 | Aug 2, 2021 | SYSTEM | (\$300.00) | | | | | | | | | | | | | | | |
| | | | | | 14 | Feb 2, 2022 | SYSTEM | \$300.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero). | | | | | | | | | | | | | | |
| | 0500 | | | Overrun - T | Overrun - Total | | | \$0.00 | | | | | | | | | | | | | | | |
| | | | Overrun - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0590 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | |
| | 0630 | 4 IN. WHITE WATERBORNE PAVEMENT MARKING | Material | | 5 | Jun 16, 2021 | SYSTEM | \$5,805.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | WARKING | | | 5 | Jun 16, 2021 | SYSTEM | (\$5,805.50) | | | | | | | | | | | | | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$5,805.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$5,805.50) | | | | | | | | | | | | | | | |
| | | | | | | 7 | Jul 16, 2021 | SYSTEM | \$5,805.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | | | |
| | | | | | | 7 | Jul 16, 2021 | SYSTEM | (\$5,805.50) | | | | | | | | | | | | | | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$5,805.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$5,805.50) | | | | | | | | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$5,805.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$5,805.50) | | | | | | | | | | | | | | | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$5,805.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate. | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | 10 | 10 | Sep 2, 2021 | SYSTEM | (\$5,805.50) | |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$5,805.50) | | | | | | | | | | | | | | |
| | | | | | | | 12 | Oct 1, 2021 | SYSTEM | \$7,256.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | (\$7,256.80) | | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | |
| | | | Other Item Adjustment | REFL | 12 | Oct 1, 2021 | linkd1 | \$349.71 | See Adjustment Worksheet | | | | | | | | | | | | | | |
| | | | | REFL - Tota | ıl | | | \$349.71 | | | | | | | | | | | | | | | |
| | | | Other Item A | djustment - T | otal | | | \$349.71 | | | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| J5S3277 | 0630 - | Total | | | | | | \$349.71 | |
| | 0640 | 4 IN. YELLOW WATERBORNE PAVEMENT | Material | | 5 | Jun 16, 2021 | SYSTEM | \$5,181.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | MARKING | | | 5 | Jun 16, 2021 | SYSTEM | (\$5,181.12) | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$5,181.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$5,181.12) | |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | \$5,181.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | (\$5,181.12) | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$5,181.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$5,181.12) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$5,181.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$5,181.12) | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$5,181.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$5,181.12) | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | \$5,181.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$5,181.12) | |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | \$6,476.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | (\$6,476.40) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Other Item Adjustment | REFL | 12 | Oct 1, 2021 | linkd1 | \$308.40 | See Adjustment Worksheet |
| | | | | REFL - Tota | | | | \$308.40 | |
| | | | Other Item A | djustment - T | otal | | | \$308.40 | |
| | 0640 - | | O# " | CT! | 40 | D î | 15. 1. 14 | \$308.40 | Description and and individual found has the |
| | 0650 | MODIFIED COLDMILLING (DEPTH | Other Item Adjustment | OTHR | | Dec 2, 2021 | linkd1 | \$5,444.40 | Previous entered adjustment fixed by this entry. |
| | | TRANSITIONS) | | OTHR - Tota | | | | \$5,444.40 | |
| | | | Other Item A | | | | 0)/0==:/ | \$5,444.40 | |
| | | | Overrun | Overrun | 4 | Jun 2, 2021 | SYSTEM | \$5,444.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user mcwhom1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 4 | Jun 2, 2021 | mcwhom1 | (\$5,444.40) | This overrun amount is pending change order |
| | | | | | 4 | Jun 2, 2021 | SYSTEM | (\$5,444.40) | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$5,444.40) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$5,444.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$5,444.40) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|---------|---|--------------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|
| J5S3277 | 0650 | MODIFIED COLDMILLING (DEPTH | Overrun | Overrun | 6 | Jul 1, 2021 | SYSTEM | \$5,444.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | TRANSITIONS) | | | 7 | Jul 16, 2021 | SYSTEM | (\$5,444.40) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 7 | Jul 16, 2021 | SYSTEM | \$5,444.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate. |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$5,444.40) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | \$5,444.40 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',12.00000 - 12.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | (\$5,444.40) | |
| | | | Overrun - To | | | | | (\$5,444.40) | |
| | 0650 - | · Total | | | | | | \$0.00 | |
| J5S3277 - | - Total | | | | | | | \$13,976.95 | |
| J5S3393 | 0740 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | 10 | Sep 2, 2021 | SYSTEM | \$4,400.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$4,400.40) | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | \$4,400.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$4,400.40) | |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | \$4,400.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | (\$4,400.40) | |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | \$4,400.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | (\$4,400.40) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0740 - | - Total | | | | | | \$0.00 | |
| | 0750 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR | Material | | 8 | Aug 2, 2021 | SYSTEM | \$531,360.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | . 661 22 (661) | | | 8 | Aug 2, 2021 | SYSTEM | (\$531,360.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Other Item Adjustment | ACAD | 8 | Aug 2, 2021 | linkd1 | \$34,612.20 | Line 750 98401 tons +\$34612.20 |
| | | | | | 9 | Aug 16, 2021 | linkd1 | \$12,229.73 | Line 750 2948.7 tons + \$12,229.73 |
| | | | | ACAD - Tota | al | | | \$46,841.93 | |
| | | | Other Item A | djustment - T | otal | | | \$46,841.93 | |
| | | | Overrun | Overrun | 9 | Aug 16, 2021 | SYSTEM | (\$39,187.80) | |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | \$39,187.80 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',54.00000 - 54.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - To | tal | | | | \$0.00 | |
| | 0750 - | · Total | | | | | | \$46,841.93 | |
| | 0760 | TACK COAT | Material | | 8 | Aug 2, | SYSTEM | \$20,704.00 | This adjustment offsets the original system-generated Material Payment |
| | | | | | | | | | |



| ject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | |
|------|--------------------|--|---|-----------------------------|----------------|--|-----------------------------|--|---|---|--|---------------|--|
| 3393 | 0760 | TACK COAT | Material | | | 2021 | | | Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$20,704.00) | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$25,978.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$25,978.00) | | | | | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$25,978.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$25,978.00) | | | | | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | \$25,978.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$25,978.00) | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | |
| | 0760 - | Total | | | | | | \$0.00 | | | | | |
| | 0840 | 4 IN. WHITE WATERBORNE PAVEMENT MARKING | Material | | 9 | Aug 16, 2021 | SYSTEM | \$13,687.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | |
| | | WARRING | | | 9 | Aug 16, 2021 | SYSTEM | (\$13,687.90) | | | | | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$13,687.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate. | | | | |
| | | | | | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$13,687.90) | |
| | | | | | | | 11 | Sep 15, 2021 | SYSTEM | \$13,687.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate. | | |
| | | | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$13,687.90) | | | |
| | | | | | | 12 | Oct 1, 2021 | SYSTEM | \$13,687.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | |
| | | | | | 12 | Oct 1, | SYSTEM | (\$13,687.90) | | | | | |
| | | | | | | 2021 | | , | | | | | |
| | | | | - Total | | 2021 | | \$0.00 | | | | | |
| | | | Material - To | tal | 10 | | | \$0.00 \$0.00 | | | | | |
| | | | Material - To Other Item Adjustment | tal REFL | | Oct 1, 2021 | linkd1 | \$0.00 \$0.00 \$676.52 | See Adjustment Worksheet | | | | |
| | | | Other Item Adjustment | REFL - Tota | ıl | Oct 1, | linkd1 | \$0.00 \$0.00 \$676.52 | See Adjustment Worksheet | | | | |
| | 0849 | Total | Other Item Adjustment | tal REFL | ıl | Oct 1, | linkd1 | \$0.00 \$0.00 \$676.52 \$676.52 | See Adjustment Worksheet | | | | |
| | 0840 - 0850 | 4 IN. YELLOW WATERBORNE | Other Item Adjustment | REFL - Tota | ıl | Oct 1, | linkd1 | \$0.00 \$0.00 \$676.52 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment | | | | |
| | | 4 IN. YELLOW | Other Item Adjustment Other Item A | REFL - Tota | l otal | Oct 1, 2021 Aug 16, 2021 Aug 16, | | \$0.00 \$0.00 \$676.52 \$676.52 \$676.52 | This adjustment offsets the original system-generated Material Payment | | | | |
| | | 4 IN. YELLOW WATERBORNE PAVEMENT | Other Item Adjustment Other Item A | REFL - Tota | otal | Oct 1, 2021 Aug 16, 2021 | SYSTEM | \$0.00 \$0.00 \$676.52 \$676.52 \$676.52 \$676.52 \$11,408.46 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment | | | | |
| | | 4 IN. YELLOW WATERBORNE PAVEMENT | Other Item Adjustment Other Item A | REFL - Tota | otal 9 | Oct 1, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, | SYSTEM | \$0.00 \$0.00 \$676.52 \$676.52 \$676.52 \$11,408.46 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment | | | | |
| ı | | 4 IN. YELLOW WATERBORNE PAVEMENT | Other Item Adjustment Other Item A | REFL - Tota | 9 9 | Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, | SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$676.52 \$676.52 \$676.52 \$11,408.46 (\$11,408.46) | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment | | | | |
| 1 | | 4 IN. YELLOW WATERBORNE PAVEMENT | Other Item Adjustment Other Item A | REFL - Tota | 9 9 10 | Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 15, | SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$676.52 \$676.52 \$676.52 \$11,408.46 (\$11,408.46) | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment | | | | |



| JASSES 1985 All YELD Market 1 | Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|---|---------|--------|------------------------------|--------------------|-----------------------------|---|---|--|--|--|--|
| Marterial = Total Sp. 20 | J5S3393 | 0850 | WATERBORNE PAVEMENT | Material | | 12 | | SYSTEM | (\$11,408.46) | Estimate Exception 16 on the current Payment Estimate. | |
| Contraction Stockpile Transaction Security Secu | | | WARKING | | - Total | | | | \$0.00 | | |
| September Sept | | | | Material - To | tal | | | | \$0.00 | | |
| Contraction Stockyle Transaction Transa | | | | | | | | linkd1 | | See Adjustment Worksheet | |
| Construction Cons | | | | Other Henry A | | | | | | | |
| MICS BIDGE Construction 9 Aug 16 2021 1013 286.00 Phymerel Estimate Item Adjustment generated Stockpile Transaction 2021 1013 286.00 Phymerel Estimate Item Adjustment generated Stockpile Transaction 2021 2 | | 0850 - | . Total | Other item A | ajustment - 1 | otai | | | | | |
| Construction Stockpile Total Construction Stockpile STM Total Construction Stockpile STM Total Construction Stockpile STM Total Construction Stockpile STM Total S13,256.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STM Total S13,256.00 Payment Estimate Item Adjustment generated Stockpile Transaction FRASHVONTHY END TERM Stockpile STM Total Construction Stockpile STM Total SYSTEM SS0.00000 The adjustment officis the original system-generated Malarial Payment Estimate Exception 1 to n the current Payment Estimate Standard Exception 1 to n the current Payment Estimate Standard Exception 1 to n the current Payment Estimate T | | | MGS BRIDGE APP. TRANS SEC | | | 9 | | SYSTEM | | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| Construction Stockpile 1 Apr 5, 2031 13,255.00 Payment Estimate Item Adjustment generated Stockpile Transaction 13,255.00 13,2 | | | (REG/NO CURB) | | - Total | | | | (\$13,256.00) | | |
| Stockpile | | | | Construction | Stockpile - 1 | Γotal | | | (\$13,256.00) | | |
| Construction Stockpile STMI - Total \$13,255.00 | | | | Stockpile | | 1 | | SYSTEM | \$13,256.00 | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| 1 | | | | | | | | | | | |
| TYPE A CRASH-WORTH Stockpile Total Construction Stockpile Total Construction Stockpile Total (\$12,448.00) Favorent Estimate Item Adjustment generated Stockpile Transaction Stockpile Total Construction Stockpile Total Construction Stockpile Total SYSTEM S12,448.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total SYSTEM S12,448.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total SYSTEM S12,448.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total SYSTEM S12,448.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total SYSTEM S12,448.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total SYSTEM S12,448.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total SYSTEM S12,448.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total SYSTEM S12,448.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total SYSTEM S12,448.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total SYSTEM S12,448.00 Total SYSTEM S12,448.00 Total System-generated Material Payment Estimate Item Adjustment offsets the criginal system-generated Material Payment Estimate Item Adjustment Global Stockpile System Syst | | | | Construction | Stockpile S | ΓΜΙ - Total | | | | | |
| CRASHWORTH No TERMINA NASH Construction Stockpile - Total (\$12,448.00) Construction Stockpile - Total (\$12,448.00) Construction Stockpile - Total (\$12,448.00) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile - Total (\$12,448.00) Stockpile - Total (\$12,448.00) Stockpile - Total (\$12,448.00) Construction Stockpile STMI - Total (\$12,448.00) Stockpile - Total (\$12,448.00) | | | | Construction | | 0 | Aug 16 | CVCTEM | | Doumant Estimate Item Adjustment generated Steelails Transaction | |
| Construction Stockpile - Total Construction 1 | | 0890 | CRASHWORTHY | | | 9 | | SYSTEM | , , | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| Construction Substitute | | | | Construction | | Fotol | | | | | |
| Stockpile STM -Total | | | Construction Stockpile | | i Stockpile - I | | Apr 5 | SVSTEM | | Payment Estimate Item Adjustment generated Stockhille Transaction | |
| | | | | Total | 1 | | STSTEW | | rayment Estimate item Aujustment generated Stockpile Transaction | | |
| Separate Superation Super | | | | Construction | | FMI Total | | | | | |
| 2021 SYSTEM \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mowhom1 overridding Payment | | 0890 - | · Total | Construction | r otockpile o | i wii - Totai | | | | | |
| 2021 Estimate Item Adjustment (0004) due to user mexhom1 overridding Payment | | | | | | | | | | | |
| 5 Jun 16, 2021 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate Payment Estimate Exception 13 on the current Payment Estimate Payment Estimate Exception 13 on the current Payment Estimate Payment Estimate Exception 13 on the current Payment Estimate Payment Estimate Exception 13 on the current Payment Estimate Payment Estimate Exception 13 on the current Payment Estimate Payment Estimate Exception 13 on the current Payment Estimate. 7 Jul 16, 2021 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. 8 Aug 2, 2021 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. 8 Aug 2, 2021 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate Estimate Exception 16 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Estimate Estimate Exception 17 on the current Payment Estimate Estimate Estimate Exception 17 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Estimate Estimate Exception 17 on the current Payment Estimate Exception 18 on the current Pay | | 0900 | 0 CURB BLOCKOUT | CURB BLOCKOUT | Material | | 4 | Jun 2, | SYSTEM | \$93,000.00 | This adjustment offsets the original system-generated Material Payment |
| 2021 Sestimate Exception 9 on the current Payment Estimate. Jul 16, 2021 SySTEM \$93,000.00 1 This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. SySTEM \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. Jul 16, 2021 Jul 16, SySTEM \$93,000.00 Jul 16, SySTEM \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. Jul 16, SySTEM (\$93,000.00) SySTEM \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. Aug 2, SySTEM \$93,000.00 SySTEM \$93,000.00 Aug 16, SySTEM \$93,000.00 Aug 16, SySTEM \$93,000.00 Aug 16, SySTEM \$93,000.00 SySTEM \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate. Aug 2, SySTEM \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate. SySTEM \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate. Sep 2, SySTEM \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate. Sep 2, SySTEM \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate. | | 0900 | CURB BLOCKOUT | Material | | | 2021 | | | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment | |
| 2021 6 Jul 1, 2021 8 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. 6 Jul 1, 2021 7 Jul 16, 2021 8 \$93,000.00 This adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. 7 Jul 16, 2021 8 Aug 2, 2021 8 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. 7 Jul 16, 2021 8 Aug 2, 2021 8 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 17 on the current Payment Estimate Estimate Exception 12 on the current Payment Estimate Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate. | | 0900 | CURB BLOCKOUT | Material | | | 2021 Jun 2, | | | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment | |
| Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. 6 Jul 1, 2021 \$YSTEM (\$93,000.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. 7 Jul 16, 2021 \$YSTEM (\$93,000.00) \$\$ 8 Aug 2, 2021 \$\$ 8 Aug 2, 2021 \$\$ 9 Aug 16, 2021 \$\$ 10 \$\$ 11 \$\$ 11 \$\$ 11 \$\$ 12 \$\$ 11 \$\$ 12 \$\$ 12 \$\$ 13 \$\$ 14 \$\$ 15 \$\$ 15 \$\$ 16 \$\$ 16 \$\$ 17 \$\$ 18 \$\$ 18 \$\$ 19 \$\$ 10 \$\$ 10 \$\$ 10 \$\$ 10 \$\$ 10 \$\$ 10 \$\$ 10 \$\$ 10 \$\$ 10 \$\$ 10 \$\$ 10 \$\$ 11 \$\$ 11 \$\$ 12 \$\$ 11 \$\$ 12 \$\$ 12 \$\$ 12 \$\$ 13 \$\$ 14 \$\$ 15 \$\$ 16 \$\$ 16 \$\$ 17 \$\$ 18 \$\$ 18 \$\$ 19 \$\$ 10 \$\$ 11 \$\$ 12 \$\$ 13 \$\$ 14 \$\$ 15 \$\$ 16 \$\$ 16 \$\$ 17 \$\$ 18 \$\$ 18 \$\$ 19 \$\$ 10 \$\$ | | 0900 | CURB BLOCKOUT | Material | | 4 | Jun 2, 2021 Jun 16, | SYSTEM | (\$93,000.00) | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment | |
| 2021 7 | | 0900 | CURB BLOCKOUT | Material | | 5 | Jun 2, 2021 Jun 16, 2021 Jun 16, | SYSTEM SYSTEM | (\$93,000.00) \$93,000.00 | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment | |
| Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. 7 Jul 16, 2021 | | 0900 | CURB BLOCKOUT | Material | | 5 | Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, | SYSTEM SYSTEM SYSTEM | (\$93,000.00) \$93,000.00 (\$93,000.00) | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment | |
| 8 Aug 2, 2021 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user link11 overridding Payment Estimate Exception 15 on the current Payment Estimate. 8 Aug 2, 2021 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 9 Aug 16, 2021 \$93,000.00 (\$93,000.00) 10 Sep 2, SYSTEM \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate. | | 0900 | CURB BLOCKOUT | Material | | 4 5 5 | 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, | SYSTEM SYSTEM SYSTEM SYSTEM | (\$93,000.00) \$93,000.00 (\$93,000.00) \$93,000.00 | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment | |
| Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 8 | | 0900 | CURB BLOCKOUT | Material | | 45566 | 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 1, | SYSTEM SYSTEM SYSTEM SYSTEM | (\$93,000.00) \$93,000.00 (\$93,000.00) \$93,000.00 | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment | |
| 9 Aug 16, 2021 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 9 Aug 16, 2021 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate. 10 Sep 2, SYSTEM (\$93,000.00) | | 0900 | CURB BLOCKOUT | Material | | 4 5 5 6 6 7 7 | 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$93,000.00) \$93,000.00 (\$93,000.00) \$93,000.00 (\$93,000.00) | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment | |
| Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 9 Aug 16, 2021 10 Sep 2, 2021 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate. | | 0900 | CURB BLOCKOUT | Material | | 4 5 5 6 6 7 7 | 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$93,000.00) \$93,000.00 (\$93,000.00) \$93,000.00 (\$93,000.00) (\$93,000.00) | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. | |
| 2021 10 Sep 2, 2021 \$93,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate. | | 0900 | CURB BLOCKOUT | Material | | 4 5 5 6 6 7 7 8 8 | 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$93,000.00) \$93,000.00 (\$93,000.00) \$93,000.00 (\$93,000.00) (\$93,000.00) \$93,000.00 | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. | |
| 2021 Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate. 10 Sep 2, SYSTEM (\$93,000.00) | | 0900 | CURB BLOCKOUT | Material | | 4 5 5 6 6 7 7 8 8 8 | 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, Aug 16, | SYSTEM | (\$93,000.00) \$93,000.00 (\$93,000.00) \$93,000.00 (\$93,000.00) (\$93,000.00) (\$93,000.00) | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate. | |
| | | 0900 | CURB BLOCKOUT | Material | | 4 5 5 6 6 7 7 8 8 8 9 | 2021 Jun 16, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 | SYSTEM | (\$93,000.00) \$93,000.00 (\$93,000.00) \$93,000.00 (\$93,000.00) (\$93,000.00) (\$93,000.00) \$93,000.00 | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate. | |
| | | 0900 | CURB BLOCKOUT | Material | | 4 5 5 6 6 7 7 8 8 9 | 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, | SYSTEM | (\$93,000.00) \$93,000.00 (\$93,000.00) \$93,000.00 (\$93,000.00) (\$93,000.00) (\$93,000.00) (\$93,000.00) | Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | |





| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|--------|---------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J5S3393 | 0900 | CURB BLOCKOUT | Material | | 11 | Sep 15, 2021 | SYSTEM | \$93,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate. |
| | | | | | 11 | Sep 15, 2021 | SYSTEM | (\$93,000.00) | |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | \$93,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 12 | Oct 1, 2021 | SYSTEM | (\$93,000.00) | |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | \$93,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 13 | Dec 2, 2021 | SYSTEM | (\$93,000.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0900 - | Total | | | | | | \$0.00 | |
| J5S3393 - | Total | | | | | | | \$47,894.55 | |
| Overall - | Total | | | | | | | \$191,228.12 | |