

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 3, 2023

Final Estimate Number	Contract ID	210122-D02	Pay Period Start	February 16, 2022	Original Contract Amount	\$5,294,709.41
16	Prime Contracto	r N.B. West Contracting Company	Pay Period End			
					Current Contract Amount	\$4,807,155.57

Approval Date		By User
August 3, 2023	Generated and Approved (and should be considered Draft) at the Project Office Level by	gabelj3
September 1, 2023	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	holdtc
September 6, 2023	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2021	November 1, 2021	October 5, 2021	100.00%

	Contract Informational Date	tes	Milestones						
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract						
Acceptance Date	October 7, 2022	October 7, 2022							
Awarded Date	February 3, 2021	February 3, 2021							
Letting Date	January 22, 2021	January 22, 2021							
Notice to Proceed Date	March 8, 2021	March 8, 2021							
Work Began Date J5P3236	April 19, 2021	April 19, 2021							
Work Began Date J5S3277	May 25, 2021	May 25, 2021							
Work Began Date J5S3393	July 23, 2021	July 23, 2021							

This Estimate	Previous	To Date	
\$0.00	\$4,807,155.59	\$4,807,155.59	
(\$226.68)	\$191,228.12	\$191,001.44	
\$0.00	\$0.00	\$0.00	
\$0.00	\$0.00	\$0.00	
\$0.00	\$0.00	\$0.00	
\$0.00	\$0.00	\$0.00	
	\$4,998,383.71	\$4,998,157.03	
(\$226.68)			
	\$0.00 (\$226.68) \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$4,807,155.59 (\$226.68) \$191,228.12 \$0.00	\$0.00 \$4,807,155.59 \$4,807,155.59 (\$226.68) \$191,228.12 \$191,001.44 \$0.00 \$0.0

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Line item	Aujusti	Hents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3236	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment	Asphalt Cement Price Adjustment	Correction to Estimate #6. Original adjustment, did not include quantity from 7/1/21			(\$27,151.44)
	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment	Asphalt Cement Price Adjustment	Correction to Estimate #7. Quantity should have been included in adjustment for Estimate #6.			(\$3,063.89)
	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment	Asphalt Cement Price Adjustment	Corrected for period of Estimate #6. Quanitity for period: 11,725 tons			\$29,986.69
	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment	Asphalt Cement Price Adjustment	Correction to Estimate #9			(\$728.33)

Revision 3/23/2023 Page 1 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 3, 2023

Final Estimate Number Contr	act ID	210122-D02	Pay Period Start	February 16, 2022	Original Contract Amount	\$5,294,709.41
16 Prime	Contractor	N.B. West Contracting Company	Pay Period End		Net Change Order Amount (Current Contract Amount	

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3236	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)			Corrected for period of Estimate #9. Quantity includes correction from 2/9/22 posting.			\$730.29
Total								(\$226.68)

Revision 3/23/2023 Page 2 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						0					
					(Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J5P3236	FAF 68-1(10)	Resurface and shoulder improvements	68/HH	PHELPS	from Rte. 8 to Rte. 19 near Salem and Rte. HH from Rte. 32 to the end of state maintenance						
J5S3277	FAS S401(84)	Pavement improvements	F	DENT	from Rte. 32 to Rte. E						
J5S3393	FAS S402(50)	Pavement Improvements	K	PHELPS	from Rte. 63 to the end of	of state maintenance					
Totals by	Job Numbe	rs									
J5P3236	Posted Item Pay Gross Item Adjustments Gross Item Pay			tem Pay	This Estimate \$0.00 (\$226.68) (\$226.68)	Previous \$3,497,043.04 \$129,356.62 \$3,626,399.66	To Date \$3,497,043.04 \$129,129.94 \$3,626,172.98				
	Liquid	tive centive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J5S3277		d Item Pay Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$341,467.71 \$13,976.95 \$355,444.66	To Date \$341,467.71 \$13,976.95 \$355,444.66				
	Liquid	tive centive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J5S3393		d Item Pay Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$968,644.84 \$47,894.55 \$1,016,539.39	To Date \$968,644.84 \$47,894.55 \$1,016,539.39				
	Liquid	tive centive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 3/23/2023 Page 3 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 3/23/2023 Page 4 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ote: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted am	ount at the	time the Es	timate was	Generat	ea.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-D02	J5P3236	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$105,600.00	\$105,600.00
		0001	0020	2063000	CLASS 3 EXCAVATION	234.00	0.00	234.00	CUYD	234.00	\$23.10	\$5,405.40
		0001	0030	2063300	CLASS 4 EXCAVATION	670.00	0.00	670.00	CUYD	670.00	\$60.50	\$40,535.00
		0001	0040	2079909	MISC.MODIFIED LINEAR GRADING, CLASS II	2,592.00	-52.60	2,539.40	STA	2,539.40	\$144.25	\$366,308.45
		0001	0050	2142000	FURNISHING ROCK FILL	303.00	15.67	318.67	CUYD	318.67	\$26.50	\$8,444.76
		0001	0060	2143000	PLACING ROCK FILL	303.00	15.67	318.67	CUYD	318.67	\$36.00	\$11,472.12
		0001	0070	2163500	PARTIAL REMOVAL OF CULVERT CONCRETE	1.00	0.00	1.00	LS	1.00	\$10,600.00	\$10,600.00
		0001	0080	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	306.00	0.00	306.00	SQYD	306.00	\$8.50	\$2,601.00
		0001	0090	3105002	GRAVEL (A) OR CRUSHED STONE (B)	1,477.00	-1,022.30	454.70	TONS	454.70	\$50.00	\$22,735.00
		0001	0100	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	21,398.90	-1,916.36	19,482.54	TONS	19,482.54	\$47.00	\$915,679.38
		0001	0110	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	25,306.60	-3,580.20	21,726.40	TONS	21,726.40	\$48.00	\$1,042,867.20
		0001	0120	4071005	LEVELING) TACK COAT	36,782.00	-17,434.00	19,348.00	GAL	19,348.00	\$1.89	\$36,567.72
		0001	0130	6097000	ROCK LINING	59.00	0.00	59.00	CUYD	59.00	\$70.00	\$4,130.00
		0001	0140	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0150	6161005	CONSTRUCTION SIGNS	4,359.00	-640.25	3,718.75	SQFT	3,718.75	\$4.25	\$15,804.69
		0001	0160	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$100.00	\$200.00
		0001	0170	6161009	FLAG ASSEMBLY	37.00	-7.00	30.00	EA	30.00	\$30.00	\$900.00
		0001	0180	6161025	CHANNELIZER (TRIM LINE)	400.00	0.00	400.00	EA	400.00	\$15.00	\$6,000.00
		0001	0190	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	8.00	2.00	10.00	EA	10.00	\$250.00	\$2,500.00
		0001	0200	6161052	WARNING LIGHT, TYPE B	2.00	-2.00	0.00	EA	0.00	\$100.00	\$0.00
		0001	0210	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	8.00	-1.00	7.00	EA	7.00	\$2,500.00	\$17,500.00
		0004	0220	6162004	RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS	8.00	-8.00	0.00	EA	0.00	\$100.00	\$0.00
		0001	0230	6181000	MOBILIZATION			1.00	LS		\$455,000.00	
		0001				1.00	0.00					\$455,000.00
		0001	0240	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	-3.00	1.00	EA	1.00	\$600.00	\$600.00
		0001	0250	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	18.00	18.00	36.00	LF	36.00	\$20.00	\$720.00
		0001 0260	0260	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	259,585.00	0.00	259,585.00	LF	259,585.00	\$0.09	\$23,362.65
		0001	0270	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	229,234.00	0.00	229,234.00	LF	229,234.00	\$0.10	\$21,777.23
		0001	0280	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	820.00	0.00	820.00	SQYD	820.00	\$10.15	\$8,323.00
		0001	0290	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	631.00	0.00	631.00	SQYD	631.00	\$4.50	\$2,839.50
		0001	0300	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,476.20	0.00	2,476.20	STA	2,476.20	\$10.00	\$24,762.00
		0001	0310	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	1,320.90	0.00	1,320.90	STA	1,320.90	\$10.00	\$13,209.00
		0001	0320	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$4,500.00	\$4,500.00
		0001	0330	7034041	CLASS B-1 CONCRETE (CULVERTS)	171.00	0.00	171.00	CUYD	171.00	\$1,024.50	\$175,189.50
		0001	0340	7039901	MISC.Culvert Headwall Modification	1.00	-1.00	0.00	LS	0.00	\$8,300.00	\$0.00
		0001	0350	7061030	REINFORCING STEEL (CULVERTS)	25,600.00	0.00	25,600.00	LB	25,600.00	\$3.30	\$84,480.00
		0001	0360	7250424	24 IN. PIPE GROUP C	76.00	0.00	76.00	LF	76.00	\$92.25	\$7,011.00
		0001	0370	7250430	30 IN. PIPE GROUP C	8.00	0.00	8.00	LF	8.00	\$207.00	\$1,656.00
		0001	0380	7250436	36 IN. PIPE GROUP C	8.00	0.00	8.00	LF	8.00	\$215.00	\$1,720.00
		0001	0390	7250442	42 IN. PIPE GROUP C	8.00	0.00	8.00	LF	8.00	\$223.00	\$1,784.00
		0001	0400	7250448	48 IN. PIPE GROUP C	16.00	-16.00	0.00	LF	0.00	\$228.00	\$0.00
		0001	0410	7320824A	24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$825.00	\$1,650.00
		0001	0420	7320830A	30 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,095.00	\$2,190.00
		0001	0430	7320836A	36 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,254.00	\$2,508.00

Page 5 of 26 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
122-D02	J5P3236	0001	0450	7320848A	48 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	4.00	-4.00	0.00	EA	0.00	\$1,881.00	\$0.0
		0001	0460	8051000A	SEEDING - COOL SEASON GRASSES	59.70	-42.20	17.50	ACRE	17.50	\$1.00	\$17.5
		0001	0470	8061004	SEDIMENT TRAP ROCK	150.10	-150.10	0.00	CUYD	0.00	\$66.00	\$0.
		0001	0480	8061005	ROCK DITCH CHECK	1,001.00	-707.00	294.00	LF	294.00	\$15.40	\$4,527.
		0001	0490	8061006	ALTERNATE DITCH CHECK	125.00	0.00	125.00	LF	125.00	\$13.50	\$1,687.
		0001	0500	8061016	SEDIMENT REMOVAL	1,001.00	-1,001.00	0.00	CUYD	0.00	\$2.00	\$0.
		0001	0510	8061017	TEMPORARY SEEDING	11.90	-8.40	3.50	ACRE	3.50	\$1.00	\$3.
		0001	0520	8061019	SILT FENCE	5,003.00	-5,003.00	0.00	LF	0.00	\$2.35	\$0.
		0040	0660	9039901	MISC.Adjusting Existing Signs	1.00	-1.00	0.00	LS	0.00	\$7,500.00	\$0
		0070	0670	7039903	MISC.HEADWALL MODIFICATION	68.00	-68.00	0.00	LF	0.00	\$110.00	\$0
		0071	0680	7039903	MISC.HEADWALL MODIFICATION	94.00	-94.00	0.00	LF	0.00	\$110.00	\$0
		0072	0690	7039903	MISC.HEADWALL MODIFICATION	45.00	0.00	45.00	LF	45.00	\$110.00	\$4,950
		0073	0700	7039903	MISC.HEADWALL MODIFICATION	52.00	-52.00	0.00	LF	0.00	\$110.00	\$0.
		0073	0710	7040106	FULL DEPTH REPAIR	10.00	-10.00	0.00	SQFT	0.00	\$500.00	\$0
		0001	5001	7279901	MISC.48" Pipe including excavation, grading, and pavement.	0.00	1.00	1.00	LS	1.00	\$29,646.32	\$29,646
		0001	5002	7039901	MISC.Headwall Modification on Box at Log Mile 29.211 Rte 68	0.00	1.00	1.00	LS	1.00	\$2,800.00	\$2,800
	Project J		otal Value	Posted to D	ate as of Report Generated Date							\$3,497,043.
	J5S3277	0001	0530	3105002	GRAVEL (A) OR CRUSHED STONE (B)	270.00	-215.00	55.00	TONS	55.00	\$50.00	\$2,750
		0001	0540	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	6,281.60	-1,985.20	4,296.40	TONS	4,296.40	\$46.00	\$197,634
		0001	0550	4071005	TACK COAT	7,306.00	-2,117.00	5,189.00	GAL	5,189.00	\$1.89	\$9,807
		0001	0560	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000
		0001	0570	6161005	CONSTRUCTION SIGNS	1,026.00	0.00	1,026.00	SQFT	1,026.00	\$4.25	\$4,360
		0001	0580	6161009	FLAG ASSEMBLY	11.00	0.00	11.00	EA	11.00	\$30.00	\$330
		0001	0590	6161025	CHANNELIZER (TRIM LINE)	100.00	20.00	120.00	EA	120.00	\$15.00	\$1,800
		0001 0600 61610	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000	
		0001	0610	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	-4.00	0.00	EA	0.00	\$100.00	\$0
		0001	0620	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$75,500.00	\$75,500
		0001	0630	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	72,568.00	0.00	72,568.00	LF	72,568.00	\$0.10	\$7,256
		0001	0640	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	61,680.00	0.00	61,680.00	LF	61,680.00	\$0.10	\$6,476
		0001	0650	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,009.00	453.70	2,462.70	SQYD	2,462.70	\$12.00	\$29,552
	Project J	5 S3277 - To	tal Value	Posted to D	ate as of Report Generated Date							\$341,467
	J5S3393	0001	0720	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$1,200.00	\$1,200
		0001	0730	2153000	SHAPING SLOPES, CLASS III	12.00	0.00	12.00	100F	12.00	\$1,200.00	\$14,400
		0001	0740	3105002	GRAVEL (A) OR CRUSHED STONE (B)	288.00	-172.20	115.80	TONS	115.80	\$38.00	\$4,400
		0001	0750	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	12,063.00	725.70	12,788.70	TONS	12,788.70	\$54.00	\$690,589
		0001	0760	4071005	TACK COAT	13,459.00	-470.00	12,989.00	GAL	12,989.00	\$2.00	\$25,978
		0001	0770	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000
		0001	0780	6161005	CONSTRUCTION SIGNS	1,265.00	-117.50	1,147.50	SQFT	1,147.50	\$4.25	\$4,876
		0001	0790	6161009	FLAG ASSEMBLY	10.00	0.00	10.00	EA	10.00	\$30.00	\$300
		0001	0800	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	100.00	\$15.00	\$1,500
		0001	0810	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000
		0001	0820	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	-4.00	0.00	EA	0.00	\$100.00	\$0.
		0001	0020									
		0001	0830	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$43,500.00	\$43,500.

Revision 3/23/2023 Page 6 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
										Qty		
210122-D02	J5S3393	0001	0850	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	108,652.00	0.00	108,652.00	LF	108,652.00	\$0.10	\$11,408.46
		0001	0860	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	885.00	0.00	885.00	SQYD	885.00	\$6.70	\$5,929.50
		0001	0870	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	817.00	0.00	817.00	SQYD	817.00	\$6.70	\$5,473.90
		0010	0880	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	8.00	0.00	8.00	EA	8.00	\$3,000.00	\$24,000.00
		0010	0890	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	8.00	\$2,800.00	\$22,400.00
		0070	0900	7034600	CURB BLOCKOUT	375.00	0.00	375.00	LF	375.00	\$248.00	\$93,000.00
	Project J5S3393 - Total Value Posted to Date as of Report Generated Date											\$968,644.84
210122-D02 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$4,807,155.56

Revision 3/23/2023 Page 7 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

				nental to the Estimate and is pro s for Construction Signs (if appli								
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J5P3236	0150	March 31,	76	GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		39.165		1.00	10			10
		2021		CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		39.051		1.00	12			12
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		17.275		1.00	12			12
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		17.162		1.00	10			10
				GO20-2 48x24 8.00 END ROAD WORK		17.062		1.00	8			8
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		17.057		1.00	8			8
				GO20-2 48x24 8.00 END ROAD WORK		39.306		1.00	8			8
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		39.278		1.00	8			8
		May 1, 2021	768	WO3-4(48) 48x48 16.00 BE PREPARED TO STOP			Various	12.00	16			192
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD			Various	12.00	16			192
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			Various	12.00	16			192
				WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS			Various	12.00	16			192
		May 15, 2021	108	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			37.632 -91.539	1.00	16			16
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			37.629 -91.541	1.00	16			16
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE			37.633 -91.540	1.00	12			12
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE			37.591 -91.545	1.00	12			12
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES			37.634 -91.540	1.00	10			10
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES			37.589 -91.545	1.00	10			10
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE			37.588 -91.545	1.00	8			8
				GO20-2 48x24 8.00 END ROAD WORK			37.636 -91.540	1.00	8			8
				GO20-2 48x24 8.00 END ROAD WORK			37.595 -91.545	1.00	8			8
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE			37.636 -91.540	1.00	8			8
	0150 - To	otal										952
J5S3277	0570	June 3, 2021	590	Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET			various location on project	7.50	1	Pilot car in use & follow 18x12	1.50	7.5
				WO3-4(48) 48x48 16.00 BE PREPARED TO STOP			various location on project	7.00	16			112
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD			various location on project	6.00	16			96
				GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR			various location on project	2.00	8.75			17.5
				WO20-7a 48x48 16.00 FLAGGER (SYMBOL)			various location on project	11.00	16			176
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			various location on project	11.00	16			176
				GO20-4 36x18 4.50 PILOT CAR			various	1.00	4.5			4.5

Revision 3/23/2023 Page 8 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The infor	mation	below t	his line are details	for Construction Signs (if applied	cable).							
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J5S3277	0570	June 3, 2021	590	FOLLOW ME			location on project					
	0570 - To	otal										589.5
J5S3393	0780	June 1, 2021	76	CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		13.022		1.00	12			12
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		13.04		1.00	10			10
				GO20-2 48x24 8.00 END ROAD WORK		13.040		1.00	8			8
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		0.026		1.00	8			8
				GO20-2 48x24 8.00 END ROAD WORK		0.007		1.00	8			8
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		.297		1.00	12			12
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		13.042		1.00	8			8
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		.142		1.00	10			10
	0780 - To	otal										76

Revision 3/23/2023 Page 9 of 26



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
36	0030	CLASS 4 EXCAVATION	Overrun	Overrun	9	Aug 16, 2021	SYSTEM	(\$36.30)	
					14	Feb 2, 2022	SYSTEM	\$36.30	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',60.50000 - 60.50000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0030 -	Total						\$0.00	
	0050	FURNISHING ROCK FILL	Material		3	May 16, 2021	SYSTEM	\$415.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcwhom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	(\$415.26)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	9	Aug 16, 2021	SYSTEM	(\$415.26)	
					13	Dec 2, 2021	SYSTEM	\$415.26	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',26.50000 - 26.50000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0050 -	Total						\$0.00	
	0060	PLACING ROCK FILL	Overrun	Overrun	9	Aug 16, 2021	SYSTEM	(\$564.12)	
					13	Dec 2, 2021	SYSTEM	\$564.12	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',36.00000 - 36.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0060 -	Total						\$0.00	
	0000	TVDE 4							
	0800	TYPE 1 AGGREGATE FOR BASE (4 IN.	Material		9	Aug 16, 2021	SYSTEM	\$2,601.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	0080	AGGREGATE	Material		9		SYSTEM	\$2,601.00 (\$2,601.00)	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment
	0080	AGGREGATE FOR BASE (4 IN.	Material			2021 Aug 16,			Estimate Item Adjustment (0005) due to user linkd1 overridding Payment
	0080	AGGREGATE FOR BASE (4 IN.	Material		9	2021 Aug 16, 2021 Sep 2,	SYSTEM	(\$2,601.00)	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
	0080	AGGREGATE FOR BASE (4 IN.	Material		9	2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM	(\$2,601.00) \$2,601.00	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
	0080	AGGREGATE FOR BASE (4 IN.	Material		9 10 10	2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 15,	SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00)	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
	0080	AGGREGATE FOR BASE (4 IN.	Material		9 10 10 11	2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 15, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
	0080	AGGREGATE FOR BASE (4 IN.	Material		9 10 10 11 11 11	2021 Aug 16, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
	0080	AGGREGATE FOR BASE (4 IN.	Material		9 10 10 11 11 11 12	2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 Oct 1, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00)	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
	0080	AGGREGATE FOR BASE (4 IN.	Material		9 10 10 11 11 12 12 12	2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 15, 2021 Oct 1, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
	0080	AGGREGATE FOR BASE (4 IN.	Material	- Total	9 10 10 11 11 12 12 13	2021 Aug 16, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00)	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
	0080	AGGREGATE FOR BASE (4 IN.	Material - To		9 10 10 11 11 12 12 13	2021 Aug 16, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00)	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
	0080 -	AGGREGATE FOR BASE (4 IN. THICK)			9 10 10 11 11 12 12 13	2021 Aug 16, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
		AGGREGATE FOR BASE (4 IN. THICK)	Material - To		9 10 10 11 11 12 12 13	2021 Aug 16, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 \$2,601.00 \$2,601.00	Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0090	GRAVEL (A) OR CRUSHED STONE (B)	Material		8	Aug 2, 2021	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$4,400.00)	
					9	Aug 16, 2021	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$4,400.00)	
					10	Sep 2, 2021	SYSTEM	\$17,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$17,935.00)	
					11	Sep 15, 2021	SYSTEM	\$17,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$17,935.00)	
					12	Oct 1, 2021	SYSTEM	\$22,735.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$22,735.00)	
					13	Dec 2, 2021	SYSTEM	\$22,735.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$22,735.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0090 -	- Total						\$0.00	
	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	Material		6	Jul 1, 2021	SYSTEM	\$853,042.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	0100	PAVEMENT	Material		6		SYSTEM	\$853,042.48 (\$853,042.48)	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
	0100	PAVEMENT MIXTURE	Material			2021 Jul 1,			Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
	0100	PAVEMENT MIXTURE	Material		6	Jul 1, 2021 Jul 16,	SYSTEM	(\$853,042.48)	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment
	0100	PAVEMENT MIXTURE	Material		6	Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM	(\$853,042.48) \$905,146.68	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment
	0100	PAVEMENT MIXTURE	Material		6 7 7	Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM	(\$853,042.48) \$905,146.68 (\$905,146.68)	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment
	0100	PAVEMENT MIXTURE	Material		6 7 7 8	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$853,042.48) \$905,146.68 (\$905,146.68) \$905,146.68	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment
	0100	PAVEMENT MIXTURE	Material		6 7 7 8 8 8	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$853,042.48) \$905,146.68 (\$905,146.68) \$905,146.68	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment
	0100	PAVEMENT MIXTURE	Material		6 7 7 8 8 8 9	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$853,042.48) \$905,146.68 (\$905,146.68) \$905,146.68 (\$905,146.68) \$633,651.18	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment
	0100	PAVEMENT MIXTURE	Material		6 7 7 8 8 8 9 9	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$853,042.48) \$905,146.68 (\$905,146.68) \$905,146.68 (\$905,146.68) \$633,651.18	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.
	0100	PAVEMENT MIXTURE	Material		6 7 7 8 8 9 9 10	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$853,042.48) \$905,146.68 (\$905,146.68) \$905,146.68 (\$905,146.68) \$633,651.18 (\$633,651.18) \$619,551.18	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.
	0100	PAVEMENT MIXTURE	Material		6 7 7 8 8 8 9 9 10 10 10	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM	(\$853,042.48) \$905,146.68 (\$905,146.68) \$905,146.68 (\$905,146.68) \$633,651.18 (\$633,651.18) \$619,551.18	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.
	0100	PAVEMENT MIXTURE	Material		6 7 7 8 8 9 9 10 10 11 11	2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 15, 2021	SYSTEM	(\$853,042.48) \$905,146.68 (\$905,146.68) \$905,146.68 (\$905,146.68) \$633,651.18 (\$633,651.18) \$619,551.18 (\$619,551.18)	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0100	BITUMINOUS PAVEMENT MIXTURE	Material		13	Dec 2, 2021	SYSTEM	\$619,551.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		PG64-22 (BAS			13	Dec 2, 2021	SYSTEM	(\$619,551.18)	
					14	Feb 2, 2022	SYSTEM	\$619,574.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Feb 2, 2022	SYSTEM	(\$619,574.68)	
					15	Feb 15, 2022	SYSTEM	\$619,579.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Feb 15, 2022	SYSTEM	(\$619,579.38)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	ACAD	5	Jun 16, 2021	linkd1	\$19,266.67	7533.4 tons
					6	Jul 1, 2021	linkd1	\$27,151.44	10,616.4 tons + \$27,151.44
					7	Jul 16, 2021	linkd1	\$3,063.89	1108.6 tons , 3.3% VAC , +\$3063.89
					9	Aug 16, 2021	linkd1	\$728.33	Line 100 223.5 tons + \$728.33
					16	Aug 3, 2023	gabelj3	\$29,986.69	Corrected for period of Estimate #6. Quanitity for period: 11,725 tons
					16	Aug 3, 2023	gabelj3	\$730.29	Corrected for period of Estimate #9. Quantity includes correction from 2/9/22 posting.
					16	Aug 3, 2023	gabelj3	(\$27,151.44)	Correction to Estimate #6. Original adjustment, did not include quantity from 7/1/21
					16	Aug 3, 2023	gabelj3	(\$3,063.89)	Correction to Estimate #7. Quantity should have been included in adjustment for Estimate #6.
					16	Aug 3, 2023	gabelj3	(\$728.33)	Correction to Estimate #9
				ACAD - Tota	al			\$49,983.65	
			Other Item A	djustment - T	otal			\$49,983.65	
	0100 -	Total						\$49,983.65	
	0110	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		7	Jul 16, 2021	SYSTEM	\$611,025.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		1 004-22 (0011			7	Jul 16, 2021	SYSTEM	(\$611,025.60)	
					8	Aug 2, 2021	SYSTEM	\$1,032,096.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$1,032,096.00)	
					10	Sep 2, 2021	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$416,467.20)	
					11	Sep 15, 2021	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$416,467.20)	
					12	Oct 1, 2021	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$416,467.20)	
					13	Dec 2, 2021	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0110	BITUMINOUS PAVEMENT	Material		13	Dec 2, 2021	SYSTEM	(\$416,467.20)	
		MIXTURE PG64-22 (SUR			14	Feb 2, 2022	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Feb 2, 2022	SYSTEM	(\$416,467.20)	
					15	Feb 15, 2022	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Feb 15, 2022	SYSTEM	(\$416,467.20)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	ACAD	7	Jul 16, 2021	linkd1	\$42,644.50	12729.70 tons, 4.00% VAC, +\$42,644.50
					8	Aug 2, 2021	linkd1	\$29,387.21	Line 110 8772.3 Tons +\$29,387.21
					9	Aug 16, 2021	linkd1	\$886.38	Line 110 224.4 tons + \$886.38
				ACAD - Tota	al			\$72,918.09	
			Other Item A	djustment - T	otal			\$72,918.09	
	0110 -	Total						\$72,918.09	
	0120	TACK COAT	Material		5	Jun 16, 2021	SYSTEM	\$1,763.37	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$1,763.37)	
					6	Jul 1, 2021	SYSTEM	\$3,600.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$3,600.45)	
					7	Jul 16, 2021	SYSTEM	\$22,880.34	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$22,880.34)	
					8	Aug 2, 2021	SYSTEM	\$34,808.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$34,808.13)	
					9	Aug 16, 2021	SYSTEM	\$35,084.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$35,084.07)	
					10	Sep 2, 2021	SYSTEM	\$35,084.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$35,084.07)	
					11	Sep 15, 2021	SYSTEM	\$35,084.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$35,084.07)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0120 -	Total						\$0.00	
	0130	ROCK LINING	Material		6	Jul 1, 2021	SYSTEM	\$1,918.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0130	ROCK LINING	Material		6	Jul 1, 2021	SYSTEM	(\$1,918.00)	
					7	Jul 16, 2021	SYSTEM	\$1,918.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$1,918.00)	
					8	Aug 2, 2021	SYSTEM	\$1,918.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$1,918.00)	
					9	Aug 16, 2021	SYSTEM	\$4,130.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$4,130.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
	0130 -	Total						\$0.00	
	0160	ADVANCED WARNING RAIL SYSTEM	Material		2	May 3, 2021	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		OTOTEW			2	May 3, 2021	SYSTEM	(\$200.00)	Estimate Exception 1 on the current 1 ayricht Estimate.
					3	May 16, 2021	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcwhom1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	(\$200.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0160 -	Total						\$0.00	
			Material		0	Marrio	OVOTEM		This adjusts and effects the minimal content of Material December
	0170	FLAG ASSEMBLY	Material		2	May 3, 2021	SYSTEM	\$720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	May 3, 2021	SYSTEM	(\$720.00)	
					3	May 16, 2021	SYSTEM	\$720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcwhom1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	(\$720.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0170 -	- Total							
	0180	CHANNELIZER (TRIM LINE)	Material		2	May 3, 2021	SYSTEM	\$0.00 \$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	0180		Material		2		SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0003) due to user linkd1 overridding Payment
	0180		Material			2021 May 3,		\$0.00 \$3,000.00	Estimate Item Adjustment (0003) due to user linkd1 overridding Payment
	0180		Material		2	2021 May 3, 2021 May 16,	SYSTEM	\$0.00 \$3,000.00 (\$3,000.00)	Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment
	0180		Material	- Total	2	May 3, 2021 May 16, 2021 May 16,	SYSTEM	\$0.00 \$3,000.00 (\$3,000.00) \$3,000.00	Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment
	0180		Material Material - To		2	May 3, 2021 May 16, 2021 May 16,	SYSTEM	\$0.00 \$3,000.00 (\$3,000.00) \$3,000.00	Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment
	0180	(TRIM LINE)			2	May 3, 2021 May 16, 2021 May 16,	SYSTEM	\$0.00 \$3,000.00 (\$3,000.00) \$3,000.00 (\$3,000.00) \$0.00	Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment
	0180 -	(TRIM LINE)	Material - To	tal	3 3	2021 May 3, 2021 May 16, 2021 May 16, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 \$3,000.00 (\$3,000.00) \$3,000.00 (\$3,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment
		Total TYPE III MOVEABLE BARRICADE WITH			3 3	May 3, 2021 May 16, 2021 May 16,	SYSTEM	\$0.00 \$3,000.00 (\$3,000.00) \$3,000.00 (\$3,000.00) \$0.00	Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment
	0180 -	Total TYPE III MOVEABLE	Material - To	tal	3 3 8 14	2021 May 3, 2021 May 16, 2021 May 16, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 \$3,000.00 (\$3,000.00) \$3,000.00 (\$3,000.00) \$0.00 \$0.00 (\$500.00)	Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0190	TYPE III MOVEABLE BARRICADE WITH LIGHTS	Overrun - To	tal				\$0.00	
	0190 -	· Total						\$0.00	
	0210	CMS W/O COMMUNICATION INTERFACE,	Material		2	May 3, 2021	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		CONT F/			2	May 3, 2021	SYSTEM	(\$10,000.00)	
					3	May 16, 2021	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcwhom1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	(\$10,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	8	Aug 2, 2021	SYSTEM	(\$7,500.00)	
					13	Dec 2, 2021	SYSTEM	\$7,500.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2500.00000 - 2500.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0210 -	· Total						\$0.00	
	0260	4 IN. WHITE WATERBORNE PAVEMENT	Material		10	Sep 2, 2021	SYSTEM	\$2,271.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		MARKING			10	Sep 2, 2021	SYSTEM	(\$2,271.60)	
					11	Sep 15, 2021	SYSTEM	\$23,362.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$23,362.65)	
					12	Oct 1, 2021	SYSTEM	\$23,362.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$23,362.65)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	REFL	12	Oct 1, 2021	linkd1	\$1,168.13	See Adjustment Sheet
				REFL - Tota	ıl			\$1,168.13	
			Other Item A	.djustment - T	otal			\$1,168.13	
	0260 -	·Total						\$1,168.13	
	0270	4 IN. YELLOW WATERBORNE PAVEMENT	Material		10	Sep 2, 2021	SYSTEM	\$21,777.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
		MARKING			10	Sep 2, 2021	SYSTEM	(\$21,777.23)	
					11	Sep 15, 2021	SYSTEM	\$21,777.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$21,777.23)	
					12	Oct 1, 2021	SYSTEM	\$21,777.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$21,777.23)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item	REFL	12	Oct 1,	linkd1	\$1,120.95	See Adjustment Worksheet



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0270	4 IN. YELLOW WATERBORNE	Adjustment			2021			
		PAVEMENT MARKING		REFL - Tota				\$1,120.95	
	0070		Other Item A	djustment - T	otal			\$1,120.95	
	0330	CLASS B-1 CONCRETE	Material		2	May 3, 2021	SYSTEM	\$1,120.95 \$34,320.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment
		(CULVERTS)			2	May 3, 2021	SYSTEM	(\$34,320.75)	Estimate Exception 5 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcwhom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	(\$82,216.12)	
					4	Jun 2, 2021	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcwhom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 2, 2021	SYSTEM	(\$82,216.12)	
					5	Jun 16, 2021	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$82,216.12)	
					6	Jul 1, 2021	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$82,216.12)	
					7	Jul 16, 2021	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$82,216.12)	
					8	Aug 2, 2021	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$82,216.12)	
				- Total				\$0.00	
			Material - To					\$0.00	
			Other Item Adjustment	SUBI	3	May 17, 2021	mcwhom1	(\$550.00)	Aplex poured the floor in box 0.765 on Rte. HH with Non chlorinated accelerant. I talked to Eric Abbott and we decided that the box Floor would be fine to leave in place but a deduct would need to be taken. A total of 5.25 yards were poured in the floor so Eric decided that a deduct of \$550.00 would be appropriate
				SUBI - Tota				(\$550.00)	
			Other Item A	djustment - T	otal			(\$550.00)	
	0330	- Total 24 IN. PIPE CULVERT GROUP C	Material		13	Dec 2, 2021	SYSTEM	(\$550.00) \$7,011.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$7,011.00)	Estimate Exception 11 on the current rayment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0360 -	- Total						\$0.00	
	0370	30 IN. PIPE CULVERT GROUP C	Material		13	Dec 2, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$1,656.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0370	- Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0380	36 IN. PIPE CULVERT GROUP C	Material		13	Dec 2, 2021	SYSTEM	\$1,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$1,720.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0380 -	Total						\$0.00	
	0390	42 IN. PIPE CULVERT GROUP C	Material		13	Dec 2, 2021	SYSTEM	\$1,784.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$1,784.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0390 -							\$0.00	
	0460	SEEDING - COOL SEASON GRASSES	Material		12	Oct 1, 2021	SYSTEM	\$17.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$17.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0460 -							\$0.00	
	0480	ROCK DITCH CHECK	Material		7	Jul 16, 2021	SYSTEM	\$4,527.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$4,527.60)	
					8	Aug 2, 2021	SYSTEM	\$4,527.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$4,527.60)	
					9	Aug 16, 2021	SYSTEM	\$4,527.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$4,527.60)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0480 -	Total						\$0.00	
	0490	ALTERNATE DITCH CHECK	Material		2	May 3, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					2	May 3, 2021	SYSTEM	(\$1,687.50)	
					3	May 16, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcwhom1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	(\$1,687.50)	
					4	Jun 2, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcwhom1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Jun 2, 2021	SYSTEM	(\$1,687.50)	
					5	Jun 16, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$1,687.50)	
					6	Jul 1, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.



CONSTRUCTION Adjustment 2022 culverts on the original line item 0340. This steel is left over from Bridges,	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2011 2011	J5P3236	0490		Material		6		SYSTEM	(\$1,687.50)	
2021 8						7		SYSTEM	\$1,687.50	Estimate Item Adjustment (0009) due to user linkd1 overridding Payment
2021 Editionals Blank Adjustment (0751) due to user limits Exception 2 on the current Payment Editionals (1974)						7		SYSTEM	(\$1,687.50)	
9						8		SYSTEM	\$1,687.50	Estimate Item Adjustment (0013) due to user linkd1 overridding Payment
2021 Estimate bean Agujustment (0011) due to user linked overridding Psyment Estimate Exception 22 on the current Psyment Estimate.						8		SYSTEM	(\$1,687.50)	
2021 3.00 10.00						9		SYSTEM	\$1,687.50	Estimate Item Adjustment (0011) due to user linkd1 overridding Payment
						9		SYSTEM	(\$1,687.50)	
0510 TEMPORARY SEEDING Material					- Total				\$0.00	
				Material - To	tal				\$0.00	
SEEDING		0490 -	Total						\$0.00	
2021 8		0510		Material		7		SYSTEM	\$3.50	Estimate Item Adjustment (0010) due to user linkd1 overridding Payment
2021 Estimate Item Adjustment (0014) due to user linked overridding Payment Estimate Estimate Exception 22 on the current Payment Estimate Payment Payment Estimate Payment Estimate Payment Payment Payment Payment Payment Payment Payment Estimate Payment Payme						7		SYSTEM	(\$3.50)	
2021 9						8		SYSTEM	\$3.50	Estimate Item Adjustment (0014) due to user linkd1 overridding Payment
2021 Estimate Exception 23 on the current Payment Estimate Exception 23 on the current Payment Estimate Exception 23 on the current Payment Estimate.						8		SYSTEM	(\$3.50)	
2021 10 Sep 2, 2021 20						9		SYSTEM	\$3.50	Estimate Item Adjustment (0012) due to user linkd1 overridding Payment
2021 Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.						9		SYSTEM	(\$3.50)	
2021						10		SYSTEM	\$3.50	Estimate Item Adjustment (0008) due to user linkd1 overridding Payment
Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate. 11 Sep 15, SYSTEM (\$3.50) 12 Oct 1, SYSTEM \$3.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 24 on the current Payment Estimate. 12 Oct 1, SYSTEM (\$3.50) - Total \$0.00 Material - Total \$0.00 Material - Total \$0.00 Misc. CONCRETE CONSTRUCTION Adjustment Summer Summe						10		SYSTEM	(\$3.50)	
2021 12						11		SYSTEM	\$3.50	Estimate Item Adjustment (0008) due to user linkd1 overridding Payment
2021 Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.						11		SYSTEM	(\$3.50)	
Total Total Total S0.00 Material - Total S0.00 MISC. CONCRETE CONSTRUCTION Adjustment CONSTRUCTION MATL - Total Other Item Adjustment - Total S0.00 MATL - Total S0.00 MATL - Total S4,489.12 Other Item Adjustment - Total S4,489.12 S022 JSP3236 - Total S129,129.94 JSS3277 S40 BITUMINOUS PAVEMENT S50.00 Material - Total S4,489.12 S129,129.94 S129,129.94 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment						12		SYSTEM	\$3.50	Estimate Item Adjustment (0008) due to user linkd1 overridding Payment
Material - Total S0.00 MISC. CONCRETE CONSTRUCTION MATL 14 Feb 2, 2022 linkd1 \$4,489.12 Material Takeover for steel delivered to job that was not used on the other bo culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that we received from the contractor. MATL - Total \$4,489.12						12		SYSTEM	(\$3.50)	
Solution					- Total				\$0.00	
Source Misc. Concrete Other Item Adjustment Material 14 Feb 2, 2022 Iinkd1 \$4,489.12 Material Takeover for steel delivered to job that was not used on the other bound on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. Material Takeover for steel delivered to job that was not used on the other bound or culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. Material Takeover for steel delivered to job that was not used on the other bound or culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was received from the contractor. Substitute Substi				Material - To	tal				\$0.00	
CONSTRUCTION Adjustment 2022 culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that we received from the contractor. MATL - Total \$4,489.12 Other Item Adjustment - Total \$4,489.12 J593236 - Total \$129,129.94 J5S3277 0540 BITUMINOUS PAVEMENT 5 Jun 16, SYSTEM \$197,634.40 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment		0510 -	Total						\$0.00	
Other Item Adjustment - Total \$4,489.12 5002 - Total \$4,489.12 J5P3236 - Total \$129,129.94 J5S3277 0540 BITUMINOUS PAVEMENT 5 Jun 16, SYSTEM 2021 \$197,634.40 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment		5002			MATL	14		linkd1	\$4,489.12	S0141, S0151, S0171. Price includes 5% overhead above the invoice that was
Solution Solution State					MATL - Tota	il			\$4,489.12	
J5P3236 - Total J5S3277 0540 BITUMINOUS PAVEMENT 5 Jun 16, SYSTEM 2021 \$197,634.40 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment				Other Item A	djustment - T	otal			\$4,489.12	
J5S3277 0540 BITUMINOUS PAVEMENT 5 Jun 16, SYSTEM \$197,634.40 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment		5002 -	Total						\$4,489.12	
PAVEMENT 2021 Estimate Item Adjustment (0006) due to user linkd1 overridding Payment	J5P3236 -	Total							\$129,129.94	
	J5S3277	0540	PAVEMENT MIXTURE	Material		5		SYSTEM	\$197,634.40	Estimate Item Adjustment (0006) due to user linkd1 overridding Payment
PG64-22 (SUR 5 Jun 16, 2021 (\$197,634.40)			PG64-22 (SUR			5		SYSTEM	(\$197,634.40)	



BTILMINOUS PANEMENT MIXTURE PG64-22 (SUR Metrial PG64-22 (SUR PANEMENT MIXTURE PG64-22 (SUR PG64-22 (SUR	Payment Payment Payment Payment Payment
7 Jul 16, 2021 SYSTEM (\$197,634.40) 7 Jul 16, 2021 SYSTEM (\$197,634.40) 8 Aug 2, 2021 SYSTEM (\$197,634.40) 8 Aug 2, 2021 SYSTEM (\$197,634.40) 8 Aug 2, 2021 SYSTEM (\$197,634.40) 9 Aug 16, 2021 SYSTEM (\$197,634.40) 9 Aug 16, 2021 SYSTEM (\$197,634.40) 10 Sep 2, 2021 SYSTEM (\$59,634.40) 10 Sep 2, 2021 SYSTEM (\$59,634.40) 10 Sep 2, 2021 SYSTEM (\$59,634.40) 11 Sep 15, 2021 SYSTEM (\$13,634.40) 12 Oct 1, SYSTEM (\$13,634.40) 13 Sep 15, 2021 SYSTEM (\$13,634.40) 14 Oct 1, SYSTEM (\$13,634.40) 15 Sep 16, 2021 SYSTEM (\$13,634.40) 16 Sep 17, 2021 SYSTEM (\$13,634.40) 17 Sep 18, 2021 SYSTEM (\$13,634.40) 18 Sep 19, 2021 SYSTEM (\$13,634.40)	Payment payment
Estimate Item Adjustment (0012) due to user linkd 1 overridding Estimate Exception 4 on the current Payment Estimate. 7	Payment payment
2021 8 Aug 2, 2021 SYSTEM \$197,634.40 This adjustment offsets the original system-generated Material Estimate Exception 5 on the current Payment Estimate. 8 Aug 2, 2021 SYSTEM (\$197,634.40) 9 Aug 16, 2021 SYSTEM \$59,634.40 10 Sep 2, 2021 This adjustment offsets the original system-generated Material Estimate Exception 4 on the current Payment Estimate. 9 Aug 16, 2021 SYSTEM (\$59,634.40) 10 Sep 2, 2021 This adjustment offsets the original system-generated Material Estimate Exception 4 on the current Payment Estimate. 9 Aug 16, 2021 This adjustment offsets the original system-generated Material Estimate Exception 6 on the current Payment Estimate. 10 Sep 2, 2021 SYSTEM (\$13,634.40) 11 Sep 15, 2021 This adjustment offsets the original system-generated Material Estimate Exception 6 on the current Payment Estimate. 11 Sep 15, 2021 This adjustment offsets the original system-generated Material Estimate Exception 6 on the current Payment Estimate. 11 Sep 15, 2021 This adjustment offsets the original system-generated Material Estimate Exception 6 on the current Payment Estimate. 12 Oct 1, SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material Estimate Exception 6 on the current Payment Estimate. 12 Oct 1, SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material Estimate Exception 6 on the current Payment Estimate. 13 Sep 15, 2021 This adjustment offsets the original system-generated Material Estimate Exception 6 on the current Payment Estimate.	p Payment Payment
Estimate Item Adjustment (0018) due to user linkd1 overridding Estimate Exception 5 on the current Payment Estimate. 8 Aug 2, 2021 SYSTEM (\$197,634.40) 9 Aug 16, 2021 Estimate Exception 5 on the current Payment Estimate. 9 Aug 16, 2021 SYSTEM (\$59,634.40) 10 Sep 2, 2021 SYSTEM \$13,634.40 10 Sep 2, 2021 SYSTEM (\$13,634.40) 10 Sep 2, 2021 SYSTEM (\$13,634.40) 11 Sep 15, 2021 SYSTEM \$13,634.40 12 Oct 1, 2021 SYSTEM (\$13,634.40) 13 Sep 15, 2021 SYSTEM S13,634.40 14 Sep 15, SYSTEM S13,634.40 15 Sep 15, SYSTEM S13,634.40 16 Sep 15, SYSTEM S13,634.40 17 Sep 15, SYSTEM S13,634.40 18 Sep 15, SYSTEM S13,634.40 19 Sep 15, SYSTEM S13,634.40 10 Sep 15, SYSTEM S13,634.40 11 Sep 15, SYSTEM S13,634.40 12 Oct 1, SYSTEM S13,634.40 13 Sep 15, SYSTEM S13,634.40 14 Sep 15, SYSTEM S13,634.40 15 Sep 15, SYSTEM S13,634.40 16 Sep 15, SYSTEM S13,634.40 17 Sep 15, SYSTEM S13,634.40 18 Sep 15, SYSTEM S13,634.40 19 Sep 15, SYSTEM S13,634.40 10 Sep 15, SYSTEM S13,634.40 11 Sep 15, SYSTEM S13,634.40 12 Oct 1, SYSTEM S13,634.40 13 SYSTEM S13,634.40 14 Sep 15, SYSTEM S13,634.40 15 Sep 15, SYSTEM S13,634.40 16 Sep 15, SYSTEM S13,634.40 17 Sep 15, SYSTEM S13,634.40 18 Sep 15, SYSTEM S13,634.40 19 SYSTEM S13,634.40 10 Sep 2, SYSTEM S13,634.40	p Payment Payment
9 Aug 16, 2021 SYSTEM \$59,634.40 This adjustment offsets the original system-generated Material If Estimate Exception 4 on the current Payment Estimate. 9 Aug 16, 2021 SYSTEM (\$59,634.40) 10 Sep 2, 2021 SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material If Estimate Exception 6 on the current Payment Estimate. 10 Sep 2, 2021 SYSTEM (\$13,634.40) 11 Sep 15, 2021 SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material If Estimate Exception 6 on the current Payment Estimate. 11 Sep 15, 2021 SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material If Estimate Item Adjustment (0014) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate. 11 Sep 15, 2021 SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material If Estimate Item Adjustment (0013) due to user linkd1 overridding Estimate Item Adjustment (0013) due to user linkd1 overridding Estimate Item Adjustment (0013) due to user linkd1 overridding Estimate Item Adjustment (0013) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate. 12 Oct 1, SYSTEM \$13,634.40	
Estimate Item Adjustment (0019) due to user linkd1 overridding Estimate Exception 4 on the current Payment Estimate. 9 Aug 16, 2021 10 Sep 2, 2021 11 Sep 15, 2021 12 Oct 1, SYSTEM 2021 Estimate Item Adjustment (0019) due to user linkd1 overridding Estimate Exception 4 on the current Payment Estimate. 10 Sep 2, SYSTEM \$13,634.40 Estimate Item Adjustment (0014) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate. 10 Sep 15, SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material Festimate Item Adjustment (0014) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate. 11 Sep 15, 2021 12 Oct 1, SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material Festimate Exception 6 on the current Payment Estimate. 13 Sep 15, 2021 14 Oct 1, SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material Festimate Item Adjustment (0013) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate.	
2021 10 Sep 2, 2021 SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material R Estimate Item Adjustment (0014) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate. 10 Sep 2, 2021 SYSTEM (\$13,634.40) 11 Sep 15, 2021 Sep 15, SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material R Estimate Item Adjustment (0014) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate. 11 Sep 15, SYSTEM (\$13,634.40) 12 Oct 1, SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material R Estimate Item Adjustment (0013) due to user linkd1 overridding Estimate Item Adjustment (0013) due to user linkd1 overridding Estimate Item Adjustment (0013) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate.	
Estimate Item Adjustment (0014) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate.	
11 Sep 15, 2021 \$13,634.40 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0014) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate. 11 Sep 15, 2021 \$13,634.40 \$13,634.40 \$ 12 Oct 1, 2021 \$13,634.40 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0013) due to user linkd1 overridding Estimate Item Adjustment (0013) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate.	
2021 Estimate Item Adjustment (0014) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate.	
2021 12 Oct 1, SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0013) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate. 12 Oct 1, SYSTEM (\$13,634.40)	
2021 Estimate Item Adjustment (0013) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate. 12 Oct 1, SYSTEM (\$13,634.40)	
Dec 2, SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material F Estimate Item Adjustment (0017) due to user linkd1 overridding Estimate Exception 6 on the current Payment Estimate.	
13 Dec 2, SYSTEM (\$13,634.40)	
14 Feb 2, SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material Festimate Item Adjustment (0006) due to user linkd1 overridding Estimate Exception 3 on the current Payment Estimate.	
14 Feb 2, SYSTEM (\$13,634.40)	
15 Feb 15, SYSTEM \$13,634.40 This adjustment offsets the original system-generated Material f Estimate Item Adjustment (0003) due to user linkd1 overridding Estimate Exception 3 on the current Payment Estimate.	
15 Feb 15, SYSTEM (\$13,634.40)	
- Total \$0.00	
Material - Total \$0.00	
Adjustment 2021	
ACAD - Total \$13,318.84 Other Item Adjustment - Total \$13,318.84	
0540 - Total \$13,318.84	
TACK COAT Material 5 Jun 16, 2021 \$9,807.21 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0007) due to user linkd1 overridding Estimate Exception 3 on the current Payment Estimate.	
5 Jun 16, SYSTEM (\$9,807.21)	
6 Jul 1, SYSTEM \$9,807.21 This adjustment offsets the original system-generated Material Festimate Item Adjustment (0009) due to user linkd1 overridding Estimate Exception 4 on the current Payment Estimate.	
6 Jul 1, SYSTEM (\$9,807.21)	Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3277	0550	TACK COAT	Material		7	Jul 16, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$9,807.21)	
					8	Aug 2, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$9,807.21)	
					9	Aug 16, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$9,807.21)	
					10	Sep 2, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$9,807.21)	
					11	Sep 15, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$9,807.21)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0550 -	Total						\$0.00	
	0570	CONSTRUCTION SIGNS	Overrun	Overrun	8	Aug 2, 2021	SYSTEM	(\$1,531.06)	
					13	Dec 2, 2021	SYSTEM	\$1,531.06	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4.25000 - 4.25000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - To	tal				\$0.00	
	0570 -	Total						\$0.00	
	0590	CHANNELIZER (TRIM LINE)							
	0590		Overrun	Overrun	8	Aug 2, 2021	SYSTEM	(\$300.00)	
	0590		Overrun	Overrun	14		SYSTEM	\$300.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero).
	0590		Overrun	Overrun - T	14	2021 Feb 2,		` ′	previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is
	0590		Overrun - To	Overrun - T	14	2021 Feb 2,		\$300.00	previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is
	0590 -	(TRIM LINE)		Overrun - T	14	2021 Feb 2,		\$300.00	previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is
		Total 4 IN. WHITE WATERBORNE PAVEMENT	Overrun - To	Overrun - T	14	2021 Feb 2,		\$300.00 \$0.00 \$0.00	previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is
	0590 -	(TRIM LINE) Total 4 IN. WHITE WATERBORNE	Overrun - To	Overrun - T	14 otal	2021 Feb 2, 2022 Jun 16,	SYSTEM	\$300.00 \$0.00 \$0.00	previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment
	0590 -	Total 4 IN. WHITE WATERBORNE PAVEMENT	Overrun - To	Overrun - T	14 otal	Jun 16, 2021 Jun 16, 2021	SYSTEM	\$300.00 \$0.00 \$0.00 \$0.00 \$5,805.50	previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment
	0590 -	Total 4 IN. WHITE WATERBORNE PAVEMENT	Overrun - To	Overrun - T	14 otal 5 5 5	Jun 16, 2021 Jun 16, 2021 Jun 16, 1021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM	\$300.00 \$0.00 \$0.00 \$5,805.50 (\$5,805.50)	previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment
	0590 -	Total 4 IN. WHITE WATERBORNE PAVEMENT	Overrun - To	Overrun - T	14 otal 5 5 6	Jun 16, 2021 Jun 16, 2021 Jun 17, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$300.00 \$0.00 \$0.00 \$5,805.50 (\$5,805.50)	previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment
	0590 -	Total 4 IN. WHITE WATERBORNE PAVEMENT	Overrun - To	Overrun - T	14 otal 5 5 6 6	Jun 16, 2021 Jul 1, 2021 Jul 16, 201 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$300.00 \$0.00 \$0.00 \$5,805.50 (\$5,805.50) \$5,805.50	previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate.
	0590 -	Total 4 IN. WHITE WATERBORNE PAVEMENT	Overrun - To	Overrun - T	14 5 5 6 6 7	Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$300.00 \$0.00 \$0.00 \$5,805.50 (\$5,805.50) \$5,805.50 (\$5,805.50)	previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate.
	0590 -	Total 4 IN. WHITE WATERBORNE PAVEMENT	Overrun - To	Overrun - T	14 5 5 6 6 7 7	Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$300.00 \$0.00 \$0.00 \$5,805.50 (\$5,805.50) \$5,805.50 (\$5,805.50)	previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J5S3277	0630	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material						Estimate Exception 11 on the current Payment Estimate.	
					9	Aug 16, 2021	SYSTEM	(\$5,805.50)		
					10	Sep 2, 2021	SYSTEM	\$5,805.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					10	Sep 2, 2021	SYSTEM	(\$5,805.50)		
					11	Sep 15, 2021	SYSTEM	\$5,805.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					11	Sep 15, 2021	SYSTEM	(\$5,805.50)		
					12	Oct 1, 2021	SYSTEM	\$7,256.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					12	Oct 1, 2021	SYSTEM	(\$7,256.80)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
			Other Item Adjustment	REFL	12	Oct 1, 2021	linkd1	\$349.71	See Adjustment Worksheet	
				REFL - Tota	ıl			\$349.71		
			Other Item A	djustment - Total				\$349.71		
	0630 -							\$349.71		
	0640	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		5	Jun 16, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					5	Jun 16, 2021	SYSTEM	(\$5,181.12)		
					6	Jul 1, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					6	Jul 1, 2021	SYSTEM	(\$5,181.12)		
					7	Jul 16, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					7	Jul 16, 2021	SYSTEM	(\$5,181.12)		
					8	Aug 2, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					8	Aug 2, 2021	SYSTEM	(\$5,181.12)		
					9	Aug 16, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					9	Aug 16, 2021	SYSTEM	(\$5,181.12)		
						10	Sep 2, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$5,181.12)		
					11	Sep 15, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					11	Sep 15, 2021	SYSTEM	(\$5,181.12)		
					12	Oct 1, 2021	SYSTEM	\$6,476.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					12	Oct 1, 2021	SYSTEM	(\$6,476.40)		
				- Total				\$0.00		



March Marc	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
PAVILLED Other Item Adjustment Total S100-00	J5S3277	0640		Material - To	tal				\$0.00				
Column			PAVEMENT		REFL	12		linkd1	\$308.40	See Adjustment Worksheet			
MODIFIED COLUMILIAN Applications Column Total					REFL - Tota	ıl			\$308.40				
Modern Communication Com				Other Item A	djustment - T	otal			\$308.40				
CCL DML IN		0640 -	- Total						\$308.40				
TRANSITIONS		0650	COLDMILLING		OTHR	13		linkd1	\$5,444.40	Previous entered adjustment fixed by this entry.			
Power					OTHR - Total				\$5,444.40				
Part				Other Item A	.djustment - T	otal			\$5,444.40				
A				Overrun	Overrun	4		SYSTEM	\$5,444.40	Estimate Item Adjustment (0001) due to user mcwhom1 overridding Payment			
Section Sect						4		mcwhom1	(\$5,444.40)	This overrun amount is pending change order			
						4		SYSTEM	(\$5,444.40)				
2021 SYSTEM SyA44.40 SySTEM SyA44.40 Averaged Price Adjustment from this item on all previous payment estimates of 10.0000 is applied (if non-zero).						5		SYSTEM	(\$5,444.40)				
Second S						5		SYSTEM	\$5,444.40	Estimate Item Adjustment (0001) due to user linkd1 overridding Payment			
2021 SYSTEM 2021 SYSTEM Estimate Item Adjustment (0007) due to user linked revertiding Payment Estimate.						6		SYSTEM	(\$5,444.40)				
2021 7						6		SYSTEM	\$5,444.40	Estimate Item Adjustment (0001) due to user linkd1 overridding Payment			
2021 September Setimate Item Adjustment (0001) due to user linked to verridding Payment						7		SYSTEM	(\$5,444.40)				
2021 13 Dec 2, 2021 55,444.40 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',12,00000 - 12,00000, 'is applied (if non-zero). Overrun - Total						7		SYSTEM	\$5,444.40	Estimate Item Adjustment (0001) due to user linkd1 overridding Payment			
Second S						8		SYSTEM	(\$5,444.40)				
Description						13		SYSTEM	\$5,444.40	previous payment estimates. Price Adjustments of ',12.00000 - 12.00000, 'is			
JSS3277 - Total					Overrun - T	otal			(\$5,444.40)				
J\$\$3277 - Total				Overrun - To	tal				(\$5,444.40)				
10 Sep 2, 2021 20		0650 -	- Total						\$0.00				
CRUSHED STONE (B) 2021 Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	J5S3277	- Total							\$13,976.95				
11	J5S3393	0740	CRUSHED STONE	Material		10		SYSTEM	\$4,400.40	Estimate Item Adjustment (0009) due to user linkd1 overridding Payment			
2021 Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						10		SYSTEM	(\$4,400.40)				
12									11		SYSTEM	\$4,400.40	Estimate Item Adjustment (0009) due to user linkd1 overridding Payment
Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 12 Oct 1, 2021								11		SYSTEM	(\$4,400.40)		
2021 13 Dec 2, 2021 13 Dec 3 SYSTEM (\$4,400.40) 14 Dec 4 SYSTEM (\$4,400.40) 15 Dec 5 SYSTEM (\$4,400.40) 16 Dec 7 SYSTEM (\$4,400.40) 17 This adjustment offsets the original system-generated Material Payment Estimate ltem Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 18 Dec 2, 2021 19 SYSTEM (\$4,400.40) 10 System State						12		SYSTEM	\$4,400.40	Estimate Item Adjustment (0009) due to user linkd1 overridding Payment			
2021 Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 13						12		SYSTEM	(\$4,400.40)				
2021 \$0.00 Material - Total \$0.00						13		SYSTEM	\$4,400.40	Estimate Item Adjustment (0015) due to user linkd1 overridding Payment			
Material - Total \$0.00						13		SYSTEM	(\$4,400.40)				
					- Total				\$0.00				
0740 - Total \$0.00				Material - To	tal				\$0.00				
		0740	- Total						\$0.00				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3393	0750	BITUMINOUS PAVEMENT MIXTURE	Material		8	Aug 2, 2021	SYSTEM	\$531,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		PG64-22 (SUR			8	Aug 2, 2021	SYSTEM	(\$531,360.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	ACAD	8	Aug 2, 2021	linkd1	\$34,612.20	Line 750 98401 tons +\$34612.20
					9	Aug 16, 2021	linkd1	\$12,229.73	Line 750 2948.7 tons + \$12,229.73
				ACAD - Tota	al			\$46,841.93	
			Other Item A	djustment - T	otal			\$46,841.93	
			Overrun	Overrun	9	Aug 16, 2021	SYSTEM	(\$39,187.80)	
					13	Dec 2, 2021	SYSTEM	\$39,187.80	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',54.00000 - 54.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0750 -	·Total						\$46,841.93	
	0760	TACK COAT	Material		8	Aug 2, 2021	SYSTEM	\$20,704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$20,704.00)	
					9	Aug 16, 2021	SYSTEM	\$25,978.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$25,978.00)	
					10	Sep 2, 2021	SYSTEM	\$25,978.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$25,978.00)	
					11	Sep 15, 2021	SYSTEM	\$25,978.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$25,978.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0760 -	· Total						\$0.00	
	0840	4 IN. WHITE WATERBORNE PAVEMENT	Material	aterial	9	Aug 16, 2021	SYSTEM	\$13,687.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		MARKING			9	Aug 16, 2021	SYSTEM	(\$13,687.90)	
					10	Sep 2, 2021	SYSTEM	\$13,687.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$13,687.90)	
					11	Sep 15, 2021	SYSTEM	\$13,687.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$13,687.90)	
					12	Oct 1, 2021	SYSTEM	\$13,687.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$13,687.90)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5S3393	0840	4 IN. WHITE	Material	- Total				\$0.00	
		WATERBORNE PAVEMENT	Material - To	tal				\$0.00	
		MARKING	Other Item Adjustment	REFL	12	Oct 1, 2021	linkd1	\$676.52	See Adjustment Worksheet
				REFL - Tota	ı			\$676.52	
	Other Item Adjustment - Total							\$676.52	
	0840 -	0840 - Total							
	0850	4 IN. YELLOW WATERBORNE PAVEMENT	Material		9	Aug 16, 2021	SYSTEM	\$11,408.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		MARKING			9	Aug 16, 2021	SYSTEM	(\$11,408.46)	
					10	Sep 2, 2021	SYSTEM	\$11,408.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$11,408.46)	
					11	Sep 15, 2021	SYSTEM	\$11,408.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$11,408.46)	
					12	Oct 1, 2021	SYSTEM	\$11,408.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$11,408.46)	
				- Total					
			Material - To	tal				\$0.00	
			Other Item Adjustment	REFL	12	Oct 1, 2021	linkd1	\$376.10	See Adjustment Worksheet
			REFL - Total					\$376.10	
			Other Item A	djustment - T	otal			\$376.10	
	0850 -	Total						\$376.10	
	0880	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		9	Aug 16, 2021	SYSTEM	(\$13,256.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			O a made mandia.	- Total				(\$13,256.00)	
				Stockpile - 1	otai				
							0)/07514	(\$13,256.00)	
			Construction Stockpile STMI	- Total	1	Apr 5, 2021	SYSTEM	\$13,256.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile STMI	- Total		2021	SYSTEM	\$13,256.00 \$13,256.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	0000	Total	Stockpile STMI	- Total stockpile S		2021	SYSTEM	\$13,256.00 \$13,256.00 \$13,256.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	0880 -	TYPE A CRASHWORTHY	Stockpile STMI			2021	SYSTEM	\$13,256.00 \$13,256.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
		TYPE A CRASHWORTHY END TERMINAL	Stockpile STMI Construction Construction		ГМI - Tota	2021 Aug 16,		\$13,256.00 \$13,256.00 \$13,256.00 \$0.00	
		TYPE A CRASHWORTHY	Stockpile STMI Construction Construction Stockpile	Stockpile S	ΓMI - Tota 9	2021 Aug 16,		\$13,256.00 \$13,256.00 \$13,256.00 \$0.00 (\$12,448.00)	
		TYPE A CRASHWORTHY END TERMINAL	Stockpile STMI Construction Construction Stockpile Construction Construction	Stockpile S	ΓMI - Tota 9	Aug 16, 2021		\$13,256.00 \$13,256.00 \$13,256.00 \$0.00 (\$12,448.00)	
		TYPE A CRASHWORTHY END TERMINAL	Stockpile STMI Construction Construction Stockpile Construction	Stockpile ST	FMI - Tota 9 Fotal	2021 Aug 16, 2021	SYSTEM	\$13,256.00 \$13,256.00 \$13,256.00 \$0.00 (\$12,448.00) (\$12,448.00) \$12,448.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		TYPE A CRASHWORTHY END TERMINAL	Stockpile STMI Construction Construction Stockpile Construction Construction Stockpile STMI	Stockpile ST - Total Stockpile - Total - Total	9 Fotal	Aug 16, 2021 Apr 5, 2021	SYSTEM	\$13,256.00 \$13,256.00 \$13,256.00 \$0.00 (\$12,448.00) (\$12,448.00) \$12,448.00 \$12,448.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	0890	TYPE A CRASHWORTHY END TERMINAL (MASH)	Stockpile STMI Construction Construction Stockpile Construction Construction Stockpile STMI	Stockpile ST	9 Fotal	Aug 16, 2021 Apr 5, 2021	SYSTEM	\$13,256.00 \$13,256.00 \$13,256.00 \$0.00 (\$12,448.00) (\$12,448.00) \$12,448.00 \$12,448.00 \$12,448.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		TYPE A CRASHWORTHY END TERMINAL (MASH)	Stockpile STMI Construction Construction Stockpile Construction Construction Stockpile STMI	Stockpile ST - Total Stockpile - Total - Total	9 Fotal	Aug 16, 2021 Apr 5, 2021	SYSTEM	\$13,256.00 \$13,256.00 \$13,256.00 \$0.00 (\$12,448.00) (\$12,448.00) \$12,448.00 \$12,448.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment
	0890	TYPE A CRASHWORTHY END TERMINAL (MASH)	Stockpile STMI Construction Construction Stockpile Construction Stockpile STMI Construction	Stockpile ST - Total Stockpile - Total - Total	9 Fotal 1	Aug 16, 2021 Apr 5, 2021 Jun 2, 2021 Jun 2,	SYSTEM	\$13,256.00 \$13,256.00 \$13,256.00 \$0.00 (\$12,448.00) (\$12,448.00) \$12,448.00 \$12,448.00 \$12,448.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment
	0890	TYPE A CRASHWORTHY END TERMINAL (MASH)	Stockpile STMI Construction Construction Stockpile Construction Stockpile STMI Construction	Stockpile ST - Total Stockpile - Total - Total	9 Fotal 1 FMI - Total 4	Aug 16, 2021 Apr 5, 2021 Jun 2, 2021	SYSTEM SYSTEM	\$13,256.00 \$13,256.00 \$13,256.00 \$0.00 (\$12,448.00) (\$12,448.00) \$12,448.00 \$12,448.00 \$12,448.00 \$0.00 \$93,000.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J5S3393	0900	CURB BLOCKOUT	Material		6	Jul 1, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.										
					6	Jul 1, 2021	SYSTEM	(\$93,000.00)											
					7	Jul 16, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.										
					7	Jul 16, 2021	SYSTEM	(\$93,000.00)											
					8	Aug 2, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.										
					8	Aug 2, 2021	SYSTEM	(\$93,000.00)											
					9	Aug 16, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.										
					9	Aug 16, 2021	SYSTEM	(\$93,000.00)											
					10	Sep 2, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.										
					10	Sep 2, 2021	SYSTEM	(\$93,000.00)											
					11	Sep 15, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.										
					11	Sep 15, 2021	SYSTEM	(\$93,000.00)											
							12	Oct 1, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.								
									12	Oct 1, 2021	SYSTEM	(\$93,000.00)							
																		13	Dec 2, 2021
					1	13	Dec 2, 2021	SYSTEM	(\$93,000.00)										
				- Total				\$0.00											
			Material - To	tal				\$0.00											
	0900	- Total						\$0.00											
J5S3393 -	- Total							\$47,894.55											
Overall -	Total							\$191,001.44											

MoDOT

Contract Adjustments for Contract - 210122-D02

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 26 of 26