

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2021

Progress Estimate Number	Contract ID 210122-D03	Pay Period Start August 16, 2021 Original Contract Amount \$4,125,000.00
11	Prime Contractor KCI Construction Company	Pay Period End September 1, 2021 Net Change Order Amount \$0.00
""		Current Contract Amount \$4,125,000.00

Approval Date				By User
September 2, 2021	Generated and A	approved (and should be considered	d Draft) at the Project Office Level by	lafava1
September 3, 2021	Reviewed and Appro	ved (and should be considered Dra	ft) at the Resident Engineer Level by	browns1
September 3, 2021	F	Reviewed and Approved at the Cen	tral Office Controllers Office Level by	ramses1
0-1-11-0	 0	A -to-al O - model to a D-to	0/ -5 0	

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021		52.40%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	February 3, 2021	February 3, 2021	
Letting Date	January 22, 2021	January 22, 2021	
Notice to Proceed Date	February 18, 2021	February 18, 2021	
Work Began Date			

Contract Total Pa	ay For Estimate No. 11			
		This Estimate	Previous	To Date
210122-D03				
	Total Posted Items Pay	\$301,337.11	\$1,860,157.89	\$2,161,495.00
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$1,860,157.89	\$2,161,495.00
Contract Total Pa	avable This Estimate	\$301 337 11		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3337	0170	6181000	MOBILIZATION	LS	\$1,623,609.980	0.064	\$103,911.04
	0190	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$1.000	3,999	\$3,999.00
	0200	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$1.000	3,125	\$3,125.00
	0210	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$4.000	1,181	\$4,724.00
	0220	8069901	MISC.Erosion Control	LS	\$17,000.000	1	\$17,000.00
	0240	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$132.230	42.1	\$5,566.88
	0250	7040104	HALF-SOLE REPAIR	SQFT	\$85.700	50	\$4,285.00
	0270	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	LS	\$152,928.000	0.15	\$22,939.20
	0280	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	LS	\$27,000.000	0.25	\$6,750.00
	0290	7125961	GRAY EPOXY-MASTIC PRIMER	LS	\$7,500.000	0.25	\$1,875.00
	0300	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$49.600	468	\$23,212.80
	0310	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$138.970	709.14	\$98,549.19
	0320	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	LS	\$36,000.000	0.15	\$5,400.00
Project J5	P3337 - To	tal					\$301,337.11

Revision 4/1/2020 Page 1 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2021

Progress Estimate Number
11 Contract ID 210122-D03 Pay Period Start August 16, 2021 Original Contract Amount \$4,125,000.00 Prime Contractor KCI Construction Company Pay Period End September 1, 2021 Net Change Order Amount \$0.00 Current Contract Amount \$4,125,000.00

 Project Number
 Line Number
 Item Code
 Item Description
 Unit Unit Price
 Current Installed Amount

 Overall - Total
 \$301,337.11

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

roject	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
umber	No.	nom Description	Туре	Adjustment Type	Comments	Quantity	Adjustment Unit Price	amount
P3337	0190	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-3,999	\$1.00	(\$3,999.00)
	0190	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user lafava1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	3,999	\$1.00	\$3,999.00
	0200	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-3,125	\$1.00	(\$3,125.00)
	0200	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user lafava1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	3,125	\$1.00	\$3,125.00
	0210	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-1,181	\$4.00	(\$4,724.00)
	0210	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	1,181	\$4.00	\$4,724.00
	0220	MISC.	Material			-1	\$17,000.00	(\$17,000.00
	0220	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user lafava1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	1	\$17,000.00	\$17,000.00
	0250	HALF-SOLE REPAIR	Material			-378	\$85.70	(\$32,394.60
	0250	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user lafava1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	378	\$85.70	\$32,394.60
	0290	GRAY EPOXY-MASTIC PRIMER	Material			-1	\$7,500.00	(\$7,500.00)
	0290	GRAY EPOXY-MASTIC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user lafava1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	1	\$7,500.00	\$7,500.00
	0300	OPEN CELL FOAM JOINT SEAL	Material			-468	\$49.60	(\$23,212.80)
	0300	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user lafava1 overridding Payment Estimate Exception 11	468	\$49.60	\$23,212.80

Revision 4/1/2020 Page 2 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2021

Progre	ss Esti 1	mate Number 1	Contract ID Prime Contra	210122- actor KCI Con		Pay Period Start August 16, 2021 Original Contract Amount \$4,12 npany Pay Period End September 1, 2021 Net Change Order Amount \$0.00 Current Contract Amount \$4,12						
Project Number	Line No.	Item Des	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
J5P3337						on the current Payment Estimate.						
Total									\$0.00			

Revision 4/1/2020 Page 3 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	ontract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5P3337	FAF 54-3(193)	Bridge rehabilitation	54,63	COLE	over the Missouri River		
Totals by J	Job Number	rs					
J5P3337					This Estimate	Previous	To Date
	Posted	l Item Pay			\$301,337.11	\$1,860,157.89	\$2,161,495.00
	Gross	Item Adjustme			\$0.00	\$0.00	\$0.00
			Gross	Item Pay	\$301,337.11	\$1,860,157.89	\$2,161,495.00
	Incent	ive			\$0.00	\$0.00	\$0.00
	Disinc				\$0.00	\$0.00	\$0.00
	Liquid	ated Damages			\$0.00	\$0.00	\$0.00
		Contract Adjus			\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 4 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 6205902A, Project Item Line Number 0190, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 6205902A, Project Item Line Number 0190, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 6205903A, Project Item Line Number 0200, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 6205903A, Project Item Line Number 0200, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 6205906A, Project Item Line Number 0210, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 6205906A, Project Item Line Number 0210, Material Set 6205906A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7040104, Project Item Line Number 0250, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7040104, Project Item Line Number 0250, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7040104, Project Item Line Number 0250, Material Set 704010496, Material 0704CMRP - Rapid Set Concrete Patching Material, Acceptance Action Generic 0704CMRP is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7125961, Project Item Line Number 0290, Material Set 712596196, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7172054, Project Item Line Number 0300, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 8069901, Project Item Line Number 0220, Material Set 806990196, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	lafava1: Awaiting test entry from MoDot.	lafava1	Overridden

Revision 4/1/2020 Page 5 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-D03	J5P3337	0001	0010	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$0.01	\$0.02
		0001	0020	6161005	CONSTRUCTION SIGNS	957.00	0.00	957.00	SQFT	419.00	\$8.50	\$3,561.50
		0001	0030	6161008	ADVANCED WARNING RAIL SYSTEM	5.00	0.00	5.00	EA	5.00	\$45.00	\$225.00
		0001	0040	6161009	FLAG ASSEMBLY	5.00	0.00	5.00	EA	5.00	\$25.00	\$125.00
		0001	0050	6161025	CHANNELIZER (TRIM LINE)	102.00	0.00	102.00	EA	102.00	\$20.00	\$2,040.00
		0001	0060	6161030	TYPE III MOVEABLE BARRICADE	6.00	0.00	6.00	EA	0.00	\$125.00	\$0.00
		0001	0070	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	15.00	0.00	15.00	EA	13.00	\$225.00	\$2,925.00
		0001	0080	6161033	DIRECTIONAL INDICATOR BARRICADE	30.00	0.00	30.00	EA	30.00	\$75.00	\$2,250.00
		0001	0090	6161034	DIRECTIONAL INDICATOR BARRICADE WITH LIGHT	6.00	0.00	6.00	EA	0.00	\$105.00	\$0.00
		0001	0100	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$1,000.00	\$3,000.00
		0001	0110	6161052	WARNING LIGHT, TYPE B	5.00	0.00	5.00	EA	0.00	\$95.00	\$0.00
		0001	0120	6161055	SEQUENTIAL FLASHING WARNING LIGHT	30.00	0.00	30.00	EA	0.00	\$55.00	\$0.00
		0001	0130	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	10.00	0.00	10.00	EA	7.00	\$2,200.00	\$15,400.00
		0001	0140	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	0.00	\$4,000.00	\$0.00
		0001	0150	6169901	MISC.NAVIGATIONAL TRAFFIC CONTROL	1.00	0.00	1.00	LS	1.00	\$14,650.00	\$14,650.00
		0001	0160	6169902	MISC.DETECTABLE PEDESTRIAN BARRICADE	2.00	0.00	2.00	EA	0.00	\$250.00	\$0.00
		0001	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$1,623,609.98	\$412,396.93
		0001	0180	6181010	RAILROAD ENGINEERING	1.00	0.00	1.00	LS	0.04	\$24,025.00	\$1,033.08
		0001	0190	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,999.00	0.00	3,999.00	LF	3,999.00	\$1.00	\$3,999.00
		0001	0200	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,125.00	0.00	3,125.00	LF	3,125.00	\$1.00	\$3,125.00
		0001	0210	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,181.00	0.00	1,181.00	LF	1,181.00	\$4.00	\$4,724.00
		0001	0220	8069901	MISC.Erosion Control	1.00	0.00	1.00	LS	1.00	\$17,000.00	\$17,000.00
		0070	0230	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	16,382.00	0.00	16,382.00	SQYD	16,382.00	\$30.50	\$499,651.00
		0070	0240	7040101	SUBSTRUCTURE REPAIR (FORMED)	2,000.00	0.00	2,000.00	SQFT	1,713.39	\$132.23	\$226,561.56
		0070	0250	7040104	HALF-SOLE REPAIR	1,000.00	0.00	1,000.00	SQFT	378.00	\$85.70	\$32,394.60
		0070	0260	7040110	EPOXY PRESSURE INJECTING	4,921.00	0.00	4,921.00	LF	0.00	\$29.50	\$0.00
		0070	0270	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.90	\$152,928.00	\$137,635.20
		0070	0280	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	1.00	\$27,000.00	\$27,000.00
		0070	0290	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	1.00	\$7,500.00	\$7,500.00
		0070	0300	7172054	OPEN CELL FOAM JOINT SEAL	515.00	0.00	515.00	LF	468.00	\$49.60	\$23,212.80
		0071	0310	7040101	SUBSTRUCTURE REPAIR (FORMED)	8,000.00	0.00	8,000.00	SQFT	4,955.64	\$138.97	\$688,685.29
		0071	0320	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.90	\$36,000.00	\$32,400.00
					ate as of Report Generated Date							\$2,161,494.98
210122-D03 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$2,161,494.98

Page 6 of 13 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3337

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0170	6181000	MOBILIZATION	8/27/21	9/2/21	0.06	LS		168.821		169.413		
0190	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	8/16/21	8/17/21	22.00	LF	End of Bridge to Mainstreet ramp Gore	103.437		103.454		
				8/17/21	71.00	LF	Mainstreet Ramp to Bridge	168.768		168.821		
				8/17/21	781.00	LF	Bridge A4497	168.821		169.413		
				8/17/21	3,125.00	LF	Bridge A4497	168.821		169.413		
0200	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	8/16/21	8/17/21	3,125.00	LF	Bridge A4497	168.821		169.413		
0210	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAINT	8/16/21	8/17/21	200.00	LF	End of Bridge to Rt W gore	169.413		169.451		
				8/17/21	200.00	LF	Rt 50 ramp gore east to bridge	103.509		103.454		
				8/17/21	781.00	LF	Bridge A4497 skipps	168.821		169.413		
0220	8069901	MISC. EROSION CONTROL	8/27/21	9/2/21	1.00	LS	Under bridges A4497 and L0550	168.821		169.413		
0240	7040101	SUBSTRUCTURE REPAIR (FORMED)	8/31/21	9/1/21	42.10	SQFT	enbent 1 delam areas on head wall 5 locations					
0250	7040104	HALF-SOLE REPAIR	8/30/21	9/2/21	50.00	SQFT	A4497 bridge deck	169.340				
0270	7110200	PROTECTIVE COATING - CONCRETE BENTS AND	8/27/21	9/2/21	0.15	LS	A4497 Substructure	168.821		169.413		
0280	7125102	SURF PREP FOR APPL EPOXY- MASTIC PRIMER	8/30/21	9/2/21	0.25	LS	A4497 bridge joints	168.821		169.413		
0290	7125961	GRAY EPOXY-MASTIC PRIMER	8/27/21	9/2/21	0.25	LS	A4497 joints	168.821		169.413		
0300	7172054	OPEN CELL FOAM JOINT SEAL	8/18/21	8/23/21	468.00	LF	L4, L8, L12, L16, L20, L20', L16', L12', L8', L4' manufacturer: EM Seal seal name: BEJS System					
0310	7040101	SUBSTRUCTURE REPAIR (FORMED)	8/30/21	9/2/21	43.20	SQFT	enbent 1					
				9/2/21	85.70	SQFT	Pier 2 lower parts (5 pieces)	103.437				
				9/2/21	114.14	SQFT	bent 2 second half	103.437				
				9/2/21	466.10	SQFT	Pier 3 north face of east leg(4), west leg (3), and span(2)					
0320	7110200	PROTECTIVE COATING - CONCRETE BENTS AND	8/27/21	9/2/21	0.15	LS		168.821		169.413		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 7 of 13



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3337	0010	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material		8	Jul 20, 2021	SYSTEM	\$0.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brookw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jul 20, 2021	SYSTEM	(\$0.01)	
					9	Aug 2, 2021	SYSTEM	\$0.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user lafava1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$0.02)	
					10	Aug 16, 2021	SYSTEM	\$0.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user bashoa1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$0.02)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0010 -	Total						\$0.00	
	0020	CONSTRUCTION SIGNS	Material		8	Jul 20, 2021	SYSTEM	\$3,153.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brookw1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jul 20, 2021	SYSTEM	(\$3,153.50)	
					9	Aug 2, 2021	SYSTEM	\$3,561.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lafava1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$3,561.50)	
					10	Aug 16, 2021	SYSTEM	\$3,561.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bashoa1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$3,561.50)	
				- Total				\$0.00	
			Material - Tota				\$0.00		
		Total						\$0.00	
	0030	ADVANCED WARNING RAIL SYSTEM	AIL		8	Jul 20, 2021	SYSTEM	\$225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brookw1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jul 20, 2021	SYSTEM	(\$225.00)	
					9	Aug 2, 2021	SYSTEM	\$225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$225.00)	
					10	Aug 16, 2021	SYSTEM	\$225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bashoa1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$225.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0030 -	Total						\$0.00	
	0040	FLAG ASSEMBLY	Material		8	Jul 20, 2021	SYSTEM	\$125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brookw1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Jul 20, 2021	SYSTEM	(\$125.00)	
					9	Aug 2, 2021	SYSTEM	\$125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lafava1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$125.00)	
					10	Aug 16,	SYSTEM	\$125.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J5P3337	0040	FLAG ASSEMBLY	Material			2021			Estimate Item Adjustment (0004) due to user bashoa1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					10	Aug 16, 2021	SYSTEM	(\$125.00)		
				- Total				\$0.00		
			Material - Tota	l e				\$0.00		
	0040 -	Total						\$0.00		
	0050	CHANNELIZER (TRIM LINE)	Material		8	Jul 20, 2021	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brookw1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					8	Jul 20, 2021	SYSTEM	(\$2,040.00)		
					9	Aug 2, 2021	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					9	Aug 2, 2021	SYSTEM	(\$2,040.00)		
					10	Aug 16, 2021	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bashoa1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					10	Aug 16, 2021	SYSTEM	(\$2,040.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	0050 -	Total						\$0.00		
	0070	TYPE III MOVEABLE BARRICADE WITH LIGHTS	Material		8	Jul 20, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brookw1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					8	Jul 20, 2021	SYSTEM	(\$2,700.00)		
					9	Aug 2, 2021	SYSTEM	\$2,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user lafava1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					9	Aug 2, 2021	SYSTEM	(\$2,925.00)		
					10	Aug 16, 2021	SYSTEM	\$2,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bashoa1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					10	Aug 16, 2021	SYSTEM	(\$2,925.00)		
				- Total				\$0.00		
			Material - Tota	Total				\$0.00		
	0070 -	Total						\$0.00		
	0800	DIRECTIONAL INDICATOR BARRICADE	TOR		8	Jul 20, 2021	SYSTEM	\$2,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brookw1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
						8	Jul 20, 2021	SYSTEM	(\$2,250.00)	
					9	Aug 2, 2021	SYSTEM	\$2,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user lafava1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					9	Aug 2, 2021	SYSTEM	(\$2,250.00)		
					10	Aug 16, 2021	SYSTEM	\$2,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bashoa1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					10	Aug 16, 2021	SYSTEM	(\$2,250.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	0080 -	Total						\$0.00		
	0100	FLASHING ARROW PANEL	Material		8	Jul 20, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brookw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	



Type Adjustment Number Date By	arks
Туре	
J5P3337 0100 FLASHING ARROW PANEL	
9 Aug 2, 2021 \$3,000.00 This adjustment offsets the original syste Estimate Item Adjustment (0008) due to Estimate Exception 8 on the current Pay	user lafava1 overridding Payment
9 Aug 2, 2021 (\$3,000.00)	
10 Aug 16, 2021 \$3,000.00 This adjustment offsets the original syste Estimate Item Adjustment (0008) due to Estimate Exception 8 on the current Pay	user bashoa1 overridding Payment
10 Aug 16, 2021 SYSTEM (\$3,000.00)	
- Total \$0.00	
Material - Total \$0.00	
0100 - Total \$0.00	
0130 CMS W/O COMMUNICATION INTERFACE, 8 Jul 20, 2021 \$15,400.00 This adjustment offsets the original syste Estimate Item Adjustment (0009) due to Estimate Exception 9 on the current Pay	user brookw1 overridding Payment
CONT F/ 8 Jul 20, SYSTEM (\$15,400.00)	
9 Aug 2, 2021 SYSTEM \$15,400.00 This adjustment offsets the original syste Estimate Item Adjustment (0009) due to Estimate Exception 9 on the current Pay	user lafava1 overridding Payment
9 Aug 2, 2021 (\$15,400.00)	
10 Aug 16, SYSTEM \$15,400.00 This adjustment offsets the original syste 2021 Estimate Item Adjustment (0009) due to	user bashoa1 overridding Payment
Estimate Exception 9 on the current Pay	
Estimate Exception 9 on the current Pay 10 Aug 16, 2021 (\$15,400.00)	
10 Aug 16, SYSTEM (\$15,400.00)	
10 Aug 16, SYSTEM (\$15,400.00)	
10 Aug 16, 2021 SYSTEM (\$15,400.00) - Total \$0.00	
10 Aug 16, 2021 SYSTEM (\$15,400.00) - Total \$0.00 Material - Total \$0.00	user lafava1 overridding Payment
10 Aug 16, 2021 \$YSTEM (\$15,400.00)	user lafava1 overridding Payment
10 Aug 16, 2021 \$15,400.00	user lafava1 overridding Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment
10 Aug 16, 2021 \$YSTEM (\$15,400.00)	user lafava1 overridding Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment
10 Aug 16, 2021 \$9.00	em-generated Material Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment user lafava1 overridding Payment
10 Aug 16, 2021 \$15,400.00	em-generated Material Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment user lafava1 overridding Payment
10	em-generated Material Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment user lafava1 overridding Payment
10	em-generated Material Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment user lafava1 overridding Payment
10	em-generated Material Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment yment Estimate. em-generated Material Payment user lafava1 overridding Payment user lafava1 overridding Payment
10	em-generated Material Payment yment Estimate.
10	em-generated Material Payment yment Estimate.
10	em-generated Material Payment yment Estimate.
10	em-generated Material Payment yment Estimate.
10	em-generated Material Payment yment Estimate.
10	em-generated Material Payment user lafava1 overridding Payment viser lafava1 overridding Payment viser lafava1 overridding Payment viser lafava1 overridding Payment user lafava1 overridding Payment viser lafava1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3337	0200	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material	- Total				\$0.00	
			Material - Tota					\$0.00	
	0200 -							\$0.00	
	0210		Material		11	Sep 2, 2021	SYSTEM	\$4,724.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$4,724.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0210 -	Total						\$0.00	
	0220	MISC. EROSION CONTROL	Material		11	Sep 2, 2021	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lafava1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$17,000.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0220 -	Total						\$0.00	
	0240	REPAIR	IR		1	Apr 2, 2021	SYSTEM	(\$14,867.94)	
		(FORMED)			2	Apr 16, 2021	SYSTEM	(\$17,328.74)	
					3	May 3, 2021	SYSTEM	\$17,328.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lafava1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 3, 2021	SYSTEM	(\$17,328.74)	
					4	May 17, 2021	SYSTEM	\$71,888.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user lafava1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$71,888.16)	
					5	Jun 1, 2021	SYSTEM	\$112,969.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lafava1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jun 1, 2021	SYSTEM	(\$112,969.38)	
					6	Jun 17, 2021	SYSTEM	\$164,151.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lafava1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$164,151.64)	
						7	Jun 30, 2021	SYSTEM	\$210,436.11
					7	Jun 30, 2021	SYSTEM	(\$210,436.11)	
				- Total				(\$32,196.68)	
			Material - Total					(\$32,196.68)	
			MaterialCredit		2	Apr 16, 2021	SYSTEM	\$14,867.94	
					3	May 3, 2021	SYSTEM	\$17,328.74	
				- Total				\$32,196.68	
			MaterialCredit	- Total				\$32,196.68	
			Other Item	PPPS	1	Apr 2,	lafava1	\$14,867.94	lafava1: tests to be entered at a later date
			Adjustment		2	2021 Apr 16, 2021	lafava1	\$2,460.80	lafava1: Tests to be entered at later date
					3	May 3,	lafava1	(\$17,328.74)	lafava1: Zeroed-out PPPS adjustments on Estimates 1 & 2 and began
						2021			overriding exceptions on Estimate 3.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3337	0240	REPAIR	Other Item Adjustment	PPPS - Tota	ı			\$0.00	
		(FORMED)	Other Item Ad	justment - To	tal			\$0.00	
	0240 -	Total						\$0.00	
	0250	HALF-SOLE REPAIR	Material		9	Aug 2, 2021	SYSTEM	\$28,109.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user lafava1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$28,109.60)	
					10	Aug 16, 2021	SYSTEM	\$28,109.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bashoa1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$28,109.60)	
					11	Sep 2, 2021	SYSTEM	\$32,394.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lafava1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$32,394.60)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0250 -	Total						\$0.00	
	0270	PROTECTIVE COATING - CONCRETE BENTS AND	Material		7	Jun 30, 2021	SYSTEM	\$76,464.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Jun 30, 2021	SYSTEM	(\$76,464.00)	
				- Total	- Total			\$0.00	
			Material - Tota	ı				\$0.00	
	0270 -	Total						\$0.00	
	0290	GRAY EPOXY- MASTIC PRIMER			8	Jul 20, 2021	SYSTEM	\$5,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brookw1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Jul 20, 2021	SYSTEM	(\$5,625.00)	
					9	Aug 2, 2021	SYSTEM	\$5,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user lafava1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$5,625.00)	
					10	Aug 16, 2021	SYSTEM	\$5,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bashoa1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$5,625.00)	
					11	Sep 2, 2021	SYSTEM	\$7,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user lafava1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$7,500.00)	
				- Total				\$0.00	
	Material - Total							\$0.00	
	0290 -				44	0 1	0)/0=	\$0.00	
	0300	OPEN CELL FOAM JOINT SEAL	Material		11	Sep 2, 2021	SYSTEM	\$23,212.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user lafava1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$23,212.80)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0300 -						0)/0==:	\$0.00	
	0310	SUBSTRUCTURE REPAIR (FORMED)	Material		2	Apr 16, 2021	SYSTEM	(\$43,159.91)	



SP3337 0310 SUSTRICTURE Makind	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
2021 4	J5P3337	0310	REPAIR	Material	,,,	3		SYSTEM	\$155,599.15	Estimate Item Adjustment (0004) due to user lafava1 overridding Payment	
A						3		SYSTEM	(\$155,599.15)		
2021 2021						4		SYSTEM	\$191,750.81	Estimate Item Adjustment (0002) due to user lafava1 overridding Payment	
2021 2021							4		SYSTEM	(\$191,750.81)	
2021 2021							5		SYSTEM	\$214,243.10	Estimate Item Adjustment (0003) due to user lafava1 overridding Payment
6						5		SYSTEM	(\$214,243.10)		
6 Jun 16 SySTEM S247,815,47 2021 SySTEM S289,175,72 This adjustment diffects the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate SySTEM S289,175,72 This adjustment (5004) due to use inflowed overridding Payment Estimate Exception 8 on the current Payment Estimate. SySTEM S289,175,72 SySTEM SyST						6	Jun 17,	SYSTEM	\$247,815.47	Estimate Item Adjustment (0003) due to user lafava1 overridding Payment	
Total						6		SYSTEM	(\$247,815.47)	Estimate Exception 3 on the current rayment Estimate.	
Total						7	Jun 30,	SYSTEM	\$289,175.72	Estimate Item Adjustment (0004) due to user lafava1 overridding Payment	
Material - Total S43,159.91						7		SYSTEM	(\$289,175.72)		
MaterialCredit 3 May 3, SYSTEM \$43,159.91					- Total				(\$43,159.91)		
Section Sect				Material - Tota	l				(\$43,159.91)		
Material Credit - Total S43,159.91 Iafava1				MaterialCredit		3		SYSTEM	\$43,159.91		
Other Item Adjustment PPPS 2 Apr 16, Iafavat \$43,159.91 Iafavat : Tests to be entered at later date				MaterialCredit	- Total				\$43,159.91		
Adjustment 2021 3 May 3, Iafava1 (\$43,159.91) Iafava1: Zeroed-out PPPS adjustments on Estimate 2 and began overriding exceptions on Estimate 3.					- Total				\$43,159.91		
2021 S0.00					PPPS	2		lafava1	\$43,159.91	lafava1: Tests to be entered at later date	
Other Item Adjustment - Total \$0.00						3		lafava1	(\$43,159.91)		
0320 PROTECTIVE COATING - CONCRETE BENTS AND 4					PPPS - Tota	ıl			\$0.00		
D320 PROTECTIVE COATING - CONCRETE BENTS AND				Other Item Ad	justment - To	tal			\$0.00		
COATING-CONCRETE BENTS AND		0310 -	Total						\$0.00		
4		0320	COATING - CONCRETE			4		SYSTEM	\$3,600.00	Estimate Item Adjustment (0003) due to user lafava1 overridding Payment	
2021 System Estimate Item Adjustment (0004) due to user lafava1 overridding Payment			DENTO AND			4		SYSTEM	(\$3,600.00)		
2021						5		SYSTEM	\$7,200.00	Estimate Item Adjustment (0004) due to user lafava1 overridding Payment	
2021 Estimate Item Adjustment (0004) dué to user lafava1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							5		SYSTEM	(\$7,200.00)	
2021 7						6		SYSTEM	\$7,200.00	Estimate Item Adjustment (0004) due to user lafava1 overridding Payment	
2021 Estimate Item Adjustment (0005) due to user lafava1 overridding Payment Estimate Exception 11 on the current Payment Estimate. 7						6		SYSTEM	(\$7,200.00)		
2021						7		SYSTEM	\$18,000.00	Estimate Item Adjustment (0005) due to user lafava1 overridding Payment	
Material - Total \$0.00						7		SYSTEM	(\$18,000.00)		
0320 - Total \$0.00 J5P3337 - Total \$0.00					- Total				\$0.00		
J5P3337 - Total \$0.00				Material - Tota	l e				\$0.00		
		0320 -	Total						\$0.00		
Overall - Total \$0.00	J5P3337 -	Total							\$0.00		
	Overall -	Total							\$0.00		