

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 1, 2021

Progress Estimate Number 5 Contract ID 210122-D03 Prime Contractor KCI Construction Compa	Pay Period StartMay 16, 2021Original Contract Amount\$4,125,Pay Period EndJune 1, 2021Net Change Order Amount\$0.00Current Contract Amount\$4,125,	
---	--	--

By User		Approval Date
el by browns1	Generated and Approved (and should be considered Draft) at the Project Office Level by	June 4, 2021
el by browns1	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	June 4, 2021
el by greggd1	Reviewed and Approved at the Central Office Controllers Office Level by	June 4, 2021

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021		13.49%

	Milestones					
Date Description	Original Completion Date	No Milestones Exist for Contract				
Acceptance Date						
Awarded Date	February 3, 2021	February 3, 2021				
Letting Date	January 22, 2021	January 22, 2021				
Notice to Proceed Date	February 18, 2021	February 18, 2021				
Work Began Date						

Contract Total Pay For Estimate No. 5										
		This Estimate	Previous	To Date						
210122-D03										
	Total Posted Items Pay	\$185,734.55	\$370,559.48	\$556,294.03						
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	•		\$370,559.48	\$556,294.03						
Contract Total Pa	yable This Estimate:	\$185,734.55								

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J5P3337	0150	6169901	MISC.NAVIGATIONAL TRAFFIC CONTROL	DNAL TRAFFIC CONTROL LS \$14,650.000				
	0170	6181000	MOBILIZATION	LS	\$1,623,609.980	0.064	\$103,911.04	
	0240	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$132.230	310.68	\$41,081.22	
	0310	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$138.970	161.85	\$22,492.29	
	0320	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	LS	\$36,000.000	0.1	\$3,600.00	
Project J5P3	337 - Total						\$185,734.55	
Overall - Tot	al						\$185,734.55	

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate					
Project Number	Line No.	Item Description	Adjustment Type	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J5P3337	0150	MISC.	Material		-1	\$14,650.00	(\$14,650.00)
	0150	MISC.	Material	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user lafava1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1	\$14,650.00	\$14,650.00
	0240	SUBSTRUCTURE REPAIR (FORMED)	Material		-854.34	\$132.23	(\$112,969.38)
	0240	SUBSTRUCTURE REPAIR (FORMED)	Material	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user lafava1	854.34	\$132.23	\$112,969.38

Revision 4/1/2020 Page 1 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 1, 2021

Progress Estimate Number 5 Contract ID 210122-D03 Pay Period Start Pay Period End June 1, 2021 Original Contract Amount \$4,125,000.00 \$0.0

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3337				overridding Payment Estimate Exception 2 on the current Payment Estimate.				
	0310	SUBSTRUCTURE REPAIR (FORMED)	Material			-1,541.65	\$138.97	(\$214,243.10)
	0310	SUBSTRUCTURE REPAIR (FORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	1,541.65	\$138.97	\$214,243.10
	0320	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material			-0.2	\$36,000.00	(\$7,200.00)
	0320	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user lafava1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	0.2	\$36,000.00	\$7,200.00
Total								\$0.00

Revision 4/1/2020 Page 2 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	Contract Project Informati	on				
Project Number											
J5P3337	FAF 54-3(193)	Bridge rehabilitation	54,63	COLE	over the Missouri River						
Totals by .	Job Numbe	rs									
J5P3337		d Item Pay Item Adjustme		Item Pay	This Estimate \$185,734.55 \$0.00 \$185,734.55	Previous \$370,559.48 \$0.00 \$370,559.48	To Date \$556,294.03 \$0.00 \$556,294.03				
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 4/1/2020 Page 3 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 6169901, Project Item Line Number 0150, Material Set 6169901, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	lafava1: Waiting for Materials Division to correct sampling checklist	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7040101, Project Item Line Number 0240, Material Set 704010196, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	lafava1: Awaiting test entry from Materials Division	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7040101, Project Item Line Number 0240, Material Set 704010196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	lafava1: Awaiting test entry from Materials Division	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7040101, Project Item Line Number 0240, Material Set 704010196, Material 0704CMRP - Rapid Set Concrete Patching Material, Acceptance Action Generic 0704CMRP is insufficient.	lafava1: Awaiting test entry from Materials Division	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7040101, Project Item Line Number 0310, Material Set 704010196, Material 0704CMRP - Rapid Set Concrete Patching Material, Acceptance Action Generic 0704CMRP is insufficient.	lafava1: Awaiting test entry from Materials Division	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7040101, Project Item Line Number 0310, Material Set 704010196, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	lafava1: Awaiting 28 day strength test results	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7040101, Project Item Line Number 0310, Material Set 704010196, Material 0501CCSPEC - Concrete, Special, misc. or unusual use, Acceptance Action Generic 0501CCSPEC is insufficient.	lafava1: Awaiting test entry from Materials Division	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7040101, Project Item Line Number 0310, Material Set 704010196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	lafava1: Awaiting test entry from Materials Division	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7040101, Project Item Line Number 0310, Material Set 704010196, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	lafava1: Awaiting test entry from Materials Division	lafava1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3337, Item 7110200, Project Item Line Number 0320, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	lafava1: Awaiting test entry. Product data sheet on file.	lafava1	Overridden

Revision 4/1/2020 Page 4 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bid Net Total Unit Total

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-D03	J5P3337	0001	0010	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$0.01	\$0.00
		0001	0020	6161005	CONSTRUCTION SIGNS	957.00	0.00	957.00	SQFT	0.00	\$8.50	\$0.00
		0001	0030	6161008	ADVANCED WARNING RAIL SYSTEM	5.00	0.00	5.00	EA	0.00	\$45.00	\$0.00
		0001	0040	6161009	FLAG ASSEMBLY	5.00	0.00	5.00	EA	0.00	\$25.00	\$0.00
		0001	0050	6161025	CHANNELIZER (TRIM LINE)	102.00	0.00	102.00	EA	0.00	\$20.00	\$0.00
		0001	0060	6161030	TYPE III MOVEABLE BARRICADE	6.00	0.00	6.00	EA	0.00	\$125.00	\$0.00
		0001	0070	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	15.00	0.00	15.00	EA	0.00	\$225.00	\$0.00
		0001	0080	6161033	DIRECTIONAL INDICATOR BARRICADE	30.00	0.00	30.00	EA	0.00	\$75.00	\$0.00
		0001	0090	6161034	DIRECTIONAL INDICATOR BARRICADE WITH LIGHT	6.00	0.00	6.00	EA	0.00	\$105.00	\$0.00
		0001	0100	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.00
		0001	0110	6161052	WARNING LIGHT, TYPE B	5.00	0.00	5.00	EA	0.00	\$95.00	\$0.00
		0001	0120	6161055	SEQUENTIAL FLASHING WARNING LIGHT	30.00	0.00	30.00	EA	0.00	\$55.00	\$0.00
		0001 013		6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	10.00	0.00	10.00	EA	0.00	\$2,200.00	\$0.00
		0001	0140	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	0.00	\$4,000.00	\$0.00
		0001	0150	6169901	MISC.NAVIGATIONAL TRAFFIC CONTROL	1.00	0.00	1.00	LS	1.00	\$14,650.00	\$14,650.00
		0001	0160	6169902	MISC.DETECTABLE PEDESTRIAN BARRICADE	2.00	0.00	2.00	EA	0.00	\$250.00	\$0.00
		0001	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.13	\$1,623,609.98	\$206,198.47
		0001	0180	6181010	RAILROAD ENGINEERING	1.00	0.00	1.00	LS	0.04	\$24,025.00	\$1,033.08
		0001	0190	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,999.00	0.00	3,999.00	LF	0.00	\$1.00	\$0.00
		0001	0200	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,125.00	0.00	3,125.00	LF	0.00	\$1.00	\$0.00
		0001	0210	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,181.00	0.00	1,181.00	LF	0.00	\$4.00	\$0.00
		0001	0220	8069901	MISC.Erosion Control	1.00	0.00	1.00	LS	0.00	\$17,000.00	\$0.00
		0070	0230	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER/SEALER	16,382.00	0.00	16,382.00	SQYD	0.00	\$30.50	\$0.00
		0070	0240	7040101	SUBSTRUCTURE REPAIR (FORMED)	2,000.00	0.00	2,000.00	SQFT	854.34	\$132.23	\$112,969.38
		0070	0250	7040104	HALF-SOLE REPAIR	1,000.00	0.00	1,000.00	SQFT	0.00	\$85.70	\$0.00
		0070	0260	7040110	EPOXY PRESSURE INJECTING	4,921.00	0.00	4,921.00	LF	0.00	\$29.50	\$0.00
		0070	0270	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$152,928.00	\$0.00
		0070	0280	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$27,000.00	\$0.00
		0070	0290	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$7,500.00	\$0.00
		0070	0300	7172054	OPEN CELL FOAM JOINT SEAL	515.00	0.00	515.00	LF	0.00	\$49.60	\$0.00
		0071	0310	7040101	SUBSTRUCTURE REPAIR (FORMED)	8,000.00	0.00	8,000.00	SQFT	1,541.65	\$138.97	\$214,243.10
		0071	0320	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.20	\$36,000.00	\$7,200.00
	Project J5P3337 - Total Value Posted to Date as of Report Generated Date											\$556,294.02
0122-D03 Ove	erall - Total	Value Pos	ted to Dat	te as of Rep	ort Generated Date							\$556,294.02

Revision 4/1/2020 Page 5 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3337

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0150	6169901	MISC.	6/1/21	6/1/21	1.00	LS	Missouri River under A4497/L0550	102.390		102.976		
0170	6181000	MOBILIZATION	6/1/21	6/1/21	0.06	LS		102.390		102.976		
0240	7040101	SUBSTRUCTURE REPAIR (FORMED)	6/1/21	6/1/21	310.68	SQFT	A4497 Pier 6 web face and Bent 18 beam.	169.413		168.821		
0310	7040101	SUBSTRUCTURE REPAIR (FORMED)	6/1/21	6/1/21	161.85	SQFT		102.390		102.976		
0320	7110200	PROTECTIVE COATING - CONCRETE BENTS AND	6/1/21	6/1/21	0.10	LS	L0550 various bent caps	102.390		102.976		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 8



Line Item Adjustments by Estimate

Contract ID:190621-F01

Marcial Part	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Total 10.00	J5P3337	0150	MISC.	Material		5		SYSTEM	\$14,650.00	Estimate Item Adjustment (0001) due to user lafava1 overridding Payment
Total						5		SYSTEM	(\$14,650.00)	
1					- Total				\$0.00	
SUBSTRUCTURE REPAIR REPA				Material - Tota					\$0.00	
2		0150 -	Total						\$0.00	
2 Apr 16, SYSTEM SYSTE		0240	REPAIR	Material		1		SYSTEM	(\$14,867.94)	
September Part Pa						2		SYSTEM	(\$17,328.74)	
Algorithms						3		SYSTEM	\$17,328.74	Estimate Item Adjustment (0002) due to user lafava1 overridding Payment
4						3		SYSTEM	(\$17,328.74)	Estimate Exception 1 on the current Payment Estimate.
2021 SYSTEM ST12,888.19						4		CVCTEM	¢74 000 46	This adjustment effects the aviginal system generated Material Dayment
2021 SYSTEM S112,990 38 This adjustment offsets the original system-generated Material Payment Estimate Estimate Exception 2 on the current Payment Estimate Estimate Estimate Exception 2 on the current Payment Estimate Estimate Estimate Exception 2 on the current Payment Estimate.						4		STSTEIN	\$71,000.10	Estimate Item Adjustment (0001) due to user lafava1 overridding Payment
2021 Eathmate Item Adjustment (1002) due to user lafavard overridding Payment Estimate Estroape Exception 2 on the current Payment Estimate Estimate Exception 3 on the current Payment Estimate (1976) and 1976 (1976) a						4		SYSTEM	(\$71,888.16)	
Total (\$32,196.68)						5		SYSTEM	\$112,969.38	Estimate Item Adjustment (0002) due to user lafava1 overridding Payment
Material - Total						5		SYSTEM	(\$112,969.38)	
MaterialCredit					- Total				(\$32,196.68)	
2021 3 May 3 2021 3 May 3 2021 3 May 3 2021 2 Apr 16 2021 3 May 3 2021 3				Material - Total					(\$32,196.68)	
Company						2		SYSTEM	\$14,867.94	
MaterialCredit - Total						3		SYSTEM	\$17,328.74	
Other Item Adjustment					- Total				\$32,196.68	
Adjustment				MaterialCredit	- Total				\$32,196.68	
2021 3 May 3, 2021 5 1 1 1 1 1 1 1 1					PPPS	1		lafava1	\$14,867.94	lafava1: tests to be entered at a later date
PPPS - Total Other Item Adjustment - Total SUBSTRUCTURE REPAIR (FORMED) Material Amay 17, 2YSTEM 2021 Amy 17, 2YSTEM 2021 Amy 17, 2YSTEM 2021 SUBSTRUCTURE Estimate Item Adjustment (0002) due to user lafavar overridding Payment Estimate Exception 5 on the current Payment Estimate. Amy 17, 2YSTEM (\$191,750.81) Amy 17, 2YSTEM (\$191,750.81) SUBSTRUCTURE REPAIR (FORMED) Material Amy 17, 2YSTEM 2191,750.81 Amy 3, 3YSTEM 2021 Amy 17, 3YSTEM 2021 Amy 18, 3May 3, 3						2		lafava1	\$2,460.80	lafava1: Tests to be entered at later date
Other Item Adjustment - Total S0.00						3		lafava1	(\$17,328.74)	
SUBSTRUCTURE REPAIR (FORMED)					PPPS - Tota	ıl			\$0.00	
SUBSTRUCTURE REPAIR (FORMED) Material REPAIR (FORMED) Material REPAIR (FORMED) Material REPAIR (FORMED) SYSTEM SYST				Other Item Ad	Other Item Adjustment - Total					
(FORMED) 3			SUBSTRUCTURE REPAIR	Material		2		SYSTEM		
3 May 3, 2021 SYSTEM (\$155,599.15) 4 May 17, 2021 SYSTEM \$191,750.81 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 May 17, 2021 SYSTEM (\$191,750.81) 5 Jun 1, 2021 SYSTEM \$214,243.10 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Jun 1, 2021 (\$43,159.91)						3	May 3,	SYSTEM	\$155,599.15	
4 May 17, 2021 \$YSTEM \$191,750.81 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 May 17, 2021 \$YSTEM \$191,750.81 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Jun 1, 2021 \$YSTEM \$214,243.10 \$YSTEM \$214,24						3		SYSTEM	(\$155,599.15)	Estimate Exception 5 on the current Payment Estimate.
Estimate Item Adjustment (0002) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 May 17, 2021 5 Jun 1, 2021 SYSTEM (\$191,750.81) 2021 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Jun 1, 2021 SYSTEM (\$214,243.10) - Total (\$43,159.91)						1		SYSTEM	\$101 750 Q1	This adjustment offsate the original system generated Material Dayment
5 Jun 1, 2021 5 Jun 1, 2021 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Jun 1, 2021 (\$43,159.91)						4		STSTEW	\$191,750.61	Estimate Item Adjustment (0002) due to user lafava1 overridding Payment
Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Jun 1, 2021 (\$214,243.10) - Total (\$43,159.91)						4		SYSTEM	(\$191,750.81)	
- Total (\$43,159.91)						5		SYSTEM	\$214,243.10	Estimate Item Adjustment (0003) due to user lafava1 overridding Payment
						5		SYSTEM	(\$214,243.10)	
Material - Total (\$43,159.91)					- Total				(\$43,159.91)	
				Material - Tota	ıl				(\$43,159.91)	

Jun 4, 2021



Line Item Adjustments by Estimate

Contract ID:190621-F01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3337	0310	SUBSTRUCTURE REPAIR (FORMED)	MaterialCredit		3	May 3, 2021	SYSTEM	\$43,159.91	
				- Total				\$43,159.91	
			MaterialCredit - Total					\$43,159.91	
			Other Item Adjustment	PPPS	2	Apr 16, 2021	lafava1	\$43,159.91	lafava1: Tests to be entered at later date
					3	May 3, 2021	lafava1	(\$43,159.91)	lafava1: Zeroed-out PPPS adjustments on Estimate 2 and began overriding exceptions on Estimate 3.
				PPPS - Total				\$0.00	
			Other Item Adjustment - Total					\$0.00	
	0310 - Total							\$0.00	
	0320	PROTECTIVE COATING - CONCRETE BENTS AND	Material		4	May 17, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$3,600.00)	
					5	Jun 1, 2021	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lafava1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Jun 1,	SYSTEM	(\$7,200.00)	
					3	2021		(++,=++++)	
				- Total	3			\$0.00	
			Material - Tota		3			, ,	
	0320 -	- Total	Material - Tota		3			\$0.00	
J5P3337 -		- Total	Material - Tota					\$0.00 \$0.00	