

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2021

Progress Estimate Number	Contract ID	ontract ID 210122-H05 Pay Period September 16, Start 2021			Original Contract Amount \$2,798,7		
11	Prime Contractor	N.B. West Contracting Company	Pay Period End	September 30, 2021	Net Change Order Amount Current Contract Amount	\$40,233.75 \$2,838,959.86	

Approval Date		By User
October 1, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	REEDV1
October 1, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	dowdyd
October 4, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete				
September 30, 2021	September 30, 2021		92.85%				

	Milestones		
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	February 3, 2021	February 3, 2021	
Letting Date	January 22, 2021	January 22, 2021	
Notice to Proceed Date	April 5, 2021	April 5, 2021	
Work Began Date	April 13, 2021	April 13, 2021	

Contract Total Pay For Estimate No. 11										
		This Estimate	Previous	To Date						
210122-H05										
	Total Posted Items Pay	\$195,551.23	\$2,440,377.70	\$2,635,928.93						
	Gross Item Adjustments	\$25,499.71	\$68,489.91	\$93,989.62						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	·		\$2,508,867.61	\$2,729,918.55						
Contract Total Par	yable This Estimate:	\$221,050,94								

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount				
J9S3340	0030	2129900	MISC.MISC. SHOULDER GRADING	100F	\$298.500	374.1	\$111,668.85				
	0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$58.500	473.25	\$27,685.13				
	0800	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$49.700	83.99	\$4,174.30				
	0140	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	EA	\$500.000	2	\$1,000.00				
	0150	6161005	CONSTRUCTION SIGNS	SQFT	\$6.500	1,030	\$6,695.00				
	0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$4.500	41.1	\$184.95				
	0320	8051000A	SEEDING - COOL SEASON MIXTURES	ACRE	\$2,000.000	22	\$44,000.00				
	0360	8061016	SEDIMENT REMOVAL	CUYD	\$2.000	71.5	\$143.00				
Project J9S3	Project J9S3340 - Total										
Overall - Tot	Overall - Total										

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3340	0050	GRAVEL (A) OR CRUSHED STONE (B)	Overrun			-337.53	\$58.50	(\$19,745.51)
	0050	GRAVEL (A) OR CRUSHED STONE (B)	Overrun			-135.72	\$58.50	(\$7,939.62)

Revision 4/1/2020 Page 1 of 14



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2021

Pay Period September 16, **Progress Estimate** Original Contract Amount \$2,798,726.11 **Contract ID** 210122-H05 Number Start 2021 Pay Period End September 30, 2021 Prime N.B. West Contracting **Net Change Order** 11 \$40,233.75 Amount \$40,233.75

Current Contract Amount \$2,838,959.86 Contractor Company

ne Item	n Description	Adjustment Type	Other Item Adjustment	Comments	Adjustment Quantity	Line Item Adjustment	Adjustment amount
50 GRAVEL	(A) OR CRUSHED	Overrun	Туре	This adjustment offsets the original system-	337.53	Unit Price \$58.50	\$19,745.51
30 GIAVEE	STONE (B)	Ovenun		generated Overrun Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	337.33	ψ30.30	\$19,740.01
GRAVEL	(A) OR CRUSHED STONE (B)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user reedv1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	135.72	\$58.50	\$7,939.62
75	MISC.	Material			-1,759.31	\$47.10	(\$82,863.50
75	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,759.31	\$47.10	\$82,863.50
N	NOUS PAVEMENT MIXTURE PG64-22 RFACE LEVELING)	Other Item Adjustment	Asphalt Cement Price Adjustment	This adjustment is for the 83.99 tons of SL21-10 mix laid on September 16th 2021, the base factor was 395 and the current index was 495 for a dilfference of 100, the virgin AC was 4.0% 10/01/2021 Estimate 011			\$335.96
50 CLAS	SS B-1 CONCRETE (CULVERTS)	Material			-2.8	\$4,450.00	(\$12,460.00
50 CLAS	SS B-1 CONCRETE (CULVERTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	2.8	\$4,450.00	\$12,460.00
70 15	IN. PIPE GROUP B	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',107.00000 - 107.00000, 'is applied (if non-zero).	184	\$107.00	\$19,688.00
80 18 II	IN. PIPE GROUP B	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',111.75000 - 111.75000, 'is applied (if non-zero).	49	\$111.75	\$5,475.75
20 SEEDING	G - COOL SEASON MIXTURES	Material			-22	\$2,000.00	(\$44,000.00
20 SEEDING	G - COOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	22	\$2,000.00	\$44,000.00
				overridding Payment Estimate Exception 3 on			

Revision 4/1/2020 Page 2 of 14



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ntract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9S3340	FAS S702(59)	Pavement and shoulder improvements	J	MADISON	from Rte. 72 to Rte. 51		
Γotals by .	Job Numbe	rs					
J9S3340		d Item Pay Item Adjustme		Item Pay	This Estimate \$195,551.23 \$25,499.71 <b>\$221,050.94</b>	<b>Previous</b> \$2,440,377.70 \$68,489.91 <b>\$2,508,867.61</b>	To Date \$2,635,928.93 \$93,989.62 \$2,729,918.55
		entive		•	\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
		lated Damages Contract Adjus	tments		\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00

Revision 4/1/2020 Page 3 of 14



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3340, Item 4019910, Project Item Line Number 0075, Material Set 401991096, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	This exception is due to MoDOT RAP testing not being completed and reported in AASHTOWARE	REEDV1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3340, Item 7034041, Project Item Line Number 0250, Material Set 703404196, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	This exception is due to a sample from the testing company being unauthorized. MoDOT is working with SCI Engineering to get the sample re-authorized.	REEDV1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3340, Item 8051000A, Project Item Line Number 0320, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Waiting on the tickets for the Agricultural Lime from the contractor, this will be resolved by the next estimate.	REEDV1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3340, Item 8051000A, Project Item Line Number 0320, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Waiting on the tickets for the Slick Paper Overspray from the contractor, this will be resolved by the next estimate.	REEDV1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3340, Item 8051000A, Project Item Line Number 0320, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Waiting on the tickets for the Straw Mulch from the contractor, this will be resolved by the next estimate.	REEDV1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3340, Item 8051000A, Project Item Line Number 0320, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Waiting on the tickets for the Seed from the contractor, this will be resolved by the next estimate.	REEDV1	Overridden
Estimate Exception Type: Item Overrun: Contract 210122-H05, Contract Project J9S3340, Project Item Line Number 0050, Contract Line Item Number 0050, Item 3105002, Minor Item.	This exception is due to an overrun in the quantity for the aggregate driveways not accounted for in the original plans. Change order #3 will address these quantities.	REEDV1	Overridden
Estimate Exception Type: Item Overrun: Contract 210122-H05, Contract Project J9S3340, Project Item Line Number 0225, Contract Line Item Number 0225, Item 6214600A, Minor Item.	This exception is due to an overrun in the quantity for the Flowable Backfill not accounted for in the original plans. Change order #3 will address these quantities.	REEDV1	Overridden
Estimate Exception Type: Item Overrun: Contract 210122-H05, Contract Project J9S3340, Project Item Line Number 0340, Contract Line Item Number 0340, Item 8061005, Minor Item.	This exception is due to an overrun in the quantity for the Rock Ditch Check not accounted for in the original plans. Change order #3 will address these quantities.	REEDV1	Overridden

Revision 4/1/2020 Page 4 of 14



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Professional Pro						eport Generated date and can differ from the posted amo						Helt Billion	T. L. IV. L. DOOTED
Control   Cont	Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity			Unit	Approved	Unit Price	
MINISTER	210122-H05	J9S3340	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$32,650.00	\$31,017.50
			0001	0020	2063500	CULVERT CLEANOUT	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.00
Math			0001	0030	2129900	MISC.MISC. SHOULDER GRADING	1,873.00	0.00	1,873.00	100F	1,873.00	\$298.50	\$559,090.50
1000   1000			0001	0040	3049907	MISC.TYPE 1 AGGREGATE FOR BASE	210.00	0.00	210.00	CUYD	164.40	\$25.50	\$4,192.20
Column   C			0001	0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	194.00	0.00	194.00	TONS	703.81	\$58.50	\$41,172.88
			0001	0060	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	93.70	0.00	93.70	TONS	76.00	\$201.25	\$15,295.00
			0001	0075	4019910	MISC.OPTIONAL SHOULDER	10,802.90	0.00	10,802.90	TONS	10,759.31	\$47.10	\$506,763.50
MACHINE   MACH			0001	0080	4020520		17,460.10	0.00	17,460.10	TONS	17,438.20	\$49.70	\$866,678.54
1001   055			0001	0090	4071005		21,212.00	0.00	21,212.00	GAL	16,017.00	\$1.97	\$31,553.49
0001   0100   0000100   PURNISHING TYPE 1 ROCK DITCH LINER   200.00   0.00   200.00   CUTD   25.00   531.00   13771.00   0001   0110   0000000   1710   0000000   1710   0000000   1710   0000000   1710   0000000   1710   0000000   1710   0000000   1710   1710   00000000   1710   1710   0000000   1710   1710   0000000000								-1.00		EA			
CODE   CODE   CODE   PLACEMENT TYPE I ROCK DITCH LINER   200.00													
CODITION													
COST   COST   COST   TRUCK OR TRALER MOUNTED ATTENLATOR (TMA)   2.00   0.00   2.00   EA   2.00   \$00.00   \$1,000													
COST   0150   6151005   CONSTRUCTION SIGNS   1,825.00   0.00   1,825.00   SOFT   1,066.00   510.435.00   1,000.00   1,0													, , ,
COOT   OTHO   OTHO   OTHO   OTHOR   CHANNELIZER (TRIALINE)													
0001   0170   0161060   0161080													
0011   0180   0181008   018108													
INTERFACE_CONTRACTOR PURNISHED_CONTRACTOR													
0001   0200   6191020   ADDITIONAL MOBILIZATION FOR SEEDING   4.00   0.00   4.00   EA   0.00   \$600.00   \$0.00				0180	6161096A	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	2.00	0.00	2.00	EA	2.00	\$2,200.00	\$4,400.00
0011   0210   025000C   4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING   188,306.00   0.00   188,306.00   0.10   0.00   0.01   0.00   0.01   0.00   0.01   0.00			0001	0190	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$306,150.00	\$306,150.00
PAINT, TYPE P BEADS			0001	0200	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
MARKING PAINT, TYPE P BEADS						PAINT, TYPE P BEADS							
0001			0001 0220		6206001C		171,517.00	0.00	171,517.00	LF	0.00	\$0.11	\$0.00
0001         0240         6261000A         BITUMINOUS SHOULDER RUMBLE STRIP         1,867.70         0.00         1,867.70         STA         0.00         \$11.00         \$50.00           0001         0250         7034041         CLASS B-I CONCRETE (CULVERTS)         3.20         -0.40         2.80         CUVD         2.80         \$4,450.00         \$12,460.00           0001         0260         7250312A         12 IN. PIPE GROUP B         51.00         -51.00         0.00         LF         0.00         \$105.00         \$30.00         \$107.00         \$35.310.00           0001         0270         7250315A         15 IN. PIPE GROUP B         301.00         157.00         458.00         LF         300.00         \$111.75         \$39.112.50           0001         0290         7250324A         24 IN. PIPE GROUP B         120.00         -30.00         90.00         LF         90.00         \$118.50         \$10,665.00           0001         0300         7250336A         36 IN. PIPE GROUP B         43.00         0.00         43.00         LF         43.00         \$11.40         \$137.00         \$58.810.00           0001         0310         7350001         PIPE LINER FOR EXISTING CULVERT         48.00         56.00         104.00			0001	0225	6214600A	FLOWABLE BACKFILL	3.00	0.00	3.00	CUYD	4.50	\$335.00	\$1,507.50
0001   0250   7034041   CLASS B-I CONCRETE (CULVERTS)   3.20   -0.40   2.80   CUVD   2.80   \$4.450.00   \$12,460.00   \$1001   \$1001   \$260   7250312A   12 IN. PIPE GROUP B   51.00   -51.00   0.00   LF   0.00   \$105.00   \$0.00   \$1001   \$270   7250315A   15 IN. PIPE GROUP B   146.00   280.00   406.00   LF   330.00   \$107.00   \$35,310.00   \$1001   \$280   7250318A   18 IN. PIPE GROUP B   301.00   157.00   458.00   LF   350.00   \$111.75   \$39,112.50   \$1001   \$290   7250324A   24 IN. PIPE GROUP B   120.00   -30.00   90.00   LF   90.00   \$118.50   \$116.65   \$10.665.00   \$1001   \$			0001	0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,771.00	0.00	1,771.00	SQYD	747.20	\$4.50	\$3,362.40
0001   0260   7250312A   12 IN. PIPE GROUP B   51.00   -51.00   0.00   LF   0.00   \$105.00   \$0.00     0001   0270   7250315A   15 IN. PIPE GROUP B   146.00   260.00   406.00   LF   330.00   \$107.00   \$35.310.00     0001   0280   725032A   24 IN. PIPE GROUP B   301.00   157.00   458.00   LF   350.00   \$111.75   \$39.112.50     0001   0290   725032A   24 IN. PIPE GROUP B   120.00   -30.00   90.00   LF   90.00   \$118.50   \$10.865.00     0001   0300   7250336A   36 IN. PIPE GROUP B   43.00   0.00   43.00   LF   43.00   \$137.00   \$5.891.00     0001   0310   7350001   PIPE LINER FOR EXISTING CULVERT   48.00   56.00   104.00   LF   48.00   \$114.00   \$5.472.00     0001   0320   8051000A   SEEDING - COOL SEASON MIXTURES   43.20   0.00   43.20   ACRE   22.00   \$2.000.00   \$44.000.00     0001   0325   8061017   TEMPORARY SEEDING AND MULCHING   5.00   0.00   5.00   ACRE   0.00   \$1.900.00   \$4.760.00     0001   0330   8061004   SEDIMENT TRAP ROCK   259.00   0.00   259.00   CUYD   70.00   \$88.00   \$4.760.00     0001   0340   8061005   ROCK DITCH CHECK   200.00   0.00   5.350.00   LF   5.456.15   \$12.75   \$69.565.91     0001   0360   8061016   SEDIMENT REMOVAL   11.19.00   0.00   1.19.00   CUYD   198.50   \$2.00   \$397.00     0001   0370   8061019   SILT FENCE   4.636.00   0.00   4.636.00   LF   1.860.00   \$2.30   \$4.278.00     0040   0390   9031270   21N. PSST POST - 12 GA.   152.00   0.00   72.00   LF   0.00   \$40.00   \$0.00     0040   0400   9031271   POST ANCHOR FOR 2 IN. PSST - 12 GA.   72.00   0.00   72.00   LF   0.00   \$40.00   \$0.00     0040   0410   9035089A   SHF-FLAT SHEET FLUORESCENT   72.00   0.00   72.00   CUFD   0.00   \$36.00   \$0.00			0001	0240	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,867.70	0.00	1,867.70	STA	0.00	\$11.00	\$0.00
0001         0270         7250315A         15 IN. PIPE GROUP B         146.00         260.00         406.00         LF         330.00         \$107.00         \$35,310.00           0001         0280         7250315A         18 IN. PIPE GROUP B         301.00         157.00         458.00         LF         350.00         \$111.75         \$39,112.50           0001         0290         7250324A         24 IN. PIPE GROUP B         120.00         -30.00         90.00         LF         90.00         \$118.50         \$10,665.00           0001         0310         7250336A         36 IN. PIPE GROUP B         43.00         0.00         43.00         LF         43.00         \$117.00         \$5,891.00           0001         0310         7350001         PIPE LINER FOR EXISTING CULVERT         48.00         56.00         104.00         LF         48.00         \$114.00         \$5,472.00           0001         0325         8051000A         SEEDING - COOL SEASON MIXTURES         43.20         0.00         43.20         ACRE         22.00         \$2,000.00         \$44,000.00           0001         0325         8061001         TEMPORARY SEEDING AND MULCHING         5.00         0.00         5.00         ACRE         0.00         \$1,900.00			0001	0250	7034041	CLASS B-1 CONCRETE (CULVERTS)	3.20	-0.40	2.80	CUYD	2.80	\$4,450.00	\$12,460.00
0001   0280   7250318A   18 IN. PIPE GROUP B   301.00   157.00   458.00   LF   350.00   \$111.75   \$39,112.50			0001	0260	7250312A	12 IN. PIPE GROUP B	51.00	-51.00	0.00	LF	0.00	\$105.00	\$0.00
0001 0290 7250324A 24 IN. PIPE GROUP B 120.00 -30.00 90.00 LF 90.00 \$118.50 \$10,665.00   0001 0300 7250336A 36 IN. PIPE GROUP B 43.00 0.00 43.00 LF 43.00 \$137.00 \$5.891.00   0001 0310 7350001 PIPE LINER FOR EXISTING CULVERT 48.00 56.00 104.00 LF 48.00 \$114.00 \$5.472.00   0001 0320 8051000A \$EEDING - COOL SEASON MIXTURES 43.20 0.00 43.20 ACRE 22.00 \$2,000.00 \$44,000.00   0001 0325 8061017 TEMPORARY SEEDING AND MULCHING 5.00 0.00 5.00 ACRE 0.00 \$1,900.00 \$0.00   0001 0330 8061004 \$EDIMENT TRAP ROCK 259.00 0.00 259.00 CUVD 70.00 \$68.00 \$4.760.00   0001 0340 8061005 ROCK DITCH CHECK 5,350.00 0.00 5,350.00 LF 5,456.15 \$12.75 \$69,565.91   0001 0350 806106 ALTERNATE DITCH CHECK 200.00 0.00 200.00 LF 0.00 \$14.25 \$0.00   0001 0360 8061016 \$EDIMENT REMOVAL 11,119.00 0.00 1,119.00 CUVD 198.50 \$2.00 \$397.00   0001 0370 8061019 \$ILT FENCE 48.65.00 0.00 4.636.00 LF 1,860.00 \$2.30 \$4.278.00   0040 0380 9031270 VOOD POST, 4 IN. BY 4 IN. 120.00 0.00 152.00 LF 0.00 \$15.00 \$0.			0001	0270	7250315A	15 IN. PIPE GROUP B	146.00	260.00	406.00	LF	330.00	\$107.00	\$35,310.00
0001         0300         7250336A         36 IN. PIPE GROUP B         43.00         0.00         43.00         LF         43.00         \$137.00         \$5,891.00           0001         0310         7350001         PIPE LINER FOR EXISTING CULVERT         48.00         56.00         104.00         LF         48.00         \$114.00         \$5,472.00           0001         0320         8051000A         SEEDING - COOL SEASON MIXTURES         43.20         0.00         43.20         ACRE         22.00         \$2,000.00         \$44,000.00           0001         0325         8061017         TEMPORARY SEEDING AND MULCHING         5.00         0.00         5.00         ACRE         0.00         \$1,900.00         \$0.00           0001         0330         8061004         SEDIMENT TRAP ROCK         259.00         0.00         259.00         CUYD         70.00         \$68.00         \$4,760.00           0001         0340         8061005         ROCK DITCH CHECK         259.00         0.00         259.00         CUYD         70.00         \$68.00         \$4,760.00           0001         0350         8061006         ALTERNATE DITCH CHECK         200.00         0.00         LF         5,456.15         \$12.75         \$69,565.91			0001	0280	7250318A	18 IN. PIPE GROUP B	301.00	157.00	458.00	LF	350.00	\$111.75	\$39,112.50
0001 0310 7350001 PIPE LINER FOR EXISTING CULVERT 48.00 56.00 104.00 LF 48.00 \$114.00 \$5,472.00   0001 0320 8051000A SEEDING - COOL SEASON MIXTURES 43.20 0.00 43.20 ACRE 22.00 \$2,000.00 \$44,000.00   0001 0325 8061017 TEMPORARY SEEDING AND MULCHING 5.00 0.00 5.00 ACRE 0.00 \$1,900.00 \$0.00   0001 0330 8061004 SEDIMENT TRAP ROCK 259.00 0.00 259.00 CUYD 70.00 \$68.00 \$4,760.00   0001 0340 8061005 ROCK DITCH CHECK 5,350.00 0.00 5,350.00 LF 5,456.15 \$12.75 \$69,565.91   0001 0350 8061006 ALTERNATE DITCH CHECK 200.00 0.00 200.00 LF 0.00 \$14.25 \$0.00   0001 0360 8061016 SEDIMENT REMOVAL 1,119.00 0.00 1,119.00 CUYD 198.50 \$2.00 \$397.00   0001 0370 8061019 SILT FENCE 4,636.00 0.00 4,636.00 LF 1,860.00 \$2.30 \$4,278.00   0040 0380 9031260 WOOD POST, 4 IN. BY 4 IN. 120.00 0.00 150.00 LF 0.00 \$15.00 \$0.00   0040 0390 9031270 2 IN. PSST POST - 12 GA. 152.00 0.00 72.00 LF 0.00 \$40.00 \$0.			0001	0290	7250324A	24 IN. PIPE GROUP B	120.00	-30.00	90.00	LF	90.00	\$118.50	\$10,665.00
0001         0320         8051000A         SEEDING - COOL SEASON MIXTURES         43.20         0.00         43.20         ACRE         22.00         \$2,000.00         \$44,000.00           0001         0325         8061017         TEMPORARY SEEDING AND MULCHING         5.00         0.00         5.00         ACRE         0.00         \$1,900.00         \$0.00           0001         0330         8061004         SEDIMENT TRAP ROCK         259.00         0.00         259.00         CUYD         70.00         \$68.00         \$4,760.00           0001         0340         8061005         ROCK DITCH CHECK         5,350.00         0.00         5,350.00         LF         5,456.15         \$12.75         \$69,565.91           0001         0350         8061006         ALTERNATE DITCH CHECK         200.00         0.00         200.00         LF         0.00         \$14.25         \$0.00           0001         0360         8061016         SEDIMENT REMOVAL         1,119.00         0.00         1,119.00         CUYD         198.50         \$2.00         \$397.00           001         0370         8061019         SILT FENCE         4,636.00         0.00         4,636.00         LF         1,860.00         \$2.30         \$4,278.00 <td></td> <td></td> <td>0001</td> <td>0300</td> <td>7250336A</td> <td>36 IN. PIPE GROUP B</td> <td>43.00</td> <td>0.00</td> <td>43.00</td> <td>LF</td> <td>43.00</td> <td>\$137.00</td> <td>\$5,891.00</td>			0001	0300	7250336A	36 IN. PIPE GROUP B	43.00	0.00	43.00	LF	43.00	\$137.00	\$5,891.00
0001         0325         8061017         TEMPORARY SEEDING AND MULCHING         5.00         0.00         5.00         ACRE         0.00         \$1,900.00         \$0.00           0001         0330         8061004         SEDIMENT TRAP ROCK         259.00         0.00         259.00         CUYD         70.00         \$68.00         \$4,760.00           0001         0340         8061005         ROCK DITCH CHECK         5,350.00         0.00         5,350.00         LF         5,456.15         \$12.75         \$69,565.91           0001         0350         8061006         ALTERNATE DITCH CHECK         200.00         0.00         200.00         LF         0.00         \$14.25         \$0.00           0001         0360         8061016         SEDIMENT REMOVAL         1,119.00         0.00         1,119.00         CUYD         198.50         \$2.00         \$397.00           0001         0370         8061019         SILT FENCE         4,636.00         0.00         4,636.00         LF         1,860.00         \$2.30         \$4,278.00           0040         0380         9031260         WOOD POST, 4 IN. BY 4 IN.         120.00         0.00         120.00         LF         0.00         \$24.00         \$0.00			0001	0310	7350001	PIPE LINER FOR EXISTING CULVERT	48.00	56.00	104.00	LF	48.00	\$114.00	\$5,472.00
0001         0330         8061004         SEDIMENT TRAP ROCK         259.00         0.00         259.00         CUYD         70.00         \$68.00         \$4,760.00           0001         0340         8061005         ROCK DITCH CHECK         5,350.00         0.00         5,350.00         LF         5,456.15         \$12.75         \$69,565.91           0001         0350         8061006         ALTERNATE DITCH CHECK         200.00         0.00         200.00         LF         0.00         \$14.25         \$0.00           0001         0360         8061016         SEDIMENT REMOVAL         1,119.00         0.00         1,119.00         CUYD         198.50         \$2.00         \$397.00           0001         0370         8061019         SILT FENCE         4,636.00         0.00         4,636.00         LF         1,860.00         \$2.30         \$4,278.00           0040         0380         9031260         WOOD POST, 4 IN. BY 4 IN.         120.00         0.00         120.00         LF         0.00         \$15.00         \$0.00           0040         0390         9031270         2 IN. PSST POST - 12 GA.         152.00         0.00         152.00         LF         0.00         \$40.00         \$0.00 <t< td=""><td></td><td></td><td>0001</td><td>0320</td><td>8051000A</td><td>SEEDING - COOL SEASON MIXTURES</td><td>43.20</td><td>0.00</td><td>43.20</td><td>ACRE</td><td>22.00</td><td>\$2,000.00</td><td>\$44,000.00</td></t<>			0001	0320	8051000A	SEEDING - COOL SEASON MIXTURES	43.20	0.00	43.20	ACRE	22.00	\$2,000.00	\$44,000.00
0001         0340         8061005         ROCK DITCH CHECK         5,350.00         0.00         5,350.00         LF         5,456.15         \$12.75         \$69,565.91           0001         0350         8061006         ALTERNATE DITCH CHECK         200.00         0.00         200.00         LF         0.00         \$14.25         \$0.00           0001         0360         8061016         SEDIMENT REMOVAL         1,119.00         0.00         1,119.00         CUYD         198.50         \$2.00         \$397.00           0001         0370         8061019         SILT FENCE         4,636.00         0.00         4,636.00         LF         1,860.00         \$2.30         \$4,278.00           0040         0380         9031260         WOOD POST, 4 IN. BY 4 IN.         120.00         0.00         120.00         LF         0.00         \$15.00         \$0.00           0040         0390         9031270A         2 IN. PSST POST - 12 GA.         152.00         0.00         152.00         LF         0.00         \$40.00         \$0.00           0040         0400         9031271         POST ANCHOR FOR 2 IN. PSST - 12 GA.         72.00         0.00         72.00         LF         0.00         \$40.00         \$0.00			0001	0325	8061017	TEMPORARY SEEDING AND MULCHING	5.00	0.00	5.00	ACRE	0.00	\$1,900.00	\$0.00
0001         0350         8061006         ALTERNATE DITCH CHECK         200.00         0.00         200.00         LF         0.00         \$14.25         \$0.00           0001         0360         8061016         SEDIMENT REMOVAL         1,119.00         0.00         1,119.00         CUYD         198.50         \$2.00         \$397.00           0001         0370         8061019         SILT FENCE         4,636.00         0.00         4,636.00         LF         1,860.00         \$2.30         \$4,278.00           0040         0380         9031260         WOOD POST, 4 IN. BY 4 IN.         120.00         0.00         120.00         LF         0.00         \$15.00         \$0.00           0040         0390         9031270A         2 IN. PSST POST - 12 GA.         152.00         0.00         152.00         LF         0.00         \$40.00         \$0.00           0040         0400         9031271         POST ANCHOR FOR 2 IN. PSST - 12 GA.         72.00         0.00         72.00         LF         0.00         \$40.00         \$0.00           0040         0410         9035069A         SHF-FLAT SHEET FLUORESCENT         72.00         0.00         72.00         SQFT         0.00         \$36.00         \$0.00			0001	0330	8061004	SEDIMENT TRAP ROCK	259.00	0.00	259.00	CUYD	70.00	\$68.00	\$4,760.00
0001 0360 8061016 SEDIMENT REMOVAL 1,119.00 0.00 1,119.00 CUYD 198.50 \$2.00 \$397.00   0001 0370 8061019 SILT FENCE 4,636.00 0.00 4,636.00 LF 1,860.00 \$2.30 \$4,278.00   0040 0380 9031260 WOOD POST, 4 IN. BY 4 IN. 120.00 0.00 120.00 LF 0.00 \$15.00 \$0.00   0040 0390 9031270A 2 IN. PSST POST - 12 GA. 152.00 0.00 152.00 LF 0.00 \$24.00 \$0.00   0040 0400 9031271 POST ANCHOR FOR 2 IN. PSST - 12 GA. 72.00 0.00 72.00 LF 0.00 \$40.00 \$0.00   0040 0410 9035069A SHF-FLAT SHEET FLUORESCENT 72.00 0.00 72.00 SQFT 0.00 \$36.00 \$0.00			0001	0340	8061005	ROCK DITCH CHECK	5,350.00	0.00	5,350.00	LF	5,456.15	\$12.75	\$69,565.91
0001         0370         8061019         SILT FENCE         4,636.00         0.00         4,636.00         LF         1,860.00         \$2.30         \$4,278.00           0040         0380         9031260         WOOD POST, 4 IN. BY 4 IN.         120.00         0.00         120.00         LF         0.00         \$15.00         \$0.00           0040         0390         9031270A         2 IN. PSST POST - 12 GA.         152.00         0.00         152.00         LF         0.00         \$24.00         \$0.00           0040         0400         9031271         POST ANCHOR FOR 2 IN. PSST - 12 GA.         72.00         0.00         72.00         LF         0.00         \$40.00         \$0.00           0040         0410         9035069A         SHF-FLAT SHEET FLUORESCENT         72.00         0.00         72.00         SQFT         0.00         \$36.00         \$0.00			0001	0350	8061006	ALTERNATE DITCH CHECK	200.00	0.00	200.00	LF	0.00	\$14.25	\$0.00
0040         0380         9031260         WOOD POST, 4 IN. BY 4 IN.         120.00         0.00         120.00         LF         0.00         \$15.00         \$0.00           0040         0390         9031270A         2 IN. PSST POST - 12 GA.         152.00         0.00         152.00         LF         0.00         \$24.00         \$0.00           0040         0400         9031271         POST ANCHOR FOR 2 IN. PSST - 12 GA.         72.00         0.00         72.00         LF         0.00         \$40.00         \$0.00           0040         0410         9035069A         SHF-FLAT SHEET FLUORESCENT         72.00         0.00         72.00         SQFT         0.00         \$36.00         \$0.00			0001	0360	8061016	SEDIMENT REMOVAL	1,119.00	0.00	1,119.00	CUYD	198.50	\$2.00	\$397.00
0040         0390         9031270A         2 IN. PSST POST - 12 GA.         152.00         0.00         152.00         LF         0.00         \$24.00         \$0.00           0040         0400         9031271         POST ANCHOR FOR 2 IN. PSST - 12 GA.         72.00         0.00         72.00         LF         0.00         \$40.00         \$0.00           0040         0410         9035069A         SHF-FLAT SHEET FLUORESCENT         72.00         0.00         72.00         SQFT         0.00         \$36.00         \$0.00			0001	0370	8061019	SILT FENCE	4,636.00	0.00	4,636.00	LF	1,860.00	\$2.30	\$4,278.00
0040 0400 9031271 POST ANCHOR FOR 2 IN. PSST - 12 GA. 72.00 0.00 72.00 LF 0.00 \$40.00 \$0.0			0040	0380	9031260	WOOD POST, 4 IN. BY 4 IN.	120.00	0.00	120.00	LF	0.00	\$15.00	\$0.00
0040 0410 9035069A SHF-FLAT SHEET FLUORESCENT 72.00 0.00 72.00 SQFT 0.00 \$36.00 \$0.00			0040	0390	9031270A	2 IN. PSST POST - 12 GA.	152.00	0.00	152.00	LF	0.00	\$24.00	\$0.00
			0040	0400	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	72.00	0.00	72.00	LF	0.00	\$40.00	\$0.00
Project J9S3340 - Total Value Posted to Date as of Report Generated Date \$2,635,928.93			0040	0410	9035069A	SHF-FLAT SHEET FLUORESCENT	72.00	0.00	72.00	SQFT	0.00	\$36.00	\$0.00
		Project J	9S3340 - <u>To</u>	otal Value	Posted to D	ate as of Report Generated Date							\$2,635,928.93

Page 5 of 14 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-H05 Ove	210122-H05 Overall - Total Value Posted to Date as of Report Generated Date										\$2,635,928.93	

Revision 4/1/2020 Page 6 of 14



### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3340

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	2129900	MISC. SUBGRADING AND SHOULDERING	9/17/21	10/1/21	46.50	100F		.028		2.2		
				10/1/21	46.80			11.1		13.3		
				10/1/21	46.80	100F		13.3		15.5		
				10/1/21	46.80 46.80	100F 100F		15.5 2.2		17.8 4.4		
				10/1/21	46.80			4.4		6.6		
				10/1/21	46.80			6.6		8.9		
				10/1/21	46.80	100F		8.9		11.1		
0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	9/16/21	10/1/21	3.07	TONS		10.015	Right			
				10/1/21	3.07	TONS		10.16	Left			
				10/1/21		TONS		10.2				
				10/1/21		TONS		10.545				
				10/1/21		TONS		10.620 10.858				
				10/1/21		TONS		10.030				
				10/1/21		TONS		10.914				
				10/1/21	3.07	TONS		10.916	Right			
				10/1/21	3.07	TONS		11.335	Right			
				10/1/21	3.07	TONS		11.438	Left			
				10/1/21		TONS		11.505				
				10/1/21		TONS		12.0				
				10/1/21		TONS		12.329 12.329				
				10/1/21		TONS		12.345				
				10/1/21		TONS		12.64				
				10/1/21		TONS		13.68				
				10/1/21	3.07	TONS		13.70	Left			
				10/1/21		TONS		13.82				
				10/1/21		TONS		13.82				
				10/1/21		TONS		14.138				
				10/1/21		TONS		14.26 14.469				
				10/1/21		TONS		14.560				
				10/1/21		TONS		14.784				
				10/1/21		TONS		15.066				
				10/1/21	3.07	TONS		15.066	Right			
				10/1/21	3.07	TONS		15.155	Left			
				10/1/21		TONS		15.378				
				10/1/21		TONS		15.914				
				10/1/21		TONS		15.954 15.958				
				10/1/21		TONS		16.455				
				10/1/21		TONS		16.694				
				10/1/21		TONS		16.772				
				10/1/21	3.07	TONS		16.875	Right			
				10/1/21	3.07	TONS		17.013	Right			
				10/1/21	3.07	TONS		17.033	Left			
				10/1/21		TONS		17.033				
				10/1/21		TONS		17.089				
				10/1/21				17.089				
				10/1/21		TONS		17.32 17.396				
				10/1/21		TONS		17.434				
				10/1/21		TONS		17.52				
				10/1/21		TONS		17.56				
				10/1/21		TONS		17.62				
				10/1/21		TONS		17.764				
				10/1/21		TONS		5.35				
				10/1/21		TONS		5.40 5.688				
				10/1/21		TONS		6.212				
				10/1/21		TONS		6.215				
				10/1/21		TONS		6.215				
				10/1/21	3.07	TONS		6.351				
				10/1/21	3.07	TONS		7.18	Left			
				10/1/21		TONS		7.475				
				10/1/21		TONS		7.869				
				10/1/21		TONS		7.946				
				10/1/21		TONS		7.962				
				10/1/21		TONS		8.034 8.086				
				10/1/21		TONS		8.086				
				10/1/21		TONS		8.261				
				10/1/21		TONS		8.261				

Revision 4/1/2020 Page 7 of 14



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	9/16/21	10/1/21	3.07	TONS		8.311	Right			
				10/1/21		TONS		8.58				
				10/1/21		TONS		8.58				
				10/1/21		TONS		8.78 8.782				
				10/1/21		TONS		8.80				
				10/1/21	3.07	TONS		8.818	Left			
				10/1/21		TONS		9.164	Right			
				10/1/21		TONS		9.384				
				10/1/21		TONS		9.607				
				10/1/21		TONS			Right			
				10/1/21	3.07	TONS		9.861	Left			
				10/1/21		TONS		9.904				
				10/1/21		TONS		2.610				
				10/1/21		TONS		2.721				
				10/1/21		TONS		2.952				
				10/1/21	3.17	TONS		2.952	Right			
				10/1/21		TONS		3.122				
				10/1/21		TONS		3.249				
				10/1/21		TONS		3.472 3.576				
				10/1/21		TONS		3.576				
				10/1/21	3.17	TONS		3.72	Left			
				10/1/21		TONS		3.814				
				10/1/21		TONS		3.814 3.946				
				10/1/21		TONS		4.092				
				10/1/21		TONS		4.22				
				10/1/21	3.17	TONS		4.22	Right			
				10/1/21		TONS		4.452				
				10/1/21		TONS		4.645 4.752				
				10/1/21		TONS		4.921				
				10/1/21	3.17	TONS		4.922	Right			
				10/1/21		TONS		4.942				
				10/1/21		TONS		4.946				
				10/1/21		TONS		5.02	Right			
				10/1/21		TONS			Right			
				10/1/21	3.17	TONS		5.11	Right			
				10/1/21		TONS		5.20				
			9/17/21	10/1/21		TONS		.061	Left			
				10/1/21		TONS		.092				
				10/1/21		TONS		.152				
				10/1/21		TONS		.157	Left			
				10/1/21		TONS		.291				
				10/1/21		TONS		.312				
				10/1/21		TONS			Right			
				10/1/21		TONS			Right			
				10/1/21		TONS			Right			
				10/1/21		TONS		.612				
				10/1/21		TONS			Right Right			
				10/1/21		TONS			Right			
				10/1/21		TONS			Right			
				10/1/21		TONS		.793				
				10/1/21		TONS		.793	Right			
				10/1/21		TONS			Right			
				10/1/21		TONS			Right			
				10/1/21		TONS		.944				
				10/1/21		TONS		.947				
				10/1/21		TONS			Right Right			
				10/1/21		TONS		1.092				
				10/1/21		TONS		1.10				
				10/1/21		TONS			Right			
				10/1/21		TONS		1.20				
				10/1/21		TONS			Right Right			
				10/1/21		TONS		1.282				
				10/1/21	2.61	TONS		1.282	Right			

Revision 4/1/2020 Page 8 of 14



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	9/17/21	10/1/21	2.61	TONS		1.297	Left			
				10/1/21		TONS		1.329				
				10/1/21		TONS		1.509				
				10/1/21		TONS		1.661				
				10/1/21		TONS		1.742				
				10/1/21	2.61	TONS		1.743	Left			
				10/1/21	2.61	TONS		1.843	Left			
				10/1/21		TONS		1.910				
				10/1/21		TONS		1.913	Right			
				10/1/21		TONS		1.964				
				10/1/21		TONS		2.099				
				10/1/21	2.61	TONS		2.102	Right			
				10/1/21	2.61	TONS		2.133	Left			
				10/1/21		TONS		2.133				
				10/1/21		TONS		2.441				
				10/1/21	2.61			2.561 LM	Left			
				10/1/21				2.370	Lon			
0080		BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	9/16/21	10/1/21		TONS		0.00		17.832		
		TRUCK OR TRAILER MOUNTED ATTEN (TMA)	9/20/21	10/1/21	2.00	EA	Traffic Control Davisors and at a series and	0.00		17.83		
0150	6161005	CONSTRUCTION SIGNS	9/20/21	10/1/21	1,030.00	SQFf	Traffic Control Devices used at various locations within the project limits.	.00		17.832		
0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	9/16/21	10/1/21	1.50	SQYD	2' x 20' = 40 ÷ 27 = 1.5	.825				
				10/1/21	1.50		2' x 20' = 40 ÷ 27 = 1.5	0.5				
				10/1/21	1.50		2' x 20' = 40 ÷ 27 = 1.5	1.325				
				10/1/21	1.50		2' x 20' = 40 ÷ 27 = 1.5 2' x 20' = 40 ÷ 27 = 1.5	13.00				
				10/1/21			2' x 20' = 40 ÷ 27 = 1.5	13.25				
				10/1/21	1.50		2' x 20' = 40 ÷ 27 = 1.5	14.5				
				10/1/21	1.50	SQYD	2' x 20' = 40 ÷ 27 = 1.5	15.728				
				10/1/21	1.50	SQYD	2' x 20' = 40 ÷ 27 = 1.5	4.65				
				10/1/21			2' x 20' = 40 ÷ 27 = 1.5	7.700				
				10/1/21			2' x 20' = 40 ÷ 27 = 1.5	7.9				
				10/1/21	3.00		2@ 2' x 20' = 40 ÷ 27 = 1.5 2 x 20 = 100 ÷ 27 = 3.7	0.25 2.00		0.26		
				10/1/21			10 x 20 = 200 ÷ 27 = 7.4	0.425				
				10/1/21	10.50		2' x 20' = 40 ÷ 27 = 1.5	5.495				
0320	8051000A	SEEDING - COOL SEASON MIXTURES	9/17/21	10/1/21	10.60	ACRE		.038		8.974		
				10/1/21	11.40	ACRE		8.247		17.896		
0360	8061016	SEDIMENT REMOVAL	9/20/21			CUYD		13.63				
				10/1/21		CUYD		14.755				
				10/1/21		CUYD		15.33 15.556				
				10/1/21	0.50			16.428				
				10/1/21		CUYD			Right			
				10/1/21	1.00	CUYD		11.96	Left			
				10/1/21	1.00	CUYD		12.832	Left			
				10/1/21		CUYD		13.48				
				10/1/21		CUYD		13.561 13.606				
				10/1/21		CUYD		13.606				
				10/1/21		CUYD		14.045				
				10/1/21		CUYD		14.678				
				10/1/21	1.00	CUYD		14.74	Left			
				10/1/21		CUYD		14.996				
				10/1/21		CUYD		15.013				
				10/1/21		CUYD		15.036				
				10/1/21		CUYD		15.412 15.66				
				10/1/21		CUYD		16.14				
				10/1/21		CUYD		16.447				
				10/1/21	1.00	CUYD		16.576	Rt.			
				10/1/21		CUYD		16.662				
				10/1/21		CUYD		2.097				
				10/1/21		CUYD		2.103				
				10/1/21		CUYD		2.169 3.088				
				10/1/21		CUYD		3.115				
				10/1/21		CUYD		3.212				
				10/1/21		CUYD		4.05	Rt.			
				10/1/21		CUYD		4.081				
				10/1/21		CUYD		4.1				
				10/1/21		CUYD		4.125 4.173				
				10/1/21		CUYD		4.173				
					1.00	5		4.7				

Revision 4/1/2020 Page 9 of 14



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0360	8061016	SEDIMENT REMOVAL	9/20/21	10/1/21	1.00	CUYD		4.87	Rt.			
				10/1/21	1.00	CUYD		5.74	Rt.			
				10/1/21	1.00	CUYD		5.77	Rt.			
				10/1/21	1.00	CUYD		5.81	Rt.			
				10/1/21	1.00	CUYD		6.3	Left			
				10/1/21	1.00	CUYD		6.35	Rt.			
				10/1/21	1.00	CUYD		6.48	Rt.			
				10/1/21	1.00	CUYD			Left			
				10/1/21	1.00	CUYD		6.53	Rt.			
				10/1/21	1.00	CUYD		7.03	Left			
				10/1/21	1.00	CUYD		8.15				
				10/1/21		CUYD		8.16				
				10/1/21	1.00	CUYD		8.324				
				10/1/21		CUYD		12.815				
				10/1/21		CUYD		14.019				
				10/1/21	1.50	CUYD		15.58				
				10/1/21		CUYD		15.58				
				10/1/21	1.50	CUYD		4.87				
				10/1/21		CUYD		6.5				
				10/1/21		CUYD		12.87				
				10/1/21	2.00	CUYD		14.624	Rt.			
				10/1/21		CUYD		15.234				
				10/1/21		CUYD		17.034				
				10/1/21		CUYD		2.106				
				10/1/21	2.00	CUYD		5.86				
				10/1/21	2.00	CUYD		8.25	Left			

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 10 of 14



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3340	0040	MISC. AGGREGATE FOR BASE	Material		3	Jun 2, 2021	SYSTEM	\$3,340.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jun 2, 2021	SYSTEM	(\$3,340.50)	
					4	Jun 16, 2021	SYSTEM	\$4,192.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 16, 2021	SYSTEM	(\$4,192.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0040 -	· Total						\$0.00	
	0050	GRAVEL (A) OR CRUSHED STONE (B)	Material		3	Jun 2, 2021	SYSTEM	\$5,686.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Jun 2, 2021	SYSTEM	(\$5,686.20)	
					4	Jun 16, 2021	SYSTEM	\$10,845.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Jun 16, 2021	SYSTEM	(\$10,845.90)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	10	Sep 16, 2021	SYSTEM	(\$2,138.76)	
					11	Oct 1, 2021	SYSTEM	\$19,745.51	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Oct 1, 2021	SYSTEM	\$7,939.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user reedv1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Oct 1, 2021	SYSTEM	(\$27,685.13)	
				Overrun - T	otal			(\$2,138.76)	
			Overrun - T	otal				(\$2,138.76)	
	0050	· Total						(\$2,138.76)	
	0075	MISC.	Material		9	Sep 1, 2021	SYSTEM	\$82,863.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Sep 1, 2021	SYSTEM	(\$82,863.50)	
					10	Sep 16, 2021	SYSTEM	\$82,863.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$82,863.50)	
					11	Oct 1, 2021	SYSTEM	\$82,863.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Oct 1, 2021	SYSTEM	(\$82,863.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	9	Sep 1, 2021	REEDV1	\$35,061.90	Estimate 009, The original factor was 395 and the current factor is 493.75 for a difference of 98.75, the virgin AC is 4.0%% for this mix design.
				ACAD - Tot	al			\$35,061.90	
			Other Item	Adjustment -	Total			\$35,061.90	
	0075	Total						\$35,061.90	
	0800	BITUMINOUS	Material		9	Sep 1,	SYSTEM	\$414,898.08	This adjustment offsets the original system-generated Material Payment



Property   1										
Cellstands Exception 2 on the current Peyment Estimate.	Project	Line	Description		Adjustment				Amount	Remarks
PCG6-22 (GUR	J9S3340	0800		Material			2021			
ACAD   Total   September   ACAD   Page   Sept   September   Sept						9		SYSTEM	(\$414,898.08)	,
Material   Total					Total		2021		\$0.00	
Color   Semi   AcAD   9   Sep 1,   ACED   10   2021   2021				Metavial T						
Adjustment   2021   Sep. 16,   REEDV1   \$35,024.00   Old   Company   Sep. 16,   REEDV2   Sep. 16,   REEDV3   Sep. 17,   REED						-				
2021   2021					ACAD	9		REEDV1	\$32,974.80	the current factor is 493.75 for a difference of 98.75, the virgin AC is 4.0%% for this mix
2021   31, the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and on \$17/2021 the quantity was under reported by \$0.71 tows and quantity was under the proposed by \$0.71 tows and quantity was under the proposed by \$0.71 tows and quantity was under the proposed by						10		REEDV1	\$35,024.08	0010. There was 8756.02 tons of asphalt laid with a virgin AC of 4% and the original factor was 395 with the current factor being 495 for a difference of
ACAD - Total						10		REEDV1	\$988.05	31, the quantity was under reported by 93.71 tons and on 9/1/2021 the quantity was under reported by 156.43 tons. Asphalt laid in this period was adjusted based on an original factor of 395 with the current factor of 493.75 for
Other Item Adjustment - Total    Sep. 222.89						11		REEDV1	\$335.96	2021, the base factor was 395 and the current index was 495 for a dilfference
					ACAD - Tota	al			\$69,322.89	
TACK COAT   Material   9   Sep 1,   SYSTEM   \$13,730.90   This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate Islandar				Other Item	Adjustment -	Total			\$69,322.89	
2021   Estimate Item Adjustment (0006) due to user reedv1 overridding Payment Estimate Estimate Estimate Exception 3 on the current Payment Estimate.		0080 -	Total						\$69,322.89	
Total   So.00   Material - Total   So.00		0090	TACK COAT	Material		9		SYSTEM	\$13,730.90	Estimate Item Adjustment (0006) due to user reedv1 overridding Payment
Material - Total   S0.00						9		SYSTEM	(\$13,730.90)	
Material - Total   SySTEM   Si3,200.00   This adjustment offsets the original system-generated Material Payment Estimate Estimate Item Adjustment (0x03) due to user receiv to vertidding Payment Estimate Estim					- Total				\$0.00	
PIPE COLLAR, TYPE A  Material  2 May 17, 2021  3 Jun 2, 2021  3 Jun 2, 2021  3 Jun 2, 2021  This adjustment offsets the original system-generated Material Payment Estimate Exemption 1 on the current Payment Estimate Lem Adjustment (003) due to user receiv1 overridding Payment Estimate Exception 1 on the current Payment Estimate Lem Adjustment (004) due to user receiv1 overridding Payment Estimate Exemption 3 on the current Payment Estimate Lem Adjustment (004) due to user receiv1 overridding Payment Estimate Exception 3 on the current Payment Estimate Estimate Exception 3 on the current Payment Estimate.  1 Total  1 Other Item Adjustment DTHR - Total  Other Item Adjustment - Total  1 May 3, SYSTEM S13,200.00  This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around June 9, 2021  Other Item Adjustment - Total  1 May 3, SYSTEM S494.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate Estimate Exception 1 on the current Payment Estimate Extended to the sample 215EVTR002, this adjustment will be reversed on a future estimate				Material - To	otal				\$0.00	
PIPE COLLAR, TYPE A  Material  2 May 17, 2021  3 Jun 2, 2021  This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.  1 Total  Naterial - Total  Other Item Adjustment - Total  Other Item OTHR I May 3, REEDVI (\$494.00)  This adjustment is due to a missing certification for the sample 215EVTR002, this adjustment will be reversed on a future estimate. Estimate 001		0090 -	· Total						\$0.00	
2021   3		0095		Material		2		SYSTEM	\$13,200.00	Estimate Item Adjustment (0003) due to user reedv1 overridding Payment
Sestimate   Lem Adjustment (000Å) due to user reedv1 overridding Payment   Estimate   Exception 3 on the current Payment   Estimate   Exception 1 on the current Payment   Estimate   Exception 2 on a future estimate.   Estimate						2		SYSTEM	(\$13,200.00)	
Total   S0.00     S0.00   S0.0						3		SYSTEM	\$13,200.00	Estimate Item Adjustment (0004) due to user reedv1 overridding Payment
Material - Total   S0.00   Other Item Adjustment   OTHR   2   May 17, 2021   3   Jun 2, 2021   3   Jun 2, 2021   SYSTEM   \$13,200.00   This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around June 9, 2021   3   Jun 2, 2021   SYSTEM   \$13,200.00   This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around June 9, 2021   S0.00   Other Item Adjustment - Total   S0.00   Sugar   SySTEM   SySTEM   Sugar   SySTEM   SySTEM   Sugar   SySTEM   S						3		SYSTEM	(\$13,200.00)	
Other Item Adjustment  OTHR 2 May 17, 2021  3 Jun 2, 2021  3 Jun 2, 2021  This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around June 9, 2021  OTHR - Total \$0.00  Other Item Adjustment - Total \$0.00  OTHR - Total \$0.00  OTHR - Total \$0.00  OTHR - Total \$0.00  OTHR - Total \$0.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  I May 3, 2021  Total \$0.00  Material - Total \$0.00  Other Item OTHR 1 May 3, 2021  This adjustment is due to a missing certification for the sample 21SEVTR002, this adjustment will be reversed on a future estimate. Estimate Estimate Exception 1 will be reversed on a future estimate.					- Total				\$0.00	
Adjustment  Adjust				Material - To	otal				\$0.00	
OTHR - Total  SO.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  I May 3, 2021  - Total  OTHR I May 3, REEDV1  OTHR I May 3, 2021  This adjustment is due to a missing certification for the sample 21SEVTR002, this adjustment will be reversed on a future estimate. Estimate 001									φ <b>υ.</b> υυ	
Other Item Adjustment - Total  S0.00  O095 - Total  CONSTRUCTION SIGNS  Material  1 May 3, 2021  - Total  - Total  Material - Total  Other Item OTHR I May 3, 2021  Other Item Adjustment (DOTHR)  Adjustment (S494.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  S0.00  Material - Total  S0.00  Other Item OTHR I May 3, 2021  Other Item Adjustment OTHR I May 3, 2021  This adjustment is due to a missing certification for the sample 21SEVTR002, this adjustment will be reversed on a future estimate. Estimate 001					OTHR	2		REEDV1		not being completed. The testing for the concrete should be completed around
Solution   Signs   Material   Solution   Signs   Material   Solution   Signs   System   Sys					OTHR		2021 Jun 2,		(\$13,200.00)	not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around
O150 CONSTRUCTION SIGNS  Material  1 May 3, 2021  1 May 3, 2021  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  1 May 3, 2021  SYSTEM (\$494.00)  - Total  S0.00  Material - Total  Other Item OTHR 1 May 3, 2021  Other Item Adjustment  OTHR 1 May 3, 2021  This adjustment is due to a missing certification for the sample 21SEVTR002, this adjustment will be reversed on a future estimate. Estimate 001						3	2021 Jun 2,		(\$13,200.00) \$13,200.00	not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around
SIGNS    2021   Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.    1				Adjustment	OTHR - Tota	3 al	2021 Jun 2,		(\$13,200.00) \$13,200.00 \$0.00	not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around
- Total \$0.00  Material - Total \$0.00  Other Item OTHR 1 May 3, REEDV1 (\$494.00) This adjustment is due to a missing certification for the sample 21SEVTR002, Adjustment 2021 this adjustment will be reversed on a future estimate. Estimate 001		0095 -	Total	Adjustment	OTHR - Tota	3 al	2021 Jun 2,		(\$13,200.00) \$13,200.00 \$0.00	not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around
Material - Total \$0.00  Other Item OTHR 1 May 3, REEDV1 (\$494.00) This adjustment is due to a missing certification for the sample 21SEVTR002, Adjustment will be reversed on a future estimate. Estimate 001			CONSTRUCTION	Adjustment Other Item	OTHR - Tota	3 al Total	2021 Jun 2, 2021 May 3,	SYSTEM	(\$13,200.00) \$13,200.00 \$0.00 \$0.00	not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment
Other Item OTHR 1 May 3, REEDV1 (\$494.00) This adjustment is due to a missing certification for the sample 21SEVTR002, Adjustment will be reversed on a future estimate. Estimate 001			CONSTRUCTION	Adjustment Other Item	OTHR - Tota	3 Total	2021 Jun 2, 2021 May 3, 2021 May 3,	SYSTEM	\$13,200.00) \$13,200.00 \$0.00 \$0.00 \$494.00	not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment
Adjustment 2021 this adjustment will be reversed on a future estimate. Estimate 001			CONSTRUCTION	Adjustment Other Item	OTHR - Tota	3 Total	2021 Jun 2, 2021 May 3, 2021 May 3,	SYSTEM	(\$13,200.00) \$13,200.00 \$0.00 \$0.00 \$494.00	not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment
			CONSTRUCTION	Other Item A	OTHR - Tota Adjustment - - Total	3 Total	2021 Jun 2, 2021 May 3, 2021 May 3,	SYSTEM	(\$13,200.00) \$13,200.00 \$0.00 \$0.00 \$494.00 (\$494.00)	not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around June 9, 2021  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3340	0150	CONSTRUCTION SIGNS	Other Item Adjustment	OTHR	2	May 17, 2021	SYSTEM	\$494.00	This adjustment is due to a missing certification for the sample 21SEVTR002, this adjustment will be reversed on a future estimate. Estimate 001 05/03/2021.
				OTHR - Tota	al			\$0.00	
			Other Item	Adjustment -	Total			\$0.00	
	0150 -	Total						\$0.00	
	0180	CMS W/O COMMUNICATION INTERFACE,	Material		1	May 3, 2021	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		CONT F/			1	May 3, 2021	SYSTEM	(\$4,400.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	1	May 3, 2021	REEDV1	(\$4,400.00)	This adjustment is due to a missing certification for the sample 21SEVTR002, this adjustment will be reversed on a future estimate. Estimate 001 05/03/2021.
					2	May 17, 2021	SYSTEM	\$4,400.00	This adjustment is due to a missing certification for the sample 21SEVTR002, this adjustment will be reversed on a future estimate. Estimate 001 05/03/2021.
				OTHR - Tota	al			\$0.00	
			Other Item	Adjustment -	Total			\$0.00	
	0180 -	Total						\$0.00	
	0225	FLOWABLE BACKFILL	Overrun	Overrun		Sep 1, 2021	SYSTEM	(\$502.50)	
				Overrun - T	otal			(\$502.50)	
	0005		Overrun - T	otal				(\$502.50)	
	0225 -		Matarial		4	hur 40	OVOTEM	(\$502.50)	This adjustment off at the significal control of the significal control of the significant states of the significant state
	0250	CLASS B-1 CONCRETE (CULVERTS)	Material		4	Jun 16, 2021	SYSTEM	\$12,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Jun 16, 2021	SYSTEM	(\$12,460.00)	
					5	Jul 1, 2021	SYSTEM	\$12,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jul 1, 2021	SYSTEM	(\$12,460.00)	
					9	Sep 1, 2021	SYSTEM	\$12,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user reedv1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Sep 1, 2021	SYSTEM	(\$12,460.00)	
					11	Oct 1, 2021	SYSTEM	\$12,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Oct 1, 2021	SYSTEM	(\$12,460.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0250 -							\$0.00	
	0270	15 IN. PIPE CULVERT GROUP B	Overrun	Overrun		Jun 16, 2021	SYSTEM	(\$7,490.00)	
					9	Sep 1, 2021	SYSTEM	(\$12,198.00)	
					11	Oct 1, 2021	SYSTEM	\$19,688.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',107.00000 - 107.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0270 -							\$0.00	
	0280	18 IN. PIPE CULVERT GROUP	Overrun	Overrun	9	Sep 1, 2021	SYSTEM	(\$5,475.75)	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3340	0280	В	Overrun	Overrun	11	Oct 1, 2021	SYSTEM	\$5,475.75	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',111.75000 - 111.75000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0280 -	Total						\$0.00	
	0320	SEEDING - COOL SEASON MIXTURES	Material		11	Oct 1, 2021	SYSTEM	\$44,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Oct 1, 2021	SYSTEM	(\$44,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0320 -	Total						\$0.00	
	0330	SEDIMENT TRAP ROCK	Material		2	May 17, 2021	SYSTEM	\$2,516.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	May 17, 2021	SYSTEM	(\$2,516.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0330 -	Total						\$0.00	
	0340	ROCK DITCH CHECK							
		CHECK		OTHR	9	Sep 1, 2021	REEDV1	\$6,400.50	compensate the contractor when the rock ditch checks are removed. Estimate 009 20210901
		CILON		OTHR	10	Sep 1, 2021 Sep 17, 2021	REEDV1	\$6,400.50 (\$12,801.00)	ditch checks are removed. Estimate 009
		CILON		OTHR - Tota	10	2021 Sep 17,			ditch checks are removed. Estimate 009 20210901  This removes an adjustment from Estimate 0009 that was made to hold pay until the contractor removed the rock ditch check on highway J, the original adjustment was positive in error and this adjustment corrects the original adjustment6400.50 to remove the original adjustment and -6400.50 to correct the adjustment to hold pay to provide compensation to the contractor
		CILON	Adjustment		10 al	2021 Sep 17,		(\$12,801.00)	ditch checks are removed. Estimate 009 20210901  This removes an adjustment from Estimate 0009 that was made to hold pay until the contractor removed the rock ditch check on highway J, the original adjustment was positive in error and this adjustment corrects the original adjustment6400.50 to remove the original adjustment and -6400.50 to correct the adjustment to hold pay to provide compensation to the contractor
		CILON	Adjustment	OTHR - Tota	10 al Total	2021 Sep 17,		(\$12,801.00) (\$6,400.50)	ditch checks are removed. Estimate 009 20210901  This removes an adjustment from Estimate 0009 that was made to hold pay until the contractor removed the rock ditch check on highway J, the original adjustment was positive in error and this adjustment corrects the original adjustment6400.50 to remove the original adjustment and -6400.50 to correct the adjustment to hold pay to provide compensation to the contractor
		CILON	Adjustment  Other Item A	OTHR - Tota Adjustment -	10 al Total 10	2021 Sep 17, 2021	REEDV1	(\$12,801.00) (\$6,400.50) (\$6,400.50)	ditch checks are removed. Estimate 009 20210901  This removes an adjustment from Estimate 0009 that was made to hold pay until the contractor removed the rock ditch check on highway J, the original adjustment was positive in error and this adjustment corrects the original adjustment6400.50 to remove the original adjustment and -6400.50 to correct the adjustment to hold pay to provide compensation to the contractor
		CILON	Adjustment  Other Item A	OTHR - Tota Adjustment - Overrun Overrun - To	10 al Total 10	2021 Sep 17, 2021	REEDV1	(\$12,801.00) (\$6,400.50) (\$6,400.50) (\$1,353.41)	ditch checks are removed. Estimate 009 20210901  This removes an adjustment from Estimate 0009 that was made to hold pay until the contractor removed the rock ditch check on highway J, the original adjustment was positive in error and this adjustment corrects the original adjustment6400.50 to remove the original adjustment and -6400.50 to correct the adjustment to hold pay to provide compensation to the contractor
	0340 -		Other Item Overrun	OTHR - Tota Adjustment - Overrun Overrun - To	10 al Total 10	2021 Sep 17, 2021	REEDV1	(\$12,801.00) (\$6,400.50) (\$6,400.50) (\$1,353.41) (\$1,353.41)	ditch checks are removed. Estimate 009 20210901  This removes an adjustment from Estimate 0009 that was made to hold pay until the contractor removed the rock ditch check on highway J, the original adjustment was positive in error and this adjustment corrects the original adjustment6400.50 to remove the original adjustment and -6400.50 to correct the adjustment to hold pay to provide compensation to the contractor
J9S3340 -			Other Item Overrun	OTHR - Tota Adjustment - Overrun Overrun - To	10 al Total 10	2021 Sep 17, 2021	REEDV1	(\$12,801.00) (\$6,400.50) (\$6,400.50) (\$1,353.41) (\$1,353.41)	ditch checks are removed. Estimate 009 20210901  This removes an adjustment from Estimate 0009 that was made to hold pay until the contractor removed the rock ditch check on highway J, the original adjustment was positive in error and this adjustment corrects the original adjustment6400.50 to remove the original adjustment and -6400.50 to correct the adjustment to hold pay to provide compensation to the contractor