

Pay Estimate Created Date: September 2, 2021

Progress Estir 8	mate Number	Contract ID Prime Contractor	210219-C04 Ideker, Inc.	Pay Period Start Pay Period End	August 16, 2021 September 1, 202	Original Contract Amount Net Change Order Amount Current Contract Amount	\$4,357,163.79 \$188,165.38 \$4,545,329.17
Approval Date							By User
September 2, 2021		G	enerated and <i>i</i>	Approved (and shou	lld be considered D	raft) at the Project Office Level by	warrem1
September 2, 2021		Revie	wed and Appro	oved (and should be	considered Draft)	at the Resident Engineer Level by	warrem1
September 3, 2021				Reviewed and Appr	oved at the Central	Office Controllers Office Level by	ramses1
Original Comp	letion Date	Current Comple	tion Date	Actual Compl	letion Date	% of Current Contract Amou	int Complete
December	1, 2021	December 1,	2021			66.81%	

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	March 3, 2021	March 3, 2021	
Letting Date	February 19, 2021	February 19, 2021	
Notice to Proceed Date	May 3, 2021	May 3, 2021	
Work Began Date			

Contract Total Pa	ay For Estimate No. 8			
		This Estimate	Previous	To Date
210219-C04				
	Total Posted Items Pay	\$274,466.47	\$2,762,210.94	\$3,036,677.41
	Gross Item Adjustments	\$197,387.05	(\$88,585.83)	\$108,801.22
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$2,673,625.11	\$3,145,478.63
Contract Total Pa	avable This Estimate	\$471 853 52		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3275	0030	2031000	CLASS A EXCAVATION	CUYD	\$12.000	46	\$552.00
	0060	2063000	CLASS 3 EXCAVATION	CUYD	\$12.000	8.6	\$103.20
	0110	3040183	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	SQYD	\$10.500	1,500	\$15,750.00
	0120	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$10.500	525.3	\$5,515.65
	0130	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$11.650	3,616.1	\$42,127.57
	0140	4010150	TYPE A2 SHOULDER	SQYD	\$23.340	963.5	\$22,488.09
	0150	4019905	MISC.OPTIONAL PAVEMENT	SQYD	\$45.490	2,683.9	\$122,090.61
	0160	4019905	MISC.OPTIONAL TEMPORARY PAVEMENT	SQYD	\$28.490	202.3	\$5,763.53
	0210	6085008	PAVED APPROACH, 8 IN.	SQYD	\$62.700	189.8	\$11,900.46
	0240	6091041	CONCRETE GUTTER TYPE A	LF	\$96.250	20	\$1,925.00
	0260	6091052	CURB AND GUTTER TYPE B	LF	\$29.900	681.4	\$20,373.86
	0300	6097000	ROCK LINING	CUYD	\$225.000	4	\$900.00
	0390	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	EA	\$4,900.000	3	\$14,700.00
	0570	7250418	18 IN. PIPE GROUP C	LF	\$100.000	14	\$1,400.00
	0600	7320818A	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	EA	\$606.000	2	\$1,212.00
	0640	8061005	ROCK DITCH CHECK	LF	\$40.000	37	\$1,480.00
	0650	8061006	ALTERNATE DITCH CHECK	LF	\$13.000	16	\$208.00

Revision 4/1/2020 Page 1 of 39



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number	Contract ID Prime Contractor		Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount	\$4,357,163.79 \$188.165.38
8	Fillie Contractor	idekei, ilic.	Pay Period Elid	September 1, 2021	Current Contract Amount	\$4,545,329.17

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3275	5002	6191000	PAVEMENT EDGE TREATMENT	LF	\$7.100	370	\$2,627.00
	5003	6139901	MISC.CONCRETE PATCH FOR STORM SEWER CROSSING	LS	\$3,349.500	1	\$3,349.50
Project J	4P3275 - 1	Total					\$274,466.47
Overall -	Total						\$274 466 47

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
P3275	0030	CLASS A EXCAVATION	Price	71	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	46	\$0.12	\$5.52
	0040	EMBANKMENT IN PLACE	Material			-39,371	\$20.00	(\$787,420.00
	0040	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	39,371	\$20.00	\$787,420.00
	0040	EMBANKMENT IN PLACE	Overrun	Overrun	Quantity updated on CO 3, overrun negative adjustments are being paid back. \$189,900			\$189,900.00
	0050	COMPACTING EMBANKMENT	Material			-839	\$2.00	(\$1,678.00
	0050	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	839	\$2.00	\$1,678.00
	0110	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,500	\$0.18	\$270.00
	0110	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	Material			-1,500	\$10.50	(\$15,750.00
	0110	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1,500	\$10.50	\$15,750.00
	0120	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	189.8	\$0.09	\$17.08
	0120	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	133.2	\$0.09	\$11.99
	0120	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	202.3	\$0.09	\$18.21
	0120	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-5,162.2	\$10.50	(\$54,203.10
	0120	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	5,162.2	\$10.50	\$54,203.10
	0130	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,683.9	\$0.14	\$370.38
	0130	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	932.2	\$0.14	\$128.64
	0130	TYPE 5 AGGREGATE FOR	Material			-4,085.1	\$11.65	(\$47,591.42

Revision 4/1/2020 Page 2 of 39



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number
8 Contract ID 210219-C04 Pay Period Start August 16, 2021 September 1, 2021 September 1, 2021 Original Contract Amount September 1, 2021 Net Change Order Amount Current Contract Amount S4,357,163.79

Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.
						BASE (6 IN. THICK)	
\$47,591.42	\$11.65	4,085.1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		Material	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	0130
(\$22,488.09	\$23.34	-963.5			Material	TYPE A2 SHOULDER	0140
\$22,488.09	\$23.34	963.5	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		Material	TYPE A2 SHOULDER	0140
\$3,693.73			2,683.9 SQYD of SP190 21-13	Asphalt Cement Price Adjustment	Other Item Adjustment	MISC.	0150
\$691.67			2,683.90 SQYD of SP125 21-14.		Other Item Adjustment	MISC.	0150
(\$131,666.54	\$28.49	-4,621.5			Material	MISC.	0160
\$131,666.54	\$28.49	4,621.5	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.		Material	MISC.	0160
\$68.33	\$0.36	189.8	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		Price	PAVED APPROACH, 8 IN.	0210
(\$11,900.46	\$62.70	-189.8			Material	PAVED APPROACH, 8 IN.	0210
\$11,900.46	\$62.70	189.8	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		Material	PAVED APPROACH, 8 IN.	0210
(\$1,925.00	\$96.25	-20			Material	CONCRETE GUTTER TYPE A	0240
\$1,925.00	\$96.25	20	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate.		Material	CONCRETE GUTTER TYPE A	0240
(\$20,373.86	\$29.90	-681.4			Material	CURB AND GUTTER TYPE B	0260
\$20,373.86	\$29.90	681.4	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user schnod1 overridding Payment Estimate Exception 37 on the current Payment Estimate.		Material	CURB AND GUTTER TYPE B	0260
(\$1,700.00	\$850.00	-2			Material	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	0420
\$1,700.00	\$850.00	2	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate.		Material	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	0420
(\$11,794.00	\$1.00	-11,794			Material	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	0480

Revision 4/1/2020 Page 3 of 39



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number
8

Contract ID 210219-C04 Pay Period Start August 16, 2021 Original Contract Amount S4,357,163.79
Prime Contractor Ideker, Inc. Pay Period End September 1, 2021 September 1, 2021 Original Contract Amount Current Contract Amount S4,357,163.79
\$ 188,165.38 Original Contract Amount Current Contract Amount S4,545,329.17

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3275	0480	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 46 on the current Payment Estimate.	11,794	\$1.00	\$11,794.00
	0490	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material			-14,884	\$1.00	(\$14,884.00)
	0490	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 47 on the current Payment Estimate.	14,884	\$1.00	\$14,884.00
	0570	18 IN. PIPE GROUP C	Material			-14	\$100.00	(\$1,400.00)
	0570	18 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	14	\$100.00	\$1,400.00
	0590	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material			-2	\$606.00	(\$1,212.00)
	0590	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	2	\$606.00	\$1,212.00
	0600	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material			-2	\$606.00	(\$1,212.00)
	0600	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user schnod1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	2	\$606.00	\$1,212.00
	0640	ROCK DITCH CHECK	Overrun			-37	\$40.00	(\$1,480.00)
	0650	ALTERNATE DITCH CHECK	Material			-16	\$13.00	(\$208.00)
	0650	ALTERNATE DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	16	\$13.00	\$208.00
	0670	TEMPORARY SEEDING AND MULCHING	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1605.00000 - 1605.00000, 'is applied (if non-zero).	2.3	\$1,605.00	\$3,691.50
	5002	PAVEMENT EDGE TREATMENT	Material			-370	\$7.10	(\$2,627.00)
	5002	PAVEMENT EDGE TREATMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0038) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	370	\$7.10	\$2,627.00
J4S3278	1120	GRAVEL (A)	Material			-118	\$87.92	(\$10,374.56)
	1120	GRAVEL (A)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 6 on	118	\$87.92	\$10,374.56

Revision 4/1/2020 Page 4 of 39



Pay Estimate Created Date: September 2, 2021

Progress Estimate Number
8

Contract ID Prime Contractor Ideker, Inc.
Pay Period Start August 16, 2021 September 1, 2021 September 1, 2021 Pay Period End September 1, 2021 September 1, 2021 September 1, 2021 Net Change Order Amount Current Contract Amount Current Contract Amount \$4,357,163.79

et er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
78					the current Payment Estimate.			
	1140	TACK COAT	Material			-93	\$2.50	(\$232.50
	1140	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	93	\$2.50	\$232.5
	1150	3 IN. CONCRETE MEDIAN STRIP	Material			-11.3	\$298.60	(\$3,374.1
	1150	3 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	11.3	\$298.60	\$3,374.1
	1320	12 IN. PIPE GROUP C	Material			-50	\$54.00	(\$2,700.0
	1320	12 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate.	50	\$54.00	\$2,700.0
	1330	18 IN. PIPE GROUP C	Material			-50	\$65.00	(\$3,250.0
	1330	18 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	50	\$65.00	\$3,250.0
	1340	SEEDING - COOL SEASON MIXTURES	Material			-0.2	\$5,940.00	(\$1,188.0
	1340	SEEDING - COOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 53 on the current Payment Estimate.	0.2	\$5,940.00	\$1,188.0
	1350	ROCK DITCH CHECK	Material			-84	\$40.00	(\$3,360.0
	1350	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	84	\$40.00	\$3,360.0
	1380	CONCRETE FOOTINGS, EMBEDDED	Material			-0.1	\$1,650.00	(\$165.0
	1380	CONCRETE FOOTINGS, EMBEDDED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 58 on the current Payment Estimate.	0.1	\$1,650.00	\$165.0
	1420	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material			-2,367.5	\$58.85	(\$139,327.3
	1420	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	2,367.5	\$58.85	\$139,327.3
	1430	TACK COAT	Material			-8,950	\$2.50	(\$22,375.0
	1430	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user schnod1	8,950	\$2.50	\$22,375.00

Revision 4/1/2020 Page 5 of 39



Pay Estimate Created Date: September 2, 2021

Progr	ress Es	stimate Number 8	Contract I Prime Cor			Pay Period Start Pay Period End	August 16, 2021 September 1, 2021	Net Cha	Contract Ar inge Order A Contract An	mount \$1	4,357,163.79 88,165.38 4,545,329.17
Project Number	Line No.	Item Descrip	tion	Adjustment Type	Other Item Adjustmen Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3278							ayment Estimate Exc the current Payment I				
Total											\$197,387.05

Revision 4/1/2020 Page 6 of 39



					Cor	ntract Project Informatio	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3275	FAF 92-1(35)	Intersection improvements	92	PLATTE	at intersection of Rte. 45 Sp	our	
J4S3278	FAS S302(80)	Resurface	45	PLATTE	from Route 92 to Route 45		
Totals by	Job Numbe	ers					
J4P3275		d Item Pay Item Adjustme		Item Pay	This Estimate \$274,466.47 \$197,387.05 \$471,853.52	Previous \$1,737,674.80 (\$135,374.75) \$1,602,300.05	To Date \$2,012,141.27 \$62,012.30 \$2,074,153.57
	Liquid	tive centive dated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J4S3278		d Item Pay Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$1,024,536.14 \$46,788.92 \$1,071,325.06	To Date \$1,024,536.14 \$46,788.92 \$1,071,325.06
	Liquid	tive centive dated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 7 of 39



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 3040183, Project Item Line Number 0110, Material Set 304018396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 3040504, Project Item Line Number 0120, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 3040506, Project Item Line Number 0130, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 3101002, Project Item Line Number 1120, Material Set 310100296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 4010150, Project Item Line Number 0140, Material Set 401015096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 4010150, Project Item Line Number 0140, Material Set 401015096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 4010150, Project Item Line Number 0140, Material Set 401015096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 4019905, Project Item Line Number 0160, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 4020520, Project Item Line Number 1420, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 4071005, Project Item Line Number 1140, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 4071005, Project Item Line Number 1140, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 4071005, Project Item Line Number 1430, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 4071005, Project Item Line Number 1430, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,	No Remark was entered by Engineer	schnod1	Overridden

Revision 4/1/2020 Page 8 of 39



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 100510CPCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 1005GFCPLS - PCCP Grade F LS/DO, Acceptance Action Generic 1005GFCPLS is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 100510OPTLD1 - PCCP 1" Max LS/DO, Acceptance Action Generic 100510OPTLD1 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 100507CPCMLD - PCCP or Masonry 0-3/4" Max LS/DO, Acceptance Action Generic 100507CPCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 100507CPCMLD - PCCP or Masonry 0-3/4" Max LS/DO, Acceptance Action Generic 100507CPCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 100510OPTLD1 - PCCP 1" Max LS/DO, Acceptance Action Generic 100510OPTLD1 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 1005GFCPLS - PCCP Grade F LS/DO, Acceptance Action Generic 1005GFCPLS is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6174000A, Project Item Line Number 0420, Material Set 6174000A96, Material 0617MBPKBT.1PC - One Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.1PC is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6191000, Project Item Line Number 5002, Material Set 619100096, Material 0619PET - Material for Pavement Edge Treatment, Acceptance Action Generic 0619PET is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6205301B, Project Item Line Number 0480, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6205303B, Project Item Line Number 0490, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 7250412, Project Item Line	No Remark was entered by Engineer	schnod1	Overridden

Revision 4/1/2020 Page 9 of 39



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Number 1320, Material Set 725041296, Material 1020CPCSZC.012 - CulvPipe Zn Ctd Corrug Stl 12" 300mm, Acceptance Action Generic 1020CPCSZC.012 is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 7250418, Project Item Line Number 1330, Material Set 725041896, Material 1020CPCSZC.018 - CulvPipe Zn Ctd Corrug Stl 18" 450mm, Acceptance Action Generic 1020CPCSZC.018 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 7250418, Project Item Line Number 0570, Material Set 725041896, Material 1020CPCSZC.018 - CulvPipe Zn Ctd Corrug Stl 18" 450mm, Acceptance Action Generic 1020CPCSZC.018 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 7320618A, Project Item Line Number 0590, Material Set 7320618A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 7320818A, Project Item Line Number 0600, Material Set 7320818A96, Material 1020ESZN - Flared End Section Zinc galvanized steel, Acceptance Action Generic 1020ESZN is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 8051000A, Project Item Line Number 1340, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 8051000A, Project Item Line Number 1340, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 8051000A, Project Item Line Number 1340, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 8061005, Project Item Line Number 1350, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 8061006, Project Item Line Number 0650, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 9031010, Project Item Line Number 1380, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0640, Contract Line Item Number 0640, Item 8061005, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4S3278, Project Item Line Number 1200, Contract Line Item Number 1200, Item 6161031, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0010, Contract Line Item Number 0010, Item 2013000, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0070, Contract Line Item Number 0070, Item 2071000, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged

Revision 4/1/2020 Page 10 of 39



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)		
10219-C04	J4P3275	0001	0010	2013000	CLEARING AND GRUBBING	2.00	0.00	2.00	ACRE	3.00	\$9,000.00	\$27,000.00		
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.65	\$69,665.00	\$45,282.25		
		0001	0030	2031000	CLASS A EXCAVATION	8,110.00	0.00	8,110.00	CUYD	1,053.00	\$12.00	\$12,636.00		
		0001	0040	2035500	EMBANKMENT IN PLACE	29,876.00	13,000.00	42,876.00	CUYD	39,371.00	\$20.00	\$787,420.00		
		0001	0050	2036000	COMPACTING EMBANKMENT	6,758.00	0.00	6,758.00	CUYD	839.00	\$2.00	\$1,678.00		
		0001	0060	2063000	CLASS 3 EXCAVATION	75.00	0.00	75.00	CUYD	75.00	\$12.00	\$900.0		
		0001	0070	2071000	LINEAR GRADING CLASS 1	30.90	0.00	30.90	STA	33.90	\$550.00	\$18,645.0		
		0001	0090	2142000	FURNISHING ROCK FILL	2,040.00	0.00	2,040.00	CUYD	907.00	\$19.20	\$17,414.4		
		0001	0100	2143000	PLACING ROCK FILL	2,040.00	0.00	2,040.00	CUYD	907.00	\$11.00	\$9,977.0		
			3040183	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	1,500.00	0.00	1,500.00	SQYD	1,500.00	\$10.50	\$15,750.0			
		0001	0120	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	6,498.00	0.00	6,498.00	SQYD	5,162.20	\$10.50	\$54,203.1		
		0001	0130	3040506	16 TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	13,671.00	0.00	0.00 13,671.00 0.00 2,303.80	SQYD	4,085.10	\$11.65	\$47,591.4		
		0001	0140	4010150	TYPE A2 SHOULDER	2,303.80	0.00			963.50	\$23.34	\$22,488.0		
		0001	0150	4019905	MISC.OPTIONAL PAVEMENT	10,728.50	0.00	10,728.50	SQYD	3,152.90		\$143,425.42		
		0001	0160	4019905	MISC.OPTIONAL TEMPORARY PAVEMENT	4,621.50	0.00	4,621.50	SQYD	4,621.50	\$28.49	\$131,666.54		
		0001	0170	5029905	MISC.TINTED CONCRETE PAVEMENT (8 IN. NON-	576.60	0.00	576.60	SQYD	0.00	\$90.25	\$0.0		
					REINFORCED)									
		0001	0180	6072010	WOVEN WIRE FENCE	987.00	0.00	987.00	LF	0.00	\$18.75	\$0.00		
		0001	0190	6079902	MISC.US BOP Drive Gate	1.00	0.00	1.00	EA	0.00	\$2,910.00	\$0.00		
		0001	0200	6083006	6 IN. CONCRETE MEDIAN STRIP	976.80	0.00	976.80	SQYD	0.00	\$55.35	\$0.0		
		0001	0210	6085008	PAVED APPROACH, 8 IN.	763.40	0.00	763.40	SQYD	189.80	\$62.70	\$11,900.4		
		0001	0220	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	21.00	0.00	21.00	LF	0.00	\$52.00	\$0.0		
		0001	0230	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	39.00	0.00	39.00	LF	0.00	\$45.90	\$0.0		
		0001	0240	6091041	CONCRETE GUTTER TYPE A	127.00	0.00	127.00	LF	20.00	\$96.25	\$1,925.0		
		0001	0250	6091051	CURB AND GUTTER TYPE A	192.00	0.00	192.00	LF	0.00	\$34.85	\$0.0		
		0001	0260	6091052	CURB AND GUTTER TYPE B	1,413.00	0.00	1,413.00	LF	681.40	\$29.90	\$20,373.8		
		0001	0270	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	267.00	0.00	267.00	LF	0.00	\$7.70	\$0.0		
		0001	0280	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	192.00	0.00	192.00	LF	0.00	\$8.90	\$0.0		
		0001	0290	6092031	CONCRETE CURB LOW PROFILE TYPE E	355.00	0.00	355.00	LF	0.00	\$27.20	\$0.0		
		0001	0300	6097000	ROCK LINING	6.00	0.00	6.00	CUYD	6.00	\$225.00	\$1,350.0		
		0001	0310	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	5.00	0.00	5.00	EA	5.00	\$2,000.00	\$10,000.0		
		0001	0320	6122020	REPLACEMENT SAND BARREL	8.00	0.00	8.00	EA	3.00	\$330.00	\$990.0		
		0001	0330	6122030	IMPACT ATTENUATOR (RELOCATION)	10.00	0.00	10.00	EA	3.00	\$400.00	\$1,200.0		
		0001	0340	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.0		
		0001	0350	6161005	CONSTRUCTION SIGNS	637.00	0.00	637.00	SQFT	440.00	\$5.00	\$2,200.0		
		0001	0360	6161008	ADVANCED WARNING RAIL SYSTEM	3.00	0.00	3.00	EA	3.00	\$50.00	\$150.0		
		0001	0370	6161025	CHANNELIZER (TRIM LINE)	141.00	0.00	141.00	EA	95.00	\$23.00	\$2,185.0		
		0001	0380	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	0.00	\$50.00	\$0.0		
		0001	0390	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	7.00	0.00	7.00	EA	3.00	\$4,900.00	\$14,700.0		
		0001	0400	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	4.00	\$900.00	\$3,600.0		
		0001	0410	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR	7,925.00	0.00	7,925.00	LF	4,427.50	\$33.00	\$146,107.5		
		0001	0420	6174000A	FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	2.00	0.00	2.00	EA	2.00	\$850.00	\$1,700.0		
						7,200.00	0.00	7,200.00	LF	2,792.00	\$13.00	\$36,296.0		
								5.00			EA	2,792.00	\$400.00	
		0001	0440	01/302UA	TRANSITION	5.00	0.00	5.00		2.00	\$400.00	\$800.0		
		0001	0450	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$343,077.28	\$0.0		
		0001	0451	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$318,927.28	\$318,927.2		

Page 11 of 39 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210219-C04	J4P3275	0001	0460	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0470	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	48.00	0.00	48.00	EA	0.00	\$50.00	\$0.00
		0001	0480	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	13,131.00	0.00	13,131.00	LF	11,794.00	\$1.00	\$11,794.00
		0001	0490	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	24,834.00	0.00	24,834.00	LF	14,884.00	\$1.00	\$14,884.00
		0001	0500	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	5,679.00	0.00	5,679.00	LF	0.00	\$0.15	\$0.00
		0001	0510	6205902A	MARKING PAINT, TYPE L BEADS 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,125.00	0.00	8,125.00	LF	0.00	\$0.18	\$0.00
		0001	0520	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,107.00	0.00	2,107.00	LF	0.00	\$0.18	\$0.00
		0001	0530	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	432.00	0.00	432.00	LF	0.00	\$3.00	\$0.00
		0001	0540	6207001	PAVEMENT MARKING REMOVAL	32,031.00	0.00	32,031.00	LF	16,951.00	\$0.25	\$4,237.75
		0001	0550	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,205.00	0.00	1,205.00	SQYD	642.00	\$3.35	\$2,150.70
		0001	0560	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$5,000.00	\$2,500.00
		0001	0570	7250418	18 IN. PIPE GROUP C	35.00	0.00	35.00	LF	14.00	\$100.00	\$1,400.00
		0001	0580	7261018	18 IN. PIPE GROUP A	74.00	0.00	74.00	LF	74.00	\$73.00	\$5,402.00
		0001	0590	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$606.00	\$1,212.00
		0001	0600	7320818A	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	4.00	0.00	4.00	EA	2.00	\$606.00	\$1,212.00
		0001	0610	8051000A	SEEDING - COOL SEASON MIXTURES	7.40	0.00	7.40	ACRE	0.00	\$1,605.00	\$0.00
		0001	0620	8061003	SEDIMENT TRAP EXCAVATION	191.00	0.00	191.00	CUYD	0.00	\$8.45	\$0.00
		0001	0630	8061004	SEDIMENT TRAP ROCK	51.00	0.00	51.00	CUYD	0.00	\$90.00	\$0.00
		0001	0640	8061005	ROCK DITCH CHECK	63.00	0.00	63.00	LF	177.00	\$40.00	\$7,080.00
		0001	0650	8061006	ALTERNATE DITCH CHECK	189.00	0.00	189.00	LF	16.00	\$13.00	\$208.00
		0001	0660	8061016	SEDIMENT REMOVAL	105.00	0.00	105.00	CUYD	0.00	\$13.00	\$0.00
		0001	0670	8061017	TEMPORARY SEEDING AND MULCHING	0.70	2.30	3.00	ACRE	3.00	\$1,605.00	\$4,815.00
		0001	0680	8061019	SILT FENCE	5,955.00	0.00	5,955.00	LF	4,879.00	\$3.00	\$14,637.00
		0001	0690	8064134	TYPE 1D EROSION CONTROL BLANKET	8,624.00	0.00	8,624.00	SQYD	0.00	\$1.46	\$0.00
		0001	0700	8064135	TYPE 2A EROSION CONTROL BLANKET	2,123.00	0.00	2,123.00	SQYD	0.00	\$1.39	\$0.00
		0001	0710	8064137	TYPE 2C EROSION CONTROL BLANKET	14,850.00	0.00	14,850.00	SQYD	0.00	\$1.39	\$0.00
		0001	0720	8064138	TYPE 2D EROSION CONTROL BLANKET	9,964.00	0.00	9,964.00	SQYD	0.00	\$1.46	\$0.00
		0010	0730	6061060	MGS GUARDRAIL	1,238.00	0.00	1,238.00	LF	0.00	\$21.00	\$0.00
		0010	0740	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	2,113.00	0.00	2,113.00	LF	0.00	\$25.00	\$0.00
		0010	0750	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$800.00	\$0.00
		0010	0760	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	9.00	0.00	9.00	EA	0.00	\$2,433.00	\$0.00
		0020	0770	9011030	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	7.00	0.00	7.00	EA	0.00	\$1,793.00	\$0.00
		0020	0780	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	3.00	0.00	3.00	EA	0.00	\$2,987.50	\$0.00
		0020	0790	9011115	BRACKET ARM, 15 FT. OR 4.6 M	10.00	0.00	10.00	EA	0.00	\$852.50	\$0.00
		0020	0800	9011311	LUMINAIRE, LED-A	7.00	0.00	7.00	EA	0.00	\$473.00	\$0.00
		0020	0810	9011312	LUMINAIRE, LED-B	3.00	0.00	3.00	EA	0.00	\$205.00	\$0.00
		0020	0820	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	0.00	\$7,838.00	\$0.00
		0020	0830	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	100.00	0.00	100.00	LF	0.00	\$13.56	\$0.00
		0020	0840	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	190.00	0.00	190.00	LF	0.00	\$15.00	\$0.00
		0020	0850	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	20.00	0.00	20.00	LF	0.00	\$15.52	\$0.00
		0020	0860	9015010	TRENCHING TYPE I	92.00	0.00	92.00	LF	0.00	\$10.05	\$0.00
		0020	0870	9016110	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	0.00	\$513.40	\$0.00
		0020	0880	9017002	CABLE, 2 AWG 1 CONDUCTOR	330.00	0.00	330.00	LF	0.00	\$3.30	\$0.00
		0020	0890	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	990.00	0.00	990.00	LF	0.00	\$1.76	\$0.00
		0020	0900	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	2,300.00	0.00	2,300.00	LF	0.00	\$3.27	\$0.00



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
210219-C04	J4P3275	0020	0910	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	7.00	0.00	7.00	EA	Qty 0.00	\$970.00	\$0.00
		0020	0920	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	3.00	0.00	3.00	EA	0.00	\$970.00	\$0.00
		0020	0930	9018610	POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE,	1.00	0.00	1.00	EA	0.00	\$5,434.00	\$0.00
					LIGHTING ONLY							
		0040	0940	9031010	CONCRETE FOOTINGS, EMBEDDED	0.40	0.00	0.40	CUYD	0.00	\$1,650.00	\$0.00
		0040	0950	9031210	STRUCTURAL STEEL POSTS	190.00	0.00	190.00	LB	0.00	\$4.00	\$0.00
		0040	0960	9031220	PIPE POSTS	692.00	0.00	692.00	LB	0.00	\$5.00	\$0.00
		0040	0970	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	6.00	0.00	6.00	EA	0.00	\$225.00	\$0.00
		0040	0980	9031270A	2 IN. PSST POST - 12 GA.	277.00	0.00	277.00	LF	0.00	\$11.00	\$0.00
		0040	0990	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	48.00	0.00	48.00	LF	0.00	\$19.00	\$0.00
		0040	1000	9031272	2.25 IN. PSST POST - 12 GA.	36.00	0.00	36.00	LF	0.00	\$11.00	\$0.00
		0040	1010	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	18.00	0.00	18.00	LF	0.00	\$47.00	\$0.00
		0040	1020	9031280	2.5 IN. PSST POST - 12 GA.	227.00	0.00	227.00	LF	0.00	\$12.00	\$0.00
		0040	1030	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	42.00	0.00	42.00	LF	0.00	\$51.00	\$0.00
		0040	1040	9035004A	SH-FLAT SHEET	313.00	0.00	313.00	SQFT	0.00	\$20.00	\$0.00
		0040	1050	9035011A	ST-STRUCTURAL	66.00	0.00	66.00	SQFT	0.00	\$23.00	\$0.00
		0040	1060	9035069A	SHF-FLAT SHEET FLUORESCENT	75.00	0.00	75.00	SQFT	0.00	\$23.00	\$0.00
		0040	1070	9039902	MISC.EACH	10.00	0.00	10.00	EA	0.00	\$50.00	\$0.00
		0001	5001	6189901	MISC.CONTRACT BOND PAYMENT	0.00	1.00	1.00	LS	1.00	\$24,150.00	\$24,150.00
		0001	5002	6191000	PAVEMENT EDGE TREATMENT	0.00	370.00	370.00	LF	370.00	\$7.10	\$2,627.00
		0001	5003	6139901	MISC.CONCRETE PATCH FOR STORM SEWER CROSSING	0.00	1.00	1.00	LS	1.00	\$3,349.50	\$3,349.50
	Project J	1P3275 - To	otal Value	Posted to D	ate as of Report Generated Date							\$2,012,141.26
	J4S3278	0001	1080	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,904.00	\$2,904.00
				2022010		1.00						Ψ2,001.00
		0001	1090	2031000	CLASS A EXCAVATION	120.00	0.00	120.00	CUYD	0.00	\$88.00	\$0.00
		0001			CLASS A EXCAVATION EMBANKMENT IN PLACE							
			1090	2031000		120.00	0.00	120.00	CUYD	0.00	\$88.00	\$0.00
		0001	1090	2031000 2035500	EMBANKMENT IN PLACE	120.00 370.00	0.00	120.00 370.00	CUYD	0.00	\$88.00 \$48.00	\$0.00 \$0.00
		0001	1090 1100 1110	2031000 2035500 2063000	EMBANKMENT IN PLACE CLASS 3 EXCAVATION	120.00 370.00 24.00	0.00 0.00 0.00	120.00 370.00 24.00	CUYD CUYD	0.00 0.00 24.00	\$88.00 \$48.00 \$12.00	\$0.00 \$0.00 \$288.00
		0001 0001 0001	1090 1100 1110 1120	2031000 2035500 2063000 3101002	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A)	120.00 370.00 24.00 396.00	0.00 0.00 0.00 -278.00	120.00 370.00 24.00 118.00	CUYD CUYD CUYD TONS	0.00 0.00 24.00 118.00	\$88.00 \$48.00 \$12.00 \$87.92	\$0.00 \$0.00 \$288.00 \$10,374.56
		0001 0001 0001 0001	1090 1100 1110 1120 1130	2031000 2035500 2063000 3101002 4011209	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	120.00 370.00 24.00 396.00 124.30	0.00 0.00 0.00 -278.00 0.00	120.00 370.00 24.00 118.00 124.30	CUYD CUYD CUYD TONS	0.00 0.00 24.00 118.00 124.30	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19	\$0.00 \$0.00 \$288.00 \$10,374.56 \$10,837.72
		0001 0001 0001 0001 0001	1090 1100 1110 1120 1130 1140	2031000 2035500 2063000 3101002 4011209 4071005	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT	120.00 370.00 24.00 396.00 124.30 93.00	0.00 0.00 0.00 -278.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00	CUYD CUYD TONS TONS GAL	0.00 0.00 24.00 118.00 124.30 93.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50	\$0.00 \$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50
		0001 0001 0001 0001 0001 0001	1090 11100 11110 1120 1130 1140	2031000 2035500 2063000 3101002 4011209 4071005 6083003	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP	120.00 370.00 24.00 396.00 124.30 93.00	0.00 0.00 0.00 -278.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30	CUYD CUYD TONS TONS GAL SQYD	0.00 0.00 24.00 118.00 124.30 93.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50	\$0.00 \$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18
		0001 0001 0001 0001 0001 0001	1090 1100 1110 11120 1130 1140 1150	2031000 2035500 2063000 3101002 4011209 4071005 6083003 6161005	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS	120.00 370.00 24.00 396.00 124.30 93.00 11.30	0.00 0.00 0.00 -278.00 0.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00	CUYD CUYD TONS TONS GAL SQYD	0.00 0.00 24.00 118.00 124.30 93.00 11.30 220.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00	\$0.00 \$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18
		0001 0001 0001 0001 0001 0001 0001	1090 11100 11110 11120 1130 1140 1150 1160	2031000 2035500 2063000 3101002 4011209 4071005 6063003 6161005 6161009	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY	120.00 370.00 24.00 396.00 124.30 93.00 11.30 393.00 5.00	0.00 0.00 -278.00 0.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00 5.00	CUYD CUYD TONS TONS GAL SQYD SQFT	0.00 0.00 24.00 118.00 124.30 93.00 11.30 220.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00	\$0.00 \$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00
		0001 0001 0001 0001 0001 0001 0001 000	1090 11100 11110 11120 1130 1140 1150 1160 1170	2031000 2035500 2063000 3101002 4071005 6083003 6161005 6161009	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT	120.00 370.00 24.00 396.00 124.30 93.00 11.30 393.00 5.00	0.00 0.00 -278.00 0.00 0.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00 5.00 7.00	CUYD CUYD TONS TONS GAL SQYD SQFT EA	0.00 0.00 24.00 118.00 124.30 93.00 11.30 220.00 2.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$25.00	\$0.00 \$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00
		0001 0001 0001 0001 0001 0001 0001 000	1090 11100 11110 11120 1130 1140 1150 1160 1170 1180	2031000 2035500 2063000 3101002 4011209 4071005 6083003 6161005 6161009 6161024	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE)	120.00 370.00 24.00 396.00 124.30 93.00 11.30 393.00 5.00 7.00	0.00 0.00 -278.00 0.00 0.00 0.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00	CUYD CUYD TONS TONS GAL SQYD SQFT EA EA	0.00 0.00 24.00 118.00 124.30 93.00 11.30 220.00 0.00 80.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00	\$0.00 \$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00
		0001 0001 0001 0001 0001 0001 0001 000	1090 1100 1110 1110 1120 1130 1140 1150 1160 1170 1180 1190	2031000 2035500 2063000 3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	120.00 370.00 24.00 396.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00	0.00 0.00 -278.00 0.00 0.00 0.00 0.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00	CUYD CUYD TONS TONS GAL SQYD SQFT EA EA EA	0.00 24.00 118.00 124.30 93.00 11.30 220.00 0.00 80.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$75.00	\$0.00 \$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$0.00 \$1,650.00
		0001 0001 0001 0001 0001 0001 0001 000	1090 1100 1110 1110 1120 1130 1140 1150 1160 1170 1180 1190 1200	2031000 2035500 2063000 3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R	120.00 370.00 24.00 396.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00	0.00 0.00 -278.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00	CUYD CUYD TONS TONS GAL SQYD SQFT EA EA EA EA	0.00 24.00 118.00 124.30 93.00 11.30 220.00 2.00 0.00 80.00 22.00 3.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$75.00	\$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$0.00 \$80.00 \$1,650.00
		0001 0001 0001 0001 0001 0001 0001 000	1090 1100 1110 11120 1130 1140 1150 1160 1170 1180 1190 1210	2031000 2035500 2063000 3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MOBILIZATION	120.00 370.00 24.00 396.00 124.30 93.00 11.30 393.00 7.00 93.00 17.00 3.00	0.00 0.00 0.00 -278.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00	CUYD CUYD TONS TONS GAL SQYD SQFT EA EA EA LS	0.00 0.00 24.00 118.00 124.30 93.00 11.30 220.00 0.00 80.00 22.00 3.00 1.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$75.00 \$1,000.00	\$0.00 \$286.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$0.00 \$1,650.00 \$12,551.00
		0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	1090 1100 1110 11120 1130 1140 1150 1160 1170 1180 1190 1210 1220 1230	2031000 2035500 2063000 3101002 4011209 4071005 6063003 6161005 6161009 6161024 6161025 6161031 6161098A 6181000 6200033	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	120.00 370.00 24.00 396.00 124.30 93.00 11.30 5.00 7.00 93.00 17.00 3.00 1.00	0.00 0.00 -278.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00 7.00 93.00 17.00 3.00 1.00	CUYD CUYD TONS TONS GAL SQYD SQFT EA EA EA EA EA EA	0.00 0.00 24.00 118.00 124.30 93.00 11.30 220.00 0.00 80.00 22.00 3.00 1.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00.00	\$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$0.00 \$1,650.00 \$3,000.00
		0001 0001 0001 0001 0001 0001 0001 000	1090 1100 1110 11120 1130 1140 1150 1160 1170 1180 1190 1210 1220 1230 1240	2031000 2035500 2063000 3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A 6181000 6200033 6206000C	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	120.00 370.00 24.00 396.00 124.30 93.00 11.30 393.00 7.00 93.00 17.00 3.00 1.00 1.00 19,047.00	0.00 0.00 0.00 -278.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00 1.00 1.00 19,047.00	CUYD CUYD CUYD TONS TONS GAL SQYD SQFT EA EA LS EA LS EA	0.00 0.00 24.00 118.00 124.30 93.00 11.30 220.00 0.00 80.00 22.00 3.00 1.00 1.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000 \$1.000	\$0.00 \$286.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$0.00 \$11,650.00 \$12,551.00 \$800.00
		0001 0001 0001 0001 0001 0001 0001 000	1090 1100 1110 11120 1130 1140 1150 1160 1170 1180 1200 1210 1220 1230 1240 1250	2031000 2035500 2063000 3101002 4011209 4071005 6063003 6161005 6161024 6161025 6161031 6161098A 6181000 6200033 6206000C 6206001C	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	120.00 370.00 24.00 396.00 124.30 93.00 11.30 5.00 7.00 93.00 17.00 3.00 1.00 1.00 1.00 19,047.00	0.00 0.00 -278.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00 7.00 93.00 17.00 3.00 1.00 1.00 19,047.00	CUYD CUYD TONS TONS GAL SQYD SQFT EA EA EA EA LS EA LS EA	0.00 24.00 118.00 124.30 93.00 11.30 220.00 2.00 0.00 80.00 22.00 3.00 1.00 19,047.00 7,377.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$1.00 \$1.00 \$0.10	\$0.00 \$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$0.00 \$1,650.00 \$3,000.00 \$12,551.00 \$800.00 \$12,757.70
		0001 0001 0001 0001 0001 0001 0001 000	1090 1100 1110 1110 11120 1130 1140 1150 1160 1170 1180 1200 1210 1220 1240 1250 1260 1270 1280	2031000 2035500 2063000 3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A 6181000 6200033 6206000C 6206001C 6206108A 6221001	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	120.00 370.00 24.00 396.00 124.30 93.00 11.30 393.00 7.00 93.00 17.00 1.00 1.00 1.00 1.00 1.00 1.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00 1.00 1.00 1.00 1.00 19.047.00 7,377.00 112.00 24.00	CUYD CUYD CUYD TONS TONS GAL SQYD SQFT EA EA EA LS EA LF LF LF SQYD	0.00 0.00 24.00 118.00 124.30 93.00 11.30 220.00 0.00 80.00 2.00 1.00 1.00 1.00 1.00 19.047.00 7,377.00 112.00 24.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$1.00 \$75.00 \$100.00 \$100.00 \$100.00 \$100.00 \$100.00	\$0.00 \$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$0.00 \$3,000.00 \$1,650.00 \$41,904.70 \$737.70
		0001 0001 0001 0001 0001 0001 0001 000	1090 1100 1110 11120 11130 1140 1150 1160 1170 1180 1190 1210 1220 1230 1240 1250 1260	2031000 2035500 2063000 3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A 6181000 6200033 6206000C 6206001C 6206108A 6206124A	EMBANKMENT IN PLACE CLASS 3 EXCAVATION GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	120.00 370.00 24.00 396.00 124.30 93.00 11.30 393.00 7.00 93.00 17.00 19.047.00 19,047.00 112.00 24.00	0.00 0.00 -278.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	120.00 370.00 24.00 118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00 1.00 1.00 1.00 19,047.00 7,377.00 112.00	CUYD CUYD CUYD TONS GAL SQYD SQFT EA EA EA LS EA LS EA LF LF	0.00 0.00 24.00 118.00 124.30 93.00 11.30 220.00 0.00 80.00 22.00 3.00 1.00 1.00 19,047.00 7,377.00 112.00	\$88.00 \$48.00 \$12.00 \$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$1.00 \$1.00 \$0.10 \$0.10 \$0.50	\$0.00 \$0.00 \$288.00 \$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$0.00 \$1,650.00 \$3,000.00 \$12,551.00 \$800.00 \$12,551.00 \$800.00 \$1,904.70 \$737.70

Revision 4/1/2020 Page 13 of 39



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210219-C04	J4S3278	0001	1310	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.00
		0001	1320	7250412	12 IN. PIPE GROUP C	50.00	0.00	50.00	LF	50.00	\$54.00	\$2,700.00
		0001	1330	7250418	18 IN. PIPE GROUP C	50.00	0.00	50.00	LF	50.00	\$65.00	\$3,250.00
		0001	1340	8051000A	SEEDING - COOL SEASON MIXTURES	0.50	-0.30	0.20	ACRE	0.20	\$5,940.00	\$1,188.00
		0001	1350	8061005	ROCK DITCH CHECK	98.00	-14.00	84.00	LF	84.00	\$40.00	\$3,360.00
		0001	1360	8061016	SEDIMENT REMOVAL	21.00	-21.00	0.00	CUYD	0.00	\$13.00	\$0.00
		0001	1370	8061019	SILT FENCE	792.00	-752.00	40.00	LF	40.00	\$4.70	\$188.00
		0001	1380	9031010	CONCRETE FOOTINGS, EMBEDDED	0.10	0.00	0.10	CUYD	0.10	\$1,650.00	\$165.00
		0001	1390	9031220	PIPE POSTS	70.00	0.00	70.00	LB	70.00	\$5.00	\$350.00
		0002	1400	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	5,419.50	399.90	5,819.40	TONS	5,819.40	\$59.61	\$346,894.43
		0002	1410	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	8,564.20	-1,045.40	7,518.80	TONS	7,518.80	\$56.21	\$422,631.75
		0002	1420	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	2,280.50	87.00	2,367.50	TONS	2,367.50	\$58.85	\$139,327.38
		0002	1430	4071005	TACK COAT	17,393.00	-8,443.00	8,950.00	GAL	8,950.00	\$2.50	\$22,375.00
		0010	1460	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,175.00	0.00	1,175.00	LF	0.00	\$25.00	\$0.00
		0010	1470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$2,433.00	\$0.00
	Project J	4S3278 - To	tal Value	Posted to D	late as of Report Generated Date							\$1,024,536.12
210219-C04 Ove	erall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$3,036,677.38

Revision 4/1/2020 Page 14 of 39



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3275

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	2031000	CLASS A EXCAVATION	8/23/21	9/2/21	46.00	CUYD	Access Road	0+00		11+95.77		
0060	2063000	CLASS 3 EXCAVATION	8/20/21	9/2/21	0.40	CUYD		5+07.64		7+60		Rounding for final pay
				9/2/21	4.10	CUYD	Access road cross pipe	5+07.64		5+07.64		
			9/2/21 4.10 CUYD Access road cross pipe		7+60		7+60					
0110	3040183	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	8/30/21	9/2/21	1,500.00	SQYD	Base rock for the access road	0+99.96		11+94.51		
0120	3040504	TYPE 5 AGGREGATE FOR BASE	8/23/21	9/2/21	189.80	SQYD	Base rock at the access road approach payment	57+28.22		57+28.22		
			8/30/21	9/2/21	133.20	SQYD	Entrance to the Bureau of Prisons	9+05		9+05		
			9/1/21	9/2/21	202.30	SQYD	4" Base for the temp pavement in the truck apron	62+34.79		63+45.29		
0130	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	8/28/21	9/2/21	1,280.10	SQYD	WB 92 phase 2 east portion	63+62.53		71+37.50		
				9/2/21	1,403.80	SQYD	WB 92 Phase 2 West portion	54+00		62+12.53		
			9/1/21	9/2/21	147.70	SQYD	WB 92 A2 West End	57+68		59+74		
				9/2/21	227.10	SQYD	Base Rock under the Curb and Gutter for phase 2	59+77.09		66+34.61		
				9/2/21	237.30	SQYD	WB A2 Shoulder West End	54+00		57+30		
				9/2/21	320.10	SQYD	WB 92 A2 East End	66+39		71+41		
0140	4010150	TYPE A2 SHOULDER	9/1/21	9/2/21	16.10	SQYD	Patch #3, East End Far West Patch	71+84		72+07		
				9/2/21	17.20	SQYD	Patch #2 West End East Patch	50+24		50+56		
				9/2/21	40.20	SQYD	Patch #6, East End Far East Patch	74+52		75+08		
				9/2/21	44.80	SQYD	Patch #5, East End	73+19		73+75		
				9/2/21	68.80	SQYD	Patch #4, East End	72+23		73+11		
				9/2/21	71.30	SQYD	Patch #1 West End, far West Patch	48+86		50+11		
				9/2/21	147.70	SQYD	WB 92 Phase 2 A2 West End East of the access road	57+68		59+74		
				9/2/21	237.30	SQYD	WB 92 Phase 2 A2 Shoulder West End East of Access Road		54+00		57+30	
				9/2/21	320.10	SQYD	WB 92 Phase 2 A2 East End	66+39		71+41		
0150	4019905	MISC.	8/28/21	9/2/21	1,280.10	SQYD	WB Lane of 92 Phase 2 East portion of the roundabout	63+62.53		71+37.50		
				9/2/21	1,403.80	SQYD	WB lane of 92 Phase 2 West portion	54+00		62+12.53		
0160	4019905	MISC.	9/1/21	9/2/21	202.30	SQYD	Temp Pavement for the truck apron	62+34.79		63+45.29		
0210	6085008	PAVED APPROACH, 8 IN.	8/24/21	9/2/21	189.80	SQYD	Paved approach to the access road	57+28.22		57+28.22		
0240	6091041	CONCRETE GUTTER TYPE A	8/23/21	9/2/21	10.00	LF	Route 92 LT	59+79		59+79		
				9/2/21	10.00	LF	Route 92 LT	66+33		66+33		
0260	6091052	CURB AND GUTTER TYPE B	8/19/21	9/2/21	183.00	LF	Route 92 LT	59+77.09		61+60.09		
			8/23/21	9/2/21	498.40	LF	Route 92 LT	61+60.09		66+34.61		
0300	6097000	ROCK LINING	8/20/21	9/2/21	4.00	CUYD	Access road cross pipes (2 CY at 5+07.64 and 2 CY at 7+60)	5+07.64		7+60		
0390	6161098A	CMS W/O COMMUNICATION INTERFACE, CONT F/	9/1/21	9/2/21	1.00	EA	MO 92 W Log mile	37.364		37.364		
				9/2/21	1.00	EA	North MO 45 Log Mile	15.39		15.39		
				9/2/21	1.00	EA	SP 45 N Log Mile	1.567		1.567		
0570	7250418	18 IN. PIPE CULVERT GROUP C	8/20/21	9/2/21	14.00	LF	Access road cross pipe	7+60		7+60		Original plan QTY was 18', but we adjusted the length an elevation of the new pipe to 14' as per MoDOT design to allow for proper drainage.
0600	7320818A	18 IN. GROUP C FLARED END SEC	8/20/21	9/2/21	2.00	EA	Access road cross pipe.	7+60		7+60		
0640	8061005	ROCK DITCH CHECK	8/20/21	9/2/21	17.00	LF	RDC along ditch of access road. Sta. based off of existing CL 92	62+14		62+14		
				9/2/21	20.00	LF	RDC at the inlet end of access road cross pipe at Sta. 7+60.	64+82		64+82		
0650		ALTERNATE DITCH CHECK	8/20/21	9/2/21	16.00	LF	Alt DC along the access road. Sta. based on existing 92 CL	60+02		60+02		
5002	6191000	PAVEMENT EDGE TREATMENT	9/1/21	9/2/21	370.00	LF		54+00		57+70		
5003	6139901	MISC. PAVEMENT REPAIR	9/1/21	9/2/21	1.00	LS	RTE. 92 Slip Lane	5+69		5+69		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 15 of 39



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3275	0010	CLEARING AND GRUBBING	Overrun	Overrun	3	Jun 16, 2021	SYSTEM	(\$9,000.00)		
				Overrun - T	otal			(\$9,000.00)		
			Overrun - To	tal				(\$9,000.00)		
	0010 -	Total						(\$9,000.00)		
	0030	CLASS A EXCAVATION	Price FUEL		6	Aug 2, 2021	SYSTEM	\$104.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
					8	Sep 2, 2021	SYSTEM	\$5.52	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
				- Total				\$110.25		
			Price FUEL -	Total				\$110.25		
	0030 -	Total						\$110.25		
	0040	EMBANKMENT IN PLACE	Material		3	Jun 16, 2021	SYSTEM	\$279,620.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
						3	Jun 16, 2021	SYSTEM	(\$279,620.00)	
					4	Jul 1, 2021	SYSTEM	\$316,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					4	Jul 1, 2021	SYSTEM	(\$316,020.00)		
					5	Jul 16, 2021	SYSTEM	\$562,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					5	Jul 16, 2021	SYSTEM	(\$562,220.00)		
					6	Aug 2, 2021	SYSTEM	\$713,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					6	Aug 2, 2021	SYSTEM	(\$713,020.00)		
					7	Aug 16, 2021	SYSTEM	\$787,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					7	Aug 16, 2021	SYSTEM	(\$787,420.00)		
					8	Sep 2, 2021	SYSTEM	\$787,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					8	Sep 2, 2021	SYSTEM	(\$787,420.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
			Other Item Adjustment	OVRN	6	Aug 2, 2021	schnod1	(\$115,500.00)	Payment held until quantity is verified by contractor/MoDOT.	
				OVRN - Tota	al			(\$115,500.00)		
			Other Item A	djustment - T	otal			(\$115,500.00)		
			Overrun	Overrun	6	Aug 2, 2021	SYSTEM	(\$116,551.05)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
						6	Aug 2, 2021	SYSTEM	\$31,887.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.
					6	Aug 2, 2021	SYSTEM	\$33,098.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.	
					6	Aug 2, 2021	SYSTEM	\$35,116.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.	
					6	Aug 2, 2021	SYSTEM	\$16,448.33	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000;	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
275	0040	EMBANKMENT IN	Overrun	Overrun					Overrun Quantity Balance 5775.00.
		PLACE			7	Aug 16, 2021	SYSTEM	(\$116,533.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.17890' is applied (if non-zero).
					7	Aug 16, 2021	schnod1	(\$74,400.00)	Overrun withheld for estimate 0007.
					7	Aug 16, 2021	SYSTEM	(\$75,181.20)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Aug 16, 2021	SYSTEM	\$75,181.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 28 on the current Payment Estimate. Material Insufficiency Quantity 39371.000; Overrun Quantity Balance 9495.00.
					7	Aug 16, 2021	SYSTEM	\$116,533.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 28 on the current Payment Estimate. Material Insufficiency Quantity 39371.000; Overrun Quantity Balance 9495.00.
					8	Sep 2, 2021	schnod1	\$189,900.00	Quantity updated on CO 3, overrun negative adjustments are being paid back. \$189,900
				Overrun - T	otal			\$115,500.00	
			Overrun - To	tal				\$115,500.00	
			Price FUEL		3	Jun 16, 2021	SYSTEM	\$2,446.67	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jul 1, 2021	SYSTEM	\$318.50	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Jul 16, 2021	SYSTEM	\$2,240.42	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Aug 2, 2021	SYSTEM	\$1,372.28	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Aug 16, 2021	SYSTEM	\$781.20	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$7,159.07	
			Price FUEL -	Total				\$7,159.07	
	0040 -	· Total						\$7,159.07	
	0050	COMPACTING EMBANKMENT	Material		6	Aug 2, 2021	SYSTEM	\$1,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$1,678.00)	
					7		SYSTEM	(\$1,678.00) \$1,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
						2021 Aug 16,			Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
					7	2021 Aug 16, 2021 Aug 16,	SYSTEM	\$1,678.00	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
					7	2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM	\$1,678.00 (\$1,678.00)	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
				- Total	7 7 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM	\$1,678.00 (\$1,678.00) \$1,678.00	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
			Material - To		7 7 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM	\$1,678.00 (\$1,678.00) \$1,678.00	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
	0050 -	· Total	Material - To		7 7 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM	\$1,678.00 (\$1,678.00) \$1,678.00 (\$1,678.00)	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
	0050 - 0070	-Total LINEAR GRADING CLASS 1	Material - To		7 7 8 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM	\$1,678.00 (\$1,678.00) \$1,678.00 (\$1,678.00) \$0.00	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
		LINEAR GRADING		tal	7 7 8 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,678.00 (\$1,678.00) \$1,678.00 (\$1,678.00) \$0.00 \$0.00	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
		LINEAR GRADING		Overrun Overrun - T	7 7 8 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,678.00 (\$1,678.00) \$1,678.00 (\$1,678.00) \$0.00 \$0.00 (\$1,650.00)	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
		LINEAR GRADING CLASS 1	Overrun	Overrun Overrun - T	7 7 8 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,678.00 (\$1,678.00) \$1,678.00 (\$1,678.00) \$0.00 \$0.00 (\$1,650.00)	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
	0070	LINEAR GRADING CLASS 1 Total TYPE 1 AGGREGATE FOR BASE (8 IN.	Overrun	Overrun Overrun - T	7 7 8 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,678.00 (\$1,678.00) \$1,678.00 (\$1,678.00) \$0.00 \$0.00 (\$1,650.00) (\$1,650.00)	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
	0070	LINEAR GRADING CLASS 1 Total	Overrun Overrun - To	Overrun Overrun - T	7 7 8 8 8 4 4 otal	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Jul 1, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,678.00 (\$1,678.00) \$1,678.00 (\$1,678.00) \$0.00 \$0.00 (\$1,650.00) (\$1,650.00) (\$1,650.00)	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment
	0070	LINEAR GRADING CLASS 1 Total TYPE 1 AGGREGATE FOR BASE (8 IN.	Overrun Overrun - To	Overrun Overrun - T	7 7 8 8 8 4 4 otal 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Jul 1, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,678.00 (\$1,678.00) \$1,678.00 (\$1,678.00) \$0.00 \$0.00 (\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00)	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment
	0070	LINEAR GRADING CLASS 1 Total TYPE 1 AGGREGATE FOR BASE (8 IN.	Overrun Overrun - To	Overrun - T tal - Total	7 7 8 8 8 4 4 otal 8	2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Jul 1, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,678.00 (\$1,678.00) \$1,678.00 (\$1,678.00) \$0.00 \$0.00 \$0.00 (\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,550.00) (\$1,5750.00)	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0110	TYPE 1 AGGREGATE	Price FUEL	, ,,	8	Sep 2, 2021	SYSTEM	\$270.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		FOR BASE (8 IN. THICK)		- Total				\$270.00	
		,	Price FUEL -	Total				\$270.00	
	0110 -	Total						\$270.00	
	0120	TYPE 5 AGGREGATE FOR BASE	Material		4	Jul 1, 2021	SYSTEM	\$48,687.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$48,687.45)	
					5	Jul 16, 2021	SYSTEM	\$48,687.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$48,687.45)	
					6	Aug 2, 2021	SYSTEM	\$48,687.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$48,687.45)	
					7	Aug 16, 2021	SYSTEM	\$48,687.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$48,687.45)	
					8	Sep 2, 2021	SYSTEM	\$54,203.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$54,203.10)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		4	Jul 1, 2021	SYSTEM	\$347.77	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Sep 2, 2021	SYSTEM	\$47.28	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$395.05	
			Price FUEL -	Total				\$395.05	
		Total			_		01/07514	\$395.05	
	0130	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		7	Aug 16, 2021	SYSTEM	\$5,463.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		,			7	Aug 16, 2021	SYSTEM	(\$5,463.85)	
					8	Sep 2, 2021	SYSTEM	\$47,591.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$47,591.42)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		7	Aug 16, 2021	SYSTEM	\$64.72	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Sep 2, 2021	SYSTEM	\$499.02	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$563.74	
			Price FUEL -	Total				\$563.74	
	0130 -	Total						\$563.74	
	0140	TYPE A2 SHOULDER	Material		8	Sep 2, 2021	SYSTEM	\$22,488.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$22,488.09)	



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
P3275	0140	TYPE A2	Material	- Total				\$0.00		
		SHOULDER	Material - To	tal				\$0.00		
	0140 -	Total						\$0.00		
	0150	MISC.	Other Item Adjustment	ACAD	8	Sep 2, 2021	schnod1	\$3,693.73	2,683.9 SQYD of SP190 21-13	
					8	Sep 2, 2021	schnod1	\$691.67	2,683.90 SQYD of SP125 21-14.	
				ACAD - Tota	al			\$4,385.40		
			Other Item A	djustment - T	otal			\$4,385.40		
	0150 -	Total						\$4,385.40		
	0160	MISC.	Material		4	Jul 1, 2021	SYSTEM	\$125,903.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					4	4 Jul 1, SYSTEM (\$125,903.01)				
					5	Jul 16, 2021	SYSTEM	\$125,903.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
						5	Jul 16, 2021	SYSTEM	(\$125,903.01)	
					6	Aug 2, 2021	SYSTEM	\$125,903.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					6	Aug 2, 2021	SYSTEM	(\$125,903.01)		
					7	Aug 16, 2021	SYSTEM	\$125,903.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					7	Aug 16, 2021	SYSTEM	(\$125,903.01)		
					8	Sep 2, 2021	SYSTEM	\$131,666.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					8	Sep 2, 2021	SYSTEM	(\$131,666.54)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0160 -	Total						\$0.00		
	0210	PAVED APPROACH, 8 IN.	Material		8	Sep 2, 2021	SYSTEM	\$11,900.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
					8	Sep 2, 2021	SYSTEM	(\$11,900.46)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
			Price FUEL		8	Sep 2, 2021	SYSTEM	\$68.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
				- Total				\$68.33		
			Price FUEL -	Total				\$68.33		
	0210 -	Total						\$68.33		
	0240	CONCRETE GUTTER TYPE A	Material		8	Sep 2, 2021	SYSTEM	\$1,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
					8	Sep 2, 2021	SYSTEM	(\$1,925.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0240 -	Total						\$0.00		
	0260	CURB AND GUTTER TYPE B	Material		8	Sep 2, 2021	SYSTEM	\$20,373.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schnod1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	



APP277 CALIFORM Apparent																						
Act	Project	Line	Description		Adjustment				Amount	Remarks												
Material - Total SySTEM SySTEM Selection	J4P3275	0260		Material		8		SYSTEM	(\$20,373.86)													
SOUND COUNTRY					- Total				\$0.00													
SOUND COUNTRY				Material - To	tal				\$0.00													
Section Sect		0260 -	Total																			
2021				Material		3	lup 16	SVSTEM		This adjustment offsets the original system generated Material Payment												
4		0300	ROCK LINING	iviaterial		3		STSTEIN	\$450.00	Estimate Item Adjustment (0038) due to user schnod1 overridding Payment												
2021 Estimate Item Adjustment (0052) due to user school'd overviding Payment						3		SYSTEM	(\$450.00)													
2021 5 Jul 16, SYSTEM S450.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate. S450.00 SYSTEM S450.00 SYST						4		SYSTEM	\$450.00	Estimate Item Adjustment (0032) due to user schnod1 overridding Payment												
2021						4		SYSTEM	(\$450.00)													
Total						5		SYSTEM	\$450.00	Estimate Item Adjustment (0033) due to user schnod1 overridding Payment												
						5		SYSTEM	(\$450.00)													
1					- Total				\$0.00													
MARCED Marcel Material May 17, SYSTEM S6,000.00 This adjustment offsets the original system-generated Material Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment offsets the original system-generated Material Payment Estimate lear Adjustment offsets the original system-generated Material Payment Estimate lear Adjustment offsets the original system-generated Material Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate lear Adjustment (0003) due to user school overridding Payment Estimate Exception 16 on the current Payment Estimate exception 17 on the current Payment Estimate Exception 17 on the current Payment Estimate Exception 17 on				Material - Tot					\$0.00													
Marcial		0300 -	Total						\$0.00													
ATTENUATOR 55 MPH (58AND BARREL ARRAY)				Material		1	May 17	SVSTEM		This adjustment offsets the original system generated Material Payment												
1		0310	ATTENUATOR 55 MPH (SAND	iviateriai					\$0,000.00	Estimate Item Adjustment (0008) due to user schnod1 overridding Payment												
2021 Estimate Item Adjustment (0027) due to user woodwyl overridding Payment Estimate.			,											1		SYSTEM	(\$6,000.00)					
2021 3															2		SYSTEM	\$6,000.00	Estimate Item Adjustment (0027) due to user woodwj1 overridding Payment			
2021 Estimate Item Adjustment (0039) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.											2		SYSTEM	(\$6,000.00)								
2021						3		SYSTEM	\$6,000.00	Estimate Item Adjustment (0039) due to user schnod1 overridding Payment												
2021 Estimate Item Adjustment (0033) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.						3		SYSTEM	(\$6,000.00)													
2021						4		SYSTEM	\$6,000.00	Estimate Item Adjustment (0033) due to user schnod1 overridding Payment												
Estimate Item Adjustment (0034) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.						4		SYSTEM	(\$6,000.00)													
-Total \$0.00 Material - Total \$0.00 0310 - Total \$0.00 0320 REPLACEMENT SAND BARREL																		5		SYSTEM	\$6,000.00	Estimate Item Adjustment (0034) due to user schnod1 overridding Payment
Solution Solution						5		SYSTEM	(\$6,000.00)													
Solution Solution					- Total				\$0.00													
Solution Solution				Material - To	tal				\$0.00													
REPLACEMENT SAND BARREL Material Jun 16, 2021 SYSTEM \$990.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate. Jun 16, 2021 Jul 11, 2021 SYSTEM \$990.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schnod1 overridding Payment Estimate Item Adjustment (0034) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate. Jul 1, 2021 SYSTEM \$990.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate. Jul 16, 2021 SYSTEM \$990.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment		0310 -	Total						\$0.00													
3 Jun 16, 2021 (\$990.00) 4 Jul 1, 2021 \$990.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 4 Jul 1, 2021 \$YSTEM (\$990.00) 5 Jul 16, 2021 \$YSTEM \$990.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment		0320 REPLACEMENT	Material		3		SYSTEM		Estimate Item Adjustment (0040) due to user schnod1 overridding Payment													
4 Jul 1, 2021 SYSTEM \$990.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 4 Jul 1, 2021 (\$990.00) 5 Jul 16, 2021 SYSTEM \$990.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment					3		SYSTEM	(\$990.00)														
4 Jul 1, 2021 (\$990.00) 5 Jul 16, 2021 SYSTEM \$990.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment					4	Jul 1,	SYSTEM	\$990.00	Estimate Item Adjustment (0034) due to user schnod1 overridding Payment													
5 Jul 16, SYSTEM \$990.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment					4		SYSTEM	(\$990.00)	, -,													
						5	Jul 16,	SYSTEM	\$990.00	Estimate Item Adjustment (0035) due to user schnod1 overridding Payment												



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J4P3275	0320	REPLACEMENT SAND BARREL	Material		5	Jul 16, 2021	SYSTEM	(\$990.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0320 -	- Total						\$0.00	
	0350	CONSTRUCTION SIGNS	Material		1	May 17, 2021	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$2,040.00)	
					2	Jun 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user woodwj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$2,200.00)	
					3	Jun 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$2,200.00)	
					4	Jul 1, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$2,200.00)	
					5	Jul 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$2,200.00)	
				- Total				\$0.00	
			Material - To					\$0.00 \$0.00	
	0350 -	- Total	Material - To						
	0350 -	- Total ADVANCED WARNING RAIL SYSTEM			1	May 17, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		ADVANCED WARNING RAIL			1			\$0.00 \$0.00	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment
		ADVANCED WARNING RAIL				2021 May 17,		\$0.00 \$0.00 \$150.00	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment
		ADVANCED WARNING RAIL			1	2021 May 17, 2021 Jun 2,	SYSTEM	\$0.00 \$0.00 \$150.00 (\$150.00)	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment
		ADVANCED WARNING RAIL			1 2	2021 May 17, 2021 Jun 2, 2021 Jun 2,	SYSTEM SYSTEM	\$0.00 \$0.00 \$150.00 (\$150.00) \$150.00	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment
		ADVANCED WARNING RAIL			1 2 2	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$150.00 (\$150.00) \$150.00	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment
		ADVANCED WARNING RAIL			1 2 2 3	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$150.00 (\$150.00) \$150.00 (\$150.00)	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment
		ADVANCED WARNING RAIL			1 2 2 3 3 3	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$150.00 (\$150.00) \$150.00 (\$150.00)	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment
		ADVANCED WARNING RAIL			1 2 2 3 3 4	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$150.00 (\$150.00) \$150.00 (\$150.00) \$150.00 (\$150.00)	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment
		ADVANCED WARNING RAIL			1 2 2 3 3 4 4 4	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$150.00 (\$150.00) \$150.00 (\$150.00) \$150.00 (\$150.00)	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate.
		ADVANCED WARNING RAIL			1 2 2 3 3 4 4 5 5	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$150.00 (\$150.00) (\$150.00) (\$150.00) (\$150.00) (\$150.00) (\$150.00)	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate.
		ADVANCED WARNING RAIL		- Total	1 2 2 3 3 4 4 5 5	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$150.00 (\$150.00) (\$150.00) (\$150.00) (\$150.00) (\$150.00) (\$150.00)	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate.
	0360	ADVANCED WARNING RAIL	Material	- Total	1 2 2 3 3 4 4 5 5	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$150.00 (\$150.00) (\$150.00) (\$150.00) (\$150.00) (\$150.00) (\$150.00) (\$150.00)	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J4P3275	0370	CHANNELIZER (TRIM LINE)	Material		1	May 17, 2021	SYSTEM	(\$1,472.00)										
					2	Jun 2, 2021	SYSTEM	\$2,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user woodwj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.									
					2	Jun 2, 2021	SYSTEM	(\$2,185.00)										
					3	Jun 16, 2021	SYSTEM	\$2,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.									
					3	Jun 16, 2021	SYSTEM	(\$2,185.00)										
					4	Jul 1, 2021	SYSTEM	\$2,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.									
					4	Jul 1, 2021	SYSTEM	(\$2,185.00)										
					5	Jul 16, 2021	SYSTEM	\$2,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.									
					5	Jul 16, 2021	SYSTEM	(\$2,185.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	0370 -	Total						\$0.00										
	0400	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		1	May 17, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.									
														1	May 17, 2021	SYSTEM	(\$3,600.00)	
							2	Jun 2, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user woodwj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.							
											2	Jun 2, 2021	SYSTEM	(\$3,600.00)				
					3	Jun 16, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.									
					3	Jun 16, 2021	SYSTEM	(\$3,600.00)										
					4	Jul 1, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.									
					4	Jul 1, 2021	SYSTEM	(\$3,600.00)										
					5	Jul 16, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.									
					5	Jul 16, 2021	SYSTEM	(\$3,600.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	0400 -							\$0.00										
		Material		1	May 17, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
				1	May 17, 2021	SYSTEM	(\$96,937.50)											
				2	Jun 2, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user woodwj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
				2	Jun 2, 2021	SYSTEM	(\$96,937.50)											
					3	Jun 16, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4P3275	0410	TEMP. TRAFFIC BARRIER	Material		3	Jun 16, 2021	SYSTEM	(\$96,937.50)													
		ANCHORED., CONT			4	Jul 1, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schnod1 overridding Payment Estimate Exception 27 on the current Payment Estimate.												
					4	Jul 1, 2021	SYSTEM	(\$96,937.50)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	0410 -	Total						\$0.00													
	0420	TEMP. TRAFFIC BARRIER HEIGHT TRANSITION	Material		1	May 17, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
					1	May 17, 2021	SYSTEM	(\$1,700.00)													
					2	Jun 2, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user woodwj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.												
									2	Jun 2, 2021	SYSTEM	(\$1,700.00)									
							3	Jun 16, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.										
															3	Jun 16, 2021	SYSTEM	(\$1,700.00)			
									4	Jul 1, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user schood1 overridding Payment Estimate Exception 28 on the current Payment Estimate.								
														4	Jul 1, 2021	SYSTEM	(\$1,700.00)				
													5	Jul 16, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user schnod1 overridding Payment Estimate Exception 27 on the current Payment Estimate.				
										5	Jul 16, 2021	SYSTEM	(\$1,700.00)								
					6	Aug 2, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.												
					6	Aug 2, 2021	SYSTEM	(\$1,700.00)													
					7	Aug 16, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.												
																	7	Aug 16, 2021	SYSTEM	(\$1,700.00)	
											8	Sep 2, 2021	SYSTEM	(\$1,700.00)							
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	0420 -	Total						\$0.00													
	0480 TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	Material		1	May 17, 2021	SYSTEM	\$4,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.													
		IN.,					1							1	May 17, 2021	SYSTEM	(\$4,314.00)				
																					2
					2	Jun 2, 2021	SYSTEM	(\$4,314.00)													
								3	Jun 16, 2021	SYSTEM	\$4,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate.									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J4P3275	0480	TEMPORARY REMOVABLE	Material		3	Jun 16, 2021	SYSTEM	(\$4,314.00)																
		MARKING TAPE 4 IN.,			4	Jul 1, 2021	SYSTEM	\$4,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.															
					4	Jul 1, 2021	SYSTEM	(\$4,314.00)																
					5	Jul 16, 2021	SYSTEM	\$11,794.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate.															
					5	Jul 16, 2021	SYSTEM	(\$11,794.00)																
					6	Aug 2, 2021	SYSTEM	\$11,794.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.															
					6	Aug 2, 2021	SYSTEM	(\$11,794.00)																
					7	Aug 16, 2021	SYSTEM	\$11,794.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.															
					7	Aug 16, 2021	SYSTEM	(\$11,794.00)																
					8	Sep 2, 2021	SYSTEM	\$11,794.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 46 on the current Payment Estimate.															
									8	Sep 2, 2021	SYSTEM	(\$11,794.00)												
				- Total				\$0.00																
			Material - To	tal				\$0.00																
	0480 -						0.10==1.1	\$0.00																
	0490	TEMPORARY REMOVABLE MARKING TAPE	Material		1	May 17, 2021		\$7,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate.															
					1	May 17, 2021	SYSTEM	(\$7,428.00)																
					2	Jun 2, 2021	SYSTEM	\$7,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user woodwj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.															
					2	Jun 2, 2021	SYSTEM	(\$7,428.00)																
					3	Jun 16, 2021	SYSTEM	\$7,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.															
					3	Jun 16, 2021	SYSTEM	(\$7,428.00)																
																				4	Jul 1, 2021	SYSTEM	\$7,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
																			4	Jul 1, 2021	SYSTEM	(\$7,428.00)		
									5	Jul 16, 2021	SYSTEM	\$14,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.											
				6													5	Jul 16, 2021	SYSTEM	(\$14,884.00)				
																		6		6	Aug 2, 2021	SYSTEM	\$14,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			6 Aug 2, SYSTEM (\$14,884.00)																					
			7		7	2021 Estimate Item Adjustment (0022) due to user schnod1 of	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																	
				7	7	Aug 16, 2021	SYSTEM	(\$14,884.00)																
							8	Sep 2, 2021	SYSTEM	\$14,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment													



Description TEAPCRARY Section	ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
Material - Total	275	0490		Material						Estimate Exception 47 on the current Payment Estimate.	
Material - Total So						8		SYSTEM	(\$14,884.00)		
Material Section Sec											
September Sept				Material - To	tal						
CULVERT GROUP 8 Sep 2, 2 SYSTEM 31,400,000						-					
Total		0570	CULVERT GROUP	Material		8		SYSTEM	\$1,400.00	Estimate Item Adjustment (0032) due to user schnod1 overridding Payment	
					8			SYSTEM	(\$1,400.00)		
18 N. GROUP A Material					- Total				\$0.00		
18 IN CROUPD PLANED END P				Material - To	tal				\$0.00		
PLARED RND		0570 -	Total						\$0.00		
2021 4 Jul 1 SYSTEM \$1,212.00 Estimate Exception 45 on the current Payment Estimate Exception 39 on the current Payment Estimate Exception 45 on the current Payment Estimate Exception 51 on the current Payment Estimate Exception 51 on the current Payment Estimate Estimate Exception 51 on the current Payment Estimate Exception 52 on the current Payment Estimate Estimate Exception 52 on the current Payment Estimate Estimate Exception 52 on the current Payment Estimate Estimate Exception 52 on the curr		0590	FLARED END	Material		3		SYSTEM	\$1,212.00	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment	
2021 SySTEM (\$1,212.00)			SECT			3		SYSTEM	(\$1,212.00)		
2021 SYSTEM \$1,212.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 39 on the current Payment Estimate Exception 49 on the current Payment Estimate E						4		SYSTEM	\$1,212.00	Estimate Item Adjustment (0043) due to user schnod1 overridding Payment	
2021 Estimate Item Adjustment (0043) due to user schnod to verridding Payment Estimate Exception 39 on the current Payment Estimate.						4		SYSTEM	(\$1,212.00)		
						5		SYSTEM	\$1,212.00	Estimate Item Adjustment (0043) due to user schnod1 overridding Payment	
2021 Estimate (term Adjustment (0030) due to user schnod 1 overridding Payment Estimate Estimate Exception 21 on the current Payment Estimate.							5		SYSTEM	(\$1,212.00)	
2021							6		SYSTEM	\$1,212.00	Estimate Item Adjustment (0030) due to user schnod1 overridding Payment
2021 Estimate Item Adjustment (0023) due to user schnod 1 overridding Payment Estimate Exception 22 on the current Payment Estimate.						6		SYSTEM	(\$1,212.00)		
2021 8 Sep 2, 2021 202						7		SYSTEM	\$1,212.00	Estimate Item Adjustment (0023) due to user schnod1 overridding Payment	
B Sep 2, 2021 SYSTEM (\$1,212.00)						7		SYSTEM	(\$1,212.00)		
Naterial - Total S0.00						8		SYSTEM	\$1,212.00	Estimate Item Adjustment (0033) due to user schnod1 overridding Payment	
Solution						8		SYSTEM	(\$1,212.00)		
Solid Soli					- Total				\$0.00		
Sep 2 SYSTEM \$1,212.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 52 on the current Payment Estimate.				Material - To	tal				\$0.00		
FLARED END SEC 2021 Estimate Item Adjustment (0034) due to user schnod1 overridding Payment Estimate Exception 52 on the current Payment Estimate. 8		0590 -	Total						\$0.00		
Sep 2, 2021 SYSTEM (\$1,212.00)		0600		Material		8		SYSTEM	\$1,212.00	Estimate Item Adjustment (0034) due to user schnod1 overridding Payment	
Material - Total \$0.00						8		SYSTEM	(\$1,212.00)	. ,	
Solution					- Total				\$0.00		
ROCK DITCH CHECK A Material 3 Jun 16, 2021 SYSTEM \$1,600.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user schood 1 overridding Payment Estimate Exception 49 on the current Payment Estimate. 3 Jun 16, 2021 (\$1,600.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schood 1 overridding Payment				Material - To	tal				\$0.00		
CHECK 2021 Estimate Item Adjustment (0050) due to user schnod1 overridding Payment Estimate Exception 49 on the current Payment Estimate. 3 Jun 16, 2021 4 Jul 1, SYSTEM \$5,600.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment		0600 -	Total						\$0.00		
3 Jun 16, 2021 (\$1,600.00) 4 Jul 1, 2021 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment		0640		Material		3		SYSTEM	\$1,600.00	Estimate Item Adjustment (0050) due to user schnod1 overridding Payment	
4 Jul 1, SYSTEM \$5,600.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment						3		SYSTEM	(\$1,600.00)		
						4	Jul 1,	SYSTEM	\$5,600.00	Estimate Item Adjustment (0045) due to user schnod1 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0640	ROCK DITCH CHECK	Material		4	Jul 1, 2021	SYSTEM	(\$5,600.00)	
					5	Jul 16, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$5,600.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	OVRN	4	Jul 1, 2021	schnod1	(\$3,080.00)	Payment held for overrun exception.
					6	Aug 2, 2021	schnod1	\$3,080.00	Manual negative adjustment from estimate 0004 paid for now.
				OVRN - Total				\$0.00	
			Other Item A	djustment - T	otal			\$0.00	
			Overrun	Overrun	4	Jul 1, 2021	SYSTEM	\$3,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 62 on the current Payment Estimate. Material Insufficiency Quantity 140.000; Overrun Quantity Balance 77.00.
					4	Jul 1, 2021	SYSTEM	(\$3,080.00)	
					5	Jul 16, 2021	SYSTEM	(\$3,080.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Jul 16, 2021	SYSTEM	\$3,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 54 on the current Payment Estimate. Material Insufficiency Quantity 140.000; Overrun Quantity Balance 77.00.
					6	Aug 2, 2021	SYSTEM	(\$3,080.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Sep 2, 2021	SYSTEM	(\$1,480.00)	
				Overrun - To	otal			(\$4,560.00)	
			Overrun - To	tal				(\$4,560.00)	
	0640 -	Total						(\$4,560.00)	
	0650	ALTERNATE DITCH CHECK			8	Sep 2, 2021	SYSTEM	\$208.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$208.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0650 -	Total						\$0.00	
	0670	TEMPORARY SEEDING AND MULCHING	Material		4	Jul 1, 2021	SYSTEM	\$4,815.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$4,815.00)	
					5	Jul 16, 2021	SYSTEM	\$4,815.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$4,815.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	OVRN		Jul 1, 2021	schnod1	(\$3,691.50)	Payment held for overrun exception.
					6	Aug 2, 2021	schnod1	\$3,691.50	Manual negative adjustment from estimate 0004 paid for now.
				OVRN - Tota				\$0.00	
			Other Item A	djustment - T	otal			\$0.00	
		_	Overrun	Overrun	4	Jul 1, 2021	SYSTEM	\$3,691.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) overridding Payment Estimate Exception 63 on the current Payment Estimate. Material Insufficiency Quantity 3.000;



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
4P3275	0670	TEMPORARY SEEDING AND	Overrun	Overrun					Overrun Quantity Balance 2.30.	
		MULCHING			4	Jul 1, 2021	SYSTEM	(\$3,691.50)		
					5	Jul 16, 2021	SYSTEM	(\$3,691.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
					5	Jul 16, 2021	SYSTEM	\$3,691.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) overridding Payment Estimate Exception 55 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 2.30.	
					6	Aug 2, 2021	SYSTEM	(\$3,691.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
					8	Sep 2, 2021	SYSTEM	\$3,691.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1605.00000 - 1605.00000, 'is applied (if non-zero).	
				Overrun - T	otal			\$0.00		
			Overrun - To	tal				\$0.00		
	0670 -	Total						\$0.00		
	0680	SILT FENCE	Material		2	Jun 2, 2021	SYSTEM	\$10,641.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user woodwj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	
					2	Jun 2, 2021	SYSTEM	(\$10,641.00)		
					3	Jun 16, 2021	SYSTEM	\$10,641.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	
					3	Jun 16, 2021	SYSTEM	(\$10,641.00)		
						4	Jul 1, 2021	SYSTEM	\$14,637.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user schnod1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
						4	Jul 1, 2021	SYSTEM	(\$14,637.00)	
					5	Jul 16, 2021	SYSTEM	\$14,637.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	
					5	Jul 16, 2021	SYSTEM	(\$14,637.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0680 - 0730	Total MGS GUARDRAIL	Construction		2	Jun 2, 2021	SYSTEM	\$0.00 \$16,625.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Stockpile STMI	- Total		2021		\$16,625.00		
			Construction	Stockpile S	TMI - Total			\$16,625.00		
	0730 -	Total						\$16,625.00		
	0740	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile STMI		2	Jun 2, 2021	SYSTEM	\$32,582.46	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$32,582.46		
			Construction	Stockpile S	TMI - Tota			\$32,582.46		
	0740 -							\$32,582.46		
	0750	MGS END ANCHOR	Construction Stockpile STMI	- Total	2	Jun 2, 2021	SYSTEM	\$1,158.00 \$1,158.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Construction	Stockpile S	TML - Total			\$1,158.00		
	0750	Total	201101101					\$1,158.00		
	0760	TYPE A CRASHWORTHY	Stockpile		2	Jun 2, 2021	SYSTEM	\$13,905.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
		END TERMINAL (MASH)	STMI	- Total				\$13,905.00		
		,,	Construction	Stockpile S	TMI - Tota			\$13,905.00		
	0760 -	Total						\$13,905.00		
	5002	PAVEMENT EDGE	Material		8	Sep 2,	SYSTEM	\$2,627.00	This adjustment offsets the original system-generated Material Payment	



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks							
J4P3275	5002	TREATMENT	Material	Туре		2021			Estimate Item Adjustment (0039) due to user schoold everridding Payment							
J4F3Z13	3002	TREATMENT	iviateriai			2021			Estimate Item Adjustment (0038) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate.							
					8	Sep 2, 2021	SYSTEM	(\$2,627.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	5002 -	Total						\$0.00								
J4P3275 -	Total							\$62,012.30								
J4S3278	1120	GRAVEL (A)	Material		3	Jun 16, 2021	SYSTEM	\$10,402.69	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					3	Jun 16, 2021	SYSTEM	(\$10,402.69)								
					4	Jul 1, 2021	SYSTEM	\$10,374.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					4	Jul 1, 2021	SYSTEM	(\$10,374.56)								
					5	Jul 16, 2021	SYSTEM	\$10,374.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					5	Jul 16, 2021	SYSTEM	(\$10,374.56)								
					6	Aug 2, 2021	SYSTEM	\$10,374.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.							
					6	Aug 2, 2021	SYSTEM	(\$10,374.56)								
					7	Aug 16, 2021	SYSTEM	\$10,374.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.							
					7	Aug 16, 2021	SYSTEM	(\$10,374.56)								
							8	Sep 2, 2021	SYSTEM	\$10,374.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					8	Sep 2, 2021	SYSTEM	(\$10,374.56)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	1120 -	Total						\$0.00								
	1130	BIT. PAVEMENT MIXTURE	Price FUEL		2	Jun 2, 2021	SYSTEM	\$202.21	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
		PG64-22 (BP-1)		- Total				\$202.21								
			Price FUEL -	Total				\$202.21								
	1130 -	Total						\$202.21								
	1140	TACK COAT	Material		2	Jun 2, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
												2	Jun 2, 2021	SYSTEM	(\$232.50)	
		:	3	3	3									3	3	3
					3	Jun 16, 2021	SYSTEM	(\$232.50)								
				4	4	4	Jul 1, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
					4	Jul 1, 2021	SYSTEM	(\$232.50)								
					5	Jul 16, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
I4S3278	1140	TACK COAT	Material		5	Jul 16, 2021	SYSTEM	(\$232.50)																
					6	Aug 2, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.															
					6	Aug 2, 2021	SYSTEM	(\$232.50)																
					7	Aug 16, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					7	Aug 16, 2021	SYSTEM	(\$232.50)																
					8	Sep 2, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.															
					8	Sep 2, 2021	SYSTEM	(\$232.50)																
				- Total				\$0.00																
			Material - To					\$0.00																
	1140 -	Total						\$0.00																
	1150	3 IN. CONCRETE MEDIAN STRIP	Material		2	Jun 2, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodwj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.															
					2	Jun 2, 2021	SYSTEM	(\$3,374.18)																
					3	Jun 16, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
										3	Jun 16, 2021	SYSTEM	(\$3,374.18)											
					4	Jul 1, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.															
					4	Jul 1, 2021	SYSTEM	(\$3,374.18)																
					5	Jul 16, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.															
						ŧ				5	Jul 16, 2021	SYSTEM	(\$3,374.18)											
					6	Aug 2, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate.															
																				6	Aug 2, 2021	SYSTEM	(\$3,374.18)	
																	7	Aug 16, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
												7	Aug 16, 2021	SYSTEM	(\$3,374.18)									
					8	Sep 2, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.															
					8	Sep 2, 2021	SYSTEM	(\$3,374.18)																
				- Total				\$0.00																
			Material - To	tal				\$0.00																
	1150 -	Total						\$0.00																
	1160	CONSTRUCTION SIGNS	Material		1	May 17, 2021	SYSTEM	\$256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
					1	May 17, 2021	SYSTEM	(\$256.00)																
					2	Jun 2, 2021	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodwj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J4S3278	1160	CONSTRUCTION SIGNS	Material		2	Jun 2, 2021	SYSTEM	(\$880.00)																	
					3	Jun 16, 2021	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																
					3	Jun 16, 2021	SYSTEM	(\$880.00)																	
					4	Jul 1, 2021	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																
					4	Jul 1, 2021	SYSTEM	(\$880.00)																	
					5	Jul 16, 2021	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																
					5	Jul 16, 2021	SYSTEM	(\$880.00)	Estimate Escopicio I o si alcosa si i con agrico e e e e e e e e e e e e e e e e e e e																
				- Total		2021		\$0.00																	
			Material - To					\$0.00																	
	1160 -	Total						\$0.00																	
	1170	FLAG ASSEMBLY	Material		2	Jun 2, 2021	SYSTEM	\$50.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																
					2	Jun 2, 2021	SYSTEM	(\$50.00)																	
					3	Jun 16, 2021	SYSTEM	\$50.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																
					3	Jun 16, 2021	SYSTEM	(\$50.00)																	
					4	Jul 1, 2021	SYSTEM	\$50.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																
							4	Jul 1, 2021	SYSTEM	(\$50.00)															
														5	Jul 16, 2021	SYSTEM	\$50.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.							
					5	Jul 16, 2021	SYSTEM	(\$50.00)																	
				- Total				\$0.00																	
			Material - To	tal				\$0.00																	
	1170 -	Total						\$0.00																	
	1190	CHANNELIZER (TRIM LINE)	Material		1	May 17, 2021	SYSTEM	\$41.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																
				2	2	2 2 3	2	2	2	2								1			1	May 17, 2021	SYSTEM	(\$41.00)	
																		2		2	Jun 2, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodwj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
											2	2	1	2	Jun 2, 2021	SYSTEM	(\$80.00)								
																3	Jun 16, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.					
					3	Jun 16, 2021	SYSTEM	(\$80.00)																	
					4	Jul 1, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																
					4	Jul 1, 2021	SYSTEM	(\$80.00)																	
					5	Jul 16, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J4S3278	1190	CHANNELIZER (TRIM LINE)	Material		5	Jul 16, 2021	SYSTEM	(\$80.00)														
				- Total				\$0.00														
			Material - To	tal				\$0.00														
	1190 -	Total						\$0.00														
	1200	TYPE III MOVEABLE BARRICADE WITH LIGHTS	Material		2	Jun 2, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodwj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.													
		LIGITIO			2	Jun 2, 2021	SYSTEM	(\$1,650.00)														
					3	Jun 16, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.													
					3	Jun 16, 2021	SYSTEM	(\$1,650.00)														
					4	Jul 1, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.													
					4	Jul 1, 2021	SYSTEM	(\$1,650.00)														
					5	Jul 16, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.													
					5	Jul 16, 2021	SYSTEM	(\$1,650.00)														
			Material - Tol Other Item Adjustment	- Total					\$0.00													
				tal				\$0.00														
				Other Item Adjustment	Adjustment		6	Aug 2, 2021	schnod1	\$375.00	Manual negative adjustment from estimate 0002 paid for now.											
				OVRN - Total				\$375.00														
			Other Item A	djustment - T	otal			\$375.00														
			Overrun	Overrun	2	Jun 2, 2021	woodwj1	(\$375.00)	Manual adjustment for the overrun with material exceptions. This will be removed once they are resolved													
					2	Jun 2, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 35 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 5.00.													
					2	Jun 2, 2021	SYSTEM	(\$375.00)														
					3	Jun 16, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).													
					3	Jun 16, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 54 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 5.00.													
					4	Jul 1, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).													
																4		4	Jul 1, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 59 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 5.00.
						5	Jul 16, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
												5	5	Jul 16, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 52 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 5.00.					
					6	Aug 2, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).													
				Overrun - T	otal			(\$750.00)														
			Overrun - To	tal				(\$750.00)														
	1200 -	Total						(\$375.00)														
	1210	CMS W/O COMMUNICATION INTERFACE,	Material		1	May 17, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1210	CONT F/	Material		1	May 17, 2021	SYSTEM	(\$3,000.00)	
					2	Jun 2, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodwj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$3,000.00)	
					3	Jun 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$3,000.00)	
					4	Jul 1, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$3,000.00)	·
					5	Jul 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$3,000.00)	
				- Total				\$0.00	
			Material - To	- Total				\$0.00	
	1210 -	Total						\$0.00	
	1230	PREF THERMO PVMT MARK, R/R XING	Material		3	Jun 16, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$800.00)	
					4	Jul 1, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$800.00)	
					5	Jul 16, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$800.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1230 -	Total						\$0.00	
	1240	4 IN. WHITE WATERBORNE PAVEMENT	Material		3	Jun 16, 2021	SYSTEM	\$1,904.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
		MARKING			3	Jun 16, 2021	SYSTEM	(\$1,904.70)	
					4	Jul 1, 2021	SYSTEM	\$1,904.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$1,904.70)	
					5	Jul 16, 2021	SYSTEM	\$1,904.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$1,904.70)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1240 -	Total						\$0.00	
	1250	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		3	Jun 16, 2021	SYSTEM	\$737.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 33 on the current Payment Estimate.



Popular Line Decorption Adjustment Municipal													
March 150	Pro	ject	Line	Description		Adjustment				Amount	Remarks		
MARKENG	J4S:	3278	1250	WATERBORNE	Material	3.	3		SYSTEM	(\$737.70)			
2021 5							4		SYSTEM	\$737.70	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment		
2021							4		SYSTEM	(\$737.70)			
Total							5		SYSTEM	\$737.70	Estimate Item Adjustment (0019) due to user schnod1 overridding Payment		
1259 - Total							5		SYSTEM	(\$737.70)			
1260 SIN. WHITE Material Sin. White Sin. W						- Total				\$0.00			
1260 The Augustement offsets the original system-generated Material Pyrment Estimate Exception 35 on the current Payment Estimate Exception 35 on the cu					Material - To	tal				\$0.00			
WATERBORNET A			1250 -	Total						\$0.00			
3				8 IN. WHITE WATERBORNE	Material		3		SYSTEM	\$56.00	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment		
2021 SYSTEM (\$56.00) 2021 SYSTEM (\$56.				MARKING			3		SYSTEM	(\$56.00)			
2021 5							4		SYSTEM	\$56.00	Estimate Item Adjustment (0016) due to user schnod1 overridding Payment		
2021 SySTEM Estimate Exception 33 on the current Payment Estimate Exception 33 on the current Payment Estimate.									4		SYSTEM	(\$56.00)	
1200									5		SYSTEM	\$56.00	Estimate Item Adjustment (0020) due to user schnod1 overridding Payment
1260 - Total 1270 24 IN. WHITE WATERBORNE PAVEMENT MARKING 2021 3 Jun 16, 2021 3 Jun 16, 2021 3 Jun 16, 2021 3 Jun 16, 2021 4 Jul 1, 2021 5 Jul 16, 2021 5 Jul 16							5		SYSTEM	(\$56.00)			
1260 - Total 1270 24 IN. WHITE WATERBORNE PAVEMENT MARKING 2021 3 Jun 16, 2021 3 Jun 16, 2021 3 Jun 16, 2021 3 Jun 16, 2021 4 Jul 1, 2021 5 Jul 16, 2021 5 Jul 16						- Total				\$0.00			
1260 - Total 24 IN. WHITE WATERBORNE PAVEMENT MARKING 2021 3 Jun 16, 2021 3 Jun 16, 2021 3 Jun 16, 2021 3 Jun 16, 2021 4 Jul 1, 2021 4 Jul 1, 2021 5 Jul 16,					Material - To	tal				\$0.00			
1270			1260 -	Total						\$0.00			
3			1270	WATERBORNE PAVEMENT	Material		3		SYSTEM		Estimate Item Adjustment (0016) due to user schnod1 overridding Payment		
2021 Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 40 on the current Payment Estimate.							3		SYSTEM	(\$120.00)			
2021 5							4		SYSTEM	\$120.00	Estimate Item Adjustment (0017) due to user schnod1 overridding Payment		
Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate.									4		SYSTEM	(\$120.00)	
Total S0.00 Material - Total \$0.00							5		SYSTEM	\$120.00	Estimate Item Adjustment (0021) due to user schnod1 overridding Payment		
Solution							5		SYSTEM	(\$120.00)			
1270 - Total S0.00 12 IN. PIPE CULVERT GROUP C						- Total				\$0.00			
1320 12 IN. PIPE CULVERT GROUP C 1 May 17, 2021 SYSTEM \$2,700.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate. 1 May 17, 2021 SYSTEM \$2,700.00 2 Jun 2, 2021 SYSTEM \$2,700.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. 2 Jun 2, 2021 SYSTEM \$2,700.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 26 on the current Payment Estimate. 3 Jun 16, 2021 SYSTEM \$2,700.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment					Material - To	tal				\$0.00			
CULVERT GROUP C Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate. 1 May 17, 2021 2 Jun 2, 2021 SYSTEM \$2,700.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. 2 Jun 2, 2021 SYSTEM \$2,700.00 This adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. 3 Jun 16, 2021 SYSTEM \$2,700.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment			1270 -	Total						\$0.00			
2 Jun 2, 2021 SYSTEM \$2,700.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. 2 Jun 2, 2021 SYSTEM (\$2,700.00) 3 Jun 16, 2021 SYSTEM \$2,700.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment				12 IN. PIPE CULVERT GROUP	Material		1	May 17, 2021	SYSTEM	\$2,700.00	Estimate Item Adjustment (0004) due to user schnod1 overridding Payment		
2021 Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate. 2 Jun 2, 2021 (\$2,700.00) 3 Jun 16, SYSTEM \$2,700.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment				С									
2021 3 Jun 16, SYSTEM \$2,700.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment				С			1		SYSTEM	(\$2,700.00)			
2021 Estimate Item Adjustment (0017) due to user schnod1 overridding Payment				С				2021 Jun 2,			Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment		
				С			2	Jun 2, 2021 Jun 2, 2021	SYSTEM	\$2,700.00	Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1320	12 IN. PIPE CULVERT GROUP	Material		3	Jun 16, 2021	SYSTEM	(\$2,700.00)	
		С			4	Jul 1, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$2,700.00)	
					5	Jul 16, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$2,700.00)	
					6	Aug 2, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$2,700.00)	
					7	Aug 16, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$2,700.00)	
					8	Sep 2, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$2,700.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		Total					0) (0==14	\$0.00	
	1330	18 IN. PIPE CULVERT GROUP C	P		1	May 17, 2021		\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$3,250.00)	
					2	Jun 2, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$3,250.00)	
					3	Jun 16, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$3,250.00)	
					4	Jul 1, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$3,250.00)	
					5	Jul 16, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$3,250.00)	
					6	Aug 2, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$3,250.00)	
					7	Aug 16, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$3,250.00)	
					8	Sep 2, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment



1930 1931 1972 1972 1972 1972 1973 1973 1973 1974	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1330 - Total 1330	J4S3278	1330		Material						Estimate Exception 49 on the current Payment Estimate.	
130 - Total						8		SYSTEM	(\$3,250.00)		
130 - Total					- Total				\$0.00		
1				Material - To	tal				\$0.00		
2001 2001		1330 -	Total						\$0.00		
2 Jun 2		1340	SEASON	Material		1		SYSTEM	\$1,051.38	Estimate Item Adjustment (0006) due to user schnod1 overridding Payment	
2021						1		SYSTEM	(\$1,051.38)		
2						2		SYSTEM	\$1,051.38	Estimate Item Adjustment (0016) due to user woodwj1 overridding Payment	
2021 SySTEM St.188.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 45 on the current Payment Estimate Estimate Exception 55 on the current Payment Estimate Exception						2		SYSTEM	(\$1,051.38)	Estimate Exception 20 on the durient Laymont Estimate.	
A						3		SYSTEM	\$1,051.38	Estimate Item Adjustment (0019) due to user schnod1 overridding Payment	
2021 September September						3		SYSTEM	(\$1,051.38)		
2021 5						4		SYSTEM	\$1,188.00	Estimate Item Adjustment (0020) due to user schnod1 overridding Payment	
2021 System Stimate Stimate						4		SYSTEM	(\$1,188.00)		
2021							5		SYSTEM	\$1,188.00	Estimate Item Adjustment (0024) due to user schnod1 overridding Payment
2021 Estimate Item Adjustment (0017) due to user schnod overridding Payment Estimate Exception 22 on the current Payment Estimate Exception 22 on the current Payment Estimate.						5		SYSTEM	(\$1,188.00)		
2021 7						6		SYSTEM	\$1,188.00	Estimate Item Adjustment (0017) due to user schnod1 overridding Payment	
2021 Estimate Item Adjustment (0010) due to user schood overridding Payment Estimate Exception 23 on the current Payment Estimate.						6		SYSTEM	(\$1,188.00)		
2021						7		SYSTEM	\$1,188.00	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment	
Estimate Item Adjustment (0008) due to user schood overridding Payment Estimate Exception 53 on the current Payment Estimate. 8 Sep 2, 2021 \$995TEM (\$1,188.00) Total \$0.00						7		SYSTEM	(\$1,188.00)		
Total \$0.00						8		SYSTEM	\$1,188.00	Estimate Item Adjustment (0008) due to user schnod1 overridding Payment	
Total So.00 So.0						8		SYSTEM	(\$1,188.00)		
Solution Solution					- Total				\$0.00		
ROCK DITCH CHECK Material 1				Material - To	tal				\$0.00		
CHECK 2021 May 17, 2021 May 17, 2021 SYSTEM (\$3,360.00) 2 Jun 2, 2021 SYSTEM (\$3,360.00) 2 Jun 2, 2021 SYSTEM (\$3,360.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 32 on the current Payment Estimate. SYSTEM (\$3,360.00) 3 Jun 16, 2021 SYSTEM \$3,360.00 This adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. 3 Jun 16, 2021 SYSTEM (\$3,360.00) This adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. 3 Jun 16, 2021 SYSTEM (\$3,360.00) SYSTEM \$3,360.00 This adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.		1340 -	Total						\$0.00		
2 Jun 2, 2021 SYSTEM \$3,360.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. 2 Jun 2, 2021 3 Jun 16, 2021 \$3,360.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate. 3 Jun 16, 2021 \$SYSTEM \$3,360.00 (\$3,360.00)		1350		Material		1		SYSTEM	\$3,360.00	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment	
Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. 2 Jun 2, 2021 3 Jun 16, 2021 SYSTEM \$3,360.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate. 3 Jun 16, 2021 SYSTEM (\$3,360.00)						1		SYSTEM	(\$3,360.00)		
2021 3 Jun 16, 2021 \$3,360.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate. 3 Jun 16, 2021 \$3,360.00 (\$3,360.00)						2		SYSTEM	\$3,360.00	Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment	
2021 Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate. 3 Jun 16, 2021 (\$3,360.00)						2		SYSTEM	(\$3,360.00)		
2021						3		SYSTEM	\$3,360.00	Estimate Item Adjustment (0020) due to user schnod1 overridding Payment	
						3		SYSTEM	(\$3,360.00)		
						4		SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1350	ROCK DITCH CHECK	Material			2021			Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$3,360.00)	
					5	Jul 16, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$3,360.00)	
					6	Aug 2, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$3,360.00)	
					7	Aug 16, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$3,360.00)	
					8	Sep 2, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$3,360.00)	
				- Total				\$0.00	
	4050	Tetal	Material - To	otal				\$0.00	
		Total						\$0.00	
	1370	SILT FENCE	Material		3	Jun 16, 2021	SYSTEM	\$188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$188.00)	
				- Total	4	Jul 1, 2021	SYSTEM	\$188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$188.00)	
					5	Jul 16, 2021	SYSTEM	\$188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$188.00)	
								\$0.00	
			Material - To	ıl - Total				\$0.00	
	1370 -	Total						\$0.00	
	1380	CONCRETE FOOTINGS, EMBEDDED	Material		3	Jun 16, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$165.00)	
					4	Jul 1, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$165.00)	
					5	Jul 16, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$165.00)	
					6	Aug 2, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Aug 2,	SYSTEM	(\$165.00)	
						2021			



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1380	CONCRETE FOOTINGS, EMBEDDED	Material		7	Aug 16, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$165.00)	
					8	Sep 2, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$165.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1380 -	· Total						\$0.00	
	1400	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Overrun	Overrun	3	Jun 16, 2021	SYSTEM	(\$24,504.32)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jul 1, 2021	SYSTEM	\$2.45	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',61.26999 - 59.61000, 'is applied (if non-zero).
					6	Aug 2, 2021	SYSTEM	\$24,501.87	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',61.26999 - 59.61000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - To	tal				\$0.00	
			Price FUEL		2	Jun 2, 2021	SYSTEM	\$8,375.96	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	Jun 16, 2021	SYSTEM	\$1,113.38	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jul 1, 2021	SYSTEM	(\$0.07)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$9,489.27	
			Price FUEL -	Total				\$9,489.27	
	1400 -	· Total						\$9,489.27	
	1410	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	NT RE		2	Jun 2, 2021	SYSTEM	\$12,227.43	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jul 1, 2021	SYSTEM	\$0.02	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$12,227.45	
			Price FUEL -	Total				\$12,227.45	
		· Total		Total	-			\$12,227.45	
	1410 - 1420	BITUMINOUS PAVEMENT MIXTURE		Total	2	Jun 2, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		BITUMINOUS PAVEMENT		Total	2			\$12,227.45	Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Total		2021 Jun 2,		\$12,227.45 \$139,327.38	Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Total	2	Jun 2, 2021 Jun 16,	SYSTEM	\$12,227.45 \$139,327.38 (\$139,327.38)	Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Total	2	Jun 2, 2021 Jun 16, 2021 Jun 16,	SYSTEM SYSTEM	\$12,227.45 \$139,327.38 (\$139,327.38) \$139,327.38	Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Total	3	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1,	SYSTEM SYSTEM	\$12,227.45 \$139,327.38 (\$139,327.38) \$139,327.38 (\$139,327.38)	Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Total	2 3 3 4	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$12,227.45 \$139,327.38 (\$139,327.38) \$139,327.38 (\$139,327.38) \$139,327.38	Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Total	2 3 3 4	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$12,227.45 \$139,327.38 (\$139,327.38) \$139,327.38 (\$139,327.38) \$139,327.38	Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Total	2 3 3 4 4 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$12,227.45 \$139,327.38 (\$139,327.38) \$139,327.38 (\$139,327.38) \$139,327.38 (\$139,327.38) \$139,327.38	Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment



March Marc	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Page	J4S3278	1420	PAVEMENT	Material		7		SYSTEM	\$139,327.38	Estimate Item Adjustment (0013) due to user schnod1 overridding Payment
2021			PG64-22 (SUR			7		SYSTEM	(\$139,327.38)	
Total						8		SYSTEM	\$139,327.38	Estimate Item Adjustment (0011) due to user schnod1 overridding Payment
Material - Total						8		SYSTEM	(\$139,327.38)	
Chief Bern QVRN - Total					- Total				\$0.00	
Adjustment 2021				Material - To	tal				\$0.00	
Other Ham Adjustment - Total Overrun					OVRN	6		schnod1	\$5,261.48	Manual negative adjustment from estimate 0002 paid for now.
Overrun					OVRN - Tota	al			\$5,261.48	
2				Other Item A	.djustment - T	otal			\$5,261.48	
2				Overrun	Overrun	2		woodwj1	(\$5,261.48)	
System S						2		SYSTEM	(\$5,261.48)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
2021 3						2		SYSTEM	\$5,261.48	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 2367.500;
2021 Seminate Item Adjustment (0023) oveririding Payment Estimate Exception 55 on the current Payment Estimate. Material Insufficiency Quantity 2367-500; Overrun Quantity Balance 87:00.						3		SYSTEM	(\$5,261.48)	
2021 4						3		SYSTEM	\$5,261.48	Estimate Item Adjustment (0023) overridding Payment Estimate Exception 55 on the current Payment Estimate. Material Insufficiency Quantity 2367.500;
2021 SYSTEM SySTEM Span Spa						4		SYSTEM	(\$5,261.48)	
2021 of '1-62680' is applied (if non-zero). 5 Jul 16, 2021 sysTEM 2021 sysTEM 2021 control to the current Payment Estimate Stemate St						4		SYSTEM	\$5,261.48	Estimate Item Adjustment (0025) overridding Payment Estimate Exception 60 on the current Payment Estimate. Material Insufficiency Quantity 2367.500;
Coverrun - Total						5		SYSTEM	(\$5,261.48)	
Overrun - Total Price FUEL Price FUEL Price FUEL Price FUEL 2 Jun 2, 2021 33,851.45 Price FUEL - Total 33,851.45 Price FUEL - Total 4 Jun 1, 2021 SYSTEM SYSTEM SySTEM SySTEM SySTEM SySTEM SySTEM SySTEM System System-generated Material Payment Estimate Exception 6 on the current Payment Estimate. (\$5,261.48) Reference Item Price Adjustment Index Adjustment Type applied is FUEL \$3,851.45 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 2 Jun 2, 2021 SYSTEM System-generated Material Payment Estimate Exception 6 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate.						5		SYSTEM	\$5,261.48	Estimate Item Adjustment (0028) overridding Payment Estimate Exception 53 on the current Payment Estimate. Material Insufficiency Quantity 2367.500;
Price FUEL 2 Jun 2, 2021 SYSTEM \$3,851.45 Reference Item Price Adjustment Index Adjustment Type applied is FUEL Total Price FUEL - Total 1420 - Total 1430 TACK COAT Material 2 Jun 2, 2021 SYSTEM \$21,587.50 2 Jun 2, 2021 This adjustment (0024) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 2 Jun 16, 2021 SYSTEM \$22,375.00 3 Jun 16, 2021 SYSTEM \$22,375.00 1 Jun 16, 2021 This adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 Jun 16, 2021 SYSTEM \$22,375.00 4 Jul 1, 2021 SYSTEM \$22,375.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. 4 Jul 1, 2021 SYSTEM \$22,375.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate Estimate Exception 8 on the current Payment Estimate.					Overrun - Total				(\$5,261.48)	
Total \$3,851.45					tal				(\$5,261.48)	
TACK COAT Material 2 Jun 2, 2021 SYSTEM \$21,587.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 2 Jun 16, 2021 SYSTEM \$22,375.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 Jun 16, 2021 SYSTEM \$22,375.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate. 4 Jul 1, 2021 SYSTEM (\$22,375.00)				Price FUEL		2	. ,	SYSTEM		Reference Item Price Adjustment Index Adjustment Type applied is FUEL
TACK COAT Material 2 Jun 2, 2021 SYSTEM \$21,587.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 2 Jun 2, 2021 SYSTEM \$22,375.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 Jun 16, 2021 SYSTEM \$22,375.00 SYSTEM \$22,375.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate Estimate Exception 8 on the current Payment Estimate. 3 Jul 1, 2021 SYSTEM \$22,375.00										
TACK COAT Material 2 Jun 2, 2021 3 Jun 16, 2021 3 Jun 16, 2021 4 Jul 1, 2021 5YSTEM \$21,587.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				Price FUEL -	Total					
Estimate Item Adjustment (0024) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 2 Jun 2, 2021 3 Jun 16, 2021 \$YSTEM										
3 Jun 16, 2021 \$22,375.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 Jun 16, 2021 \$22,375.00 (\$22,375.00) 4 Jul 1, 2021 \$22,375.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		1430	TACK COAT	Material		2		SYSTEM	\$21,587.50	Estimate Item Adjustment (0024) due to user woodwj1 overridding Payment
2021 Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 Jun 16, 2021 (\$22,375.00) 4 Jul 1, 2021 SYSTEM \$22,375.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate. 4 Jul 1, 2021 SYSTEM (\$22,375.00)						2		SYSTEM	(\$21,587.50)	
4 Jul 1, 2021 SYSTEM \$22,375.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate. 4 Jul 1, 2021 SYSTEM (\$22,375.00)						3		SYSTEM	\$22,375.00	Estimate Item Adjustment (0025) due to user schnod1 overridding Payment
2021 Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate. 4 Jul 1, 2021 (\$22,375.00)						3		SYSTEM	(\$22,375.00)	
2021						4		SYSTEM	\$22,375.00	Estimate Item Adjustment (0027) due to user schnod1 overridding Payment
5 Jul 16, SYSTEM \$22,375.00 This adjustment offsets the original system-generated Material Payment						4		SYSTEM	(\$22,375.00)	
						5	Jul 16,	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
4S3278	1430	TACK COAT	Material			2021			Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					5	Jul 16, 2021	SYSTEM	(\$22,375.00)				
					6	Aug 2, 2021	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					6	Aug 2, 2021	SYSTEM	(\$22,375.00)				
					7	Aug 16, 2021	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
									7	Aug 16, 2021	SYSTEM	(\$22,375.00)
					8	Sep 2, 2021	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
					8	Sep 2, 2021	SYSTEM	(\$22,375.00)				
				- Total				\$0.00				
			Material - Total					\$0.00				
	1430 -	Total						\$0.00				
	1460	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN			2	Jun 2, 2021	SYSTEM	\$18,303.54	Payment Estimate Item Adjustment generated Stockpile Transaction			
		F1 3 IN	STIVII	- Total				\$18,303.54				
			Construction	Stockpile S	TMI - Tota			\$18,303.54				
	1460 -	Total						\$18,303.54				
	1470	TYPE A CRASHWORTHY	Stockpile		2	Jun 2, 2021	SYSTEM	\$3,090.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
		END TERMINAL (MASH)	STMI	- Total				\$3,090.00				
			Construction	Stockpile S	TMI - Tota			\$3,090.00				
	1470 -	Total						\$3,090.00				
4S3278	- Total							\$46,788.92				
Overall -	Total							\$108,801.22				