

Pay Estimate Created Date: September 16, 2021

| Progress Estima 11 | te Number | Contract ID Prime Contrac | 210219-D05 storS & A Equipment & | | mber 2, 2021 Original Contract Amo mber 15, 2021Net Change Order Am Current Contract Amo | ount\$10,278.43 | | |
|-----------------------|-------------|--|-------------------------------------|--------------------------------------|--|-----------------|--|--|
| Approval Date | | | | | | By User | | |
| September 16, 2021 | | Generated and Approved (and should be considered Draft) at the Project Office Level by | | | | | | |
| September 16, 2021 | | | Reviewed and App | proved (and should be considered Dra | aft) at the Resident Engineer Level by | oeschd1 | | |
| September 17, 2021 | | Reviewed and Approved at the Central Office Controllers Office Level by | | | | | | |
| Original Comp | letion Date | Curren | t Completion Date | Actual Completion Date | % of Current Contract Amou | Int Complete | | |
| November | 1, 2021 | No | vember 1, 2021 | | 55.98% | | | |

Contract Informational Dates

| Date Description | Original Completion Date | Current Completion Date | Date Description | Original Completion Date | Current Completion Date | Days Remaining on Milestone | Diary Charge Days |
|---------------------------|--------------------------------|-------------------------------|---|--------------------------------|-------------------------------|--------------------------------|-------------------------|
| Acceptance Date | | | Milestone - Completion Date - JSP B - Completion Date, J5P3195 | November 1, 2021 | November 1, 2021 | 42 | |
| Awarded Date | March 3, 2021 | March 3, 2021 | | | | | |
| Letting Date | February 19, 2021 | February 19, 2021 | | | | | |
| Notice to Proceed Date | April 5, 2021 | April 5, 2021 | | | | | |
| Work Began Date | April 21, 2021 | April 21, 2021 | | | | | |

Milestones

| Contract Total Pa | ay For Estimate No. 11 | | | |
|-------------------|----------------------------|---------------|----------------|----------------|
| | | This Estimate | Previous | To Date |
| 210219-D05 | | | | |
| | Total Posted Items Pay | \$339,948.92 | \$2,139,238.18 | \$2,479,187.10 |
| | Gross Item Adjustments | \$1,730.38 | \$11,271.44 | \$13,001.82 |
| | Incentive | \$0.00 | \$0.00 | \$0.00 |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 |
| | , | | \$2,150,509.62 | \$2,492,188.92 |

Contract Total Payable This Estimate: Items Paid This Estimate Period

\$341,679.30

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|---|------|---------------|--------------------------|-----------------------------|
| J5P3195 | 0010 | 2013000 | CLEARING AND GRUBBING | ACRE | \$4,062.430 | 1.5 | \$6,093.65 |
| | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | LS | \$175,733.110 | 0.05 | \$8,786.66 |
| | 0030 | 2031000 | CLASS A EXCAVATION | CUYD | \$13.990 | 1,511 | \$21,138.89 |
| | 0050 | 2036000 | COMPACTING EMBANKMENT | CUYD | \$4.090 | 514 | \$2,102.26 |
| | 0080 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | SQYD | \$8.623 | 1,682 | \$14,503.90 |
| | 0140 | 6096010A | FURNISHING TYPE 1 ROCK DITCH LINER | CUYD | \$61.080 | 105 | \$6,413.40 |
| | 0160 | 6096041 | PLACING TYPE 1 ROCK DITCH LINER | CUYD | \$12.400 | 105 | \$1,302.00 |
| | 0190 | 6113010 | FURNISHING TYPE 1 ROCK BLANKET | CUYD | \$62.890 | 191 | \$12,011.99 |
| | 0200 | 6113030 | PLACING TYPE 1 ROCK BLANKET | CUYD | \$18.320 | 191 | \$3,499.12 |
| | 0250 | 6161025 | CHANNELIZER (TRIM LINE) | EA | \$27.140 | 100 | \$2,714.00 |
| | 0260 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | EA | \$339.310 | 7 | \$2,375.17 |
| | 0470 | 7261024 | 24 IN. PIPE GROUP A | LF | \$58.170 | 48 | \$2,792.16 |
| | 0550 | 7320624A | 24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | EA | \$860.410 | 2 | \$1,720.82 |
| | 0650 | 5021308 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 | SQYD | \$49.150 | 4,506.4 | \$221,489.56 |



Pay Estimate Created Date: September 16, 2021

| Progress E | stimate Num 11 | 1001 | tract ID 210219-D05 le ContractorS & A Equipment & Builders, Ll | Pay Period StartSepte LCPay Period End Septe | mber 15, 2021 N | et Change Order A | | |
|-------------------|-------------------|--------------|--|---|------------------------|--------------------------|-----------------------------|--|
| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount | |
| J5P3195 | | | FT. JOINTS) | | | | | |
| | 0690 | 5021340 | TYPE A2 SHOULDER | SQYD | \$34.420 | 958.9 | \$33,005.34 | |
| Project J5P3 | 3195 - Total | | | | | | \$339,948.92 | |
| Overall - Total | | | | | | | | |

Contract Adjustments This Estimate

| Project lumber | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|-------------------|-------------|---|--------------------|----------------------------------|---|------------------------|---------------------------------------|----------------------|
| 5P3195 | 0030 | CLASS A EXCAVATION | Price | | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | 1,511 | \$0.10 | \$154.12 |
| | 0050 | COMPACTING EMBANKMENT | Material | | | -5,667 | \$4.09 | (\$23,178.03 |
| | 0050 | COMPACTING EMBANKMENT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 5,667 | \$4.09 | \$23,178.03 |
| | 0060 | COMPACTING IN CUT | Material | | | -80.3 | \$107.58 | (\$8,638.67 |
| | 0060 | COMPACTING IN CUT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 80.3 | \$107.58 | \$8,638.67 |
| | 0080 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Price | | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | 1,682 | \$0.12 | \$197.30 |
| | 0080 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | | -23,036 | \$8.62 | (\$198,639.66 |
| | 0080 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 23,036 | \$8.62 | \$198,639.66 |
| | 0120 | 3 IN. CONCRETE MEDIAN STRIP | Material | | | -71.1 | \$180.96 | (\$12,866.26 |
| | 0120 | 3 IN. CONCRETE MEDIAN STRIP | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | 71.1 | \$180.96 | \$12,866.26 |
| | 0190 | FURNISHING TYPE 1 ROCK BLANKET | Material | | | -191 | \$62.89 | (\$12,011.99 |
| | 0190 | FURNISHING TYPE 1 ROCK BLANKET | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | 191 | \$62.89 | \$12,011.99 |
| | 0650 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS) | Price | | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | 4,506.4 | \$0.31 | \$1,378.96 |
| | 0650 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS) | Material | | | -25,416.6 | \$49.15 | (\$1,249,225.89 |
| | 0650 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user webers1 | 25,416.6 | \$49.15 | \$1,249,225.89 |



Pay Estimate Created Date: September 16, 2021

| Progres | ss Esti 1 | mate Number 1 | Contract ID Prime Contrac | 210219-D t or S & A Equ | | Pay Period StartSeptember 2, 2021 Iders, LLCPay Period End September 15, 2021 | Net Change | Order Amoun | |
|-------------------|--------------|------------------|---|-----------------------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| Project Number | Line No. | Item De | escription | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J5P3195 | | | | | | overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | |
| | 0800 | CONDUIT, | 2 IN. RIGID, IN TRENCH | Overrun | | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | -79 | \$11.31 | (\$893.49 |
| | 0800 | CONDUIT, | 2 IN. RIGID, IN TRENCH | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | 79 | \$11.31 | \$893.49 |
| | 0920 | CONDUCTOR | NDUIT, 1 IN., 2 S AND 1 BARE UTRAL, 8 AWG | Material | | | -2,240 | \$3.39 | (\$7,593.60 |
| | 0920 | CONDUCTOR | NDUIT, 1 IN., 2 S AND 1 BARE UTRAL, 8 AWG | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate. | 2,240 | \$3.39 | \$7,593.60 |
| | 1220 | | -1 CONCRETE ERTS-BRIDGE) | Material | | | -2.9 | \$1,140.04 | (\$3,306.12 |
| | 1220 | | B-1 CONCRETE ERTS-BRIDGE) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | 2.9 | \$1,140.04 | \$3,306.12 |
| Total | | | | | | | | | \$1,730.3 |



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | (| Contract Project Informatio | n | | | | |
|-------------------|---------------------------|------------------------------|-----------|--------|----------------------------|----------------------------------|-------------------------------|--|--|--|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work | | | | |
| J5P3195 | FAF-63-3(110) | Intersection improvements | 63 | BOONE | from Rte. Y and Rte | from Rte. Y and Rte. M to Rte. H | | | | | |
| Totals by J | lob Numbers | | | | | | | | | | |
| J5P3195 | | | | | This Estimate | Previous | To Date | | | | |
| | Posted Iten Gross Item | n Pay Adjustments | | | \$339,948.92 \$1,730.38 | \$2,139,238.18 \$11,271.44 | \$2,479,187.10 \$13,001.82 | | | | |
| | | Gro | ss Item F | Pay | \$341,679.30 | \$2,150,509.62 | \$2,492,188.92 | | | | |
| | Incentive | | | | \$0.00 | \$0.00 | \$0.00 | | | | |
| | Disincentiv | e | | | \$0.00 | \$0.00 | \$0.00 | | | | |
| | Liquidated | | | | \$0.00 \$0.00 \$0.00 | | | | | | |
| | Other Cont | ract Adjustmen | ts | | \$0.00 | \$0.00 | \$0.00 | | | | |



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|--|--|---------------|------------|
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 2037075, Project Item Line Number 0060, Material Set 203707596, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 3040506, Project Item Line Number 0080, Material Set 304050696, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 5021308, Project Item Line Number 0650, Material Set 502130896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 5021308, Project Item Line Number 0650, Material Set 502130896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 6083003, Project Item Line Number 0120, Material Set 608300396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 6083003, Project Item Line Number 0120, Material Set 608300396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 6113010, Project Item Line Number 0190, Material Set 611301096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 7034040, Project Item Line Number 1220, Material Set 703404096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 7034040, Project Item Line Number 1220, Material Set 703404096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 7034040, Project Item Line Number 1220, Material Set 703404096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 9017407, Project Item Line Number 0920, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 210219-D05, Contract Project J5P3195, Project Item Line Number 0800, Contract Line Item Number 0800, Item 9013002, Minor Item. | Working on Change Order | webers1 | Overridden |



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

d date and can differ from the posted amount at the time the Estimate was Generated. N

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTI To Date (See repo generated date) |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|---|
| 10219-D05 | J5P3195 | 0001 | 0010 | 2013000 | CLEARING AND GRUBBING | 15.00 | 0.00 | 15.00 | ACRE | 6.60 | \$4,062.43 | \$26,812. |
| | | 0001 | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 0.35 | \$175,733.11 | \$61,506. |
| | | 0001 | 0030 | 2031000 | CLASS A EXCAVATION | 18,603.00 | 0.00 | 18,603.00 | CUYD | 8,754.00 | \$13.99 | \$122,468. |
| | | 0001 | 0040 | 2035500 | EMBANKMENT IN PLACE | 135.00 | 0.00 | 135.00 | CUYD | 0.00 | \$15.88 | \$0. |
| | | 0001 | 0050 | 2036000 | COMPACTING EMBANKMENT | 11,536.00 | 0.00 | 11,536.00 | CUYD | 5,667.00 | \$4.09 | \$23,178. |
| | | 0001 | 0060 | 2037075 | COMPACTING IN CUT | 239.20 | 0.00 | 239.20 | STA | 80.30 | \$107.58 | \$8,638 |
| | | 0001 | 0070 | 2071000 | LINEAR GRADING CLASS 1 | 20.20 | 0.00 | 20.20 | STA | 0.00 | \$537.52 | \$0 |
| | | 0001 | 0080 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 47,626.00 | 0.00 | 47,626.00 | SQYD | 35,036.00 | \$8.62 | \$302,115 |
| | | 0001 | 0090 | 3101003 | GRAVEL (A) | 77.00 | 0.00 | 77.00 | SQYD | 0.00 | \$30.07 | \$0 |
| | | 0001 | 0100 | 4019905 | MISC.VEGETATIVE BARRIER 3 IN. | 3,492.00 | 0.00 | 3,492.00 | SQYD | 0.00 | \$7.44 | \$0 |
| | | 0001 | 0110 | 6044011 | PIPE COLLAR, TYPE A | 8.00 | 0.00 | 8.00 | EA | 1.00 | \$612.56 | \$612 |
| | | 0001 | 0120 | 6083003 | 3 IN. CONCRETE MEDIAN STRIP | 281.90 | 0.00 | 281.90 | SQYD | 71.10 | \$180.96 | \$12,866 |
| | | 0001 | 0130 | 6085008 | PAVED APPROACH, 8 IN. | 54.20 | 0.00 | 54.20 | SQYD | 0.00 | \$257.87 | \$0 |
| | | 0001 | 0140 | 6096010A | FURNISHING TYPE 1 ROCK DITCH LINER | 188.00 | 0.00 | 188.00 | CUYD | 132.00 | \$61.08 | \$8,06 |
| | | 0001 | 0150 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 48.00 | 0.00 | 48.00 | CUYD | 0.00 | \$61.08 | \$ |
| | | 0001 | 0160 | 6096041 | PLACING TYPE 1 ROCK DITCH LINER | 188.00 | 0.00 | 188.00 | CUYD | 132.00 | \$12.40 | \$1,63 |
| | | 0001 | 0170 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | 48.00 | 0.00 | 48.00 | CUYD | 0.00 | \$46.23 | \$ |
| | | 0001 | 0180 | 6097000 | ROCK LINING | 49.00 | 0.00 | 49.00 | CUYD | 0.00 | \$91.89 | \$ |
| | | 0001 | 0190 | 6113010 | FURNISHING TYPE 1 ROCK BLANKET | 289.00 | 0.00 | 289.00 | CUYD | 191.00 | \$62.89 | \$12,01 |
| | | 0001 | 0200 | 6113030 | PLACING TYPE 1 ROCK BLANKET | 289.00 | 0.00 | 289.00 | CUYD | 191.00 | \$18.32 | \$3,49 |
| | | 0001 | 0210 | 6117000A | GABIONS | 129.00 | 0.00 | 129.00 | CUYD | 129.00 | \$271.45 | \$35,01 |
| | | 0001 | 0220 | 6141024 | GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM) | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$2,622.28 | ş |
| | | 0001 | 0230 | 6161005 | CONSTRUCTION SIGNS | 964.00 | 0.00 | 964.00 | SQFT | 760.00 | \$7.92 | \$6,01 |
| | | 0001 | 0240 | 6161010 | RELOCATED SIGNS | 1,114.00 | 0.00 | 1,114.00 | SQFT | 264.00 | \$7.92 | \$2,09 |
| | | 0001 | 0250 | 6161025 | CHANNELIZER (TRIM LINE) | 145.00 | 0 100.00 | 0 245.00 | EA | 245.00 | \$27.14 | \$6,64 |
| | | 0001 | 0260 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | 3.00 | 4.00 | 7.00 | EA | 7.00 | \$339.31 | \$2,37 |
| | | 0001 | 0270 | 6161033 | DIRECTIONAL INDICATOR BARRICADE | 76.00 | 0.00 | 76.00 | EA | 30.00 | \$113.10 | \$3,39 |
| | | 0001 | 0280 | 6161040 | FLASHING ARROW PANEL | 5.00 | 0.00 | 5.00 | EA | 2.00 | \$2,827.57 | \$5,65 |
| | | 0001 | 0290 | 6161055 | SEQUENTIAL FLASHING WARNING LIGHT | 76.00 | 0.00 | 76.00 | EA | 0.00 | \$282.76 | ş |
| | | 0001 | 0300 | 6161099 | CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$7,351.68 | \$22,05 |
| | | 0001 | 0310 | 6162004 | TEMPORARY SHORT-TERM RUMBLE STRIPS | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$7,351.68 | \$58,81 |
| | | 0001 | 0320 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 0.75 | \$239,065.66 | \$179,29 |
| | | 0001 | 0330 | 6191000 | PAVEMENT EDGE TREATMENT | 23,180.00 | 0.00 | 23,180.00 | LF | 16,950.00 | \$2.11 | \$35,76 |
| | | 0001 | 0340 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 12.00 | 0.00 | 12.00 | LF | 0.00 | \$33.93 | s |
| | | 0001 | 0350 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 27.00 | 0.00 | 27.00 | EA | 0.00 | \$395.86 | \$ |
| | | 0001 | 0360 | 6200030 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY) | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$735.17 | ę |
| | | 0001 | 0370 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 41,366.00 | 0.00 | 41,366.00 | LF | 0.00 | \$0.23 | 5 |
| | | 0001 | 0380 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 23,658.00 | 0.00 | 23,658.00 | LF | 0.00 | \$0.23 | 5 |
| | | 0001 | 0390 | 6205906A | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 1,504.00 | 0.00 | 1,504.00 | LF | 0.00 | \$0.45 | \$ |
| | | 0001 | 0400 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 2,005.00 | 0.00 | 2,005.00 | LF | 0.00 | \$0.17 | \$ |
| | | 0001 | 0410 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 3,129.00 | 0.00 | 3,129.00 | LF | 0.00 | \$0.17 | S |
| | | 0001 | 0420 | 6207001 | PAVEMENT MARKING REMOVAL | 5,795.00 | 0.00 | 5,795.00 | LF | 0.00 | \$1.13 | S |
| | | 0001 | 0430 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$52,932.06 | \$ |



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Im.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTE To Date (See repor generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 10219-D05 | J5P3195 | 0001 | 0440 | 7261012 | 12 IN. PIPE GROUP A | 122.00 | 0.00 | 122.00 | LF | 0.00 | \$47.86 | \$0.0 |
| | | 0001 | 0450 | 7261015 | 15 IN. PIPE GROUP A | 128.00 | 0.00 | 128.00 | LF | 128.00 | \$45.88 | \$5,872.6 |
| | | 0001 | 0460 | 7261018 | 18 IN. PIPE GROUP A | 87.00 | 0.00 | 87.00 | LF | 0.00 | \$62.78 | \$0.0 |
| | | 0001 | 0470 | 7261024 | 24 IN. PIPE GROUP A | 71.00 | 0.00 | 71.00 | LF | 48.00 | \$58.17 | \$2,792.1 |
| | | 0001 | 0480 | 7261030 | 30 IN. PIPE GROUP A | 17.00 | 0.00 | 17.00 | LF | 0.00 | \$122.87 | \$0.0 |
| | | 0001 | 0490 | 7261048 | 48 IN. PIPE GROUP A | 14.00 | 0.00 | 14.00 | LF | 14.00 | \$190.88 | \$2,672.3 |
| | | 0001 | 0500 | 7261060 | 60 IN. PIPE GROUP A | 49.00 | 0.00 | 49.00 | LF | 0.00 | \$200.06 | \$0.0 |
| | | 0001 | 0510 | 7311053 | PRECAST CONCRETE DROP INLET 5 FT X 3 FT | 9.00 | 0.00 | 9.00 | FT | 0.00 | \$695.97 | \$0.0 |
| | | 0001 | 0520 | 7320612A | 12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$11,136.86 | \$0.0 |
| | | 0001 | 0530 | 7320615A | 15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$735.20 | \$1,470.4 |
| | | 0001 | 0540 | 7320618A | 18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$774.90 | \$0.0 |
| | | 0001 | 0550 | 7320624A | SECTION 24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END | 4.00 | 0.00 | 4.00 | EA | 2.00 | \$860.41 | \$1,720.8 |
| | | | | | SECTION | | | | | | | |
| | | 0001 | 0560 | 7320630A | 30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$1,274.68 | \$0.0 |
| | | 0001 | 0570 | 7320648A | 48 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$2,875.76 | \$2,875.7 |
| | | 0001 | 0580 | 7320660A | 60 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$4,177.01 | \$0.0 |
| | | 0001 | 0590 | 8051000A | SEEDING - COOL SEASON MIXTURES | 10.00 | 0.00 | 10.00 | ACRE | 0.00 | \$2,431.71 | \$0.0 |
| | | 0001 | 0600 | 8061003 | SEDIMENT TRAP EXCAVATION | 24.00 | 0.00 | 24.00 | CUYD | 8.00 | \$39.59 | \$316.7 |
| | | 0001 | 0610 | 8061004 | SEDIMENT TRAP ROCK | 35.00 | 0.00 | 35.00 | CUYD | 12.00 | \$73.52 | \$882. |
| | | 0001 | 0620 | 8061005 | ROCK DITCH CHECK | 341.00 | 0.00 | 341.00 | LF | 153.00 | \$12.16 | \$1,860.4 |
| | | | 0630 | 8061007A | CURB INLET CHECK | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$197.93 | \$0.0 |
| | | | 0640 | 8061019 | SILT FENCE | 7,268.00 | 0.00 | 7,268.00 | LF | 7,090.00 | \$2.38 | \$16,874.2 |
| | | 0002 | 0650 | 5021308 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS) | 36,434.90 | 0.00 | 36,434.90 | SQYD | 25,416.60 | \$49.15 | \$1,249,225.8 |
| | | 0002 | 0660 | 6262000A | PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP | 22.20 | 0.00 | 22.20 | STA | 0.00 | \$738.74 | \$0. |
| | | 0004 | 0690 | 5021340 | TYPE A2 SHOULDER | 7,458.80 | 0.00 | 7,458.80 | SQYD | 5,323.50 | \$34.42 | \$183,234. |
| | | 0010 | 0710 | 6061061 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING | 63.00 | 0.00 | 63.00 | LF | 0.00 | \$33.37 | \$0. |
| | | 0010 | 0720 | 6061063 | MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING | 113.00 | 0.00 | 113.00 | LF | 0.00 | \$28.84 | \$0. |
| | | 0010 | 0730 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$3,749.70 | \$0. |
| | | 0010 | 0740 | 6064100 | MEDIAN GUARD CABLE 3 - STRAND | 5,115.00 | 0.00 | 5,115.00 | LF | 0.00 | \$16.41 | \$0. |
| | | 0010 | 0750 | 6064110 | ANCHOR ASSEMBLY, GUARD CABLE 3-STRAND | 14.00 | 0.00 | 14.00 | EA | 0.00 | \$3,902.04 | \$0. |
| | | 0020 | 0760 | 9011062 | LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2 | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$3,110.32 | \$0. |
| | | 0020 | 0770 | 9011106 | BRACKET ARM, 6 FT. OR 1.8 M | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$481.82 | \$0. |
| | | 0020 | 0780 | 9011313 | LUMINAIRE, LED-C | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$506.70 | \$0. |
| | | 0020 | 0790 | 9012230 | BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$6,559.96 | \$0. |
| | | 0020 | 0800 | 9013002 | CONDUIT, 2 IN. RIGID, IN TRENCH | 54.00 | 0.00 | 54.00 | LF | 133.00 | \$11.31 | \$1,504. |
| | | 0020 | 0810 | 9013003 | CONDUIT, 3 IN. RIGID, IN TRENCH | 460.00 | 0.00 | 460.00 | LF | 287.00 | \$12.44 | \$3,570. |
| | | 0020 | 0820 | 9013004 | CONDUIT, 4 IN. RIGID, IN TRENCH | 114.00 | 0.00 | 114.00 | LF | 0.00 | \$14.70 | \$0. |
| | | 0020 | 0830 | 9014004 | CONDUIT, 4 IN. RIGID, PUSHED | 949.00 | 0.00 | 949.00 | LF | 870.00 | \$32.80 | \$28,536. |
| | | 0020 | 0840 | 9015010 | TRENCHING TYPE I | 2,926.00 | 0.00 | 2,926.00 | LF | 2,584.00 | \$3.96 | \$10,232 |
| | | 0020 | 0850 | 9016110 | PULL BOX, PREFORMED CLASS 1 | 10.00 | 0.00 | 10.00 | EA | 5.00 | \$1,108.41 | \$5,542. |
| | | 0020 | 0860 | 9016112 | PULL BOX, PREFORMED CLASS 3 | 3.00 | 0.00 | 3.00 | EA | 2.00 | \$1,866.19 | \$3,732 |
| | | 0020 | 0870 | 9017002 | CABLE, 2 AWG 1 CONDUCTOR | 580.00 | 0.00 | 580.00 | LF | 0.00 | \$2.83 | \$0. |
| | | 0020 | 0880 | 9017008 | CABLE, 8 AWG 1 CONDUCTOR | 4,090.00 | 0.00 | 4,090.00 | LF | 0.00 | \$1.41 | \$0. |
| | | 0020 | 0890 | 9017110 | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET | 450.00 | 0.00 | 450.00 | LF | 0.00 | \$0.96 | \$0.0 |
| | | 0020 | 0900 | 9017202 | WIRE, 2 AWG, BARE NEUTRAL | 290.00 | 0.00 | 290.00 | LF | 0.00 | \$2.71 | \$0.0 |



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract m.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|------------------------|----------------|-------------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|------------|--|
| 10219-D05 | J5P3195 | 0020 | 0910 | 9017208 | WIRE, 8 AWG, BARE NEUTRAL | 2,060.00 | 0.00 | 2,060.00 | LF | 0.00 | \$1.35 | \$0.00 |
| | | 0020 | 0920 | 9017407 | CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG | 2,360.00 | 0.00 | 2,360.00 | LF | 2,240.00 | \$3.39 | \$7,593.60 |
| | | 0020 | 0930 | 9018245 | POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT) | 8.00 | 0.00 | 8.00 | EA | 2.00 | \$1,244.13 | \$2,488.26 |
| | | 0020 | 0940 | 9018610 | POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE, LIGHTING ONLY | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$1.13 | \$0.00 |
| | | 0020 | 0950 | 9028500 | CABLE, LOOP DETECTOR, IN DUCT | 420.00 | 0.00 | 420.00 | LF | 0.00 | \$5.09 | \$0.00 |
| | | 0020 | 0960 | 9028510 | CABLE, LOOP DETECTOR, LEAD-IN | 400.00 | 0.00 | 400.00 | LF | 0.00 | \$1.47 | \$0.00 |
| | | 0020 | 0970 | 9105020 | CONDUIT, 1 IN., LOOP DETECTOR | 30.00 | 0.00 | 30.00 | LF | 0.00 | \$9.05 | \$0.00 |
| | | 0040 | 0980 | 9031210 | STRUCTURAL STEEL POSTS | 780.00 | 0.00 | 780.00 | LB | 0.00 | \$11.54 | \$0.00 |
| | | 0040 | 0990 | 9031242 | 36 IN. SURFACE-MOUNT DELINEATOR POST | 18.00 | 0.00 | 18.00 | EA | 0.00 | \$122.86 | \$0.00 |
| | | 0040 | 1000 | 9031256 | 7 FT. CHANNEL POST DELINEATOR, WHITE | 28.00 | 0.00 | 28.00 | EA | 0.00 | \$54.45 | \$0.00 |
| | | 0040 | 1010 | 9031270A | 2 IN. PSST POST - 12 GA. | 1,043.00 | 214.00 | 1,257.00 | LF | 0.00 | \$11.59 | \$0.00 |
| | | 0040 | 1020 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | 327.00 | -3.00 | 324.00 | LF | 0.00 | \$10.70 | \$0.00 |
| | | 0040 | 1030 | 9031280 | 2.5 IN. PSST POST - 12 GA. | 202.00 | 63.00 | 265.00 | LF | 0.00 | \$13.23 | \$0.00 |
| | | 0040 | 1040 | 9031281 | POST ANCHOR FOR 2.5 IN. PSST - 7 GA. | 54.00 | 6.00 | 60.00 | LF | 0.00 | \$51.39 | \$0.00 |
| | | 0040 | 1050 | 9035004A | SH-FLAT SHEET | 932.00 | 39.00 | 971.00 | SQFT | 0.00 | \$26.40 | \$0.00 |
| | | 0040 | 1060 | 9035011A | ST-STRUCTURAL | 120.00 | 0.00 | 120.00 | SQFT | 0.00 | \$41.44 | \$0.00 |
| | | | 1070 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 175.00 | -9.00 | 166.00 | SQFT | 0.00 | \$35.02 | \$0.00 |
| | | | 1080 | 2079909 | MISC.FINE GRADING AND SEEDING (WATER LINE RELOCATION) | 7.30 | 0.00 | 7.30 | STA | 0.00 | \$2,047.11 | \$0.00 |
| | | 0060 | 1090 | 3109910 | MISC.GRAVEL (WATER LINE RELOCATION) | 250.00 | 0.00 | 250.00 | TONS | 0.00 | \$51.76 | \$0.00 |
| | | 0060 | 1100 | 6039901 | WATER | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$7,199.49 | \$0.00 |
| | | 0060 | 1110 | 6039901 | WATER | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$3,176.76 | \$0.00 |
| | | 0060 | 1120 | 6039902 | WATER | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$1,937.86 | \$0.00 |
| | | 0060 | 1130 | 6039902 | WATER | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$2,053.22 | \$0.00 |
| | | 0060 | 1140 | 6039902 | WATER | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$6,405.41 | \$0.00 |
| | | 0060 | 1150 | 6039902 | WATER | 10.00 | 0.00 | 10.00 | EA | 0.00 | \$891.27 | \$0.00 |
| | | 0060 | 1160 | 6039902 | WATER | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$1,451.52 | \$0.00 |
| | | 0060 | 1170 | 6039903 | WATER | 25.00 | 0.00 | 25.00 | LF | 0.00 | \$110.95 | \$0.00 |
| | | 0060 | 1180 | 6039903 | WATER | 55.00 | 0.00 | 55.00 | LF | 0.00 | \$145.82 | \$0.00 |
| | | 0060 | 1190 | 6039903 | WATER | 700.00 | 0.00 | 700.00 | LF | 0.00 | \$43.52 | \$0.00 |
| | | 0060 | 1200 | 6189901 | MISC.MOBILIZATION FOR WATER LINE RELOCATION | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$3,654.03 | \$0.00 |
| | | 0060 | 1210 | 7032002 | CLASS B CONCRETE (MISC) | 10.00 | 0.00 | 10.00 | CUYD | 0.00 | \$239.84 | \$0.00 |
| | | 0070 | 1220 | 7034040 | CLASS B-1 CONCRETE (CULVERTS-BRIDGE) | 2.90 | 0.00 | 2.90 | CUYD | 2.90 | \$1,140.04 | \$3,306.12 |
| | | 0070 | 1230 | 7061020 | REINFORCING STEEL (CULVERTS-BRIDGE) | 490.00 | 0.00 | 490.00 | LB | 490.00 | \$4.78 | \$2,342.20 |
| | | 0070 | 1240 | 7133000 | BRIDGE GUARDRAIL (W-BEAM) | 29.00 | 0.00 | 29.00 | LF | 0.00 | \$265.79 | \$0.00 |
| | | 0040 | 5001 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | 0.00 | 1.80 | 1.80 | CUYD | 0.00 | \$1,057.10 | \$0.00 |
| | Project J5 | 5P3195 - To | otal Value | Posted to D | ate as of Report Generated Date | | | | | | | \$2,479,187.08 |



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|---|------------------------------|---------------------|----------------------------|---------------------|----------|
| 0010 | 2013000 | CLEARING AND GRUBBING | 9/15/21 | 9/16/21 | 1.50 | ACRE | E New Salem (West), Martin Ln, E Loy Martin, and Bullard Seed | | | | | |
| 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 9/15/21 | 9/16/21 | 0.05 | LS | US 63 | | | | | |
| 0030 | 2031000 | CLASS A EXCAVATION | 9/15/21 | 9/16/21 | 500.00 | CUYD | US 63 | | | | | |
| | | | | 9/16/21 | 1,011.00 | CUYD | Martin Lane | | | | | |
| 0050 | 2036000 | COMPACTING EMBANKMENT | 9/15/21 | 9/16/21 | 14.00 | CUYD | Martin Lane | | | | | |
| | | | | 9/16/21 | 500.00 | CUYD | US 63 | | | | | |
| 0080 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 9/15/21 | 9/16/21 | 618.00 | SQYD | Loy Martin | 15+68 | | 16+62.92 | | |
| | | | | 9/16/21 | 1,064.00 | SQYD | Martin Lane | 12+50.18 | | 14+32.99 | | |
| 0140 | 6096010A | FURNISHING TYPE 1 ROCK DITCH LINER | 9/15/21 | 9/16/21 | 105.00 | CUYD | US 63 LT | 650+70 | | 657+74 | | |
| 0160 | 6096041 | PLACING TYPE 1 ROCK DITCH LINER | 9/15/21 | 9/16/21 | 105.00 | CUYD | US 63 LT | 650+70 | | 657+74 | | |
| 0190 | 6113010 | FURNISHING TYPE 1 ROCK BLANKET | 9/15/21 | 9/16/21 | 5.00 | CUYD | Minor Hill Rt | 3+92 | | 4+16 | | |
| | | | | 9/16/21 | 34.00 | CUYD | US 63 RT | 621+12 | | 622+42 | | |
| | | | | 9/16/21 | 152.00 | CUYD | US 63 RT | 614+38 | | 617+33 | | |
| 0200 | 6113030 | PLACING TYPE 1 ROCK BLANKET | 9/15/21 | 9/16/21 | 5.00 | CUYD | Minor Hill RT | 3+92 | | 4+16 | | |
| | | | | 9/16/21 | 34.00 | CUYD | US 63 RT | 621+12 | | 622+42 | | |
| | | | | 9/16/21 | 152.00 | CUYD | US 63 RT | 614+38 | | 617+33 | | |
| 0250 | 6161025 | CHANNELIZER (TRIM LINE) | 9/15/21 | 9/16/21 | 100.00 | EA | US 63 | | | | | |
| 0260 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | 9/15/21 | 9/16/21 | 7.00 | EA | US 63 | | | | | |
| 0470 | 7261024 | 24 IN. PIPE GROUP A | 9/15/21 | 9/16/21 | 48.00 | LF | E Loy Martin 10-01 and 10-02 | | | | | |
| 0550 | 7320624A | 24 IN. GROUP A FLARED END SECT | 9/15/21 | 9/16/21 | 2.00 | EA | E Loy Martin 10-01 and 10-02 | | | | | |
| 0650 | 5021308 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, | 9/15/21 | 9/16/21 | 23.80 | SQYD | E Loy Martin | 15+68 | | 15+25.88 | | |
| | | | | 9/16/21 | 614.30 | SQYD | US 63 NB | 680+58.36 | | 686+00 | | |
| | | | | 9/16/21 | 618.00 | SQYD | E Loy Martin | 15+68 | | 16+62.92 | | |
| | | | | 9/16/21 | 1,228.10 | SQYD | US 63 NB | 700+00 | | 709+20.04 | | |
| | | | | 9/16/21 | 2,022.20 | SQYD | US 63 NB | 686+00 | | 700+00 | | |
| 0690 | 5021340 | TYPE A2 SHOULDER | 9/15/21 | 9/16/21 | 227.80 | SQYD | US 63 NB | 680+33.36 | | 686+00 | | |
| | | | | 9/16/21 | 280.00 | SQYD | US 63 NB | 701+65.04 | | 709+35.04 | | |
| | | | | 9/16/21 | 451.10 | SQYD | | 686+00 | | 699+53.36 | | |

The information below this line are details for Construction Signs (if applicable). No Data Available



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---------|--------|----------------------------|--------------------|-----------------------------|------------------|-----------------|-----------------|---------------|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|---|-----------------|--------|---------------|--|
| J5P3195 | 0030 | 0030 CLASS A EXCAVATION | Price FUEL | .) p 0 | 2 | May 3, 2021 | SYSTEM | \$32.93 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 3 | May 17, 2021 | SYSTEM | \$251.27 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$143.20 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 6 | Jul 2, 2021 | SYSTEM | \$50.00 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 7 | Jul 15, 2021 | SYSTEM | \$52.00 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$52.00 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$149.76 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 11 | Sep 16, 2021 | SYSTEM | \$154.12 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$885.28 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | Price FUEL | - Total | | | | \$885.28 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 0030 - | Total | | | | | | \$885.28 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 0050 | COMPACTING EMBANKMENT | Material | | 2 | May 3, 2021 | SYSTEM | \$1,092.03 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 2 | May 3, 2021 | SYSTEM | (\$1,092.03) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 3 | May 17, 2021 | SYSTEM | \$7,889.61 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 3 | May 17, 2021 | SYSTEM | (\$7,889.61) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$7,889.61 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 4 Jun 3, 2021 | | SYSTEM | (\$7,889.61) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 5 | Jun 16, 2021 | SYSTEM | \$12,298.63 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$12,298.63) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 6 | Jul 2, 2021 | SYSTEM | \$14,343.63 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 6 | Jul 2, 2021 | SYSTEM | (\$14,343.63) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 7 | Jul 15, 2021 | SYSTEM | \$16,388.63 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 7 | Jul 15, 2021 | SYSTEM | (\$16,388.63) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$18,433.63 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$18,433.63) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$18,433.63 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$18,433.63) | |
| | | | | | | 10 | Sep 2, 2021 | SYSTEM | \$21,075.77 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$21,075.77) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|--|--|
| J5P3195 | 0050 | COMPACTING EMBANKMENT | Material | | 11 | Sep 16, 2021 | SYSTEM | \$23,178.03 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | |
| | | | | | 11 | Sep 16, 2021 | SYSTEM | (\$23,178.03) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - T | otal | | | | \$0.00 | | |
| | 0050 - | Total | | | | | | \$0.00 | | |
| | 0060 | COMPACTING IN CUT | Material | | 2 | May 3, 2021 | SYSTEM | \$258.19 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 2 | May 3, 2021 | SYSTEM | (\$258.19) | | |
| | | | | | 3 | May 17, 2021 | SYSTEM | \$5,744.77 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 3 | May 17, 2021 | SYSTEM | (\$5,744.77) | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$5,744.77 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$5,744.77) | | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$5,744.77 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$5,744.77) | | |
| | | | | | 6 | Jul 2, 2021 | SYSTEM | \$5,744.77 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 6 | Jul 2, 2021 | SYSTEM | (\$5,744.77) | | |
| | | | | | | 7 | Jul 15, 2021 | SYSTEM | \$5,744.77 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 7 | Jul 15, 2021 | SYSTEM | (\$5,744.77) | | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$5,744.77 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$5,744.77) | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$5,744.77 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$5,744.77) | | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$8,638.67 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$8,638.67) | | |
| | | | | | | 11 | Sep 16, 2021 | SYSTEM | \$8,638.67 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 11 | Sep 16, 2021 | SYSTEM | (\$8,638.67) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - T | otal | | | | \$0.00 | | |
| | 0060 - | Total | | | | | | \$0.00 | | |
| | 0080 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | 2 | May 3, 2021 | SYSTEM | \$7,717.59 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|---------|------|---------------------------|--------------------|-----------------------------|-----------------|-----------------|-----------------|--|--|--|
| J5P3195 | 0080 | AGGREGATE | Material | | 2 | May 3, 2021 | SYSTEM | (\$7,717.59) | | |
| | | FOR BASE (6 IN. THICK) | | | 3 | May 17, 2021 | SYSTEM | \$53,040.13 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | | | 3 | May 17, 2021 | SYSTEM | (\$53,040.13) | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$94,352.98 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$94,352.98) | | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$82,073.81 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$82,073.81) | | |
| | | | | | 6 | Jul 2, 2021 | SYSTEM | \$93,283.72 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | | | 6 | Jul 2, 2021 | SYSTEM | (\$93,283.72) | | |
| | | | | 7 | Jul 15, 2021 | SYSTEM | \$119,652.89 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | |
| | | | | 7 | Jul 15, 2021 | SYSTEM | (\$119,652.89) | | | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$164,337.32 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$164,337.32) | | |
| | | | | 9 | Aug 16, 2021 | SYSTEM | \$155,714.31 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$155,714.31) | | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$184,135.76 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$184,135.76) | | |
| | | | Material - To | | | 11 | Sep 16, 2021 | SYSTEM | \$198,639.66 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | | | | 11 | Sep 16, 2021 | SYSTEM |
| | | | | - Total | | | | \$0.00 \$0.00 | | |
| | | | Price FUEL | | 2 | May 3, 2021 | SYSTEM | \$67.93 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| | | | | | 3 | May 17, 2021 | SYSTEM | \$592.35 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$539.95 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$411.24 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| | | | | | 6 | Jul 2, 2021 | SYSTEM | \$264.50 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| | | | | | | 7 | Jul 15, 2021 | SYSTEM | \$485.34 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | | | 8 | Aug 2, 2021 | SYSTEM | \$858.97 |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$730.85 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |



| Nome Ope Adjustment Number Date By Preference for Pice Adjustment Index Adjustment Type appled in FUE 50 000 Statu - Frad - Statu | | | | | | | | | - | | | | | |
|---|--|----------------|--------------|--------------------|---------|----------------|-----------------|---------------|----------------|---|--|--|--------|--|
| ACCRECATE IN TRICK PUEL IN TRICK Instrument Instrument INSTRUM Instrument Instrument INSTRUM Instrument INSTRUM | ject | Line | Description | Adjustment Type | | Est. Number | Created Date | Created By | Amount | Remarks | | | | |
| N. TRCK) -16dal Vest FUEL - 10al Vest FUEL - 10al 0969 - Total 5 Jul 1 SYSTEM | 195 | 0080 | AGGREGATE | | | 11 | | SYSTEM | \$197.30 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | |
| CODD Total Survey Control Survey Control Survey Control 0100 PPE COLLER, Normalized Control Material 5 Jun 16, Jun | | | | | - Total | | | | \$4,148.43 | | | | | |
| 010 PPE COLLAR, TYPE A. Mential 5 Jun 16, 2001 SYSTEM 6612.40 5612.60 The adjustment offects the original system-generated Material Paryant Estimate Encoglob 5 on the ourset Paryant Estimate. 010 PPE COLLAR, Method 0 Jul 2, 2001 SYSTEM 6612.56) 0 Jul 2, 2001 SYSTEM 6612.60 This adjustment offects the original system-generated Material Paryant Estimate Encoglob 5 on the ourset Paryant Estimate. 010 Total U Jul 2, 2001 SYSTEM 6612.50) 010 Total U Jul 2, 2001 SYSTEM 6612.60 010 Total Total State 1 Total State 1 0110 Total Total State 1 Total State 1 0120 Total Total Total State 1 Total State 1 0120 Total Total State 1 State 1 State 1 State 1 0120 Total Total State 1 State 1 State 1 State 1 0120 Total Jul | | | | Price FUEL | - Total | | | | \$4,148.43 | | | | | |
| 010 PPE COLLAR, TYPE A. Mential 5 Jun 16, 2001 SYSTEM 6612.40 5612.60 The adjustment offects the original system-generated Material Paryant Estimate Encoglob 5 on the ourset Paryant Estimate. 010 PPE COLLAR, Method 0 Jul 2, 2001 SYSTEM 6612.56) 0 Jul 2, 2001 SYSTEM 6612.60 This adjustment offects the original system-generated Material Paryant Estimate Encoglob 5 on the ourset Paryant Estimate. 010 Total U Jul 2, 2001 SYSTEM 6612.50) 010 Total U Jul 2, 2001 SYSTEM 6612.60 010 Total Total State 1 Total State 1 0110 Total Total State 1 Total State 1 0120 Total Total Total State 1 Total State 1 0120 Total Total State 1 State 1 State 1 State 1 0120 Total Total State 1 State 1 State 1 State 1 0120 Total Jul | | 0080 - | Total | | | | | | \$4.148.43 | | | | | |
| Image: state in the state in thest in the state in thest in the state in the state in | | | PIPE COLLAR, | Material | | 5 | | SYSTEM | | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payme Estimate Exception 5 on the current Payment Estimate. | | | | |
| Image: bit is a bit is bit is a bit is a bit is a bit is bit is a bit is a bit is a bit | | | | | | 5 | | SYSTEM | (\$612.56) | | | | | |
| Image: state in the ima | | | | | | 6 | | SYSTEM | \$612.56 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payme Estimate Exception 5 on the current Payment Estimate. | | | | |
| Number Name Number Name State | | | | | | 6 | | SYSTEM | (\$612.56) | | | | | |
| O110 - Total Second | | | | | - Total | | | | \$0.00 | | | | | |
| 0120 03.1%. Material Material 7 Jul 15. 2021 SYSTEM \$12,666.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 7 Jul 15. 2021 SYSTEM \$12,666.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 8 Aug 2. 2021 SYSTEM \$12,666.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 8 Aug 2. 2021 SYSTEM \$12,866.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 9 Aug 16. 2021 SYSTEM \$12,866.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 9 Aug 16. 2021 SYSTEM \$12,866.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 10 Sep 2. 2021 SYSTEM \$12,866.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 11 Sep 16. 2021 SYSTEM \$12,866.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 11 Sep 16. 2021 SYSTEM | | | | Material - T | otal | | | | \$0.00 | | | | | |
| 0120 03.1%. Material Material 7 Jul 15. 2021 SYSTEM \$12,666.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 7 Jul 15. 2021 SYSTEM \$12,666.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 8 Aug 2. 2021 SYSTEM \$12,666.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 8 Aug 2. 2021 SYSTEM \$12,866.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 9 Aug 16. 2021 SYSTEM \$12,866.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 9 Aug 16. 2021 SYSTEM \$12,866.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 10 Sep 2. 2021 SYSTEM \$12,866.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 11 Sep 16. 2021 SYSTEM \$12,866.26 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 11 Sep 16. 2021 SYSTEM | | 01 <u>10</u> - | Total | | | | | | \$0.0 <u>0</u> | | | | | |
| | | 0120 | CONCRETE | Material | | 7 | | SYSTEM | \$12,866.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payme Estimate Exception 7 on the current Payment Estimate. | | | | |
| Vision Figure 1 2021 Section Extinuite Exception 8 on the current Payment Estimate. 8 Aug 2, 2021 SYSTEM \$12,866.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 9 Aug 16, 2021 SYSTEM \$12,866.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 9 Aug 16, 2021 SYSTEM \$12,866.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 10 Sep 2, 2021 SYSTEM \$12,866.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 10 Sep 2, 2021 SYSTEM \$12,866.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. 11 Sep 16, 2021 SYSTEM \$12,866.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. 11 Sep 16, 2021 SYSTEM \$12,866.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. | | | | | | 7 | | SYSTEM | (\$12,866.26) | | | | | |
| in the second is a | | | | | | 8 | | SYSTEM | \$12,866.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payme Estimate Exception 8 on the current Payment Estimate. | | | | |
| | | | | | | 8 | | SYSTEM | (\$12,866.26) | | | | | |
| $ \begin{array}{ c c c c } \hline c c c c c c c c c c c c c c c c c c $ | | | | | | 9 | | SYSTEM | \$12,866.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Paym Estimate Exception 6 on the current Payment Estimate. | | | | |
| 10 Sep 2, 2021 SYSTEM (\$12,866.26) 10 Sep 2, 2021 SYSTEM (\$12,866.26) 11 Sep 16, 2021 SYSTEM \$12,866.26) 11 Sep 16, 2021 SYSTEM \$12,866.26) This adjustment (0006) due to user weberst overridding Payment Estimate. 11 Sep 16, 2021 SYSTEM \$12,866.26) This adjustment (0006) due to user weberst overridding Payment Estimate. This adjustment (0007) due to user weberst overridding Payment Estimate. This adjustment (0007) due to user weberst overridding Payment Estimate. This adjustment (0007) due to user weberst overridding Payment Estimate. Total Total< | | | | | | 9 | | SYSTEM | (\$12,866.26) | | | | | |
| $ \begin{array}{c c c c c c } \hline \begin{tabular}{ c c c c c } \hline \begin{tabular}{ c c c c c c c } \hline \begin{tabular}{ c c c c c c c } \hline \begin{tabular}{ c c c c c c c c c c c c c c c c c c c$ | | | | | | 10 | | SYSTEM | \$12,866.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payme Estimate Exception 6 on the current Payment Estimate. | | | | |
| $ \begin{array}{c c c c c c } \hline & 2021 & $ | | | | | | 10 | 2021 | SYSTEM | (\$12,866.26) | | | | | |
| Image: Constraint of the second sec | | | | | | 11 | | SYSTEM | \$12,866.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payme Estimate Exception 6 on the current Payment Estimate. | | | | |
| Material - Total \$0.00 0120 - Total \$0.00 0190 FURNISHING TYPE 1 ROCK BLANKET Material | | | | | | 11 | | SYSTEM | (\$12,866.26) | | | | | |
| 0120 - Total \$0.00 0190 FURNISHING TYPE 1 ROCK BLANKET Material 11 Sep 16, 2021 SYSTEM \$12,011.99 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate. - Total - Total \$0.00 - Total \$0.00 Material - Total \$0.00 0190 - Total \$0.00 0210 GABIONS Material 4 Jun 3, 2021 SYSTEM \$20,087.30 Control - Total \$2021 \$YSTEM \$20,087.30 0210 GABIONS Material - Total \$2021 \$YSTEM \$20,087.30 0190 - Total - Total \$2021 \$YSTEM \$20,087.30 0210 GABIONS Material - Total \$YSTEM \$20,087.30 - Total - Total \$YSTEM \$20,087.30 - Total - Total \$0.00 | | | | | - Total | | | | \$0.00 | | | | | |
| 0190 FURNISHING TYPE 1 ROCK BLANKET Material Parent Material Parent 11 11 Sep 16, 2021 SYSTEM \$12,011.99 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate. 0190 - Total - Total \$0.00 0190 - Total - Total \$0.00 0190 - Total \$0.00 0210 GABIONS Material 4 Jun 3, 2021 SYSTEM \$20,087.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 0210 GABIONS Material 4 Jun 3, 2021 SYSTEM \$20,087.30 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. - Total - Total \$0.00 \$0.00 \$0.00 | | | | Material - T | otal | | | | \$0.00 | | | | | |
| TYPE 1 ROCK BLANKET TYPE 1 ROCK BLANKET 2021 2021 2021 Estimate Item Adjustment (0007) due to user webers1 overridding Paym Estimate Exception 8 on the current Payment Estimate. 11 Sep 16, 2021 SYSTEM (\$12,011.99) • Total • Total • Material - Total • Output • S0.00 • Output • Output <td <="" colspan="4" td=""><td></td><td>0120 -</td><td>Total</td><td></td><td></td><td></td><td></td><td></td><td>\$0.00</td><td></td></td> | <td></td> <td>0120 -</td> <td>Total</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>\$0.00</td> <td></td> | | | | | 0120 - | Total | | | | | | \$0.00 | |
| O190 - Total GABIONS Material - Total 2021 \$0.00 0210 GABIONS Material 4 Jun 3, 2021 SYSTEM \$20,087.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Item Adjustment (0005) due to user webers1 overridding Payment Item Adjustment (0005) due to user webers1 overridding Payment Item Adjustment (0005) due to user webers1 overridding Payment Item Adjustment (0005) due to user webers1 overridding Payment Item Adjustment Item Adjustment (0005) due to user webers1 overridding Payment Item Adjustment I | | 0190 | TYPE 1 ROCK | Material | | 11 | | SYSTEM | \$12,011.99 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payme Estimate Exception 8 on the current Payment Estimate. | | | | |
| Material - Total \$0.00 0190 - Total \$0.00 0210 GABIONS Material 4 Jun 3, 2021 SYSTEM SYSTEM SYSTEM CONSTANT - Total - Total - Total \$0.00 Material - Total - Total - Total - Total - Total \$0.00 | | | | | | 11 | | SYSTEM | (\$12,011.99) | | | | | |
| 0190 - Total \$0.00 0210 GABIONS Material 4 Jun 3, 2021 SYSTEM \$20,087.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. - Total - Total SYSTEM \$0.00 Material - Total - Total \$0.00 | | | | | - Total | | | | \$0.00 | | | | | |
| 0210 GABIONS Material 4 Jun 3, 2021 SYSTEM \$20,087.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 0210 -Total SYSTEM \$20,087.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate. 0210 -Total SYSTEM \$\$0,00 Material - Total | | | | Material - T | otal | | | | \$0.00 | | | | | |
| 0210 GABIONS Material 4 Jun 3, 2021 SYSTEM \$20,087.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 0210 - Total - Total \$\$0,000 • * * * * * * * * * * * * * * * * * * * | | 0 <u>190 -</u> | Total | | | | | | \$0.00 | | | | | |
| - Total \$0.00 Material - Total \$0.00 | | | | Material | | 4 | | SYSTEM | | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payme Estimate Exception 10 on the current Payment Estimate. | | | | |
| Material - Total \$0.00 | | | | | | 4 | | SYSTEM | (\$20,087.30) | | | | | |
| | | | | | - Total | | | | \$0.00 | | | | | |
| 0210 - Total \$0.00 | | | | Material - T | otal | | | | \$0.00 | | | | | |
| | | 0210- | Total | | | | | | \$0.00 | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|--|--|
| J5P3195 | 0330 | PAVEMENT EDGE TREATMENT | Material | | 3 | May 17, 2021 | SYSTEM | \$6,100.01 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 3 | May 17, 2021 | SYSTEM | (\$6,100.01) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0330 - | Total | | | | | | \$0.00 | |
| | 0640 | SILT FENCE | Material | | 2 | May 3, 2021 | SYSTEM | \$2,058.70 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 2 | May 3, 2021 | SYSTEM | (\$2,058.70) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0640 - | Total | | | | | | \$0.00 | |
| | 0650 | CONCRETE PAVEMENT (8 IN. NON- REINFORCED, | Material | | 2 | May 3, 2021 | SYSTEM | \$16,214.58 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 2 | May 3, 2021 | SYSTEM | (\$16,214.58) | |
| | | | | | 3 | May 17, 2021 | SYSTEM | \$146,059.06 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 3 | May 17, 2021 | SYSTEM | (\$146,059.06) | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$233,211.84 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$233,211.84) | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$398,144.49 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$398,144.49) | |
| | | | | | 6 | Jul 2, 2021 | SYSTEM | \$508,496.07 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 6 | Jul 2, 2021 | SYSTEM | (\$508,496.07) | |
| | | | | | 7 | Jul 15, 2021 | SYSTEM | \$617,668.05 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 7 | Jul 15, 2021 | SYSTEM | (\$617,668.05) | |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$772,298.86 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$772,298.86) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$885,407.76 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$885,407.76) | |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | Estimate Item Adjustment (0008) due to user webe | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$1,027,736.33) | |
| | | | | | 11 | Sep 16, 2021 | SYSTEM | \$1,249,225.89 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |



Sep 21, 2021

| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|---------|--------|---------------------------------------|---------------|--------------------|--------|-----------------|---------|------------------|--|
| | | | Туре | Adjustment Type | Number | Date | By | | |
| J5P3195 | 0650 | CONCRETE PAVEMENT (8 | Material | | 11 | Sep 16, 2021 | SYSTEM | (\$1,249,225.89) | |
| | | IN. NON- REINFORCED, | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | | | Price FUEL | | 2 | May 3, 2021 | SYSTEM | \$65.32 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 3 | May 17, 2021 | SYSTEM | \$776.69 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$521.32 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$1,006.71 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 6 | Jul 2, 2021 | SYSTEM | \$673.56 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 7 | Jul 15, 2021 | SYSTEM | \$693.01 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | \$981.58 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$828.47 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$1,042.49 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 11 | Sep 16, 2021 | SYSTEM | \$1,378.96 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | - Total | | | | \$7,968.11 | |
| | | | Price FUEL | - Total | | | | \$7,968.11 | |
| | 0650 - | Total | | | | | | \$7,968.11 | |
| | 0690 | TYPE A2 SHOULDER | Material | | 3 | May 17, 2021 | SYSTEM | \$15,960.55 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 3 | May 17, 2021 | SYSTEM | (\$15,960.55) | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$33,005.34 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$33,005.34) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | Fotal | | | | \$0.00 | |
| | 0690 - | Total | | | | | | \$0.00 | |
| | 0800 | CONDUIT, 2 IN. RIGID, IN TRENCH | Overrun | Overrun | 8 | Aug 2, 2021 | SYSTEM | \$893.49 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 8 | Aug 2, 2021 | SYSTEM | (\$893.49) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$893.49) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$893.49 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | (\$893.49) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 10 | Sep 2, 2021 | SYSTEM | \$893.49 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 11 | Sep 16, 2021 | SYSTEM | (\$893.49) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 11 | Sep 16, 2021 | SYSTEM | \$893.49 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - T | otal | | | | \$0.00 | |
| | | | | | | | | | |



Sep 21, 2021

| CONDUCTORS Appendix Support Support <th>Project</th> <th>Line</th> <th>Description</th> <th>Adjustment Type</th> <th>Other Adjustment Type</th> <th>Est. Number</th> <th>Created Date</th> <th>Created By</th> <th>Amount</th> <th>Remarks</th> | Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---|-----------|---------|--------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| CONDUCT: 00 CONDUCT: 00 Construct Paramate Exception 1 on the current Parameter Exception 2 on the current Parameter Extension 2 on the cur | J5P3195 | 0800 - | Total | | | | | | \$0.00 | |
| Nome North | | 0920 | CONDUIT, 1 IN., 2 | Material | | 8 | | SYSTEM | \$7,593.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| Image: Second | | | CONDUCTOR | | | 8 | | SYSTEM | (\$7,593.60) | |
| 0 223 223 1 223 1< | | | | | | 9 | | SYSTEM | \$7,593.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | | 9 | | SYSTEM | (\$7,593.60) | |
| Provide Provide <t< td=""><td></td><td></td><td></td><td></td><td></td><td>10</td><td></td><td>SYSTEM</td><td>\$7,593.60</td><td>This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.</td></t<> | | | | | | 10 | | SYSTEM | \$7,593.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| Image: constraint of the second sec | | | | | | 10 | | SYSTEM | (\$7,593.60) | |
| Visit Visit <th< td=""><td></td><td></td><td></td><td></td><td></td><td>11</td><td></td><td>SYSTEM</td><td>\$7,593.60</td><td>This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.</td></th<> | | | | | | 11 | | SYSTEM | \$7,593.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| Visite Visite< | | | | | | 11 | | SYSTEM | (\$7,593.60) | |
| 0920 - Total State | | | | | - Total | | | | \$0.00 | |
| 0930 PCLE FOUND.PCOINT (45 FT CN 13.5 M Material FGUND.PCOINT (3.5 M Material FGUND.PCOINT (45 FT CN 13.5 M Material FGUND.PCOINT (45 FT CN 13.5 M Material FGUND.PCOINT FGUND.PCOINT (45 FT CN 13.5 M Material FGUND.PCOINT FGUND.PCO | | | | Material - To | erial - Total | | | | | |
| FOUNDATION (45 FT, 0) 13.5 M | | 0920 - | Total | | | | | | \$0.00 | |
| is adjustment offsets the original system-generated Material Payment Sign 2, 2021 Suffset | | 0930 | FOUNDATION (45 FT. OR | Material | | 6 | | SYSTEM | \$2,488.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| Image: constraint of the | | | | | | 6 | | SYSTEM | (\$2,488.26) | |
| Image: constraint of the | | | | | | 7 | | SYSTEM | \$2,488.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| Visite Visite< | | | | | | 7 | | SYSTEM | (\$2,488.26) | |
| 1220 - Total 2021 · V SYSTEM \$2,488.26 This adjustment offsets the original system-generated Material Payment Estimate. 9 Aug 16, 2021 · SYSTEM \$2,488.26 This adjustment offsets the original system-generated Material Payment Estimate. 9 Aug 16, 2021 · SYSTEM \$2,488.26 Filterial - Total \$0.00 • • • • • • • • • • • • • • • • • • • | | | | | | 8 | | SYSTEM | \$2,488.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| 0930 - Total 0 Aug 16, 2021 SYSTEM (\$2,488.26) 0930 - Total 0 Naterial - Total \$0.00 0930 - Total \$0.00 \$0.00 1220 CLASS B-1, CORETE (CULVERTS-BRIDGE) Material 10 Sep 2, 2021 SYSTEM \$3,306.12 This adjustment offsets the original system-generated Material Payment Estimate 1220 CLASS B-1, CULVERTS-BRIDGE) 10 Sep 2, 2021 SYSTEM \$3,306.12 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 10 Sep 2, 2021 SYSTEM \$3,306.12 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 11 Sep 16, SYSTEM \$3,306.12 This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate. 11 Sep 16, SYSTEM \$3,306.12 This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate. 1220 - Total 50.00 Total \$0.00 1220 - Total \$0.00 \$13,001.82 | | | | | | 8 | | SYSTEM | (\$2,488.26) | |
| Image: Constraint of the second sec | | | | | | 9 | | SYSTEM | \$2,488.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| Material - Total Source Sou | | | | | | 9 | | SYSTEM | (\$2,488.26) | |
| 0930 - Total \$0.00 1220 CLASS B-1 CONCRETE (CULVERTS- BRIDGE) Material 10 Sep 2, 2021 SYSTEM \$3,306.12 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Item A | | | | | - Total | | | | \$0.00 | |
| 1220 CLASS B-1 CONCRETE (CULVERTS- BRIDGE) Material 10 Sep 2, 2021 SYSTEM \$3,306.12 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers 1 overridding Payment Estimate Exception 8 on the current Payment Estimate. 10 Sep 2, 2021 SYSTEM (\$3,306.12) This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 11 Sep 16, 2021 SYSTEM \$(\$3,306.12) This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate. 11 Sep 16, 2021 SYSTEM \$(\$3,306.12) This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate. 11 Sep 16, 2021 SYSTEM \$(\$3,306.12) This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate. 120 - Total - Total Sep 16, 2021 SYSTEM \$(\$3,306.12) 121 Sep 16, 2021 SYSTEM \$(\$3,306.12) Stimate Item Adjustment (0012) due to user webers 1 overridding Payment Estimate Exception 9 on the current Payment Estimate. 1220 - Total - Total \$0.00 Stimate Item Adjustment (0 | | | | Material - To | otal | | | | \$0.00 | |
| Image: CONCRETE (CULVERTS-BRIDGE) Image: Concrete (CULVERTS-BRIDGE)< | | 0930 - | Total | | | | | | \$0.00 | |
| Image: Provide the state of the st | | 1220 | CONCRETE (CULVERTS- | Material | | 10 | | SYSTEM | \$3,306.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| Image: Second | | | BRIDGE) | | | 10 | | SYSTEM | (\$3,306.12) | |
| Image: Problem in the state in the | | | | | | 11 | | SYSTEM | \$3,306.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| Material - Total \$0.00 1220 - Total \$0.00 J5P3195 - Total \$13,001.82 | | | | | | 11 | | SYSTEM | (\$3,306.12) | |
| 1220 - Total \$0.00 J5P3195 - Total \$13,001.82 | | | | | - Total | | | | \$0.00 | |
| J5P3195 - Total \$13,001.82 | | | | Material - To | otal | | | | \$0.00 | |
| | | 1220 - | Total | | | | | | \$0.00 | |
| Ouerell Total 842.004.00 | J5P3195 | - Total | | | | | | | \$13,001.82 | |
| Overall - Total \$13,001.82 | Overall - | Total | | | | | | | \$13,001.82 | |