

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2021

June 21, 2021

June 21, 2021

| Progress Es | timate Number 4 | Contract ID Prime Contractor | 210319-C02 Emery Sapp & So | ons, Inc. | Pay Period Sta Pay Period En | | t 2, 2021 t 15, 2021 | Net Change | ntract Amount Order Amount ntract Amount | \$2,376,874.20 \$0.00 \$2,376,874.20 | |
|---------------------------|--------------------------------|-------------------------------|--|---|---------------------------------|------------|-------------------------------|--------------|--|--|--|
| Approval Date | • | | | | | | | | | By User | |
| August 17, 2021 | | | Generated and Approved (and should be considered Draft) at the Project Office Level by | | | | | | | marshp3 | |
| August 17, 2021 | | | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | | | | | | | sandis1 | |
| August 18, 2021 | | | | Reviewed and Approved at the Central Office Controllers Office Level by | | | | | | | |
| Original Co | mpletion Date | Current Cor | ppletion Date Actual Completion Date % of Current Contract Amou | | | | | | | unt Complete | |
| Decemb | per 1, 2021 | Decemb | er 1, 2021 | | | | | | 28.60% | | |
| Cont | ract Informationa | I Dates | | | | Mile | estones | | | | |
| Date Description | Original Completion Date | Current Completion Date | | | | | Days Remainir on Milestone | , | | | |
| Acceptance Date | · | | Milestone - Completion Da Completion Date, J4I3436 | | te, JSP B - | June 6, 20 |)21 Ju | ine 28, 2021 | | -51 | |
| Awarded Date | April 7, 2021 | April 7, 2021 | | | | | | | | | |
| Letting Date | March 19, 2021 | March 19, 2021 | | | | | | | | | |
| Notice to Proceed Date | April 22, 2021 | April 22, 2021 | | | | | | | | | |

| Contract Total Pa | y For Estimate No. 4 | | | | |
|-------------------|--|--|---|---|--|
| | | This Estimate | Previous | To Date | |
| 210319-C02 | Total Posted Items Pay Gross Item Adjustments Incentive Disincentive Liquidated Damage Other Contract Adjustments | \$95,032.96 (\$13,756.60) \$0.00 \$0.00 \$0.00 \$0.00 | \$584,713.87 (\$21,948.40) \$0.00 \$0.00 \$0.00 \$0.00 | \$679,746.83 (\$35,705.00) \$0.00 \$0.00 \$0.00 | |
| Contract Total Pa | yable This Estimate: | \$81,276.36 | \$562,765.47 | \$644,041.83 | |

Items Paid This Estimate Period

Work Began

Date

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|---|------|------------|--------------------------|-----------------------------|
| J4S3386 | 0230 | 2063000 | CLASS 3 EXCAVATION | CUYD | \$100.000 | 305 | \$30,500.00 |
| | 0380 | 6122030 | IMPACT ATTENUATOR (RELOCATION) | EA | \$800.000 | 1 | \$800.00 |
| | 0400 | 6161005 | CONSTRUCTION SIGNS | SQFT | \$6.500 | 32 | \$208.0 |
| | 0510 | 6175010A | RELOCATING TEMPORARY TRAFFIC BARRIER | LF | \$8.000 | 287.5 | \$2,300.0 |
| | 0590 | 6207001 | PAVEMENT MARKING REMOVAL | LF | \$0.480 | 2,034 | \$976.3 |
| | 0600 | 6208076 | 4 IN TEMPORARY PAVEMENT MARKING PAINT | LF | \$0.500 | 2,921 | \$1,460.5 |
| | 0640 | 7250330A | 30 IN. PIPE GROUP B | LF | \$100.000 | 119 | \$11,900.0 |
| | 0960 | 7021212 | GALVANIZED STRUCTURAL STEEL PILES (12 IN) | LF | \$75.000 | 372 | \$27,900.0 |
| | 0970 | 7027000 | PILE POINT REINFORCEMENT | EA | \$110.000 | 12 | \$1,320.0 |
| | 0980 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | CUYD | \$850.000 | 17.3 | \$14,705.0 |
| | 1050 | 7101000 | REINFORCING STEEL (EPOXY COATED) | LB | \$1.550 | 1,911.7 | \$2,963.1 |
| Project J4S338 | 6 - Total | | | | | | \$95,032.9 |
| Overall - Total | | | | | | | \$95,032.9 |

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2021

Progress Estimate Number
4

Contract ID 210319-C02 Pay Period Start August 2, 2021 Original Contract Amount Prime Contractor Emery Sapp & Sons, Inc.

Pay Period Start August 2, 2021 Original Contract Amount Net Change Order Amount Current Contract Amount \$2,376,874.20

| | | | | | Curre | nt Contract | Amount \$ | 2,376,874.20 |
|-------------------|-------------|--|--------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J4I3436 | 0040 | MISC. | Material | | | -193.3 | \$150.00 | (\$28,995.00 |
| | 0040 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 193.3 | \$150.00 | \$28,995.00 |
| | 0050 | PIPE AGGREGATE PAVEMENT EDGE DRAIN | MaterialCredit | | | 15 | \$50.00 | \$750.00 |
| | 0050 | PIPE AGGREGATE PAVEMENT EDGE DRAIN | Material | | | -15 | \$50.00 | (\$750.00 |
| | 0060 | OUTLET PIPES AND SPLASH PADS | MaterialCredit | | | 1 | \$2,500.00 | \$2,500.00 |
| | 0060 | OUTLET PIPES AND SPLASH PADS | Material | | | -1 | \$2,500.00 | (\$2,500.00 |
| | 0160 | GUARDRAIL TYPE A | MaterialCredit | | | 38 | \$21.75 | \$826.50 |
| | 0160 | GUARDRAIL TYPE A | Material | | | -38 | \$21.75 | (\$826.50 |
| | 0160 | GUARDRAIL TYPE A | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user marshp3 overridding Payment Estimate Exception 9 on the current Payment Estimate. | 38 | \$21.75 | \$826.50 |
| J4S3386 | 0390 | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | MaterialCredit | | | 2 | \$1,000.00 | \$2,000.00 |
| | 0390 | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | Material | | | -2 | \$1,000.00 | (\$2,000.00 |
| | 0500 | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED | MaterialCredit | | | 700 | \$22.50 | \$15,750.00 |
| | 0500 | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED | Material | | | -700 | \$22.50 | (\$15,750.00 |
| | 0710 | SILT FENCE | MaterialCredit | | | 53 | \$2.30 | \$121.90 |
| | 0710 | SILT FENCE | Material | | | -53 | \$2.30 | (\$121.90 |
| | 0710 | SILT FENCE | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 25 on the current Payment Estimate. | 53 | \$2.30 | \$121.90 |
| | 0960 | GALVANIZED STRUCTURAL STEEL PILES (12 IN) | Material | | | -372 | \$75.00 | (\$27,900.00 |
| | 0960 | GALVANIZED STRUCTURAL STEEL PILES (12 IN) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user marshp3 overridding Payment Estimate Exception 12 on the current Payment Estimate. | 372 | \$75.00 | \$27,900.00 |
| | 0970 | PILE POINT REINFORCEMENT | Material | | | -12 | \$110.00 | (\$1,320.00 |
| | 0970 | PILE POINT REINFORCEMENT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user marshp3 overridding Payment Estimate Exception 13 on the current Payment Estimate. | 12 | \$110.00 | \$1,320.00 |
| | 0980 | CLASS B CONCRETE (SUBSTRUCTURE) | Material | | | -17.3 | \$850.00 | (\$14,705.00 |
| | 1050 | REINFORCING STEEL (EPOXY COATED) | Material | | | -1,911.7 | \$1.55 | (\$2,963.14 |

Revision 4/1/2020 Page 2 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2021

| Progress Estimate Number | Contract ID Prime Contractor | 210319-C02 Emery Sapp & Sons, Inc. | • | , | Original Contract Amount Net Change Order Amount | . , , |
|--------------------------|------------------------------|---------------------------------------|-----------------|---|---|-------|
| 4 | T Time Contractor | Emory cupp a cone, me. | . uy i onou zna | | Current Contract Amount | |

| | | | | | | Curre | ent Contract | Amount \$ | 2,376,874.20 |
|-------------------|-------------|---------------------|---------------------------------|--------------------|----------------------------------|--|------------------------|---------------------------------------|-------------------|
| Project Number | Line No. | Item Descrip | otion | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J4S3386 | 1050 | REINFORCI (EPOXY | NG STEEL 'COATED) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user marshp3 overridding Payment Estimate Exception 19 on the current Payment Estimate. | 1,911.7 | \$1.55 | \$2,963.14 |
| | 1120 | STABILIZED EA | ANICALLY RTH WALL SYSTEMS | Material | | | -1,620 | \$65.45 | (\$106,029.00) |
| | 1120 | STABILIZED EA | ANICALLY RTH WALL SYSTEMS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user marshp3 overridding Payment Estimate Exception 21 on the current Payment Estimate. | 1,620 | \$65.45 | \$106,029.00 |
| | 1150 | STABILIZED EA | ANICALLY RTH WALL SYSTEMS | Material | | | -1,589.4 | \$65.45 | (\$104,026.23) |
| | 1150 | STABILIZED EA | ANICALLY RTH WALL SYSTEMS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user marshp3 overridding Payment Estimate Exception 23 on the current Payment Estimate. | 1,589.4 | \$65.45 | \$104,026.23 |
| Total | | | | | | | | | (\$13,756.60) |

Revision 4/1/2020 Page 3 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | C | ontract Project Information | on | | | | |
|-------------------|---|------------------------------------|-----------------|--------|--|---|--|--|--|--|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work | | | | |
| J4I3436 | I 435-1(332) | Drainage and pavement improvements | I-435 | CLAY | from Rte. 69 to 48th Stree | et | | | | | |
| J4S3386 | 386 FAS Bridge replacement Ter CL Sty Job Numbers | | | | over I-435, 0.8 miles sout | er I-435, 0.8 miles south of Rte. 69 and 0.7 miles north of 48th Street | | | | | |
| otals by | Job Numbers | \$ | | | | | | | | | |
| J4I3436 | | Item Pay tem Adjustment | ts Gross Ite | em Pay | This Estimate \$0.00 \$826.50 \$826.50 | Previous \$74,821.50 (\$4,076.50) \$70,745.00 | To Date \$74,821.50 (\$3,250.00) \$71,571.50 | | | | |
| | | | nents | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | | | | |
| J4S3386 | | Item Pay tem Adjustment | ts Gross Ite | em Pay | This Estimate \$95,032.96 (\$14,583.10) \$80,449.86 | Previous \$509,892.37 (\$17,871.90) \$492,020.47 | To Date \$604,925.33 (\$32,455.00) \$572,470.33 | | | | |
| | | | nents | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | | | | |

Revision 4/1/2020 Page 4 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period | | | |
|---|-----------------------------------|---------------|------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project J4I3436, Item 5029905, Project Item Line Number 0040, Material Set 502990596, Material 100510OPTLD1 - PCCP 1" Max LS/DO, Acceptance Action Generic 100510OPTLD1 is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4l3436, Item 5029905, Project Item Line Number 0040, Material Set 502990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4l3436, Item 6053030A, Project Item Line Number 0050, Material Set 6053030A96, Material 1009G5DRLS - Agg for Drainage Gr5 Limestone, Acceptance Action Generic 1009G5DRLS is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4l3436, Item 6053030A, Project Item Line Number 0050, Material Set 6053030A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4l3436, Item 6054020, Project Item Line Number 0060, Material Set 605402096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4I3436, Item 6054020, Project Item Line Number 0060, Material Set 605402096, Material 1013DMPVSC4.04 - Underdrain Sch40 PVC 4" (102mm), Acceptance Action Generic 1013DMPVSC4.04 is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4I3436, Item 6054020, Project Item Line Number 0060, Material Set 605402096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4l3436, Item 6054020, Project Item Line Number 0060, Material Set 605402096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4l3436, Item 6061010, Project Item Line Number 0160, Material Set 606101096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 6123000A, Project Item Line Number 0390, Material Set 6123000A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 6173600D, Project Item Line Number 0500, Material Set 6173600D96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7021212, Project Item Line Number 0960, Material Set 702121296, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7027000, Project Item Line Number 0970, Material Set 702700096, Material 0702PLPT - Pile Point Reinforcement, Acceptance Action Generic 0702PLPT is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7032003, Project Item Line Number 0980, Material Set 703200396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7032003, Project Item Line Number 0980, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7032003, Project Item Line Number 0980, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7032003, Project Item Line Number 0980, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. | No Remark was entered by Engineer | marshp3 | Unresolved |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7101000, Project Item Line Number 1050, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7101000, Project Item Line Number 1050, Material Set 710100096, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7101000, Project Item Line Number 1050, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7201000, Project Item Line Number 1120, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7201000, Project Item Line Number 1120, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7201000, Project Item Line Number 1150, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7201000, Project Item Line Number 1150, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, | No Remark was entered by Engineer | marshp3 | Overridden |

Revision 4/1/2020 Page 5 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Bicorepandice) This Estimate Forest | | | |
|--|-----------------------------------|---------------|------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Acceptance Action Generic 1010SGBF is insufficient. | | | |
| Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 8061019, Project Item Line Number 0710, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient. | No Remark was entered by Engineer | marshp3 | Overridden |

Revision 4/1/2020 Page 6 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | and Valu Category | | Item Code | eport Generated date and can differ from the posted amo Description | Bid Quantity | Net Change Order | Total Current Quantity | as Gene Unit | Total Posted Approved | Unit Price | Total Value POSTE To Date (See report generated date) |
|----------------------|----------------|----------------------|-----------|--------------|---|-----------------|------------------------|------------------------|-----------------|-----------------------------|-------------|---|
| 10319-C02 | J4I3436 | 0001 | 0010 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | Qty 1.00 | \$7,500.00 | \$7,500.0 |
| | | 0001 | 0020 | 3030600 | FURNISHING ROCK BASE MATERIAL | 193.00 | 0.00 | 193.00 | SQYD | 193.00 | \$40.00 | \$7,720.0 |
| | | 0001 | 0030 | 3030610A | PLACING ROCK BASE | 193.00 | 0.00 | 193.00 | SQYD | 193.00 | \$30.00 | \$5,790.0 |
| | | 0001 | 0040 | 5029905 | MISC.CONCRETE PAVEMENT (16 IN, NON-REINFORCED, 15 FT JOINTS) | 193.30 | 0.00 | 193.30 | SQYD | 193.30 | \$150.00 | \$28,995.0 |
| | | 0001 | 0050 | 6053030A | PIPE AGGREGATE PAVEMENT EDGE DRAIN | 15.00 | 0.00 | 15.00 | LF | 15.00 | \$50.00 | \$750.0 |
| | | 0001 | 0060 | 6054020 | OUTLET PIPES AND SPLASH PADS | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$2,500.00 | \$2,500.0 |
| | | 0001 | 0070 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$5,000.00 | \$5,000.0 |
| | | 0001 | 0080 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 38.00 | 0.00 | 38.00 | LF | 0.00 | \$2.00 | \$0.0 |
| | | 0001 | 0090 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 75.00 | 0.00 | 75.00 | LF | 0.00 | \$2.00 | \$0.0 |
| | | 0001 | 0100 | 6240104A | SEPARATION GEOTEXTILE | 253.00 | 0.00 | 253.00 | SQYD | 253.00 | \$5.00 | \$1,265. |
| | | 0001 | 0110 | 6262000A | PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP | 0.90 | 0.00 | 0.90 | STA | 0.90 | \$12,000.00 | \$10,800. |
| | | 0001 | 0120 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$2,925.00 | \$2,925. |
| | | 0001 | 0130 | 8061006 | ALTERNATE DITCH CHECK | 40.00 | 0.00 | 40.00 | LF | 30.00 | \$25.00 | \$750. |
| | | 0001 | 0140 | 8061016 | SEDIMENT REMOVAL | 9.00 | 0.00 | 9.00 | CUYD | 0.00 | \$35.00 | \$0. |
| | | 0001 | 0150 | 8061019 | SILT FENCE | 43.00 | 0.00 | 43.00 | LF | 0.00 | \$6.50 | \$0. |
| | | 0010 | 0160 | 6061010 | GUARDRAIL TYPE A | 38.00 | 0.00 | 38.00 | LF | 38.00 | \$21.75 | \$826. |
| | | 0040 | 0170 | 9039902 | MISC.RELOCATION OF EXISTING SIGN ASSEMBLIES | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,100.00 | \$0. |
| | Project J | 4l3436 - To | tal Value | Posted to Da | ate as of Report Generated Date | | | | | | | \$74,821. |
| | J4S3386 | 0001 | 0180 | 2013000 | CLEARING AND GRUBBING | 1.00 | 0.00 | 1.00 | ACRE | 0.00 | \$10,000.00 | \$0 |
| | | 0001 | 0190 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 0.20 | \$34,000.00 | \$6,800 |
| | | 0001 | 0200 | 2031000 | CLASS A EXCAVATION | 1,787.00 | 0.00 | 1,787.00 | CUYD | 0.00 | \$20.00 | \$0 |
| | | 0001 | 0210 | 2035500 | EMBANKMENT IN PLACE | 2,250.00 | 0.00 | 2,250.00 | CUYD | 0.00 | \$25.00 | \$0 |
| | | 0001 | 0220 | 2036000 | COMPACTING EMBANKMENT | 1,454.00 | 0.00 | 1,454.00 | CUYD | 0.00 | \$5.00 | \$0 |
| | | 0001 | 0230 | 2063000 | CLASS 3 EXCAVATION | 305.00 | 0.00 | 305.00 | CUYD | 305.00 | \$100.00 | \$30,500 |
| | | 0001 | 0240 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 2,233.00 | 0.00 | 2,233.00 | SQYD | 0.00 | \$15.00 | \$0 |
| | | 0001 | 0250 | 4039905 | MISC.OPTIONAL PAVEMENT | 2,142.00 | 0.00 | 2,142.00 | SQYD | 0.00 | \$44.40 | \$0 |
| | | 0001 | 0260 | 6071012A | CHAIN-LINK FENCE (60 IN.) | 686.00 | 0.00 | 686.00 | LF | 0.00 | \$18.50 | \$0 |
| | | 0001 | 0270 | 6071050 | CHAIN-LINK FENCE (RETAINING WALLS) | 173.00 | 0.00 | 173.00 | LF | 0.00 | \$55.00 | \$0 |
| | | 0001 | 0280 | 6071102 | MODIFIED CONCRETE GUTTER TYPE B | 173.00 | 0.00 | 173.00 | LF | 0.00 | \$60.00 | \$0 |
| | | 0001 | 0290 | 6086004 | CONCRETE SIDEWALK, 4 IN. | 104.10 | 0.00 | 104.10 | SQYD | 0.00 | \$95.00 | \$0 |
| | | 0001 | 0300 | 6091051 | CURB AND GUTTER TYPE A | 252.00 | 0.00 | 252.00 | LF | 0.00 | \$65.00 | \$0 |
| | | 0001 | 0310 | 6096010A | FURNISHING TYPE 1 ROCK DITCH LINER | 4.00 | 0.00 | 4.00 | CUYD | 0.00 | \$55.00 | \$0 |
| | | 0001 | 0320 | 6096041 | PLACING TYPE 1 ROCK DITCH LINER | 4.00 | 0.00 | 4.00 | CUYD | 0.00 | \$175.00 | \$0 |
| | | 0001 | 0330 | 6097000 | ROCK LINING | 4.00 | 0.00 | 4.00 | CUYD | 0.00 | \$100.00 | \$0 |
| | | 0001 | 0340 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 24.00 | 0.00 | 24.00 | CUYD | 0.00 | \$50.00 | \$0 |
| | | 0001 | 0350 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 24.00 | 0.00 | 24.00 | CUYD | 0.00 | \$20.00 | \$0 |
| | | 0001 | 0360 | 6122017 | IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$2,000.00 | \$4,000 |
| | | 0001 | 0370 | 6122020 | REPLACEMENT SAND BARREL | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$300.00 | \$0 |
| | | 0001 | 0380 | 6122030 | IMPACT ATTENUATOR (RELOCATION) | 2.00 | 0.00 | 2.00 | EA | 1.00 | \$800.00 | \$800 |
| | | 0001 | 0390 | 6123000A | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | 3.00 | 0.00 | 3.00 | EA | 2.00 | \$1,000.00 | \$2,000 |
| | | 0001 | 0400 | 6161005 | CONSTRUCTION SIGNS | 996.00 | 0.00 | 996.00 | SQFT | 824.00 | \$6.50 | \$5,356 |
| | | 0001 | 0410 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$35.00 | \$0 |
| | | 0001 | 0420 | 6161009 | FLAG ASSEMBLY | 22.00 | 0.00 | 22.00 | EA | 0.00 | \$10.00 | \$0 |
| | | 0001 | 0430 | 6161025 | CHANNELIZER (TRIM LINE) | 154.00 | 0.00 | 154.00 | EA | 154.00 | \$30.00 | \$4,620 |
| | | 0001 | 0440 | 6161030 | TYPE III MOVEABLE BARRICADE | 35.00 | 0.00 | 35.00 | EA | 35.00 | \$150.00 | \$5,250 |
| | | CRRIT | UTTU | 0101030 | I I I L III WO Y LADLE DANNOADE | 33.00 | 0.00 | 35.00 | EA | 33.00 | φιου.υυ | |

Page 7 of 18 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Im.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTE To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|---|
| 10319-C02 | J4S3386 | 0001 | 0450 | 6161033 | DIRECTIONAL INDICATOR BARRICADE | 42.00 | 0.00 | 42.00 | EA | 28.00 | \$40.00 | \$1,120.0 |
| | | 0001 | 0460 | 6161040 | FLASHING ARROW PANEL | 3.00 | 0.00 | 3.00 | EA | 2.00 | \$900.00 | \$1,800.0 |
| | | 0001 | 0470 | 6161055 | SEQUENTIAL FLASHING WARNING LIGHT | 42.00 | 0.00 | 42.00 | EA | 28.00 | \$40.00 | \$1,120.0 |
| | | 0001 | 0480 | 6161099 | CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 31.00 | 0.00 | 31.00 | EA | 31.00 | \$2,000.00 | \$62,000.0 |
| | | 0001 | 0490 | 6162004 | TEMPORARY SHORT-TERM RUMBLE STRIPS | 10.00 | 0.00 | 10.00 | EA | 0.00 | \$1,600.00 | \$0.0 |
| | | 0001 | 0500 | 6173600D | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED | 700.00 | 0.00 | 700.00 | LF | 700.00 | \$22.50 | \$15,750.0 |
| | | 0001 | 0510 | 6175010A | RELOCATING TEMPORARY TRAFFIC BARRIER | 575.00 | 0.00 | 575.00 | LF | 287.50 | \$8.00 | \$2,300.0 |
| | | 0001 | 0520 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 0.25 | \$145,000.00 | \$36,250. |
| | | 0001 | 0530 | 6181020 | ADDITIONAL MOBILIZATION FOR SEEDING | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$600.00 | \$0. |
| | | 0001 | 0540 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 1,975.00 | 0.00 | 1,975.00 | LF | 0.00 | \$0.45 | \$0. |
| | | 0001 | 0550 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT | 1,275.00 | 0.00 | 1,275.00 | LF | 0.00 | \$0.45 | \$0. |
| | | 0001 | 0560 | 6206000C | MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING | 918.00 | 0.00 | 918.00 | LF | 0.00 | \$0.45 | \$0. |
| | | 0001 | 0570 | 6206001C | PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT | 1,466.00 | 0.00 | 1,466.00 | LF | 0.00 | \$0.45 | \$0.0 |
| | | 0001 | 0580 | 6206124A | MARKING PAINT, TYPE P BEADS 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING | 40.00 | 0.00 | 40.00 | LF | 0.00 | \$3.00 | \$0. |
| | | | 0590 | 6207001 | PAINT, TYPE P BEADS PAVEMENT MARKING REMOVAL | 11,005.00 | 0.00 | 11,005.00 | LF | 3,372.00 | \$0.48 | \$1,618. |
| | | 0001 | 0600 | 6208076 | 4 IN TEMPORARY PAVEMENT MARKING PAINT | | 0.00 | 7,755.00 | LF | 6,851.00 | \$0.48 | |
| | | 0001 | | | | 7,755.00 | | | | | | \$3,425. |
| | | 0001 | 0610 | 6214600A | FLOWABLE BACKFILL | 7.00 | 0.00 | 7.00 | CUYD | 0.00 | \$300.00 | \$0 |
| | | 0001 | 0620 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 64.00 | 0.00 | 64.00 | SQYD | 0.00 | \$5.00 | \$0 |
| | | 0001 | 0630 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$10,000.00 | \$0 |
| | | 0001 | 0640 | 7250330A | 30 IN. PIPE GROUP B | 119.00 | 0.00 | 119.00 | LF | 119.00 | \$100.00 | \$11,900 |
| | | 0001 | 0650 | 7320030A | 30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$2,000.00 | \$0 |
| | | 0001 | 0660 | 8051000A | SEEDING - COOL SEASON MIXTURES | 1.10 | 0.00 | 1.10 | ACRE | 0.00 | \$5,000.00 | \$0 |
| | | 0001 | 0670 | 8061005 | ROCK DITCH CHECK | 60.00 | 0.00 | 60.00 | LF | 50.00 | \$15.00 | \$750 |
| | | 0001 | 0680 | 8061006 | ALTERNATE DITCH CHECK | 600.00 | 0.00 | 600.00 | LF | 0.00 | \$10.50 | \$0 |
| | | 0001 | 0690 | 8061016 | SEDIMENT REMOVAL | 47.00 | 0.00 | 47.00 | CUYD | 0.00 | \$35.00 | \$0 |
| | | 0001 | 0700 | 8061017 | TEMPORARY SEEDING AND MULCHING | 1.10 | 0.00 | 1.10 | ACRE | 0.00 | \$3,000.00 | \$0 |
| | | 0001 | 0710 | 8061019 | SILT FENCE | 1,095.00 | 0.00 | 1,095.00 | LF | 53.00 | \$2.30 | \$121 |
| | | 0010 | 0720 | 6061010 | GUARDRAIL TYPE A | 188.00 | 0.00 | 188.00 | LF | 0.00 | \$21.50 | \$0 |
| | | 0010 | 0730 | 6061060 | MGS GUARDRAIL | 350.00 | 0.00 | 350.00 | LF | 0.00 | \$22.50 | \$0 |
| | | 0010 | 0740 | 6061061 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING | 400.00 | 0.00 | 400.00 | LF | 0.00 | \$25.50 | \$0 |
| | | 0010 | 0750 | 6062204A | BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (NEW CONSTRUCTION ONLY) | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$1,850.00 | \$0 |
| | | 0010 | 0760 | 6062303 | ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$500.00 | \$0 |
| | | 0010 | 0770 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$2,650.00 | \$0 |
| | | 0010 | 0780 | 6063015 | TYPE A CRASHWORTHY END TERMINAL | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$2,650.00 | \$0 |
| | | 0010 | 0790 | 6063016 | TYPE B CRASHWORTHY END TERMINAL | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$4,250.00 | \$0 |
| | | 0010 | 0800 | 6069901 | MISC.REMOVAL AND REINSTALL GUARD CABLE | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$13,000.00 | \$13,000 |
| | | 0040 | 0810 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | 1.90 | 0.00 | 1.90 | CUYD | 0.00 | \$1,050.00 | \$0 |
| | | 0040 | 0820 | 9031210 | STRUCTURAL STEEL POSTS | 600.00 | 0.00 | 600.00 | LB | 0.00 | \$4.50 | \$0 |
| | | 0040 | 0830 | 9031270A | 2 IN. PSST POST - 12 GA. | 63.00 | 0.00 | 63.00 | LF | 0.00 | \$13.00 | \$0 |
| | | 0040 | 0840 | 9031273 | POST ANCHOR FOR 2 IN. PSST - 7 GA. | 18.00 | 0.00 | 18.00 | LF | 0.00 | \$47.50 | \$0 |
| | | 0040 | 0850 | 9031280 | 2.5 IN. PSST POST - 12 GA. | 38.00 | 0.00 | 38.00 | LF | 0.00 | \$14.00 | \$0 |
| | | 0040 | 0860 | 9031281 | POST ANCHOR FOR 2.5 IN. PSST - 7 GA. | 9.00 | 0.00 | 9.00 | LF | 0.00 | \$50.50 | \$0 |
| | | 0070 | 0870 | 2024043 | REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) | 22.00 | 0.00 | 22.00 | SQFT | 22.00 | \$250.00 | \$5,500 |
| | | 20.0 | | | , | | | | | | | 7 -,-00 |

Page 8 of 18 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract .CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-----------------------|----------------|-------------|-------------|---------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 319-C02 | J4S3386 | 0070 | 0890 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 169.00 | 0.00 | 169.00 | SQYD | 0.00 | \$250.00 | \$0.00 |
| | | 0070 | 0900 | 6079903 | MISC.48 IN. ORNAMENTAL PEDESTRIAN FENCE | 372.00 | 0.00 | 372.00 | LF | 0.00 | \$160.00 | \$0.00 |
| | | 0070 | 0910 | 7011106 | DRILLED SHAFTS (4 FT. 0 IN. DIA.) | 28.00 | 0.00 | 28.00 | LF | 0.00 | \$1,200.00 | \$0.00 |
| | | 0070 | 0920 | 7011205 | ROCK SOCKETS (3 FT 6 IN. DIA.) | 45.00 | 0.00 | 45.00 | LF | 0.00 | \$350.00 | \$0.00 |
| | | 0070 | 0930 | 7011300 | VIDEO CAMERA INSPECTION | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$600.00 | \$0.00 |
| | | 0070 | 0940 | 7011400 | FOUNDATION INSPECTION HOLES | 65.00 | 0.00 | 65.00 | LF | 0.00 | \$150.00 | \$0.00 |
| | | 0070 | 0950 | 7011600 | SONIC LOGGING TESTING | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$3,500.00 | \$0.00 |
| | | 0070 | 0960 | 7021212 | GALVANIZED STRUCTURAL STEEL PILES (12 IN) | 372.00 | 0.00 | 372.00 | LF | 372.00 | \$75.00 | \$27,900.00 |
| | | 0070 | 0970 | 7027000 | PILE POINT REINFORCEMENT | 12.00 | 0.00 | 12.00 | EA | 12.00 | \$110.00 | \$1,320.00 |
| | | 0070 | 0980 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 83.10 | 0.00 | 83.10 | CUYD | 17.30 | \$850.00 | \$14,705.00 |
| | | 0070 | 0990 | 7034219A | TYPE D BARRIER | 403.00 | 0.00 | 403.00 | LF | 0.00 | \$185.00 | \$0.00 |
| | | 0070 | 1000 | 7034222 | SLAB ON CONCRETE BEAM | 848.00 | 0.00 | 848.00 | SQYD | 0.00 | \$400.00 | \$0.00 |
| | | 0070 | 1010 | 7034430 | SIDEWALK (BRIDGES) | 1,391.00 | 0.00 | 1,391.00 | SQFT | 0.00 | \$15.00 | \$0.00 |
| | | 0070 | 1020 | 7034620 | FORM LINERS | 118.00 | 0.00 | 118.00 | SQYD | 0.00 | \$40.00 | \$0.00 |
| | | 0070 | 1030 | 7056051A | 33 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM | 1,105.00 | 0.00 | 1,105.00 | LF | 0.00 | \$350.00 | \$0.00 |
| | | 0070 | 1040 | 7071000 | CONDUIT SYSTEM ON STRUCTURE | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$10,000.00 | \$0.00 |
| | | 0070 | 1050 | 7101000 | REINFORCING STEEL (EPOXY COATED) | 18,160.00 | 0.00 | 18,160.00 | LB | 1,911.70 | \$1.55 | \$2,963.14 |
| | | 0070 | 1060 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$1,750.00 | \$0.00 |
| | | 0070 | 1070 | 7161000 | PLAIN NEOPRENE BEARING PAD | 12.00 | 0.00 | 12.00 | EA | 0.00 | \$250.00 | \$0.00 |
| | | 0070 | 1080 | 7161003 | LAMINATED NEOPRENE BEARING PAD (TAPERED) | 12.00 | 0.00 | 12.00 | EA | 0.00 | \$350.00 | \$0.00 |
| | | 0070 | 1090 | 7201300 | PIPE PILE SPACERS | 12.00 | 0.00 | 12.00 | EA | 12.00 | \$1,000.00 | \$12,000.00 |
| | | 0071 | 1100 | 7110300 | CONCRETE AND MASONRY PROTECTION SYSTEM | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$1,656.00 | \$0.00 |
| | | 0071 | 1110 | 7110400 | SACRIFICIAL GRAFFITI PROTECTION SYSTEM | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$1,656.00 | \$0.00 |
| | | 0071 | 1120 | 7201000 | MECHANICALLY STABILIZED EARTH WALL SYSTEMS | 1,800.00 | 0.00 | 1,800.00 | SQFT | 1,620.00 | \$65.45 | \$106,029.00 |
| | | 0072 | 1130 | 7110300 | CONCRETE AND MASONRY PROTECTION SYSTEM | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$1,656.00 | \$0.00 |
| | | 0072 | 1140 | 7110400 | SACRIFICIAL GRAFFITI PROTECTION SYSTEM | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$1,656.00 | \$0.00 |
| | | 0072 | 1150 | 7201000 | MECHANICALLY STABILIZED EARTH WALL SYSTEMS | 1,766.00 | 0.00 | 1,766.00 | SQFT | 1,589.40 | \$65.45 | \$104,026.23 |
| | Project J | 4S3386 - To | tal Value | Posted to D | ate as of Report Generated Date | | | | | | | \$604,925.32 |
| 319-C02 Ove | erall - Total | Value Post | ted to Dat | te as of Repo | ort Generated Date | | | | | | | \$679,746.82 |

Revision 4/1/2020 Page 9 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3386

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|--|---------------------------------|---------------------|-------------------------------|---------------------|---|
| 0230 | 2063000 | CLASS 3 EXCAVATION | 8/12/21 | 8/16/21 | 305.00 | CUYD | STA 562+10 LT/RT - RANDOLPH RD | | | | | STA 562+10 LT/RT - RANDOLPH RD |
| 0380 | 6122030 | IMPACT ATTENUATOR (RELOCATION) | 8/2/21 | 8/9/21 | 1.00 | EA | SB I-435 - Phase 2/3 - Median Shoulder | | | | | Moved from SB I-435 - Outside Shoulder(previous phase) |
| 0400 | 6161005 | CONSTRUCTION SIGNS | 8/13/21 | 8/16/21 | 32.00 | SQFT | I-435 NB/SB Traffic Control | | | | | PHASE 2 SHIFT FROM PHASE 3/2 |
| 0510 | 6175010A | RELOCATING TEMPORARY TRAFFIC BARRIER | 8/2/21 | 8/9/21 | 287.50 | LF | SB I-435 Shoulder to Median Relocation | | | | | Phase 3/2 to Phase 2. |
| 0590 | 6207001 | PAVEMENT MARKING REMOVAL | 8/13/21 | 8/16/21 | 2,034.00 | LF | I-435 NB/SB Lane Shifts | | | | | PHASE 2 SHIFT FROM PHASE 3/2 |
| 0600 | 6208076 | 4 IN TEMPORARY PAVEMENT MARKING PAINT | 8/13/21 | 8/16/21 | 2,921.00 | LF | I-435 NB/SB Lane Shifts. | | | | | PHASE 2 SHIFT FROM PHASE 3/2 |
| 0640 | 7250330A | 30 IN. PIPE CULVERT GROUP B | 8/12/21 | 8/16/21 | 119.00 | LF | STA 562+10 LT/RT - RANDOLPH RD | | | | | STA 562+10 LT/RT - RANDOLPH RD |
| 0960 | 7021212 | GALVANIZED STRUCTURAL STEEL PILES (12 IN | 8/3/21 | 8/9/21 | 372.00 | LF | Piles #9-#14 - West Bent 211.0 Piles #9-#14 - Splice Cut Off Lengths 41.4 Pay Remainder to Plan Quantity 119.6 | | | | | Additional payment needed via CO for overrun and splices. |
| 0970 | 7027000 | PILE POINT REINFORCEMENT | 8/3/21 | 8/9/21 | 12.00 | EA | Piles #9-#14 - West Bent Piles #1-#6 - East Bent | | | | | Piles #9-#14 - West Bent Piles #1-#6 - East Bent |
| 0980 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 8/11/21 | 8/16/21 | 17.30 | CUYD | Bent 3 - sub pour | | | | | Beam seats down. |
| 1050 | 7101000 | REINFORCING STEEL (EPOXY COATED) | 8/11/21 | 8/16/21 | 1,911.70 | LB | Bent 3 - sub pour | | | | | Beam seats down. Estimated poundage by MDK. |

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 10 of 18



| SASSISTEM Control Co | Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | |
|--|---------|--------|-------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|--|---|--|--------|-------------|
| Total | J4I3436 | 0020 | ROCK BASE | Material | | 1 | | SYSTEM | (\$8,240.00) | | | | | | |
| Material Total 2 | | | MATERIAL | | | 2 | | SYSTEM | (\$7,720.00) | | | | | | |
| MaterialCodal 2 Jul 16, SYSTEM \$6,240.00 | | | | | - Total | | | | (\$15,960.00) | | | | | | |
| 3 | | | | Material - Tota | ı | | | | (\$15,960.00) | | | | | | |
| 102 | | | | MaterialCredit | | 2 | | SYSTEM | \$8,240.00 | | | | | | |
| Material Credit - Total | | | | | | 3 | | SYSTEM | \$7,720.00 | | | | | | |
| Overrun | | | | | - Total | | | | \$15,960.00 | | | | | | |
| 2021 | | | | MaterialCredit | - Total | | | | \$15,960.00 | | | | | | |
| Communication Communicatio | | | | Overrun | Overrun | 1 | | SYSTEM | \$520.00 | Estimate Item Adjustment (0011) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 206.000; | | | | | |
| Occurrence Occ | | | | | | 1 | | SYSTEM | (\$520.00) | | | | | | |
| | | | | | Overrun - T | otal | | | \$0.00 | | | | | | |
| PLACING ROCK Nemun Property | | | | Overrun - Tota | ıl | | | | \$0.00 | | | | | | |
| BASE | | 0020 - | Total | | | | | | \$0.00 | | | | | | |
| 2021 30.00 | | 0030 | | Overrun | Overrun | 1 | | SYSTEM | \$390.00 | Estimate Item Adjustment (0013) due to user caseyj overridding Payment | | | | | |
| Overrun - Total So.00 | | | | | | 1 | | SYSTEM | (\$390.00) | | | | | | |
| Material Total SySTEM | | | | | Overrun - T | otal | | | \$0.00 | | | | | | |
| Misc. Material 1 | | | | Overrun - Tota | ıl | | | | \$0.00 | | | | | | |
| 2021 2 Jul 16, SYSTEM (\$28,995.00) | | 0030 - | Total | | | | | | \$0.00 | | | | | | |
| 2021 3 Aug 2, 2021 202 | | 0040 | MISC. | Material | | 1 | | SYSTEM | (\$30,960.00) | | | | | | |
| 2021 Estimate Item Adjustment (0019) due to user marshp3 overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Item Item Item Item Item Item Item Ite | | | | | | | | SYSTEM | (\$28,995.00) | | | | | | |
| 2021 4 | | | | | | 3 | Aug 2, 2021 | SYSTEM | \$28,995.00 | Estimate Item Adjustment (0019) due to user marshp3 overridding Payment | | | | | |
| 2021 Estimate Item Adjustment (0013) due to user marshp3 overridding Payment | | | | | | 3 | Aug 2, 2021 | SYSTEM | (\$28,995.00) | | | | | | |
| Total (\$59,955.00) | | | | | | | | | | | | 4 | | SYSTEM | \$28,995.00 |
| Material - Total | | | | | | | | SYSTEM | (\$28,995.00) | | | | | | |
| MaterialCredit 2 | | | | | - Total | | | | (\$59,955.00) | | | | | | |
| 2021 3 Aug 2, 2021 SYSTEM \$28,995.00 -Total \$59,955.00 -Total \$59,955.00 -Total \$59,955.00 | | | | Material - Tota | l | | | | (\$59,955.00) | | | | | | |
| Degree Page | | | | MaterialCredit | | 2 | | SYSTEM | \$30,960.00 | | | | | | |
| MaterialCredit - Total Overrun Overun Overrun Overrun Overrun Overrun Overrun Overrun Overrun | | | | | | 3 | | SYSTEM | | | | | | | |
| Overrun Overrun 1 Jun 30, 2021 \$1,965.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 36 on the current Payment Estimate. Material Insufficiency Quantity 206.400; Overrun Quantity Balance 13.10. 1 Jun 30, 27STEM (\$1,965.00) | | | | | | | | | | | | | | | |
| 2021 Estimate Item Adjustment (0014) overridding Payment Estimate Exception 36 on the current Payment Estimate. Material Insufficiency Quantity 206.400; Overrun Quantity Balance 13.10. 1 Jun 30, 2YSTEM (\$1,965.00) Overrun - Total \$0.00 Overrun - Total \$0.00 Overrun - Total \$0.00 PIPE AGGREGATE Material 1 Jun 30, SYSTEM (\$1,000.00) | | | | MaterialCredit | | | | | \$59,955.00 | | | | | | |
| 2021 \$0.00 | | | | Overrun | Overrun | 1 | | SYSTEM | \$1,965.00 | Estimate Item Adjustment (0014) overridding Payment Estimate Exception 36 on the current Payment Estimate. Material Insufficiency Quantity 206.400; | | | | | |
| Overrun - Total \$0.00 0040 - Total \$0.00 0050 PIPE AGGREGATE Material 1 Jun 30, SYSTEM (\$1,000.00) | | | | | | 1 | | SYSTEM | (\$1,965.00) | | | | | | |
| 0040 - Total \$0.00 0050 PIPE AGGREGATE Material 1 Jun 30, SYSTEM (\$1,000.00) | | | | | Overrun - T | otal | | | \$0.00 | | | | | | |
| 0050 PIPE AGGREGATE Material 1 Jun 30, SYSTEM (\$1,000.00) | | | | Overrun - Tota | ıl | | | | \$0.00 | | | | | | |
| | | 0040 - | Total | | | | | | \$0.00 | | | | | | |
| | | 0050 | | Material | | 1 | | SYSTEM | (\$1,000.00) | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------------------|---|
| J4I3436 | 0050 | DRAIN | Material | ., | 2 | Jul 16, 2021 | SYSTEM | (\$750.00) | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | (\$750.00) | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | (\$750.00) | |
| | | | | - Total | | | | (\$3,250.00) | |
| | | | Material - Tota | | | | | (\$3,250.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$1,000.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$750.00 | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | \$750.00 | |
| | | | | - Total | | | | \$2,500.00 | |
| | | | MaterialCredit | - Total | | | | \$2,500.00 | |
| | | | Overrun | Overrun | 1 | Jun 30, 2021 | SYSTEM | \$250.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 37 on the current Payment Estimate. Material Insufficiency Quantity 20.000; Overrun Quantity Balance 5.00. |
| | | | | | 1 | Jun 30, 2021 | SYSTEM | (\$250.00) | |
| | | | | Overrun - Total | | | | \$0.00 | |
| | | | Overrun - Tota | | | | | \$0.00 | |
| | 0050 - | Total | | | | | | (\$750.00) | |
| | 0060 | OUTLET PIPES AND SPLASH PADS | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$2,500.00) | |
| | | | | | 2 | Jul 16, 2021 | SYSTEM | (\$2,500.00) | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | (\$2,500.00) | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | (\$2,500.00) | |
| | | | | - Total | | | | | |
| | | | Material - Tota | | | | | (\$10,000.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$2,500.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$2,500.00 | |
| | | | | - Total | 4 | Aug 16, 2021 | SYSTEM | \$2,500.00 \$7,500.00 | |
| | | | MaterialCredit | | | | | \$7,500.00 | |
| | 0060 | Total | | Total | | | | (\$2,500.00) | |
| | 0800 | 6 IN. WHITE HIGH BUILD | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$90.00) | |
| | | WATERBORNE PAINT | | | 2 | Jul 16, 2021 | SYSTEM | (\$76.00) | |
| | | | | - Total | | | | (\$166.00) | |
| | | | Material - Tota | | | | | (\$166.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$90.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$76.00 | |
| | | | | - Total | | | | \$166.00 | |
| | | | MaterialCredit | - Total | | | | \$166.00 | |
| | | | Overrun | Overrun | 1 | Jun 30, 2021 | SYSTEM | \$14.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) overridding Payment Estimate Exception 38 on the current Payment Estimate. Material Insufficiency Quantity 45.000; Overrun Quantity Balance 7.00. |
| | | | | | 1 | Jun 30, 2021 | SYSTEM | (\$14.00) | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|----------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J4I3436 | 0800 | 6 IN. WHITE HIGH BUILD | Overrun | Overrun - T | otal | | | \$0.00 | |
| | | WATERBORNE PAINT | Overrun - Tota | ı | | | | \$0.00 | |
| | 0080 - | · Total | | | | | | \$0.00 | |
| | 0090 | 6 IN. YELLOW HIGH BUILD | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$159.00) | |
| | | WATERBORNE PAINT | | | 2 | Jul 16, 2021 | SYSTEM | (\$150.00) | |
| | | | | - Total | | 2021 | | (\$309.00) | |
| | | | Material - Tota | | | | | (\$309.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$159.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$150.00 | |
| | | | | - Total | | | | \$309.00 | |
| | | | MaterialCredit | - Total | | | | \$309.00 | |
| | | | Overrun | Overrun | 1 | Jun 30, | SYSTEM | \$9.00 | This adjustment offsets the original system-generated Overrun Payment |
| | | | | | | 2021 | | ***** | Estimate Item Adjustment (0020) overridding Payment Estimate Exception 39 on the current Payment Estimate. Material Insufficiency Quantity 79.500; Overrun Quantity Balance 4.50. |
| | | | | | 1 | Jun 30, 2021 | SYSTEM | (\$9.00) | |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | ı | | | | \$0.00 | |
| | 0090 - | Total | | | | | | \$0.00 | |
| | 0100 | SEPARATION GEOTEXTILE | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$1,345.00) | |
| | | | | | 2 | Jul 16, 2021 | SYSTEM | (\$1,265.00) | |
| | | | | - Total | | | | (\$2,610.00) | |
| | | | Material - Tota | | | | | (\$2,610.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$1,345.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$1,265.00 | |
| | | | | - Total | | | | \$2,610.00 | |
| | | | MaterialCredit | - Total | | | | \$2,610.00 | |
| | | | Overrun | Overrun | 1 | Jun 30, 2021 | SYSTEM | \$80.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 269.000; Overrun Quantity Balance 16.00. |
| | | | | | 1 | Jun 30, 2021 | SYSTEM | (\$80.00) | |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | ı | | | | \$0.00 | |
| | 0100 - | · Total | | | | | | \$0.00 | |
| | 0130 | ALTERNATE DITCH CHECK | Material | | 3 | Aug 2, 2021 | SYSTEM | \$750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user marshp3 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | (\$750.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0130 - | | | | | | | \$0.00 | |
| | 0160 | GUARDRAIL TYPE A | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$826.50) | |
| | | | | | 2 | Jul 16, 2021 | SYSTEM | (\$826.50) | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | (\$826.50) | |
| | | | | | 4 | Aug 16, | SYSTEM | \$826.50 | This adjustment offsets the original system-generated Material Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|-----------|--------|--------------------------------------|---------------------------------|-----------------------------|----------------|------------------------|----------------|----------------------------|--|--|
| J4I3436 | 0160 | GUARDRAIL TYPE A | Material | | | 2021 | | | Estimate Item Adjustment (0019) due to user marshp3 overridding Payment Estimate Exception 9 on the current Payment Estimate. | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | (\$826.50) | | |
| | | | | - Total | | | | (\$2,479.50) | | |
| | | | Material - Total | | | | | (\$2,479.50) | | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$826.50 | | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$826.50 | | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | \$826.50 | | |
| | | | | - Total | | | | \$2,479.50 | | |
| | | | MaterialCredit | - Total | | | | \$2,479.50 | | |
| | 0160 - | · Total | | | | | | \$0.00 | | |
| J4I3436 - | | | | | | | | (\$3,250.00) | | |
| J4S3386 | 0360 | IMPACT ATTENUATOR 65 MPH (SAND | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$6,000.00) | | |
| | | BARREL ARRAY) | | Total | 2 | Jul 16, 2021 | SYSTEM | (\$4,000.00) | | |
| | | | Material Total | - Total | | | | (\$10,000.00) | | |
| | | | Material - Total | | 2 | lul 16 | CVCTEM | (\$10,000.00) | | |
| | | | MaterialCredit | | 3 | Jul 16, 2021 | SYSTEM | \$6,000.00 | | |
| | | | | | 3 | Aug 2, 2021 | STSTEW | \$4,000.00 | | |
| | | | | - Total | | | | \$10,000.00 | | |
| | | | MaterialCredit | - Total | | | | \$10,000.00 | | |
| | | | Overrun | Overrun | 1 | Jun 30, 2021 | SYSTEM | \$2,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00. | |
| | | | | | 1 | Jun 30, 2021 | SYSTEM | (\$2,000.00) | | |
| | | | | Overrun - T | otal | | | \$0.00 | | |
| | | | Overrun - Tota | ı | | | | \$0.00 | | |
| | 0360 - | Total | | | | | | \$0.00 | | |
| | 0390 | TRUCK OR TRAILER MOUNTED ATTEN | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$2,000.00) | | |
| | | (TMA) | | | 2 | Jul 16, 2021 | SYSTEM | (\$2,000.00) | | |
| | | | | | | 3 | Aug 2, 2021 | SYSTEM | (\$2,000.00) | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | (\$2,000.00) | | |
| | | | Material Total | - Total | | | | (\$8,000.00) | | |
| | | | Material - Total MaterialCredit | | 2 | Jul 16, | SYSTEM | (\$8,000.00) \$2,000.00 | | |
| | | | | | 3 | 2021 Aug 2, 2021 | SYSTEM | \$2,000.00 | | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | \$2,000.00 | | |
| | | | | - Total | | | | \$6,000.00 | | |
| | | | MaterialCredit | | | | | \$6,000.00 | | |
| | 0390 - | · Total | | | | | | (\$2,000.00) | | |
| | 0400 | CONSTRUCTION | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$5,148.00) | | |
| | | | | | 2 | Jul 16, 2021 | SYSTEM | (\$5,148.00) | | |
| | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-----------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J4S3386 | 0400 | CONSTRUCTION SIGNS | Material | - Total | | | | (\$10,296.00) | |
| | | Ololio | Material - Tota | | | | | (\$10,296.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$5,148.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$5,148.00 | |
| | | | | - Total | | | | \$10,296.00 | |
| | | | MaterialCredit | - Total | | | | \$10,296.00 | |
| | 0400 - | Total | | | | | | \$0.00 | |
| | 0430 | CHANNELIZER (TRIM LINE) | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$7,710.00) | |
| | | | | | 2 | Jul 16, 2021 | SYSTEM | (\$4,620.00) | |
| | | | | - Total | | | | (\$12,330.00) | |
| | | | Material - Tota | | | | | (\$12,330.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$7,710.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$4,620.00 | |
| | | | | - Total | | | | \$12,330.00 | |
| | | | MaterialCredit | | | | | \$12,330.00 | |
| | | | Overrun | Overrun | 1 | Jun 30, 2021 | SYSTEM | \$3,090.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 30 on the current Payment Estimate. Material Insufficiency Quantity 257.000; |
| | | | | | 1 | Jun 30, | SYSTEM | (\$3,090.00) | Overrun Quantity Balance 103.00. |
| | | | | | | 2021 | | | |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | <u> </u> | | | | \$0.00 | |
| | 0430 - | | | | | | | \$0.00 | |
| | 0440 | TYPE III MOVEABLE BARRICADE | Ε | | 1 | Jun 30, 2021 | SYSTEM | (\$6,000.00) | |
| | | | | | 2 | Jul 16, 2021 | SYSTEM | (\$5,250.00) | |
| | | | | - Total | | | | (\$11,250.00) | |
| | | | Material - Tota | | | | | (\$11,250.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$6,000.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$5,250.00 | |
| | | | | - Total | | | | \$11,250.00 | |
| | | | MaterialCredit | - Total | | | | \$11,250.00 | |
| | | | Overrun | Overrun | 1 | Jun 30, 2021 | SYSTEM | \$750.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 31 on the current Payment Estimate. Material Insufficiency Quantity 40.000; Overrun Quantity Balance 5.00. |
| | | | | | 1 | Jun 30, 2021 | SYSTEM | (\$750.00) | |
| | | | | Overrun - To | otal | | | \$0.00 | |
| | | | Overrun - Tota | | | | | \$0.00 | |
| | 0440 - | Total | | | | | | \$0.00 | |
| | 0450 | DIRECTIONAL INDICATOR | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$1,120.00) | |
| | | BARRICADE | | | 2 | Jul 16, 2021 | SYSTEM | (\$1,120.00) | |
| | | | | - Total | | | | (\$2,240.00) | |
| | | | Material - Tota | | | | | (\$2,240.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$1,120.00 | |
| | | | | | 3 | Aug 2, | SYSTEM | \$1,120.00 | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|
| J4S3386 | 0450 | DIRECTIONAL INDICATOR | MaterialCredit | | | 2021 | | | |
| | | BARRICADE | | - Total | | | | \$2,240.00 | |
| | | | MaterialCredit | - Total | | | | \$2,240.00 | |
| | 0450 - | · Total | | | | | | \$0.00 | |
| | 0460 | FLASHING ARROW PANEL | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$1,800.00) | |
| | | | | | 2 | Jul 16, 2021 | SYSTEM | (\$1,800.00) | |
| | | | | - Total | | | | (\$3,600.00) | |
| | | | Material - Tota | l | | | | (\$3,600.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$1,800.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$1,800.00 | |
| | | | AL (1.10 IV | - Total | | | | \$3,600.00 | |
| | | | MaterialCredit | - I otal | | | | \$3,600.00 | |
| | 0460 - | | | | | | | \$0.00 | |
| | 0470 | SEQUENTIAL FLASHING WARNING LIGHT | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$1,120.00) | |
| | | | | | 2 | Jul 16, 2021 | SYSTEM | (\$1,120.00) | |
| | | | | - Total | | | | (\$2,240.00) | |
| | | | Material - Tota | 1 | | | | (\$2,240.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$1,120.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$1,120.00 | |
| | | | | - Total | | | | \$2,240.00 | |
| | | | MaterialCredit | - Total | | | | \$2,240.00 | |
| | 0470 - | Total | | | | | | \$0.00 | |
| | 0480 | CMS WITH COMMUNICATION INTERFACE, CONT F | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$68,000.00) | |
| | | | | | 2 | Jul 16, 2021 | SYSTEM | (\$62,000.00) | |
| | | | | - Total | | | | (\$130,000.00) | |
| | | | Material - Tota | I | | | | (\$130,000.00) | |
| | | | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$68,000.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$62,000.00 | |
| | | | | - Total | | | | \$130,000.00 | |
| | | | MaterialCredit | - Total | | | | \$130,000.00 | |
| | | | Overrun | Overrun | 1 | Jun 30, 2021 | SYSTEM | \$6,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 32 on the current Payment Estimate. Material Insufficiency Quantity 34.000; Overrun Quantity Balance 3.00. |
| | | | | | 1 | Jun 30, 2021 | SYSTEM | (\$6,000.00) | |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | ı | | | | \$0.00 | |
| | 0480 - | · Total | | | | | | \$0.00 | |
| | 0500 | TEMPORARY TRAFFIC | Material | | 1 | Jun 30, 2021 | SYSTEM | (\$25,650.00) | |
| | | BARRIER, CONT. FURN/RE | | | 2 | Jul 16, 2021 | SYSTEM | (\$15,750.00) | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | (\$15,750.00) | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | (\$15,750.00) | |



| ect | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----|--------------------|---|---|-------------------------------|----------------|--|------------------|---|--|
| 386 | 0500 | TEMPORARY | Material | - Total | | | | (\$72,900.00) | |
| | | TRAFFIC BARRIER, CONT. | Material - Tota | | | | | (\$72,900.00) | |
| | | FURN/RE | MaterialCredit | | 2 | Jul 16, 2021 | SYSTEM | \$25,650.00 | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$15,750.00 | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | \$15,750.00 | |
| | | | | - Total | | | | \$57,150.00 | |
| | | | MaterialCredit | it - Total | | | | \$57,150.00 | |
| | | | Overrun | Overrun | 1 | Jun 30, 2021 | SYSTEM | \$9,900.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 1140.000; Overrun Quantity Balance 440.00. |
| | | | | | 1 | Jun 30, 2021 | SYSTEM | (\$9,900.00) | |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | ıl | | | | \$0.00 | |
| | 0500 - | Total | | | | | | (\$15,750.00) | |
| | 0670 | ROCK DITCH CHECK | Material | | 2 | Jul 16, 2021 | SYSTEM | \$750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kennem2 overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | | 2 | Jul 16, 2021 | SYSTEM | (\$750.00) | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | \$750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user marshp3 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | (\$750.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ıl | | | | \$0.00 | |
| | 0670 - | Total | | | | | | \$0.00 | |
| | 0710 | SILT FENCE | Material | | 3 | Aug 2, 2021 | SYSTEM | (\$121.90) | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | \$121.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 25 on the current Payment Estimate. |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | (\$121.90) | |
| | | | | | | 2021 | | (, , | |
| | | | | - Total | | 2021 | | (\$121.90) | |
| | | | Material - Tota | | | 2021 | | ` ′ | |
| | | | Material - Tota MaterialCredit | 1 | 4 | | SYSTEM | (\$121.90) (\$121.90) \$121.90 | |
| | | | MaterialCredit | l - Total | 4 | Aug 16, | SYSTEM | (\$121.90) (\$121.90) \$121.90 \$121.90 | |
| | | | | l - Total | 4 | Aug 16, | SYSTEM | (\$121.90) (\$121.90) \$121.90 | |
| | 0710 - 0960 | GALVANIZED | MaterialCredit MaterialCredit | l - Total | 4 | Aug 16, 2021 | SYSTEM | (\$121.90) (\$121.90) \$121.90 \$121.90 | This adjustment offsets the original system-generated Material Payment |
| | | | MaterialCredit MaterialCredit | l - Total | | Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 | | (\$121.90) (\$121.90) \$121.90 \$121.90 \$121.90 \$0.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user marshp3 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | GALVANIZED STRUCTURAL STEEL PILES (12 | MaterialCredit MaterialCredit | l - Total | 4 | Aug 16, 2021 Aug 16, 2021 | SYSTEM | (\$121.90) (\$121.90) \$121.90 \$121.90 \$121.90 \$0.00 \$27,900.00 | Estimate Item Adjustment (0005) due to user marshp3 overridding Payment |
| | | GALVANIZED STRUCTURAL STEEL PILES (12 | MaterialCredit MaterialCredit | - Total - Total - Total | 4 | Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 | SYSTEM | (\$121.90) (\$121.90) \$121.90 \$121.90 \$121.90 \$0.00 \$27,900.00 | Estimate Item Adjustment (0005) due to user marshp3 overridding Payment |
| | | GALVANIZED STRUCTURAL STEEL PILES (12 IN | MaterialCredit MaterialCredit Material | - Total - Total - Total | 4 | Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 | SYSTEM | (\$121.90) (\$121.90) \$121.90 \$121.90 \$121.90 \$0.00 \$27,900.00 (\$27,900.00) | Estimate Item Adjustment (0005) due to user marshp3 overridding Payment |
| | 0960 | GALVANIZED STRUCTURAL STEEL PILES (12 IN | MaterialCredit MaterialCredit Material | - Total - Total - Total | 4 | Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 | SYSTEM | (\$121.90) (\$121.90) \$121.90 \$121.90 \$121.90 \$0.00 \$27,900.00) (\$27,900.00) \$0.00 | Estimate Item Adjustment (0005) due to user marshp3 overridding Payment |
| | 0960 - | GALVANIZED STRUCTURAL STEEL PILES (12 IN | Material Credit Material Credit Material Material - Tota | - Total - Total - Total | 4 | Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 | SYSTEM SYSTEM | (\$121.90) (\$121.90) \$121.90 \$121.90 \$121.90 \$0.00 \$27,900.00 (\$27,900.00) \$0.00 \$0.00 | Estimate Item Adjustment (0005) due to user marshp3 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user marshp3 overridding Payment |
| | 0960 - | GALVANIZED STRUCTURAL STEEL PILES (12 IN | Material Credit Material Credit Material Material - Tota | - Total - Total - Total | 4 | Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 | SYSTEM SYSTEM | (\$121.90) (\$121.90) (\$121.90 \$121.90 \$121.90 \$0.00 \$27,900.00 (\$27,900.00) \$0.00 \$0.00 \$1,320.00 | Estimate Item Adjustment (0005) due to user marshp3 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user marshp3 overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | |
|-----------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|---|-----------------|--------|--------------|---|--|---|----------------|--------|----------------|--|
| J4S3386 | 0970 - | Total | | | | | | \$0.00 | | | | | | | | | | | | |
| | 0980 | CLASS B CONCRETE (SUBSTRUCTURE) | Material | | 4 | Aug 16, 2021 | SYSTEM | (\$14,705.00) | | | | | | | | | | | | |
| | | (SUBSTRUCTURE) | | - Total | | | | (\$14,705.00) | | | | | | | | | | | | |
| | | | Material - Tota | | | | | (\$14,705.00) | | | | | | | | | | | | |
| | 0980 - | Total | | | | | | (\$14,705.00) | | | | | | | | | | | | |
| | 1050 | REINFORCING STEEL (EPOXY COATED) | | | 4 | Aug 16, 2021 | SYSTEM | \$2,963.14 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user marshp3 overridding Payment Estimate Exception 19 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | (\$2,963.14) | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - Tota | ıl | | | | \$0.00 | | | | | | | | | | | | |
| | 1050 - | Total | | | | | | \$0.00 | | | | | | | | | | | | |
| | 1120 | MECHANICALLY STABILIZED EARTH WALL SYS | Material | | 3 | Aug 2, 2021 | SYSTEM | \$106,029.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user marshp3 overridding Payment Estimate Exception 14 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 3 | Aug 2, 2021 | SYSTEM | (\$106,029.00) | | | | | | | | | | | | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | \$106,029.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user marshp3 overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | (\$106,029.00) | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - Tota | | | | | \$0.00 | | | | | | | | | | | | |
| | 1120 - | Total | | | | | | \$0.00 | | | | | | | | | | | | |
| | 1150 | MECHANICALLY STABILIZED EARTH WALL SYS | Material | | 3 | Aug 2, 2021 | SYSTEM | \$104,026.23 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user marshp3 overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 3 | Aug 2, 2021 | SYSTEM | (\$104,026.23) | |
| | | | | | | | | | | 4 | Aug 16, 2021 | SYSTEM | \$104,026.23 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user marshp3 overridding Payment Estimate Exception 23 on the current Payment Estimate. | | | | | | |
| | | | | | 4 | Aug 16, 2021 | SYSTEM | (\$104,026.23) | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - Tota | | | | | \$0.00 | | | | | | | | | | | | |
| | 1150 - | Total | | | | | | \$0.00 | | | | | | | | | | | | |
| J4S3386 - | Total | | | | | | | (\$32,455.00) | | | | | | | | | | | | |
| Overall - | Total | | | | | | | (\$35,705.00) | | | | | | | | | | | | |