

Notice to

Proceed Date
Work Began
Date

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2021

May 10, 2021

May 10, 2021

Progress Esti		Contract ID Prime Contractor		Pay Period Start Pay Period End		t 15, 2021 I	Net Char	Contract Amount nge Order Amount Contract Amount	\$502,424.00 \$19,009.24 \$521,433.24	
Approval Date										By User
August 16, 2021		G	enerated and A	proved	(and should be co	nsidere	d Draft) at th	e Projec	t Office Level by	beckc2
August 16, 2021		Revie	wed and Approv	ed (and	should be conside	red Dra	aft) at the Re	sident Er	ngineer Level by	grahac
August 17, 2021			R	eviewed	and Approved at t	he Cen	tral Office C	ontrollers	office Level by	ramses1
Original Com	pletion Date	Current Comp	letion Date	Act	ual Completion D	ate	% o	f Curren	t Contract Amoun	t Complete
December	1, 2021	December 1	1, 2021						78.27%	
Co	ntract Informatio	nal Dates					Milestone	s		
Date Description	Original Completion Da	Current ate Completion D		escriptio	Original Completion [		Current Completion		Days Remaining on Milestone	Diary Charge Days
Acceptance Date			Milestor Calenda		August 9, 202	21 A	August 17, 2	021	(	D
Awarded Date	April 7, 2021	April 7, 2021								
Letting Date	March 19, 2021	March 19, 2021								

Contract Total Pa	ay For Estimate No. 5				
		This Estimate	Previous	To Date	
210319-D01					
	Total Posted Items Pay	\$63,531.40	\$344,614.95	\$408,146.35	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$344,614.95	\$408,146.35	
<b>Contract Total Pa</b>	ayable This Estimate:	\$63,531.40			

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5I3324	0060	6161005	CONSTRUCTION SIGNS	SQFT	\$8.000	16	\$128.00
	0270	7039903	MISC.Pile Encasement	LF	\$480.000	61	\$29,280.00
	0330	7129903	MISC.Steel Pile Repair	LF	\$610.000	55.94	\$34,123.40
Project J5l3324 - 1	Γotal						\$63,531.40
Overall - Total							\$63,531.40

### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract

Line Item	Adjust	tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5I3324	0290	CLEANING AND EPOXY COATING	Material			-990.5	\$15.00	(\$14,857.50)
	0290	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user beckc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	990.5	\$15.00	\$14,857.50
	0300	FABRICATED STRUCTURAL CARBON STEEL (MISC)	Material			-2,352	\$18.50	(\$43,512.00)
	0300	FABRICATED STRUCTURAL	Material		This adjustment offsets the original system-	2,352	\$18.50	\$43,512.00

Revision 4/1/2020 Page 1 of 10



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2021

Progress Estimate Number	Contract ID	210319-D01	Pay Period Start	August 2, 2021	Original Contract Amount	\$502,424.00
5	Prime Contractor	Kozeny-Wagner, Inc.	Pay Period End	August 15, 2021	Net Change Order Amount	\$19,009.24
3					Current Contract Amount	\$521,433.24

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5I3324		CARBON STEEL (MISC)			generated Material Payment Estimate Item Adjustment (0002) due to user beckc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
	0320	GRAY EPOXY-MASTIC PRIMER	Material			-0.9	\$7,500.00	(\$6,750.00
	0320	GRAY EPOXY-MASTIC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user beckc2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	0.9	\$7,500.00	\$6,750.00
	5002	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-3,833	\$0.83	(\$3,181.39)
	5002	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	3,833	\$0.83	\$3,181.39
	5003	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-3,833	\$0.83	(\$3,181.39)
	5003	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user beckc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	3,833	\$0.83	\$3,181.39
Total								\$0.00

Revision 4/1/2020 Page 2 of 10



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Con	ntract Project Informa	tion
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5I3324	I 44-2(318)	Bridge rehabilitation	I-44	LACLEDE	over Gasconade Overflow		
Totals by	Job Numb	ers					
J5I3324		ed Item Pay s Item Adjustm		Item Pay	This Estimate \$63,531.40 \$0.00 \$63,531.40	Previous \$344,614.95 \$0.00 \$344,614.95	<b>To Date</b> \$408,146.35 \$0.00 <b>\$408,146.35</b>
	Liqui	ntive centive dated Damages r Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 10



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5l3324, Item 6206000C, Project Item Line Number 5002, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with Materials	beckc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3324, Item 6206000C, Project Item Line Number 5002, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Working with Materials	beckc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3324, Item 6206001C, Project Item Line Number 5003, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Working with Materials	beckc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3324, Item 6206001C, Project Item Line Number 5003, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with Materials	beckc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3324, Item 7040113, Project Item Line Number 0290, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient.	Working with Materials	beckc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3324, Item 7121000, Project Item Line Number 0300, Material Set 712100096, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	Working with Materials	beckc2	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3324, Item 7125961, Project Item Line Number 0320, Material Set 712596196, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	Working with Materials	beckc2	Overridden

Revision 4/1/2020 Page 4 of 10



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ntract ONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
9-D01	J5l3324	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$40,608.67	\$40,608.
		0001	0020	2153000	SHAPING SLOPES, CLASS III	3.00	0.00	3.00	100F	3.00	\$941.00	\$2,823.
		0001	0030	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	1.00	1.00	2.00	EA	2.00	\$1,500.00	\$3,000
		0001	0040	6122030	IMPACT ATTENUATOR (RELOCATION)	1.00	-1.00	0.00	EA	0.00	\$1,000.00	\$0
		0001	0050	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000
		0001	0060	6161005	CONSTRUCTION SIGNS	551.00	376.00	927.00	SQFT	894.00	\$8.00	\$7,152
		0001	0070	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	0.00	8.00	EA	2.00	\$95.00	\$190
		0001	0800	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	0.00	\$12.00	\$0
		0001	0090	6161025	CHANNELIZER (TRIM LINE)	135.00	0.00	135.00	EA	135.00	\$19.00	\$2,565
		0001	0100	6161033	DIRECTIONAL INDICATOR BARRICADE	15.00	0.00	15.00	EA	15.00	\$60.00	\$900
		0001	0110	6161040	FLASHING ARROW PANEL	1.00	0.00	1.00	EA	1.00	\$600.00	\$600
		0001	0120	6161055	SEQUENTIAL FLASHING WARNING LIGHT	15.00	0.00	15.00	EA	15.00	\$80.00	\$1,200
		0001	0130	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	1.00	5.00	EA	5.00	\$2,650.00	\$13,250
		0001	0140	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	2.00	6.00	EA	6.00	\$850.00	\$5,100
		0001	0150	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	650.00	650.00	1,300.00	LF	1,300.00	\$20.00	\$26,000
		0001	0160	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	650.00	-650.00	0.00	LF	0.00	\$10.00	\$0
		0001	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$49,000.00	\$49,000
		0001	0180	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,844.00	-3,844.00	0.00	LF	0.00	\$0.83	\$0
		0001	0190	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	3,844.00	-3,844.00	0.00	LF	0.00	\$0.83	\$0
		0001	0200	6205902A	$\boldsymbol{6}$ IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,142.00	0.00	3,142.00	LF	0.00	\$0.48	\$0
		0001	0210	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,331.00	0.00	1,331.00	LF	0.00	\$0.48	\$0
		0001	0220	6207001	PAVEMENT MARKING REMOVAL	8,316.00	3,309.00	11,625.00	LF	8,985.00	\$0.50	\$4,492
		0010	0230	6061060	MGS GUARDRAIL	188.00	0.00	188.00	LF	62.50	\$32.50	\$2,031
		0010	0240	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	3.00	0.00	3.00	EA	1.00	\$4,867.00	\$4,867
		0010	0250	6066400	GUARDRAIL, RELOCATED AND MODIFIED	63.00	0.00	63.00	LF	0.00	\$20.50	\$0
		0070	0260	2162000	REMOVAL AND STORAGE OF EXISTING BRIDGE RAIL	255.00	0.00	255.00	LF	255.00	\$19.00	\$4,845
		0070	0270	7039903	MISC.Pile Encasement	96.00	0.00	96.00	LF	61.00	\$480.00	\$29,280
		0070	0280	7040107	SLAB EDGE REPAIR (BRIDGES)	70.00	0.00	70.00	LF	49.00	\$340.00	\$16,660
		0070	0290	7040113	CLEANING AND EPOXY COATING	1,381.00	0.00	1,381.00	SQFT	990.50	\$15.00	\$14,857
		0070	0300	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	3,040.00	0.00	3,040.00	LB	2,352.00	\$18.50	\$43,512
		0070	0310	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.90	\$7,500.00	\$6,750
		0070	0320	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.90	\$7,500.00	\$6,750
		0070	0330	7129903	MISC.Steel Pile Repair	131.00	0.00	131.00	LF	116.44	\$610.00	\$71,028
		0070	0340	7134000	BRIDGE GUARDRAIL (THRIE BEAM)	255.00	0.00	255.00	LF	125.00	\$314.45	\$39,306
		0001	5001	6189901	MISC.Misc. Mobilization (Streetwise Stage 1 to Stage 2)	0.00	1.00	1.00	LS	1.00	\$3,015.00	\$3,015
		0001	5002	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0.00	3,833.00	3,833.00	LF	3,833.00	\$0.83	\$3,18
		0001	5003	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0.00	3,833.00	3,833.00	LF	3,833.00	\$0.83	\$3,181
	Project I	513324 - To	tal Valuo	Posted to D	ate as of Report Generated Date							\$408,146

Revision 4/1/2020 Page 5 of 10



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5l3324

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0060	6161005	CONSTRUCTION SIGNS	8/5/21	8/5/21	16.00	SQFT	Route I-44 WB 148.431 Rt 57 WO4-1aL 16SQFT	148.431		148.431		installed on 7/8/21
0270	7039903	MISC. CONCRETE CONSTRUCTION	8/11/21	8/12/21	40.00	LF	bent 3 and 2 piles of bent 4 complete					bent 3 and 2 piles of bent 4 complete
			8/12/21	8/12/21	21.00	LF	bent 4, piles 20-25					pile 20 was 6 feet the rest were 5 feet
0330	7129903	MISC. STRUCTURAL STEEL CONSTRUCTION	8/14/21	8/16/21	55.94	LF		149.834		149.858		Pile Repairs completed. This item will be removed and paid as a contingent item at a later date.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 10



JSI3324   0030	ints of ',1500.00000 - 1500.00000,
BARREL ARRAY)  4 Aug 2, 2021 \$1,500.00 Unit price based on averaged overrun adjustr previous payment estimates. Price Adjustmen 'is applied (if non-zero).  Overrun - Total \$0.00  Overrun - Total \$0.00  CONSTRUCTION SIGNS  Overrun   1 Jun 16, 2021   2 Jul 1, 2021   3 Jul 16, 2021   3 Jul 16, 2021   3 Jul 16, 2021   3 SYSTEM \$624.00 Unit price based on averaged overrun adjustr previous payment estimates. Price Adjustmen applied (if non-zero).  4 Aug 2, 2021 \$912.00 Unit price based on averaged overrun adjustr previous payment estimates. Price Adjustmen applied (if non-zero).	ints of ',1500.00000 - 1500.00000,
Overrun - Total   \$0.00	
Occupant   Overrun   Ove	
Overrun SIGNS  Overrun 1 Jun 16, 2021 (\$792.00)  2 Jul 1, 2021 (\$792.00)  3 Jul 16, 2021 \$SYSTEM (\$792.00)  4 Aug 2, 2021 \$SYSTEM \$912.00 Unit price based on averaged overrun adjustr previous payment estimates. Price Adjustmen applied (if non-zero).	
SIGNS  2021  2 Jul 1, SYSTEM (\$792.00)  3 Jul 16, 2021  \$ SYSTEM \$624.00 Unit price based on averaged overrun adjustre previous payment estimates. Price Adjustment applied (if non-zero).  4 Aug 2, 2021  \$ SYSTEM \$912.00 Unit price based on averaged overrun adjustre previous payment estimates. Price Adjustment applied (if non-zero).	
2021  3 Jul 16, 2021  \$ \$624.00 Unit price based on averaged overrun adjustre previous payment estimates. Price Adjustment applied (if non-zero).  4 Aug 2, 2021  \$ \$912.00 Unit price based on averaged overrun adjustre previous payment estimates. Price Adjustment applied (if non-zero).	
2021 previous payment estimates. Price Adjustmen applied (if non-zero).  4 Aug 2, 2021 \$912.00 Unit price based on averaged overrun adjustr previous payment estimates. Price Adjustmen applied (if non-zero).	
2021 previous payment estimates. Price Adjustmer applied (if non-zero).	
Overrun - Total \$0.00	
Overrun - Total \$0.00	
0060 - Total \$0.00	
0130 CMS WITH COMMUNICATION INTERFACE, 1 Jun 16, SYSTEM \$10,600.00 This adjustment offsets the original system-great Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Communication in the current	r thompp1 overridding Payment
CONT F 1 Jun 16, SYSTEM (\$10,600.00)	
2 Jul 1, SYSTEM \$13,250.00 This adjustment offsets the original system-greater to the strength of the system of th	r thompp1 overridding Payment
2 Jul 1, SYSTEM (\$13,250.00)	
- Total \$0.00	
Material - Total \$0.00	
Overrun Overrun 2 Jul 1, 2021 \$2,650.00 This adjustment offsets the original system-greater term Adjustment (0002) overridding on the current Payment Estimate. Material Institution Overrun Quantity Balance 1.00.	Payment Estimate Exception 11
2 Jul 1, SYSTEM (\$2,650.00)	
Overrun - Total \$0.00	
Overrun - Total \$0.00	
0130 - Total \$0.00	
0140 TEMPORARY LONG-TERM RUMBLE STRIPS Material 1 Jun 16, 2021 \$3,400.00 This adjustment offsets the original system-great system-great 1 System \$3,400.00 Estimate Item Adjustment (0003) due to user Estimate Exception 2 on the current Payment	thompp1 overridding Payment
1 Jun 16, SYSTEM (\$3,400.00)	
2 Jul 1, SYSTEM \$3,400.00 This adjustment offsets the original system-greater to the system of the s	thompp1 overridding Payment
2 Jul 1, SYSTEM (\$3,400.00)	
- Total \$0.00	
Material - Total \$0.00	
Overrun Overrun 3 Jul 16, SYSTEM (\$1,700.00)	
4 Aug 2, 2021 SYSTEM \$1,700.00 Unit price based on averaged overrun adjustr previous payment estimates. Price Adjustment applied (if non-zero).	
Overrun - Total \$0.00	
Overrun - Total \$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3324	0140 -	Total						\$0.00	
	0150	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		1	Jun 16, 2021	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thompp1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		TORIVIL			1	Jun 16, 2021	SYSTEM	(\$13,000.00)	
					2	Jul 1, 2021	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thompp1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$13,000.00)	
					3	Jul 16, 2021	SYSTEM	\$26,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thompp1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jul 16, 2021	SYSTEM	(\$26,000.00)	
					4	Aug 2, 2021	SYSTEM	\$26,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user beckc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$26,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	3	Jul 16, 2021	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 10 on the current Payment Estimate. Material Insufficiency Quantity 1300.000; Overrun Quantity Balance 650.00.
					3	Jul 16, 2021	SYSTEM	(\$13,000.00)	
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0150 -	Total						\$0.00	
	0180	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	Material		1	Jun 16, 2021	SYSTEM	\$2,085.79	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		IIV.,			1	Jun 16, 2021	SYSTEM	(\$2,085.79)	
					2	Jul 1, 2021	SYSTEM	\$2,085.79	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user thompp1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$2,085.79)	
					3	Jul 16, 2021	SYSTEM	\$3,181.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user thompp1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Jul 16, 2021	SYSTEM	(\$3,181.39)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0180 -	Total						\$0.00	
	0190	TEMPORARY REMOVABLE MARKING TAPE	Material		1	Jun 16, 2021	SYSTEM	\$2,085.79	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user thompp1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$2,085.79)	
					2	Jul 1, 2021	SYSTEM	\$2,085.79	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user thompp1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$2,085.79)	
					3	Jul 16, 2021	SYSTEM	\$3,181.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user thompp1 overridding Payment Estimate Exception 3 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3324	0190	TEMPORARY REMOVABLE MARKING TAPE	Material		3	Jul 16, 2021	SYSTEM	(\$3,181.39)	
		W/ (( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( (		- Total				\$0.00	
			Material - Total					\$0.00	
	0190 -	Total						\$0.00	
	0230	MGS GUARDRAIL	Material		2	Jul 1, 2021	SYSTEM	\$2,031.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$2,031.25)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0230 -	Total						\$0.00	
	0240	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Material		2	Jul 1, 2021	SYSTEM	\$4,867.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user thompp1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$4,867.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0240 -	Total						\$0.00	
	0280	SLAB EDGE REPAIR (BRIDGES)	Material		2	Jul 1, 2021	SYSTEM	\$11,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user thompp1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$11,900.00)	
			- Total					\$0.00	
			Material - T	Material - Total				\$0.00	
	0280 -	280 - Total						\$0.00	
	0290								
	0290	CLEANING AND EPOXY COATING	Material		3	Jul 16, 2021	SYSTEM	\$10,357.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	0290		Material		3		SYSTEM SYSTEM		Estimate Item Adjustment (0008) due to user thompp1 overridding Payment
	0290		Material			2021 Jul 16,		\$10,357.50	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment
	0290		Material		3	Jul 16, 2021 Aug 2,	SYSTEM	\$10,357.50 (\$10,357.50)	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment
	0290		Material		3	Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM	\$10,357.50 (\$10,357.50) \$14,857.50	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment
	0290		Material		3 4	Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,357.50 (\$10,357.50) \$14,857.50 (\$14,857.50)	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user beckc2 overridding Payment
	0290		Material	- Total	3 4 4 5	2021  Jul 16, 2021  Aug 2, 2021  Aug 2, 2021  Aug 16, 2021  Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,357.50 (\$10,357.50) \$14,857.50 (\$14,857.50) \$14,857.50	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user beckc2 overridding Payment
	0290		Material - To		3 4 4 5	2021  Jul 16, 2021  Aug 2, 2021  Aug 2, 2021  Aug 16, 2021  Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,357.50 (\$10,357.50) \$14,857.50 (\$14,857.50) \$14,857.50 (\$14,857.50)	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user beckc2 overridding Payment
	0290	EPOXY COATING			3 4 4 5	2021  Jul 16, 2021  Aug 2, 2021  Aug 2, 2021  Aug 16, 2021  Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,357.50 (\$10,357.50) \$14,857.50 (\$14,857.50) \$14,857.50 (\$14,857.50)	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user beckc2 overridding Payment
		EPOXY COATING			3 4 4 5	2021  Jul 16, 2021  Aug 2, 2021  Aug 2, 2021  Aug 16, 2021  Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,357.50 (\$10,357.50) \$14,857.50 (\$14,857.50) \$14,857.50 (\$14,857.50) \$0.00	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user beckc2 overridding Payment
	0290 -	Total  FAB. STRUCT. CARBON STEEL	Material - To		3 4 4 5	2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10,357.50 (\$10,357.50) \$14,857.50 (\$14,857.50) \$14,857.50 (\$14,857.50) \$0.00 \$0.00	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user beckc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user thompp1 overridding Payment Estimate Item Adjustment (0009) due to user thompp1 overridding Payment
	0290 -	Total  FAB. STRUCT. CARBON STEEL	Material - To		3 4 4 5 5 5	2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10,357.50 (\$10,357.50) \$14,857.50 (\$14,857.50) \$14,857.50 (\$14,857.50) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user beckc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user thompp1 overridding Payment Estimate Item Adjustment (0009) due to user thompp1 overridding Payment
	0290 -	Total  FAB. STRUCT. CARBON STEEL	Material - To		3 4 4 5 5 3 3	2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021  Aug 16, 2021  Jul 16, 2021  Jul 16, 2021  Aug 2, 4021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10,357.50 (\$10,357.50) \$14,857.50 (\$14,857.50) \$14,857.50 (\$14,857.50) \$0.00 \$0.00 \$28,120.00 (\$28,120.00)	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user beckc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user thompp1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user beckc2 overridding Payment Estimate Item Adjustment (0006) due to user beckc2 overridding Payment
	0290 -	Total  FAB. STRUCT. CARBON STEEL	Material - To		3 4 4 5 5 3 3 4	2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021  Jul 16, 2021  Jul 16, 2021  Jul 16, 2021  Aug 2, 2021  Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10,357.50 (\$10,357.50) \$14,857.50 (\$14,857.50) \$14,857.50 (\$14,857.50) \$0.00 \$0.00 \$0.00 \$28,120.00 (\$28,120.00) \$43,512.00	Estimate Item Adjustment (0008) due to user thompp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user beckc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user thompp1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user beckc2 overridding Payment Estimate Item Adjustment (0006) due to user beckc2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3324	0300	FAB. STRUCT. CARBON STEEL (MISC)	Material			2021			
				- Total				\$0.00	
	Material - Total							\$0.00	
	0300 -							\$0.00	
	0320	GRAY EPOXY- MASTIC PRIMER	Material		3	Jul 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user thompp1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Jul 16, 2021	SYSTEM	(\$3,000.00)	
					4	Aug 2, 2021	SYSTEM	\$6,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user beckc2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$6,750.00)	
					5	Aug 16, 2021	SYSTEM	\$6,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user beckc2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$6,750.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0320 -	Total						\$0.00	
	0340	BRIDGE GUARDRAIL (THRIE BEAM)	Material		2	Jul 1, 2021	SYSTEM	\$39,306.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user thompp1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$39,306.25)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0340 -	Total						\$0.00	
	5002	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		4	Aug 2, 2021	SYSTEM	\$3,181.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user beckc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$3,181.39)	
					5	Aug 16, 2021	SYSTEM	\$3,181.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user beckc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$3,181.39)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5002 -	Total						\$0.00	
	5003	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		4	Aug 2, 2021	SYSTEM	\$3,181.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user beckc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$3,181.39)	
					5	Aug 16, 2021	SYSTEM	\$3,181.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user beckc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$3,181.39)	
			- Total					\$0.00	
			Material - To	otal				\$0.00	
	5003 - Total							\$0.00	
J5l3324 -	Total							\$0.00	
Overall -	Total							\$0.00	