

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 1, 2022

Progress Estim	Progress Estimate Number 19		Contract ID 210319-F05 Pay Period Start February 16, 2022 Original Contract Ar Prime Contractor Gerstner Electric, Inc. Pay Period End March 1, 2022 Net Change Order A Current Contract Ar							
Approval Date						By User				
March 1, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by									
March 2, 2022		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by								
March 3, 2022		Reviewed and Approved at the Central Office Controllers Office Level by ramses:								
Original Completion Date		Current Con	npletion Date	% of Current Contract Amou	ınt Complete					
January 2	8, 2022	January								

	Milestones		
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	April 7, 2021	April 7, 2021	
Letting Date	March 19, 2021	March 19, 2021	
Notice to Proceed Date	May 10, 2021	May 10, 2021	
Work Began Date	May 10, 2021	May 10, 2021	

Contract Total Pay For Estimate No. 19									
	This Estimate	Previous	To Date						
210319-F05									
Total Posted Items Pay	\$0.00	\$1,330,350.93	\$1,330,350.93						
Gross Item Adjustments	\$0.00	\$0.00	\$0.00						
Incentive	\$0.00	\$0.00	\$0.00						
Disincentive	\$0.00	\$0.00	\$0.00						
Liquidated Damage	\$0.00	\$0.00	\$0.00						
Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
		\$1,330,350.93	\$1,330,350.93						
Contract Total Payable This Estimate:	\$0.00								

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

No Data Available


Page 1 of 8 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	n						
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work								
J6Q3469	FAS S502(75)	ITS improvements	Various	ST LOUIS CITY	at various locations withi	at various locations within the St. Louis District							
J6Q3473	FAS S502(76)	ITS improvements	Various	ST LOUIS	at various locations throu	at various locations throughout the St. Louis District							
Totals by J	Job Numbe	rs											
J6Q3469	Q3469 Posted Item Pay Gross Item Adjustments Gross Item Pay			This Estimate \$0.00 \$0.00 \$0.00	Previous \$804,818.43 \$0.00 \$804,818.43	To Date \$804,818.43 \$0.00 \$804,818.43							
Incentive Disincentive Liquidated Damages Other Contract Adjustments				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00							
J6Q3473 Posted Item Pay Gross Item Adjustments Gross Item Pay				em Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$525,532.50 \$0.00 \$525,532.50	To Date \$525,532.50 \$0.00 \$525,532.50						
Incentive Disincentive Liquidated Damages Other Contract Adjustments			\$0.00 \$0.00 \$0.00		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00							

Revision 4/1/2020 Page 2 of 8





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

RACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POST To Date (See rep generated date
05 .	J6Q3469	0001	0010	6169901	MISC.Temporary Traffic Control	1.00	0.00	1.00	LS	1.00	\$32,000.00	\$32,00
		0001	0020	6169902	MISC.NTCIP Changable Message Sign (Contractor Furnish & Retain)	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$
		0001	0030	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$40,300.82	\$40,30
		0050	0040	9108201	CABLE, 1 AWG, 1 CONDUCTOR, POWER	840.00	0.00	840.00	LF	840.00	\$3.75	\$3,15
		0050	0050	9108202	CABLE, 2 AWG, 1 CONDUCTOR, POWER	1,810.00	-7.00	1,803.00	LF	1,803.00	\$3.20	\$5,76
		0050	0060	9108206	CABLE, 6 AWG, 1 CONDUCTOR, POWER	350.00	0.00	350.00	LF	0.00	\$1.70	\$
		0050	0070	9108401	WIRE, 1 AWG, BARE NEUTRAL	280.00	0.00	280.00	LF	280.00	\$2.90	\$81
		0050	0080	9108402	WIRE, 2 AWG, BARE NEUTRAL	610.00	-9.00	601.00	LF	601.00	\$2.50	\$1,50
		0050	0090	9108406	WIRE, 6 AWG, BARE NEUTRAL	120.00	0.00	120.00	LF	0.00	\$1.20	\$
		0050	0100	9109100	BASE, CONCRETE	9.00	3.00	12.00	CUYD	12.00	\$2,100.00	\$25,20
		0050	0110	9109901	MISC.DMS Training	1.00	0.00	1.00	LS	0.00	\$1.00	\$
		0050	0120	9109902	MISC.Dynamic Message Sign Retrofit	7.00	0.00	7.00	EA	7.00	\$88,000.00	\$616,00
		0050	0130	9109902	MISC.Fiber Optic Fusion Splice	92.00	22.00	114.00	EA	114.00	\$62.00	\$7,06
		0050	0140	9109902	MISC.Fiber Optic Jumper SM	26.00	0.00	26.00	EA	26.00	\$30.00	\$78
		0050	0150	9109902	MISC.Fiber Optic Pigtail SM	26.00	0.00	26.00	EA	26.00	\$12.00	\$31
		0050	0160	9109902	MISC.Install Communications Equipment	8.00	-1.00	7.00	EA	7.00	\$480.00	\$3,36
		0050	0170	9109902	MISC.Install Conduit Into Existing Box	11.00	0.00	11.00	EA	11.00	\$225.00	\$2,47
		0050	0180	9109902	MISC.Install IP-Addressable Power Strip	7.00	-2.00	5.00	EA	5.00	\$100.00	\$50
		0050	0190	9109902	MISC.Intercept Conduit With Pull Box	1.00	0.00	1.00	EA	1.00	\$525.00	\$52
		0050	0200	9109902	MISC.ITS Pull Box, Class 2	1.00	0.00	1.00	EA	1.00	\$1,950.00	\$1,98
		0050	0210	9109902	MISC.Modified Type 7 Cabinet	6.00	0.00	6.00	EA	6.00	\$3,325.00	\$19,95
		0050	0220	9109902	MISC.Rack-Mounted Interconnect Center	6.00	0.00	6.00	EA	6.00	\$500.00	\$3,00
		0050	0230	9109902	MISC.Remove and Salvage Pole-Mounted Cabinet	5.00	1.00	6.00	EA	6.00	\$275.00	\$1,68
			0240	9109902	MISC.Salvage Existing Sign Components	7.00	0.00	7.00	EA	7.00	\$300.00	\$2,10
		0050										
		0050	0250	9109902	MISC.Sign Structure Base Mesh	7.00	0.00	7.00	EA	7.00	\$350.00	\$2,45
		0050	0260	9109902	MISC.Sign Structure Inspection	7.00	0.00	7.00	EA	7.00	\$2,700.00	\$18,90
		0050	0270	9109903	MISC.24-Strand SM Fiber Optic Cable	204.00	0.00	204.00	LF	0.00	\$4.00	
		0050	0280	9109903		172.00	82.00	254.00	LF	254.00	\$18.00	\$4,57
		0050	0290	9109903	MISC.Conduit, PVC, Trench, 3"	161.00	15.00	176.00	LF	176.00	\$21.00	\$3,69
		0050	0300	9109903	MISC.DMS Control Cable	1,057.00	40.00	1,097.00	LF	1,097.00	\$3.50	\$3,83
		0050	0310	9109903	MISC.Remove and Reinstall FO Cable	375.00	0.00	375.00	LF	375.00	\$4.00	\$1,50
		0050	0320		MISC.Remove and Reinstall Power Cable	728.00	0.00	728.00	LF	728.00	\$2.00	\$1,45
					Date as of Report Generated Date	1.00	0.00	4.00	1.0	4.00	00 000 00	\$804,8
,	J6Q3473	0001	0330	6169901		1.00	0.00	1.00	LS	1.00	\$2,000.00	\$2,00
		0001	0340	6181000		1.00	0.00	1.00	LS	1.00	\$8,000.00	\$8,00
		0050	0350	9109902	·	150.00	0.00	150.00	EA	150.00	\$2,400.00	\$360,00
		0050	0360	9109902	· ·	150.00	0.00	150.00	EA	150.00	\$700.00	\$105,00
		0050	0370		MISC.Remove CCTV Camera & Assembly	149.00	0.00	149.00	EA	149.00	\$200.00	\$29,80
		0050	0380		MISC.CCTV Camera Cable	18,900.00	-2,314.00	16,586.00	LF	16,586.00	\$1.25	\$20,73
	Project IS	Q3473 - To	otal Value	Posted to	Date as of Report Generated Date							\$525,53

Revision 4/1/2020 Page 4 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 5 of 8



Line Item Adjustments by Estimate

Contract ID:190621-F01

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J6Q3469	0100	D100 BASE, CONCRETE	Material		1	Jun 3, 2021	SYSTEM	\$25,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jun 3, 2021	SYSTEM	(\$25,200.00)	
					2	Jun 16, 2021	SYSTEM	\$25,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jun 16, 2021	SYSTEM	(\$25,200.00)	
					3	Jul 1, 2021	SYSTEM	\$25,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jul 1, 2021	SYSTEM	(\$25,200.00)	
					4	Jul 16, 2021	SYSTEM	\$25,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jul 16, 2021	SYSTEM	(\$25,200.00)	
					5	Aug 2, 2021	SYSTEM	\$25,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Aug 2, 2021	SYSTEM	(\$25,200.00)	
					6	Aug 16, 2021	SYSTEM	\$25,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Aug 16, 2021	SYSTEM	(\$25,200.00)	
				- Total				\$0.00	
			Material - To					¢0.00	
			Materiai - 10	otai				\$0.00	
			Other Item Adjustment	OADJ	1	Jun 3, 2021	norton1	(\$6,300.00)	While trying to override a materials exception generated by AWP it was discovered that AWP was overriding an Item overrun. When I attempted to correct the item overrun AWP would not allow me to do this and paid for the Item overrun in the estimate. I am making line item adjustment to remove the Item overrun override.
			Other Item		7		norton1		discovered that AWP was overriding an Item overrun. When I attempted to correct the item overrun AWP would not allow me to do this and paid for the Item overrun in the estimate. I am making line item adjustment to remove the
			Other Item		7	2021 Sep 2,		(\$6,300.00)	discovered that AWP was overriding an Item overrun. When I attempted to correct the item overrun AWP would not allow me to do this and paid for the Item overrun in the estimate. I am making line item adjustment to remove the Item overrun override. This Item adjustment is being entered to balance out the user entered line item adjustment on estimate 1. The additional 3.0 CY of concrete needed to install
			Other Item Adjustment	OADJ	7 al	2021 Sep 2,		(\$6,300.00) \$6,300.00	discovered that AWP was overriding an Item overrun. When I attempted to correct the item overrun AWP would not allow me to do this and paid for the Item overrun in the estimate. I am making line item adjustment to remove the Item overrun override. This Item adjustment is being entered to balance out the user entered line item adjustment on estimate 1. The additional 3.0 CY of concrete needed to install
			Other Item Adjustment	OADJ - Tota	7 al Total	2021 Sep 2,		(\$6,300.00) \$6,300.00 \$0.00	discovered that AWP was overriding an Item overrun. When I attempted to correct the item overrun AWP would not allow me to do this and paid for the Item overrun in the estimate. I am making line item adjustment to remove the Item overrun override. This Item adjustment is being entered to balance out the user entered line item adjustment on estimate 1. The additional 3.0 CY of concrete needed to install
			Other Item Adjustment	OADJ - Tota Adjustment -	7 al Total	2021 Sep 2, 2021	norton1	\$6,300.00 \$6,300.00 \$0.00	discovered that AWP was overriding an Item overrun. When I attempted to correct the item overrun AWP would not allow me to do this and paid for the Item overrun in the estimate. I am making line item adjustment to remove the Item overrun override. This Item adjustment is being entered to balance out the user entered line item adjustment on estimate 1. The additional 3.0 CY of concrete needed to install Type 7 ITS cabinets was approved on change order 1. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000;
			Other Item Adjustment	OADJ - Tota Adjustment -	7 al Total	2021 Sep 2, 2021 Jun 3, 2021	norton1	\$6,300.00 \$6,300.00 \$0.00 \$6,090.00	discovered that AWP was overriding an Item overrun. When I attempted to correct the item overrun AWP would not allow me to do this and paid for the Item overrun in the estimate. I am making line item adjustment to remove the Item overrun override. This Item adjustment is being entered to balance out the user entered line item adjustment on estimate 1. The additional 3.0 CY of concrete needed to install Type 7 ITS cabinets was approved on change order 1. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000; Overrun Quantity Balance 3.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000;
			Other Item Adjustment	OADJ - Tota Adjustment -	7 Total 1	2021 Sep 2, 2021 Jun 3, 2021 Jun 3,	norton1 SYSTEM SYSTEM	\$6,300.00) \$6,300.00 \$0.00 \$6,090.00	discovered that AWP was overriding an Item overrun. When I attempted to correct the item overrun AWP would not allow me to do this and paid for the Item overrun in the estimate. I am making line item adjustment to remove the Item overrun override. This Item adjustment is being entered to balance out the user entered line item adjustment on estimate 1. The additional 3.0 CY of concrete needed to install Type 7 ITS cabinets was approved on change order 1. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000; Overrun Quantity Balance 3.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000;
			Other Item Adjustment	OADJ - Tota Adjustment -	7 Total 1	2021 Sep 2, 2021 Jun 3, 2021 Jun 3, 2021 Jun 3, 2021	norton1 SYSTEM SYSTEM	\$6,300.00) \$6,300.00 \$0.00 \$6,090.00 \$210.00 (\$6,300.00)	discovered that AWP was overriding an Item overrun. When I attempted to correct the item overrun AWP would not allow me to do this and paid for the Item overrun in the estimate. I am making line item adjustment to remove the Item overrun override. This Item adjustment is being entered to balance out the user entered line item adjustment on estimate 1. The additional 3.0 CY of concrete needed to install Type 7 ITS cabinets was approved on change order 1. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000; Overrun Quantity Balance 3.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000; Overrun Quantity Balance 3.00.
			Other Item Adjustment	OADJ - Tota Adjustment -	7 Total 1 1 2	2021 Sep 2, 2021 Jun 3, 2021 Jun 3, 2021 Jun 16, 2021 Jun 16,	norton1 SYSTEM SYSTEM SYSTEM	\$6,300.00) \$6,300.00 \$0.00 \$6,090.00 \$210.00 (\$6,300.00)	discovered that AWP was overriding an Item overrun. When I attempted to correct the item overrun AWP would not allow me to do this and paid for the Item overrun in the estimate. I am making line item adjustment to remove the Item overrun override. This Item adjustment is being entered to balance out the user entered line item adjustment on estimate 1. The additional 3.0 CY of concrete needed to install Type 7 ITS cabinets was approved on change order 1. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000; Overrun Quantity Balance 3.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000; Overrun Quantity Balance 3.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000;



Line Item Adjustments by Estimate

Contract ID:190621-F01

		5		0.11							
roject	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks		
			,,	Type			,				
Q3469	0100	BASE, CONCRETE	Overrun	Overrun	4	Jul 16, 2021	SYSTEM	(\$6,300.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
					4	Jul 16, 2021	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000; Overrun Quantity Balance 3.00.		
					5	Aug 2, 2021	SYSTEM	(\$6,300.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
					5	Aug 2, 2021	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000; Overrun Quantity Balance 3.00.		
					6	Aug 16, 2021	SYSTEM	(\$6,300.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
					6	Aug 16, 2021	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 12.000; Overrun Quantity Balance 3.00.		
				Overrun - T	otal			\$0.00			
			Overrun - T	otal				\$0.00			
	0100 -	- Total						\$0.00			
	0130	MISC. ITS	Overrun	Overrun	15	Jan 3, 2022	SYSTEM	(\$1,364.00)			
					17	Feb 1, 2022	SYSTEM	\$1,364.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',62.00000 - 62.00000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - T	otal				\$0.00			
q	0130 -) - Total						\$0.00			
	0230	MISC. ITS	S Overrun	n Overrun	15	Jan 3, 2022	SYSTEM	(\$275.00)			
						Feb 1, 2022	SYSTEM	\$275.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',275.00000 - 275.00000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - T	otal				\$0.00			
	0230 -	- Total						\$0.00			
	0280	MISC. ITS	Overrun	Overrun	Overrun	Overrun	1	Jun 3, 2021	SYSTEM	(\$1,476.00)	
					7 8		SYSTEM	\$1,476.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',18.00000 - 18.00000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - T	otal				\$0.00			
	0280 -	- Total						\$0.00			
	0290	MISC. ITS	Overrun	Overrun	1	Jun 3, 2021	SYSTEM	(\$315.00)			
					7	Sep 1, 2021	SYSTEM	\$315.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',21.00000 - 21.00000, 'is applied (if non-zero).		
			Overrun - Total					\$0.00			
			Overrun - T	otal				\$0.00			
	0290 -	- Total						\$0.00			
	0300	MISC. ITS	Overrun	Overrun	15	Jan 3, 2022	SYSTEM	(\$140.00)			
					17	Feb 1, 2022	SYSTEM	\$140.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.50000 - 3.50000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			

Mar 4, 2022



Line Item Adjustments by Estimate

Contract ID:190621-F01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6Q3469	0300	MISC. ITS	Overrun - T	otal				\$0.00	
	0300 -	Total					\$0.00		
J6Q3469 -	J6Q3469 - Total							\$0.00	
Overall - Total							\$0.00		