

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 15, 2021

Progress Estimate Number	Contract ID	210319-H01	Pay Period Start	September 2, 2021	Original Contract Amount	\$4,800,000.00
7	Prime Contractor	Pace Construction Company, LLC	Pay Period End	September 15, 2021	Net Change Order Amount Current Contract Amount	\$0.00 \$4,800,000.00

Approval Date		By User
September 15, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	ROTHEL
September 16, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	PULLIA
September 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2021	November 1, 2021		41.22%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	No Milestones Exist for Contract	
Acceptance Date			
Awarded Date	April 7, 2021	April 7, 2021	
Letting Date	March 19, 2021	March 19, 2021	
Notice to Proceed Date	May 10, 2021	May 10, 2021	
Work Began Date			

Contract Total Pay For Estimate No. 7										
		This Estimate	Previous	To Date						
210319-H01										
	Total Posted Items Pay	\$271,344.30	\$1,707,040.31	\$1,978,384.61						
	Gross Item Adjustments	(\$124,550.38)	(\$30,047.67)	(\$154,598.05)						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	·		\$1,676,992.64	\$1,823,786.56						
Contract Total Page 1	avable This Estimate:	\$146.793.92								

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9P3458	0040	2072000	LINEAR GRADING CLASS 2	STA	\$550.000	5.1	\$2,805.00
	0800	3040163	TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$10.000	709	\$7,090.00
	0120	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	TONS	\$59.000	2,664.1	\$157,181.90
	0130	4019905	MISC.OPTIONAL FULL DEPTH PAVEMENT	SQYD	\$36.000	708.9	\$25,520.4
	0150	4071005	TACK COAT	GAL	\$2.100	600	\$1,260.0
	0370	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$2,500.000	0.5	\$1,250.0
	0480	8061005	ROCK DITCH CHECK	LF	\$6.250	84	\$525.0
	0650	7034214	CLASS B-2 CONCRETE	CUYD	\$1,820.000	34.4	\$62,608.0
	0700	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$2.400	5,460	\$13,104.0
Project J9P34	58 - Total						\$271,344.3
Overall - Tota							\$271,344.3

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 15, 2021

Progress Estimate Number 7
Prime Contractor
Page Construction Company, LLC
Prime Contractor
Page Period Start
Page Period End
September 2, 2021
Page Period End
September 15, 2021
Page Period End
September 15, 2021
Page Period End
September 15, 2021
Page Period End
September 2, 2021
Page Period End
September 15, 2021
Page Period End
September 2, 2021
Page Period End
September 15, 2021
Page Period End
September 2, 2021
Page Period End
September 2, 2021
Page Period End
September 3, 2021
Page Period

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3458	0800	TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	709	\$0.03	\$21.20
	0120	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,086.5	\$0.43	\$468.19
	0120	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,577.6	\$0.43	\$679.82
	0120	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment	Asphalt Cement Price Adjustment	This Adjustment is being made for the total tons of asphalt laid during this estimate period.			\$4,597.32
	0120	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment		This Adjustment is being made in accordance with Order Record #1 and Order Record #2 for a total of 611.90 tons equaling - \$1284.99, and 1105.80 tons equaling - \$2322.18 for total Asphalt AC price adjustments.			(\$3,607.17)
	0120	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment	Substandard Item	This adjustment is being made for in accordance with Order Record #1 and #2 for Bit Base laid during this estimate period. 1717.7 tons at contract price of \$59.00.			(\$101,344.30)
	0130	MISC.	Other Item Adjustment		This adjustment is being made for the total square yards of asphalt laid during this estimate period.			\$777.84
	0130	MISC.	Other Item Adjustment	Substandard Item	This adjustment is being made in accordance with Order Record #1. This adjustment is removing the AC price adjustment.			(\$777.84)
	0130	MISC.	Other Item Adjustment		This adjustment is in accordance with Order Record #1 for SQYDS of Bit Base laid during this estimate period. 708.9 SQYDS at the contract price of \$36.00			(\$25,520.00)
	0130	MISC.	Other Item Adjustment	Fuel Price	This adjustment is being made for optional pavement installed during this estimate period.			\$154.56
	0150	TACK COAT	Material			-600	\$2.10	(\$1,260.00)
	0150	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.	600	\$2.10	\$1,260.00
	0280	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-2,600	\$2.00	(\$5,200.00)
	0280	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 26 on the current Payment Estimate.	2,600	\$2.00	\$5,200.00
	0480	ROCK DITCH CHECK	Overrun			-84	\$6.25	(\$525.00)
	0480	ROCK DITCH CHECK	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 27 on the current Payment Estimate.	84	\$6.25	\$525.00
	0500	SILT FENCE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-3,961	\$2.50	(\$9,902.50)
	0500	SILT FENCE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item	3,961	\$2.50	\$9,902.50

Revision 4/1/2020 Page 2 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 15, 2021

Progress Estimate Number 7

Contract ID 210319-H01 Pay Period Start September 2, 2021 Original Contract Amount \$4,800,000.00 Pay Period End September 15, 2021 Original Contract Amount \$4,800,000.00 Pay Period End September 15, 2021 Original Contract Amount \$4,800,000.00 Pay Period End September 15, 2021 Original Contract Amount \$4,800,000.00 Pay Period End September 2, 2021 Original Contract Amount \$4,800,000.00 Pay Period End September 2, 2021 Original Contract Amount \$4,800,000.00 Pay Period End September 2, 2021 Original Contract Amount \$4,800,000.00 Pay Period End September 2, 2021 Original Contract Amount \$4,800,000.00 Pay Period End September 2, 2021 Pay Period End September 2,

						urrent Contra	act Amount	\$4,600,000.00
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3458					Adjustment (0007) due to user rothel overridding Payment Estimate Exception 24 on the current Payment Estimate.			
	0660	CURB BLOCKOUT	Material			-388	\$87.00	(\$33,756.00)
	0660	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 11 on the current Payment Estimate.	388	\$87.00	\$33,756.00
	0670	HALF-SOLE REPAIR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 25 on the current Payment Estimate. Material Insufficiency Quantity 2455.000; Overrun Quantity Balance 1455.00.	1,455	\$49.25	\$71,658.75
	0670	HALF-SOLE REPAIR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-1,455	\$49.25	(\$71,658.75)
	0670	HALF-SOLE REPAIR	Material			-2,455	\$49.25	(\$120,908.75)
	0670	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 17 on the current Payment Estimate.	2,455	\$49.25	\$120,908.75
Total								(\$124,550.38)

Revision 4/1/2020 Page 3 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					С	ontract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9P3458	P3458 FAF Resurface and add rumblestripes 160 OZARK from Rte. 5 to Rte. 101						
Γotals by J	Job Number	rs					
J9P3458		l Item Pay Item Adjustme		Item Pay	This Estimate \$271,344.30 (\$124,550.38) \$146,793.92	Previous \$1,707,040.31 (\$30,047.67) \$1,676,992.64	To Date \$1,978,384.61 (\$154,598.05) \$1,823,786.56
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 4 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 4071005, Project Item Line Number 0150, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 4071005, Project Item Line Number 0150, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034001, Project Item Line Number 0380, Material Set 703400196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034001, Project Item Line Number 0380, Material Set 703400196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034001, Project Item Line Number 0380, Material Set 703400196, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034001, Project Item Line Number 0380, Material Set 703400196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034001, Project Item Line Number 0380, Material Set 703400196, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034214, Project Item Line Number 0650, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034214, Project Item Line Number 0650, Material Set 703421496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034214, Project Item Line Number 0650, Material Set 703421496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034600, Project Item Line Number 0660, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034600, Project Item Line Number 0660, Material Set 703460096, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034600, Project Item Line Number 0660, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034600, Project Item Line Number 0660, Material Set 703460096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034600, Project Item Line Number 0660, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7034600, Project Item Line Number 0660, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7040104, Project Item Line Number 0670, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7040104, Project Item Line Number 0670, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7101000, Project Item Line Number 0700, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7101000, Project Item Line Number 0700, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7101000, Project Item Line Number 0700, Material Set 710100096, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7101000, Project Item Line Number 0700, Material Set 710100096, Material 1036RSDFEC42M25 - Rein Steel EC No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3458, Item 7101000, Project Item Line Number 0700, Material Set 710100096, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Item Overrun: Contract 210319-H01, Contract Project J9P3458, Project Item Line Number 0500, Contract Line Item Number 0500, Item 8061019, Minor Item.	No Remark was entered by Engineer	ROTHEL	Overridden

Revision 4/1/2020 Page 5 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Item Overrun: Contract 210319-H01, Contract Project J9P3458, Project Item Line Number 0670, Contract Line Item Number 0670, Item 7040104, Minor Item.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Item Overrun: Contract 210319-H01, Contract Project J9P3458, Project Item Line Number 0280, Contract Line Item Number 0280, Item 6205301B, Minor Item.	No Remark was entered by Engineer	ROTHEL	Overridden
Estimate Exception Type: Item Overrun: Contract 210319-H01, Contract Project J9P3458, Project Item Line Number 0480, Contract Line Item Number 0480, Item 8061005, Minor Item.	No Remark was entered by Engineer	ROTHEL	Overridden

Revision 4/1/2020 Page 6 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted ame Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210319-H01	J9P3458	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$127,339.95	\$127,339.95
		0001	0020	2031000	CLASS A EXCAVATION	45.00	0.00	45.00	CUYD	45.00	\$100.00	\$4,500.00
		0001	0030	2063500	CULVERT CLEANOUT	6.00	0.00	6.00	EA	6.00	\$2,000.00	\$12,000.00
		0001	0040	2072000	LINEAR GRADING CLASS 2	10.30	0.00	10.30	STA	5.10	\$550.00	\$2,805.00
		0001	0050	2129900	MISC.SHOULDER GRADING	1,995.20	0.00	1,995.20	100F	1,575.20	\$390.00	\$614,328.00
		0001	0060	2142000	FURNISHING ROCK FILL	400.00	0.00	400.00	CUYD	0.00	\$1.00	\$0.00
		0001	0070	2143000	PLACING ROCK FILL	400.00	0.00	400.00	CUYD	0.00	\$20.00	\$0.00
		0001	0800	3040163	TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)	1,418.00	0.00	1,418.00	SQYD	709.00	\$10.00	\$7,090.00
		0001	0090	3049907	MISC.TYPE 1 AGGREGATE	607.00	0.00	607.00	CUYD	563.00	\$50.00	\$28,150.00
		0001	0100	3105002	GRAVEL (A) OR CRUSHED STONE (B)	684.00	0.00	684.00	TONS	630.00	\$30.00	\$18,900.00
		0001	0110	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	9,369.60	0.00	9,369.60	TONS	298.80	\$65.00	\$19,422.00
		0001	0120	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	10,501.60	0.00	10,501.60	TONS	4,171.30	\$59.00	\$246,106.70
		0001	0130	4019905	MISC.OPTIONAL FULL DEPTH PAVEMENT	1,417.80	0.00	1,417.80	SQYD	708.90	\$36.00	\$25,520.40
		0001	0140	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	16,444.70	0.00	16,444.70	TONS	0.00	\$63.50	\$0.00
		0001	0150	4071005	TACK COAT	29,839.00	0.00	29,839.00	GAL	950.00	\$2.10	\$1,995.00
		0001	0160	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	2,140.00	0.00	2,140.00	CUYD	0.00	\$1.00	\$0.00
		0001	0170	6096042	PLACING TYPE 2 ROCK DITCH LINER	2,140.00	0.00	2,140.00	CUYD	0.00	\$20.00	\$0.00
		0001	0180	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0190	6161005	CONSTRUCTION SIGNS	2,634.00	0.00	2,634.00	SQFT	539.00	\$4.50	\$2,425.50
		0001	0200	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	6.00	\$60.00	\$360.00
		0001	0210	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$10.25	\$82.00
		0001	0220	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	200.00	\$18.00	\$3,600.00
		0001	0230	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$5,500.00	\$11,000.00
		0001	0240	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$300,000.00	\$225,000.00
		0001	0250	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0260	6200013	COLD APPLIED TAPE PAVEMENT MARKING, 24 IN. WHITE	48.00	0.00	48.00	LF	48.00	\$20.00	\$960.00
		0001	0270	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	11.00	0.00	11.00	EA	0.00	\$270.00	\$0.00
		0001	0280	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,500.00	0.00	1,500.00	LF	4,100.00	\$2.00	\$8,200.00
		0001	0290	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	238,704.00	0.00	238,704.00	LF	0.00	\$0.10	\$0.00
		0001	0300	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT. TYPE P BEADS	219,141.00	0.00	219,141.00	LF	0.00	\$0.10	\$0.00
		0001	0310	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	343.00	0.00	343.00	LF	0.00	\$5.00	\$0.00
		0001	0320	6207001	PAVEMENT MARKING REMOVAL	13,140.00	0.00	13,140.00	LF	6,850.00	\$0.70	\$4,795.00
		0001	0330	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	8,898.00	0.00	8,898.00	SQYD	0.00	\$2.85	\$0.00
		0001	0340	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6,126.00	0.00	6,126.00	SQYD	0.00	\$2.85	\$0.00
		0001	0350	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	6,459.00	0.00	6,459.00	SQYD	0.00	\$2.00	\$0.00
		0001	0360	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,524.10	0.00	1,524.10	STA	0.00	\$20.00	\$0.00
		0001	0370	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$2,500.00	\$1,250.00
		0001	0380	7034001	CLASS B-1 CONCRETE	3.40	0.00	3.40	CUYD	3.40	\$1,000.00	\$3,400.00
		0001	0390	7250312A	12 IN. PIPE GROUP B	3.00	0.00	3.00	LF	3.00	\$50.00	\$150.00
		0001	0400	7250315A	15 IN. PIPE GROUP B	176.00	0.00	176.00	LF	176.00	\$50.00	\$8,800.00
		0001	0410	7250318A	18 IN. PIPE GROUP B	264.00	0.00	264.00	LF	264.00	\$60.00	\$15,840.00
		0001	0420	7250324A	24 IN. PIPE GROUP B	212.00	0.00	212.00	LF	212.00	\$80.00	\$16,960.00
		0001	0430	7250342A	42 IN. PIPE GROUP B	144.00	0.00	144.00	LF	72.00	\$120.00	\$8,640.00
		0001	0440	7250415	15 IN. PIPE GROUP C	1,120.00	0.00	1,120.00	LF	1,088.00	\$40.00	\$43,520.00

Page 7 of 18 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract Project No.	ct Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
19-H01 J9P34	0001	0450	7250418	18 IN. PIPE GROUP C	128.00	0.00	128.00	LF	128.00	\$50.00	\$6,400.00
	0001	0460	7350001	PIPE LINER FOR EXISTING CULVERT	202.00	0.00	202.00	LF	201.00	\$200.00	\$40,200.00
	0001	0470	8051000A	SEEDING - COOL SEASON MIXTURES	45.40	0.00	45.40	ACRE	0.00	\$2,150.00	\$0.00
	0001	0480	8061005	ROCK DITCH CHECK	2,060.00	0.00	2,060.00	LF	6,523.00	\$6.25	\$40,768.75
	0001	0490	8061016	SEDIMENT REMOVAL	191.00	0.00	191.00	CUYD	50.00	\$1.00	\$50.00
	0001	0500	8061019	SILT FENCE	1,900.00	0.00	1,900.00	LF	7,203.00	\$2.50	\$18,007.50
	0010	0510	6061060	MGS GUARDRAIL	2,413.00	0.00	2,413.00	LF	1,738.00	\$22.50	\$39,105.00
	0010	0520	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	6.00	0.00	6.00	EA	4.00	\$2,900.00	\$11,600.00
	0010	0530	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	13.00	0.00	13.00	EA	9.00	\$2,700.00	\$24,300.00
	0010	0540	6063020	TYPE C CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	1.00	\$28,125.00	\$28,125.00
	0030	0550	9029401	TEMPORARY TRAFFIC SIGNALS AND LIGHTING	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
	0040	0560	9031260	WOOD POST, 4 IN. BY 4 IN.	270.00	0.00	270.00	LF	0.00	\$5.00	\$0.0
	0040	0570	9031270A	2 IN. PSST POST - 12 GA.	264.00	0.00	264.00	LF	0.00	\$14.00	\$0.00
	0040	0580	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	66.00	0.00	66.00	LF	0.00	\$40.00	\$0.0
	0040	0590	9035004A	SH-FLAT SHEET	66.00	0.00	66.00	SQFT	0.00	\$36.00	\$0.0
	0070	0600	2024018	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	1.00	0.00	1.00	LF	1.00	\$1,800.00	\$1,800.0
	0070	0610	2161500	REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE	16,669.00	0.00	16,669.00	SQFT	16,669.00	\$0.65	\$10,834.8
	0070	0620	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	153.00	0.00	153.00	LF	153.00	\$405.00	\$61,965.00
	0070	0630	2169903	MISC.Remove and Replace Curb	28.00	0.00	28.00	LF	14.00	\$525.00	\$7,350.0
	0070	0640	6233000	EPOXY POLYMER WEARING SURFACE	1,919.00	0.00	1,919.00	SQYD	0.00	\$41.75	\$0.0
	0070	0650	7034214	CLASS B-2 CONCRETE	68.80	0.00	68.80	CUYD	68.80	\$1,820.00	\$125,216.0
	0070	0660	7034600	CURB BLOCKOUT	775.00	0.00	775.00	LF	388.00	\$87.00	\$33,756.0
	0070	0670	7040104	HALF-SOLE REPAIR	1,000.00	0.00	1,000.00	SQFT	2,455.00	\$49.25	\$120,908.7
	0070	0680	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	0.00	\$62.10	\$0.00
	0070	0690	7040113	CLEANING AND EPOXY COATING	2,769.00	0.00	2,769.00	SQFT	1,385.00	\$6.00	\$8,310.0
	0070	0700	7101000	REINFORCING STEEL (EPOXY COATED)	10,920.00	0.00	10,920.00	LB	10,920.00	\$2.40	\$26,208.0
Duele	10D3458 T	otal Value	Posted to D	ate as of Report Generated Date							\$2,068,044.40

Page 8 of 18 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9P3458

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0040	2072000	LINEAR GRADING CLASS 2	9/13/21	9/15/21	5.10	STA	Rte. 160 @ Bulldog Drive	Log Mi. 195.840		Log Mi. 196.035		
0080	3040163	TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)	9/13/21	9/15/21	709.00	SQYD	Rte. 160 @ Bulldog Drive	Log Mi. 195.840		Log Mi. 196.035		
0120	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	9/13/21	9/15/21	1,086.50	TONS	Rte. 160	Log MI. 195.760		Log Mi. 198.296		
			9/14/21	9/15/21	1,577.60	TONS		Log MI. 198.296		Log MI. 202.302		
0130	4019905	MISC.	9/13/21	9/15/21	708.90	SQYD	Rte. 160 @ Bulldog Drive	Log MI. 195.840		Log Mi. 196.035		
0150	4071005	TACK COAT	9/13/21	9/15/21	300.00	GAL	Rte. 160 Rt	Log Mi. 195.760		Log Mi. 198.296		
			9/14/21	9/15/21	300.00	GAL	Rte. 160	Log Mi. 198.296		Log Mi. 202.302		
0370	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	9/13/21	9/15/21	0.50	LS	Rte. 160	Log Mi. 192.042		Log Mi. 215.517		
0480	8061005	ROCK DITCH CHECK	9/3/21	9/9/21	84.00	LF		Log Mi. 206.000		Log Mi. 215.000		
0650	7034214	CLASS B-2 CONCRETE	9/7/21	9/9/21	17.10	CUYD	Bridge A25012	Log Mi. 194.655		Log Mi. 194.726		
			9/13/21	9/15/21	17.30	CUYD	Bridge #A25012 Bent #1 Expansion Stage #2 Construction	Log Mi. 194.655		Log Mi. 194.726		
0700	7101000	REINFORCING STEEL (EPOXY COATED)	9/7/21	9/9/21	2,730.00	LB	Bridge #A25012	Log Mi. 194.655		Log Mi. 194.726		
			9/13/21	9/15/21	2,730.00	LB	Bridge #A25012 Bent #1 Expansion Stage #2 Construction	Log Mi. 194.655		Log Mi. 194.726		

The information below this line are details for Construction Signs (if applicable).

oject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
3458	0190 June 7, 2021 351		351	CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		192.042 to 215.517		2.0	12			2
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		192.042 to 215.517		2.00	8			1
				GO20-2 48x24 8.00 END ROAD WORK		192.042 to 215.517		2.00	8			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		192.042 to 215.517		2.00	10			:
				GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR		192.042 to 215.517		4.00	8.75			;
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		192.042 to 215.517		4.00	16			
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		192.042 to 215.517		4.00	16			
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		192.042 to 215.517		48.00	1	18x12 Pilot Car in Use Wait and Follow		
				WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS		192.042 to 215.517		4.00	16			
		June 15, 2021	188	WO1-4R 48x48 16.00 REVERSE CURVE (SYMBOL RIGHT ARROW)		Log Mi. 192.042 to 215.517		1.00	16			
				R10-6 24x36 6.00 STOP HERE ON RED (45 DEGREE ARROW		Log Mi. 192.042 to Log Mi. 215.517		2.00	6			
				WO3-3 48x48 16.00 SIGNAL AHEAD (SYMBOL)		Log Mi. 192.042 to 215.517		2.00	16			:
				WO3-1 48x48 16.00 STOP AHEAD (SYMBOL)		Log Mi. 192.042 to Log Mi. 215.517		8.00	16			1:
	0190 - Total											5

Revision 4/1/2020 Page 9 of 18



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J9P3458	0020	CLASS A EXCAVATION	Price FUEL		3	Jul 15, 2021	SYSTEM	\$1.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				\$1.26					
			Price FUEL	- Total				\$1.26					
	0020 -	Total						\$1.26					
	0800	TYPE 1 AGGREGATE FOR BASE (6 IN.	Price FUEL		7	Sep 15, 2021	SYSTEM	\$21.20	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
		THICK)		- Total				\$21.20					
			Price FUEL	- Total				\$21.20					
	0080 -	Total						\$21.20					
	0090	MISC. AGGREGATE FOR BASE	Material		1	Jun 16, 2021	SYSTEM	\$14,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					1	Jun 16, 2021	SYSTEM	(\$14,800.00)					
					2	Jul 1, 2021	SYSTEM	\$28,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					2	Jul 1, 2021	SYSTEM	(\$28,150.00)					
							3	Jul 15, 2021	SYSTEM	\$28,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.		
							3	Jul 15, 2021	SYSTEM	(\$28,150.00)			
							4	Aug 2, 2021	SYSTEM	\$28,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.		
										4	Aug 2, 2021	SYSTEM	(\$28,150.00)
						5	Aug 16, 2021	SYSTEM	\$28,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.			
										5	Aug 16, 2021	SYSTEM	(\$28,150.00)
							6	Sep 2, 2021	SYSTEM	\$28,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					6	Sep 2, 2021	SYSTEM	(\$28,150.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0090 -	Total						\$0.00					
	0100	GRAVEL (A) OR CRUSHED STONE (B)	Material		1	Jun 16, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					1	Jun 16, 2021	SYSTEM	(\$9,000.00)					
							2	Jul 1, 2021	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.		
							3			2	Jul 1, 2021	SYSTEM	(\$18,000.00)
									3	Jul 15, 2021	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	3	3	3	Jul 15, 2021	SYSTEM	(\$18,900.00)			
			4 A	4		4	Aug 2, 2021	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.			
				Aug 2, 2021	SYSTEM	(\$18,900.00)							
					5	Aug 16,	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment				



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
458	0100	GRAVEL (A) OR CRUSHED STONE (B)	Material			2021			Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.			
		(b)			5	Aug 16, 2021	SYSTEM	(\$18,900.00)				
					6	Sep 2, 2021	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					6	Sep 2, 2021	SYSTEM	(\$18,900.00)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0100 -	Total						\$0.00				
	0110	BIT. PAVEMENT MIXTURE PG64-22 (BP-2)	Other Item Adjustment	ACAD	1	Jun 16, 2021	ROTHEL	\$279.00				
		. 60 . 22 (5. 2)			2	Jul 1, 2021	ROTHEL	\$276.77	This Adjustment is being made for 148.8 tons of BP-2 mix laid during this estimate period.			
				ACAD - Tota	al			\$555.77				
				Adjustment -	Total			\$555.77				
			Price FUEL		1	Jun 16, 2021	SYSTEM	\$59.76	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					2	Jul 1, 2021	SYSTEM	\$59.29	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				- Total				\$119.05				
			Price FUEL	- Total				\$119.05				
J	0110 -	Total						\$674.82				
	0120	BITUMINOUS PAVEMENT MIXTURE	Other Item Adjustment	ACAD		Sep 15, 2021	ROTHEL	\$4,597.32	This Adjustment is being made for the total tons of asphalt laid during this estimate period.			
		MIXTURE PG64-22 (BAS					ACAD - Tota	al			\$4,597.32	
				SUBI	7	Sep 15, 2021	ROTHEL	(\$3,607.17)	This Adjustment is being made in accordance with Order Record #1 and Order Record #2 for a total of 611.90 tons equaling - \$1284.99, and 1105.80 tons equaling - \$2322.18 for total Asphalt AC price adjustments.			
					7	Sep 15, 2021	ROTHEL	(\$101,344.30)	This adjustment is being made for in accordance with Order Record #1 and #2 for Bit Base laid during this estimate period. 1717.7 tons at contract price of \$59.00.			
				SUBI - Total				(\$104,951.47)				
			Other Item /	Adjustment -	Total			(\$100,354.15)				
			Price FUEL		7	Sep 15, 2021	SYSTEM	\$1,148.01	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				- Total				\$1,148.01				
			Price FUEL	- Total				\$1,148.01				
J	0120 -							(\$99,206.14)				
	0130	MISC.	Other Item Adjustment	ACAD		Sep 15, 2021	ROTHEL	\$777.84	This adjustment is being made for the total square yards of asphalt laid during this estimate period.			
				ACAD - Tota			DC=:	\$777.84				
				FUEL		Sep 15, 2021	ROTHEL	\$154.56	This adjustment is being made for optional pavement installed during this estimate period.			
				FUEL - Tota				\$154.56				
				SUBI		Sep 15, 2021	ROTHEL	(\$777.84)	This adjustment is being made in accordance with Order Record #1. This adjustment is removing the AC price adjustment.			
					7	Sep 15, 2021	ROTHEL	(\$25,520.00)	This adjustment is in accordance with Order Record #1 for SQYDS of Bit Base laid during this estimate period. 708.9 SQYDS at the contract price of \$36.00			
				SUBI - Total				(\$26,297.84)				
			Other Item /	Adjustment -	Total			(\$25,365.44)				
J	0130 -							(\$25,365.44)				
	0150	TACK COAT	Material		7	Sep 15, 2021	SYSTEM	\$1,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					7	Sep 15, 2021	SYSTEM	(\$1,260.00)				
						2021						



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0150	TACK COAT	Material	Type - Total				\$0.00	
001 0400	0130	TACK COAT	Material - T					\$0.00	
	0150 -	· Total						\$0.00	
	0200	ADVANCED WARNING RAIL SYSTEM	Material		1	Jun 16, 2021	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$360.00)	
					2	Jul 1, 2021	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$360.00)	
					3	Jul 15, 2021	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$360.00)	
					4	Aug 2, 2021	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$360.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0200 -	Total						\$0.00	
	0210	FLAG ASSEMBLY	Material		1	Jun 16, 2021	SYSTEM	\$82.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$82.00)	
					2	Jul 1, 2021	SYSTEM	\$82.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$82.00)	
					3	Jul 15, 2021	SYSTEM	\$82.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user rothel overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$82.00)	
					4 Aug 2, SYSTEM \$82.00 This adjustment offsets the or Estimate Item Adjustment (00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user rothel overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					4	Aug 2, 2021	SYSTEM	(\$82.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0210 -	Total						\$0.00	
	0220	CHANNELIZER (TRIM LINE)	CHANNELIZER Material		1	Jun 16, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 5 on the current Payment Estimate.
				1	Jun 16, 2021	SYSTEM	(\$3,600.00)		
					2	Jul 1, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user rothel overridding Payment Estimate Exception 5 on the current Payment Estimate.
				2	Jul 1, 2021	SYSTEM	(\$3,600.00)		
					3	Jul 15, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user rothel overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$3,600.00)	



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks								
			Туре	Adjustment Type	Number	Date	Ву										
J9P3458	0220	CHANNELIZER (TRIM LINE)	Material		4	Aug 2, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 5 on the current Payment Estimate.								
					4	Aug 2, 2021	SYSTEM	(\$3,600.00)									
				- Total				\$0.00									
			Material - T	otal				\$0.00									
	0220 -	· Total						\$0.00									
	0230	CMS W/O COMMUNICATION INTERFACE,	Material		1	Jun 16, 2021	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate.								
		CONT F/			1	Jun 16, 2021	SYSTEM	(\$11,000.00)									
					2	Jul 1, 2021	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate.								
					2	Jul 1, 2021	SYSTEM	(\$11,000.00)									
					3	Jul 15, 2021	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate.								
					3	Jul 15, 2021	SYSTEM	(\$11,000.00)									
								4	Aug 2, 2021	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					4	Aug 2, 2021	SYSTEM	(\$11,000.00)									
				- Total				\$0.00									
			Material - T	otal				\$0.00									
	0230 -	· Total						\$0.00									
	0280	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	Material		1	Jun 16, 2021	SYSTEM	\$4,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate.								
		114.,											1	L 40	OVOTERA		
						Jun 16, 2021	SYSTEM	(\$4,350.00)									
					2		SYSTEM	(\$4,350.00) \$4,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate.								
						2021 Jul 1,		, , ,	Estimate Item Adjustment (0016) due to user rothel overridding Payment								
					2	Jul 1, 2021 Jul 1,	SYSTEM	\$4,350.00	Estimate Item Adjustment (0016) due to user rothel overridding Payment								
					2	2021 Jul 1, 2021 Jul 1, 2021 Jul 15,	SYSTEM	\$4,350.00 (\$4,350.00)	Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment								
					2 2 3	2021 Jul 1, 2021 Jul 1, 2021 Jul 15, 2021 Jul 15,	SYSTEM SYSTEM	\$4,350.00 (\$4,350.00) \$4,350.00	Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment								
					2 2 3 3	2021 Jul 1, 2021 Jul 1, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM	\$4,350.00 (\$4,350.00) \$4,350.00 (\$4,350.00)	Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment								
					2 2 3 3 4	2021 Jul 1, 2021 Jul 1, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,350.00 (\$4,350.00) \$4,350.00 (\$4,350.00) \$4,350.00	Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment								
					2 2 3 3 4	2021 Jul 1, 2021 Jul 1, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,350.00 (\$4,350.00) \$4,350.00 (\$4,350.00) \$4,350.00	Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment								
				- Total	2 2 3 3 4 4 5	2021 Jul 1, 2021 Jul 1, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,350.00 (\$4,350.00) \$4,350.00 (\$4,350.00) \$4,350.00 (\$4,350.00) \$8,200.00	Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment								
			Material - T		2 2 3 3 4 4 5	2021 Jul 1, 2021 Jul 1, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,350.00 (\$4,350.00) \$4,350.00 (\$4,350.00) \$4,350.00 (\$4,350.00) \$8,200.00	Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment								
			Material - T		2 2 3 4 4 5	2021 Jul 1, 2021 Jul 1, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,350.00 (\$4,350.00) \$4,350.00 (\$4,350.00) \$4,350.00 (\$4,350.00) \$8,200.00 (\$8,200.00)	Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment								
				otal	2 2 3 4 4 5	2021 Jul 1, 2021 Jul 1, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,350.00 (\$4,350.00) \$4,350.00 (\$4,350.00) \$4,350.00 (\$4,350.00) \$8,200.00 \$0.00	Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 2175.000;								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0280	TEMPORARY REMOVABLE	Overrun	Overrun	2	Jul 1, 2021	SYSTEM	(\$1,350.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
		MARKING TAPE 4 IN.,			2	Jul 1, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception 17 on the current Payment Estimate. Material Insufficiency Quantity 2175.000; Overrun Quantity Balance 675.00.
					3	Jul 15, 2021	SYSTEM	(\$1,350.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Jul 15, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 2175.000; Overrun Quantity Balance 675.00.
					4	Aug 2, 2021	SYSTEM	(\$1,350.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	Aug 2, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 39 on the current Payment Estimate. Material Insufficiency Quantity 2175.000; Overrun Quantity Balance 675.00.
					5	Aug 16, 2021	SYSTEM	(\$1,350.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Aug 16, 2021	SYSTEM	\$3,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 26 on the current Payment Estimate. Material Insufficiency Quantity 4100.000; Overrun Quantity Balance 2600.00.
					5	Aug 16, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 26 on the current Payment Estimate. Material Insufficiency Quantity 4100.000; Overrun Quantity Balance 2600.00.
					5	Aug 16, 2021	SYSTEM	(\$3,850.00)	
					6	Sep 2, 2021	SYSTEM	(\$5,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Sep 2, 2021	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user rothel overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Sep 15, 2021	SYSTEM	(\$5,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Sep 15, 2021	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 26 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
	0280 -	Total	Overrun - T	otai				\$0.00 \$0.00	
	0380	CLASS B-1 CONCRETE	Material		1	Jun 16, 2021	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user rothel overridding Payment Estimate Exception 8 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$1,300.00)	
					2	Jul 1, 2021	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user rothel overridding Payment Estimate Exception 8 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$3,400.00)	
					3	Jul 15, 2021	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user rothel overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$3,400.00)	
					4	Aug 2, 2021	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$3,400.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0380 -	Total						\$0.00	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0460	PIPE LINER FOR EXISTING CULVERT	Material	,,	3	Jul 15, 2021	SYSTEM	\$40,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user rothel overridding Payment Estimate Exception 16 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$40,200.00)	
					4	Aug 2, 2021	SYSTEM	\$40,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user rothel overridding Payment Estimate Exception 36 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$40,200.00)	
					5	Aug 16, 2021	SYSTEM	\$40,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 24 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$40,200.00)	
					6	Sep 2, 2021	SYSTEM	\$40,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$40,200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0460 -	Total						\$0.00	
	0480	ROCK DITCH CHECK	Material		2	Jul 1, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user rothel overridding Payment Estimate Exception 16 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$1,600.00)	
					3	Jul 15, 2021	SYSTEM	\$25,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 17 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$25,950.00)	
					4	Aug 2, 2021	SYSTEM	\$40,243.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 37 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$40,243.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	3	Jul 15, 2021	SYSTEM	\$8,331.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00.
					3	Jul 15, 2021	SYSTEM	\$2,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00.
					3	Jul 15, 2021	SYSTEM	\$1,993.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00.
					3	Jul 15, 2021	SYSTEM	(\$13,075.00)	
					4	Aug 2, 2021	SYSTEM	(\$13,075.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	Aug 2, 2021	SYSTEM	\$5,981.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00.
					4	Aug 2, 2021	SYSTEM	\$8,312.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00.
					4	Aug 2, 2021	SYSTEM	\$13,075.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000;



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0480	ROCK DITCH	Overrun	Overrun					Overrun Quantity Balance 4379.00.
		CHECK			4	Aug 2, 2021	SYSTEM	(\$14,293.75)	
					5	Aug 16, 2021	SYSTEM	(\$27,368.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Sep 15, 2021	SYSTEM	\$525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Sep 15, 2021	SYSTEM	(\$525.00)	
				Overrun - T	otal			(\$27,368.75)	
			Overrun - T	otal				(\$27,368.75)	
	0480 -	Total						(\$27,368.75)	
	0500	SILT FENCE	Material		3	Jul 15, 2021	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user rothel overridding Payment Estimate Exception 18 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$4,890.00)	
					4	Aug 2, 2021	SYSTEM	\$8,105.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 38 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$8,105.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Overrun	Overrun	3	Jul 15, 2021	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000; Overrun Quantity Balance 56.00.
					3	Jul 15, 2021	SYSTEM	(\$140.00)	
					4	Aug 2, 2021	SYSTEM	(\$140.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	Aug 2, 2021	SYSTEM	\$3,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00.
					4	Aug 2, 2021	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00.
					4	Aug 2, 2021	SYSTEM	(\$3,215.00)	
					5	Aug 16, 2021	SYSTEM	(\$3,355.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Sep 2, 2021	SYSTEM	\$9,902.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 28 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$9,902.50)	
					7	Sep 15, 2021	SYSTEM	(\$9,902.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Sep 15, 2021	SYSTEM	\$9,902.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 24 on the current Payment Estimate.
				Overrun - T	otal			(\$3,355.00)	
			Overrun - T	otal				(\$3,355.00)	
	0500 -	Total						(\$3,355.00)	
	0650	CLASS B-2 CONCRETE	Material		4	Aug 2, 2021	SYSTEM	\$62,608.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user rothel overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$62,608.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J9P3458	0650	CLASS B-2 CONCRETE	Material - To	otal				\$0.00					
	0650 -	Total						\$0.00					
	0660	CURB BLOCKOUT	Material		4	Aug 2, 2021	SYSTEM	\$33,756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user rothel overridding Payment Estimate Exception 21 on the current Payment Estimate.				
					4	Aug 2, 2021	SYSTEM	(\$33,756.00)					
					5	Aug 16, 2021	SYSTEM	\$33,756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 12 on the current Payment Estimate.				
					5	Aug 16, 2021	SYSTEM	(\$33,756.00)					
					6	Sep 2, 2021	SYSTEM	\$33,756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 11 on the current Payment Estimate.				
					6	Sep 2, 2021	SYSTEM	(\$33,756.00)					
					7	Sep 15, 2021	SYSTEM	\$33,756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 11 on the current Payment Estimate.				
					7	Sep 15, 2021	SYSTEM	(\$33,756.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0660 -	Total						\$0.00					
	0670	HALF-SOLE REPAIR	Material		2	Jul 1, 2021	SYSTEM	\$35,952.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user rothel overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					2	Jul 1, 2021	SYSTEM	(\$35,952.50)					
					3	Jul 15, 2021	SYSTEM	\$35,952.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user rothel overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					3	Jul 15, 2021	SYSTEM	(\$35,952.50)					
					4	Aug 2, 2021	SYSTEM	\$35,952.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user rothel overridding Payment Estimate Exception 29 on the current Payment Estimate.				
									4	Aug 2, 2021	SYSTEM	(\$35,952.50)	
					6	Sep 2, 2021	SYSTEM	\$120,908.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user rothel overridding Payment Estimate Exception 17 on the current Payment Estimate.				
				6	6	Sep 2, 2021	SYSTEM	(\$120,908.75)					
						7	Sep 15, 2021	SYSTEM	\$120,908.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 17 on the current Payment Estimate.			
					7	Sep 15, 2021	SYSTEM	(\$120,908.75)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
									6	Sep 2, 2021	SYSTEM	\$71,658.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 2455.000; Overrun Quantity Balance 1455.00.
					6	Sep 2, 2021	SYSTEM	(\$71,658.75)					
					7	Sep 15, 2021	SYSTEM	(\$71,658.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
					7	Sep 15, 2021	SYSTEM	\$71,658.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 25 on the current Payment Estimate. Material Insufficiency Quantity 2455.000; Overrun Quantity Balance 1455.00.				





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0670	HALF-SOLE	Overrun	Overrun - T	otal			\$0.00	
		REPAIR	Overrun - T	otal				\$0.00	
	0670 -	Total						\$0.00	
	0690	CLEANING AND EPOXY COATING	Material		4	Aug 2, 2021	SYSTEM	\$8,310.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user rothel overridding Payment Estimate Exception 30 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$8,310.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0690 -	Total						\$0.00	
	0700	REINFORCING STEEL (EPOXY COATED)	Material		4	Aug 2, 2021	SYSTEM	\$13,104.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user rothel overridding Payment Estimate Exception 31 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$13,104.00)	
					5	Aug 16, 2021	SYSTEM	\$13,104.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$13,104.00)	
					6	Sep 2, 2021	SYSTEM	\$13,104.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 21 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$13,104.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0700 -	Total						\$0.00	
J9P3458 -	Total							(\$154,598.05)	
Overall -	Total							(\$154,598.05)	