

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 2, 2021

Progress Estimate Number	Contract ID	210416-F02	Pay Period Start	November 16, 2021	Original Contract Amou	unt\$12,888,486.49
10	Prime Contractor	Gershenson Construction Co., Inc.	Pay Period End	d December 1, 2021	Net Change Order Amount Current Contract Amou	\$56,981.50 Int \$12,945,467.99
Approval Date						Bylleer

By User				e	Approval Date			
Aubucj	d Draft) at the Project Office Level by	nber 2, 2021 Generated and Approved (and should be considered Draft) at the Project Office Level I						
janssm	December 3, 2021 Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by							
ramses1	tral Office Controllers Office Level by	Reviewed and Approved at the Central Office Controllers Office Lev						
unt Complete	% of Current Contract Amou	Actual Completion Date	Current Completion Date	ompletion Date	Original Completic			
	11.78%		September 1, 2023	nber 1, 2023	September 1, 2023			

	Contract Informational Dates									
Date Description	No Milestones Exist for Contract									
Acceptance Date										
Awarded Date	May 5, 2021	May 5, 2021								
Letting Date	April 16, 2021	April 16, 2021								
Notice to Proceed Date	July 6, 2021	July 6, 2021								
Work Began Date	July 7, 2021	July 7, 2021								

Contract Total P	ay For Estimate No. 10			
		This Estimate	Previous	To Date
210416-F02				
	Total Posted Items Pay	\$314,862.01	\$1,210,449.39	\$1,525,311.40
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$1,210,449.39	\$1,525,311.40
Contract Total P	avable This Estimate:	\$314 862 01		

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3048	0030	2071000	LINEAR GRADING CLASS 1	STA	\$10,515.060	0.38	\$3,995.72
	0040	2072000	LINEAR GRADING CLASS 2	STA	\$383.920	2.2	\$844.62
	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$7.000	1,362.3	\$9,536.10
	0180	6081012	TRUNCATED DOMES	SQFT	\$22.230	30	\$666.90
	0200	6085008	PAVED APPROACH, 8 IN.	SQYD	\$61.480	601.3	\$36,967.92
	0220	6086007	CONCRETE SIDEWALK, 7 IN.	SQYD	\$55.620	16.1	\$895.48
	0240	6089902	MISC.CONCRETE CURB RAMP, CORAL COLOR	EA	\$1,897.700	6	\$11,386.20
	0270	6089905	MISC.CONCRETE SIDEWALK, 4 IN., CORAL COLOR	SQYD	\$45.270	545	\$24,672.15
	0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$31.970	115.5	\$3,692.54
	0310	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	LF	\$20.780	8	\$166.24
	0390	6119905	MISC.SLOPE PROTECTION, CORAL COLOR	SQYD	\$101.870	13.3	\$1,354.87
	0511	6181000	MOBILIZATION	LS	\$764,077.280	0.25	\$191,019.32
	0740	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$40,000.000	0.019	\$760.00
	1460	9029100	BASE, CONCRETE	CUYD	\$1,350.000	3.52	\$4,752.00
	5002	6081012	TRUNCATED DOMES	SQFT	\$24.230	70	\$1,696.10
	5004	6089905	MISC.Misc. Concrete Sidewalk, 7 IN. Coral Color	SQYD	\$63.000	199.9	\$12,593.70
	5005	6091052	CURB AND GUTTER TYPE B	LF	\$31.970	146	\$4,667.62

Revision 4/1/2020 Page 1 of 23



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 2, 2021

Pay Period **Progress Estimate** November 16, **Contract ID** 210416-F02 Original Contract Amount \$12,888,486.49 2021 Start Number Prime Gershenson Construction Co., Net Change Order 10 Pay Period End December 1, 2021 \$56,981.50 Contractor Amount Current Contract Amount \$12,945,467.99

Project Number	,		Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J6S3048	5006	6099903	MISC.Integral Curb (6 IN Height and Under), Type A, Coral Color	LF	\$21.780	238.5	\$5,194.53			
Project J6S30	Project J6S3048 - Total									
Overall - Tota	overall - Total									

#### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3048	0050	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	Material			-51.8	\$12.00	(\$621.60)
	0050	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.	51.8	\$12.00	\$621.60
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-8,534.5	\$7.00	(\$59,741.50)
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.	8,534.5	\$7.00	\$59,741.50
	0200	PAVED APPROACH, 8 IN.	Material			-3,009.9	\$61.48	(\$185,048.65)
	0200	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 5 on the current Payment Estimate.	3,009.9	\$61.48	\$185,048.65
	0210	CONCRETE SIDEWALK, 4 IN.	Material			-809.8	\$38.80	(\$31,420.24)
	0210	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate.	809.8	\$38.80	\$31,420.24
	0220	CONCRETE SIDEWALK, 7 IN.	Material			-75	\$55.62	(\$4,171.50)
	0220	CONCRETE SIDEWALK, 7 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 9 on the current Payment Estimate.	75	\$55.62	\$4,171.50
	0230	MISC.	Material			-7	\$1,400.00	(\$9,800.00)
	0230	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate.	7	\$1,400.00	\$9,800.00
	0310	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-94	\$20.78	(\$1,953.32)
	0310	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user aubucj	94	\$20.78	\$1,953.32

Revision 4/1/2020 Page 2 of 23



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 2, 2021

Pay Period Start **Progress Estimate** November 16, Original Contract Amount \$12,888,486.49 **Contract ID** 210416-F02 2021 Number Prime Gershenson Construction Co., Net Change Order 10 Pay Period End December 1, 2021 \$56,981.50 Contractor Amount Current Contract Amount \$12,945,467.99

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3048					overridding Payment Estimate Exception 26 on the current Payment Estimate.			
	0390	MISC.	Material			-44.47	\$101.87	(\$4,530.16
	0390	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 34 on the current Payment Estimate.	44.47	\$101.87	\$4,530.16
	1460	BASE, CONCRETE	Material			-7.92	\$1,350.00	(\$10,692.00
	1460	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 38 on the current Payment Estimate.	7.92	\$1,350.00	\$10,692.00
	5004	MISC.	Material			-595.5	\$63.00	(\$37,516.50
	5004	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user aubucj overridding Payment Estimate Exception 18 on the current Payment Estimate.	595.5	\$63.00	\$37,516.50
	5005	CURB AND GUTTER TYPE B	Material			-917.7	\$31.97	(\$29,338.87
	5005	CURB AND GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 24 on the current Payment Estimate.	917.7	\$31.97	\$29,338.87
	5006	MISC.	Material			-679.65	\$21.78	(\$14,802.78
	5006	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user aubucj overridding Payment Estimate Exception 29 on the current Payment Estimate.	679.65	\$21.78	\$14,802.78
otal								\$0.0

Revision 4/1/2020 Page 3 of 23



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Cor	ntract Project Informati	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3048	FAF- S500(34)	ADA, signals & entrance improvements	180	ST LOUIS	from Pennridge Drive to I-17	0	
Γotals by J	Job Numbe	rs					
J6S3048		d Item Pay Item Adjustme		Item Pay	This Estimate \$314,862.01 \$0.00 \$314,862.01	Previous \$1,210,449.39 \$0.00 \$1,210,449.39	<b>To Date</b> \$1,525,311.40 \$0.00 <b>\$1,525,311.40</b>
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 4 of 23



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

**Exceptions (Discrepancies) This Estimate Period** 

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 3040183, Project Item Line Number 0050, Material Set 304018396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed Concrete, Acceptance Action Generic 1007RCBT1T5 is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086004, Project Item Line Number 0210, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086007, Project Item Line Number 0220, Material Set 608600796, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086007, Project Item Line Number 0220, Material Set 608600796, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086007, Project Item Line Number 0220, Material Set 608600796, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086007, Project Item Line Number 0220, Material Set 608600796, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089902, Project Item Line Number 0230, Material Set 608990296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089902, Project Item Line Number 0230, Material Set 608990296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089902, Project Item Line Number 0230, Material Set 608990296, Material 0501CCB1 - Concrete, Class B-1 No Air, Acceptance Action Generic 0501CCB1 is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 0270, Material Set 6089905, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 0270, Material Set 6089905, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 5004, Material Set 608990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 5004, Material Set 608990596, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 5004, Material Set 608990596, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 5004, Material Set 608990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6091010, Project Item Line Number 0290, Material Set 609101096, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6091010, Project Item Line Number 0290, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6091052, Project Item Line Number 5005, Material Set 609105296, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden

Revision 4/1/2020 Page 5 of 23



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

**Exceptions (Discrepancies) This Estimate Period** 

Exceptions / Discrepencies	Explanation	Entered By	Status
Generic 0501CCPA.A is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6091052, Project Item Line Number 5005, Material Set 609105296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6092011, Project Item Line Number 0310, Material Set 609201196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6092011, Project Item Line Number 0310, Material Set 609201196, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6092011, Project Item Line Number 0310, Material Set 609201196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 1036RSDFEC28M13 - Rein Steel EC No. 4/M13 Gr 40/M280 @, Acceptance Action Generic ReSteelBars is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6119905, Project Item Line Number 0390, Material Set 6119905, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6119905, Project Item Line Number 0390, Material Set 6119905, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6119905, Project Item Line Number 0390, Material Set 6119905, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6119905, Project Item Line Number 0390, Material Set 6119905, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 9029100, Project Item Line Number 1460, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/02/21	Aubucj	Overridden

Revision 4/1/2020 Page 6 of 23



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
210416-F02	J6S3048	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	Qty	\$895,794.32	\$179,158.86
		0001	0020	2063000	CLASS 3 EXCAVATION	222.00	0.00	222.00	CUYD	0.00	\$20.00	\$0.00
		0001	0030	2071000	LINEAR GRADING CLASS 1	25.00	0.00	25.00	STA	3.73	\$10,515.06	\$39,221.17
		0001	0040	2072000	LINEAR GRADING CLASS 2	320.50	0.00	320.50	STA	75.61	\$383.92	\$29,028.19
		0001	0050	3040183	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	2,721.00	0.00	2,721.00	SQYD	51.80	\$12.00	\$621.60
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	33,892.00	0.00	33,892.00	SQYD	8,728.90	\$7.00	\$61,102.30
		0001	0070	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	704.70	0.00	704.70	TONS	8.00	\$160.00	\$1,280.00
		0001	0080	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	38,263.90	0.00	38,263.90	TONS	0.00	\$85.50	\$0.00
		0001	0090	4079912	MISC.HARD PENETRATION ASPHALT EMULSION (SS1-VH)	28,179.00	0.00	28,179.00	GAL	0.00	\$2.55	\$0.00
		0001	0100	5021310	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT.	697.10	0.00	697.10	SQYD	0.00	\$82.21	\$0.00
		0001	0110	6039902	JOINTS) WATER	40.00	0.00	40.00	EA	0.00	\$350.00	\$0.00
		0001	0120	6039902	WATER	40.00	0.00	40.00	EA	0.00	\$250.00	\$0.00
		0001	0130	6042010	ADJUSTING MANHOLE	65.00	0.00	65.00	EA	0.00	\$557.35	\$0.00
		0001	0140	6042020	ADJUSTING BASIN OR INLET	28.00	0.00	28.00	EA	0.00	\$463.02	\$0.00
		0001	0150	6044011	PIPE COLLAR, TYPE A	2.00	0.00	2.00	EA	0.00	\$1,033.78	\$0.00
		0001	0160	6049902	MISC.CONVERT INLET TO MANHOLE	5.00	0.00	5.00	EA	0.00	\$1,550.84	\$0.00
		0001	0170	6071060	PEDESTRIAN FENCE (STRUCTURES)	36.00	0.00	36.00	LF	0.00	\$157.87	\$0.00
		0001	0180	6081012	TRUNCATED DOMES	4,984.00	-2,240.00	2,744.00	SQFT	218.00	\$22.23	\$4,846.14
		0001	0190	6083006	6 IN. CONCRETE MEDIAN STRIP	989.00	0.00	989.00	SQYD	12.10	\$58.92	\$712.93
		0001	0200	6085008	PAVED APPROACH, 8 IN.	11,544.40	0.00	11,544.40	SQYD	3,167.90	\$61.48	\$194,762.49
		0001	0210	6086004	CONCRETE SIDEWALK, 4 IN.	9,752.20	0.00	9,752.20	SQYD	809.80	\$38.80	\$31,420.24
		0001	0220	6086007	CONCRETE SIDEWALK, 7 IN.	1,849.90	0.00	1,849.90	SQYD	111.40	\$55.62	\$6,196.07
		0001	0230	6089902	MISC.CONCRETE CURB RAMP	97.00	0.00	97.00	EA	7.00	\$1,400.00	\$9,800.00
		0001	0240	6089902	MISC.CONCRETE CURB RAMP, CORAL COLOR	128.00	0.00	128.00	EA	28.00	\$1,897.70	\$53,135.60
		0001	0250	6089905	MISC.CONCRETE SIDEWALK REPAIR, 4 IN.	80.00	0.00	80.00	SQYD	0.00	\$62.33	\$0.00
		0001	0260	6089905	MISC.CONCRETE SIDEWALK REPAIR, 4 IN., CORAL COLOR	80.00	0.00	80.00	SQYD	0.00	\$66.41	\$0.00
		0001	0270	6089905	MISC.CONCRETE SIDEWALK, 4 IN., CORAL COLOR	8,608.30	-750.00	7,858.30	SQYD	4,059.60	\$45.27	\$183,778.09
		0001	0280	6089905	MISC.SIDEWALK GRINDING	15.00	0.00	15.00	SQYD	0.00	\$50.00	\$0.00
		0001	0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	10,374.00	-6,950.00	3,424.00	LF	572.83	\$31.97	\$18,313.38
		0001	0300	6091041	CONCRETE GUTTER TYPE A	9.00	0.00	9.00	LF	0.00	\$100.00	\$0.00
		0001	0310	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	3,437.00	0.00	3,437.00	LF	163.00	\$20.78	\$3,387.14
		0001	0320	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	117.00	0.00	117.00	LF	0.00	\$21.38	\$0.00
		0001	0330	6092031	CONCRETE CURB LOW PROFILE TYPE E	34.00	0.00	34.00	LF	0.00	\$20.00	\$0.00
		0001	0340	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	92.00	0.00	92.00	CUYD	0.00	\$47.96	\$0.00
		0001	0350	6096042	PLACING TYPE 2 ROCK DITCH LINER	92.00	0.00	92.00	CUYD	0.00	\$54.42	\$0.00
		0001	0360	6099903	MISC.LANDSCAPE CURB	343.00	0.00	343.00	LF	0.00	\$98.77	\$0.00
		0001	0370	6099903	MISC.SLOTTED INTEGRAL CURB	364.00	0.00	364.00	LF	0.00	\$19.88	\$0.00
		0001	0380	6116010A	SLOPE PROTECTION	955.00	0.00	955.00	SQYD	0.00	\$91.62	\$0.00
		0001	0390	6119905	MISC.SLOPE PROTECTION, CORAL COLOR	795.00	0.00	795.00	SQYD	44.47	\$101.87	\$4,530.16
		0001	0400	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	179.10	0.00	179.10	SQYD	0.00	\$271.30	\$0.00
		0001	0410	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	179.00	0.00	179.00	SQYD	0.00	\$5.00	\$0.00
		0001	0420	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	179.00	0.00	179.00	SQYD	0.00	\$11.00	\$0.00
		0001	0430	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,378.00	0.00	1,378.00	LF	0.00	\$6.00	\$0.00
		0001	0440	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION)	320.00	0.00	320.00	EA	0.00	\$5.98	\$0.00
		0001	0450	6141120	FOR FULL DEPTH PAVEMENT REPAIR  CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X	5.00	0.00	5.00	EA	0.00	\$923.77	\$0.00
		5551			600MM)			2.30		2.30		11.00

Revision 4/1/2020 Page 7 of 23



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and valu	es are b	ased on R	eport Generated date and can differ from the posted am	ount at the	time the E	stimate was	Genera	itea.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-F02	J6S3048	0001	0460	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	3.00	0.00	3.00	EA	0.00	\$1,154.78	\$0.00
		0001	0470	6143010	MANHOLE FRAME AND COVER, TYPE 1-A	6.00	0.00	6.00	EA	0.00	\$320.26	\$0.00
		0001	0480	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$239,762.00	\$119,881.00
		0001	0490	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED/RETAINED	6.00	0.00	6.00	EA	2.00	\$3,200.00	\$6,400.00
		0001	0500	6179903	MISC.CONCRETE TRAFFIC BARRIER, TYPE C (PERFORATED)	665.00	0.00	665.00	LF	0.00	\$132.86	\$0.00
		0001	0510	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$844,409.28	\$0.00
		0001	0511	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.50	\$764,077.28	\$382,038.64
		0001	0520	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0530	6191000	PAVEMENT EDGE TREATMENT	28,023.00	0.00	28,023.00	LF	0.00	\$1.29	\$0.00
		0001	0540	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	4,710.00	0.00	4,710.00	LF	0.00	\$6.00	\$0.00
		0001	0550	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE	46.00	0.00	46.00	LF	0.00	\$11.00	\$0.00
		0001	0560	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	3,702.00	0.00	3,702.00	LF	0.00	\$17.00	\$0.00
		0001	0570	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	154.00	0.00	154.00	LF	0.00	\$18.00	\$0.00
		0001	0580	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	315.00	0.00	315.00	EA	0.00	\$270.00	\$0.00
		0001	0590	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	38.00	0.00	38.00	EA	0.00	\$25.00	\$0.00
		0001	0600	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	24.00	0.00	24.00	EA	0.00	\$40.00	\$0.00
		0001	0610	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	1,356.00	0.00	1,356.00	EA	0.00	\$180.00	\$0.00
		0001	0620	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	685.00	0.00	685.00	EA	0.00	\$50.00	\$0.00
		0001	0630	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	74,277.00	0.00	74,277.00	LF	0.00	\$0.17	\$0.00
		0001	0640	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	107,464.00	0.00	107,464.00	LF	0.00	\$0.22	\$0.00
		0001	0650	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	208.00	0.00	208.00	LF	0.00	\$1.00	\$0.00
		0001	0660	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,029.00	0.00	2,029.00	LF	0.00	\$2.00	\$0.00
		0001	0670	6207001	PAVEMENT MARKING REMOVAL	23,067.00	0.00	23,067.00	LF	0.00	\$0.75	\$0.00
		0001	0680	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	31.00	0.00	31.00	EA	0.00	\$50.00	\$0.00
		0001	0690	6209902	MISC.18 IN. WHITE ISLAND TUBULAR MARKIER	172.00	0.00	172.00	EA	0.00	\$52.80	\$0.00
		0001	0700	6209902	MISC.18 IN. YELLOW ISLAND TUBULAR MARKER	155.00	0.00	155.00	EA	0.00	\$52.80	\$0.00
		0001	0710	6209903	MISC.PREFORMED THERMOPLASTIC PAVEEMNT MARKING, 6 IN. YELLOW	1,061.00	0.00	1,061.00	LF	0.00	\$6.00	\$0.00
		0001	0720	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	281,790.00	0.00	281,790.00	SQYD	0.00	\$1.33	\$0.00
		0001	0730	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	276.00	0.00	276.00	SQYD	0.00	\$3.50	\$0.00
		0001	0740	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.19	\$40,000.00	\$7,600.00
		0001	0750	7039903	MISC.SPECIAL GUTTER RETAINING WALL	435.00	0.00	435.00	LF	0.00	\$102.84	\$0.00
		0001	0760	7209904	MISC.SMALL BLOCK RETAINING WALL	606.00	0.00	606.00	SQFT	0.00	\$67.83	\$0.00
		0001	0770	7261012	12 IN. PIPE GROUP A	32.00	0.00	32.00	LF	0.00	\$167.61	\$0.00
		0001	0780	7261018	18 IN. PIPE GROUP A	26.00	0.00	26.00	LF	0.00	\$198.93	\$0.00
		0001	0790	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	5.00	0.00	5.00	FT	0.00	\$623.31	\$0.00
		0001	0800	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	20.00	0.00	20.00	FT	0.00	\$366.12	\$0.00
		0001	0810	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	10.00	0.00	10.00	FT	0.00	\$467.70	\$0.00
		0001	0820	7319902	MISC.SPECIAL DRAINAGE STRUCTURE	3.00	0.00	3.00	EA	0.00	\$5,183.98	\$0.00
		0001	0830	7319913	MISC.DOUBLE CURB INLET	10.00	0.00	10.00	FT	0.00	\$825.48	\$0.00
		0001	0840	8031000A	TURF TYPE TALL FESCUE SODDING	9,697.00	0.00	9,697.00	SQYD	1,005.00	\$9.50	\$9,547.50
		0001	0850		SEEDING - COOL SEASON MIXTURES	0.30	0.00	0.30	ACRE	0.00	\$9,680.00	\$0.00
		0001	0860	8061005	ROCK DITCH CHECK	40.00	0.00	40.00	LF	0.00	\$12.00	\$0.00
		0001	0870	8061007A	CURB INLET CHECK	335.00	0.00	335.00	EA	0.00	\$95.00	\$0.00

Page 8 of 23 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-F02	J6S3048	0001	0880	8061016	SEDIMENT REMOVAL	450.00	0.00	450.00	CUYD	0.00	\$1.00	\$0.00
		0001	0890	8061017	TEMPORARY SEEDING AND MULCHING	0.30	0.00	0.30	ACRE	0.00	\$4,840.00	\$0.00
		0001	0900	8061019	SILT FENCE	11,135.00	0.00	11,135.00	LF	0.00	\$2.95	\$0.00
		0001	0910	8064138	TYPE 2D EROSION CONTROL BLANKET	1,528.00	0.00	1,528.00	SQYD	0.00	\$2.95	\$0.00
		0001	0920	8069905	MISC.LANDSCAPING RESTORATION	500.00	0.00	500.00	SQYD	0.00	\$35.00	\$0.00
		0010	0930	6061060	MGS GUARDRAIL	175.00	0.00	175.00	LF	0.00	\$23.90	\$0.00
		0010	0940	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	4.00	0.00	4.00	EA	0.00	\$3,053.40	\$0.00
		0010	0950	6061080	MGS END ANCHOR	4.00	0.00	4.00	EA	0.00	\$1,209.00	\$0.00
		0010	0960	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$2,629.50	\$0.00
		0020	0970	9011010	RELOCATED POLE	1.00	0.00	1.00	EA	0.00	\$400.00	\$0.00
		0020	0980	9011250	LUMINAIRE, 150 WATT HIGH PRESSURE SODIUM	6.00	-6.00	0.00	EA	0.00	\$930.00	\$0.00
		0020	0990	9011311	(UNDERPASS)  LUMINAIRE, LED-A	7.00	0.00	7.00	EA	0.00	\$300.00	\$0.00
		0020	1000	9014003	CONDUIT, 3 IN. RIGID, PUSHED	91.00	0.00	91.00	LF	0.00	\$28.00	\$0.00
		0020	1010	9015010	TRENCHING TYPE I	26.00	0.00	26.00	LF	0.00	\$8.00	\$0.00
		0020	1020	9016110	PULL BOX, PREFORMED CLASS 1	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.00
			1030	9017110	CABLE. 10 AWG 1 CONDUCTOR, POLE AND BRACKET	90.00	0.00	90.00	LF	0.00	\$0.85	\$0.00
		0020	1040	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	140.00	0.00	140.00	LF	0.00	\$5.80	\$0.00
					NEUTRAL, 6 AWG							
		0020	1050	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	30.00	0.00	30.00	LF	0.00	\$5.30	\$0.00
		0020	1060	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	1.00	0.00	1.00	EA	0.00	\$876.00	\$0.00
		0030	1070	9020113	SIGNAL HEAD, TYPE 3T	4.00	0.00	4.00	EA	0.00	\$702.00	\$0.00
		0030	1080	9020213	SIGNAL HEAD, TYPE 3S	9.00	0.00	9.00	EA	0.00	\$673.00	\$0.00
		0030	1090	9020215	SIGNAL HEAD, TYPE 5S	1.00	0.00	1.00	EA	0.00	\$931.00	\$0.00
		0030	1100	9020513	SIGNAL HEAD, TYPE 3B	104.00	0.00	104.00	EA	0.00	\$875.00	\$0.00
		0030	1110	9020514	SIGNAL HEAD, TYPE 4B	9.00	0.00	9.00	EA	0.00	\$960.00	\$0.00
		0030	1120	9020515	SIGNAL HEAD, TYPE 5B	2.00	0.00	2.00	EA	0.00	\$1,217.00	\$0.00
		0030	1130	9020833	SH-FLAT SHEET - SIGNAL SIGN	754.00	0.00	754.00	SQFT	0.00	\$30.00	\$0.00
		0030	1140	9020834	SIGNAL SIGN, MOUNTING HARDWARE	95.00	0.00	95.00	EA	0.00	\$352.00	\$0.00
		0030	1150	9022708	POST, SIGNAL 8 FT. OR 2.4 M	160.00	0.00	160.00	EA	0.00	\$526.00	\$0.00
		0030	1160	9022715	POST, SIGNAL 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	0.00	\$678.00	\$0.00
		0030	1170	9023125	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	1.00	0.00	1.00	EA	0.00	\$7,194.00	\$0.00
		0030	1180	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$8,729.00	\$0.00
		0030	1190	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	3.00	0.00	3.00	EA	0.00	\$10,217.00	\$0.00
		0030	1200	9023145	POST, TYPE CL, 45 FT. ARM OR 13.7 M ARM	1.00	0.00	1.00	EA	0.00	\$10,538.00	\$0.00
		0030	1210	9023150	POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	0.00	\$11,345.00	\$0.00
		0030	1220	9023155	POST, TYPE CL, 55 FT. ARM	1.00	0.00	1.00	EA	0.00	\$12,722.00	\$0.00
		0030	1230	9023220	POST, TYPE C, 20 FT. ARM OR 6.1 M ARM	2.00	0.00	2.00	EA	0.00	\$5,285.00	\$0.00
		0030	1240	9023225	POST, TYPE C, 25 FT. ARM OR 7.6 M ARM	3.00	0.00	3.00	EA	0.00	\$6,096.00	\$0.00
		0030	1250	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	4.00	0.00	4.00	EA	0.00	\$7,084.00	\$0.00
		0030	1260	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	3.00	0.00	3.00	EA	0.00	\$7,500.00	\$0.00
		0030	1270	9023240	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	2.00	0.00	2.00	EA	0.00	\$8,651.00	\$0.00
		0030	1280	9023245	POST, TYPE C, 45 FT. ARM OR 13.7 M ARM	6.00	0.00	6.00	EA	0.00	\$8,900.00	\$0.00
		0030	1290	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	6.00	0.00	6.00	EA	0.00	\$9,235.00	\$0.00
		0030	1300	9023255	POST, TYPE C, 55 FT. ARM	4.00	0.00	4.00	EA	0.00	\$10,627.00	\$0.00
		0030	1310	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	7.00	0.00	7.00	EA	0.00	\$15,200.00	\$0.00
		0030	1320	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	541.00	0.00	541.00	LF	0.00	\$8.30	\$0.00
		0030	1330	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	3,675.00	0.00	3,675.00	LF	0.00	\$11.00	\$0.00

Page 9 of 23 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-F02	J6S3048	0030	1340	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	18.00	0.00	18.00	LF	0.00	\$12.60	\$0.00
		0030	1350	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	205.00	0.00	205.00	LF	0.00	\$27.00	\$0.00
		0030	1360	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	6,873.00	0.00	6,873.00	LF	431.00	\$25.00	\$10,775.00
		0030	1370	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	253.00	0.00	253.00	LF	0.00	\$25.00	\$0.00
		0030	1380	9028206	CABLE, 6 AWG 1 CONDUCTOR, POWER	910.00	0.00	910.00	LF	0.00	\$1.40	\$0.00
		0030	1390	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	1,220.00	0.00	1,220.00	LF	0.00	\$1.25	\$0.00
		0030	1400	9028308	CABLE, 16 AWG 2 CONDUCTOR	36,360.00	0.00	36,360.00	LF	0.00	\$0.85	\$0.00
		0030	1410	9028310	CABLE, 16 AWG 5 CONDUCTOR	35,860.00	0.00	35,860.00	LF	0.00	\$1.00	\$0.00
		0030	1420	9028311	CABLE, 16 AWG 7 CONDUCTOR	28,720.00	0.00	28,720.00	LF	0.00	\$1.15	\$0.00
		0030	1430	9028810	PULL BOX, PREFORMED CLASS 1	28.00	0.00	28.00	EA	1.00	\$1,000.00	\$1,000.00
		0030	1440	9028811	PULL BOX, PREFORMED CLASS 2	17.00	0.00	17.00	EA	0.00	\$1,250.00	\$0.00
		0030	1450	9028812	PULL BOX, PREFORMED CLASS 3	16.00	0.00	16.00	EA	1.00	\$1,600.00	\$1,600.00
		0030	1460	9029100	BASE, CONCRETE	211.70	0.00	211.70	CUYD	9.68	\$1,350.00	\$13,068.00
		0030	1470	9029400	TEMPORARY TRAFFIC SIGNALS	1.00	0.00	1.00	LS	0.00	\$12,000.00	\$0.00
		0030	1480	9029901	MISC.POT HOLING UTILITY FACILITIES	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0030	1490	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE, PROGRAMMING, AND ADJUSTMENT	1.00	0.00	1.00	LS	0.00	\$23,000.00	\$0.00
		0030	1500	9029902	MISC.ADJUST TO GRADE PULL BOX	93.00	0.00	93.00	EA	4.00	\$500.00	\$2,000.00
		0030	1510	9029902	MISC.AUDIBLE PEDESTRIAN PUSH BUTTON & SIGNING W/	200.00	0.00	200.00	EA	0.00	\$630.00	\$0.00
		0030	1512	9029902	VERBAL WALK MESSAGE  MISC.CABINET MODIFICATION – FEE FEE INTERSECTION	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1514	9029902	MISC.CABINET MODIFICATION – HOME DEPOT INTERSECTION	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1515	9029902	MISC.CABINET MODIFICATION – ADIE INTERSECTION	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1516	9029902	MISC.CABINET MODIFICATION – CYPRESS INTERSECTION	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1518	9029902	MISC.CABINET MODIFICATION – ST. TIMOTHY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1520	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	189.00	0.00	189.00	EA	0.00	\$390.00	\$0.00
		0030	1522	9029902	MISC.CABINET MODIFICATION – ASHBY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$890.00	\$0.00
		0030	1524	9029902	MISC.CABINET MODIFICATION – INTERNATIONAL PLAZA	1.00	0.00	1.00	EA	0.00	\$780.00	\$0.00
		0030	1525	9029902	INTERSECTION  MISC.CABINET MODIFICATION – ST. GREGORY	1.00	0.00	1.00	EA	0.00	\$780.00	\$0.00
					INTERSECTION							
		0030	1526	9029902	MISC.CABINET MODIFICATION – WISMER INTERSECTION	1.00	0.00	1.00	EA	0.00	\$736.00	\$0.00
		0030	1527	9029902	MISC.CABINET MODIFICATION – LYNNTOWN INTERSECTION	1.00	0.00	1.00	EA	0.00	\$780.00	\$0.00
		0030	1528	9029902	MISC.CABINET MODIFICATION – EDMUNDSON INTERSECTION	1.00	0.00	1.00	EA	0.00	\$670.00	\$0.00
		0030	1530	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	6.00	0.00	6.00	EA	0.00	\$1,225.00	\$0.00
		0030	1540	9029902	MISC.OPTIONAL DETECTION - DEPAUL INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1550	9029902	MISC.OPTIONAL DETECTION - EB I-70 RAMPS INTERSECTION	1.00	0.00	1.00	EA	0.00	\$12,890.00	\$0.00
		0030	1560	9029902	MISC.OPTIONAL DETECTION - FEE FEE INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1570	9029902	MISC.OPTIONAL DETECTION - HILLTOP INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1580	9029902	MISC.OPTIONAL DETECTION - HOME DEPOT INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1590	9029902	MISC.OPTIONAL DETECTION - MARK TWAIN INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1600	9029902	MISC.OPTIONAL DETECTION - ST. TIMOTHY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1610	9029902	MISC.OPTIONAL DETECTION - WB I-70 RAMPS INTERSECTION	1.00	0.00	1.00	EA	0.00	\$12,800.00	\$0.00
		0030	1620	9029902	MISC.OPTIONAL DETECTION CYPRESS INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1630	9029902	MISC.OPTIONAL DETETION - HARMONY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1640	9029902	MISC.PAD MOUNTED 120 VOLT SIGNAL POWER SUPPLY	1.00	0.00	1.00	EA	0.00	\$3,900.00	\$0.00
		0030	1650	9029902	MISC.PAD MOUNTED 120 VOLT SIGNAL POWER SUPPLY & 120 VOLT LIGHTING CONTROLLER	1.00	0.00	1.00	EA	0.00	\$5,800.00	\$0.00
		0030	1660	9029902	MISC.PAD MOUNTED 120 VOLT SIGNAL POWER SUPPLY & 120 VOLT LIGHTING CONTROLLER WITH UNINTERRUPTIBLE POWER SUPPLY	1.00	0.00	1.00	EA	0.00	\$13,600.00	\$0.00
		0030	1670	9029902	MISC.PAD MOUNTED 120V/240V SIGNAL POWER SUPPLY & LIGHTING CONTROLLER WITH UNINTERRUPTIBLE POWER	5.00	0.00	5.00	EA	0.00	\$15,300.00	\$0.00
Revision 4/1/202	20											Page 10 of 23



#### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
10416-F02	J6S3048				SUPPLY							
		0030	1680	9029902	MISC.SL DISTRICT VIDEO DETECTION SYSTEM	6.00	0.00	6.00	EA	0.00	\$18,200.00	\$0.00
		0030	1690	9029902	MISC.VIDEO DETECTION MODIFICAITON - ASHBY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$19,000.00	\$0.0
		0030	1700	9029902	MISC.VIDEO DETECTION MODIFICATION - ADIE INTERSECTION	1.00	0.00	1.00	EA	0.00	\$5,900.00	\$0.0
		0030	1710	9029902	MISC.VIDEO DETECTION MODIFICATION - BROWN INTERSECTION	1.00	0.00	1.00	EA	0.00	\$300.00	\$0.0
		0030	1720	9029902	MISC.VIDEO DETECTION MODIFICATION - EDUNDSON INTERSECTION	1.00	0.00	1.00	EA	0.00	\$300.00	\$0.0
		0030	1730	9029902	MISC.VIDEO DETECTION MODIFICATION - INTERNATIONAL PLAZA INTERSECTION	1.00	0.00	1.00	EA	0.00	\$10,000.00	\$0.0
		0030	1740	9029902	MISC.VIDEO DETECTION MODIFICATION - LYNN TOWN	1.00	0.00	1.00	EA	0.00	\$10,000.00	\$0.0
		0030	1750	9029902	INTERSECTION MISC.VIDEO DETECTION MODIFICATION - MCKIBBON	1.00	0.00	1.00	EA	0.00	\$10,000.00	\$0.0
		0030	1760	9029902	INTERSECTION  MISC.VIDEO DETECTION MODIFICATION - ST. GREGORY	1.00	0.00	1.00	EA	0.00	\$6,000.00	\$0.0
					INTERSECTION							
		0030	1770	9029902	MISC.VIDEO DETECTION MODIFICATION - ST. JOHN CROSSING INTERSECTION	1.00	0.00	1.00	EA	0.00	\$350.00	\$0.0
		0030	1780	9029902	MISC.VIDEO DETECTION MODIFICATION - WISMER INTERSECTION	1.00	0.00	1.00	EA	0.00	\$350.00	\$0.0
		0030	1790	9029902	MISC.VIDEO DETECTION MODIFICATION - WOODSON INTERSECTION	1.00	0.00	1.00	EA	0.00	\$350.00	\$0.0
		0030	1800	9029903	MISC.2 CONDUCTOR 12 AWG LUMINAIRE CONTROL CABLE	2,280.00	0.00	2,280.00	LF	0.00	\$0.90	\$0.0
		0040	1810	9031010	CONCRETE FOOTINGS, EMBEDDED	7.20	0.00	7.20	CUYD	0.00	\$1,074.00	\$0.0
		0040	1820	9031220	PIPE POSTS	4,930.00	0.00	4,930.00	LB	0.00	\$4.36	\$0.0
		0040	1830	9031270A	2 IN. PSST POST - 12 GA.	1,983.00	0.00	1,983.00	LF	0.00	\$14.85	\$0.0
		0040	1840	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	564.00	0.00	564.00	LF	0.00	\$25.77	\$0.0
		0040	1850	9031280	2.5 IN. PSST POST - 12 GA.	509.00	0.00	509.00	LF	0.00	\$16.65	\$0.0
		0040	1860	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	132.00	0.00	132.00	LF	0.00	\$50.37	\$0.0
		0040	1870	9035004A	SH-FLAT SHEET	1,732.00	0.00	1,732.00	SQFT	0.00	\$15.96	\$0.0
		0040	1880	9035069A	SHF-FLAT SHEET FLUORESCENT	304.00	0.00	304.00	SQFT	0.00	\$19.56	\$0.0
		0040	1890	9039902	MISC.REMOVE AND RELOCATE EXISTING GROUND MOUNT SIGN	27.00	0.00	27.00	EA	0.00	\$132.27	\$0.0
		0050	1900	9108816	PULL BOX, PREFORMED CLASS 5	4.00	0.00	4.00	EA	0.00	\$1,500.00	\$0.0
		0050	1910	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$7,373.00	\$0.0
		0050	1920	9109902	MISC.CCTV CAMERA ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$3,600.00	\$0.0
		0050	1930	9109902	MISC.FIBER OPTIC PIGTAIL, SM, FURNISH AND INSTALL	46.00	0.00	46.00	EA	0.00	\$57.00	\$0.0
		0050	1940	9109902	MISC.FIRER OPTIC JUMPER, SM, FURNISH AND INSTALL	36.00	0.00	36.00	EA	0.00	\$51.00	\$0.0
		0050	1950	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$1,800.00	\$0.0
		0050	1960	9109902	MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - ASHBY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.0
		0050	1970	9109902	MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - DEPAUL INTERSECTION	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.0
		0050	1980	9109902	MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - LINDBERGH INTERSECTION	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.0
		0050	1990	9109902	MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT -	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.0
		0050	2000	9109902	MCKELVEY INTERSECTION  MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT -	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.0
		0050	2010	9109902	NATURAL BRIDGE INTERSECTION  MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT -	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.
		0050	2020	9109902	NB I-270 INTERSECTION  MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT -	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.0
		0050	2030	9109902	PENNRIDGE INTERSECTION  MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT -	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.0
		0050	2040	9109902	SB I-270 INTERSECTION  MISC.SM FIBER OPTIC FUSION SPLICE	160.00	0.00	160.00	EA	0.00	\$49.00	\$0.0
		0050	2050	9109902	MISC.WALL-MOUNTED INTERCONNECT CENTER, FURNISH	7.00	0.00	7.00	EA	0.00	\$910.00	\$0.
					AND INSTALL							
		0050	2060	9109903	MISC.CCTV CAMERA CABLE	190.00	0.00	190.00	LF	0.00	\$1.25	\$0.0
		0050	2070	9109903	MISC.CONDUIT, 2 - 2 IN., RIGID, IN TRENCH	140.00	0.00	140.00	LF	0.00	\$28.00	\$0.0
		0050	2080	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND SINGLE MODE	5,390.00	0.00	5,390.00	LF	0.00	\$3.25	\$0.0

Revision 4/1/2020 Page 11 of 23



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-F02	J6S3048	0050	2090	9109903	MISC.MODOT ITS ASSETS RELOCATION	1,000.00	0.00	1,000.00	LF	0.00	\$11.00	\$0.00
		0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$80,332.00	\$80,332.00
		0001	5002	6081012	TRUNCATED DOMES	0.00	2,240.00	2,240.00	SQFT	428.10	\$24.23	\$10,372.86
		0020	5003	9019902	MISC.Luminaire, LED Wall Pack (Underpass)	0.00	6.00	6.00	EA	0.00	\$930.00	\$0.00
		0001	5004	6089905	MISC.Misc. Concrete Sidewalk, 7 IN. Coral Color	0.00	750.00	750.00	SQYD	595.50	\$63.00	\$37,516.50
		0001	5005	6091052	CURB AND GUTTER TYPE B	0.00	6,950.00	6,950.00	LF	938.20	\$31.97	\$29,994.25
		0001	5006	6099903	MISC.Integral Curb (6 IN Height and Under), Type A, Coral Color	0.00	1,800.00	1,800.00	LF	679.65	\$21.78	\$14,802.78
	Project J6S3048 - Total Value Posted to Date as of Report Generated Date											
210416-F02 Ove	erall - Total	Value Post	ted to Dat	te as of Rep	ort Generated Date							\$1.548,222,90

Revision 4/1/2020 Page 12 of 23



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3048

roject.	J6S3048	0										
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	2071000	LINEAR GRADING CLASS 1	11/16/21	11/17/21	0.38	STA		415+51.88 LT		407+52.49 LT		Sta 415+51.88 LT: 0.09 Sta 409+19.18 LT: 0.09 Sta 408+21.58 LT: 0.1
0040	2072000	LINEAR GRADING CLASS 2	11/16/21	11/17/21	2.20	STA	WB 180	412+97.76		417+05.65		Sta 407+52.49 LT: 0.1
0060	3040504	TYPE 5 AGGREGATE FOR BASE	11/16/21	11/17/21	210.30	SQYD	WB 180	417+05 LT		LT 407+52.49 LT		Underneath various sections of sidewalk and paved approaches. 17.5' x 6', 10' x 7', 3' x 7', 3' x 8', 15' x 31.5', 10' x 7', 10'
			11/17/21	11/18/21	78.60	SQYD	WB 180	435+15		411+98.77		7', 19' x 7', 30' x 14.5', 16' x 14', 15' x 16', 5' x 11' x 0.5 Underneath 16.1 SQYD of 7" sidewalk and 62.5 SQYD
			11/18/21	11/23/21			WB 180	LT 437+25		LT 419+70		paved approach.
			11/19/21	11/23/21			WB 180, Phillips 66 entrance and Red Dot Storage	LT 410+45.71		LT 409+19.18		Sta 410+45.71 LT: 14' x 34'
			11/22/21	11/29/21			entrance. WB 180	LT 419+70		LT 402+00.65		Sta 409+19.18 LT: 14.5' x 31' Underneath various sections of sidewalk and paved
			11/23/21	11/29/21	313.60		WB 180	LT 415+93.57		LT 399+00		approach.  Underneath various sections of sidewalks and ramps
			11/24/21	11/29/21			WB 180	LT 402+00.65		LT 409+19.18		between Glentowne Dr. and Advance Auto Parts.  Underneath paved approaches at Phillips 66, Big Jay!
			11/29/21	12/1/21			WB 180	LT 408+90		LT 407+05		and Taco Bell.  Underneath various sections of sidewalk.
			11/30/21	12/1/21			WB 180	LT 402+79.32		LT 400+29.96		Underneath paved approaches.
0180	6081012	TRUNCATED DOMES	11/17/21	11/18/21	30.00		Island on north side of Woodson.	LT 435+15		LT		3 5' x 2' sets of domes in island.
		PAVED APPROACH, 8 IN.					WB 180	LT 415+51.88		407+52.49		Sta 415+51.88 LT: 15' x 31.5' = 52.5 SQYD
0200	000000	TAVES ALT TOAGE, OILV.	11/10/21	11111121	133.40	OQID	WE ISO	LT		LT		Sta 409+19.18 LT: 30' x 14.5' = 48.3 SQYD Sta 408+21.58 LT: 16' x 14' = 24.9 SQYD Sta 407+52.49 LT: 15' x 16' (Square) + 5' x 11' (Triang = 29.7 SQYD
			11/17/21	11/18/21	62.50	SQYD	Breckenridge Hills Police Department West half and Pop's Kitchen East entrance West half.	414+12.96 LT		411+98.77 LT		Sta 414+12.96: 13' x 16.5' = 23.8 SQYD Sta 411+98.77: 14.5' x 24' = 38.7 SQYD
			11/19/21	11/23/21	102.80	SQYD	WB 180, Phillips 66 entrance and Red Dot Storage entrance.	410+45.71 LT		409+19.18 LT		Sta 410+45.71 LT: 14' x 34' Sta 409+19.18 LT: 14.5' x 31'
			11/22/21	11/29/21	52.50	SQYD	WB 180	402+79.32 LT		402+00.65 LT		O'Reilly Auto Parts East Half, Sta 402+79.32 LT: 16' > = 33.8 sqyd Taco Bell East Half: 16' x 10.5' = 18.7 sqyd
			11/24/21	11/29/21	112.10	SQYD	WB 180	402+00.65 LT		409+19.18 LT		Phillips 66 West Entrance, West Half Sta 409+19.18 L 14 x 32 = 48.8 styd Big Jay's East Entrance, West Half Sta 408+21.58 LT Big Jay's East Of East Half Sta 402+00.65 LT: 6" x 14 7.5 x 9tyd Big Jay's West Entrance, West Half, Sta 407+52.49 L 15 x 14.5" = 28.4 styd
			11/30/21	12/1/21	116.00	SQYD		402+79.32 LT		400+29.96 LT		Sta 402+79.32 LT O'Reilly W. Half: 16' x 16.5' = 29.3 Sta 402+00.65 LT Taco Bell W. Half: 16' x 17.5' = 31. sqyd Sta 400+29.96 LT between Taco Bell and Advance Al Parts: 22' x 16' (Square) and 16' x 18.5' (triangle) = 55
0220	6086007	CONCRETE SIDEWALK, 7 IN.	11/17/21	11/18/21	16.10	SQYD	Woodson and 180 North island.	435+15 LT				Sections of 11' x 5', 9' x 5', and 9' x 5'
0240	6089902	MISC. CONCRETE	11/18/21	11/23/21	2.00	EA	180 and Woodson	436+45.46 LT		435+02.65 LT		1 curb ramp on NE corner and 1 curb ramp on NW co of 180 and Woodson intersection.
			11/22/21	11/29/21	3.00	EA	WB 180 - Woodson, Edmundson, and Glentowne	436+07.95 LT		415+07.94 LT		
			11/23/21	11/29/21	1.00	EA	180 and Glentowne Dr.	415+93.57 LT				
0270	6089905	MISC. CONCRETE	11/16/21	11/17/21	19.80	SQYD	WB 180	416+40 LT		413+05 LT		Sections of 3' x 7', 3' x 8', and 19' x 7'
			11/18/21	11/23/21	152.00	SQYD	WB 180	437+25 LT		419+70 LT		In front of school near Woodson: 6' x 27' NW Corner of 180 and Woodson: 48 SQYD In front of Automax: 27' x 6' NE Corner of 180 and Woodson: 68 SQYD
			11/22/21	11/29/21	90.50	SQYD	WB 180	419+70 LT		409+75 LT		Edmundson + 180 NE Corner: 35' x 6' = 23.3 sqyd Glentowne Dr. West Corner: 5' x 7.5' = 4.2 sqyd In front of Smart Buy Car Sales: 45.5' x 6' = 30.3 sqyd Between Pop's Kitchen and Phillips 66: 5' x 7' = 3.9 sq In front of Phillips 66: 3'' x 7' = 28.8 sqyd
			11/23/21	11/29/21	261.30	SQYD	WB 180	409+70 LT		399+00 LT		In front of Phillips 66: $6.5' \times 7 = 5.1$ sqyd in front of Phillips 66: $ch$ 148. $2.5' \times 7 = 2.2$ sqyd in front of Antique Store. $55' \times 8.5' = 51$ sqyd in front of Antique Store. $55' \times 8.5' = 51$ sqyd in front of Antique Store/Strip Mall parking lot: $11' \times 9'$ sqyd in front of O'Reilly's 47.5' $\times 7' = 36.9$ sqyd in front of Taco Bell: $7' \times 78.5' = 61.1$ sqyd in front of Taconac Auto Parts: $7.5' \times 94' = 73.1$ sqyd
			11/29/21	12/1/21	21.40	SQYD	WB 180	407+10 LT		408+00 LT		In front of Big Jay's sign: 14' x 7.5' = 11.7 sqyd In front of Big Jay's building: 7' x 12.5' = 9.7 sqyd
0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	11/16/21	11/17/21	11.00	LF		414+39 LT		414+50 LT		
			11/17/21	11/18/21	40.00	LF	Woodson and 180 North island.	435+15 LT		LI		Sections of 8', 7', 8.5', 9', and 7.5'
			11/18/21	11/23/21	42.50	LF	NE corner 180 and Woodson	436+70		436+00		
			11/24/21	11/29/21	22.00	LF	WB 180	416+40		405+05		
0310	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	11/19/21	11/23/21	8.00	LF		410+45.71		409+19.18		
0390	6119905	MISC. EMBANKMENT PROTECTION	11/16/21	11/17/21	11.30	SQYD	Wb 180 in between Smart Car and Lilly Peez	416+88		417+05		22.5' x 4.5'
			11/29/21	12/1/21	2.00	SQYD	WB 180	LT 407+05		LT		3' x 6'
0511	6181000	MOBILIZATION	12/1/21	12/2/21	0.25	LS		LT 0				10% of contract complete.
0740	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	12/1/21	12/1/21	0.02	LS		0				
1460	9029100	BASE, CONCRETE	12/1/21	12/1/21	3.52	CUYD	Ashby and St. Timothy Intersections North side.	345+55 LT		337+10 LT		(4) C Bases at Ashby - 2 in NW quadrant, 2 in NE quandrant
												(4) C Bases at St. Timothy - 2 in NW quadrant, 2 in NE quadrant.

Revision 4/1/2020 Page 13 of 23



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
5002	6081012	TRUNCATED DOMES	11/22/21	11/29/21	35.00	SQFT	WB 180 - Woodson, Edmundson, and Glentowne	436+07.95 LT		415+07.94 LT		5' x 2' at Woodson, 5' x 2' at Edmundson, and 7.5' x 2' at Glentowne.
			11/23/21	11/29/21	15.00	SQFT	180 and Glentowne Dr.	415+93.57 LT				2' x 7.5' = 15 sqft
5004	6089905	MISC. CONCRETE	11/16/21	11/17/21	35.10	SQYD	WB 180	417+05 LT		413+00 LT		Sta 416+88 - Sta 417+05: 17.5' x 6' Sta 415+50 - Sta 415+60: 10' x 7' Sta 414+30 - Sta 414+40: 10' x 7' Sta 414+30 - Sta 414+30: 10' x 7'
			11/18/21	11/23/21	6.70	SQYD	In front of Automax	419+95 LT		420+05 LT		6' x 10'
			11/22/21	11/29/21	66.50	SQYD	WB 180	417+60 LT		410+00 LT		In front of Smart Buy Car Sales: 10' x 6' = 6.7 sqyd Between Breckenridge Hills PD and Sports Energizers: 9' x 7' = 7 sqyd In front of Unique Distributors: 11' x 7' = 8.6 sqyd In front of Pops Kitchen: 20.5' x 7' and 8' x 5.5' = 20.8 sqyd Between Pop's Kitchen and Phillips 66: 20' x 7' = 15.6 sqyd In front of Phillips 66: 10' x 7' = 7.8 sqyd
			11/23/21	11/29/21	52.30	SQYD	WB 180	409+70 LT		403+00 LT		In front of Phillips 66: 10' x 7' = 7.8 sqyd In front of Phillips 66 Car Wash: 10' x 7' = 7.8 sqyd In front of Antique Store: 20' x 8.5' = 18.9 sqyd In front of Antique Store: 20' x 8.5' = 18.9 sqyd In front of Antique Store/Strip Mall parking lot: 10' x 9' = 10 sqyd In front of O'Reilly's: 10' x 7' = 7.8 sqyd
			11/29/21	12/1/21	39.30	SQYD	WB 180	408+90 LT		407+05 LT		In front of Phillips 66 Car Wash: 10.5' x 7' = 8.2 sqyd In front of Big Jay's Sign: 20' x 7.5' = 16.7 sqyd In front of Big Jays Building: 7' x 10' and 10' x 6' = 14.4 sqyd
5005	6091052	CURB AND GUTTER TYPE B	11/16/21	11/17/21	33.50	LF	WB 180	415+51.88 LT		408+21.58 LT		14', 10', and 9.5'
			11/17/21	11/18/21	13.50	LF	WB 180	414+12.96 LT		411+98.77 LT		Sta 414+12.96 LT: 6.5' Sta 411+98.77 LT: 7'
			11/19/21	11/23/21	21.00	LF		410+45.71 LT		409+19.18 LT		
			11/22/21	11/29/21	22.00	LF		402+79.32 LT		402+00.62 LT		10' curb and gutter at O'Reilly's entrance 12' curb and gutter at Taco Bell entrance
			11/24/21	11/29/21	31.00	LF	WB 180	416+40 LT		407+52.49 LT		
			11/30/21	12/1/21	25.00	LF		402+79.32 LT		402+00.65 LT		Sta 402+79.32 LT O'Reilly: 13' Sta 402+00.65 LT Taco Bell: 12'
5006	6099903	MISC. PAVED DRAINAGE	11/16/21	11/17/21	36.00	LF	WB 180	415+60 LT		416+15 LT		Sections of 18.5', 8', and 9'
			11/18/21	11/23/21	8.50	LF	In front of Automax	419+95 LT		420+05 LT		
			11/22/21	11/29/21	111.50	LF	WB 180	417+60 LT		410+70 LT		In front of Smart Buy Car Sales: 8.5' Between Breckennidge Hills PD and Sports Energizers: 10' In front of Unique Distributors: 13' In front of Pog's Klitchen: 33' In front of Phillips 66: 47'
			11/23/21	11/29/21	46.50	LF	WB 180	409+70 LT		403+00 LT		In front of Phillips 66: 17.5' In front of Phillips 66 Car Wash: 10' In front of Antique Store: 5' In front of Antique Store/Strip Mall parking lot: 4' In front of O'Reilly's: 10'
			11/29/21	12/1/21	36.00	LF		408+90 LT		407+05 LT		In front of Phillips 66 Car Wash: 4.5' In front of Big Jay's Sign: 19' In front of Big Jays Building: 12.5'

<u>The information below this line are details for Construction Signs (if applicable).</u>

No Data Available

Revision 4/1/2020 Page 14 of 23

Dec 13, 2021



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J6S3048	0050	TYPE 1 AGGREGATE FOR BASE (8	Material		7	Oct 18, 2021	SYSTEM	\$621.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.		
		IN. THICK)			7	Oct 18, 2021	SYSTEM	(\$621.60)			
					8	Nov 3, 2021	SYSTEM	\$621.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					8	Nov 3, 2021	SYSTEM	(\$621.60)			
					9	Nov 16, 2021	SYSTEM	\$621.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					9	Nov 16, 2021	SYSTEM	(\$621.60)			
					10	Dec 2, 2021	SYSTEM	\$621.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					10	Dec 2, 2021	SYSTEM	(\$621.60)			
				- Total				\$0.00			
			Material - T	otal				\$0.00			
	0050 -	Total						\$0.00			
	0060	TYPE 5 AGGREGATE FOR BASE	Material		3	Aug 17, 2021	SYSTEM	\$3,244.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.		
						3	Aug 16, 2021	SYSTEM	(\$3,244.50)		
					4	Sep 3, 2021	SYSTEM	\$10,092.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					4	Sep 2, 2021	SYSTEM	(\$10,092.60)			
					5	Sep 16, 2021	SYSTEM	\$17,085.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					5	Sep 16, 2021	SYSTEM	(\$17,085.60)			
					6	Oct 4, 2021	SYSTEM	\$32,813.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schmij8 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					6	Oct 4, 2021	SYSTEM	(\$32,813.20)			
					7	Oct 18, 2021	SYSTEM	\$36,999.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					7	Oct 18, 2021	SYSTEM	(\$36,999.90)			
					8	Nov 3, 2021	SYSTEM	\$44,692.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					8	Nov 3, 2021	SYSTEM	(\$44,692.20)			
					9	Nov 16, 2021	SYSTEM	\$50,205.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					9	Nov 16, 2021	SYSTEM	(\$50,205.40)			
							10	Dec 2, 2021	SYSTEM	\$59,741.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Dec 2, 2021	SYSTEM	(\$59,741.50)			
				- Total				\$0.00			



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3048	0060	TYPE 5 AGGREGATE FOR BASE	Material - To	otal				\$0.00	
	0060 -	Total						\$0.00	
	0180	TRUNCATED DOMES	Material		2	Aug 3, 2021	SYSTEM	\$866.97	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Aug 3, 2021	SYSTEM	(\$866.97)	
					3	Aug 17, 2021	SYSTEM	\$2,489.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$2,489.76)	
					4	Sep 3, 2021	SYSTEM	\$4,468.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$4,468.23)	
					5	Sep 16, 2021	SYSTEM	\$6,557.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$6,557.85)	
					6	Oct 4, 2021	SYSTEM	\$7,080.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schmij8 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Oct 4, 2021	SYSTEM	(\$7,080.26)	
					7	Oct 18, 2021	SYSTEM	\$222.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$222.30)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0180 -	Total						\$0.00	
	0200	PAVED APPROACH, 8 IN.	Material		2	Aug 3, 2021	SYSTEM	\$5,027.83	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Aug 3, 2021	SYSTEM	(\$5,027.83)	
					3	Aug 17, 2021	SYSTEM	\$18,276.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$18,276.77)	
					4	Sep 3, 2021	SYSTEM	\$50,941.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$50,941.10)	
					5	Sep 16, 2021	SYSTEM	\$78,428.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$78,428.81)	
					6	Oct 4, 2021	SYSTEM	\$93,215.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Oct 4, 2021	SYSTEM	(\$93,215.98)	
					7	Oct 18, 2021	SYSTEM	\$108,407.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 6 on the current Payment Estimate.





# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J6S3048	0200	PAVED APPROACH, 8	Material		7	Oct 18, 2021	SYSTEM	(\$108,407.68)				
		IN.			8	Nov 3, 2021	SYSTEM	\$120,371.69	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					8	Nov 3, 2021	SYSTEM	(\$120,371.69)				
					9	Nov 16, 2021	SYSTEM	\$148,080.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					9	Nov 16, 2021	SYSTEM	(\$148,080.73)				
					10	Dec 2, 2021	SYSTEM	\$185,048.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 5 on the current Payment Estimate.			
					10	Dec 2, 2021	SYSTEM	(\$185,048.65)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0200 -	Total						\$0.00				
	0210	CONCRETE SIDEWALK, 4 IN.	Material		2	Aug 3, 2021	SYSTEM	\$129.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					2	Aug 3, 2021	SYSTEM	(\$129.20)				
					3	Aug 17, 2021	SYSTEM	\$594.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate.			
								3	Aug 16, 2021	SYSTEM	(\$594.80)	
					4	Sep 3, 2021	SYSTEM	\$594.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					4	Sep 2, 2021	SYSTEM	(\$594.80)				
					5	Sep 16, 2021	SYSTEM	\$1,972.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					5	Sep 16, 2021	SYSTEM	(\$1,972.20)				
					6	Oct 4, 2021	SYSTEM	\$2,002.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schmij8 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					6	Oct 4, 2021	SYSTEM	(\$2,002.08)				
					7	Oct 18, 2021	SYSTEM	\$2,242.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					7	Oct 18, 2021	SYSTEM	(\$2,242.64)				
					8	Nov 3, 2021	SYSTEM	\$25,670.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					8	Nov 3, 2021	SYSTEM	(\$25,670.08)				
						9	Nov 16, 2021	SYSTEM	\$31,420.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					9	Nov 16, 2021	SYSTEM	(\$31,420.24)				
					10	Dec 2, 2021	SYSTEM	\$31,420.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					10	Dec 2, 2021	SYSTEM	(\$31,420.24)				



# Line Item Adjustments by Estimate

Droinet	Line	Description	A dissatura a mt	Other	Est.	Created	Created	Amount	Remarks		
Project	Line	Description	Adjustment Type	Adjustment	Number	Date	By	Amount	Remains		
J6S3048	0210	CONCRETE	Material	Type - Total				\$0.00			
0000010	02.0	SIDEWALK, 4 IN.	Material - To					\$0.00			
	0210 -	Total						\$0.00			
	0220	CONCRETE SIDEWALK, 7 IN.	Material		7	Oct 18, 2021	SYSTEM	\$506.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate.		
					7	Oct 18, 2021	SYSTEM	(\$506.14)			
					8	Nov 3, 2021	SYSTEM	\$2,285.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					8	Nov 3, 2021	SYSTEM	(\$2,285.98)			
					9	Nov 16, 2021	SYSTEM	\$3,276.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate.		
					9	Nov 16, 2021	SYSTEM	(\$3,276.02)			
					10	Dec 2, 2021	SYSTEM	\$4,171.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 9 on the current Payment Estimate.		
					10	Dec 2, 2021	SYSTEM	(\$4,171.50)			
				- Total				\$0.00			
			Material - To	ntal				\$0.00			
	0220	) - Total						\$0.00			
	0230	MISC. CONCRETE		Material		8	Nov 3, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 11 on the current Payment Estimate.	
						8	Nov 3, 2021	SYSTEM	(\$1,400.00)		
									9	Nov 16, 2021	SYSTEM
					9	Nov 16, 2021	SYSTEM	(\$9,800.00)			
					10	Dec 2, 2021	SYSTEM	\$9,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate.		
					10	Dec 2, 2021	SYSTEM	(\$9,800.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0230 -	Total						\$0.00			
	0240	MISC. CONCRETE	Material		2	Aug 3, 2021	SYSTEM	\$3,795.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate.		
					2	Aug 3, 2021	SYSTEM	(\$3,795.40)			
					3	Aug 17, 2021	SYSTEM	\$9,488.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate.		
				3	Aug 16, 2021	SYSTEM	(\$9,488.50)				
					4	Sep 3, 2021	SYSTEM	\$18,977.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					4	Sep 2, 2021	SYSTEM	(\$18,977.00)			
					5	Sep 16, 2021	SYSTEM	\$30,363.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate.		

Dec 13, 2021



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3048	0240	MISC. CONCRETE	Material		5	Sep 16, 2021	SYSTEM	(\$30,363.20)	
					6	Oct 4, 2021	SYSTEM	\$39,851.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schmij8 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Oct 4, 2021	SYSTEM	(\$39,851.70)	
					7	Oct 18, 2021	SYSTEM	\$41,749.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$41,749.40)	
					8	Nov 3, 2021	SYSTEM	\$41,749.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$41,749.40)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0240 -	Total						\$0.00	
	0270	MISC. CONCRETE	Material		2	Aug 3, 2021	SYSTEM	\$11,173.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 18 on the current Payment Estimate.
					2	Aug 3, 2021	SYSTEM	(\$11,173.99)	
					3	Aug 17, 2021	SYSTEM	\$30,368.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 14 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$30,368.47)	
					4	Sep 3, 2021	SYSTEM	\$50,604.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$50,604.16)	
					5	Sep 16, 2021	SYSTEM	\$73,977.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$73,977.07)	
					6	Oct 4, 2021	SYSTEM	\$128,652.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schmij8 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Oct 4, 2021		(\$128,652.81)	
					7	Oct 18, 2021	SYSTEM	\$102,251.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$102,251.80)	
					8	Nov 3, 2021	SYSTEM	\$110,622.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$110,622.22)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0270 -	Total						\$0.00	
	0290	CONCRETE CURB (6 IN. HEIGHT AND	Material		2	Aug 3, 2021	SYSTEM	\$8,392.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 23 on the current Payment Estimate.
		UNDER)			2	Aug 3, 2021	SYSTEM	(\$8,392.12)	



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3048	0290	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	Material		3	Aug 17, 2021	SYSTEM	\$12,036.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 18 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$12,036.70)	
					4	Sep 3, 2021	SYSTEM	\$12,644.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$12,644.14)	
					5	Sep 16, 2021	SYSTEM	\$14,961.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$14,961.96)	
					6	Oct 4, 2021	SYSTEM	\$15,217.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schmij8 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Oct 4, 2021	SYSTEM	(\$15,217.72)	
					7	Oct 18, 2021	SYSTEM	\$7,827.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user aubucj overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$7,827.22)	
					8	Nov 3, 2021	SYSTEM	\$9,809.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user aubucj overridding Payment Estimate Exception 19 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$9,809.36)	
					9	Nov 16, 2021	SYSTEM	\$13,198.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Nov 16, 2021	SYSTEM	(\$13,198.18)	
				- Total				\$0.00	
	0290 -	Material - Total  0290 - Total						\$0.00 \$0.00	
	0310	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		4	Sep 3, 2021	SYSTEM	\$2,618.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$2,618.28)	
					5	Sep 16, 2021	SYSTEM	\$4,550.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$4,550.82)	
					6	Oct 4, 2021	SYSTEM	\$4,737.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schmij8 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Oct 4, 2021	SYSTEM	(\$4,737.84)	
					7	Oct 18, 2021	SYSTEM	\$103.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user aubucj overridding Payment Estimate Exception 20 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$103.90)	
					8	Nov 3, 2021	SYSTEM	\$664.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user aubucj overridding Payment Estimate Exception 20 on the current Payment Estimate.
					8	Nov 3,	SYSTEM	(\$664.96)	
						2021		, ,	



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J6S3048	0310	INTEGRAL	Material	71					Estimate Exception 25 on the current Payment Estimate.								
		CURB (6 IN. HEIGHT AND UNDER)			9	Nov 16, 2021	SYSTEM	(\$1,787.08)									
					10	Dec 2, 2021	SYSTEM	\$1,953.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 26 on the current Payment Estimate.								
					10	Dec 2, 2021	SYSTEM	(\$1,953.32)									
				- Total				\$0.00									
			Material - T	otal				\$0.00									
	0310 -	10 - Total															
	0390	MISC. EMBANKMENT PROTECTION	Material		2	Aug 3, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 27 on the current Payment Estimate.								
					2	Aug 3, 2021	SYSTEM	(\$3,175.29)									
					3	Aug 17, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 21 on the current Payment Estimate.								
					3	Aug 16, 2021	SYSTEM	(\$3,175.29)									
					4	Sep 3, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 16 on the current Payment Estimate.								
					4	Sep 2, 2021	SYSTEM	(\$3,175.29)									
					5	Sep 16, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 16 on the current Payment Estimate.								
					5	Sep 16, 2021	SYSTEM	(\$3,175.29)									
					6	Oct 4, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schmij8 overridding Payment Estimate Exception 17 on the current Payment Estimate.								
					6	Oct 4, 2021	SYSTEM	(\$3,175.29)									
					7	Oct 18, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 28 on the current Payment Estimate.								
					7	Oct 18, 2021	SYSTEM	(\$3,175.29)									
					8	Nov 3, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 27 on the current Payment Estimate.								
					8	Nov 3, 2021	SYSTEM	(\$3,175.29)									
											9	9	9	Nov 16, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 32 on the current Payment Estimate.
											9	Nov 16, 2021	SYSTEM	(\$3,175.29)			
					10	Dec 2, 2021	SYSTEM	\$4,530.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 34 on the current Payment Estimate.								
					10	Dec 2, 2021	SYSTEM	(\$4,530.16)									
				- Total				\$0.00									
			Material - T	Total				\$0.00									
	0390 -	Total						\$0.00									
	0480	MISC.	Material		3	Aug 17, 2021	SYSTEM	\$11,988.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 25 on the current Payment Estimate.								
					3	Aug 16,	SYSTEM	(\$11,988.10)									



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
1000040	0.400	MICO	Matarial	Type		2021			
J6S3048	0480	MISC.	Material	- Total		2021		¢0.00	
								\$0.00	
			Material - T	otai				\$0.00	
		- Total						\$0.00	
	0490	MISC. TRAFFIC CONTROL DEVICES	Material		3	Aug 17, 2021	SYSTEM	\$6,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 26 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$6,400.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0490 -	- Total						\$0.00	
	0840	TURF TYPE TALL FESCUE SODDING	Material		6	Oct 4, 2021	SYSTEM	\$7,647.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schmij8 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Oct 4, 2021	SYSTEM	(\$7,647.50)	
					7	Oct 18, 2021	SYSTEM	\$7,647.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 31 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$7,647.50)	
					8	Nov 3, 2021	SYSTEM	\$7,647.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 30 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$7,647.50)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0840 -	- Total						\$0.00	
	1460	BASE, CONCRETE	Material		8	Nov 3, 2021	SYSTEM	\$4,158.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user aubucj overridding Payment Estimate Exception 31 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$4,158.00)	
					9	Nov 16,	SYSTEM	\$5,940.00	This adjustment affects the original system generated Metavial Dayment
						2021		, , , , , , , , ,	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate.
					9		SYSTEM	(\$5,940.00)	Estimate Item Adjustment (0010) due to user aubucj overridding Payment
					9	2021 Nov 16,	SYSTEM SYSTEM		Estimate Item Adjustment (0010) due to user aubucj overridding Payment
						2021 Nov 16, 2021 Dec 2,		(\$5,940.00)	Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment
				- Total	10	2021 Nov 16, 2021 Dec 2, 2021	SYSTEM	(\$5,940.00) \$10,692.00	Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment
			Material - T		10	2021 Nov 16, 2021 Dec 2, 2021	SYSTEM	(\$5,940.00) \$10,692.00 (\$10,692.00)	Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment
	1460 -	- Total	Material - T		10	2021 Nov 16, 2021 Dec 2, 2021	SYSTEM	(\$5,940.00) \$10,692.00 (\$10,692.00)	Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment
	1460 - 5002	-Total TRUNCATED DOMES	Material - T		10	2021 Nov 16, 2021 Dec 2, 2021	SYSTEM	(\$5,940.00) \$10,692.00 (\$10,692.00) \$0.00	Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment
		TRUNCATED			10	2021 Nov 16, 2021 Dec 2, 2021 Dec 2, 2021	SYSTEM	(\$5,940.00) \$10,692.00 (\$10,692.00) \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user aubucj overridding Payment
		TRUNCATED			10	2021  Nov 16, 2021  Dec 2, 2021  Dec 2, 2021  Oct 18, 2021  Oct 18, 2021	SYSTEM SYSTEM SYSTEM	(\$5,940.00) \$10,692.00 (\$10,692.00) \$0.00 \$0.00 \$8,676.76	Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user aubucj overridding Payment
		TRUNCATED		otal - Total	10	2021  Nov 16, 2021  Dec 2, 2021  Dec 2, 2021  Oct 18, 2021  Oct 18, 2021	SYSTEM SYSTEM SYSTEM	(\$5,940.00) \$10,692.00 (\$10,692.00) \$0.00 \$0.00 \$8,676.76	Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user aubucj overridding Payment
	5002	TRUNCATED	Material	otal - Total	10	2021  Nov 16, 2021  Dec 2, 2021  Dec 2, 2021  Oct 18, 2021  Oct 18, 2021	SYSTEM SYSTEM SYSTEM	(\$5,940.00) \$10,692.00 (\$10,692.00) \$0.00 \$0.00 \$8,676.76 (\$8,676.76)	Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user aubucj overridding Payment
	5002	TRUNCATED DOMES	Material	otal - Total	10	2021  Nov 16, 2021  Dec 2, 2021  Dec 2, 2021  Oct 18, 2021  Oct 18, 2021	SYSTEM SYSTEM SYSTEM	(\$5,940.00) \$10,692.00 (\$10,692.00) \$0.00 \$0.00 \$8,676.76 (\$8,676.76) \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 38 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user aubucj overridding Payment

Dec 13, 2021

# MoDOT

# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3048	5004	MISC.	Material			2021			
		CONCRETE			8	Nov 3, 2021	SYSTEM	\$24,922.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user aubucj overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$24,922.80)	
					9	Nov 16, 2021	SYSTEM	\$24,922.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user aubucj overridding Payment Estimate Exception 18 on the current Payment Estimate.
					9	Nov 16, 2021	SYSTEM	(\$24,922.80)	
					10	Dec 2, 2021	SYSTEM	\$37,516.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user aubucj overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Dec 2, 2021	SYSTEM	(\$37,516.50)	
				- Total				\$0.00	
			Material - To	Material - Total					
	5004 -	· Total						\$0.00	
	5005	CURB AND GUTTER TYPE B	Material		9	Nov 16, 2021	SYSTEM	\$24,671.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user aubucj overridding Payment Estimate Exception 23 on the current Payment Estimate.
					9	Nov 16, 2021	SYSTEM	(\$24,671.25)	
					10	Dec 2, 2021	SYSTEM	\$29,338.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 24 on the current Payment Estimate.
					10	Dec 2, 2021	SYSTEM	(\$29,338.87)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5005 -	· Total						\$0.00	
	5006	MISC. PAVED DRAINAGE	Material		7	Oct 18, 2021	SYSTEM	\$8,878.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user aubucj overridding Payment Estimate Exception 23 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$8,878.62)	
					8	Nov 3, 2021	SYSTEM	\$9,608.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user aubucj overridding Payment Estimate Exception 23 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$9,608.25)	
					9	Nov 16, 2021	SYSTEM	\$9,608.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user aubucj overridding Payment Estimate Exception 28 on the current Payment Estimate.
					9	Nov 16, 2021	SYSTEM	(\$9,608.25)	
					10	Dec 2, 2021	SYSTEM	\$14,802.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user aubucj overridding Payment Estimate Exception 29 on the current Payment Estimate.
					10	Dec 2, 2021	SYSTEM	(\$14,802.78)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5006	Total						\$0.00	
J6S3048 -	Total							\$0.00	
Overall -	Total						\$0.00		