

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 16, 2021

| Progress Estimate Number | Contract ID | 210416-F02 | Pay Period Start | December 2, 2021 | Original Contract Amou | nt\$12,888,486.49 |
|-----------------------------|---------------------|-----------------------------------|---------------------|----------------------|---|-----------------------------------|
| 11 | Prime Contractor | Gershenson Construction Co., Inc. | Pay Period End | December 15, 2021 | Net Change Order Amount Current Contract Amount | \$56,981.50 nt \$12,945,467.99 |

| Approval Date | | By User |
|-------------------|--|---------|
| December 17, 2021 | Generated and Approved (and should be considered Draft) at the Project Office Level by | Aubucj |
| December 17, 2021 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | BAUERD1 |
| December 20, 2021 | Reviewed and Approved at the Central Office Controllers Office Level by | ramses1 |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete |
|--------------------------|-------------------------|------------------------|---------------------------------------|
| September 1, 2023 | September 1, 2023 | | 12.73% |

| | Contract Informational Dat | tes | Milestones |
|------------------------|----------------------------------|----------------|------------|
| Date Description | No Milestones Exist for Contract | | |
| Acceptance Date | | | |
| Awarded Date | May 5, 2021 | May 5, 2021 | |
| Letting Date | April 16, 2021 | April 16, 2021 | |
| Notice to Proceed Date | July 6, 2021 | July 6, 2021 | |
| Work Began Date | July 7, 2021 | July 7, 2021 | |

| Contract Total Pa | ay For Estimate No. 11 | | | |
|-------------------|----------------------------|---------------|----------------|----------------|
| | | This Estimate | Previous | To Date |
| 210416-F02 | | | | |
| | Total Posted Items Pay | \$123,199.65 | \$1,525,311.40 | \$1,648,511.05 |
| | Gross Item Adjustments | \$0.00 | \$0.00 | \$0.00 |
| | Incentive | \$0.00 | \$0.00 | \$0.00 |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 |
| | | | \$1,525,311.40 | \$1,648,511.05 |
| Contract Total Pa | wahle This Estimate | \$123 199 65 | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|---|------|--------------|--------------------------|-----------------------------|
| J6S3048 | 0060 | 3040504 | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) | SQYD | \$7.000 | 1,048.7 | \$7,340.90 |
| | 0180 | 6081012 | TRUNCATED DOMES | SQFT | \$22.230 | 50 | \$1,111.50 |
| | 0190 | 6083006 | 6 IN. CONCRETE MEDIAN STRIP | SQYD | \$58.920 | 12.1 | \$712.93 |
| | 0200 | 6085008 | PAVED APPROACH, 8 IN. | SQYD | \$61.480 | 737.9 | \$45,366.09 |
| | 0210 | 6086004 | CONCRETE SIDEWALK, 4 IN. | SQYD | \$38.800 | 29.3 | \$1,136.84 |
| | 0220 | 6086007 | CONCRETE SIDEWALK, 7 IN. | SQYD | \$55.620 | 43.1 | \$2,397.22 |
| | 0240 | 6089902 | MISC.CONCRETE CURB RAMP, CORAL COLOR | EA | \$1,897.700 | 6 | \$11,386.20 |
| | 0270 | 6089905 | MISC.CONCRETE SIDEWALK, 4 IN., CORAL COLOR | SQYD | \$45.270 | 153.5 | \$6,948.95 |
| | 0290 | 6091010 | CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S | LF | \$31.970 | 345 | \$11,029.65 |
| | 0310 | 6092011 | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A | LF | \$20.780 | 79 | \$1,641.62 |
| | 0740 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | LS | \$40,000.000 | 0.019 | \$760.00 |
| | 1330 | 9025300 | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE | LF | \$11.000 | 408 | \$4,488.00 |
| | 1360 | 9027300 | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE | LF | \$25.000 | 195 | \$4,875.00 |
| | 1430 | 9028810 | PULL BOX, PREFORMED CLASS 1 | EA | \$1,000.000 | 4 | \$4,000.00 |
| | 1440 | 9028811 | PULL BOX, PREFORMED CLASS 2 | EA | \$1,250.000 | 3 | \$3,750.00 |

Revision 4/1/2020 Page 1 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 16, 2021

| Progress Estimate Number | Contract ID | 210416-F02 | Pay Period Start | December 2, 2021 | Original Contract Amount | t \$12,888,486.49 |
|-----------------------------|---------------------|-----------------------------------|---------------------|----------------------|---|---------------------------------|
| 11 | Prime Contractor | Gershenson Construction Co., Inc. | Pay Period End | December 15, 2021 | Net Change Order Amount Current Contract Amount | \$56,981.50 :\$12,945,467.99 |

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount | |
|-------------------------|----------------|--------------|---|------|-------------|--------------------------|-----------------------------|--|
| J6S3048 | 1450 | 9028812 | PULL BOX, PREFORMED CLASS 3 | EA | \$1,600.000 | 1 | \$1,600.00 | |
| | 1460 | 9029100 | BASE, CONCRETE | CUYD | \$1,350.000 | 2.2 | \$2,970.00 | |
| | 1500 | 9029902 | MISC.ADJUST TO GRADE PULL BOX | EA | \$500.000 | 2 | \$1,000.00 | |
| | 5002 | 6081012 | TRUNCATED DOMES | SQFT | \$24.230 | 61 | \$1,478.03 | |
| | 5004 | 6089905 | MISC.Misc. Concrete Sidewalk, 7 IN. Coral Color | SQYD | \$63.000 | 84.9 | \$5,348.70 | |
| | 5005 | 6091052 | CURB AND GUTTER TYPE B | LF | \$31.970 | 58 | \$1,854.26 | |
| | 5006 | 6099903 | MISC.Integral Curb (6 IN Height and Under), Type A, Coral Color | LF | \$21.780 | 92 | \$2,003.76 | |
| Project J6S3048 - Total | | | | | | | | |
| Overall - Total | | | | | | | | |

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|-------------------|-------------|---|--------------------|----------------------------------|---|------------------------|---------------------------------------|-------------------|
| J6S3048 | 0060 | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) | Material | | | -9,583.2 | \$7.00 | (\$67,082.40) |
| | 0060 | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate. | 9,583.2 | \$7.00 | \$67,082.40 |
| (| 0190 | 6 IN. CONCRETE MEDIAN STRIP | Material | | | -12.1 | \$58.92 | (\$712.93) |
| | 0190 | 6 IN. CONCRETE MEDIAN STRIP | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate. | 12.1 | \$58.92 | \$712.93 |
| | 0200 | PAVED APPROACH, 8 IN. | Material | | | -3,747.8 | \$61.48 | (\$230,414.74) |
| | 0200 | PAVED APPROACH, 8 IN. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 5 on the current Payment Estimate. | 3,747.8 | \$61.48 | \$230,414.74 |
| | 0220 | CONCRETE SIDEWALK, 7 IN. | Material | | | -118.1 | \$55.62 | (\$6,568.72) |
| | 0220 | CONCRETE SIDEWALK, 7 IN. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate. | 118.1 | \$55.62 | \$6,568.72 |
| | 0230 | MISC. | Material | | | -7 | \$1,400.00 | (\$9,800.00) |
| | 0230 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate. | 7 | \$1,400.00 | \$9,800.00 |
| | 0310 | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A | Material | | | -173 | \$20.78 | (\$3,594.94) |
| | 0310 | INTEGRAL CURB (6 IN. | Material | | This adjustment offsets the original system- | 173 | \$20.78 | \$3,594.94 |

Revision 4/1/2020 Page 2 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 16, 2021

Pay Period Progress Estimate Contract ID 210416-F02 December 2, 2021 Original Contract Amount \$12,888,486.49 Start Number Pay Period End December 15, 2021 Prime Gershenson Construction Co., Net Change Order 11 \$56,981.50 Contractor Amount Current Contract Amount \$12,945,467.99

| Adjustment amount | Line Item Adjustment Unit Price | Adjustment Quantity | Comments | Other Item Adjustment Type | Adjustment Type | Item Description | Line No. | Project Number |
|----------------------|---------------------------------------|------------------------|---|----------------------------------|--------------------|--------------------------|-------------|-------------------|
| | | | generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | HEIGHT AND UNDER) TYPE A | | J6S3048 |
| (\$4,530.16 | \$101.87 | -44.47 | | | Material | MISC. | 0390 | |
| \$4,530.16 | \$101.87 | 44.47 | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 29 on the current Payment Estimate. | | Material | MISC. | 0390 | |
| (\$42,865.20 | \$63.00 | -680.4 | | | Material | MISC. | 5004 | |
| \$42,865.20 | \$63.00 | 680.4 | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate. | | Material | MISC. | 5004 | |
| (\$31,193.13 | \$31.97 | -975.7 | | | Material | CURB AND GUTTER TYPE B | 5005 | |
| \$31,193.13 | \$31.97 | 975.7 | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 19 on the current Payment Estimate. | | Material | CURB AND GUTTER TYPE B | 5005 | |
| (\$16,806.54 | \$21.78 | -771.65 | | | Material | MISC. | 5006 | |
| \$16,806.54 | \$21.78 | 771.65 | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 24 on the current Payment Estimate. | | Material | MISC. | 5006 | |
| \$0.00 | | | | | | | | otal |

Revision 4/1/2020 Page 3 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | Cor | ntract Project Informat | ion |
|-------------------|----------------------------|--|--------|-------------|-------------------------------|---------------------------------|---------------------------------|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work |
| J6S3048 | FAF- S500(34) | ADA, signals & entrance improvements | 180 | ST LOUIS | from Pennridge Drive to I-17 | 0 | |
| Γotals by J | Job Numbe | rs | | | | | |
| J6S3048 | | | | | This Estimate | Previous | To Date |
| | | d Item Pay | | | \$123,199.65 | \$1,525,311.40 | \$1,648,511.05 |
| | Gross | Item Adjustme | | tem Pay | \$0.00 \$123,199.65 | \$0.00 \$1,525,311.40 | \$0.00 \$1,648,511.05 |
| | | | GIUSSI | temray | \$123,193.03 | \$1,525,511.40 | \$1,040,311.03 |
| | Incent | | | | \$0.00 | \$0.00 | \$0.00 |
| | | entive | | | \$0.00 | \$0.00 | \$0.00 |
| | | lated Damages | | | \$0.00 | \$0.00 | \$0.00 |
| | Other | Contract Adjus | tments | | \$0.00 | \$0.00 | \$0.00 |

Revision 4/1/2020 Page 4 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period | | | |
|---|---|---------------|------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6083006, Project Item Line Number 0190, Material Set 608300696, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6083006, Project Item Line Number 0190, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6083006, Project Item Line Number 0190, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086007, Project Item Line Number 0220, Material Set 608600796, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086007, Project Item Line Number 0220, Material Set 608600796, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086007, Project Item Line Number 0220, Material Set 608600796, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089902, Project Item Line Number 0230, Material Set 608990296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089902, Project Item Line Number 0230, Material Set 608990296, Material 0501CCB1 - Concrete, Class B-1 No Air, Acceptance Action Generic 0501CCB1 is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 0270, Material Set 6089905, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 5004, Material Set 608990596, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 5004, Material Set 608990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 5004, Material Set 608990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 5004, Material Set 608990596, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6091010, Project Item Line Number 0290, Material Set 609101096, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6091010, Project Item Line Number 0290, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6091052, Project Item Line Number 5005, Material Set 609105296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6091052, Project Item Line Number 5005, Material Set 609105296, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6092011, Project Item Line Number 0310, Material Set 609201196, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6092011, Project Item Line Number 0310, Material Set 609201196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6092011, Project Item Line Number 0310, Material Set 609201196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |

Revision 4/1/2020 Page 5 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|--|---|---------------|------------|
| Generic 0501CCPA.A is insufficient. | | | |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 1036RSDFEC28M13 - Rein Steel EC No. 4/M13 Gr 40/M280 @, Acceptance Action Generic ReSteelBars is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6119905, Project Item Line Number 0390, Material Set 6119905, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6119905, Project Item Line Number 0390, Material Set 6119905, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6119905, Project Item Line Number 0390, Material Set 6119905, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6119905, Project Item Line Number 0390, Material Set 6119905, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient. | Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 12/17/21 | Aubucj | Overridden |

Revision 4/1/2020 Page 6 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | eport Generated date and can differ from the posted amo Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------|------|-----------------------------|--------------|--|
| 210416-F02 | J6S3048 | 0001 | 0010 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | Qty | \$895,794.32 | \$179,158.86 |
| | | 0001 | 0020 | 2063000 | CLASS 3 EXCAVATION | 222.00 | 0.00 | 222.00 | CUYD | 0.00 | \$20.00 | \$0.00 |
| | | 0001 | 0030 | 2071000 | LINEAR GRADING CLASS 1 | 25.00 | 0.00 | 25.00 | STA | 3.73 | \$10,515.06 | \$39,221.17 |
| | | 0001 | 0040 | 2072000 | LINEAR GRADING CLASS 2 | 320.50 | 0.00 | 320.50 | STA | 75.61 | \$383.92 | \$29,028.19 |
| | | 0001 | 0050 | 3040183 | TYPE 1 AGGREGATE FOR BASE (8 IN. THICK) | 2,721.00 | 0.00 | 2,721.00 | SQYD | 51.80 | \$12.00 | \$621.60 |
| | | 0001 | 0060 | 3040504 | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) | 33,892.00 | 0.00 | 33,892.00 | SQYD | 9,694.60 | \$7.00 | \$67,862.20 |
| | | 0001 | 0070 | 4011209 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | 704.70 | 0.00 | 704.70 | TONS | 8.00 | \$160.00 | \$1,280.00 |
| | | 0001 | 0080 | 4030109 | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX) | 38,263.90 | 0.00 | 38,263.90 | TONS | 0.00 | \$85.50 | \$0.00 |
| | | 0001 | 0090 | 4079912 | MISC.HARD PENETRATION ASPHALT EMULSION (SS1-VH) | 28,179.00 | 0.00 | 28,179.00 | GAL | 0.00 | \$2.55 | \$0.00 |
| | | 0001 | 0100 | 5021310 | CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. | 697.10 | 0.00 | 697.10 | SQYD | 0.00 | \$82.21 | \$0.00 |
| | | 0004 | 0110 | 6039902 | JOINTS) WATER | 40.00 | 0.00 | 40.00 | EA | 0.00 | \$350.00 | \$0.00 |
| | | 0001 | 0120 | 6039902 | WATER | 40.00 | 0.00 | 40.00 | EA | 0.00 | \$250.00 | \$0.00 |
| | | 0001 | 0130 | 6042010 | ADJUSTING MANHOLE | 65.00 | 0.00 | 65.00 | EA | 0.00 | \$557.35 | \$0.00 |
| | | 0001 | | | | | | | | | | |
| | | 0001 | 0140 | 6042020 | ADJUSTING BASIN OR INLET | 28.00 | 0.00 | 28.00 | EA | 0.00 | \$463.02 | \$0.00 |
| | | 0001 | 0150 | 6044011 | PIPE COLLAR, TYPE A | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$1,033.78 | \$0.00 |
| | | 0001 | 0160 | 6049902 | MISC.CONVERT INLET TO MANHOLE | 5.00 | 0.00 | 5.00 | EA | 0.00 | \$1,550.84 | \$0.00 |
| | | 0001 | 0170 | 6071060 | PEDESTRIAN FENCE (STRUCTURES) | 36.00 | 0.00 | 36.00 | LF | 0.00 | \$157.87 | \$0.00 |
| | | 0001 | 0180 | 6081012 | TRUNCATED DOMES | 4,984.00 | -2,240.00 | 2,744.00 | SQFT | 218.00 | \$22.23 | \$4,846.14 |
| | | 0001 | 0190 | 6083006 | 6 IN. CONCRETE MEDIAN STRIP | 989.00 | 0.00 | 989.00 | SQYD | 12.10 | \$58.92 | \$712.93 |
| | | 0001 | 0200 | 6085008 | PAVED APPROACH, 8 IN. | 11,544.40 | 0.00 | 11,544.40 | SQYD | 3,805.10 | \$61.48 | \$233,937.55 |
| | | 0001 | 0210 | 6086004 | CONCRETE SIDEWALK, 4 IN. | 9,752.20 | 0.00 | 9,752.20 | SQYD | 839.10 | \$38.80 | \$32,557.08 |
| | | 0001 | 0220 | 6086007 | CONCRETE SIDEWALK, 7 IN. | 1,849.90 | 0.00 | 1,849.90 | SQYD | 118.10 | \$55.62 | \$6,568.72 |
| | | 0001 | 0230 | 6089902 | MISC.CONCRETE CURB RAMP | 97.00 | 0.00 | 97.00 | EA | 7.00 | \$1,400.00 | \$9,800.00 |
| | | 0001 | 0240 | 6089902 | MISC.CONCRETE CURB RAMP, CORAL COLOR | 128.00 | 0.00 | 128.00 | EA | 37.00 | \$1,897.70 | \$70,214.90 |
| | | 0001 | 0250 | 6089905 | MISC.CONCRETE SIDEWALK REPAIR, 4 IN. | 80.00 | 0.00 | 80.00 | SQYD | 0.00 | \$62.33 | \$0.00 |
| | | 0001 | 0260 | 6089905 | MISC.CONCRETE SIDEWALK REPAIR, 4 IN., CORAL COLOR | 80.00 | 0.00 | 80.00 | SQYD | 0.00 | \$66.41 | \$0.00 |
| | | 0001 | 0270 | 6089905 | MISC.CONCRETE SIDEWALK, 4 IN., CORAL COLOR | 8,608.30 | -750.00 | 7,858.30 | SQYD | 4,261.20 | \$45.27 | \$192,904.52 |
| | | 0001 | 0280 | 6089905 | MISC.SIDEWALK GRINDING | 15.00 | 0.00 | 15.00 | SQYD | 0.00 | \$50.00 | \$0.00 |
| | | 0001 | 0290 | 6091010 | CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S | 10,374.00 | ., | 3,424.00 | LF | 873.33 | \$31.97 | \$27,920.36 |
| | | 0001 | 0300 | 6091041 | CONCRETE GUTTER TYPE A | 9.00 | 0.00 | 9.00 | LF | 0.00 | \$100.00 | \$0.00 |
| | | 0001 | 0310 | 6092011 | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A | 3,437.00 | 0.00 | 3,437.00 | LF | 173.00 | \$20.78 | \$3,594.94 |
| | | 0001 | 0320 | 6092021 | INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A | 117.00 | 0.00 | 117.00 | LF | 0.00 | \$21.38 | \$0.00 |
| | | 0001 | 0330 | 6092031 | CONCRETE CURB LOW PROFILE TYPE E | 34.00 | 0.00 | 34.00 | LF | 0.00 | \$20.00 | \$0.00 |
| | | 0001 | 0340 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 92.00 | 0.00 | 92.00 | CUYD | 0.00 | \$47.96 | \$0.00 |
| | | 0001 | 0350 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | 92.00 | 0.00 | 92.00 | CUYD | 0.00 | \$54.42 | \$0.00 |
| | | 0001 | 0360 | 6099903 | MISC.LANDSCAPE CURB | 343.00 | 0.00 | 343.00 | LF | 0.00 | \$98.77 | \$0.00 |
| | | 0001 | 0370 | 6099903 | MISC.SLOTTED INTEGRAL CURB | 364.00 | 0.00 | 364.00 | LF | 0.00 | \$19.88 | \$0.00 |
| | | 0001 | 0380 | 6116010A | SLOPE PROTECTION | 955.00 | 0.00 | 955.00 | SQYD | 0.00 | \$91.62 | \$0.00 |
| | | 0001 | 0390 | 6119905 | MISC.SLOPE PROTECTION, CORAL COLOR | 795.00 | 0.00 | 795.00 | SQYD | 44.47 | \$101.87 | \$4,530.16 |
| | | 0001 | 0400 | 6131010 | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR | 179.10 | 0.00 | 179.10 | SQYD | 0.00 | \$271.30 | \$0.00 |
| | | 0001 | 0410 | 6131012 | SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) | 179.00 | 0.00 | 179.00 | SQYD | 0.00 | \$5.00 | \$0.00 |
| | | 0001 | 0420 | 6131013 | TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) | 179.00 | 0.00 | 179.00 | SQYD | 0.00 | \$11.00 | \$0.00 |
| | | 0001 | 0430 | 6131014 | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) | 1,378.00 | 0.00 | 1,378.00 | LF | 0.00 | \$6.00 | \$0.00 |
| | | 0001 | 0440 | 6131015 | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR | 320.00 | 0.00 | 320.00 | EA | 0.00 | \$5.98 | \$0.00 |
| | | 0001 | 0450 | 6141120 | CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X | 5.00 | 0.00 | 5.00 | EA | 0.00 | \$923.77 | \$0.00 |
| | | | | | 600MM) | | | | | | | |

Page 7 of 24 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Note: Posted Q | uantities | and Valu | es are b | pased on R | eport Generated date and can differ from the posted am | ount at the | time the E | stimate was | Genera | ited. | | |
|-------------------------|----------------|----------|-------------|--------------------|--|-----------------|------------------------|------------------------------|--------|------------------------------------|-----------------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 210416-F02 | J6S3048 | 0001 | 0460 | 6141121 | CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM) | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$1,154.78 | \$0.00 |
| | | 0001 | 0470 | 6143010 | MANHOLE FRAME AND COVER, TYPE 1-A | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$320.26 | \$0.00 |
| | | 0001 | 0480 | 6169901 | MISC.TEMPORARY TRAFFIC CONTROL | 1.00 | 0.00 | 1.00 | LS | 0.50 | \$239,762.00 | \$119,881.00 |
| | | 0001 | 0490 | 6169902 | MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED/RETAINED | 6.00 | 0.00 | 6.00 | EA | 2.00 | \$3,200.00 | \$6,400.00 |
| | | 0001 | 0500 | 6179903 | MISC.CONCRETE TRAFFIC BARRIER, TYPE C (PERFORATED) | 665.00 | 0.00 | 665.00 | LF | 0.00 | \$132.86 | \$0.00 |
| | | 0001 | 0510 | 6181000 | MOBILIZATION | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$844,409.28 | \$0.00 |
| | | 0001 | 0511 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 0.50 | \$764,077.28 | \$382,038.64 |
| | | 0001 | 0520 | 6181020 | ADDITIONAL MOBILIZATION FOR SEEDING | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$600.00 | \$0.00 |
| | | 0001 | 0530 | 6191000 | PAVEMENT EDGE TREATMENT | 28,023.00 | 0.00 | 28,023.00 | LF | 0.00 | \$1.29 | \$0.00 |
| | | 0001 | 0540 | 6200009 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE | 4,710.00 | 0.00 | 4,710.00 | LF | 0.00 | \$6.00 | \$0.00 |
| | | 0001 | 0550 | 6200012 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE | 46.00 | 0.00 | 46.00 | LF | 0.00 | \$11.00 | \$0.00 |
| | | 0001 | 0560 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 3,702.00 | 0.00 | 3,702.00 | LF | 0.00 | \$17.00 | \$0.00 |
| | | 0001 | 0570 | 6200018 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. | 154.00 | 0.00 | 154.00 | LF | 0.00 | \$18.00 | \$0.00 |
| | | 0001 | 0580 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, | 315.00 | 0.00 | 315.00 | EA | 0.00 | \$270.00 | \$0.00 |
| | | 0001 | 0590 | 6200024 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, | 38.00 | 0.00 | 38.00 | EA | 0.00 | \$25.00 | \$0.00 |
| | | 0001 | 0600 | 6200027 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, | 24.00 | 0.00 | 24.00 | EA | 0.00 | \$40.00 | \$0.00 |
| | | 0001 | 0610 | 6200036 | COMBINATION STR/LT/RT PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN | 1,356.00 | 0.00 | 1,356.00 | EA | 0.00 | \$180.00 | \$0.00 |
| | | 0001 | 0620 | 6200042 | WHITE MIDBLOCK PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN | 685.00 | 0.00 | 685.00 | EA | 0.00 | \$50.00 | \$0.00 |
| | | 0001 | 0630 | 6205901A | WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT | 74,277.00 | 0.00 | 74,277.00 | LF | 0.00 | \$0.17 | \$0.00 |
| | | 0001 | 0640 | 6205902A | MARKING PAINT, TYPE L BEADS 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING | 107,464.00 | 0.00 | 107,464.00 | LF | 0.00 | \$0.22 | \$0.00 |
| | | 0001 | 0650 | 6205903A | PAINT, TYPE L BEADS 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT | 208.00 | 0.00 | 208.00 | LF | 0.00 | \$1.00 | \$0.00 |
| | | 0001 | 0660 | 6205906A | MARKING PAINT, TYPE L BEADS 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT | 2,029.00 | 0.00 | 2,029.00 | LF | 0.00 | \$2.00 | \$0.00 |
| | | | | | MARKING PAINT, TYPE L BEADS | | | | LF | | | |
| | | 0001 | 0670 | 6207001 6207002 | PAVEMENT MARKING REMOVAL PAVEMENT MARKING REMOVAL (SYMBOLS) | 23,067.00 | 0.00 | 23,067.00 | EA | 0.00 | \$0.75 \$50.00 | \$0.00 \$0.00 |
| | | 0001 | 0690 | 6209902 | MISC.18 IN. WHITE ISLAND TUBULAR MARKIER | 172.00 | 0.00 | 172.00 | EA | 0.00 | \$52.80 | \$0.00 |
| | | 0001 | 0700 | 6209902 | MISC.18 IN. YELLOW ISLAND TUBULAR MARKER | 155.00 | 0.00 | 155.00 | EA | 0.00 | \$52.80 | \$0.00 |
| | | 0001 | 0710 | 6209903 | MISC.PREFORMED THERMOPLASTIC PAVEEMNT MARKING, 6 | 1,061.00 | 0.00 | 1,061.00 | LF | 0.00 | \$6.00 | \$0.00 |
| | | 0001 | 0720 | 6221001 | IN. YELLOW COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF | 281,790.00 | 0.00 | 281,790.00 | SQYD | 0.00 | \$1.33 | \$0.00 |
| | | | | | SURFACING (3 IN. THICK OR LESS) | 276.00 | 0.00 | | SQYD | 0.00 | | \$0.00 |
| | | 0001 | 0730 | 6274000 | PERMANENT EROSION CONTROL GEOTEXTILE CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 276.00 | LS | 0.00 | \$3.50 \$40.000.00 | \$8,360.00 |
| | | 0001 | 0750 | 7039903 | MISC.SPECIAL GUTTER RETAINING WALL | 435.00 | 0.00 | 435.00 | LF | 0.21 | \$102.84 | \$0.00 |
| | | 0001 | 0760 | 7209904 | MISC.SMALL BLOCK RETAINING WALL | 606.00 | 0.00 | 606.00 | SQFT | 0.00 | \$67.83 | \$0.00 |
| | | 0001 | 0770 | 7261012 | 12 IN. PIPE GROUP A | 32.00 | 0.00 | 32.00 | LF | 0.00 | \$167.61 | \$0.00 |
| | | 0001 | 0780 | 7261018 | 18 IN. PIPE GROUP A | 26.00 | 0.00 | 26.00 | LF | 0.00 | \$198.93 | \$0.00 |
| | | 0001 | 0790 | 7310048 | PRECAST CONCRETE MANHOLE - 48 IN. | 5.00 | 0.00 | 5.00 | FT | 0.00 | \$623.31 | \$0.00 |
| | | 0001 | 0800 | 7311022 | PRECAST CONCRETE DROP INLET 2 FT X 2 FT | 20.00 | 0.00 | 20.00 | FT | 0.00 | \$366.12 | \$0.00 |
| | | 0001 | 0810 | 7311042 | PRECAST CONCRETE DROP INLET 4 FT X 2 FT | 10.00 | 0.00 | 10.00 | FT | 0.00 | \$467.70 | \$0.00 |
| | | 0001 | 0820 | 7319902 | MISC.SPECIAL DRAINAGE STRUCTURE | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$5,183.98 | \$0.00 |
| | | 0001 | 0830 | 7319913 | MISC.DOUBLE CURB INLET | 10.00 | 0.00 | 10.00 | FT | 0.00 | \$825.48 | \$0.00 |
| | | 0001 | 0840 | 8031000A | TURF TYPE TALL FESCUE SODDING | 9,697.00 | 0.00 | 9,697.00 | SQYD | 1,005.00 | \$9.50 | \$9,547.50 |
| | | 0001 | 0850 | 8051000A | SEEDING - COOL SEASON MIXTURES | 0.30 | 0.00 | 0.30 | ACRE | 0.00 | \$9,680.00 | \$0.00 |
| | | 0001 | 0860 | 8061005 | ROCK DITCH CHECK | 40.00 | 0.00 | 40.00 | LF | 0.00 | \$12.00 | \$0.00 |
| | | 0001 | 0870 | 8061007A | CURB INLET CHECK | 335.00 | 0.00 | 335.00 | EA | 0.00 | \$95.00 | \$0.00 |

Revision 4/1/2020 Page 8 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract m.CONTRACT | Project No. | Category | Line No. | Item Code | eport Generated date and can differ from the posted amo Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTE To Date (See repo generated date) |
|------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|---|
| 0416-F02 | J6S3048 | 0001 | 0880 | 8061016 | SEDIMENT REMOVAL | 450.00 | 0.00 | 450.00 | CUYD | 0.00 | \$1.00 | \$0.0 |
| | | 0001 | 0890 | 8061017 | TEMPORARY SEEDING AND MULCHING | 0.30 | 0.00 | 0.30 | ACRE | 0.00 | \$4,840.00 | \$0.0 |
| | | 0001 | 0900 | 8061019 | SILT FENCE | 11,135.00 | 0.00 | 11,135.00 | LF | 0.00 | \$2.95 | \$0.0 |
| | | 0001 | 0910 | 8064138 | TYPE 2D EROSION CONTROL BLANKET | 1,528.00 | 0.00 | 1,528.00 | SQYD | 0.00 | \$2.95 | \$0.0 |
| | | 0001 | 0920 | 8069905 | MISC.LANDSCAPING RESTORATION | 500.00 | 0.00 | 500.00 | SQYD | 0.00 | \$35.00 | \$0.0 |
| | | 0010 | 0930 | 6061060 | MGS GUARDRAIL | 175.00 | 0.00 | 175.00 | LF | 0.00 | \$23.90 | \$0.0 |
| | | 0010 | 0940 | 6061068 | MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$3,053.40 | \$0.0 |
| | | 0010 | 0950 | 6061080 | CURB) MGS END ANCHOR | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$1,209.00 | \$0. |
| | | 0010 | 0960 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$2,629.50 | \$0. |
| | | | 0970 | 9011010 | RELOCATED POLE | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$400.00 | \$0. |
| | | 0020 | | | | | | | | | | |
| | | 0020 | 0980 | 9011250 | LUMINAIRE, 150 WATT HIGH PRESSURE SODIUM (UNDERPASS) | 6.00 | -6.00 | 0.00 | EA | 0.00 | \$930.00 | \$0 |
| | | 0020 | 0990 | 9011311 | LUMINAIRE, LED-A | 7.00 | 0.00 | 7.00 | EA | 0.00 | \$300.00 | \$0 |
| | | 0020 | 1000 | 9014003 | CONDUIT, 3 IN. RIGID, PUSHED | 91.00 | 0.00 | 91.00 | LF | 0.00 | \$28.00 | \$0 |
| | | 0020 | 1010 | 9015010 | TRENCHING TYPE I | 26.00 | 0.00 | 26.00 | LF | 0.00 | \$8.00 | \$0 |
| | | 0020 | 1020 | 9016110 | PULL BOX, PREFORMED CLASS 1 | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$1,000.00 | \$0 |
| | | 0020 | 1030 | 9017110 | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET | 90.00 | 0.00 | 90.00 | LF | 0.00 | \$0.85 | \$0 |
| | | 0020 | 1040 | 9017404 | CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG | 140.00 | 0.00 | 140.00 | LF | 0.00 | \$5.80 | \$0 |
| | | 0020 | 1050 | 9017407 | CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE | 30.00 | 0.00 | 30.00 | LF | 0.00 | \$5.30 | \$0 |
| | | 0020 | 1060 | 9018230 | NEUTRAL, 8 AWG POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT) | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$876.00 | \$0 |
| | | 0030 | 1070 | 9020113 | SIGNAL HEAD, TYPE 3T | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$702.00 | \$0 |
| | | 0030 | 1080 | 9020213 | SIGNAL HEAD, TYPE 3S | 9.00 | 0.00 | 9.00 | EA | 0.00 | \$673.00 | \$(|
| | | 0030 | 1090 | 9020215 | SIGNAL HEAD, TYPE 5S | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$931.00 | \$0 |
| | | 0030 | 1100 | 9020513 | SIGNAL HEAD, TYPE 3B | 104.00 | 0.00 | 104.00 | EA | 0.00 | \$875.00 | \$(|
| | | 0030 | 1110 | 9020514 | SIGNAL HEAD, TYPE 4B | 9.00 | 0.00 | 9.00 | EA | 0.00 | \$960.00 | \$(|
| | | 0030 | 1120 | 9020515 | SIGNAL HEAD, TYPE 5B | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$1,217.00 | \$(|
| | | 0030 | 1130 | 9020833 | SH-FLAT SHEET - SIGNAL SIGN | 754.00 | 0.00 | 754.00 | SQFT | 0.00 | \$30.00 | \$1 |
| | | 0030 | 1140 | 9020834 | SIGNAL SIGN, MOUNTING HARDWARE | 95.00 | 0.00 | 95.00 | EA | 0.00 | \$352.00 | \$1 |
| | | 0030 | 1150 | 9022708 | POST, SIGNAL 8 FT. OR 2.4 M | 160.00 | 0.00 | 160.00 | EA | 0.00 | \$526.00 | \$1 |
| | | | 1160 | 9022715 | POST, SIGNAL 15 FT. OR 4.6 M | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$678.00 | |
| | | 0030 | 1170 | 9022715 | POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$7,194.00 | \$1 |
| | | 0030 | 1180 | 9023125 | | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$8,729.00 | \$(|
| | | 0030 | | | POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM | | | | | | | \$(|
| | | 0030 | 1190 | 9023140 | POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$10,217.00 | \$0 |
| | | 0030 | 1200 | 9023145 | POST, TYPE CL, 45 FT. ARM OR 13.7 M ARM | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$10,538.00 | \$(|
| | | 0030 | 1210 | 9023150 | POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$11,345.00 | \$0 |
| | | 0030 | 1220 | 9023155 | POST, TYPE CL, 55 FT. ARM | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$12,722.00 | \$0 |
| | | 0030 | 1230 | 9023220 | POST, TYPE C, 20 FT. ARM OR 6.1 M ARM | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$5,285.00 | \$0 |
| | | 0030 | 1240 | 9023225 | POST, TYPE C, 25 FT. ARM OR 7.6 M ARM | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$6,096.00 | \$0 |
| | | 0030 | 1250 | 9023230 | POST, TYPE C, 30 FT. ARM OR 9.1 M ARM | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$7,084.00 | \$1 |
| | | 0030 | 1260 | 9023235 | POST, TYPE C, 35 FT. ARM OR 10.7 M ARM | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$7,500.00 | \$ |
| | | 0030 | 1270 | 9023240 | POST, TYPE C, 40 FT. ARM OR 12.2 M ARM | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$8,651.00 | \$1 |
| | | 0030 | 1280 | 9023245 | POST, TYPE C, 45 FT. ARM OR 13.7 M ARM | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$8,900.00 | \$0 |
| | | 0030 | 1290 | 9023250 | POST, TYPE C, 50 FT. ARM OR 15.2 M ARM | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$9,235.00 | \$ |
| | | 0030 | 1300 | 9023255 | POST, TYPE C, 55 FT. ARM | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$10,627.00 | \$ |
| | | 0030 | 1310 | 9024283 | CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER | 7.00 | 0.00 | 7.00 | EA | 0.00 | \$15,200.00 | \$ |
| | | 0030 | 1320 | 9025200 | CONDUIT, 2 IN., TRENCH WITH TRACER WIRE | 541.00 | 0.00 | 541.00 | LF | 0.00 | \$8.30 | \$0 |
| | | 0030 | 1330 | 9025300 | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE | 3,675.00 | 0.00 | 3,675.00 | LF | 408.00 | \$11.00 | \$4,488 |

Revision 4/1/2020 Page 9 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 210416-F02 | J6S3048 | 0030 | 1340 | 9025400 | CONDUIT, 4 IN., TRENCH WITH TRACER WIRE | 18.00 | 0.00 | 18.00 | LF | 0.00 | \$12.60 | \$0.00 |
| | | 0030 | 1350 | 9027200 | CONDUIT, 2 IN., PUSHED WITH TRACER WIRE | 205.00 | 0.00 | 205.00 | LF | 0.00 | \$27.00 | \$0.00 |
| | | 0030 | 1360 | 9027300 | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE | 6,873.00 | 0.00 | 6,873.00 | LF | 626.00 | \$25.00 | \$15,650.00 |
| | | 0030 | 1370 | 9027400 | CONDUIT, 4 IN., PUSHED WITH TRACER WIRE | 253.00 | 0.00 | 253.00 | LF | 0.00 | \$25.00 | \$0.00 |
| | | 0030 | 1380 | 9028206 | CABLE, 6 AWG 1 CONDUCTOR, POWER | 910.00 | 0.00 | 910.00 | LF | 0.00 | \$1.40 | \$0.00 |
| | | 0030 | 1390 | 9028208 | CABLE, 8 AWG 1 CONDUCTOR, POWER | 1,220.00 | 0.00 | 1,220.00 | LF | 0.00 | \$1.25 | \$0.00 |
| | | 0030 | 1400 | 9028308 | CABLE, 16 AWG 2 CONDUCTOR | 36,360.00 | 0.00 | 36,360.00 | LF | 0.00 | \$0.85 | \$0.00 |
| | | 0030 | 1410 | 9028310 | CABLE, 16 AWG 5 CONDUCTOR | 35,860.00 | 0.00 | 35,860.00 | LF | 0.00 | \$1.00 | \$0.00 |
| | | 0030 | 1420 | 9028311 | CABLE, 16 AWG 7 CONDUCTOR | 28,720.00 | 0.00 | 28,720.00 | LF | 0.00 | \$1.15 | \$0.00 |
| | | 0030 | 1430 | 9028810 | PULL BOX, PREFORMED CLASS 1 | 28.00 | 0.00 | 28.00 | EA | 5.00 | \$1,000.00 | \$5,000.00 |
| | | 0030 | 1440 | 9028811 | PULL BOX, PREFORMED CLASS 2 | 17.00 | 0.00 | 17.00 | EA | 3.00 | \$1,250.00 | \$3,750.00 |
| | | 0030 | 1450 | 9028812 | PULL BOX, PREFORMED CLASS 3 | 16.00 | 0.00 | 16.00 | EA | 1.00 | \$1,600.00 | \$1,600.00 |
| | | 0030 | 1460 | 9029100 | BASE, CONCRETE | 211.70 | 0.00 | 211.70 | CUYD | 10.12 | \$1,350.00 | \$13,662.00 |
| | | 0030 | 1470 | 9029400 | TEMPORARY TRAFFIC SIGNALS | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$12,000.00 | \$0.00 |
| | | 0030 | 1480 | 9029901 | MISC.POT HOLING UTILITY FACILITIES | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$5,000.00 | \$0.00 |
| | | 0030 | 1490 | 9029901 | MISC.TRAFFIC SIGNAL MAINTENANCE, PROGRAMMING, AND ADJUSTMENT | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$23,000.00 | \$0.00 |
| | | 0030 | 1500 | 9029902 | MISC.ADJUST TO GRADE PULL BOX | 93.00 | 0.00 | 93.00 | EA | 5.00 | \$500.00 | \$2,500.00 |
| | | 0030 | 1510 | 9029902 | MISC.AUDIBLE PEDESTRIAN PUSH BUTTON & SIGNING W/ | 200.00 | 0.00 | 200.00 | EA | 0.00 | \$630.00 | \$0.00 |
| | | 0030 | 1512 | 9029902 | VERBAL WALK MESSAGE MISC.CABINET MODIFICATION – FEE FEE INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$760.00 | \$0.00 |
| | | 0030 | 1514 | 9029902 | MISC.CABINET MODIFICATION – HOME DEPOT INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$760.00 | \$0.00 |
| | | 0030 | 1515 | 9029902 | MISC.CABINET MODIFICATION – ADIE INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$760.00 | \$0.00 |
| | | 0030 | 1516 | 9029902 | MISC.CABINET MODIFICATION – CYPRESS INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$760.00 | \$0.00 |
| | | 0030 | 1518 | 9029902 | MISC.CABINET MODIFICATION – ST. TIMOTHY INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$760.00 | \$0.00 |
| | | 0030 | 1520 | 9029902 | MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S | 189.00 | 0.00 | 189.00 | EA | 0.00 | \$390.00 | \$0.00 |
| | | 0030 | 1522 | 9029902 | MISC.CABINET MODIFICATION – ASHBY INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$890.00 | \$0.00 |
| | | 0030 | 1524 | 9029902 | MISC.CABINET MODIFICATION – INTERNATIONAL PLAZA | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$780.00 | \$0.00 |
| | | 0030 | 1525 | 9029902 | INTERSECTION MISC.CABINET MODIFICATION – ST. GREGORY | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$780.00 | \$0.00 |
| | | | | | INTERSECTION | | | | | | | |
| | | 0030 | 1526 | 9029902 | MISC.CABINET MODIFICATION – WISMER INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$736.00 | \$0.00 |
| | | 0030 | 1527 | 9029902 | MISC.CABINET MODIFICATION – LYNNTOWN INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$780.00 | \$0.00 |
| | | 0030 | 1528 | 9029902 | MISC.CABINET MODIFICATION – EDMUNDSON INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$670.00 | \$0.00 |
| | | 0030 | 1530 | 9029902 | MISC.NETWORK CONNECTED SIGNAL MONITOR | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$1,225.00 | \$0.00 |
| | | 0030 | 1540 | 9029902 | MISC.OPTIONAL DETECTION - DEPAUL INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$18,800.00 | \$0.00 |
| | | 0030 | 1550 | 9029902 | MISC.OPTIONAL DETECTION - EB I-70 RAMPS INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$12,890.00 | \$0.00 |
| | | 0030 | 1560 | 9029902 | MISC.OPTIONAL DETECTION - FEE FEE INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$18,800.00 | \$0.00 |
| | | 0030 | 1570 | 9029902 | MISC.OPTIONAL DETECTION - HILLTOP INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$18,800.00 | \$0.00 |
| | | 0030 | 1580 | 9029902 | MISC.OPTIONAL DETECTION - HOME DEPOT INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$18,800.00 | \$0.00 |
| | | 0030 | 1590 | 9029902 | MISC.OPTIONAL DETECTION - MARK TWAIN INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$18,800.00 | \$0.00 |
| | | 0030 | 1600 | 9029902 | MISC.OPTIONAL DETECTION - ST. TIMOTHY INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$18,800.00 | \$0.00 |
| | | 0030 | 1610 | 9029902 | MISC.OPTIONAL DETECTION - WB I-70 RAMPS INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$12,800.00 | \$0.00 |
| | | 0030 | 1620 | 9029902 | MISC.OPTIONAL DETECTION CYPRESS INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$18,800.00 | \$0.00 |
| | | 0030 | 1630 | 9029902 | MISC.OPTIONAL DETETION - HARMONY INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$18,800.00 | \$0.00 |
| | | 0030 | 1640 | 9029902 | MISC.PAD MOUNTED 120 VOLT SIGNAL POWER SUPPLY | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$3,900.00 | \$0.00 |
| | | 0030 | 1650 | 9029902 | MISC.PAD MOUNTED 120 VOLT SIGNAL POWER SUPPLY & 120 VOLT LIGHTING CONTROLLER | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$5,800.00 | \$0.00 |
| | | 0030 | 1660 | 9029902 | MISC.PAD MOUNTED 120 VOLT SIGNAL POWER SUPPLY & 120 VOLT LIGHTING CONTROLLER WITH UNINTERRUPTIBLE POWER SUPPLY | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$13,600.00 | \$0.00 |
| | | 0030 | 1670 | 9029902 | MISC.PAD MOUNTED 120V/240V SIGNAL POWER SUPPLY & LIGHTING CONTROLLER WITH UNINTERRUPTIBLE POWER | 5.00 | 0.00 | 5.00 | EA | 0.00 | \$15,300.00 | \$0.00 |
| Revision 4/1/202 | 20 | | | | | | | | | | | Page 10 of 24 |



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract | | | | | eport Generated date and can differ from the posted am | Bid | | | Unit | | Heit Deise | T-4-LV-III- DOCTED |
|-------------------------|----------------|----------|-------------|--------------|---|----------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 210416-F02 | J6S3048 | | | | SUPPLY | | | | | | | |
| | | 0030 | 1680 | 9029902 | MISC.SL DISTRICT VIDEO DETECTION SYSTEM | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$18,200.00 | \$0.00 |
| | | 0030 | 1690 | 9029902 | MISC.VIDEO DETECTION MODIFICAITON - ASHBY INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$19,000.00 | \$0.00 |
| | | 0030 | 1700 | 9029902 | MISC.VIDEO DETECTION MODIFICATION - ADIE INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$5,900.00 | \$0.00 |
| | | 0030 | 1710 | 9029902 | MISC.VIDEO DETECTION MODIFICATION - BROWN INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$300.00 | \$0.00 |
| | | 0030 | 1720 | 9029902 | MISC.VIDEO DETECTION MODIFICATION - EDUNDSON INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$300.00 | \$0.00 |
| | | 0030 | 1730 | 9029902 | MISC.VIDEO DETECTION MODIFICATION - INTERNATIONAL PLAZA INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$10,000.00 | \$0.00 |
| | | 0030 | 1740 | 9029902 | MISC.VIDEO DETECTION MODIFICATION - LYNN TOWN INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$10,000.00 | \$0.00 |
| | | 0030 | 1750 | 9029902 | MISC.VIDEO DETECTION MODIFICATION - MCKIBBON INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$10,000.00 | \$0.00 |
| | | 0030 | 1760 | 9029902 | MISC.VIDEO DETECTION MODIFICATION - ST. GREGORY INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$6,000.00 | \$0.00 |
| | | 0030 | 1770 | 9029902 | MISC.VIDEO DETECTION MODIFICATION - ST. JOHN CROSSING INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$350.00 | \$0.00 |
| | | 0030 | 1780 | 9029902 | MISC.VIDEO DETECTION MODIFICATION - WISMER INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$350.00 | \$0.00 |
| | | 0030 | 1790 | 9029902 | MISC.VIDEO DETECTION MODIFICATION - WOODSON INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$350.00 | \$0.00 |
| | | 0030 | 1800 | 9029903 | MISC.2 CONDUCTOR 12 AWG LUMINAIRE CONTROL CABLE | 2,280.00 | 0.00 | 2,280.00 | LF | 0.00 | \$0.90 | \$0.00 |
| | | 0040 | 1810 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | 7.20 | 0.00 | 7.20 | CUYD | 0.00 | \$1,074.00 | \$0.00 |
| | | 0040 | 1820 | 9031220 | PIPE POSTS | 4,930.00 | 0.00 | 4,930.00 | LB | 0.00 | \$4.36 | \$0.00 |
| | | 0040 | 1830 | 9031270A | 2 IN. PSST POST - 12 GA. | 1,983.00 | 0.00 | 1,983.00 | LF | 0.00 | \$14.85 | \$0.00 |
| | | 0040 | 1840 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | 564.00 | 0.00 | 564.00 | LF | 0.00 | \$25.77 | \$0.00 |
| | | 0040 | 1850 | 9031280 | 2.5 IN. PSST POST - 12 GA. | 509.00 | 0.00 | 509.00 | LF | 0.00 | \$16.65 | \$0.00 |
| | | 0040 | 1860 | 9031281 | POST ANCHOR FOR 2.5 IN. PSST - 7 GA. | 132.00 | 0.00 | 132.00 | LF | 0.00 | \$50.37 | \$0.00 |
| | | 0040 | 1870 | 9035004A | SH-FLAT SHEET | 1,732.00 | 0.00 | 1,732.00 | SQFT | 0.00 | \$15.96 | \$0.00 |
| | | 0040 | 1880 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 304.00 | 0.00 | 304.00 | SQFT | 0.00 | \$19.56 | \$0.00 |
| | | 0040 | 1890 | 9039902 | MISC.REMOVE AND RELOCATE EXISTING GROUND MOUNT | 27.00 | 0.00 | 27.00 | EA | 0.00 | \$132.27 | \$0.00 |
| | | 0050 | 1900 | 9108816 | PULL BOX, PREFORMED CLASS 5 | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$1,500.00 | \$0.00 |
| | | 0050 | 1910 | 9109901 | MISC.ITS ASSET MANAGEMENT TOOL | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$7,373.00 | \$0.00 |
| | | 0050 | 1920 | 9109902 | MISC.CCTV CAMERA ASSEMBLY | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$3,600.00 | \$0.00 |
| | | 0050 | 1930 | 9109902 | MISC.FIBER OPTIC PIGTAIL, SM, FURNISH AND INSTALL | 46.00 | 0.00 | 46.00 | EA | 0.00 | \$57.00 | \$0.00 |
| | | 0050 | 1940 | 9109902 | MISC.FIRER OPTIC JUMPER, SM, FURNISH AND INSTALL | 36.00 | 0.00 | 36.00 | EA | 0.00 | \$51.00 | \$0.00 |
| | | 0050 | 1950 | 9109902 | MISC.INSTALL CCTV CAMERA ASSEMBLY | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$1,800.00 | \$0.00 |
| | | 0050 | 1960 | 9109902 | MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - ASHBY INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,000.00 | \$0.00 |
| | | 0050 | 1970 | 9109902 | MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - DEPAUL INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,000.00 | \$0.00 |
| | | 0050 | 1980 | 9109902 | MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - LINDBERGH INTERSECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,000.00 | \$0.00 |
| | | 0050 | 1990 | 9109902 | MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,000.00 | \$0.00 |
| | | 0050 | 2000 | 9109902 | MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,000.00 | \$0.00 |
| | | 0050 | 2010 | 9109902 | NATURAL BRIDGE INTERSECTION MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,000.00 | \$0.00 |
| | | 0050 | 2020 | 9109902 | NB I-270 INTERSECTION MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,000.00 | \$0.00 |
| | | 0050 | 2030 | 9109902 | PENNRIDGE INTERSECTION MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,000.00 | \$0.00 |
| | | 0050 | 2040 | 9109902 | SB I-270 INTERSECTION MISC.SM FIBER OPTIC FUSION SPLICE | 160.00 | 0.00 | 160.00 | EA | 0.00 | \$49.00 | \$0.00 |
| | | 0050 | 2050 | 9109902 | MISC.WALL-MOUNTED INTERCONNECT CENTER, FURNISH AND INSTALL | 7.00 | 0.00 | 7.00 | EA | 0.00 | \$910.00 | \$0.00 |
| | | 0050 | 2060 | 9109903 | MISC.CCTV CAMERA CABLE | 190.00 | 0.00 | 190.00 | LF | 0.00 | \$1.25 | \$0.00 |
| | | 0050 | 2070 | 9109903 | MISC.CONDUIT, 2 - 2 IN., RIGID, IN TRENCH | 140.00 | 0.00 | 140.00 | LF | 0.00 | \$28.00 | \$0.00 |
| | | 0050 | 2080 | 9109903 | MISC.FIBER OPTIC CABLE, 24 STRAND SINGLE MODE | 5,390.00 | 0.00 | 5,390.00 | LF | 0.00 | \$3.25 | \$0.00 |

Page 11 of 24 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|--|------------|-------------|---------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 210416-F02 | J6S3048 | 0050 | 2090 | 9109903 | MISC.MODOT ITS ASSETS RELOCATION | 1,000.00 | 0.00 | 1,000.00 | LF | 0.00 | \$11.00 | \$0.00 |
| | | 0001 | 5001 | 6189901 | MISC.Contract Bond Payment | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$80,332.00 | \$80,332.00 |
| | | 0001 | 5002 | 6081012 | TRUNCATED DOMES | 0.00 | 2,240.00 | 2,240.00 | SQFT | 529.10 | \$24.23 | \$12,820.09 |
| | | 0020 | 5003 | 9019902 | MISC.Luminaire, LED Wall Pack (Underpass) | 0.00 | 6.00 | 6.00 | EA | 0.00 | \$930.00 | \$0.00 |
| | | 0001 | 5004 | 6089905 | MISC.Misc. Concrete Sidewalk, 7 IN. Coral Color | 0.00 | 750.00 | 750.00 | SQYD | 686.40 | \$63.00 | \$43,243.20 |
| | | 0001 | 5005 | 6091052 | CURB AND GUTTER TYPE B | 0.00 | 6,950.00 | 6,950.00 | LF | 975.70 | \$31.97 | \$31,193.13 |
| | | 0001 | 5006 | 6099903 | MISC.Integral Curb (6 IN Height and Under), Type A, Coral Color | 0.00 | 1,800.00 | 1,800.00 | LF | 783.65 | \$21.78 | \$17,067.90 |
| | Project J6S3048 - Total Value Posted to Date as of Report Generated Date | | | | | | | | | | | |
| 210416-F02 Ove | rall - Total | Value Post | ed to Dat | te as of Repo | ort Generated Date | | | | | | | \$1,662,292.79 |

Revision 4/1/2020 Page 12 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3048

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------------|--|-------------|-------------------------|--------------------|-------|--|------------------------------|---------------------|----------------------------|---------------------|--|
| 0060 | 3040504 | TYPE 5 AGGREGATE FOR BASE | 12/2/21 | 12/10/21 | 2.00 | SQYD | | 0 | | | | Adjusting quantities from 11-24-21 |
| | | | 12/3/21 | 12/13/21 | 192.40 | SQYD | WB 180 | 419+34.93 LT | | 396+90.21 LT | | Underneath various areas of sidewalk in islands and driveways. |
| | | | 12/6/21 | 12/14/21 | 159.00 227.10 | | Driveways in front of Title Loans and East half of Wright | 380+06.20 | | 375+07.68 | | |
| | | | 12/8/21 | 12/14/21 | 139.70 | SQYD | Avenue. | LT 400+29.96 | | 114+61.71 | | Underneath various sections of driveways and sidewalk |
| | | | 12/9/21 | 12/15/21 | 160.00 | SQYD | | LT 500+95.83 | | LT | | |
| | | | 12/10/21 | 12/15/21 | 12.40 | SQYD | | LT 344+90 | | | | |
| | | | 12/14/21 | 12/15/21 | 156.10 | SQYD | Endicott, Walton, and Marshall | LT 500+95.83 | | 474+64.83 | | |
| 0180 | 6081012 | TRUNCATED DOMES | 12/3/21 | 12/13/21 | 50.00 | SQFT | 180 and Edmundson Islands | LT 419+34.93 | | LT 418+48.42 | | 5 sets of 5' x 2' domes in islands. |
| 0190 | 6083006 | 6 IN. CONCRETE MEDIAN STRIP | 12/3/21 | 12/13/21 | 12.10 | SQYD | NE Corner of Edmundson | LT 419+34.93 | | LT 419+16.88 | | Plan quantity for reconstructed island. |
| 0200 | 6085008 | PAVED APPROACH, 8 IN. | 12/2/21 | 12/10/21 | 2.00 | SQYD | | LT 0 | | LT | | Adjusting quantities from 11-24-21 |
| | | | 12/3/21 | 12/13/21 | 156.00 | SQYD | WB 180 between Advance Auto Parts and Produce Stand | 397+57.91 | | 396+90.21 | | Sta 397+57.91 LT: 13.5' x 35' = 52.5 sqyd |
| | | | 10/7/01 | 10/14/01 | 227 10 | eovn | Driveweys in front of Title Leans and East half of Wright | 200+06 20 | | 275±07 69 | | Sta 396+90.21 LT: 13.5' x 69' = 103.5 sqyd |
| | | | 12/7/21 | 12/14/21 | 227.10 | SQYD | Driveways in front of Title Loans and East half of Wright Avenue. | 380+06.20 LT | | 375+07.68 LT | | STA 380-06.20 LT West half: 12.5' x 19.5' = 27.1 sqyd STA 379-11.76 LT: 15' x 66' = 110 sqyd STA 378-51.54 LT: 36.5' x 11.5' = 46.6 sqyd STA 375-07.68 LT Wright Rd. E half: 16' x 15' square a 16' x 19.5' triangle = 44 sqyd |
| | | | 12/8/21 | 12/14/21 | 103.70 | SQYD | Driveway between taco bell and advance auto parts and driveway between Adie and gifted center. | 400+29.96 LT | | 314+61.71 LT | | STA 400+29.96 LT: 16' x 30' square and 16' x 9.5' triang = 61.8 sqyd STA 314+61.71 LT: 14.5' x 26' = 41.9 sqyd |
| | | | 12/9/21 | 12/15/21 | 93.00 | SQYD | Endicott | 500+95.83 LT | | | | 31' x 15' square and 31' x 24' triangle = 93 sqyd |
| | | | 12/14/21 | 12/15/21 | 156.10 | SQYD | Endicott, Walton, and Marshall | 500+95.83 LT | | 474+64.83 LT | | Endicott middle section STA 500+95.83 LT: 13' x 30.5' = 44.1 sqyd |
| | | | | | | | | Li | | Li | | Walton East half STA 497+04.73 LT: 13.5' x 16' square and 13.5' x 16' triangle = 36 sqyd Marshall East half STA 474+04.83 LT: 19' x 27' square and 19' x 18' triangle = 76 sqyd |
| 0210 | 6086004 | CONCRETE SIDEWALK, 4 IN. | 12/8/21 | 12/14/21 | 29.30 | SQYD | WB 180 West of Adie Rd. | 314+80 LT | | 315+24 LT | | 44' x 6' = 29.3 sqyd |
| 0220 | 6086007 | CONCRETE SIDEWALK, 7 IN. | 12/3/21 | 12/13/21 | 36.40 | SQYD | 180 and Edmundson Islands | 419+34.93 LT | | 418+48.42 LT | | NE island: 18.9 sqyd NW island: 31.5' x 5' = 17.5 sqyd |
| | | | 12/8/21 | 12/14/21 | 6.70 | SQYD | WB 180 West of Adie Rd. | 314+70 LT | | 314+80 LT | | 6' x 10' = 6.7 sqyd |
| 0240 | 6089902 | MISC. CONCRETE | 12/6/21 | 12/14/21 | 1.00 | EA | NW Edmundson | 418+36.28 LT | | | | |
| | | | 12/9/21 | 12/15/21 | 2.00 | EA | NE corner of International Plaza. | 354+35.78 LT | | 354+18.51 LT | | |
| | | | 12/10/21 | 12/15/21 | 3.00 | EA | International and Ashby | 353+58.62 LT | | 345+34.90 LT | | 1 ramp NW International 2 ramps NE Ashby |
| 0270 | 6089905 | MISC. CONCRETE | 12/6/21 | 12/14/21 | 120.00 | | | 0 | | | | |
| | | | 12/9/21 | 12/15/21 | 21.10 | | WB 180 | 418+10 LT 344+90 | | 354+50 LT | | In front of Advance Auto Parts: 7' x 15.5' = 12.1 sqyd Edmundson NW corner: 5' x 5' = 2.8 sqyd International Plaza NE corner: 8' x 7' = 6.2 sqyd |
| 0290 | 6091010 | CONCRETE CURB (6 IN. HEIGHT AND UNDER) | 12/3/21 | 12/13/21 | 44.50 | LF | | LT 418+25 | | 407+10 | | NW corner of Edmundson: 32' |
| | | | 12/6/21 | 12/14/21 | 257.00 | I F | WB 180 at St. Timothy, Ashby, and International | LT 354+50 | | LT 336+96.86 | | In front of big Jay's: 12.5' St. Timothy: 94 ft |
| | | | | | | | | LT | | LT | | Ashby: 75 ft International Plaza: 88 ft |
| | | | 12/8/21 | 12/14/21 | 9.50 | LF | WB 180 west of Adie. | 315+00 LT | | | | |
| | | | 12/14/21 | 12/15/21 | 34.00 | LF | | 497+04.73 LT | | 474+64.83 LT | | 17' at Walton 17' at Marshall |
| 0310 | 6092011 | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) | 12/3/21 | 12/13/21 | 69.00 | | Edmundson NW island | 418+48.42 LT | | 418+75.30 LT | | |
| | | | 12/8/21 | 12/14/21 | 10.00 | LF | WB 180 west of Adie. | 314+70 LT | | 314+80 LT | | |
| | 6274000 9025300 | CONTRACTOR FURNISHED SURVEYING AND STAKI CONDUIT, 3 IN., TRENCH WITH TRACER WIRE | 12/15/21 | 12/16/21 | 0.02 | LS | | 0 | | | | Getting signal items up to date. |
| | 9027300 | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE | 12/15/21 | 12/16/21 | 195.00 | LF | | 0 | | | | Getting signal items up to date. |
| | 9028810 | PULL BOX, PREFORMED CLASS 1 | 12/15/21 | 12/16/21 | 4.00 | EA | | 0 | | | | Getting signal items up to date. |
| 1440 | 9028811 | PULL BOX, PREFORMED CLASS 2 | 12/15/21 | 12/16/21 | 3.00 | EA | | 0 | | | | Getting signal items up to date. |
| 1450 | 9028812 | PULL BOX, PREFORMED CLASS 3 | 12/3/21 | 12/13/21 | 1.00 | EA | NE island at Cypress. | 328+90 LT | | | | |
| 1460 | 9029100 | BASE, CONCRETE | 12/3/21 | 12/13/21 | 1.76 0.44 | | 180 and Cypress islands | 328+10.80 LT | | 328+85.89 LT | | C Bases 1, 2, 3, and 4 on Cypress Islands. Getting signal items up to date. |
| 1500 | 9029902 | MISC. | 12/3/21 | 12/13/21 | 1.00 | | NE island at Cypress. | 328+90 LT | | | | |
| | | | 12/9/21 | 12/15/21 | 1.00 | EA | NE corner of Edmundson. | 418+15 LT | | | | |
| 5002 | 6081012 | TRUNCATED DOMES | 12/6/21 | 12/14/21 | 10.00 | SQFT | NW Edmundson | 418+36.28 LT | | | | |
| | | | 12/9/21 | 12/15/21 | 21.00 | SQFT | NE corner of International Plaza. | 354+35.78 LT | | 354+18.51 LT | | 5' x 2' = 10 sqft 5.5' x 2' = 11 sqft |
| | | | 12/10/21 | 12/15/21 | 30.00 | SQFT | International and Ashby | 353+58.62 LT | | 345+34.90 LT | | 10 sqft NW International 20 sqft NE Ashby |
| 5004 | 6089905 | MISC. CONCRETE | 12/6/21 | 12/14/21 | 39.00 | SQYD | | 0 | | | | |
| | | | 12/9/21 | 12/15/21 | 45.90 | SQYD | WB 180 | 400+00 LT | | 378+20 LT | | In front of Advance Auto Parts: 7' x 10' = 7.8 sqyd Sidewalk in front of manhole conversion #25: 6.5' x 20' = 14.4 sqyd Sidewalk in front of Title Loans: 7' x 20.5' = 15.9 sqyd Sidewalk by 9793 and Advance Auto Parts: 7' x 10' = 7.8 sqyd |
| | | | | | 20.50 | LE | | 397+57.91 | | 396+90.21 | | Sta 397+57 91 T: 10 5' |
| 5005 | 6091052 | CURB AND GUTTER TYPE B | 12/3/21 | 12/13/21 | 20.50 | LF | | 397+57.91 LT | | LT | | Sta 396+90.21 LT: 10' |

Revision 4/1/2020 Page 13 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|------------------------|-------------|-------------------------|--------------------|-------|----------|------------------------------|---------------------|----------------------------|---------------------|--|
| 5005 | 6091052 | CURB AND GUTTER TYPE B | 12/8/21 | 12/14/21 | 19.50 | LF | | 400+29.96 LT | | 314+61.71 LT | | STA 400+29.96 LT: 11.5' STA 314+61.71 LT: 8' |
| 5006 | 6099903 | MISC. PAVED DRAINAGE | 12/6/21 | 12/14/21 | 32.00 | LF | | 0 | | | | |
| | | | 12/9/21 | 12/15/21 | 60.00 | LF | | 400+00 LT | | 378+20 LT | | In front of Advance Auto Parts: 17' Sidewalk in front of manhole conversion #25: 21' Sidewalk in front of Title Loans: 22' |

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 14 of 24



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J6S3048 | 0050 | TYPE 1 AGGREGATE FOR BASE (8 | Material | | 7 | Oct 18, 2021 | SYSTEM | \$621.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | IN. THICK) | | | 7 | Oct 18, 2021 | SYSTEM | (\$621.60) | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | \$621.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$621.60) | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | \$621.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | (\$621.60) | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | \$621.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | (\$621.60) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0050 - | Total | | | | | | \$0.00 | |
| | 0060 | TYPE 5 AGGREGATE FOR BASE | Material | | 3 | Aug 17, 2021 | SYSTEM | \$3,244.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 3 | Aug 16, 2021 | SYSTEM | (\$3,244.50) | |
| | | | | | 4 | Sep 3, 2021 | SYSTEM | \$10,092.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 4 | Sep 2, 2021 | SYSTEM | (\$10,092.60) | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | \$17,085.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | (\$17,085.60) | |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | \$32,813.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schmij8 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | (\$32,813.20) | |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | \$36,999.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | (\$36,999.90) | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | \$44,692.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$44,692.20) | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | \$50,205.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | (\$50,205.40) | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | \$59,741.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | (\$59,741.50) | |
| | | | | | 11 | Dec 17, 2021 | SYSTEM | \$67,082.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | |
|---------|--------|--------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|-----------------|--|----------|---|
| J6S3048 | 0060 | TYPE 5 AGGREGATE FOR BASE | Material | | 11 | Dec 17, 2021 | SYSTEM | (\$67,082.40) | Estimate Exception 1 on the current Payment Estimate. | | |
| | | | | - Total | | 2021 | | \$0.00 | | | |
| | | | Material - To | | | | | \$0.00 | | | |
| | 0060 - | Total | | | | | | \$0.00 | | | |
| | 0180 | TRUNCATED DOMES | Material | | 2 | Aug 3, 2021 | SYSTEM | \$866.97 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate. | | |
| | | | | | 2 | Aug 3, 2021 | SYSTEM | (\$866.97) | | | |
| | | | | | 3 | Aug 17, 2021 | SYSTEM | \$2,489.76 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate. | | |
| | | | | | 3 | Aug 16, 2021 | SYSTEM | (\$2,489.76) | | | |
| | | | | | 4 | Sep 3, 2021 | SYSTEM | \$4,468.23 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate. | | |
| | | | | | 4 | Sep 2, 2021 | SYSTEM | (\$4,468.23) | | | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | \$6,557.85 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate. | | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | (\$6,557.85) | | | |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | \$7,080.26 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schmij8 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | (\$7,080.26) | | | |
| | | | | | | | 7 | Oct 18, 2021 | SYSTEM | \$222.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | (\$222.30) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | otal | | | | \$0.00 | | | |
| | 0180 - | Total | | | | | | \$0.00 | | | |
| | 0190 | 6 IN. CONCRETE MEDIAN STRIP | Material | | 11 | Dec 17, 2021 | SYSTEM | \$712.93 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate. | | |
| | | OHAF | | | 11 | Dec 17, 2021 | SYSTEM | (\$712.93) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | otal | | | | \$0.00 | | | |
| | 0190 - | Total | | | | | | \$0.00 | | | |
| | 0200 | PAVED APPROACH, 8 IN. | Material | | 2 | Aug 3, 2021 | SYSTEM | \$5,027.83 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate. | | |
| | | | | | 2 | Aug 3, 2021 | SYSTEM | (\$5,027.83) | | | |
| | | | | | 3 | Aug 17, 2021 | SYSTEM | \$18,276.77 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 3 on the current Payment Estimate. | | |
| | | | | | 3 | Aug 16, 2021 | SYSTEM | (\$18,276.77) | | | |
| | | | | | 4 | Sep 3, 2021 | SYSTEM | \$50,941.10 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 3 on the current Payment Estimate. | | |
| | | | | | 4 | Sep 2, 2021 | SYSTEM | (\$50,941.10) | | | |



MoDOT

Line Item Adjustments by Estimate

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|------------------|--|
| J6S3048 | 0200 | PAVED APPROACH, 8 IN. | Material | | 5 | Sep 16, 2021 | SYSTEM | \$78,428.81 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | (\$78,428.81) | |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | \$93,215.98 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | (\$93,215.98) | |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | \$108,407.68 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | (\$108,407.68) | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | \$120,371.69 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$120,371.69) | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | \$148,080.73 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | (\$148,080.73) | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | \$185,048.65 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | (\$185,048.65) | |
| | | | | | 11 | Dec 17, 2021 | SYSTEM | \$230,414.74 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 11 | Dec 17, 2021 | SYSTEM | (\$230,414.74) | |
| | | | | - Total | | | | \$0.00 | |
| | 0200 - | Total | Material - To | otal | | | | \$0.00 \$0.00 | |
| | 0210 | CONCRETE SIDEWALK, 4 IN. | Material | | 2 | Aug 3, 2021 | SYSTEM | \$129.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 2 | Aug 3, 2021 | SYSTEM | (\$129.20) | |
| | | | | | 3 | Aug 17, 2021 | SYSTEM | \$594.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 3 | Aug 16, 2021 | SYSTEM | (\$594.80) | |
| | | | | | 4 | Sep 3, 2021 | SYSTEM | \$594.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 4 | Sep 2, 2021 | SYSTEM | (\$594.80) | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | \$1,972.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | (\$1,972.20) | |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | \$2,002.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schmij8 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | (\$2,002.08) | |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | \$2,242.64 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|---------|--------|--------------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|--|--|
| J6S3048 | 0210 | CONCRETE | Material | | | | | | Estimate Exception 9 on the current Payment Estimate. | |
| | | SIDEWALK, 4 IN. | | | 7 | Oct 18, 2021 | SYSTEM | (\$2,242.64) | | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | \$25,670.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate. | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$25,670.08) | | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | \$31,420.24 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate. | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | (\$31,420.24) | | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | \$31,420.24 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate. | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | (\$31,420.24) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | otal | | | | \$0.00 | | |
| | 0210 - | Total | | | | | | \$0.00 | | |
| | 0220 | CONCRETE SIDEWALK, 7 IN. | Material | | 7 | Oct 18, 2021 | SYSTEM | \$506.14 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate. | |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | (\$506.14) | | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | \$2,285.98 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate. | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$2,285.98) | | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | \$3,276.02 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate. | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | (\$3,276.02) | | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | \$4,171.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 9 on the current Payment Estimate. | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | (\$4,171.50) | | |
| | | | | | | 11 | Dec 17, 2021 | SYSTEM | \$6,568.72 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 11 | Dec 17, 2021 | SYSTEM | (\$6,568.72) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - T | Total | | | | \$0.00 | | |
| | 0220 - | Total | | | | | | \$0.00 | | |
| | 0230 | MISC. CONCRETE | Material | | 8 | Nov 3, 2021 | SYSTEM | \$1,400.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 11 on the current Payment Estimate. | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$1,400.00) | | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | \$9,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate. | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | (\$9,800.00) | | |
| | | | | | 10 | 10 | Dec 2, 2021 | SYSTEM | \$9,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 10 | Dec 2, | SYSTEM | (\$9,800.00) | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-------------------|--------------------|-----------------------------|----------------|-----------------|----------------|---------------|--|
| J6S3048 | 0230 | MISC. | Material | | | 2021 | | | |
| | | CONCRETE | | | 11 | Dec 17, 2021 | SYSTEM | \$9,800.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 11 | Dec 17, 2021 | SYSTEM | (\$9,800.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0230 - | Total | | | | | | \$0.00 | |
| | 0240 | MISC. CONCRETE | Material | | 2 | Aug 3, 2021 | SYSTEM | \$3,795.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 2 | Aug 3, 2021 | SYSTEM | (\$3,795.40) | |
| | | | | | 3 | Aug 17, 2021 | SYSTEM | \$9,488.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 3 | Aug 16, 2021 | SYSTEM | (\$9,488.50) | |
| | | | | | 4 | Sep 3, 2021 | SYSTEM | \$18,977.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 4 | Sep 2, 2021 | SYSTEM | (\$18,977.00) | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | \$30,363.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | (\$30,363.20) | |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | \$39,851.70 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schmij8 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | (\$39,851.70) | |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | \$41,749.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | (\$41,749.40) | |
| | | | | | 8 | 8 | Nov 3, 2021 | SYSTEM | \$41,749.40 |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$41,749.40) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | Total | | | | \$0.00 | |
| | 0240 - | Total | | | | | | \$0.00 | |
| | 0270 | MISC. CONCRETE | Material | | 2 | Aug 3, 2021 | SYSTEM | \$11,173.99 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 2 | Aug 3, 2021 | SYSTEM | (\$11,173.99) | |
| | | | | | 3 | Aug 17, 2021 | SYSTEM | \$30,368.47 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 3 | Aug 16, 2021 | SYSTEM | (\$30,368.47) | |
| | | | | | 4 | Sep 3, 2021 | SYSTEM | \$50,604.16 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 4 | Sep 2, 2021 | SYSTEM | (\$50,604.16) | |
| | | | | | 5 | Sep 16, | SYSTEM | \$73,977.07 | This adjustment offsets the original system-generated Material Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | |
|---------|--------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|-----------------|---|--|---|
| J6S3048 | 0270 | MISC. CONCRETE | Material | | | 2021 | | | Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate. | | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | (\$73,977.07) | | | |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | \$128,652.81 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schmij8 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | (\$128,652.81) | | | |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | \$102,251.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 14 on the current Payment Estimate. | | |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | (\$102,251.80) | | | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | \$110,622.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 15 on the current Payment Estimate. | | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$110,622.22) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - T | otal | | | | \$0.00 | | | |
| | 0270 - | Total | | | | | | \$0.00 | | | |
| | 0290 | CONCRETE CURB (6 IN. HEIGHT AND | Material | Material | | 2 | Aug 3, 2021 | SYSTEM | \$8,392.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 23 on the current Payment Estimate. | |
| | | UNDER) | | | 2 | Aug 3, 2021 | SYSTEM | (\$8,392.12) | | | |
| | | | | | 3 | Aug 17, 2021 | SYSTEM | \$12,036.70 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 18 on the current Payment Estimate. | | |
| | | | | | 3 | Aug 16, 2021 | SYSTEM | (\$12,036.70) | | | |
| | | | | | 4 | Sep 3, 2021 | SYSTEM | \$12,644.14 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 12 on the current Payment Estimate. | | |
| | | | | | 4 | Sep 2, 2021 | SYSTEM | (\$12,644.14) | | | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | \$14,961.96 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 12 on the current Payment Estimate. | | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | (\$14,961.96) | | | |
| | | | | | | | 6 | Oct 4, 2021 | SYSTEM | \$15,217.72 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schmij8 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | (\$15,217.72) | | | |
| | | | | | | 7 | Oct 18, 2021 | SYSTEM | \$7,827.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user aubucj overridding Payment Estimate Exception 19 on the current Payment Estimate. | |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | (\$7,827.22) | | | |
| | | | | | | | 8 | Nov 3, 2021 | SYSTEM | \$9,809.36 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user aubucj overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$9,809.36) | | | |
| | | | | | | 9 | 9 | Nov 16, 2021 | SYSTEM | \$13,198.18 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | (\$13,198.18) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - T | otal | | | | \$0.00 | | | |

MoDOT

Line Item Adjustments by Estimate

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|-----------------|--------------|---|--|----|----|----|----|-----------------|--------|------------|--|
| J6S3048 | 0290 - | Total | | | | | | \$0.00 | | | | | | | | | | |
| | 0310 | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) | Material | | 4 | Sep 3, 2021 | SYSTEM | \$2,618.28 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | | | | | | | |
| | | ONDEN | | | 4 | Sep 2, 2021 | SYSTEM | (\$2,618.28) | | | | | | | | | | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | \$4,550.82 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | (\$4,550.82) | | | | | | | | | | |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | \$4,737.84 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schmij8 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 6 | Oct 4, 2021 | SYSTEM | (\$4,737.84) | | | | | | | | | | |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | \$103.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user aubucj overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | (\$103.90) | | | | | | | | | | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | \$664.96 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user aubucj overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$664.96) | | | | | | | | | | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | \$1,787.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 25 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | (\$1,787.08) | | | | | | | | | | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | \$1,953.32 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 26 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | (\$1,953.32) | | | | | | | | | | |
| | | | | | | | | | 1 | 11 | 11 | 11 | 11 | 11 | Dec 17, 2021 | SYSTEM | \$3,594.94 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | | 11 | Dec 17, 2021 | SYSTEM | (\$3,594.94) | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | | |
| | 0310 - | Total | | | | | | \$0.00 | | | | | | | | | | |
| | 0390 | MISC. EMBANKMENT PROTECTION | Material | rial | 2 | Aug 3, 2021 | SYSTEM | \$3,175.29 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 27 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 2 | Aug 3, 2021 | SYSTEM | (\$3,175.29) | | | | | | | | | | |
| | | | | | | 3 | Aug 17, 2021 | SYSTEM | \$3,175.29 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | | | | | | |
| | | | | | 3 | Aug 16, 2021 | SYSTEM | (\$3,175.29) | | | | | | | | | | |
| | | | | | 4 | Sep 3, 2021 | SYSTEM | \$3,175.29 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 4 | Sep 2, 2021 | SYSTEM | (\$3,175.29) | | | | | | | | | | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | \$3,175.29 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 5 | Sep 16, 2021 | SYSTEM | (\$3,175.29) | | | | | | | | | | |



| Project Line Description Adjustment Type Adjustment Type Date Date Date Date Date Date Date Dat | m-generated Material Payment user schmijß overridding Payment yment Estimate. m-generated Material Payment user aubucj overridding Payment yment Estimate. m-generated Material Payment |
|--|---|
| EMBANKMENT PROTECTION 2021 Estimate Item Adjustment (0003) due to user's Estimate Exception 17 on the current Paymen | user schmijß overridding Payment yment Estimate. m-generated Material Payment user aubucj overridding Payment yment Estimate. m-generated Material Payment |
| 2021 7 Oct 18, 2021 8 SYSTEM \$3,175.29 This adjustment offsets the original system-ge Estimate Item Adjustment (0004) due to user a Estimate Exception 28 on the current Paymen 7 Oct 18, 2021 8 Nov 3, 2021 8 Nov 3, 2021 8 Nov 3, SYSTEM (\$3,175.29) This adjustment offsets the original system-ge Estimate Item Adjustment (0004) due to user a Estimate Item Adjustment (0004) due to user a Estimate Exception 27 on the current Paymen 8 Nov 3, SYSTEM (\$3,175.29) | user aubucj overridding Payment yment Estimate. m-generated Material Payment |
| Estimate Item Adjustment (0004) due to user a Estimate Exception 28 on the current Paymen 7 Oct 18, 2021 8 Nov 3, SYSTEM \$3,175.29 8 Nov 3, SYSTEM \$3,175.29 This adjustment offsets the original system-ge Estimate Item Adjustment (0004) due to user a Estimate Exception 27 on the current Paymen 8 Nov 3, SYSTEM (\$3,175.29) | user aubucj overridding Payment yment Estimate. m-generated Material Payment |
| 8 Nov 3, 2021 8 Nov 3, 2021 SYSTEM \$3,175.29 This adjustment offsets the original system-ge Estimate Item Adjustment (0004) due to user a Estimate Exception 27 on the current Paymen 8 Nov 3, SYSTEM (\$3,175.29) | |
| 2021 Estimate Item Adjustment (0004) due to user a Estimate Exception 27 on the current Paymen 8 Nov 3, SYSTEM (\$3,175.29) | |
| | |
| | |
| 9 Nov 16, 2021 SYSTEM \$3,175.29 This adjustment offsets the original system-ge Estimate Item Adjustment (0003) due to user a Estimate Exception 32 on the current Paymen | user aubucj overridding Payment |
| 9 Nov 16, SYSTEM (\$3,175.29) | |
| 10 Dec 2, 2021 SYSTEM \$4,530.16 This adjustment offsets the original system-ge Estimate Item Adjustment (0003) due to user a Estimate Exception 34 on the current Paymen | user aubucj overridding Payment |
| 10 Dec 2, 2021 SYSTEM (\$4,530.16) | |
| Dec 17, SYSTEM \$4,530.16 This adjustment offsets the original system-ge Estimate Item Adjustment (0002) due to user a Estimate Exception 29 on the current Paymen | user aubucj overridding Payment |
| 11 Dec 17, 2021 (\$4,530.16) | |
| - Total \$0.00 | |
| 10.11 | |
| Material - Total \$0.00 | |
| | |
| Material - Total \$0.00 | user aubucj overridding Payment |
| Material - Total \$0.00 0390 - Total \$0.00 0480 MISC. Material 3 Aug 17, SYSTEM \$11,988.10 This adjustment offsets the original system-ge Estimate Item Adjustment (0003) due to user a | user aubucj overridding Payment |
| Material - Total \$0.00 0390 - Total 0480 MISC. Material 3 Aug 17, 2021 \$11,988.10 This adjustment offsets the original system-ge Estimate Item Adjustment (0003) due to user a Estimate Exception 25 on the current Payment 3 Aug 16, SYSTEM (\$11,988.10) | user aubucj overridding Payment |
| Material - Total \$0.00 | user aubucj overridding Payment |
| Material - Total \$0.00 | user aubucj overridding Payment |
| Material - Total \$0.00 | user aubucj overridding Payment yment Estimate. m-generated Material Payment user aubucj overridding Payment |
| Material - Total \$0.00 | user aubucj overridding Payment yment Estimate. m-generated Material Payment user aubucj overridding Payment |
| Material - Total \$0.00 | user aubucj overridding Payment yment Estimate. m-generated Material Payment user aubucj overridding Payment |
| Material - Total \$0.00 | user aubucj overridding Payment yment Estimate. m-generated Material Payment user aubucj overridding Payment |
| Material - Total \$0.00 | user aubucj overridding Payment yment Estimate. m-generated Material Payment user aubucj overridding Payment |
| Material - Total \$0.00 | m-generated Material Payment yment Estimate. m-generated Material Payment user aubucj overridding Payment yment Estimate. m-generated Material Payment yment Estimate. |
| Material - Total \$0.00 | m-generated Material Payment yment Estimate. m-generated Material Payment user aubucj overridding Payment yment Estimate. m-generated Material Payment yment Estimate. |
| Material - Total S0.00 | m-generated Material Payment user subucj overridding Payment user aubucj overridding Payment yment Estimate. m-generated Material Payment user schmijß overridding Payment user schmijß overridding Payment yment Estimate. |
| Material - Total S0.00 | m-generated Material Payment user subucj overridding Payment user aubucj overridding Payment yment Estimate. m-generated Material Payment user schmijß overridding Payment user schmijß overridding Payment yment Estimate. |
| Material - Total \$0.00 | m-generated Material Payment user aubucj overridding Payment buser schmijß overridding Payment user schmijß overridding Payment user schmijß overridding Payment user schmijß overridding Payment user aubucj overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J6S3048 | 0840 | TURF TYPE TALL FESCUE SODDING | Material | | | 2021 | | | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 0840 - | Total | | | | | | \$0.00 | |
| | 1460 | BASE, CONCRETE | Material | | 8 | Nov 3, 2021 | SYSTEM | \$4,158.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user aubucj overridding Payment Estimate Exception 31 on the current Payment Estimate. |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$4,158.00) | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | \$5,940.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 35 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | (\$5,940.00) | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | \$10,692.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 38 on the current Payment Estimate. |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | (\$10,692.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 1460 - | Total | | | | | | \$0.00 | |
| | 5002 | TRUNCATED DOMES | | | 7 | Oct 18, 2021 | SYSTEM | \$8,676.76 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user aubucj overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | (\$8,676.76) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 5002 - | Total | | | | | | \$0.00 | |
| | 5004 | MISC. CONCRETE | Material | | 7 | Oct 18, 2021 | SYSTEM | \$19,656.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user aubucj overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | (\$19,656.00) | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | \$24,922.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user aubucj overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$24,922.80) | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | \$24,922.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user aubucj overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | (\$24,922.80) | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | \$37,516.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user aubucj overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | (\$37,516.50) | |
| | | | | | 11 | Dec 17, 2021 | SYSTEM | \$42,865.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 11 | Dec 17, 2021 | SYSTEM | (\$42,865.20) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - T | otal | | | | \$0.00 | |
| | 5004 - | Total | | | | | | \$0.00 | |
| | 5005 | CURB AND GUTTER TYPE B | Material | | 9 | Nov 16, 2021 | SYSTEM | \$24,671.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user aubucj overridding Payment Estimate Exception 23 on the current Payment Estimate. |



MoDOT

Line Item Adjustments by Estimate

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|-----------|---------|------------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|--|--|
| J6S3048 | 5005 | CURB AND GUTTER TYPE B | Material | | 9 | Nov 16, 2021 | SYSTEM | (\$24,671.25) | | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | \$29,338.87 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 24 on the current Payment Estimate. | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | (\$29,338.87) | | |
| | | | | | 11 | Dec 17, 2021 | SYSTEM | \$31,193.13 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 19 on the current Payment Estimate. | |
| | | | | | 11 | Dec 17, 2021 | SYSTEM | (\$31,193.13) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | otal | | | | \$0.00 | | |
| | 5005 - | Total | | | | | | \$0.00 | | |
| | 5006 | MISC. PAVED DRAINAGE | Material | | 7 | Oct 18, 2021 | SYSTEM | \$8,878.62 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user aubucj overridding Payment Estimate Exception 23 on the current Payment Estimate. | |
| | | | | | 7 | Oct 18, 2021 | SYSTEM | (\$8,878.62) | | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | \$9,608.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user aubucj overridding Payment Estimate Exception 23 on the current Payment Estimate. | |
| | | | | | 8 | Nov 3, 2021 | SYSTEM | (\$9,608.25) | | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | \$9,608.25 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user aubucj overridding Payment Estimate Exception 28 on the current Payment Estimate. | |
| | | | | | 9 | Nov 16, 2021 | SYSTEM | (\$9,608.25) | | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | \$14,802.78 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user aubucj overridding Payment Estimate Exception 29 on the current Payment Estimate. | |
| | | | | | 10 | Dec 2, 2021 | SYSTEM | (\$14,802.78) | | |
| | | | | | 1 | 11 | Dec 17, 2021 | SYSTEM | \$16,806.54 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | | | 11 | Dec 17, 2021 | SYSTEM | (\$16,806.54) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | otal | | | | \$0.00 | | |
| | 5006 - | Total | | | | | | \$0.00 | | |
| J6S3048 - | - Total | | | | | | | \$0.00 | | |
| Overall - | Total | | | | | | | \$0.00 | | |