25.92%



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 18, 2022

July 1, 2023

Progress Estimate Number 23		Contract ID Prime Contractor	210521-F01 KCI Construction Cor		tart July 1, 20 nd July 15, 2	O22 Original Contract Amount Current Contract Amount Current Contract Amount	\$30,573,000.00 \$546,150.68 \$31,119,150.68
Approval Date							By User
July 18, 2022			Generated and Ap	proved (and should be	considered D	raft) at the Project Office Level by	schirj1
July 19, 2022		I	Reviewed and Approve	ed (and should be con	idered Draft)	at the Resident Engineer Level by	morgac1
July 20, 2022	Reviewed and Approved at the Central Office Controllers Office Level by						
Original Completion Date		Current Con	pletion Date	Actual Completion	Date	% of Current Contract Amou	int Complete

	Contract Informational Dates										
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract								
Acceptance Date											
Awarded Date	June 2, 2021	June 2, 2021									
Letting Date	May 21, 2021	May 21, 2021									
Notice to Proceed Date	July 26, 2021	July 26, 2021									
Open to Traffic Date											
Work Began Date	August 3, 2021	August 3, 2021									

July 1, 2023

Contract Total Pay For Estimate No. 23										
		This Estimate	Previous	To Date						
210521-F01										
	Total Posted Items Pay	\$613,521.45	\$7,451,787.26	\$8,065,308.71						
	Gross Item Adjustments	\$290,169.54	\$161,771.56	\$451,941.10						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	-		\$7,613,558.82	\$8,517,249.81						
<b>Contract Total Pag</b>	yable This Estimate:	\$903,690.99								

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S1718	0070	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$6.300	1,147.34	\$7,228.24
	0130	5021107	CONCRETE PAVEMENT ( 7 IN. NON-REINF)	SQYD	\$88.000	278.66	\$24,522.08
	0180	6081012	TRUNCATED DOMES	SQFT	\$15.000	10	\$150.00
	0210	6085007	PAVED APPROACH, 7 IN.	SQYD	\$76.000	470.38	\$35,748.88
	0220	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$50.000	259.89	\$12,994.50
	0250	6089902	MISC.CONCRETE CURB RAMP (7 IN. THICK)	EA	\$1,765.000	5	\$8,825.00
	0260	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$30.000	33.5	\$1,005.00
	0270	6091052	CURB AND GUTTER TYPE B	LF	\$30.000	143	\$4,290.00
	0290	6092012	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B	LF	\$19.000	90	\$1,710.00
	0320	6113020	FURNISHING TYPE 2 ROCK BLANKET	CUYD	\$30.000	232.2	\$6,966.00
	0330	6113040	PLACING TYPE 2 ROCK BLANKET	CUYD	\$18.000	232.2	\$4,179.60
	0410	6161008	ADVANCED WARNING RAIL SYSTEM	EA	\$35.000	4	\$140.00
	0420	6161009	FLAG ASSEMBLY	EA	\$25.000	5	\$125.00
	0430	6169901	MISC.TEMPORARY TRAFFIC CONTROL	LS	\$750,000.000	0.25	\$187,500.00
	0450	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	EA	\$3,500.000	2	\$7,000.00
	0660	6240104A	SEPARATION GEOTEXTILE	SQYD	\$4.000	412	\$1,648.00
	0750	8061016	SEDIMENT REMOVAL	CUYD	\$16.000	0.75	\$12.00
	1440	2063000	CLASS 3 EXCAVATION	CUYD	\$31.000	1,390.65	\$43,110.15
	1480	7250315A	15 IN. PIPE GROUP B	LF	\$73.000	26	\$1,898.00

Revision 4/1/2020 Page 1 of 59



Pay Estimate Created Date: July 18, 2022

Progress Estimate Number 23		Contract ID Prime Contractor	210521-F01 Pay Period Start tor KCI Construction Company Pay Period End			Original Contract Amount Net Change Order Amount Current Contract Amount		\$30,573,000.00 \$546,150.68 \$31,119,150.68	
Project Number	Line Number	Item Code		Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J6S1718	1490	7250318A	18 IN. PIPE GROUP	РВ		LF	\$81.000	55	\$4,455.00
	1510	7250324A	24 IN. PIPE GROUP	РВ		LF	\$98.000	235	\$23,030.00
	1520	7250330A	30 IN. PIPE GROUP	РВ		LF	\$121.000	8	\$968.00
	1530	7250336A	36 IN. PIPE GROUP	РВ		LF	\$143.000	106	\$15,158.00
	1560	7259903	MISC.CLASS III RC	P PIPE - 15"		LF	\$103.000	33	\$3,399.00
	1590	7261015	15 IN. PIPE GROUP	PA		LF	\$99.000	101	\$9,999.00
	1620	7261024	24 IN. PIPE GROUP	PA		LF	\$112.000	285	\$31,920.00
	1720	7319903	MISC.MSD PCC 2 (	GRATE INLET WITH SIDE IN	TAKE - 60" BASE	LF	\$1,014.000	10	\$10,140.00
	1750	7319903	MISC.MSD PCC 48	'MANHOLE		LF	\$775.000	27	\$20,925.00
	1770	7319903	MISC.MSD PCC 60	' MANHOLE		LF	\$917.000	8	\$7,336.00
	1780	7319903	MISC.MSD PCC 60	' MANHOLE WITH LOCKING	COVER	LF	\$957.000	6	\$5,742.00
	1790	7319903	MISC.MSD PCC 72	' MANHOLE WITH LOCKING	COVER	LF	\$1,116.000	6	\$6,696.00

#### EΑ \$100.00 1870 6039932 GAS \$100.000 1 1880 ADJUSTING MANHOLE EΑ 4 \$1,000.00 6042010 \$250.000 Project J6S1718 - Total \$529,891.45 J6S1718B CUYD 2550 2039907 MISC.SOFT SOIL REMEDIATION \$63.000 1,010 \$63,630.00 MISC.VERTICAL DRAIN FOR THREE-SIDED STRUCTURE 3150 7159902 EΑ \$25,000.000 0.5 \$12,500.00 3210 MISC.WATERPROOFING MEMBRANE FOR THREE-SIDED LS \$15,000.000 \$7,500.00 7339901 0.5

LF

LF

LF

\$963.000

\$770.000

\$998.000

23

5

14

STRUCTURE Project J6S1718B - Total

MISC.MSD PCC DOUBLE STREET INLET

MISC.MSD PCC SINGLE STREET INLET - 48" BASE

MISC.MSD PCC SINGLE STREET INLET - 60" BASE

\$83,630.00 \$613,521.45

\$22,149.00

\$3,850.00

\$13,972.00

#### Contract Adjustments This Estimate

Overall - Total

1810

1820

1830

7319903

7319903

7319903

No Contract Adjustments Exist on Contract

ne Item A	<u>djustm</u>	ents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
	0070	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-11,313.18	\$6.30	(\$71,273.03
	0070	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0066) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	11,313.18	\$6.30	\$71,273.03
	0150	CONCRETE APPROACH PAVEMENT	Material			-116.7	\$115.00	(\$13,420.50)
	0150	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0067) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	116.7	\$115.00	\$13,420.50
	0280	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-96.5	\$18.50	(\$1,785.25)
	0280	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0068) due to user schirj1 overridding Payment Estimate Exception 12	96.5	\$18.50	\$1,785.25

Revision 4/1/2020 Page 2 of 59



Pay Estimate Created Date: July 18, 2022

Progress Estimate Number 23 Contract ID 210521-F01 Pay Period Start July 1, 2022 Original Contract Amount S430,573,000.00 Pay Period End July 15, 2022 Original Contract Amount S46,150.68 Current Contract Amount S41,150.68

ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
1718					on the current Payment Estimate.			
	0350	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-115.5	\$3.00	(\$346.50
	0350	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0069) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	115.5	\$3.00	\$346.50
	0740	CURB INLET CHECK	Material			-12	\$15.25	(\$183.00
	0740	CURB INLET CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0070) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	12	\$15.25	\$183.00
	0800	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$17,847.84
	0810	BRACKET ARM, 15 FT. OR 4.6 M	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$7,576.68
	0990	SIGNAL SIGN, MOUNTING HARDWARE	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$5,625.00
	1000	POST, SIGNAL 8 FT. OR 2.4 M	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$11,718.31
	1010	POST, SIGNAL 15 FT. OR 4.6 M	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$2,047.64
	1030	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$10,473.04
	1040	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$12,695.78
	1050	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$6,554.92
	1060	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$34,285.61
	1070	POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$9,703.63
	1075	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$7,599.34
	1077	POST, TYPE B, LONGEST ARM 20 FT. OR 6.1 M	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$5,339.52
	1080	POST, TYPE BL, LONGEST ARM 35 FT. OR 10.7 M	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$10,737.75
	1090	POST, TYPE BL, LONGEST ARM 55 FT.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$15,812.56
	1320	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$23,505.66
	1590	15 IN. PIPE GROUP A	Overrun			-21	\$99.00	(\$2,079.00
	1670	MISC.	Material			-5	\$1,962.00	(\$9,810.00
	1670	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0071) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	5	\$1,962.00	\$9,810.00
	1690	MISC.	Material			-7	\$2,253.00	(\$15,771.00
	1690	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0072) due to user schirj1	7	\$2,253.00	\$15,771.00

Revision 4/1/2020 Page 3 of 59



Pay Estimate Created Date: July 18, 2022

Progress Estimate Number 23 Contract ID Prime Contractor KCI Construction Company Pay Period Start July 1, 2022 Original Contract Amount \$30,573,000.00 \$546,150.68 Current Contract Amount \$31,119,150.68

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S1718					overridding Payment Estimate Exception 34 on the current Payment Estimate.			
	1860	WATER	Material			-1	\$4,859.00	(\$4,859.00
	1860	WATER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0073) due to user schirj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	1	\$4,859.00	\$4,859.00
	1910	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$9,984.32
	1920	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$10,856.20
	2210	TYPE D BARRIER	Material			-271	\$140.00	(\$37,940.00
	2210	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0074) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	271	\$140.00	\$37,940.00
	2220	SIDEWALK (BRIDGES)	Material			-2,259	\$17.00	(\$38,403.00)
	2220	SIDEWALK (BRIDGES)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0075) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	2,259	\$17.00	\$38,403.00
	2290	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material			-598	\$87.00	(\$52,026.00)
	2290	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	598	\$87.00	\$52,026.00
	2320	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-91	\$724.00	(\$65,884.00)
	2320	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0077) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	91	\$724.00	\$65,884.00
J6S1718B	2680	CONCRETE PAVEMENT ( 7 IN. NON-REINF)	Material			-520.19	\$88.00	(\$45,776.72)
	2680	CONCRETE PAVEMENT ( 7 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0052) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	520.19	\$88.00	\$45,776.72
	2880	MISC.	Material			-742.653	\$34.00	(\$25,250.20)
	2880	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0053) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	742.653	\$34.00	\$25,250.20
	2940	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B	Material			-261.5	\$19.00	(\$4,968.50)
	2940	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0054) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	261.5	\$19.00	\$4,968.50

Revision 4/1/2020 Page 4 of 59



Pay Estimate Created Date: July 18, 2022

Progress Estimate Number
23

Contract ID 210521-F01 Pay Period Start July 1, 2022 July 15, 2022 Pay Period End July 15, 2022 Pay Period End July 15, 2022 Net Change Order Amount 5430,573,000.00 \$4546,150.68 Current Contract Amount \$30,573,000.00 \$4546,150.68 \$454,150.68

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
S1718B	3060	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-26	\$550.00	(\$14,300.00
	3060	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0055) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	26	\$550.00	\$14,300.00
	3130	REINFORCING STEEL (EPOXY COATED)	Material			-945	\$3.00	(\$2,835.00
	3130	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0056) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	945	\$3.00	\$2,835.00
	3160	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-459.9	\$45.00	(\$20,695.50
	3160	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0057) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	459.9	\$45.00	\$20,695.50
	3610	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$18,692.09
	3610	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material			-566	\$3.15	(\$1,782.90
	3610	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0058) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	566	\$3.15	\$1,782.90
	3680	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$512.00
	3700	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$5,417.80
	3710	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$1,941.55
	3840	SEWER	Material			-257	\$827.00	(\$212,539.00
	3840	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	257	\$827.00	\$212,539.00
	3850	SEWER	Material			-109	\$1,057.00	(\$115,213.00
	3850	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0060) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	109	\$1,057.00	\$115,213.00
	3870	SEWER	Material			-334	\$432.00	(\$144,288.00
3	3870	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0061) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	334	\$432.00	\$144,288.00
	4110	SEWER	Material			-26	\$130.00	(\$3,380.00
	4110	SEWER	Material		This adjustment offsets the original system-	26	\$130.00	\$3,380.00

Revision 4/1/2020 Page 5 of 59



Pay Estimate Created Date: July 18, 2022

Progress Estimate Number
23

Contract ID 210521-F01 Pay Period Start Pay Period End Pay Period E

					Currei	nt Contract A	illount po	31,119,150.68
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S1718B					generated Material Payment Estimate Item Adjustment (0062) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.			
	4130	SEWER	Material			-24.5	\$171.00	(\$4,189.50
	4130	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0063) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	24.5	\$171.00	\$4,189.50
	4140	SEWER	Material			-109	\$274.00	(\$29,866.00
	4140	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0064) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	109	\$274.00	\$29,866.00
	4150	SEWER	Material			-115	\$286.00	(\$32,890.00)
	4150	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0065) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	115	\$286.00	\$32,890.00
J6S1718C	4810	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material			-3,744	\$3.15	(\$11,793.60
	4810	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0078) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	3,744	\$3.15	\$11,793.60
	4830	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$63,321.30
	4830	MISC.	Material			-3	\$3,863.00	(\$11,589.00
	4830	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0079) due to user schirj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	3	\$3,863.00	\$11,589.00
Total								\$290,169.54

Revision 4/1/2020 Page 6 of 59



					C	Contract Project Information				
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J6S1718	FAF-100-1(70)	Pavement, ADA, Signal and Drainage improvements	100	ST LOUIS	from Big Bend Roa	ad to Lindbergh Boulevard				
J6S1718B	FAF-100-1(80)	Pedestrian Trail, Underpass & Sanitary Sewer	100	ST LOUIS	from Bremerton to	from Bremerton to Black Creek				
J6S1718C	FAF-100-1(81)	Pedestrian and Streetscape enhancements	100	ST LOUIS	from Kenmore Driv	ve to Lindbergh				
Γotals by Jo	b Numbers									
J6S1718	Posted Item Gross Item A	Adjustments	Item Pa	/	This Estimate \$529,891.45 \$200,284.80 \$730,176.25	Previous \$4,810,080.59 \$54,329.68 \$4,864,410.27	To Date \$5,339,972.04 \$254,614.48 \$5,594,586.52			
	Disincentive Liquidated D	Incentive Disincentive Liquidated Damages Other Contract Adjustments			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J6S1718B	Posted Item Gross Item A	Adjustments	Item Pa	/	This Estimate \$83,630.00 \$26,563.44 \$110,193.44	Previous \$2,533,679.47 \$33,566.96 \$2,567,246.43	To Date \$2,617,309.47 \$60,130.40 \$2,677,439.87			
	Incentive Disincentive Liquidated D Other Contra				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J6S1718C	Posted Item Pay Gross Item Adjustments			This Estimate \$0.00 \$63,321.30 \$63,321.30	Previous \$108,027.20 \$73,874.92 \$181,902.12	<b>To Date</b> \$108,027.20 \$137,196.22 <b>\$245,223.42</b>				
	Incentive Disincentive Liquidated D Other Contra				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 7 of 59



### **Exceptions (Discrepancies) This Estimate Period**

Naches 2010, Maleria de 2016/2016 (Aberia 2016/2017) (Alfordia de 2016/2017) (	Exceptions (Discrepancies) This Estimate Period			
Naches 2010, Maleria de 2016/2016 (Aberia 2016/2017) (Alfordia de 2016/2017) (	Exceptions / Discrepencies	Explanation		Status
Namera 2000. Material Set 2007 1010pt. Baterial públi CCPACQA. A comprehe recursion corrector mix COLO. A Acceptance Actino Generic Bill 1010pt. COLO. A recursion and conference Bill 1010pt. COLO. A recursion and color of the piblic and color of the pi	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 3040504, Project Item Line Number 0070, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number of 100, Material Set 50040000, Material Set 500400000, Material Set 10040000000000000000000000000000000000	Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 5021107, Project Item Line Number 2680, Material Set 502110796, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Numbers of 100, Material Set 50410008, Material 1072/HTBE-40101 - The Bar Fp Cold 401 No. 0A119 Gr.  Estimate Econotion Type: Insufficient Materials: Project 2,551718, Item 5051000, Project Item Line  Cellisation Econotion Type: Insufficient Materials: Project 2,551718, Item 5051000, Project Item Line  Cellisation Econotion Type: Insufficient Materials: Project 2,551718, Item 5051000, Project Item Line  Cellisation Econotion Type: Insufficient Materials: Project 2,551718, Item 5051000, Project Item Line  Cellisation Econotion Type: Insufficient Materials: Project 2,551718, Item 5051000, Project Item Line  Northwerb of 100, Muterials 56510100098, Material 5651000098, Allerial 605100094000, Project Item Line  Northwerb of 100, Muterial 56510100098, Material 56510009800, Item 100009800, Project Item Line  Northwerb of 100, Muterial 565100009800, Material 90510007400, Material 5670009800, Item 100009800, Project Item Line  Northwerb of 100, Muterial 565100009800, Material 9051000740, Material 90510009800, Item 00009800, Project Item Line  Northwerb 0500, Muterial 565100009800, Material 9051000740, Item 00009800, Project Item Line  Northwerb 0500, Muterial 565100009800, Material 9051000740, Item 000098000, Project Item Line  Northwerb 0500, Muterial 565100009800, Material 9051000740000, Project Item Line  Northwerb 0500, Muterial 565100009800, Material 90510007400000000000000000000000000000000	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 5041000, Project Item Line Number 0150, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 2015, Material Set 5041 (00000, Material 1072/HTE20310 - Tie Bar Ep Cord 407 No. 0A110 Gr.  Eliminate Ecoption Type: Insufficient Materials: Propez 1861718, Nem 5041000, Project tiern Line COCDA, Acceptance Action Generic 6001007 ADCOA in surfacion Corner of Congress of Cong	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 5041000, Project Item Line Number 0150, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 315, Material Set 504 10006B, Material CSTOCCPACCA Concele, Parement contractor mix of COOA, Acceptance Advance Advance General Confection (COOA), Acceptance Advanced (COOA), Acceptance (COOA), Acceptanc	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 5041000, Project Item Line Number 0150, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 1980, Material Set 605902026, Material GS97026, Project Item Line Variance Secretor Dispute Insufficient Standard Project 48917188, Item 6059923, Project Item Line Variance 3400, Material Secretor Secret	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 5041000, Project Item Line Number 0150, Material Set 504100096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 389, Material Set 60393238, Material 0726MPFC - Force Main Pipe, Acceptance Action Generic 0726MFC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J851718B, Item 0339923, Project Item Line Number 3850, Material Set 60393238, Material 0726MPFC - Force Main Pipe, Acceptance Action Generic 0726MFC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J851718B, Item 0339923, Project Item Line Number 3970, Material Set 60393238, Material 0726MPFC - Force Main Pipe, Acceptance Action Generic 0726MFC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J851718B, Item 0399023, Project Item Line Number 3970, Material Set 60393238, Material 0726MPFC - Force Main Pipe, Acceptance Action Generic 0726MFC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J851718B, Item 0399027, Project Item Line Number 3970, Material Set 600390389, Material 0726MPC PACCOA - Concrete, Privment contractor mix OCOA, Acceptance Action Generic 0810 CCPACCOA is insufficient.  Working with materials to complete required testing.  Schipti Concrete Privment Contractor mix OCOA, Acceptance Action Generic 0810 CCPACCOA is insufficient.  Number 3970, Material Set 6100126PA Material Conforce Action Generic 0810 CCPACCOA is insufficient.  Number 3970, Material Set 6100126PA Material Conforce Action Generic 0810 CCPACCOA is insufficient.  Number 3970, Material Set 6100126PA Material Conforce Action Generic 0810 CCPACCOA is insufficient.  Number 3970, Material Set 6100126PA Material Conforce Action Generic 0810 CCPACCOA is insufficient.  Number 3970, Material Set 7001274 Number 3970 CCPACCOA Concrete, Purvenent contractor mix OCOA, Acceptance Action Generic 0810 CCPACCOA is insufficient.  Schipti Concrete Purvenent Set 7001274 Number 3970 CCPACCOA Concrete Purvenent Contractor mix OCOA, Acceptance Action Generic 0810 CCPACCOA is insufficient.  Schipti Concrete Set 7001274 Number 3970 CCPACCOA Concrete Set 9001274 Number 3970 Material Set 7001274 Number 3970	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 6039902, Project Item Line Number 1860, Material Set 603990296, Material 0603WL - Material for Waterline, Acceptance Action Generic 0603WL is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 380. Material Set 603992396, Material 0728MPFC - Force Main Pipe, Acceptance Action Generic 0728MPFC is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSS17188, tem 6039932, Project Item Line Number 3870, Material 384698, Material 38690FG, Material 36910FGP, Carco Main Pipe, Acceptance Action Generic 0728MPFC is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSS17188, tem 6039905, Project Item Line Number 2880, Material Set 60399056, Material 36910CPAQCQA - Concrete, Pavment contractor mix or COCA. Acceptance Action Generic 05010CPAQCQA is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSS1718, tem 6029012, Project Item Line Number 2880, Material Set 602901396, Material 50910CPAQCQA - Concrete, Pavment contractor mix or COCA. Acceptance Action Generic 05010CPAQCQA is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSS1718, tem 6029012, Project Item Line Number 2890, Material Set 602901396, Material 20910CPAQCQA is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSS1718, tem 6029012, Project Item Line Number 290, Material Set 61301025, Material 20910CPAQCQA is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSS1718, tem 6131012, Project Item Line Number 290, Material Set 61301025, Material 20910CPAQCQA is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSS1718, tem 703112, Project Item Line Number 290, Material Set 61301025, Material 20910CPAQCQA is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSS1718, tem 703112, Project Item Line Number 290, Material Set 70310396, Material Set 70310496, Material Set 70310496, Material Set 70310496, Materi	Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 6039923, Project Item Line Number 3840, Material Set 603992396, Material 0726MPFC - Force Main Pipe, Acceptance Action Generic 0726MPFC is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 370, Material Set 603992396, Material O726MPFC - Force Main Pipe, Acceptance Action Generic 0726MPC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J851718B, Item 6039005, Project Item Line Number 280, Material Set 603903966, Material 6010CPAQCDA: Concrete, Pawment contractor mix or COCA, Acceptance Action Generic 05010CPAQCDA: Insufficient.  Estimate Exception Type: Insufficient Materials: Project J851718 Item 6032011, Project Item Line Number 280, Material Set 603020196, Material 05010CPAQCDA: Concrete, Pawment contractor mix or COCA, Acceptance Action Generic 05010CPAQCDA: Insufficient  Estimate Exception Type: Insufficient Materials: Project J851718B, Item 6032012, Project Item Line Number 2604, Material Set 60302196, Material 05010CPAQCDA: Concrete, Pawment contractor mix or COCAA, Acceptance Action Generic 05010CPAQCDA: Insufficient  Estimate Exception Type: Insufficient Materials: Project J851718, Item 6131012, Project Item Line Number 2604, Material Set 61310126, Material 603000XCS - Compacted Set of Subgrade  Estimate Exception Type: Insufficient Materials: Project J851718, Item 6131012, Project Item Line Number 2604, Material Set 61310126, Material 60300XCS - Compacted Set of Subgrade  Estimate Exception Type: Insufficient Materials: Project J851718, Item 7032030, Project Item Line Number 2509, Material Set 70320396, Material 60710CS is insufficient  Estimate Exception Type: Insufficient Materials: Project J851718, Item 7032030, Project Item Line Number 2600, Material Set 70320396, Material 60710CS A: Concrete, Class B w/Air, Acceptance Action Generic 0736075C is insufficient.  Estimate Exception Type: Insufficient Materials: Project J851718, Item 7032003, Project Item Line Number 2600, Material Set 70320396, Material 60710CS A: Concrete, Class B w/Air, Acceptance Action Generic 07507CS is insufficient.  Estimate Exception Type: Insufficient Materials: Project J851718, Item 7034219A, Project Item Line Number 2500, Material Set 70320396, Material 60510CS A: Concrete, C	Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 6039923, Project Item Line Number 3850, Material Set 603992396, Material 0726MPFC - Force Main Pipe, Acceptance Action Generic 0726MPFC is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 280, Material Set 60899696, Material GS01CCPAQCOA - Concrete, Pawment contractor mix or COCA, Acceptance Action Generic OS01CCPAQCOA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J8S1718, Item 6092011, Project Item Line Number 280, Material Set 600201186, Material GS01CCPAQCOA - Concrete, Pawment contractor mix or COCA, Acceptance Action Generic 0501CCPAQCOA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J8S1718, Item 6131012, Project Item Line Number 280, Material Set 6002011266, Material GS01CCPAQCOA - Concrete, Pawment contractor mix or COCA, Acceptance Action Generic 0501CCPAQCOA - Compacted Soil for Subgrade Compact Soil Material Set 70121256, Material GS01CCPAQCOA - Compacted Soil for Subgrade Compacted Soil Material Set 7012121256, Material GS01CCPAQCOA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J8S1718, Item 6131012, Project Item Line Number 200, Material Set 70121256, Material GS00XCS - Compacted Soil for Subgrade Soil for Subgrade Compacted Soil for Subgrade Soil for Subgra	Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 6039923, Project Item Line Number 3870, Material Set 603992396, Material 0726MPFC - Force Main Pipe, Acceptance Action Generic 0726MPFC is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 0280, Material Set 609201196, Material OSIOCCPAQCQA - Concrete, Pawment contractor mix or COCA, Acceptance Action Genetic 05010CPAQCQA is insufficient.  Estimate Exception Type: Insufficient Materials: Project, JSS1718B, Item 6092012, Project Item Line Number 2300, Material OSIOCCPAQCQA - Concrete, Pawment contractor mix or COCA, Acceptance Action Genetic 05010CPACQA - Concrete, Pawment contractor mix or COCA, Acceptance Action Genetic 05010CPACQAC - Concrete, Pawment contractor mix or COCA, Acceptance Action Genetic 05010CPACQAC - Concrete, Pawment Contractor mix or COCA, Acceptance Action Genetic 0500XCS - Compacted Soll for Subgrade of Contractor Mix or COCA, Acceptance Action Genetic 0500XCS is insufficient.  Estimate Exception Type: Insufficient Materials: Project, JSS1718, Item 7021212, Project Item Line Number 2900, Material Set 702121296, Material OSIOCCS - Galvanizing of Components for Str Steel, Acceptance Action Genetic 0702XTCS in Sufficient.  Estimate Exception Type: Insufficient Materials: Project, JSS1718, Item 7032003, Project Item Line Number 2000, Material Set 703203996, Material OSIOCCB, A. Concrete, Class B w/Air, Acceptance Action Genetic 05010CB. As insufficient Materials: Project, JSS1718, Item 7032003, Project Item Line Number 2000, Material Set 70320396, Material OSIOCCB, A. Concrete, Class B w/Air, Acceptance Action Genetic 05010CB, As insufficient Materials: Project, JSS1718, Item 7034203, Project Item Line Number 2010, Material Set 70320396, Material OSIOCCB, A. Concrete, Class B w/Air, Acceptance Action Genetic 05010CB, As insufficient Materials: Project, JSS1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material OSIOCCB, A. Concrete Sealer (CS) - Siliane @. Acceptance Action Genetic 05050CB, Line Materials (CS) - Siliane &. Concrete Sealer (CS)	Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 6089905, Project Item Line Number 2880, Material Set 608990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 2940, Material Set 609201296, Material DS 071CPAQCOA - Concrete, Pawment contractor mix or QCOA, Accoptance Action Generic 0501CCPAQCOA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 6131012, Project Item Line Number 0350, Material Set 613101296, Material 2000XCSC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7021212, Project Item Line Number 2010, Material Set 702121096, Material O712STZC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 2020, Material Set 70212096, Material O501CCB. A - Concrete, Class B w/Air, Acceptance Action Generic 05010CB. A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 3006, Material Set 70320398, Material 0501CCB. A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB. A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 2020, Material Set 703200398, Material 10501CCB. A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB. A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 10530SSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 0501CCB. A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2220, Material Set 7034219A96, Material DS01CCB. A - Concrete, Class B-1 w/Air, Acceptance Action Generic 10530CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A. Project Item Line Number 2220, Material Set 7034219A96, Material DS01CCB1. A - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line N	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 6092011, Project Item Line Number 0280, Material Set 609201196, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 0350, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade or Cimbankment, Acceptance Action Generic 0200XXCS is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032013, Project Item Line Number 2290, Material Set 702121296, Material Set 702121296, Material Set 702121296, Material Set 703200396, Mater	Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 6092012, Project Item Line Number 2940, Material Set 609201296, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 2290, Material Set 702121296, Material 0712STZC - Galvanizing of Components for Str Steel, Acceptance Action Generic 0712STZC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7032003, Project Item Line Number 3060, Material Set 703200396, Material 0501CCB.A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB.A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 2320, Material Set 703200396, Material 0501CCB.A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB.A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 9501CCB.A - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 0505CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 9501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 70344319, Project Item Line Number 2220, Material Set 7034219A96, Material 9501CCB1.A - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 0501CCB1.A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 703443096, Material 10501CCB2.A - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 053CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 3130, Material Set 703443096, Material 10368SSRECAB - Epoxy Cld Sprl Sti Rein for Anch Bolts @, Acceptance Action Generic Reinforcing/Misc is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSSRECAB - Epoxy Cld Sprl Sti Rein f	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 6131012, Project Item Line Number 0350, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 2320, Material Set 703200396, Material 0501CCB.A Concrete, Class B w/Air, Acceptance Action Generic 0501CCB.A is insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 2320, Material Set 703200396, Material 0501CCB.A Concrete, Class B w/Air, Acceptance Action Generic 0501CCB.A is insufficient.  Setimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A9, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 0501CCB1.A is insufficient.  Setimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 0501CCB1.A is insufficient.  Setimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.  Setimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 703443096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 053CSSIL is insufficient.  Setimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2200, Material Set 703443096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.  Setimate Exception Type: Insufficient Materials: Project J6S1718B, Item 701000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Spri Stl Rein for Anch Bolts @, Acceptance Action Generic ReiforcingMisc is insufficient.  Setimate Exception Type: Insufficient Materials: Project J6S1718B, Item 701000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Spri Stl Rein for Anch Bolts @, Acceptance Action Generic ReiforcingMisc	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7021212, Project Item Line Number 2290, Material Set 702121296, Material 0712STZC - Galvanizing of Components for Str Steel, Acceptance Action Generic 0712STZC is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 2320, Material Set 703200396, Material 0501CCB. A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB. A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line (CS) - Silane (C	Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7032003, Project Item Line Number 3060, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 2210, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 703443096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 703443096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ResteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSDEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ResteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSDEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ResteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Working with materials to complete required testing.  Working with materials to complete req	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 2320, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 2210, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 703443096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 703443096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Working with materials to complete required testing.  Working with materials to complete required testing.  Schirj1 Overridden  Working with materials to complete required testing.  Schirj1 Overridden	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 2220, Material Set 703443096, Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 703443096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1038RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.  Working with materials to complete required testing.  Working with materials to complete required testing.  Schirj1  Overridden  Working with materials to complete required testing.  Schirj1  Overridden  Vorridden  Working with materials to complete required testing.  Schirj1  Overridden  Vorridden  Schirj1  Overridden  Working with materials to complete required testing.  Schirj1  Overridden  Working with materials to complete required testing.  Schirj1  Overridden  Schirj1  Overridden  Working with materials to complete required testing.  Schirj1  Overridden  Working with materials to complete required testing.  Schirj1  Overridden  Working with materials to complete required testing.  Schirj1  Overridden  Working with materials to complete required testing.	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 2220, Material Set 703443096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Working with materials to complete required testing.  Working with materials to complete required testing.  Schirj1  Overridden  Working with materials to complete required testing.  Schirj1  Overridden	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 703443096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 3130, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line  Working with materials to complete required testing.  Schirj1 Overridden  Overridden	Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 703443096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Number 3130, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Working with materials to complete required testing. schirj1 Overridden	Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
	Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
	Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Number 3160, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved	Working with materials to complete required testing.	schirj1	Overridden

Revision 4/1/2020 Page 8 of 59



### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period  Exceptions / Discrepancies	Explanation	Entered By	Status
Design, Acceptance Action Generic 0720MSEW is insufficient.		Бу	
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Number 3160, Material Set 720100096, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Number 3160, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Number 3160, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7269923, Project Item Line Number 4110, Material Set 726992396, Material 4028SPPV08 - 8" PVC Sewer Pipe, Acceptance Action Generic 4028SPPV08 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7269923, Project Item Line Number 4130, Material Set 726992396, Material 4028SPPV08 - 8" PVC Sewer Pipe, Acceptance Action Generic 4028SPPV08 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7269923, Project Item Line Number 4140, Material Set 726992396, Material 4028SPPV08 - 8" PVC Sewer Pipe, Acceptance Action Generic 4028SPPV08 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7269923, Project Item Line Number 4150, Material Set 726992396, Material 4028SPPV08 - 8" PVC Sewer Pipe, Acceptance Action Generic 4028SPPV08 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7319902, Project Item Line Number 1670, Material Set 7319902, Material 0614DFMNFC - Manhole Frame and Cover, Acceptance Action Generic 0614DFMNFC is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7319902, Project Item Line Number 1670, Material Set 7319902, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7319902, Project Item Line Number 1690, Material Set 7319902, Material 0614DFMNFC - Manhole Frame and Cover, Acceptance Action Generic 0614DFMNFC is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 8061007A, Project Item Line Number 0740, Material Set 8061007A96, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 9017407, Project Item Line Number 3610, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718C, Item 9017407, Project Item Line Number 4810, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718C, Item 9019902, Project Item Line Number 4830, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Item Overrun: Contract 210521-F01, Contract Project J6S1718, Project Item Line Number 1590, Contract Line Item Number 1590, Item 7261015, Minor Item.	Waiting to complete change order for these items.	schirj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210521-F01, Contract Project J6S1718B, Project Item Line Number 2770, Contract Line Item Number 2770, Item 6081012, Minor Item.	Waiting to complete change order for these items.	schirj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210521-F01, Contract Project J6S1718, Project Item Line Number 1550, Contract Line Item Number 1550, Item 7259903, Minor Item.	Waiting to complete change order for these items.	schirj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210521-F01, Contract Project J6S1718, Project Item Line Number 2230, Contract Line Item Number 2230, Item 7040104, Minor Item.	Waiting to complete change order for these items.	schirj1	Acknowledged

Revision 4/1/2020 Page 9 of 59



#### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
10521-F01	J6S1718	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$2,469,600.00	\$691,488.0
		0001	0020	2031000	CLASS A EXCAVATION	596.00	0.00	596.00	CUYD	0.00	\$13.40	\$0.0
		0001	0030	2035500	EMBANKMENT IN PLACE	106.00	0.00	106.00	CUYD	0.00	\$8.00	\$0.0
		0001	0040	2036000	COMPACTING EMBANKMENT	477.00	0.00	477.00	CUYD	0.00	\$10.45	\$0.0
		0001	0050	2037075	COMPACTING IN CUT	2.00	0.00	2.00	STA	0.00	\$2,123.00	\$0.0
		0001	0060	2071000	LINEAR GRADING CLASS 1	403.50	-403.50	0.00	STA	0.00	\$900.00	\$0.0
		0001	0070	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	60,618.00	0.00	60,618.00	SQYD	11,371.91	\$6.30	\$71,643.0
		0001	0080	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	1,248.30	0.00	1,248.30	TONS	0.00	\$124.50	\$0.0
		0001	0090	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	3,242.40	0.00	3,242.40	TONS	0.00	\$139.00	\$0.0
		0001	0100	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	12,462.40	0.00	12,462.40	TONS	0.00	\$87.00	\$0.0
		0001	0110	4030208	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP190C MIX)	14,886.20	0.00	14,886.20	TONS	0.00	\$80.00	\$0.0
		0001	0120	4071005	TACK COAT	31,850.00	0.00	31,850.00	GAL	30.00	\$2.50	\$75.0
		0001	0130	5021107	CONCRETE PAVEMENT ( 7 IN. NON-REINF)	7,894.00	0.00	7,894.00	SQYD	332.45	\$88.00	\$29,255.6
		0001	0140	5021109	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	2,377.40	0.00	2,377.40	SQYD	529.60	\$82.00	\$43,427.2
		0001	0150	5041000	CONCRETE APPROACH PAVEMENT	481.70	0.00	481.70	SQYD	116.70	\$115.00	\$13,420.5
		0001	0160	6071102	MODIFIED CONCRETE GUTTER TYPE B	424.00	0.00	424.00	LF	0.00	\$35.00	\$0.0
		0001	0170	6079903	MISC.48 " Decorative Pedestrian Fence (Structures)	733.00	0.00	733.00	LF	0.00	\$105.00	\$0.0
		0001	0180	6081012	TRUNCATED DOMES	2,477.00	0.00	2,477.00	SQFT	170.90	\$15.00	\$2,563.5
		0001	0190	6083008	8 IN. CONCRETE MEDIAN STRIP	1,535.20	0.00	1,535.20	SQYD	0.00	\$90.00	\$0.0
		0001	0200	6084023	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	424.00	0.00	424.00	LF	0.00	\$130.00	\$0.0
		0001	0210	6085007	PAVED APPROACH, 7 IN.	14,086.90	0.00	14,086.90	SQYD	4,174.40	\$76.00	\$317,254.4
		0001	0220	6086004	CONCRETE SIDEWALK, 4 IN.	14,425.90	0.00	14,425.90	SQYD	2,684.96	\$50.00	\$134,248.0
		0001	0230	6086008	CONCRETE SIDEWALK, 8 IN.	182.70	0.00	182.70	SQYD	0.00	\$84.00	\$0.0
		0001	0240	6089901	MISC.STAIRS AND HANDRAILS AT CURB RAMP 72	1.00	0.00	1.00	LS	0.00	\$5,700.00	\$0.0
		0001	0250	6089902	MISC.CONCRETE CURB RAMP (7 IN. THICK)	153.00	0.00	153.00	EA	19.00	\$1,765.00	\$33,535.0
		0001	0260	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	14,712.00	0.00	14,712.00	LF	2,711.36	\$30.00	\$81,340.8
		0001	0270	6091052	CURB AND GUTTER TYPE B	17,779.00	0.00	17,779.00	LF	5,041.59	\$30.00	\$151,247.7
		0001	0280	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	1,311.00	0.00	1,311.00	LF	96.50	\$18.50	\$1,785.2
		0001	0290	6092012	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B	3,878.00	0.00	3,878.00	LF	102.00	\$19.00	\$1,938.0
		0001	0300	6099903	MISC.MODIFIED CURB	873.00	0.00	873.00	LF	264.40	\$28.00	\$7,403.2
		0001	0310	6099903	MISC.MODIFIED CURB TYPE A	774.00	0.00	774.00	LF	79.30	\$25.50	\$2,022.1
		0001	0320	6113020	FURNISHING TYPE 2 ROCK BLANKET	716.00	0.00	716.00	CUYD	608.60	\$30.00	\$18,258.0
		0001	0330	6113040	PLACING TYPE 2 ROCK BLANKET	716.00	0.00	716.00	CUYD	608.60	\$18.00	\$10,954.8
		0001	0340	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	304.00	0.00	304.00	SQYD	115.50	\$200.00	\$23,100.0
		0001	0350	6131012	DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	304.00	0.00	304.00	SQYD	115.50	\$3.00	\$346.5
		0001	0360	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	304.00	0.00	304.00	SQYD	115.50	\$4.00	\$462.0
		0001	0370	6131014	(PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER	1,266.00	0.00	1,266.00	LF	147.00	\$4.50	\$661.5
		0001	0380	6131015	AND INTERNAL SAW CUTS)  DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION)	760.00	0.00	760.00	EA	34.00	\$15.00	\$510.0
		0001	0390	6131017	FOR FULL DEPTH PAVEMENT REPAIR  DOWEL BAR (FURNISHING AND INSTALLATION WITH	380.00	0.00	380.00	EA	2.00	\$13.00	\$26.0
		0004	0400	6161005	BASKETS) FOR FULL DEPTH PAVEMENT REPAIR CONSTRUCTION SIGNS	2 102 00	0.00	2 102 00	SQFT	2 102 00	\$9.50	\$10,060.0
		0001	0410	6161005		2,102.00	0.00	2,102.00		2,102.00	\$35.00	\$19,969.0 \$140.0
		0001		6161008	ADVANCED WARNING RAIL SYSTEM	87.00		87.00	EA	4.00		
		0001	0420	6161009	FLAG ASSEMBLY	39.00	0.00	39.00	EA	5.00	\$25.00	\$125.0
		0001	0430	6169901	MISC TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.40	\$750,000.00	\$300,000.0
		0001	0440	6169901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$18,000.00	\$0.0
		0001	0450	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	6.00	0.00	6.00	EA	6.00	\$3,500.00	\$21,000.0
		0001	0460	6173101	CONCRETE TRAFFIC BARRIER, TYPE D (MODIFIED)	33.00	0.00	33.00	LF	0.00	\$250.00	\$0.0

Revision 4/1/2020 Page 10 of 59



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

		ed.	Generate	timate was	ne the Es	ınt at the tir	port Generated date and can differ from the posted amou	ased on Re	s are ba	nd Values	Quantities a	ote: Posted Q
Total Value POS To Date (See re generated date	Unit Price	Total Posted Approved Qty	Unit	Total Current Quantity	Net Change Order	Bid Quantity	Description	Item Code	Line No.	Category	Project No.	Contract Nm.CONTRACT
\$30,58	\$22.45	1,362.50	LF	1,450.00	0.00	1,450.00	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	6173600D	0470	0001	J6S1718	10521-F01
\$4,56	\$8.50	537.50	LF	1,260.00	0.00	1,260.00	RELOCATING TEMPORARY TRAFFIC BARRIER	6175010A	0480	0001		
\$	\$643.00	0.00	EA	9.00	0.00	9.00	MISC.CONCRETE BARRIER HEIGHT TRANSITION	6179902	0490	0001		
5	\$3,099,938.53	0.00	LS	0.00	-1.00	1.00	MOBILIZATION	6181000	0500	0001		
\$1,482,96	\$2,965,936.53	0.50	LS	1.00	1.00	0.00	MOBILIZATION	6181000	0501	0001		
\$	\$20.00	0.00	LF	2,680.00	0.00	2,680.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	6200015	0510	0001		
5	\$300.00	0.00	EA	83.00	0.00	83.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	6200021	0520	0001		
\$	\$350.00	0.00	EA	11.00	0.00	11.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	6200027	0530	0001		
\$	\$1,600.00	0.00	EA	8.00	1.00	7.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	6200036	0540	0001		
\$	\$50.00	0.00	EA	24.00	0.00	24.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	6200042	0550	0001		
\$79	\$0.16	4,957.00	LF	64,692.00	0.00	64,692.00	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	6205901A	0560	0001		
\$1,25	\$0.22	5,696.00	LF	82,056.00	0.00	82,056.00	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	6205902A	0570	0001		
5	\$1.00	0.00	LF	2,401.00	0.00	2,401.00	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6206000C	0580	0001		
5	\$5.00	0.00	LF	258.00	0.00	258.00	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6206125A	0590	0001		
5	\$20.00	0.00	LF	72.00	0.00	72.00	4 IN. WHITE ACRYLIC COPOLYMER FAST DRY PAVEMENT MARKING PAINT	6206150A	0600	0001		
5	\$10.00	0.00	LF	168.00	0.00	168.00	4 IN. YELLOW ACRYLIC COPOLYMER FAST DRY PAVEMENT MARKING PAINT	6206151A	0610	0001		
\$4,23	\$0.70	6,055.00	LF	17,981.00	0.00	17,981.00	PAVEMENT MARKING REMOVAL	6207001	0620	0001		
\$	\$40.00	0.00	EA	37.00	0.00	37.00	MISC.PARKING BLOCK	6209902	0630	0001		
\$	\$13.25	0.00	SQYD	2,366.00	0.00	2,366.00	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	6221001	0640	0001		
\$	\$3.45	0.00	SQYD	120,693.00	0.00	120,693.00	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	6221003	0650	0001		
\$4,13	\$4.00	1,033.10	SQYD	1,182.00	0.00	1,182.00	SEPARATION GEOTEXTILE	6240104A	0660	0001		
\$41,25	\$275,000.00	0.15	LS	1.00	0.00	1.00	CONTRACTOR FURNISHED SURVEYING AND STAKING	6274000	0670	0001		
\$	\$45.00	0.00	SQFT	2,272.00	0.00	2,272.00	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	7201000	0680	0001		
5	\$60.00	0.00	SQFT	135.00	0.00	135.00	MISC.RE-CONSTRUCT WALL IN PLACE	7209904	0690	0001		
5	\$36.00	0.00	SQFT	2,277.00	0.00	2,277.00	MISC.SMALL BLOCK WALL	7209904	0700	0001		
5	\$8.45	0.00	SQYD	17,974.00	0.00	17,974.00	TURF TYPE TALL FESCUE SODDING	8031000A	0710	0001		
\$	\$5,000.00	0.00	ACRE	1.00	0.00	1.00	MISC.FERTILIZER, SEEDING, AND MULCHING	8059919	0720	0001		
5	\$1.90	0.00	LF	6.00	0.00	6.00	ALTERNATE DITCH CHECK	8061006	0730	0001		
\$18	\$15.25	12.00	EA	204.00	0.00	204.00	CURB INLET CHECK	8061007A	0740	0001		
\$1,08	\$16.00	67.85	CUYD	370.00	0.00	370.00	SEDIMENT REMOVAL	8061016	0750	0001		
5	\$1,800.00	0.00	ACRE	2.00	0.00	2.00	TEMPORARY SEEDING	8061017	0760	0001		
5	\$0.35	0.00	LF	17,312.00	0.00	17,312.00	SILT FENCE	8061019	0770	0001		
\$6,05	\$25.00	242.00	LF	456.00	0.00	456.00	TYPE C BERM	8061050	0780	0001		
\$	\$1,900.00	0.00	EA	2.00	0.00	2.00	RELOCATED POLE	9011010	0790	0020		
5	\$2,186.00	0.00	EA	12.00	0.00	12.00	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	9011030	0800	0020		
	\$847.00	0.00	EA	12.00	0.00	12.00	BRACKET ARM, 15 FT. OR 4.6 M	9011115	0810	0020		
	\$425.00	0.00	EA	25.00	0.00	25.00	LUMINAIRE, LED-A	9011311	0820	0020		
5	\$10.50	0.00	LF	92.00	0.00	92.00	CONDUIT, 2 IN. RIGID, IN TRENCH	9013002	0830	0020		
\$	\$27.50	0.00	LF	309.00	0.00	309.00	CONDUIT, 4 IN. RIGID, PUSHED	9014004	0840	0020		
	\$6.00	0.00	LF	89.00	0.00	89.00	TRENCHING TYPE I	9015010	0850	0020		
	\$1.00	0.00	LF	2,500.00	0.00	2,500.00	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	9017110	0860	0020		
	\$5.20	0.00	LF	570.00	0.00	570.00	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	9017407	0870	0020		
,	ψ0.20	0.00		57 0.00	5.00	370.00	NEUTRAL, 8 AWG		0880			
	\$980.00	0.00	EA	12.00	0.00	12.00	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	9018230		0020		

Revision 4/1/2020 Page 11 of 59



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amou Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718	0020	0900	9019902	MISC.REMOVE AND RELOCATE PRIVATELY-OWNED LIGHT POLE	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00
		0030	0910	9020115	SIGNAL HEAD, TYPE 5T	1.00	0.00	1.00	EA	0.00	\$971.00	\$0.00
		0030	0920	9020211	SIGNAL HEAD, TYPE 1S	52.00	0.00	52.00	EA	0.00	\$443.00	\$0.00
		0030	0930	9020213	SIGNAL HEAD, TYPE 3S	6.00	0.00	6.00	EA	0.00	\$679.00	\$0.00
		0030	0940	9020214	SIGNAL HEAD, TYPE 4S	6.00	0.00	6.00	EA	0.00	\$815.00	\$0.00
		0030	0950	9020215	SIGNAL HEAD, TYPE 5S	3.00	0.00	3.00	EA	0.00	\$940.00	\$0.00
		0030	0960	9020513	SIGNAL HEAD, TYPE 3B	30.00	0.00	30.00	EA	0.00	\$877.00	\$0.00
		0030	0970	9020514	SIGNAL HEAD, TYPE 4B	11.00	0.00	11.00	EA	0.00	\$1,021.00	\$0.00
		0030	0980	9020515	SIGNAL HEAD, TYPE 5B	2.00	0.00	2.00	EA	0.00	\$1,346.00	\$0.00
		0030	0985	9020833	SH-FLAT SHEET - SIGNAL SIGN	242.00	0.00	242.00	SQFT	0.00	\$34.33	\$0.00
		0030	0990	9020834	SIGNAL SIGN, MOUNTING HARDWARE	40.00	0.00	40.00	EA	0.00	\$297.00	\$0.00
		0030	1000	9022708	POST, SIGNAL 8 FT. OR 2.4 M	31.00	0.00	31.00	EA	0.00	\$538.00	\$0.00
		0030	1010	9022715	POST, SIGNAL 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	0.00	\$690.00	\$0.00
		0030	1030	9023125	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	2.00	0.00	2.00	EA	0.00	\$6,917.00	\$0.00
		0030	1040	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	2.00	0.00	2.00	EA	0.00	\$8,117.00	\$0.00
		0030	1050	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	0.00	\$8,018.00	\$0.00
		0030	1060	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	4.00	0.00	4.00	EA	0.00	\$10,954.00	\$0.00
		0030	1070	9023150	POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	0.00	\$12,000.00	\$0.00
		0030	1075	9023240	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	1.00	0.00	1.00	EA	0.00	\$9,361.00	\$0.00
		0030	1077	9023320	POST, TYPE B, LONGEST ARM 20 FT. OR 6.1 M	1.00	0.00	1.00	EA	0.00	\$7,728.00	\$0.00
		0030	1080	9023435	POST, TYPE BL, LONGEST ARM 35 FT. OR 10.7 M	1.00	0.00	1.00	EA	0.00	\$13,405.00	\$0.00
		0030	1090	9023455	POST, TYPE BL, LONGEST ARM 55 FT.	1.00	0.00	1.00	EA	0.00	\$20,332.00	\$0.00
		0030	1100	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	5.00	0.00	5.00	EA	0.00	\$16,878.00	\$0.00
		0030	1110	9024975	VIDEO DETECTION SYSTEM	7.00	0.00	7.00	EA	0.00	\$16,428.00	\$0.00
		0030	1120	9025020	CONDUIT, 1 IN., LOOP DETECTOR WITH TRACER WIRE	30.00	0.00	30.00	LF	0.00	\$16.00	\$0.00
		0030	1130	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	1,840.00	0.00	1,840.00	LF	0.00	\$12.50	\$0.00
		0030	1140	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	700.00	0.00	700.00	LF	0.00	\$13.50	\$0.00
		0030	1150	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	330.00	0.00	330.00	LF	0.00	\$15.60	\$0.00
		0030	1160	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	480.00	0.00	480.00	LF	0.00	\$24.00	\$0.00
		0030	1170	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	100.00	0.00	100.00	LF	0.00	\$25.00	\$0.00
		0030	1180	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	1,130.00	0.00	1,130.00	LF	0.00	\$27.00	\$0.00
		0030	1190	9027502	CONDUIT, 2 IN., EXTERNAL ON STRUCTURE	30.00	0.00	30.00	LF	0.00	\$94.00	\$0.00
		0030	1200	9028204	CABLE, 4 AWG 1 CONDUCTOR, POWER	300.00	0.00	300.00	LF	0.00	\$2.25	\$0.00
		0030	1210	9028302	CABLE, 12 AWG 2 CONDUCTOR	2,380.00	0.00	2,380.00	LF	0.00	\$1.25	\$0.00
		0030	1220	9028308	CABLE, 16 AWG 2 CONDUCTOR	8,290.00	0.00	8,290.00	LF	0.00	\$1.15	\$0.00
		0030	1230	9028310	CABLE, 16 AWG 5 CONDUCTOR	8,360.00	0.00	8,360.00	LF	0.00	\$1.25	\$0.00
		0030	1240	9028311	CABLE, 16 AWG 7 CONDUCTOR	12,210.00	0.00	12,210.00	LF	0.00	\$1.35	\$0.00
		0030	1250	9028611	POWER SUPPLY ASSEMBLY, TYPE 1 WITH 120V LIGHTING CONTROL CABINET	1.00	0.00	1.00	EA	0.00	\$3,569.00	\$0.00
		0030	1260	9028621	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET	2.00	0.00	2.00	EA	0.00	\$4,800.00	\$0.00
		0030	1270	9028810	PULL BOX, PREFORMED CLASS 1	6.00	0.00	6.00	EA	0.00	\$990.00	\$0.00
		0030	1280	9028811	PULL BOX, PREFORMED CLASS 2	11.00	0.00	11.00	EA	0.00	\$1,350.00	\$0.00
		0030	1290	9028812	PULL BOX, PREFORMED CLASS 3	5.00	0.00	5.00	EA	0.00	\$1,650.00	\$0.00
		0030	1300	9028821	PULL BOX, CONCRETE, DOUBLE, TYPE A	3.00	0.00	3.00	EA	0.00	\$3,400.00	\$0.00
		0030	1310	9029100	BASE, CONCRETE	69.40	0.00	69.40	CUYD	0.00	\$1,350.00	\$0.00
		0030	1320	9029902	MISC.AUDIBLE PEDESTRIAN PUSH BUTTONS AND SIGNING	54.00	0.00	54.00	EA	0.00	\$726.00	\$0.00
		0030	1330	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	7.00	0.00	7.00	EA	0.00	\$1,196.00	\$0.00

Page 12 of 59 Revision 4/1/2020



### Total Paid / All Items / All Estimates (Including this Estimate)

otc. i ostcu Qt	uanililes a	iliu values	s are ba	sea on Re	port Generated date and can differ from the posted amou	int at the til	me the Es	timate was	General	ea.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718	0030	1340	9029902	MISC.RECTANGULAR RAPID FLASHING BEACON	7.00	0.00	7.00	EA	0.00	\$10,171.00	\$0.00
		0040	1350	9031010	CONCRETE FOOTINGS, EMBEDDED	8.80	0.00	8.80	CUYD	0.00	\$1,000.00	\$0.00
		0040	1360	9031220	PIPE POSTS	5,590.00	0.00	5,590.00	LB	0.00	\$7.00	\$0.00
		0040	1370	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	24.00	0.00	24.00	EA	0.00	\$300.00	\$0.00
		0040	1380	9031250A	U-CHANNEL POST, 3 LB	84.00	0.00	84.00	LF	0.00	\$20.00	\$0.00
		0040	1390	9031260	WOOD POST, 4 IN. BY 4 IN.	46.00	0.00	46.00	LF	0.00	\$25.00	\$0.00
		0040	1400	9031261	WOOD POST, 4 IN. BY 6 IN.	28.00	0.00	28.00	LF	0.00	\$25.00	\$0.00
		0040	1410	9031270A	2 IN. PSST POST - 12 GA.	2,507.00	0.00	2,507.00	LF	0.00	\$15.00	\$0.00
		0040	1420	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	582.00	0.00	582.00	LF	0.00	\$28.00	\$0.00
		0040	1430	9035004A	SH-FLAT SHEET	1,763.00	0.00	1,763.00	SQFT	0.00	\$25.00	\$0.00
		0055	1440	2063000	CLASS 3 EXCAVATION	14,695.00	0.00	14,695.00	CUYD	3,916.40	\$31.00	\$121,408.40
		0055	1450	2063500	CULVERT CLEANOUT	3.00	0.00	3.00	EA	1.00	\$2,080.00	\$2,080.00
		0055	1460	6149902	MISC.ADA COMPLIANT GRATE	1.00	0.00	1.00	EA	0.00	\$1,116.00	\$0.00
		0055	1470	7250312A	12 IN. PIPE GROUP B	25.00	0.00	25.00	LF	0.00	\$96.00	\$0.00
		0055	1480	7250315A	15 IN. PIPE GROUP B	2,420.00	0.00	2,420.00	LF	912.90	\$73.00	\$66,641.70
		0055	1490	7250318A	18 IN. PIPE GROUP B	5,456.00	0.00	5,456.00	LF	514.00	\$81.00	\$41,634.00
		0055	1500	7250321A	21 IN. PIPE GROUP B	310.00	0.00	310.00	LF	0.00	\$98.00	\$0.00
		0055	1510	7250324A	24 IN. PIPE GROUP B	1,102.00	0.00	1,102.00	LF	235.00	\$98.00	\$23,030.00
		0055	1520	7250330A	30 IN. PIPE GROUP B	154.00	0.00	154.00	LF	38.00	\$121.00	\$4,598.00
		0055	1530	7250336A	36 IN. PIPE GROUP B	493.00	0.00	493.00	LF	342.00	\$143.00	\$48,906.00
		0055	1540	7259902	MISC.8" CLEANOUT	1.00	0.00	1.00	EA	1.00	\$1,244.00	\$1,244.00
		0055	1550	7259903	MISC.8" PVC PIPE	5.00	0.00	5.00	LF	18.00	\$114.00	\$2,052.00
		0055	1560	7259903	MISC.CLASS III RCP PIPE - 15"	141.00	0.00	141.00	LF	85.00	\$103.00	\$8,755.00
		0055	1570	7259903	MISC.CLASS III RCP PIPE - 18"	169.00	0.00	169.00	LF	45.00	\$118.00	\$5,310.00
		0055	1580	7259903	MISC.CLASS III RCP PIPE - 21"	12.00	0.00	12.00	LF	0.00	\$168.00	\$0.00
		0055	1590	7261015	15 IN. PIPE GROUP A	271.00	0.00	271.00	LF	292.00	\$99.00	\$28,908.00
		0055	1600	7261018	18 IN. PIPE GROUP A	1,272.00	0.00	1,272.00	LF	0.00	\$91.00	\$0.00
		0055	1610	7261021	21 IN. PIPE GROUP A	124.00	0.00	124.00	LF	0.00	\$103.00	\$0.00
		0055	1620	7261024	24 IN. PIPE GROUP A	383.00	0.00	383.00	LF	317.00	\$112.00	\$35,504.00
		0055	1630	7261030	30 IN. PIPE GROUP A	166.00	0.00	166.00	LF	62.00	\$121.00	\$7,502.00
		0055	1640	7261036	36 IN. PIPE GROUP A	183.00	0.00	183.00	LF	0.00	\$137.00	\$0.00
		0055	1650	7269902	MISC.MSD STANDARD CONNECTION TO LARGE SEWERS	3.00	0.00	3.00	EA	0.00	\$5,307.00	\$0.00
		0055	1660	7319902	MISC.REPLACE EXISTING INLET TOP WITH MAHNOLE FRAME AND LOCKING COVER	2.00	0.00	2.00	EA	0.00	\$1,888.00	\$0.00
		0055	1670	7319902	MISC.REPLACE EXISTING INLET TOP WITH MANHOLE FRAME AND COVER	9.00	0.00	9.00	EA	5.00	\$1,962.00	\$9,810.00
		0055	1680	7319902	MISC.REPLACE EXISTING MANHOLE COVER WITH LOCKING COVER	3.00	0.00	3.00	EA	0.00	\$939.00	\$0.00
		0055	1690	7319902	MISC.TBR&R PER MSD INSPECTOR	20.00	0.00	20.00	EA	7.00	\$2,253.00	\$15,771.00
		0055	1700	7319903	MISC.MSC PCC DOUBLE TRAPPED STEET INLET	8.00	0.00	8.00	LF	8.00	\$1,628.00	\$13,024.00
		0055	1710	7319903	MISC.MSD PCC 2 GRATE INLET WITH SIDE INTAKE - 48" BASE	155.00	0.00	155.00	LF	10.00	\$1,001.00	\$10,010.00
		0055	1720	7319903	MISC.MSD PCC 2 GRATE INLET WITH SIDE INTAKE - 60" BASE	46.00	0.00	46.00	LF	41.00	\$1,014.00	\$41,574.00
		0055	1730	7319903	MISC.MSD PCC 2 GRATE STEET INLET - 48" BASE	27.00	0.00	27.00	LF	16.00	\$816.00	\$13,056.00
		0055	1740	7319903	MISC.MSD PCC 42" SHORT TOP MANHOLE	6.00	0.00	6.00	LF	6.00	\$708.00	\$4,248.00
		0055	1750	7319903	MISC.MSD PCC 48" MANHOLE	249.00	0.00	249.00	LF	59.00	\$775.00	\$45,725.00
		0055	1760	7319903	MISC.MSD PCC 48" MANHOLE WITH LOCKING COVER	45.00	0.00	45.00	LF	8.00	\$792.00	\$6,336.00
		0055	1770	7319903	MISC.MSD PCC 60" MANHOLE	50.00	0.00	50.00	LF	14.00	\$917.00	\$12,838.00
		0055	1780	7319903	MISC.MSD PCC 60" MANHOLE WITH LOCKING COVER	19.00	0.00	19.00	LF	6.00	\$957.00	\$5,742.00
		0055	1790	7319903	MISC.MSD PCC 72" MANHOLE WITH LOCKING COVER	6.00	0.00	6.00	LF	6.00	\$1,116.00	\$6,696.00

Revision 4/1/2020 Page 13 of 59



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

-t-1\/-l DOC	Heit Deine						port Generated date and can differ from the posted amour				
otal Value POS To Date (See rep generated date	Unit Price	Total Posted Approved Qty	Unit	Total Current Quantity	Net Change Order	Bid Quantity	Description	Line Item No. Code	No.	Project Category No.	Contract m.CONTRACT
\$5,18	\$1,037.00	5.00	LF	5.00	0.00	5.00	MISC.MSD PCC AREA INLET - 4 SIDES	00 7319903	1800	J6S1718 0055	10521-F01
\$63,55	\$963.00	66.00	LF	313.00	0.00	313.00	MISC.MSD PCC DOUBLE STREET INLET	10 7319903	1810	0055	
\$59,29	\$770.00	77.00	LF	167.00	0.00	167.00	MISC.MSD PCC SINGLE STREET INLET - 48" BASE	20 7319903	1820	0055	
\$13,97	\$998.00	14.00	LF	53.00	0.00	53.00	MISC.MSD PCC SINGLE STREET INLET - 60" BASE	30 7319903	1830	0055	
\$	\$1,335.00	0.00	LF	5.00	0.00	5.00	MISC.MSD PCC TRAPPED 2 GRATE INLET WITH SIDE INTAKE - 48" BASE	40 7319903	1840	0055	
\$1,60	\$100.00	16.00	EA	81.00	0.00	81.00	WATER	50 6039902	1850	0060	
\$4,85	\$4,859.00	1.00	EA	44.00	0.00	44.00	WATER	60 6039902	1860	0060	
\$1,00	\$100.00	10.00	EA	127.00	0.00	127.00	GAS	70 6039932	1870	0060	
\$6,25	\$250.00	25.00	EA	165.00	0.00	165.00	ADJUSTING MANHOLE	80 6042010	1880	0060	
\$5,73	\$956.00	6.00	EA	34.00	0.00	34.00	ADJUSTING BASIN OR INLET	90 6042020	1890	0060	
\$	\$1,519.00	0.00	LS	1.00	0.00	1.00	MISC.Relocate Video Detection System	00 9029901	1900	0065	
\$	\$6,232.00	0.00	EA	2.00	0.00	2.00	MISC.19' Pole, w/38' Mast Arm, Steel	10 9029902	1910	0065	
\$	\$6,604.00	0.00	EA	2.00	0.00	2.00	MISC.19' Pole, w/44' Mast Arm, Steel	20 9029902	1920	0065	
\$	\$2,300.00	0.00	EA	4.00	0.00	4.00	MISC.Base, Type B-9, Concrete	30 9029902	1930	0065	
\$	\$1,348.00	0.00	EA	1.00	0.00	1.00	MISC.Base, Type C-3, Concrete	40 9029902		0065	
\$	\$2,979.00	0.00	EA	1.00	0.00	1.00	MISC.Base, Type D-8PH, Concrete	50 9029902	1950	0065	
\$	\$980.00	0.00	EA	1.00	0.00	1.00	MISC Conduit Repair (locate broken conduit, excavate, remove existing cable, repair/replace conduit, reinstall cable, backfill and restore) (Does not include sidewalk or pavement removal and replacement)	9029902		0065	
\$	\$900.00	0.00	EA	8.00	0.00	8.00	MISC.Detector, Pedestrian Push Button, APS, Freezeproof	70 9029902	1970	0065	
\$	\$560.00	0.00	EA	1.00	0.00	1.00	MISC.Post, Signal, w/Sq. Pedestal Base and Post Cap, 10' Total Height, Aluminum	80 9029902	1980	0065	
	\$3,400.00	0.00	EA	1.00	0.00	1.00	MISC.Pull Box, Double, Concrete	90 9029902	1990	0065	
	\$2,300.00	0.00	EA	4.00	0.00	4.00	MISC.Pull Box, Single, Concrete	00 9029902	2000	0065	
	\$386.00	0.00	EA	8.00	0.00	8.00	MISC.Signal Head, Type 1S, Pedestrian	10 9029902	2010	0065	
	\$1,715.00	0.00	EA	4.00	0.00	4.00	MISC.Signal Head, Type 34S	20 9029902	2020	0065	
5	\$878.00	0.00	EA	8.00	0.00	8.00	MISC.Signal Head, Type 3B, Terminal Compartment, and Astro Bracket Mounting	30 9029902	2030	0065	
\$	\$1,021.00	0.00	EA	4.00	0.00	4.00	MISC.Signal Head, Type 4B, Terminal Compartment, and Astro Bracket Mounting	40 9029902	2040	0065	
	\$1.00	0.00	EA	4.00	0.00	4.00	MISC.Signal Head, Type 4S	50 9029902	2050	0065	
:	\$1.00	0.00	LF	200.00	0.00	200.00	MISC.Cable, Communication, #18 Gauge, 4 Conductor (APS)	60 9029903	2060	0065	
	\$1.80	0.00	LF	100.00	0.00	100.00	MISC.Cable, Power, #6 Gauge, 1 Conductor	70 9029903	2070	0065	
	\$1.20	0.00	LF	180.00	0.00	180.00	MISC.Cable, Power, Video Detection Camera	80 9029903	2080	0065	
	\$1.10	0.00	LF	4,000.00	0.00	4,000.00	MISC.Cable, Push Button and/or Detector Loop Lead-In, #18 Gauge, 2 Conductor (Shielded)	90 9029903	2090	0065	
	\$1.30	0.00	LF	730.00	0.00	730.00	MISC.Cable, Signal, #14 Gauge, 5 Conductor	00 9029903	2100	0065	
	\$1.55	0.00	LF	3,610.00	0.00	3,610.00	MISC.Cable, Signal, #14 Gauge, 7 Conductor	10 9029903	2110	0065	
	\$26.00	0.00	LF	490.00	0.00	490.00	MISC.Conduit, 4"	20 9029903	2120	0065	
	\$1.80	0.00	LF	260.00	0.00	260.00	MISC.Wire, Stranded Ground, #6 Gauge	30 9029903	2130	0065	
\$17,8	\$66.00	271.00	LF	271.00	0.00	271.00	CURB REMOVAL	40 2164000	2140	0070	
\$6,9	\$52.00	134.00	LF	134.00	0.00	134.00	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	50 2165000		0070	
\$30,4	\$45.00	676.00	SQFT	676.00	0.00	676.00	MISC.PARTIAL REMOVAL & REPLACEMENT OF APPROACH SLAB	60 2169904		0070	
\$18,3	\$15.00	1,220.00	SQFT	1,220.00	0.00	1,220.00	MISC.REMOVAL OF EXISTING CANTILEVER SIDEWALK	70 2169904	2170	0070	
	\$130.00	0.00	LF	269.00	0.00	269.00	MISC.(30 IN.) DECORATIVE PEDESTRIAN FENCE			0070	
	\$120.00	0.00	LF	37.00	0.00	37.00	MISC.(74.5 IN.) DECORATIVE PEDESTRIAN FENCE			0070	
	\$58.00	0.00	SQYD	1,298.00	0.00	1,298.00	MISC.EPOXY URETHANE POLYMER WEARING SURFACE			0070	
\$37,9	\$140.00	271.00	LF	271.00	0.00	271.00	TYPE D BARRIER			0070	
\$38,4	\$17.00	2,259.00	SQFT	2,259.00	0.00	2,259.00	SIDEWALK (BRIDGES)			0070	
\$10,4	\$65.00	160.00	SQFT	50.00	0.00	50.00	HALF-SOLE REPAIR			0070	
,										33.3	

Revision 4/1/2020 Page 14 of 59



### Total Paid / All Items / All Estimates (Including this Estimate)

		ina value	o are ba	ocu on rec	port Generated date and can differ from the posted amou	int at the tir	ne the Es	umate was	Generale	ea.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718	0071	2250	2061000	CLASS 1 EXCAVATION	114.00	0.00	114.00	CUYD	114.00	\$55.00	\$6,270.00
		0071	2260	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$150,000.00	\$150,000.00
		0071	2270	5031010A	BRIDGE APPROACH SLAB (MAJOR)	418.00	0.00	418.00	SQYD	0.00	\$252.00	\$0.00
		0071	2280	6079903	MISC.DECORATIVE PEDESTRIAN FENCE	265.00	0.00	265.00	LF	0.00	\$301.00	\$0.00
		0071	2290	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	826.00	0.00	826.00	LF	598.00	\$87.00	\$52,026.00
		0071	2300	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0071	2310	7027000	PILE POINT REINFORCEMENT	28.00	0.00	28.00	EA	28.00	\$150.00	\$4,200.00
		0071	2320	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	91.00	0.00	91.00	CUYD	91.00	\$724.00	\$65,884.00
		0071	2330	7034219A	TYPE D BARRIER	398.00	0.00	398.00	LF	0.00	\$140.00	\$0.00
		0071	2340	7034221	SLAB ON CONCRETE NU-GIRDER	1,201.00	0.00	1,201.00	SQYD	0.00	\$360.00	\$0.00
		0071	2350	7034430	SIDEWALK (BRIDGES)	1,007.00	0.00	1,007.00	SQFT	0.00	\$13.00	\$0.00
		0071	2360	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	1,210.00	0.00	1,210.00	LF	1,210.00	\$267.50	\$323,675.00
		0071	2370	7079903	MISC.CONDUIT SYSTEM ON STRUCTURE	283.00	0.00	283.00	LF	0.00	\$25.00	\$0.00
		0071	2380	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE	6.00	0.00	6.00	EA	0.00	\$600.00	\$0.00
		0071	2390	7123610	GIRDERS SLAB DRAIN	12.00	0.00	12.00	EA	0.00	\$240.00	\$0.00
		0071	2400	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$4,600.00	\$0.00
		0071	2410	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	22.00	0.00	22.00	EA	0.00	\$360.00	\$0.00
		0001	5001	6189901	MISC.Payment for Contract Bond	0.00	1.00	1.00	LS	1.00	\$134,002.00	\$134,002.00
		0001	5002	2079909	MISC.Modified Linear Grading, Class 2	0.00	403.50	403.50	STA	90.00	\$1,600.00	\$144,000.00
		0055	5003	2063100	CLASS 3 EXCAVATION IN ROCK	0.00	20.00	20.00	CUYD	0.00	\$85.00	\$0.00
	Project J69		al Value F	Posted to Da	te as of Report Generated Date						·	\$5,353,856.11
	J6S1718B	0001	2420	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.20	\$150,000.00	\$30,000.00
		0001	2430	2024027	REMOVAL OF THERMAL SYSTEM INSULATION ACM (FRIABLE)	4.00	0.00	4.00	SQFT	4.00	\$187.50	\$750.00
								1.00				φ100.00
		0001	2440	2024038	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE)	15.00	-15.00	0.00	SQFT	0.00	\$50.00	\$0.00
											\$50.00 \$4.30	\$0.00
		0001	2440	2024038	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE)	15.00	-15.00	0.00	SQFT	0.00		\$0.00 \$13,357.09
		0001	2440 2450	2024038	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS	15.00 1,924.00	-15.00 1,182.30	0.00 3,106.30	SQFT	0.00 3,106.30	\$4.30	
		0001 0001 0001	2440 2450 2460 2470 2480	2024038 2024043 2024046 2024070 2024098	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE)	15.00 1,924.00 627.00	-15.00 1,182.30 0.00	0.00 3,106.30 627.00	SQFT SQFT LF SQFT SQFT	0.00 3,106.30 627.00	\$4.30 \$12.00 \$19.50 \$7.45	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00
		0001 0001 0001 0001	2440 2450 2460 2470	2024038 2024043 2024046 2024070	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE)  REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)  REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE)  REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE)  REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE	15.00 1,924.00 627.00 310.00	-15.00 1,182.30 0.00 40.00	0.00 3,106.30 627.00 350.00	SQFT SQFT LF SQFT	0.00 3,106.30 627.00 350.00	\$4.30 \$12.00 \$19.50	\$0.00 \$13,357.09 \$7,524.00
		0001 0001 0001 0001 0001	2440 2450 2460 2470 2480	2024038 2024043 2024046 2024070 2024098	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE)	15.00 1,924.00 627.00 310.00 1,914.00	-15.00 1,182.30 0.00 40.00	0.00 3,106.30 627.00 350.00 1,914.00	SQFT SQFT LF SQFT SQFT	0.00 3,106.30 627.00 350.00 1,914.00	\$4.30 \$12.00 \$19.50 \$7.45	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00
		0001 0001 0001 0001 0001	2440 2450 2460 2470 2480 2490	2024038 2024043 2024046 2024070 2024098 2029950	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS	15.00 1,924.00 627.00 310.00 1,914.00	-15.00 1,182.30 0.00 40.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00	SQFT SQFT LF SQFT SQFT LS	0.00 3,106.30 627.00 350.00 1,914.00	\$4.30 \$12.00 \$19.50 \$7.45	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00
		0001 0001 0001 0001 0001 0001	2440 2450 2460 2470 2480 2490 2500	2024038 2024043 2024046 2024070 2024098 2029950 2031000	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION	15.00 1,924.00 627.00 310.00 1,914.00 1.00	-15.00 1,182.30 0.00 40.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00	SQFT SQFT LF SQFT SQFT LS CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00
		0001 0001 0001 0001 0001 0001 0001	2440 2450 2460 2470 2480 2490 2500 2510	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00	SQFT  LF  SQFT  SQFT  SQFT  CUYD  CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00	SQFT  LF  SQFT  SQFT  CUYD  CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2500 2510 2520 2530	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00	SQFT  SQFT  LF  SQFT  LS  CUYD  CUYD  CUYD  STA	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2500 2510 2520 2530 2540	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,361.00 18.10	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43	0.00 3,106.30 627.00 350.00 1,914.00 12,116.00 1,900.00 1,361.00	SQFT SQFT LF SQFT LS CUYD CUYD CUYD STA CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00 0.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$4.50 \$8.50 \$500.00	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00 \$0.00 \$0.00 \$63,630.00
		0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00 1361.00 1090.00 2,020.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00	0.00 3,106,30 627,00 350,00 1,914,00 1.00 12,116,00 1,900,00 1,361,00 19,53 109,00 2,020,00	SQFT SQFT LF SQFT LS CUYD CUYD STA CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00 0.00 1,010.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00 \$0.00 \$0.00 \$63,630.00
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2063000	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC. AMENDED SOILS MISC. SOFT SOIL REMEDIATION CLASS 3 EXCAVATION	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,361.00 18.10 109.00 2,020.00 3,403.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 19.53 109.00 2,020.00 3,403.00	SQFT SQFT LF SQFT LS CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00 0.00 1,010.00 0.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00 \$0.00 \$0.00 \$63,630.00 \$8,062.50
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2039907 2063000 2063300	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION CLASS 4 EXCAVATION	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00 18.10 109.00 2,020.00 3,403.00 751.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 19.53 109.00 2,020.00 3,403.00 751.00	SQFT SQFT LF SQFT LS CUYD CUYD STA CUYD CUYD CUYD CUYD CUYD CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00 1,010.00 1,010.00 0.00 375.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00 \$33.00	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00 \$0.00 \$0.00 \$63,630.00 \$8,062.50 \$124,480.00
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2039907 2063000 2063300 2065500	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION CLASS 3 EXCAVATION CLASS 4 EXCAVATION CLASS 4 EXCAVATION	15.00 1,924.00 627.00 310.00 1,914.00 12,116.00 1,900.00 1,361.00 109.00 2,020.00 3,403.00 751.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00	SQFT SQFT LF SQFT LS CUYD CUYD STA CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00 1,010.00 1,010.00 0.00 375.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00 \$21.50	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00 \$0.00 \$0.00 \$63,630.00 \$8,062.50 \$124,480.00 \$23,624.94
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2039907 2063000 2063300 2065500 3040504	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION CLASS 4 EXCAVATION TEMPORARY SHORING TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,361.00 18.10 109.00 2,020.00 3,403.00 751.00 1.00 8,428.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 1.00 8,428.00	SQFT SQFT LF SQFT LS CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00 1,010.00 0.00 375.00 0.50 3,749.99	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00 \$21.50 \$248,960.00	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00 \$0.00 \$0.00 \$83,630.00 \$8,062.50 \$124,480.00 \$23,624.94
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580 2590	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2063000 2063300 2065500 3040504	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION TEMPORARY SHORING TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,361.00 18.10 109.00 2,020.00 3,403.00 751.00 1.00 8,428.00 4,095.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 1.00 8,428.00 4,095.00	SQFT SQFT LF SQFT LS CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00 0.00 1,010.00 0.00 375.00 0.50 3,749.99	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$33.00 \$21.50 \$248,960.00 \$6.30 \$8.30	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00 \$0.00 \$0.00 \$63,630.00 \$8,062.50 \$124,480.00 \$23,624.94 \$0.00
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580 2590 2600	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2063000 2063300 2065500 3040504 3040905	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION TEMPORARY SHORING TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) MISC.ASTM NO. 2 AGGREGATE 12 IN. THICK	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 4,095.00 4,095.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 1.00 8,428.00 4,095.00 216.00	SQFT SQFT LF SQFT LS CUYD CUYD STA CUYD CUYD CUYD STA SQFT CUYD STA CUYD STA CUYD STA CUYD SQYD SQYD SQYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00 1,010.00 0.00 375.00 0.50 3,749.99 0.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$33.00 \$21.50 \$63.00 \$248,960.00 \$63.00	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00 \$0.00 \$0.00 \$63,630.00 \$124,480.00 \$23,624.94 \$0.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580 2600 2610 2620	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2063000 2063300 2065500 3040504 3049905	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NON-FRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION CLASS 4 EXCAVATION TEMPORARY SHORING TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) MISC.ASTM NO. 2 AGGREGATE 12 IN. THICK MISC.ASTM NO. 57 AGGREGATE 4 IN. THICK	15.00 1,924.00 627.00 310.00 1,914.00 12,116.00 1,900.00 1,361.00 18.10 109.00 2,020.00 3,403.00 751.00 8,428.00 4,095.00 216.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	0.00 3,106.30 627.00 350.00 1,914.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 4,095.00 216.00	SQFT SQFT LF SQFT LS CUYD CUYD STA CUYD CUYD CUYD STA SQYD SQYD SQYD SQYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00 1,010.00 0.50 3,749.99 0.00 0.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00 \$21.50 \$248,960.00 \$6.30 \$8.00 \$17.75	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00 \$0.00 \$0.00 \$63,630.00 \$8,062.50 \$124,480.00 \$23,624.94 \$0.00 \$0.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580 2590 2610 2620 2630	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2063300 2063300 2065500 3040504 3040506 3049905 3049905	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION TEMPORARY SHORING TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) MISC.ASTM NO. 2 AGGREGATE 12 IN. THICK MISC.ASTM NO. 57 AGGREGATE 2 IN. THICK	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 4,095.00 216.00 216.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 1.00 4,095.00 216.00 216.00	SQFT SQFT LF SQFT LS CUYD CUYD CUYD CUYD CUYD CUYD STA CUYD CUYD SQYD SQYD SQYD SQYD SQYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00 1,010.00 0.00 375.00 0.50 3,749.99 0.00 0.00 0.00	\$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00 \$21.50 \$248,960.00 \$8.30 \$17.75	\$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$0.00 \$0.00 \$0.00 \$63,630.00 \$8,062.50 \$124,480.00 \$23,624.94 \$0.00

Revision 4/1/2020 Page 15 of 59



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amou Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718B	0001	2670	4019905	MISC.OPTIONAL PAVEMENT	2,887.20	0.00	2,887.20	SQYD	Qty 0.00	\$59.00	\$0.00
210021101	00011105	0001	2680	5021107	CONCRETE PAVEMENT ( 7 IN. NON-REINF)	1,645.00	0.00	1,645.00	SQYD	520.19	\$88.00	\$45,776.72
		0001	2690	5021109	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	1,054.60	0.00	1,054.60	SQYD	854.07	\$82.00	\$70,033.74
		0001	2700	5029903	MISC.12 IN. CONCRETE HEADER	987.00	0.00	987.00	LF	0.00	\$41.00	\$0.00
		0001	2710	5029907	MISC.CLASS B CONCRETE (CONCRETE ENCASEMENT)	5.00	0.00	5.00	CUYD	0.00	\$1,000.00	\$0.00
		0001	2720	6071102	MODIFIED CONCRETE GUTTER TYPE B	207.00	0.00	207.00	LF	0.00	\$35.00	\$0.00
		0001	2730	6079902	MISC.TEMPORARY DRIVE GATE	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0001	2740	6079903	MISC.18" DECORATIVE PEDESTRIAN FENCE (STRUCTURES)	278.00	0.00	278.00	LF	0.00	\$105.00	\$0.00
		0001	2750	6079903	MISC.48" DECORATIVE PEDESTRIAN FENCE ( STRUCTURES)	684.00	0.00	684.00	LF	0.00	\$105.00	\$0.00
		0001	2760	6079903	MISC.72-INCH TEMPORARY CHAIN LINK FENCE	228.00	0.00	228.00	LF	228.00	\$18.00	\$4,104.00
		0001	2770	6081012	TRUNCATED DOMES	158.00	0.00	158.00	SQFT	220.20	\$18.00	\$3,963.60
		0001	2780	6083008	8 IN. CONCRETE MEDIAN STRIP	18.90	0.00	18.90	SQYD	0.00	\$95.00	\$0.00
		0001	2790	6084023	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	81.00	0.00	81.00	LF	0.00	\$130.00	\$0.00
		0001	2800	6085007	PAVED APPROACH, 7 IN.	473.80	0.00	473.80	SQYD	0.00	\$78.00	\$0.00
		0001	2810	6089901	MISC.THICKENED SIDEWALK SLAB OVER BOX CULVERT	1.00	0.00	1.00	LS	0.00	\$700.00	\$0.00
		0001	2820	6089902	MISC.7 IN. CONCRETE CURB RAMP (10 FT WIDE)	19.00	0.00	19.00	EA	11.00	\$2,500.00	\$27,500.00
		0001	2830	6089902	MISC.BANNER POLE	24.00	0.00	24.00	EA	0.00	\$7,450.00	\$0.00
		0001	2840	6089902	MISC.BENCH	2.00	0.00	2.00	EA	0.00	\$3,400.00	\$0.00
		0001	2850	6089902	MISC.STREET SIGN POLES, POWDERCOATED	18.00	0.00	18.00	EA	0.00	\$500.00	\$0.00
		0001	2860	6089902	MISC.WARNING AND REGULATORY SIGN POLES,	74.00	0.00	74.00	EA	0.00	\$500.00	\$0.00
			2070	0000000	POWDERCOATED  MICE WASTE PERCYCLING PECEPTAGES	4.00	0.00	4.00	F.A.	0.00	62 500 00	<b>*</b> 0.00
		0001	2870	6089902	MISC.WASTE/RECYCLING RECEPTACLE	1.00	0.00	1.00	EA	0.00	\$3,500.00	\$0.00
		0001	2880	6089905	MISC 4 2/4 INCL CONCRETE SIDEWALK (10 FT WIDE)	4,870.60	0.00	4,870.60	SQYD	2,409.32	\$34.00	\$81,916.88
		0001	2890	6089905	MISC 4-3/4 INCH CONCRETE MEDIAN STRIP	16.20	0.00	16.20	SQYD	0.00	\$84.00	\$0.00
		0001		6089905	MISC.ROGERS PARKWAY CONCRETE PAVERS	634.00	0.00	634.00	LF	0.00	\$148.50	\$0.00
		0001	2910	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	216.00	0.00	216.00		37.80	\$30.00	\$1,134.00
		0001	2920	6091052	CURB AND GUTTER TYPE B	542.00	0.00	542.00	LF	0.00	\$33.00	\$0.00
		0001	2930	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	570.00	0.00	570.00	LF	329.50	\$18.50	\$6,095.75
		0001	2940	6092012	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B	1,017.00	0.00	1,017.00	LF LF	261.50	\$19.00	\$4,968.50
		0001	2960	6099903	MISC.MODIFIED CURB	500.00 216.00	0.00	500.00	SQYD	236.00	\$28.00 \$148.50	\$6,608.00
		0001	2900	0109905	MISC.PERMEABLE INTERLOCKING CONCRETE PAVERS ( 3-1/8 IN. THICK)	216.00	0.00	216.00	SQTD	0.00	\$146.50	\$0.00
		0001	2970	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$150,000.00	\$0.00
		0001	2980	6173200	CONCRETE TRAFFIC BARRIER, TYPE E	183.00	0.00	183.00	LF	0.00	\$140.00	\$0.00
		0001	2990	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$500,000.00	\$250,000.00
		0001	3000	6206150A	4 IN. WHITE ACRYLIC COPOLYMER FAST DRY PAVEMENT MARKING PAINT	773.00	0.00	773.00	LF	0.00	\$5.00	\$0.00
		0001	3010	6206151A	4 IN. YELLOW ACRYLIC COPOLYMER FAST DRY PAVEMENT MARKING PAINT	27.00	0.00	27.00	LF	0.00	\$20.00	\$0.00
		0001	3020	6209902	MISC.ACCESSIBLE PARKING SYMBOL	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0001	3030	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,611.00	0.00	1,611.00	SQYD	0.00	\$13.25	\$0.00
		0001	3040	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.05	\$75,000.00	\$3,750.00
		0001	3050	7032002	CLASS B CONCRETE (MISC)	65.40	27.40	92.80	CUYD	0.00	\$425.00	\$0.00
		0001	3060	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	51.10	0.00	51.10	CUYD	26.00	\$550.00	\$14,300.00
		0001	3070	7039902	MISC.PEDESTRIAN UNDERPASS CAST STONE MASONRY	4.00	0.00	4.00	EA	0.00	\$3,642.00	\$0.00
		0001	3080	7039903	COLUMN MISC.PEDESTRIAN UNDERPASS CAST STONE MASONRY	36.00	0.00	36.00	LF	0.00	\$242.85	\$0.00
					COPING							
		0001	3090	7039904	MISC.PEDESTRIAN UNDERPASS CAST STONE MASONRY FACADE	196.00	0.00	196.00	SQFT	0.00	\$177.37	\$0.00
		0001	3100	7039904	MISC.PEDESTRIAN UNDERPASS INTERIOR PAINT	1,065.00	0.00	1,065.00	SQFT	0.00	\$8.70	\$0.00
		0001	3110	7039904	MISC.PEDESTRIAN UNDERPASS WALL PANEL	1,022.00	0.00	1,022.00	SQFT	0.00	\$75.45	\$0.00

Revision 4/1/2020 Page 16 of 59



### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q	uantities a	ind Value	s are ba	sed on Re	port Generated date and can differ from the posted amou	ınt at the tir	ne the Es	timate was	Generate	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718B	0001	3120	7039904	MISC.PEDESTRIAN UNDERPASS WAVE PANEL	330.00	0.00	330.00	SQFT	0.00	\$75.45	\$0.00
		0001	3130	7101000	REINFORCING STEEL (EPOXY COATED)	1,890.00	0.00	1,890.00	LB	945.00	\$3.00	\$2,835.00
		0001	3140	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$9,134.50	\$0.00
		0001	3150	7159902	MISC.VERTICAL DRAIN FOR THREE-SIDED STRUCTURE	1.00	0.00	1.00	EA	0.50	\$25,000.00	\$12,500.00
		0001	3160	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	1,036.00	0.00	1,036.00	SQFT	459.90	\$45.00	\$20,695.50
		0001	3170	7201200	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	1,762.00	0.00	1,762.00	CUYD	0.00	\$38.00	\$0.00
		0001	3180	7209904	MISC.PRECAST CONCRETE MODULAR BLOCK WALL	4,532.00	0.00	4,532.00	SQFT	0.00	\$55.00	\$0.00
		0001	3190	7209904	MISC.SMALL BLOCK WALL	429.00	0.00	429.00	SQFT	0.00	\$36.00	\$0.00
		0001	3200	7339901	MISC.PRECAST CONCRETE STRUCTURE	1.00	0.00	1.00	LS	0.50	\$250,000.00	\$125,000.00
		0001	3210	7339901	MISC.WATERPROOFING MEMBRANE FOR THREE-SIDED STRUCTURE	1.00	0.00	1.00	LS	0.50	\$15,000.00	\$7,500.00
		0001	3220	8031000A	TURF TYPE TALL FESCUE SODDING	406.00	0.00	406.00	SQYD	0.00	\$8.45	\$0.00
		0001	3230	8039905A	MISC.SODDING	3,960.00	405.00	4,365.00	SQYD	0.00	\$8.45	\$0.00
		0001	3240	8041000	TOPSOIL	225.00	0.00	225.00	CUYD	0.00	\$45.00	\$0.00
		0001	3250	8049907A	MISC.PLANTING SOIL MIX	517.00	0.00	517.00	CUYD	0.00	\$50.00	\$0.00
		0001	3260	8051000A	SEEDING - COOL SEASON GRASSES	10.00	0.00	10.00	ACRE	0.00	\$5,000.00	\$0.00
		0001	3270	8069901	MISC.DEWATERING	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0001	3280	8080119	BLACK GUM	18.00	0.00	18.00	EA	0.00	\$575.00	\$0.00
		0001	3290	8089901	MISC.IRRIGATION SYSTEM	1.00	0.00	1.00	LS	0.00	\$13,860.00	\$0.00
		0001	3300	8089902	MISC.ANDORRA CREEPING JUNIPER	401.00	0.00	401.00	EA	0.00	\$57.00	\$0.00
		0001	3310	8089902	MISC.BALTIMORE ORIOLE DAYLILY	1,775.00	0.00	1,775.00	EA	0.00	\$31.00	\$0.00
		0001	3320	8089902	MISC.BLACK-EYED SUSAN	588.00	0.00	588.00	EA	0.00	\$21.00	\$0.00
		0001	3330	8089902	MISC.BLUE GRAMA 'BLOND AMBITION'	1,154.00	0.00	1,154.00	EA	0.00	\$42.00	\$0.00
		0001	3340	8089902	MISC.EASTERN REDBUD	13.00	0.00	13.00	EA	0.00	\$575.00	\$0.00
		0001	3350	8089902	MISC.FEATHER REED GRASS	63.00	0.00	63.00	EA	0.00	\$53.00	\$0.00
		0001	3360	8089902	MISC.GINKGO BILOBA	22.00	0.00	22.00	EA	0.00	\$650.00	\$0.00
		0001	3370	8089902	MISC.GREY OWL JUNIPER	116.00	0.00	116.00	EA	0.00	\$53.00	\$0.00
		0001	3380	8089902	MISC.GRO-LOW SUMAC	382.00	0.00	382.00	EA	0.00	\$53.00	\$0.00
		0001	3390	8089902	MISC.HEATH ASTER	521.00	0.00	521.00	EA	0.00	\$37.00	\$0.00
		0001	3400	8089902	MISC.JAPANESE ZELKOVA	19.00	0.00	19.00	EA	0.00	\$575.00	\$0.00
		0001	3410	8089902	MISC.KOUSA DOGWOOD	8.00	0.00	8.00	EA	0.00	\$575.00	\$0.00
		0001	3420	8089902	MISC.LITTLE BLUESTEM	890.00	0.00	890.00	EA	0.00	\$22.00	\$0.00
		0001	3430	8089902	MISC.NEW JERSEY TEA	103.00	0.00	103.00	EA	0.00	\$33.00	\$0.00
		0001	3440	8089902	MISC.PRAIRIE DROPSEED	382.00	0.00	382.00	EA	0.00	\$22.00	\$0.00
		0001	3450	8089902	MISC.RIVER BIRCH	6.00	0.00	6.00	EA	0.00	\$575.00	\$0.00
		0001	3460	8089902	MISC.SILVER LINDEN	3.00	0.00	3.00	EA	0.00	\$600.00	\$0.00
		0001	3470	8089902	MISC.THREADLEAF COREOPSIS	626.00	0.00	626.00	EA	0.00	\$23.00	\$0.00
		0001	3480	8089902	MISC.WOODLAND PHLOX	1,588.00	0.00	1,588.00	EA	0.00	\$24.00	\$0.00
		0001	3490	8089902	MISC.YELLOW TWIG DOGWOOD	123.00	0.00	123.00	EA	0.00	\$55.00	\$0.00
		0001	3500	8089903	MISC.LANDSCAPE EDGING	147.00	0.00	147.00	LF	0.00	\$40.00	\$0.00
		0001	3510	9039904	MISC.BLACK VINYL SIGN WRAP	519.00	0.00	519.00	SQFT	0.00	\$6.00	\$0.00
		0010	3520	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	50.00	0.00	50.00	LF	0.00	\$33.00	\$0.00
		0010	3530	6062204A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER	1.00	0.00	1.00	EA	0.00	\$3,000.00	\$0.00
		0010	3540	6062300A	CURB) (NEW CONSTRUCTION ONLY) TRANSITION SECTION, 6.5 FT. POSTS	1.00	0.00	1.00	EA	0.00	\$400.00	\$0.00
		0010	3550	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	0.00	\$2,800.00	\$0.00
		0020	3560	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	6.00	0.00	6.00	EA	0.00	\$5,800.00	\$0.00
		0020	3570	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	34.00	0.00	34.00	LF	0.00	\$13.50	\$0.00

Revision 4/1/2020 Page 17 of 59



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report General

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718B	0020	3580	9014004	CONDUIT, 4 IN. RIGID, PUSHED	1,283.00	0.00	1,283.00	LF	0.00	\$26.50	\$0.0
		0020	3590	9015010	TRENCHING TYPE I	9,570.00	0.00	9,570.00	LF	566.00	\$4.50	\$2,547.0
		0020	3600	9016110	PULL BOX, PREFORMED CLASS 1	32.00	0.00	32.00	EA	0.00	\$980.00	\$0.0
		0020	3610	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	13,160.00	0.00	13,160.00	LF	566.00	\$3.15	\$1,782.9
		0020	3620	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	6.00	0.00	6.00	EA	0.00	\$6,400.00	\$0.0
		0020	3630	9019902	MISC.F1-LED TWIN FIXTURE AND POLE ASSEMBLY AT UNDERPASS	4.00	0.00	4.00	EA	0.00	\$3,084.00	\$0.0
		0020	3640	9019902	MISC.F-2 LED UNDERPASS UP/DOWN FIXTURE, 4 FOOT LENGTH	4.00	0.00	4.00	EA	0.00	\$1,227.00	\$0.0
		0020	3650	9019902	MISC.F2-LED UNDERPASS UP/DOWN FIXTURE, 8 FOOT LENGTH	18.00	0.00	18.00	EA	0.00	\$1,596.00	\$0.
		0020	3660	9019902	MISC.ORNAMENTAL LIGHT POLE AND LUMINAIRE - BRENTWOOD STREETSCAPE	92.00	0.00	92.00	EA	0.00	\$4,300.00	\$0.
		0030	3670	9029902	MISC.BLACK POWDER COATED MAST ARM AND SIGNAL POST	4.00	0.00	4.00	EA	0.00	\$1,200.00	\$0.
		0030	3680	9029902	MISC.BLACK POWDER COATED PEDESTRIAN POST	2.00	0.00	2.00	EA	0.00	\$256.00	\$0.
		0030	3690	9029902	MISC.DETECTOR, PEDESTRIAN PUSH BUTTON, APS FREEZEPROOF	8.00	0.00	8.00	EA	0.00	\$908.00	\$0.
		0030	3700	9029902	MISC.ILLUMINATED STREET SIGN	4.00	0.00	4.00	EA	0.00	\$2,144.00	\$0.
		0030	3710	9029902	MISC.POST, SIGNAL W/SQ PEDESTAL BASE AND POST CAP, 10' TOTAL HEIGHT, ALUMINUM	5.00	0.00	5.00	EA	0.00	\$549.00	\$0.
		0030	3720	9029902	MISC.PREFORMED PULL BOX - 17 IN. W X 30 IN. L X 26 IN. MIN. H - REINFROCED POLYMER CONCRETE	7.00	0.00	7.00	EA	0.00	\$995.00	\$0.
		0030	3730	9029903	MISC.CABLE, DETECTOR LOOP, #14 GAUGE, 1 CONDUCTOR W/TUBE JACKET (IN SAWED SLOT)	3,590.00	0.00	3,590.00	LF	0.00	\$4.60	\$0.
		0030	3735	9029903	MISC.CABLE, PUSH BUTTON AND/OR DETECTOR LOOP LEAD- IN, 18 GAUGE, 2 CONDUCTOR (SHIELDED)	5,860.00	0.00	5,860.00	LF	0.00	\$1.10	\$0.
		0030	3740	9029903	MISC.CABLE, DETECTOR LOOP, #14 GAUGE, 1 CONDUCTOR, W/TUBE JACKET (IN CONDUIT AND PULL BOXES)	210.00	0.00	210.00	LF	0.00	\$0.50	\$0
		0030	3750	9029907	MISC.BASE, TYPE C-3, CONCRETE	1.40	0.00	1.40	CUYD	0.00	\$2,600.00	\$0
		0030	3760	9039904	MISC.BLACK VINYL SIGN WRAP, SIGNAL SIGNS	110.00	0.00	110.00	SQFT	0.00	\$3.25	\$0
		0050	3770	6039921	SEWER	1.00	0.00	1.00	LS	0.50	\$72,500.00	\$36,250
		0050	3780	6039921	SEWER	1.00	0.00	1.00	LS	0.00	\$7,500.00	\$0
		0050	3790	6039922	SEWER	6.00	0.00	6.00	EA	6.00	\$5,869.00	\$35,214
		0050	3800	6039922	SEWER	2.00	0.00	2.00	EA	0.00	\$7,328.00	\$0
		0050	3810	6039922	SEWER	5.00	0.00	5.00	EA	0.00	\$340.00	\$0
		0050	3820	6039922	SEWER	5.00	0.00	5.00	EA	0.00	\$283.00	\$0
		0050	3830	6039923	SEWER	335.00	0.00	335.00	LF	0.00	\$50.00	\$0
		0050	3840	6039923	SEWER	257.00	0.00	257.00	LF	257.00	\$827.00	\$212,539
		0050	3850	6039923	SEWER	120.00	0.00	120.00	LF	109.00	\$1,057.00	\$115,213
		0050	3860	6039923	SEWER	41.00	0.00	41.00	LF	0.00	\$188.00	\$0
		0050	3870	6039923	SEWER	424.00	0.00	424.00	LF	334.00	\$432.00	\$144,288
		0050	3880	6039924	SEWER	544.00	0.00	544.00	CUYD	543.63	\$381.00	\$207,123
		0050	3890	6039924	SEWER	210.00	0.00	210.00	CUYD	210.00	\$118.00	\$24,780
		0050	3900	6039924	SEWER	2,330.00	0.00	2,330.00	CUYD	2,329.70	\$50.00	\$116,485
		0050	3910	6039924	SEWER	2,394.00	0.00	2,394.00	CUYD	1,480.66	\$112.00	\$165,833
		0050	3920	6039925	SEWER	444.00	0.00	444.00	SQYD	0.00	\$5.00	\$0
		0050	3930	6039925	SEWER	53.00	0.00	53.00	SQYD	0.00	\$200.00	\$0
		0050	3940	6039925	SEWER	323.00	0.00	323.00	SQYD	0.00	\$150.00	\$0
		0055	3950	6049902	MISC.OBSERVATION WELL	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0
		0055	3960	6059903	MISC.4" RIGID SCHEDULE 40 PVC	57.00	0.00	57.00	LF	0.00	\$40.00	\$0
		0055	3970	6059903	MISC.PERFORATED UNDERDRAIN 4" RIGID SCHEDULE 40 PVC	54.00	0.00	54.00	LF	0.00	\$60.00	\$0
		0055	3980	6249905	MISC.MSD TYPE 4 FILTER FABRIC	281.00	0.00	281.00	SQYD	0.00	\$6.00	\$0
		0055	3990	7250312A	12 IN. PIPE GROUP B	219.00	0.00	219.00	LF	0.00	\$122.00	\$0
		0055	4000	7250318A	18 IN. PIPE GROUP B	72.00	0.00	72.00	LF	0.00	\$115.00	\$0

Revision 4/1/2020 Page 18 of 59



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

tract NTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amou Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
F01	J6S1718B	0055	4010	7250324A	24 IN. PIPE GROUP B	79.00	0.00	79.00	LF	0.00	\$134.00	\$0.00
		0055	4020	7250348A	48 IN. PIPE GROUP B	486.00	0.00	486.00	LF	486.00	\$208.00	\$101,088.00
		0055	4030	7259903	MISC.10 IN. C-900 PIPE	114.00	0.00	114.00	LF	0.00	\$176.00	\$0.00
		0055	4040	7259903	MISC.12 IN. PIPE GROUP B - PVC	32.00	0.00	32.00	LF	0.00	\$125.00	\$0.00
		0055	4050	7259903	MISC.6 IN. PIPE GROUP B - PVC	20.00	0.00	20.00	LF	0.00	\$92.00	\$0.00
		0055	4060	7259903	MISC.8 IN. C-900 PIPE	8.00	0.00	8.00	LF	0.00	\$134.00	\$0.00
		0055	4070	7261012	12 IN. PIPE GROUP A	136.00	0.00	136.00	LF	0.00	\$60.00	\$0.00
		0055	4080	7261018	18 IN. PIPE GROUP A	38.00	0.00	38.00	LF	0.00	\$99.00	\$0.00
		0055	4090	7261048	48 IN. PIPE GROUP A	120.00	0.00	120.00	LF	20.80	\$315.00	\$6,552.00
		0055	4100	7269923	SEWER	341.00	0.00	341.00	LF	0.00	\$112.00	\$0.00
		0055	4110	7269923	SEWER	26.00	0.00	26.00	LF	26.00	\$130.00	\$3,380.00
		0055	4120	7269923	SEWER	192.00	0.00	192.00	LF	0.00	\$117.00	\$0.00
		0055	4130	7269923	SEWER	40.00	0.00	40.00	LF	24.50	\$171.00	\$4,189.50
		0055	4140	7269923	SEWER	109.00	0.00	109.00	LF	109.00	\$274.00	\$29,866.00
		0055	4150	7269923	SEWER	115.00	0.00	115.00	LF	115.00	\$286.00	\$32,890.00
		0055	4160	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	60.00	0.00	60.00	FT	0.00	\$689.00	\$0.00
		0055	4170	7310060	PRECAST CONCRETE MANHOLE - 60 IN.	8.00	0.00	8.00	FT	0.00	\$829.00	\$0.00
		0055	4180	7319902	MISC.12 IN. DRAIN BASIN WITH PEDESTRIAN GRATE	4.00	0.00	4.00	EA	0.00	\$4,120.00	\$0.00
		0055	4190	7319902	MISC.42 IN. AREA INLET	3.00	0.00	3.00	EA	0.00	\$3,590.00	\$0.00
		0055	4200	7319902	MISC.42 IN. CURB INLET	3.00	0.00	3.00	EA	0.00	\$3,447.00	\$0.00
		0055	4210	7319902	MISC.42 IN. GRATE INLET WITH SIDE INTAKE	1.00	0.00	1.00	EA	0.00	\$5,025.00	\$0.00
			4220	7319902	MISC.48" HYDRODYNAMIC SEPARATOR	1.00	0.00	1.00	EA	0.00	\$46,106.00	\$0.00
		0055	4230	7319902	MISC.48" MANHOLE WITH EXTERNAL FOULWATER DROP	1.00	0.00	1.00	EA	0.00	\$9,874.00	\$0.00
		0055	4240	7319902	MISC.72 IN. MANHOLE WITH 42 IN. REDUCER	7.00	0.00	7.00	EA	7.00	\$11,498.00	\$80,486.00
		0055										
		0055	4250	7319902	MISC.96 IN. MANHOLE WITH 42 IN. REDUCER	3.00	0.00	3.00	EA	2.00	\$12,749.00	\$25,498.00
		0055	4260	7319902	MISC.DOUBLE CURB INLET	5.00	0.00	5.00	EA	0.00	\$5,035.00	\$0.00
		0055	4270	7319903	MISC.SANITARY 48 IN. MANHOLE	9.00	0.00	9.00	LF	0.00	\$521.00	\$0.00
		0060	4280	6039902	WATER	1.00	0.00	1.00	EA	0.00	\$100.00	\$0.00
		0060	4290	6039923	SEWER	114.00	0.00	114.00	LF	0.00	\$179.00	\$0.00
		0060	4300	6039923	SEWER	8.00	0.00	8.00	LF	0.00	\$134.00	\$0.00
		0060	4310	6039924	SEWER	5.00	0.00	5.00	CUYD	0.00	\$372.00	\$0.00
		0060	4320	6039932	GAS	2.00	0.00	2.00	EA	0.00	\$100.00	\$0.00
		0060	4330	6042010	ADJUSTING MANHOLE	5.00	0.00	5.00	EA	0.00	\$250.00	\$0.00
		0001	5101	2029901	MISC.Removal of Transite (Category II Non-Friable)	0.00	1.00	1.00	LS	1.00	\$4,168.50	\$4,168.50
		0001	5102	2024018	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	0.00	50.00	50.00	LF	0.00	\$52.50	\$0.00
		0050	5103	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00	LS	1.00	\$6,109.63	\$6,109.63
		0001	5104	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00	LS	1.00	\$4,463.92	\$4,463.92
		0001	5105	2029901	MISC.Additional Removal OF Improvements For Rogers Parkway	0.00	1.00	1.00	LS	0.00	\$7,638.44	\$0.00
		0020	5106	9019901	MISC.Receptacles on Ornamental Lighting (City of Brentwood)	0.00	1.00	1.00	LS	0.00	\$75,337.50	\$0.00
		1718B - To			ate as of Report Generated Date							\$2,617,309.47
	J6S1718C	0001	4340	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.20	\$50,000.00	\$10,000.00
		0001	4350	2071000	LINEAR GRADING CLASS 1	4.60	-4.60	0.00	STA	0.00	\$900.00	\$0.00
		0001	4360	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,249.00	0.00	1,249.00	SQYD	0.00	\$6.30	\$0.00
		0001	4370	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	37.90	0.00	37.90	TONS	12.80	\$124.50	\$1,593.60
		0001	4380	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	92.70	0.00	92.70	TONS	29.50	\$139.00	\$4,100.50
		0001	4390	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	64.30	0.00	64.30	TONS	0.00	\$87.00	\$0.00
		0001	4400	4030208	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP190C MIX)	37.50	0.00	37.50	TONS	0.00	\$80.00	\$0.00

Page 19 of 59 Revision 4/1/2020



#### Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
)521-F01	J6S1718C	0001	4410	4071005	TACK COAT	175.00	0.00	175.00	GAL	10.00	\$2.50	\$25.0
		0001	4420	5021107	CONCRETE PAVEMENT ( 7 IN. NON-REINF)	360.00	0.00	360.00	SQYD	0.00	\$88.00	\$0.0
		0001	4430	6071102	MODIFIED CONCRETE GUTTER TYPE B	79.00	0.00	79.00	LF	0.00	\$35.00	\$0.
		0001	4440	6079903	MISC.48" DECORATIVE PEDESTRIAN FENCE (STRUCTURES)	336.00	0.00	336.00	LF	0.00	\$105.00	\$0.
		0001	4450	6079903	MISC.72-INCH TEMPORARY CHAIN LINK FENCE	1,159.00	0.00	1,159.00	LF	1,159.00	\$18.00	\$20,862.
		0001	4460	6079903	MISC.GREEN POWDER COATED CHAIN LINK FENCE (48 IN.)	1,159.00	0.00	1,159.00	LF	0.00	\$30.00	\$0.
		0001	4470	6084023	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	403.00	0.00	403.00	LF	0.00	\$130.00	\$0.
		0001	4480	6085007	PAVED APPROACH, 7 IN.	179.30	0.00	179.30	SQYD	0.00	\$76.00	\$0.
		0001	4490	6086004	CONCRETE SIDEWALK, 4 IN.	257.00	0.00	257.00	SQYD	0.00	\$50.00	\$0.
		0001	4500	6089905	MISC.DECORATIVE CONCRETE PAVING	213.30	0.00	213.30	SQYD	0.00	\$150.00	\$0.
		0001	4510	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	120.00	0.00	120.00	LF	0.00	\$30.00	\$0.
		0001	4520	6091052	CURB AND GUTTER TYPE B	157.00	0.00	157.00	LF	0.00	\$33.00	\$0
		0001	4530	6099903	MISC.MODIFIED CONCRETE CURB TYPE A	11.00	0.00	11.00	LF	0.00	\$26.00	\$0.
		0001	4540	6099903	MISC.MODIFIED CURB	191.00	0.00	191.00	LF	0.00	\$28.00	\$0
		0001	4550	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$50,000.00	\$0
		0001	4560	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$50,000.00	\$25,000
		0001	4570	6209902	MISC.BIKE LANE ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING	7.00	0.00	7.00	EA	0.00	\$250.00	\$0
		0001	4580	6209902	MISC.BIKE LANE BIKE PREFORMED THERMOPLASTIC PAVEMENT MARKING	7.00	0.00	7.00	EA	0.00	\$250.00	\$0
		0001	4590	6209902	MISC.SHARED USE SHARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING	2.00	0.00	2.00	EA	0.00	\$250.00	\$0
		0001	4600	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	304.00	0.00	304.00	SQYD	0.00	\$3.45	\$1
		0001	4610	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$25,000.00	\$
		0001	4620	7011103	DRILLED SHAFTS (2 FT. 6 IN. DIA.)	11.00	0.00	11.00	LF	0.00	\$200.00	\$1
		0001	4630	7034214	CLASS B-2 CONCRETE	0.70	0.00	0.70	CUYD	0.00	\$1,700.00	\$1
		0001	4640	7061000	REINFORCING STEEL	450.00	0.00	450.00	LB	0.00	\$5.00	\$0
		0001	4650	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	1,397.00	0.00	1,397.00	SQFT	0.00	\$45.00	\$0
		0001	4670	7209904	MISC.SMALL BLOCK WALL	1,606.00	0.00	1,606.00	SQFT	0.00	\$36.00	\$0
		0001	4680	8080504	RED OSIER DOGWOOD	24.00	0.00	24.00	EA	0.00	\$33.00	\$1
		0001	4690	8089901	MISC.VERTICAL GATEWAY MONUMENT	1.00	0.00	1.00	LS	0.00	\$21,645.00	\$0
		0001	4700	8089902	MISC.CRIMSON PYGMY BARBERRY	63.00	0.00	63.00	EA	0.00	\$66.00	\$1
		0001	4710	8089902	MISC.DWARF WINGED BURNING BUSH	10.00	0.00	10.00	EA	0.00	\$77.00	\$1
		0001	4720	8089902	MISC.ELIJAH BLUE FESCUE	21.00	0.00	21.00	EA	0.00	\$53.00	\$1
		0001	4730	8089902	MISC.SHAMROCK INKBERRY	20.00	0.00	20.00	EA	0.00	\$77.00	\$(
		0001	4740	8089902	MISC.SPARTAN JUNIPER	21.00	0.00	21.00	EA	0.00	\$72.00	\$(
		0001	4750	8089902	MISC.WINTERGREEN BOXWOOD	30.00	0.00	30.00	EA	0.00	\$77.00	\$(
		0020	4760	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	3.00	0.00	3.00	EA	0.00	\$4,537.00	\$(
		0020	4770	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	20.00	0.00	20.00	LF	6.00	\$16.00	\$96
		0020	4780	9014004	CONDUIT, 4 IN. RIGID, PUSHED	865.00	0.00	865.00	LF	200.00	\$26.50	\$5,300
		0020	4790	9015010	TRENCHING TYPE I	8,527.00	0.00	8,527.00	LF	3,055.00	\$4.50	\$13,747
		0020	4800	9016110	PULL BOX, PREFORMED CLASS 1	15.00	0.00	15.00	EA	4.00	\$980.00	\$3,92
		0020	4810	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	11,160.00	0.00	11,160.00	LF	3,744.00	\$3.15	\$11,79
		0020	4820	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	3.00	0.00	3.00	EA	0.00	\$3,000.00	\$
		0020	4830	9019902	MISC.ORNAMENTAL LIGHT POLE AND LUMINAIRE - KIRKWOOD STREETSCAPING	94.00	0.00	94.00	EA	3.00	\$3,863.00	\$11,58
		0020	4840	9019902	MISC.REMOVE AND RELOCATE PRIVATELY-OWNED LIGHT POLE	9.00	0.00	9.00	EA	0.00	\$1,500.00	\$
		0060	4850	6039932	GAS	1.00	0.00	1.00	EA	0.00	\$100.00	\$1
		0020	5201	9019901	MISC.Receptacles on Ornamental Lighting (City of Kirkwood)	0.00	1.00	1.00	LS	0.00	\$133,970.55	\$0

Revision 4/1/2020 Page 20 of 59



#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and	nd Values are based on Report Gene	erated date and can differ from the posted amount at the time the Estimate was Generated.

Note. I obtou &	aannaa a			004 011 110	port contrated date and earl affer from the posted affect			umate mae	000			
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718C	0001	5202	2079909	MISC.Modified Linear Grading, Class 2	0.00	4.60	4.60	STA	0.00	\$1,600.00	\$0.00
	Project J65	61718C - To	tal Value	Posted to D	ate as of Report Generated Date							\$108,027.20
210521-F01 Overall - Total Value Posted to Date as of Report Generated Date											\$8,079,192.78	

Revision 4/1/2020 Page 21 of 59



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0070	3040504	TYPE 5 AGGREGATE FOR BASE	7/1/22		37.70	SQYD	Wendy's Approach Entrance	162+26	LT			
				7/7/22	96.90	SQYD	Urgent Care Approach Entrance	159+63	LT			
				7/7/22	118.00	SQYD	Starbucks East Half of Approach	168+08	LT			
			7/5/22	7/11/22	5.56	SQYD	Brentwood Place Apartments blind lady sidewalk.	100+65	RT			
				7/11/22	7.56	SQYD	Sidewalk Curb at Ramp 74	161+77.59	LT	162+00	LT	
				7/11/22	32.44	SQYD	Sidewalk at Ramp 76	165+46.48	LT	165+83.75	LT	
			7/6/22	7/14/22	107.10	SQYD	Starbucks Approach	168+08	LT			
			7/7/22	7/14/22	46.67	SQYD	C&G No Leash Needed	168+98.18	LT	170+33.30	LT	
				7/14/22	57.05	SQYD	No Leash Needed East Half of Approach	170+64.50	LT			
			7/11/22	7/14/22	72.22	SQYD	Sidewalk in front of RSI Kitchen & Bath	166+44.49	LT	168+98.18	LT	
			7/12/22	7/14/22	4.40	SQYD	NE corner of Hanley/Manchester quadrant pavement	29+62.25	RT			
				7/14/22	5.00	SQYD	NE corner of Hanley/Manchester quadrant pavement	33+55.91	LT	34+04.98	LT	
				7/14/22	278.69	SQYD	NE corner of Hanley/Manchester quadrant pavement	33+55.91	RT	34+04.98	RT	
			7/13/22	7/18/22	58.98	SQYD	Sidewalk- RSI Kitchen and Bath	166+44.49	LT	168+98.18	LT	
				7/18/22	69.90	SQYD	Sidewalk- RSI Kitchen and Bath	168+98.18	LT	170+43.76	LT	
			7/15/22	7/18/22	1.00	SQYD	C&G No Leash and Car Wash	170+90	LT	170+93.50	LT	
				7/18/22	13.23	SQYD	Sidewalk- RSI Kitchen and Bath	168+98.18	LT	170+43.76	LT	
				7/18/22	28.89	SQYD	Car Wash East Approach	171+17.00	LT			
				7/18/22	49.00	SQYD	C&G Car Wash	171+47.62	LT	172+92.23	LT	
				7/18/22	57.05	SQYD	No Leah Needed West Half Entrance	170+64.50	LT			
130	5021107	CONCRETE PAVEMENT ( 7 IN. NON-REINF)	7/12/22	7/14/22	278.66	SQYD	NE corner of Hanley/Manchester quadrant pavement	33+55.91	LT	34+04.98	LT	
180	6081012	TRUNCATED DOMES	7/13/22	7/18/22	10.00	SQFT	Curb Ramp 80 RSI Kitchen and Bath	168+98.18	LT	170+43.76	LT	
210	6085007	PAVED APPROACH, 7 IN.				SQYD	Wendy's Approach	162+26				
				7/7/22	96.88	SQYD	Urgent Care Approach	159+63				
				7/7/22			Starbucks East Half of Approach	166+08				
			7/6/22	7/14/22	107.10	SQYD	Starbucks Approach	168+08	LT			
				7/14/22			No Leash Needed East Half	170+64.50				
				7/14/22	4.38	SQYD	NE corner of Hanley/Manchester partial approach	29+62.25				
					28.89		Car Wash East Approach	171+17.00				
				7/18/22			No Leash West Half Approach	170+64.50				
220	6086004	CONCRETE SIDEWALK, 4 IN.	7/5/22	7/11/22	5.56	SQYD	Brentwood Place Apartments sidewalk for blind lady.	100+65				
				7/11/22	7.56	SQYD	Sidewalk at Ramp 74	161+77.57		162+00	LT	
				7/11/22				165+46.48		165+83.75		
			7/11/22				Sidewalk in front of RSI Kitchen & Bath	166+44.49		168+98.18		
							Sidewalk-RSI Kitchen and Bath	166+44.49		168+98.18		
			7713722	7/18/22			Sidewalk- RSI Kitchen and Bath	168+98.18		170+43.76		
			7/15/22		13.23		Sidewalk - RSI Kitchen and Bath	168+98.18		170+43.76		
250	6080002	MISC. CONCRETE		7/11/22		EA		161+77.57		162+00		
230	0009902	WISC. CONCRETE	113122	7/11/22	1.00		Curb Ramp 75	162+51.76		162+76.08		
				7/11/22		EA				165+83.75		
			7/44/00	.,	1.00			165+46.48				
					1.00	EA		166+44.49		168+98.18 170+43.76		
000	0001010	ACCURATE OURS OF THE SECURIT AND UNIDERS					Curb Ramp 80	168+98.18		170+43.76	LI	
260	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)		7/7/22	4.50	LF		168+08		100.00		
				7/14/22	19.00	LF		161+77.57		162+00	LI	
			7/7/22	7/14/22	10.00	LF	No Leash Needed East Half	170+64.50				
270	6091052	CURB AND GUTTER TYPE B		7/14/22	140.00	LF		168+98.18		170+33.30		
			7/15/22			LF	C&G No Leash and Car Wash	170+90	LT	170+93.50	LT	
290	6092012	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)		7/18/22	3.00							
		,	7/12/22	7/14/22	90.00		NE corner of Hanley/Manchester quadrant curb	33+55.91	LT	34+04.98	LT	
	6113020	FURNISHING TYPE 2 ROCK BLANKET	7/12/22 7/8/22	7/14/22 7/18/22	90.00	CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket	33+55.91 31+44	LT	32+30	LT	
		,	7/12/22 7/8/22	7/14/22	90.00	CUYD	NE corner of Hanley/Manchester quadrant curb	33+55.91	LT		LT	
330		FURNISHING TYPE 2 ROCK BLANKET	7/12/22 7/8/22 7/8/22	7/14/22 7/18/22 7/18/22	90.00	CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket	33+55.91 31+44 31+44	LT RT/LT	32+30		
330 410	6113040 6161008	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET	7/12/22 7/8/22 7/8/22 7/12/22	7/14/22 7/18/22 7/18/22	90.00 232.20 232.20	CUYD CUYD EA	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket	33+55.91 31+44 31+44 1+45		32+30 32+30 281+06 281+06	RT/LT RT/LT	
330 410 420	6113040 6161008	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY	7/12/22 7/8/22 7/8/22 7/12/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22	90.00 232.20 232.20 4.00	CUYD CUYD EA EA	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits	33+55.91 31+44 31+44 1+45	RT/LT RT/LT	32+30 32+30 281+06	RT/LT RT/LT	
330 410 420 430	6113040 6161008 6161009 6169901	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22	90.00 232.20 232.20 4.00 5.00	CUYD CUYD EA EA LS	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits	33+55.91 31+44 31+44 1+45	RT/LT RT/LT RT/LT	32+30 32+30 281+06 281+06	RT/LT RT/LT	
330 410 420 430 450	6113040 6161008 6161009 6169901 6169902	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC.	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22	90.00 232.20 232.20 4.00 5.00 0.25 2.00	CUYD CUYD EA EA LS	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits	33+55.91 31+44 31+44 1+45 1+45 0+00	RT/LT RT/LT RT/LT	32+30 32+30 281+06 281+06	RT/LT RT/LT	
330 410 420 430 450 360	6113040 6161008 6161009 6169901 6169902 6240104A	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/8/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22	90.00 232.20 232.20 4.00 5.00 0.25 2.00 412.00	CUYD CUYD EA EA LS EA SQYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00	RT/LT RT/LT RT/LT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT	VARIOUS LOCATIONS ON THE JOB SITE
330 410 420 430 450 360	6113040 6161008 6161009 6169901 6169902 6240104A	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/8/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22	90.00 232.20 232.20 4.00 5.00 0.25 2.00 412.00 0.25	CUYD CUYD EA EA LS EA SQYD CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Lob Limits East Side Blanket	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00	RT/LT RT/LT RT/LT RT/LT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT	
330 410 420 430 450 660	6113040 6161008 6161009 6169901 6169902 6240104A	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/8/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22	90.00 232.20 232.20 4.00 5.00 0.25 2.00 412.00 0.25 0.25	CUYD CUYD EA EA LS EA SQYD CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits East Side Blanket ROUTE 100	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00	RT/LT RT/LT RT/LT RT/LT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT	
330 110 120 130 150 360 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/8/22 7/11/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22	90.00 232.20 232.20 4.00 5.00 0.25 2.00 412.00 0.25 0.25	CUYD CUYD EA EA LS EA SQYD CUYD CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits East Side Blanket ROUTE 100 ROUTE 100	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00	RT/LT RT/LT RT/LT RT/LT LT/RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AV
330 410 420 430 450 660 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/8/22 7/11/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22	90.00 232.20 4.00 5.00 0.25 2.00 412.00 0.25 0.25 0.25	CUYD CUYD EA EA LS EA SQYD CUYD CUYD CUYD CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits  East Side Blanket East Side Blanket ROUTE 100 ROUTE 100 ROUTE 100	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44	RT/LT RT/LT RT/LT RT/LT LT/RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVE
330 410 420 430 450 660 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/8/22 7/11/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22	90.00 232.20 232.20 4.00 5.00 0.25 2.00 412.00 0.25 0.25 0.25 0.25 8.00 9.00	CUYD CUYD EA EA LS EA SQYD CUYD CUYD CUYD CUYD CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits East Side Blanket ROUTE 100 ROUTE 100 ROUTE 100 Structure ID: MH-343A	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44	RT/LT RT/LT RT/LT RT/LT RT/LT RT/LT RT/RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVE
330 410 420 430 450 660 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/8/22 7/11/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22	90.00 232.20 232.20 4.00 5.00 0.25 2.00 412.00 0.25 0.25 0.25 0.25 8.00 9.00	CUYD CUYD EA EA LS EA SQYD CUYD CUYD CUYD CUYD CUYD CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket  East Side of Blanket  Job Limits  Job Limits  Job Limits  Four Ender Side Blanket  ROUTE 100  ROUTE 100  ROUTE 100  Structure ID: MH-343A  Structure ID: MH-243A  Pipe ID: SS-343A-1	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RT/LT RT/LT RT/LT RT/LT RT/LT RT/LT RT/RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVE
330 110 120 130 150 360 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/8/22 7/11/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22	90.00 232.20 4.00 5.00 0.25 2.00 412.00 0.25 0.25 0.25 8.00 9.00 15.00	CUYD CUYD EA EA LS EA SQYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD CU	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits  Job Limits  Grant Gr	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RT/LT RT/LT RT/LT RT/LT RT/LT RT/LT RT/RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVI VARIOUS LOCATIONS ALONG ROUTE 100
330 110 120 130 150 360 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/8/22 7/11/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22	90.00 232.20 4.00 5.00 0.25 2.00 412.00 0.25 0.25 0.25 8.00 9.00 15.00	CUYD CUYD EA EA LS EA SQYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD CU	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits  Job Limits  East Side Blanket ROUTE 100 ROUTE 100 ROUTE 100 ROUTE 100 Structure ID: MH-343A Structure ID: MH-299D-4 Structure ID: MH-299D-4 Structure ID: SI-343A Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-343A-1 MH-343A to DI-343	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RT/LT RT/LT RT/LT RT/LT RT/LT RT/LT RT/RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVI VARIOUS LOCATIONS ALONG ROUTE 100
330 410 420 430 450 660 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/8/22 7/11/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/7/22 7/7/22	90.00 232.20 4.00 5.00 0.25 2.00 412.00 0.25 0.25 0.25 0.25 8.00 9.00 9.00 15.00 88.70	CUYD CUYD EA EA LS EA SQYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD CU	NE corner of Hanley/Manchester quadrant curb East Side Blanket Job Limits Job Limits Job Limits Job Limits Fast Side Blanket Fast Side Blanket ROUTE 100 ROUTE 100 ROUTE 100 ROUTE 100 Structure ID: MH-343A Structure ID: MH-259D-4 Structure ID: SI-343A Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-29D-3 MH-209D-3 In H-209D-4	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RT/LT RT/LT RT/LT RT/LT RT/LT RT/LT RT/RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVI VARIOUS LOCATIONS ALONG ROUTE 100
330 410 420 430 450 660 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/8/22 7/11/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/7/22 7/7/22	90.00 232.20 4.00 5.00 0.25 2.00 412.00 0.25 0.25 0.25 0.25 8.00 9.00 9.00 15.00 88.70	CUYD CUYD EA EA LS EA SQYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD CU	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits  Job Limits  East Side Blanket ROUTE 100 ROUTE 100 ROUTE 100 ROUTE 100 Structure ID: MH-343A Structure ID: MH-299D-4 Structure ID: MH-299D-4 Structure ID: SI-343A Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-343A-1 MH-343A to DI-343	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RT/LT RT/LT RT/LT RT/LT LT/RT  RT RT RT RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVI VARIOUS LOCATIONS ALONG ROUTE 100
330 410 420 430 450 660 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/11/22 7/11/22 7/11/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/19/22 7/19/22	90.00 232.20 4.00 5.00 0.25 2.00 412.00 0.25 0.25 0.25 8.00 9.00 15.00 88.70	CUYD CUYD EA EA LS EA SQYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD CU	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits  Job Limits  East Side Blanket ROUTE 100 ROUTE 100 Structure ID: MH-343A Structure ID: MH-29D-4 Structure ID: SI-343A Pipe ID: SS-343A-1 MH-343A to ID:343 Pipe ID: SS-29D-3 MH-209D-3 to MH-209D-4 Structure IN: MH-209D-4	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RT/LT RT/LT RT/LT RT/LT LT/RT  RT RT RT RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVI VARIOUS LOCATIONS ALONG ROUTE 100
330 410 420 430 450 660 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/12/22 7/11/22 7/11/22 7/15/22 7/15/22	7/14/22 7/18/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/17/22 7/7/22 7/7/22 7/7/22 7/7/22	90.00 232.20 4.00 5.00 0.25 2.00 412.00 0.25 0.25 8.00 9.00 9.00 15.00 88.70 80.00	CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits Job Limits Job Limits  Least Side Blanket ROUTE 100 ROUTE 100 ROUTE 100 ROUTE 100 Structure ID: MH-343A Structure ID: MH-243A Structure ID: SI-343A Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-29BD-3 MH-29DD-3 to MH-20D-4 Structure ID: SS-209D-3 to MH-20D-4 Pipe ID: SS-209D-3 Structure ID: SS-209D-3	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RT/LT RT/LT RT/LT RT/LT RT/LT RT/LT LT/RT RT RT RT RT RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVI VARIOUS LOCATIONS ALONG ROUTE 100
330 410 420 430 450 660 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/12/22 7/11/22 7/11/22 7/15/22 7/15/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/17/22 7/7/22 7/7/22 7/7/22 7/11/22 7/11/22 7/11/22 7/11/22	90.00 232.20 4.00 5.02 5.00 412.00 0.25 0.25 8.00 9.00 15.00 88.70 80.00 60.25	CUYD CUYD EAA EAA LS EAA SQYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD CU	NE corner of Hanley/Manchester quadrant curb East Side Blanket Job Limits Job Limits Job Limits Job Limits  Least Side Blanket Least Side Blanket Least Side Blanket ROUTE 100 ROUTE 100 ROUTE 100 ROUTE 100 Structure ID: MH-343A Structure ID: MH-299D-4 Structure ID: MH-299D-4 Structure ID: SI-343A Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-2909-3 MH-209D-3 to MH-209D-4 Structure ID: SS-209D-3 Structure RD: MH-209D-3 to MH-209D-4 Pipe ID: SS-209D-3 B307 Manchester Road Structure Rur: 2G-209D-2 to MH-209D-3 Pipe ID: SS-209D-2	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RT/LT RT/LT RT/LT RT/LT LT/RT  RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT RT/LT RT/LT RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVI VARIOUS LOCATIONS ALONG ROUTE 100
330 410 420 430 450 660 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/12/22 7/11/22 7/11/22 7/15/22 7/15/22	7/14/22 7/18/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/17/22 7/7/22 7/7/22 7/7/22 7/7/22	90.00 232.20 4.00 5.02 5.00 412.00 0.25 0.25 8.00 9.00 15.00 88.70 80.00 60.25	CUYD CUYD EAA EAA LS EAA SQYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD CU	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits Job Limits Job Limits  Least Side Blanket ROUTE 100 ROUTE 100 ROUTE 100 ROUTE 100 Structure ID: MH-343A Structure ID: MH-243A Structure ID: SI-343A Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-29BD-3 MH-29DD-3 to MH-20D-4 Structure ID: SS-209D-3 to MH-20D-4 Pipe ID: SS-209D-3 Structure ID: SS-209D-3	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RT/LT RT/LT RT/LT RT/LT RT/LT RT/LT LT/RT  RT RT RT RT RT RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT RT/LT RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVI VARIOUS LOCATIONS ALONG ROUTE 100
1330 1410 1420 1430 1450 1660	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/12/22 7/11/22 7/11/22 7/15/22 7/15/22	7/14/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/17/22 7/7/22 7/7/22 7/7/22 7/11/22 7/11/22 7/11/22 7/11/22	90.00 232.20 4.00 0.25 2.00 412.00 0.25 8.00 9.00 9.00 88.70 80.00 60.25 2.25 8.00	CUYD CUYD CUYD EA EA LS EA SQYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD CU	NE corner of Hanley/Manchester quadrant curb East Side Blanket Job Limits Job Limits Job Limits Job Limits  Job Limits  Job Limits  East Side Blanket ROUTE 100 ROUTE 100 ROUTE 100 ROUTE 100 Structure ID: MH-343A Structure ID: MH-343A Structure ID: MH-29D-4 Structure ID: SI-343A Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-209D-3 Structure Run: MH-209D-4 Structure Run: MH-209D-1 to MH-209D-4 Pipe ID: SS-209D-3 Structure Run: 2GI-209D-2 to MH-209D-3 Pipe ID: SS-209D-2 Structure Run: MH-209D-3 to MH-209D-9 Pipe ID: SS-209D-2 Structure Run: MH-209D-3 to MH-209D-4 Pipe ID: SS-209D-2	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RT/LT RT/LT RT/LT RT/LT LT/RT  RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT RT/LT RT/LT RT/LT RT/LT	SEDIMAENT REMOVAL ALONG DOROTHY AVE VARIOUS LOCATIONS ALONG ROUTE 100
330 410 420 430 450 660 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/12/22 7/11/22 7/11/22 7/15/22 7/15/22	7/14/22 7/18/22 7/18/22 7/18/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/17/22 7/17/22 7/17/22 7/17/22 7/17/22 7/17/22 7/17/22 7/17/22	90.00 232.20 4.00 0.25 2.00 412.00 0.25 8.00 9.00 9.00 88.70 80.00 60.25 2.25 8.00	CUYD CUYD CUYD EA EA LS EA SQYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD CU	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits Job Limits Job Limits  Job Limits  Job Limits  Job Limits  Least Side Blanket ROUTE 100 ROUTE 100 ROUTE 100 Structure 10: MH-343A Structure ID: MH-343A Structure ID: MH-343A Structure ID: SI-343A Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-299D-3 MH-299D-1 SMH-299D-4 Structure Run: MH-209D-4 Structure Run: MH-209D-4 Structure Run: MH-209D-9 Structure Run: MH-209D-1 to MH-209D-9 Pipe ID: SS-209D-2 to MH-209D-3 Pipe ID: SS-209D-2 Structure Run: MH-209D-1 to MH-209D-9 Pipe ID: SS-209D-3 Pipe ID: SS-209D-3 Pipe ID: SS-209D-3	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RT/LT RT/LT RT/LT RT/LT RT/LT LT//RT RT R	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT RT/LT RT/LT RT RT RT RT RT RT RT RT RT	SEDIMAENT REMOVAL ALONG DOROTHY AVI VARIOUS LOCATIONS ALONG ROUTE 100
330 410 420 430 450 660 750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/12/22 7/11/22 7/11/22 7/15/22 7/16/22 7/16/22	7/14/22 7/18/22 7/18/22 7/18/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/17/22 7/17/22 7/17/22 7/17/22 7/17/22 7/17/22 7/17/22 7/17/22	90.00 232.20 4.00 0.25 2.00 0.25 2.00 412.00 0.25 0.25 8.00 9.00 15.00 88.70 88.70 12.52 2.00 12.52 14.10	CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket Job Limits Job Limits Job Limits Job Limits  Job Limits  Job Limits  East Side Blanket ROUTE 100 ROUTE 100 ROUTE 100 ROUTE 100 Structure ID: MH-343A Structure ID: MH-343A Structure ID: MH-29D-4 Structure ID: SI-343A Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-343A-1 MH-343A to DI-343 Pipe ID: SS-209D-3 Structure Run: MH-209D-4 Structure Run: MH-209D-1 to MH-209D-4 Pipe ID: SS-209D-3 Structure Run: 2GI-209D-2 to MH-209D-3 Pipe ID: SS-209D-2 Structure Run: MH-209D-3 to MH-209D-9 Pipe ID: SS-209D-2 Structure Run: MH-209D-3 to MH-209D-4 Pipe ID: SS-209D-2	33+55.91 31+44 31+44 1+45 1+45 0+00 0+00 31+44 169+89 54+37	RTALT RTALT RTALT RTALT LTART  RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT RT/LT RT/LT RT RT RT RT RT RT RT RT RT	SEDIMAENT REMOVAL ALONG DOROTHY AVE VARIOUS LOCATIONS ALONG ROUTE 100
3320 3330 3330 4410 4420 4430 4450 6660 7750	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/12/22 7/11/22 7/11/22 7/15/22 7/16/22 7/16/22	7/14/22 7/18/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/18/22	90.00 232.20 232.20 4.00 0.25 2.00 412.00 0.25 0.25 8.00 9.00 15.00 88.70 80.00 12.52 2.00 12.52	CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket East Side of Blanket Job Limits Job Limits Job Limits Job Limits  Job Limits  Fast Side Blanket  East Side Blanket  ROUTE 100  ROUTE 100  ROUTE 100  ROUTE 100  Structure ID: MH-343A  Structure ID: MH-343A  Structure ID: SH-343A  Pipe ID: SS-343A-1 MH-343A to DI-343  Pipe ID: SS-343A-1 MH-343A to DI-343  Pipe ID: SS-2090-3  Structure Run: MH-209D-4  Structure Run: MH-209D-5 to MH-209D-4 Pipe ID: SS-209D-3  Structure Run: MH-209D-3 to MH-209D-3  Pipe ID: SS-209D-3  Structure Run: MH-209D-3 to MH-209D-4 Pipe ID: SS-209D-3  Structure Run: MH-209D-3 to MH-209D-4 Pipe ID: SS-209D-3  Structure Run: MH-209D-3 to MH-209D-4 Pipe ID: SS-209D-3	33+55.91 31+44 31+44 1+45 0+00 0+00 31+44 169+89 54+37 169+89	RT/LT RT/LT RT/LT RT/LT RT/LT RT/LT RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT RT/LT RT/LT RT RT RT RT RT RT RT RT RT	SEDIMAENT REMOVAL ALONG DOROTHY AVE VARIOUS LOCATIONS ALONG ROUTE 100
1330 1410 1420 1430 1450 1660	6113040 6161008 6161009 6169901 6169902 6240104A 8061016	FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY MISC. MISC. TRAFFIC CONTROL DEVICES SEPARATION GEOTEXTILE SEDIMENT REMOVAL	7/12/22 7/8/22 7/8/22 7/8/22 7/12/22 7/12/22 7/12/22 7/12/22 7/12/22 7/11/22 7/11/22 7/15/22 7/16/22 7/16/22	7/14/22 7/18/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/18/22 7/14/22 7/14/22 7/14/22 7/14/22	90.00 232.20 4.00 6.00 0.25 0.25 0.25 0.25 0.25 0.25 0.25 0	CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	NE corner of Hanley/Manchester quadrant curb East Side Blanket  East Side of Blanket  Job Limits  Last Side Blanket  ROUTE 100  ROUTE 100  ROUTE 100  Structure 10: MH-343A  Structure 1D: MH-343A  Structure 1D: SI-343A  Pipe 10: SS-343A-1  NH-343A to DI-343  Pipe 10: SS-299D-3  Structure Run: MH-209D-4  Structure Run: MH-209D-3 to MH-209D-4  Pipe 10: SS-209D-3  Structure Run: 2GI-209D-2 to MH-209D-3  Pipe 10: SS-209D-3  Structure Run: MH-209D-3 to MH-209D-4  Pipe 10: SS-209D-3  Structure Run: MH-209D-3 to MH-209D-4  Pipe 10: SS-209D-3  Structure Run: MH-209D-4  Pipe 10: SS-209D-3  Structure Run: 2GI-209E-2 to 2GI-209D-2  Pipe 10: SS-209E-2  Pipe 10: SS-209E-2	33+55.91 31+44 31+44 14+5 0+00 0+00 31+44 169+89 54+37 169+89	RT/LT RT/LT RT/LT RT/LT RT/LT RT/LT RT	32+30 32+30 281+06 281+06 30+00	RT/LT RT/LT RT/LT RT/LT RT/LT RT RT RT RT RT RT RT RT	SEDIMAENT REMOVAL ALONG DOROTHY AVE VARIOUS LOCATIONS ALONG ROUTE 100

Revision 4/1/2020 Page 22 of 59



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line lumber	Item Code	Description	DWR Date	Approval	Quantity Posted	Units	Location	From Station/	Offset/ Distance	To Station/	Offset/ Distance	Comments
1440	2063000	CLASS 3 EXCAVATION	7/11/22	Date				Log Mile		Log Mile		MANCHESTER
				7/18/22	7.26	CUYD	ROUTE 100		LT			FROM STRUCTURE SI-345D TO STRUCTURE SI-345 STRUCTURE ID SS-345D AT MUECK
				7/18/22	11.00	CUYD	ROUTE 100	45+21.55	RT			STRUCTURE ID MH-208D-3 AT 8148 MANCHESTER
				7/18/22	12.00	CUYD	ROUTE 100		LT			FROM STRUCTURE SI-345B TO STRUCTURE SI-345 AT STATION ID SS-345B AT CAR WASH/TRANSMISSION SHOP
				7/18/22	13.00	CUYD	ROUTE 100	55+17.64	RT			STRUCTURE ID MH-209C-1 AT CECELIA
				7/18/22	13.00	CUYD	ROUTE 100		RT			FROM STRUCTURE DI-208B TO MH-208B-1 STRUCTURE ID SS-208B AT 8141 MANCHESTER
				7/18/22	15.00	CUYD	ROUTE 100	54+46.25	RT			STRUCTURE ID SI-209C-0 AT WEST OF CECELIA
				7/18/22	16.00	CUYD	ROUTE 100	54+53	RT			STRUCTURE ID SI-209C EAST OF CECELIA
				7/18/22 7/18/22			ROUTE 100 ROUTE 100	45+24.17 56+51.09				STRUCTURE ID DI-208B AT 8147 MANCHESTER RE STRUCTURE ID MH-209C-2 AT NORTH EAST SIDE
				7/18/22			ROUTE 100	30131.03	RT			NAVIGATE PARKING LOT  FROM STRUCTURE MH-208D-2 TO STRUCTURE MH-208D-3 STRUCTURE ID SS-208D-2 AT LK2
				7/18/22	35.00	CUYD	ROUTE 100		RT			BUILDING FROM STRUCTURE DI-208B TO MH-208B-1 STRUCTURE ID SS-208B AT 8141 MANCHESTER
				7/18/22	35.00	CUYD	ROUTE 100		RT			FROM STRUCTURE ID DI-208B TO STRUCTURE MH-208B-1 STRUCTURE ID SS-208B AT 8141
				7/18/22	55.00	CUYD	ROUTE 100		RT			MANCHESTER  FROM STRUCTURE MH-208D-2 TO STRUCTURE MH-208D-3 STRUCTURE ID SS-208D-2 AT LK2
				7/18/22	70.00	CUYD	ROUTE 100		RT			BUILDING FROM STRUCTURE ID MH-209C-1 TO STRUCTURE
				7/18/22	74.00	CUYD	ROUTE 100		RT			MH-209C-2 STRUCTURE ID SS-209C-1 AT CECELIA FROM STRUCTURE MH-343A TO STRUCTURE DI-3- STRUCTURE ID SS-343A-1 AT EZ STORAGE ROCK
				7/18/22	89.00	CUYD	ROUTE 100		RT			HILL FROM STRUCTURE SI-209C TO STRUCTURE MH-209C-1 STRUCTURE ID SS-209C AT CECELIA
				7/18/22	115.00	CUYD	ROUTE 100		RT			FROM STRUCTURE MH-209C-1 TO STRUCTURE MH-209C-2 STRUCTURE ID SS-209C-1 AT CECELIA
				7/18/22	132.00	CUYD	ROUTE 100		RT			FROM STRUCTURE MH-209C-2 TO STRUCTURE MH-209C-3EX STRUCTURE ID SS-209C-2 AT NAVIGATE
			7/12/22	7/14/22	10.00	CUYD	Structure Run: DI-209A to MH-209C-1 Pipe ID: SS-209A		RT		RT	I WOULD
				7/14/22	18.00	CUYD	Pipe ID: DI-209A	55+28.02	RT		RT	
				7/14/22	18.00	CUYD	Structure Run: DI-209B to MH-209C-1 Pipe ID: SS-209B		RT		RT	
				7/14/22	19.00	CUYD	Pipe ID: DI-209B	55+00.15	RT		RT	
			7/14/22				Pipe ID: MH-208D-2		RT		RT	
				7/18/22	13.44	CUYD	Structure Run: MH-208D-1 to MH-208D-2 Pipe ID: SS-208D-1		RT		RT	
				7/18/22			Pipe ID: DI-208C	47+53.25			RT	
				7/18/22	150.48	CUYD	Structure Run: MH-208D-2 to MH-208D-3 Pipe ID: SS-208D-2		RT		RT	
1480	7250315A	15 IN. PIPE CULVERT GROUP B	7/11/22	7/14/22	2.00	LF	Structure Run: 2GI-209E-1 to 2GI-209E-2 Pipe ID: SS-209E-1		RT		RT	
				7/18/22	24.00	LF	ROUTE 100		LT			FROM STRUCTURE SI-345D TO STRUCTURE SI-34 STRUCTURE ID SS-345D AT AUTO TINT
1490	7250318A	18 IN. PIPE CULVERT GROUP B	7/7/22	7/14/22	16.00	LF	Structure Run: 2GI-209E-2 to 2GI-209D-1		RT		RT	ONCOTONE IS SO GIOSTI TOTO TIM
			7/11/22	7/14/22	39.00	LF	Pipe ID: SS-209E-2 Structure Run: 2GI-209E-2 to 2GI-209D-1		RT		RT	
							Pipe ID: SS-209E-2				101	
1510	7250324A	24 IN. PIPE CULVERT GROUP B	7/11/22	7/18/22	24.00		ROUTE 100		RT			FROM STRUCTURE MH-208D-2 TO STRUCTURE MH-208D-3 STRUCTURE ID SS-208D-2 AT LK2 BUILDING
				7/18/22	48.00		ROUTE 100		RT			FROM STRUCTURE MH-208D-2 TO STRUCTURE MH-208D-3 STRUCTURE ID SS-208D-2 AT LK2 BUILDING
			7/14/22	7/18/22	8.00	LF	Structure Run: MH-208D-1 to MH-208D-2 Pipe ID: SS-208D-1		RT		RT	
				7/18/22	131.00	LF	Structure Run: MH-208D-2 to MH-208D-3 Pipe ID: SS-208D-2		RT		RT	
1520	7250330A	30 IN. PIPE CULVERT GROUP B	7/11/22	7/18/22	8.00	LF	ROUTE 100		RT			FROM STRUCTURE 2GI-208A-2 TO STRUCTURE 2GI208 AT STRUCTURE ID SS-208A-2 AT 8131 MANCHESTER
1530	7250336A	36 IN. PIPE CULVERT GROUP B	7/11/22	7/18/22	4.00	LF	ROUTE 100		RT			FROM STRUCTURE SI-209C-0 TO STRUCTURE SI-209C STRUCTURE ID SS-209D-5 EAST OF CECE
				7/18/22	43.00	LF	ROUTE 100		RT			FROM STRUCTURE MH-209C-2 TO STRUCTURE MH-209C-3 STRUCTURE ID SS-209C-2 AT HELEN A
				7/18/22	59.00	LF	ROUTE 100		RT			FROM STRUCTURE SI-209C TO STRUCTURE
1560	7259903	MISC. METAL PIPE	7/12/22	7/14/22	13.00	LE	Structure Run: DI-209A to MH-209C-1		RT		RT	MH-209C-1 STRUCTURE ID SS-209C AT CECELIA
1000	7200000		7712722				Pipe ID: SS-209A					
				7/14/22	20.00	LF	Structure Run: DI-209B to MH-209C-1 Pipe ID: SS-209B		RT		RT	
1590	7261015	15 IN. PIPE GROUP A	7/1/22		8.00		Pipe ID: SS-343A-1					
			7/11/22	7/7/22	13.00		Pipe ID: SS-343A-1 MH-343A to DI-343 ROUTE 100		RT			FROM STRUCUTE MH-343A TO STRUCTURE DI-34
1000	7004007	24 IN DIDE CROUD A										STRUCTURE ID SS-343A-1 AT EZ STORAGE ROCK HILL
1620	1∠61024	24 IN. PIPE GROUP A	7/1/22	7/7/22	88.00		Pipe ID: SS-209D-3 MH-209D-3 to MH-209D-4 Structure Run: MH-209D-3 to MH-209D-4		RT		RT	
			7/6/22	7/14/22	56.00		Pipe ID: SS-209D-3 Structure Run: MH-209D-3 to MH-209D-4		RT		RT	
				7/14/22	3.00	LF	Pipe ID: SS-209D-3 Structure Run: 2GI-209D-1 to 2GI-209D-2		RT		RT	
				7/14/22	3.00	LF	Pipe ID: SS-209D-1 Structure Run: MH-209D-3 to MH-209D-4 Pipe ID: SS-209D-3		RT		RT	
				7/14/22	5.00	15	Pipe ID: SS-209D-3 Structure Run: 2GI-209D-2 to MH-209D-3		RT		RT	

Revision 4/1/2020 Page 23 of 59



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1620	7261024	24 IN. PIPE GROUP A	7/11/22	7/18/22	6.00	LF	ROUTE 100		RT			FROM STRUCTURE MH-208B-3 TO STRUCTURE DI-208B STRUCTURE ID SS-208D-3 AT 8141 MANCHESTER
				7/18/22	12.00	LF	ROUTE 100		RT			FROM STRUCTURE DI-208B TO STRUCTURE MH-208B-1 STRUCTURE ID SS-208B
				7/18/22	32.00	LF	ROUTE 100		RT			FROM STRUCTURE DI-208B TO STRUCTURE MH- D08B-1 STRUCTURE ID SS-208B AT 8141 MANCHESTER
1720	7319903	MISC. MANHOLES AND DROP INLETS	7/11/22	7/14/22	5.00	LF	Pipe ID: 2GI-209E-1	51+32.42	RT			
				7/14/22	5.00	LF	Pipe ID: 2GI-209E-2	51+32.42	RT			
1750	7319903	MISC. MANHOLES AND DROP INLETS	7/1/22	7/7/22	5.00	LF	MH-209D-4	54+37	RT			
				7/7/22	5.00	LF	MH-343A	169+89	RT			
			7/11/22	7/18/22	6.00	LF	ROUTE 100	45+21.55	RT			STRUCTURE ID MH-208D-1 AT 8148 MANCHESTER
			7/14/22	7/18/22	5.00	LF	Pipe ID: MH-208D-2	47+52.56	RT			
				7/18/22	6.00	LF	Pipe ID: MH-208D-1	48+10.16	RT			
1770	7319903	MISC. MANHOLES AND DROP INLETS	7/11/22	7/18/22	8.00	LF	ROUTE 100	56+51.09	RT			NORTH EAST SIDE OF NAVIGATE PARKING LOT
1780	7319903	MISC. MANHOLES AND DROP INLETS	7/11/22	7/18/22	6.00	LF	ROUTE 100	56+51.09	RT			STRUCTURE ID MH-209C-2 AT NORTH EAST SIDE OF NAVIGATE PARKING LOT
1790	7319903	MISC. MANHOLES AND DROP INLETS	7/11/22	7/18/22	6.00	LF	ROUTE 100	55+17.64	RT			STRUCTURE ID MH-209C-1 AT CECELIA
1810	7319903	MISC. MANHOLES AND DROP INLETS	7/11/22	7/18/22	6.00	LF	ROUTE 100	45+24.17	RT			STRUCTURE ID DI-208B AT 8147 MANCHESTER RD
			7/12/22	7/14/22	6.00	LF	Pipe ID: DI-209A	55+28.02	RT			
				7/14/22	6.00	LF	Pipe ID: DI-209B	55+00.15	RT			
			7/14/22	7/18/22	5.00	LF	Pipe ID: DI-208C	47+53.25	RT			
1820	7319903	MISC. MANHOLES AND DROP INLETS	7/1/22	7/7/22	5.00	LF	SI-343A	269+89				
1830	7319903	MISC. MANHOLES AND DROP INLETS	7/11/22	7/18/22	7.00	LF	ROUTE 100	54+46.25	RT			STRUCTURE ID SI-209C-0 WEST OF CECELIA
				7/18/22	7.00	LF	ROUTE 100	54+53.76	RT			STRUCTURE ID SI-209C WEST OF CECELIA
1870	6039932	GAS - UTILITY ITEM	7/7/22	7/14/22	1.00	EA	No Leash Needed	170+60.77	LT			
1880	6042010	ADJUSTING MANHOLE	7/11/22	7/18/22	1.00	EA	ROUTE 100	174+09.07	RT			ALLEN AUTO APPROACH ENTRANCE
				7/18/22	1.00	EA	ROUTE 100	179+35.78	RT			BIANCO PROPERTIES - C&G
				7/18/22	1.00	EA	ROUTE 100	192+05.51	RT			ROCKHILL CLEANERS
			7/15/22	7/18/22	1.00	EA		172+38.37	LT			

#### Project: J6S1718B

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
2550	2039907	MISC.	7/13/22	7/18/22	1,010.00	CUYD	Pedestrian Underpass Walls 4,5, and 6	6+32.24	LT	8+33.11	LT	
3150	7159902	MISC.	7/8/22	7/18/22	0.50	EA	Phase 1 Tunnel	6+32		6+79		
3210	7339901	MISC.	7/7/22	7/12/22	0.50	LS	Phase 1 Pedestrian Tunnel					

The information below this line are details for Construction Signs (if applicable), No Data Available

Revision 4/1/2020 Page 24 of 59



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	0070	TYPE 5 AGGREGATE FOR BASE	Material		6	Nov 2, 2021	SYSTEM	\$1,440.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Nov 2, 2021	SYSTEM	(\$1,440.18)	
					7	Nov 15, 2021	SYSTEM	\$3,793.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$3,793.86)	
					8	Dec 2, 2021	SYSTEM	\$5,880.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$5,880.42)	, ,
					9	Dec 16, 2021	SYSTEM	\$11,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Dec 16, 2021	SYSTEM	(\$11,088.00)	
					10	Jan 3, 2022	SYSTEM	\$14,165.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Jan 3, 2022	SYSTEM	(\$14,165.55)	
					11	Jan 18, 2022	SYSTEM	\$17,583.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Jan 18, 2022	SYSTEM	(\$17,583.30)	
					12	Feb 1, 2022	SYSTEM	\$20,444.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Feb 1, 2022	SYSTEM	(\$20,444.26)	
					13	Feb 16, 2022	SYSTEM	\$22,144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Feb 16, 2022	SYSTEM	(\$22,144.00)	
					14	Mar 1, 2022	SYSTEM	\$24,859.61	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Mar 1, 2022	SYSTEM	(\$24,859.61)	
					15	Mar 16, 2022	SYSTEM	\$30,004.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$30,004.57)	,
					16	Apr 4, 2022	SYSTEM	\$33,636.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$33,636.64)	
					17	Apr 18, 2022	SYSTEM	\$36,271.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$36,271.18)	
					18	May 2, 2022	SYSTEM	\$42,418.03	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$42,418.03)	,
					19	May 16, 2022	SYSTEM	\$52,594.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					19	May 16,	SYSTEM	(\$52,594.73)	, ,



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6S1718	0070	TYPE 5	Material			2022															
		AGGREGATE FOR BASE			20	Jun 2, 2022	SYSTEM	\$57,328.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.												
					20	Jun 2, 2022	SYSTEM	(\$57,328.99)													
					21	Jun 16, 2022	SYSTEM	\$60,755.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.												
					21	Jun 16, 2022	SYSTEM	(\$60,755.18)													
					22	Jul 1, 2022	SYSTEM	\$64,044.79	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.												
					22	Jul 1, 2022	SYSTEM	(\$64,044.79)	, ,												
					23	Jul 18, 2022	SYSTEM	\$71,273.03	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.												
					23	Jul 18, 2022	SYSTEM	(\$71,273.03)													
				- Total		2022		\$0.00													
			Material - Tot					\$0.00													
	0070 -	- Total						\$0.00													
	0130	CONCRETE PAVEMENT ( 7 IN. NON-REINF)	Material		9	Dec 16, 2021	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					9	Dec 16, 2021	SYSTEM	(\$1,478.40)													
					10	Jan 3, 2022	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
					10	Jan 3, 2022	SYSTEM	(\$1,478.40)													
					11	Jan 18, 2022	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
					11	Jan 18, 2022	SYSTEM	(\$1,478.40)													
					12	Feb 1, 2022	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
					12	Feb 1, 2022	SYSTEM	(\$1,478.40)													
					13	Feb 16, 2022	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
					13	Feb 16, 2022	SYSTEM	(\$1,478.40)													
					14	Mar 1, 2022	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
					14	Mar 1, 2022	SYSTEM	(\$1,478.40)													
									1	15	15	15	15				15	Mar 16, 2022	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
															15	Mar 16, 2022	SYSTEM	(\$1,478.40)			
																				16	Apr 4, 2022
					16	Apr 4, 2022	SYSTEM	(\$2,094.40)													
					17	Apr 18, 2022	SYSTEM	\$2,094.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J6S1718	0130	CONCRETE PAVEMENT ( 7 IN.	Material	7,7	17	Apr 18, 2022	SYSTEM	(\$2,094.40)							
		NON-RÈINF)			18	May 2, 2022	SYSTEM	\$2,094.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
					18	May 2, 2022	SYSTEM	(\$2,094.40)							
					19	May 16, 2022	SYSTEM	\$3,267.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					19	May 16, 2022	SYSTEM	(\$3,267.44)							
					20	Jun 2, 2022	SYSTEM	\$4,733.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
					20	Jun 2, 2022	SYSTEM	(\$4,733.52)							
				- Total				\$0.00							
			Material - To	tal				\$0.00							
	0130 -	- Total						\$0.00							
	0140	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material		6	Nov 2, 2021	SYSTEM	\$9,905.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					6	Nov 2, 2021	SYSTEM	(\$9,905.60)							
					7	Nov 15, 2021	SYSTEM	\$17,015.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					7	Nov 15, 2021	SYSTEM	(\$17,015.00)							
					8	Dec 2, 2021	SYSTEM	\$17,015.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
					8	Dec 2, 2021	SYSTEM	(\$17,015.00)							
					9	Dec 16, 2021	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
					9	Dec 16, 2021	SYSTEM	(\$37,277.20)							
					10	Jan 3, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						
					10	Jan 3, 2022	SYSTEM	(\$37,277.20)							
					11	Jan 18, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						
					11	Jan 18, 2022	SYSTEM	(\$37,277.20)							
					12	Feb 1, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						
					12	Feb 1, 2022	SYSTEM	(\$37,277.20)							
											13	Feb 16, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					13	Feb 16, 2022	SYSTEM	(\$37,277.20)							
					14	Mar 1, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						
					14	Mar 1, 2022	SYSTEM	(\$37,277.20)							
					15	Mar 16, 2022	SYSTEM	\$43,895.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	0140	CONCRETE PAVEMENT ( 9 IN.	Material		15	Mar 16, 2022	SYSTEM	(\$43,895.42)	
		NON-REINF)			16	Apr 4, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$37,277.20)	
					17	Apr 18, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$37,277.20)	
					18	May 2, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$37,277.20)	
					19	May 16, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$37,277.20)	
					20	Jun 2, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			Material - Tot		20	Jun 2, 2022	SYSTEM	(\$37,277.20)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0140 -	- Total						\$0.00	
	0150	CONCRETE APPROACH PAVEMENT	Material		19	May 16, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$13,420.50)	
					20	Jun 2, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$13,420.50)	
					21	Jun 16, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user schirj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$13,420.50)	
					22	Jul 1, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$13,420.50)	
					23	Jul 18, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$13,420.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		- Total						\$0.00	
	0210	PAVED APPROACH, 7 IN.	Material		6	Nov 2, 2021	SYSTEM	\$1,808.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Nov 2, 2021	SYSTEM	(\$1,808.80)	
					7	Nov 15, 2021	SYSTEM	\$9,484.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Nov 15,	SYSTEM	(\$9,484.80)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	0210	PAVED APPROACH, 7 IN.	Material			2021			
		APPROACH, 7 IIV.			8	Dec 2, 2021	SYSTEM	\$25,064.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$25,064.80)	
					9	Dec 16, 2021	SYSTEM	\$47,530.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj¹ overridding Payment Estimate Exception 16 on the current Payment Estimate.
					9	Dec 16, 2021	SYSTEM	(\$47,530.40)	
					10	Jan 3, 2022	SYSTEM	\$59,120.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Jan 3, 2022	SYSTEM	(\$59,120.40)	
					11	Jan 18, 2022	SYSTEM	\$79,579.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Jan 18, 2022	SYSTEM	(\$79,579.60)	
					12	Feb 1, 2022	SYSTEM	\$92,916.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					12	Feb 1, 2022	SYSTEM	(\$92,916.84)	
					13	Feb 16, 2022	SYSTEM	\$99,261.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					13	Feb 16, 2022	SYSTEM	(\$99,261.32)	
					14	Mar 1, 2022	SYSTEM	\$113,541.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					14	Mar 1, 2022	SYSTEM	(\$113,541.72)	
					15	Mar 16, 2022	SYSTEM	\$129,024.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$129,024.44)	
					16	Apr 4, 2022	SYSTEM	\$162,121.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$162,121.68)	
					17	Apr 18, 2022	SYSTEM	\$181,030.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$181,030.48)	
					18	May 2, 2022	SYSTEM	\$204,634.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$204,634.56)	
					19	May 16, 2022	SYSTEM	\$236,441.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$236,441.32)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0210 -	Total						\$0.00	
	0220	CONCRETE SIDEWALK, 4 IN.	Material		6	Nov 2, 2021	SYSTEM	\$6,015.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	0220	CONCRETE SIDEWALK, 4 IN.	Material		6	Nov 2, 2021	SYSTEM	(\$6,015.00)	
					7	Nov 15, 2021	SYSTEM	\$12,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$12,950.00)	
					8	Dec 2, 2021	SYSTEM	\$14,305.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$14,305.00)	
					9	Dec 16, 2021	SYSTEM	\$22,445.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					9	Dec 16, 2021	SYSTEM	(\$22,445.00)	
					10	Jan 3, 2022	SYSTEM	\$29,005.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					10	Jan 3, 2022	SYSTEM	(\$29,005.00)	
					11	Jan 18, 2022	SYSTEM	\$29,936.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					11	Jan 18, 2022	SYSTEM	(\$29,936.00)	
					12	Feb 1, 2022	SYSTEM	\$40,869.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					12	Feb 1, 2022	SYSTEM	(\$40,869.00)	
					13	Feb 16, 2022	SYSTEM	\$42,549.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					13	Feb 16, 2022	SYSTEM	(\$42,549.00)	
					14	Mar 1, 2022	SYSTEM	\$49,964.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					14	Mar 1, 2022	SYSTEM	(\$49,964.50)	
					15	Mar 16, 2022	SYSTEM	\$66,135.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$66,135.50)	
					16	Apr 4, 2022	SYSTEM	\$66,186.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$66,186.00)	
					17	Apr 18, 2022	SYSTEM	\$69,894.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$69,894.50)	
					18	May 2, 2022	SYSTEM	\$79,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$79,450.00)	
					19	May 16, 2022	SYSTEM	\$91,951.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$91,951.50)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6S1718	0220	CONCRETE SIDEWALK, 4 IN.	Material - To	tal				\$0.00		
	0220 -	Total						\$0.00		
	0250	MISC. CONCRETE	Material		7	Nov 15, 2021	SYSTEM	\$5,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
					7	Nov 15, 2021	SYSTEM	(\$5,295.00)		
					8	Dec 2, 2021	SYSTEM	\$5,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
					8	Dec 2, 2021	SYSTEM	(\$5,295.00)		
					9	Dec 16, 2021	SYSTEM	\$7,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	
					9	Dec 16, 2021	SYSTEM	(\$7,060.00)		
					10	Jan 3, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					10	Jan 3, 2022	SYSTEM	(\$10,590.00)		
					11	Jan 18, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
						11	Jan 18, 2022	SYSTEM	(\$10,590.00)	
					12	Feb 1, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
					12	Feb 1, 2022	SYSTEM	(\$10,590.00)		
					13	Feb 16, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
					13	Feb 16, 2022	SYSTEM	(\$10,590.00)		
					14	Mar 1, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
					14	Mar 1, 2022	SYSTEM	(\$10,590.00)		
					15	Mar 16, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
					15	Mar 16, 2022	SYSTEM	(\$10,590.00)		
					16	Apr 4, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	
					16	Apr 4, 2022	SYSTEM	(\$10,590.00)		
					17	Apr 18, 2022	SYSTEM	\$12,355.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
					17	Apr 18, 2022	SYSTEM	(\$12,355.00)		
					18	May 2, 2022	SYSTEM	\$12,355.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
					18	May 2, 2022	SYSTEM	(\$12,355.00)		
					19	May 16, 2022	SYSTEM	\$14,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	
					19	May 16, 2022	SYSTEM	(\$14,120.00)		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6S1718	0250	MISC. CONCRETE	Material	- Total				\$0.00														
			Material - To	tal				\$0.00														
	0250 -	- Total						\$0.00														
	0260	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	Material		6	Nov 2, 2021	SYSTEM	\$15,855.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.													
					6	Nov 2, 2021	SYSTEM	(\$15,855.00)														
					7	Nov 15, 2021	SYSTEM	\$17,445.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.													
					7	Nov 15, 2021	SYSTEM	(\$17,445.00)														
					8	Dec 2, 2021	SYSTEM	\$17,445.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.													
					8	Dec 2, 2021	SYSTEM	(\$17,445.00)														
					9	Dec 16, 2021	SYSTEM	\$22,101.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.													
					9	Dec 16, 2021	SYSTEM	(\$22,101.00)														
					10	Jan 3, 2022	SYSTEM	\$22,194.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.													
					10	Jan 3, 2022	SYSTEM	(\$22,194.00)														
					11	11	Jan 18, 2022	SYSTEM	\$23,919.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.												
					11	Jan 18, 2022	SYSTEM	(\$23,919.00)														
					12	Feb 1, 2022	SYSTEM	\$26,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.													
					12	Feb 1, 2022	SYSTEM	(\$26,502.00)														
					13	Feb 16, 2022	SYSTEM	\$26,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.													
					13	Feb 16, 2022	SYSTEM	(\$26,502.00)														
					14	14	Mar 1, 2022	SYSTEM	\$26,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.												
																		14	Mar 1, 2022	SYSTEM	(\$26,502.00)	
																		15	Mar 16, 2022	SYSTEM	\$32,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$32,475.00)														
							16	Apr 4, 2022	SYSTEM	\$33,708.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.											
							16	Apr 4, 2022	SYSTEM	(\$33,708.00)												
					17	Apr 18, 2022	SYSTEM	\$39,729.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.													
					17	Apr 18, 2022	SYSTEM	(\$39,729.00)														
					18	May 2, 2022	SYSTEM	\$43,711.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.													
					18	May 2, 2022	SYSTEM	(\$43,711.50)														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J6S1718	0260	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	Material		19	May 16, 2022	SYSTEM	\$57,541.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.								
					19	May 16, 2022	SYSTEM	(\$57,541.80)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	0260 -	· Total						\$0.00									
	0270	CURB AND GUTTER TYPE B	Material		8	Dec 2, 2021	SYSTEM	\$5,724.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.								
					8	Dec 2, 2021	SYSTEM	(\$5,724.00)									
					9	Dec 16, 2021	SYSTEM	\$12,030.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.								
					9	Dec 16, 2021	SYSTEM	(\$12,030.00)									
					10	Jan 3, 2022	SYSTEM	\$26,457.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.								
					10	Jan 3, 2022	SYSTEM	(\$26,457.00)									
					11	Jan 18, 2022	SYSTEM	\$50,775.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.								
					11	Jan 18, 2022	SYSTEM	(\$50,775.00)									
					12	Feb 1, 2022	SYSTEM	\$55,842.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.								
					12	Feb 1, 2022	SYSTEM	(\$55,842.00)									
					13	Feb 16, 2022	SYSTEM	\$69,582.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.								
					13	Feb 16, 2022	SYSTEM	(\$69,582.00)									
					14	Mar 1, 2022	SYSTEM	\$78,102.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schinj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.								
					14	Mar 1, 2022	SYSTEM	(\$78,102.00)									
					15	Mar 16, 2022	SYSTEM	\$93,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.								
					15	Mar 16, 2022	SYSTEM	(\$93,342.00)									
													16	Apr 4, 2022	SYSTEM	\$103,083.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$103,083.00)									
												17	Apr 18, 2022	SYSTEM	\$106,458.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	
					17	Apr 18, 2022	SYSTEM	(\$106,458.00)									
					18	May 2, 2022	SYSTEM	\$113,588.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.								
					18	May 2, 2022	SYSTEM	(\$113,588.70)									
					19	May 16, 2022	SYSTEM	\$118,133.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.								
					19	May 16, 2022	SYSTEM	(\$118,133.70)									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6S1718	0270	CURB AND	Material	- Total				\$0.00		
		GUTTER TYPE B Material - Total						\$0.00		
	0270 -	Total						\$0.00		
	0280	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		21	Jun 16, 2022	SYSTEM	\$610.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					21	Jun 16, 2022	SYSTEM	(\$610.50)		
					22	Jul 1, 2022	SYSTEM	\$1,785.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					22	Jul 1, 2022	SYSTEM	(\$1,785.25)		
					23	Jul 18, 2022	SYSTEM	\$1,785.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					23	Jul 18, 2022	SYSTEM	(\$1,785.25)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0280 -	- Total						\$0.00		
	0290	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		6	Nov 2, 2021	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
					6	Nov 2, 2021	SYSTEM	(\$228.00)		
					7	Nov 15, 2021	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	
					7	Nov 15, 2021	SYSTEM	(\$228.00)		
					8	Dec 2, 2021	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
					8	Dec 2, 2021	SYSTEM	(\$228.00)		
					9	Dec 16, 2021	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	
					9	Dec 16, 2021	SYSTEM	(\$228.00)		
					10	Jan 3, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
					10	Jan 3, 2022	SYSTEM	(\$228.00)		
					11	Jan 18, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	
					11	Jan 18, 2022	SYSTEM	(\$228.00)		
						12	Feb 1, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					12	Feb 1, 2022	SYSTEM	(\$228.00)		
					13	Feb 16, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	
					13	Feb 16, 2022	SYSTEM	(\$228.00)		
					14	Mar 1, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	
					14	Mar 1, 2022	SYSTEM	(\$228.00)		
					15	Mar 16,	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment	



Material   150   March   150   March   150   Mart   150	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
15	J6S1718	0290	(6 IN. HEIGHT AND	Material			2022					
2022   SYSTEM   SYSTEM   SYSTEM   SZ28.00   This adjustment offsets the original system-generated Material Payment Edinate Succession 30 on the current Pa			UNDER)			15		SYSTEM	(\$228.00)			
17						16		SYSTEM	\$228.00	Estimate Item Adjustment (0021) due to user schirj1 overridding Payment		
2022   17   2022   18   2023   2000						16		SYSTEM	(\$228.00)			
18						17		SYSTEM	\$228.00	Estimate Item Adjustment (0021) due to user schirj1 overridding Payment		
Estimate Decoption 50 on the current Payment Estimate   Section						17		SYSTEM	(\$228.00)			
19						18		SYSTEM	\$228.00	Estimate Item Adjustment (0025) due to user schirj1 overridding Payment		
2022   Estimate Item Adjustment (0025) duto to user schift] rowndriding Payment Estimate Exception 38 on the current Payment Estimate.   2022   200						18		SYSTEM	(\$228.00)			
Total   Material - Total   S0.00						19		SYSTEM	\$228.00	Estimate Item Adjustment (0025) due to user schirj1 overridding Payment		
Solid   Soli						19		SYSTEM	(\$228.00)			
13					- Total				\$0.00			
13				Material - To	al - Total		\$0.00					
DRAINAGE   2022   Estimate Item Adjustment (0072) due to user's chirji overridding Payment Estimate Exception 33 on the current Payment Estimate Exception 35 on the current Payment Estimate Exception 35 on the current Payment Estimate Estimate Estimate Exception 35 on the current Payment Estimate Estimate Estimate Exception 35 on the current Payment Estimate Estimate Estimate Exception 35 on the current Payment Estimate Estimate Exception 47 on the current Payment Estimate Estimate Estimate Exception 47 on the current Payment Estimate Estimate Estimate Exception 47 on the current Payment Estimate Estimate Estimate Exception 53 on the current Payment Estimate Estimate Estimate Exception 53 on the current Payment Estimate Estimate Exception 53 on the current Payment Estimate Estimate Exception 53 on the current Payment Estimate Exception 53 on the current Payment Estimate Estimate Exception 53 on the current Payment Estimate Exception 53 on the current Payment Estimate Estimate Exception 53 on the current Payment Estimate Exception 53 on the current Payment Estimate Estimate Exception 53 on the current Payment Estimate Estimate Exception 53 on the current Payment Estimate Estimate Exception 53 on th		0290 -	- Total						\$0.00			
14 Mar 1, 2022 SYSTEM \$1,649.20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirjl overridding Payment Estimate Exception 35 on the current Payment Estimate Item Adjustment (0013) due to user schirjl overridding Payment Estimate Exception 35 on the current Payment Estimate Item Adjustment (0017) due to user schirjl overridding Payment Estimate Item Adjustment (0017) due to user schirjl overridding Payment Estimate Item Adjustment (0017) due to user schirjl overridding Payment Item Adjustment (0017) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0022) due to user schirjl overridding Payment Item Adjustment (0023) due to user schirjl overridding Payment Item Adjustment (0023) due to user schirjl overridding Payment Item Adjustment (0023) due to user schirjl overridding Payment Item Adjustment (0023) due to user schirjl overridding Payment Item Adjustment (0023) due to user schirjl overridding Payment Item Adjustment (0023) due to user schirjl overridding Payment Item Adjustment (0023) due to user schirjl overridding Payment Item Adjustment (0023) due to user schirjl overridding Payment Item Adjustment (0023) due to user schirjl overridding Payment Item Adjustment (0023) due to user schirjl overridding Payment Item Adjustment (0023) due to user schirjl o		0300		Material		13		SYSTEM	\$1,649.20	Estimate Item Adjustment (0012) due to user schirj1 overridding Payment		
2022 Estimate Item Adjustment (0013) due to user schirjf overridding Payment Estimate Estimate Exception 33 on the current Payment Estimate Estimate Exception 33 on the current Payment Estimate Item Adjustment (0017) due to user schirjf overridding Payment Estimate Item Adjustment (0017) due to user schirjf overridding Payment Estimate Item Adjustment (0017) due to user schirjf overridding Payment Estimate Item Adjustment (0017) due to user schirjf overridding Payment Estimate Exception 35 on the current Payment Estimate Item Adjustment (0022) due to user schirjf overridding Payment Estimate Item Adjustment (0022) due to user schirjf overridding Payment Estimate Item Adjustment (0022) due to user schirjf overridding Payment Estimate Exception 47 on the current Payment Estimate Item Adjustment (0022) due to user schirjf overridding Payment Estimate Item Adjustment (0022) due to user schirjf overridding Payment Estimate Item Adjustment (0022) due to user schirjf overridding Payment Estimate Item Adjustment (0022) due to user schirjf overridding Payment Estimate Exception 53 on the current Payment Estimate Item Adjustment (0026) due to user schirjf overridding Payment Estimate Item Adjustment (0026) due to user schirjf overridding Payment Estimate Item Adjustment (0026) due to user schirjf overridding Payment Estimate Exception 53 on the current Payment Estimate Item Adjustment (0026) due to user schirjf overridding Payment Estimate Exception 53 on the current Payment Estimate Item Adjustment (0026) due to user schirjf overridding Payment Estimate Exception 53 on the current Payment Estimate Item Adjustment (0026) due to user schirjf overridding Payment Estimate Item Adjustment (0026) due to user schirjf overridding Payment Estimate Item Adjustment (0026) due to user schirjf overridding Payment Estimate Item Adjustment (0016) due to user schirjf overridding Payment Estimate Item Adjustment (0016) due to user schirjf overridding Payment Estimate Item Adjustment (0016) due to user schirjf overridding Payment Estimat						13		SYSTEM	(\$1,649.20)			
15   Mar 16,   SYSTEM   \$1,649.20   Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate Payment Estimate Exception 35 on the current Payment Estimate Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 47 on the current Payment Estimate Payment Estimate Exception 47 on the current Payment Estimate Payment Estimate Exception 47 on the current Payment Estimate Payment Estimate Exception 53 on the current Payment Estimate Payment Estimate Exception 53 on the current Payment Estimate Exception 53 on the current Payment Estimate Payment Estimate Exception 53 on the current Payment Estimate Payment Estimate Exception 53 on the current Payment Estimate Payment Estimate Exception 53 on the current Payment Estimate Payment Estimate Exception 53 on the current Payment Estimate Estimate Exception 53 on the current Payment Estimate Exception 54 on the current Payment Estimate Exception 55 on the current Payment Estimate Payment Estimate Exception 55 on the current Payment Estimate Payment Estimate Exception 55 on the current Payment Estimate Payment Estimate Exception 55 on the current Payment Estimate Payment Estimate Exception 55 on the current Payment Estimate Exception 55 on the current Payment Estimate Exception 55 on the current Payment Estimate Estimate Exception 55 on the current Payment Estimate Exception 55 on the current Payment Estimate Payment Estimate Exception 55 on the curre						14		SYSTEM	\$1,649.20	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment		
Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.  15 Mar 16, 2022  16 Apr 4, 2022  17 Apr 18, 2022  18 Apr 18, 2022  19 Apr 18, 2022  10 Apr 18, 2022  10 Apr 18, 2022  10 Apr 18, 2022  11 Apr 18, 2022  12 Apr 18, 2022  13 Apr 18, 2022  14 Apr 18, 2022  15 Apr 18, 2022  16 Apr 18, 2022  17 Apr 18, 2022  18 May 2, 2022  18 May 2, 2022  19 May 16, 2022  19 May 16, 2022  19 May 16, 2022  19 May 16, 2022  20 Jun 2, SYSTEM  20 SYSTEM  21 This adjustment offsets the original						14		SYSTEM	(\$1,649.20)			
2022  16 Apr 4, 2022  17 Apr 18, 2022  18 May 2, 2022  18 May 2, 2022  18 May 2, 2022  19 May 16, SYSTEM 26,633.20  2022  19 May 16, SYSTEM 2022  2024  19 May 16, SYSTEM 2022  2025  2026  2027  2028  2029  2029  2029  2029  2020						15		SYSTEM	\$1,649.20	Estimate Item Adjustment (0017) due to user schirj1 overridding Payment		
Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.  16						15		SYSTEM	(\$1,649.20)			
2022  17 Apr 18, 2YSTEM \$1,649.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 53 on the current Payment Estimate.  17 Apr 18, 2YSTEM (\$1,649.20) 2022  18 May 2, 2O22  18 May 2, 2O22  19 May 16, 2O22  19 May 16, 2O22  19 May 16, 2O22  20 Jun 2, 2O22  20 Jun 2, 2O22  20 Jun 2, SYSTEM \$6,633.20						16		SYSTEM	\$1,649.20	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment		
Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.  17						16		SYSTEM	(\$1,649.20)			
2022  18 May 2, 2022  18 May 2, 2022  19 May 16, 2022  19 May 16, 2022  20 Jun 2, 2022  20 Jun 2, SYSTEM  \$6,633.20  \$6,633.20  This adjustment offsets the original system-generated Material Payment Estimate Exception 53 on the current Payment Estimate.  18 May 2, 2022  19 May 16, 2022  19 May 16, 2022  20 Jun 2, SYSTEM  \$6,633.20  This adjustment offsets the original system-generated Material Payment Estimate Exception 39 on the current Payment Estimate.  19 May 16, 2022  20 Jun 2, SYSTEM  \$6,633.20  This adjustment offsets the original system-generated Material Payment Estimate Exception 39 on the current Payment Estimate.						17		SYSTEM	\$1,649.20	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment		
Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.  18 May 2, 2022  19 May 16, 2022  19 May 16, 2022  19 May 16, 2022  19 May 16, 2022  20 Jun 2, 2022  20 Jun 2, SYSTEM  \$6,633.20  \$6,633.20  This adjustment offsets the original system-generated Material Payment Estimate Exception 39 on the current Payment Estimate.  19 May 16, 2022  20 Jun 2, SYSTEM  \$6,633.20  This adjustment offsets the original system-generated Material Payment Estimate Exception 39 on the current Payment Estimate.  20 Jun 2, SYSTEM  \$6,633.20  \$6,633.20  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.						17		SYSTEM	(\$1,649.20)			
2022  19 May 16, 2022  19 May 16, 2022  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.  19 May 16, 2022  20 Jun 2, SYSTEM \$6,633.20  \$6,633.20  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  20 Jun 2, SYSTEM \$6,633.20)								18		SYSTEM	\$6,633.20	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment
2022 Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.  19 May 16, 2022  20 Jun 2, SYSTEM \$6,633.20  SYSTEM \$6,633.20  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.						18		SYSTEM	(\$6,633.20)			
20 Jun 2, 2022  SYSTEM \$6,633.20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  20 Jun 2, SYSTEM (\$6,633.20)						19		SYSTEM	\$6,633.20	Estimate Item Adjustment (0026) due to user schirj1 overridding Payment		
2022 Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  20 Jun 2, SYSTEM (\$6,633.20)						19		SYSTEM	(\$6,633.20)			
						20		SYSTEM	\$6,633.20	Estimate Item Adjustment (0016) due to user schirj1 overridding Payment		
						20		SYSTEM	(\$6,633.20)			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J6S1718	0300	MISC. PAVED DRAINAGE	Material	- Total				\$0.00																	
	Material - Total							\$0.00																	
		Total						\$0.00																	
	0310	MISC. PAVED DRAINAGE	Material		19	May 16, 2022	SYSTEM	\$2,022.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.																
					19	May 16, 2022	SYSTEM	(\$2,022.15)																	
				- Total				\$0.00																	
			Material - To	tal				\$0.00																	
	0310 -						0)10==11	\$0.00																	
	0340	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		11	Jan 18, 2022	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.																
					11	Jan 18, 2022	SYSTEM	(\$3,800.00)																	
					12	Feb 1, 2022	SYSTEM	\$13,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.																
					12	Feb 1, 2022	SYSTEM	(\$13,560.00)																	
					13	Feb 16, 2022	SYSTEM	\$23,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.																
					13	Feb 16, 2022	SYSTEM	(\$23,100.00)																	
					14	Mar 1, 2022	SYSTEM	\$23,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.																
					14	Mar 1, 2022	SYSTEM	(\$23,100.00)																	
					15	Mar 16, 2022	SYSTEM	\$23,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.																
					15	Mar 16, 2022	SYSTEM	(\$23,100.00)																	
					16	Apr 4, 2022	SYSTEM	\$23,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.																
					16	Apr 4, 2022	SYSTEM	(\$23,100.00)																	
					17	Apr 18, 2022	SYSTEM	\$23,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.																
					17	Apr 18, 2022	SYSTEM	(\$23,100.00)																	
																					18	May 2, 2022	SYSTEM	\$23,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
						18	May 2, 2022	SYSTEM	(\$23,100.00)																
																			19	May 16, 2022	SYSTEM	\$23,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.		
					19	May 16, 2022	SYSTEM	(\$23,100.00)																	
					20	Jun 2, 2022	SYSTEM	\$23,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																
					20	Jun 2, 2022	SYSTEM	(\$23,100.00)																	
				- Total				\$0.00																	
			Material - To	aterial - Total				\$0.00																	
	0340 -	Total						\$0.00																	
	0350	SUBGRADE COMPACTION (6	Material		12	Feb 1, 2022	SYSTEM	\$146.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J6S1718	0350	IN. DEPTH) (PAVEM	Material						Estimate Exception 39 on the current Payment Estimate.														
		(I AVEIN			12	Feb 1, 2022	SYSTEM	(\$146.40)															
					13	Feb 16, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.														
					13	Feb 16, 2022	SYSTEM	(\$346.50)															
					14	Mar 1, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.														
					14	Mar 1, 2022	SYSTEM	(\$346.50)															
							15	Mar 16, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.												
							15	Mar 16, 2022	SYSTEM	(\$346.50)													
											16	Apr 4, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.								
											16	Apr 4, 2022	SYSTEM	(\$346.50)									
					17	Apr 18, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.														
					17	Apr 18, 2022	SYSTEM	(\$346.50)															
					18	May 2, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.														
								18	May 2, 2022	SYSTEM	(\$346.50)												
						19	May 16, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.													
							19	May 16, 2022	SYSTEM	(\$346.50)													
					20	Jun 2, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.														
									20	Jun 2, 2022	SYSTEM	(\$346.50)											
					21	Jun 16, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
																			21	Jun 16, 2022	SYSTEM	(\$346.50)	
												22	Jul 1, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
										22	Jul 1, 2022	SYSTEM	(\$346.50)										
					23	Jul 18, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.														
					23	Jul 18, 2022	SYSTEM	(\$346.50)															
				- Total				\$0.00															
			Material - Tot	tal				\$0.00															
	0350 -							\$0.00															
	0360	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	Material		12	Feb 1, 2022	SYSTEM	\$195.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.														
					12	Feb 1, 2022	SYSTEM	(\$195.20)															
					13	Feb 16,	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J6S1718	0360	TYPE 1 OR 5 AGGREGATE FOR	Material			2022			Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.														
		BASE (4 IN. TH			13	Feb 16, 2022	SYSTEM	(\$462.00)															
					14	Mar 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.														
					14	Mar 1, 2022	SYSTEM	(\$462.00)															
					15	Mar 16, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.														
					15	Mar 16, 2022	SYSTEM	(\$462.00)															
						16	Apr 4, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schirj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.													
												16	Apr 4, 2022	SYSTEM	(\$462.00)								
													17	Apr 18, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schirj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.						
											17	Apr 18, 2022	SYSTEM	(\$462.00)									
					18	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.														
					18	May 2, 2022	SYSTEM	(\$462.00)															
					19	May 16, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schirj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.														
								19	May 16, 2022	SYSTEM	(\$462.00)												
					20	Jun 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.														
						20	Jun 2, 2022	SYSTEM	(\$462.00)														
						21	Jun 16, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.													
					21	Jun 16, 2022	SYSTEM	(\$462.00)															
				- Total				\$0.00															
	0260	· Total	Material - To	tal				\$0.00 \$0.00															
	0380	DOWEL BAR (DRILLING, FURNISHING AND	Material		12	Feb 1, 2022	SYSTEM	\$120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.														
		INST							T	Τ   -	T   -	T	T	ST	ST	ST -	Г		12	Feb 1, 2022	SYSTEM	(\$120.00)	
					13	Feb 16, 2022	SYSTEM	\$120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.														
					13	Feb 16, 2022	SYSTEM	(\$120.00)															
					14	Mar 1, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.														
					14	Mar 1, 2022	SYSTEM	(\$510.00)															
					15	Mar 16, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.														
					15	Mar 16, 2022	SYSTEM	(\$510.00)															



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	0380	DOWEL BAR (DRILLING, FURNISHING AND	Material		16	Apr 4, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
		INST			16	Apr 4, 2022	SYSTEM	(\$510.00)	
					17	Apr 18, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$510.00)	
					18	May 2, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schirj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$510.00)	
					19	May 16, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$510.00)	
					20	Jun 2, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$510.00)	
					21	Jun 16, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$510.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0380 -	- Total						\$0.00	
	0390	DOWEL BAR (FURNISH AND INSTALL WITH BASK	Material		12	Feb 1, 2022	SYSTEM	\$13.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
		BASK			12	Feb 1, 2022	SYSTEM	(\$13.00)	
					13	Feb 16,	SYSTEM	\$13.00	This adjustment offsets the original system-generated Material Payment
						2022		Ψ10.00	Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					13	Feb 16, 2022	SYSTEM	(\$13.00)	Estimate Item Adjustment (0017) due to user schirj1 overridding Payment
					13	Feb 16,	SYSTEM		Estimate Item Adjustment (0017) due to user schirj1 overridding Payment
						Feb 16, 2022 Mar 1,		(\$13.00)	Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment
					14	Feb 16, 2022 Mar 1, 2022 Mar 1,	SYSTEM	(\$13.00) \$26.00	Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment
					14	Feb 16, 2022 Mar 1, 2022 Mar 1, 2022 Mar 16,	SYSTEM	(\$13.00) \$26.00 (\$26.00)	Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment
					14 14 15	Feb 16, 2022  Mar 1, 2022  Mar 1, 2022  Mar 16, 2022	SYSTEM SYSTEM SYSTEM	(\$13.00) \$26.00 (\$26.00) \$26.00	Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment
					14 14 15	Feb 16, 2022  Mar 1, 2022  Mar 1, 2022  Mar 16, 2022  Mar 16, 2022  Apr 4,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$13.00) \$26.00 (\$26.00) \$26.00	Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment
					14 14 15 15	Feb 16, 2022 Mar 1, 2022 Mar 1, 2022 Mar 16, 2022 Mar 16, 2022 Apr 4, 2022 Apr 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$13.00) \$26.00 (\$26.00) \$26.00 (\$26.00)	Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment
					14 14 15 15 16 16	Feb 16, 2022  Mar 1, 2022  Mar 16, 2022  Mar 16, 2022  Apr 4, 2022  Apr 4, 2022  Apr 18,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$13.00) \$26.00 (\$26.00) \$26.00 (\$26.00) (\$26.00)	Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 57 on the current Payment Estimate.
					14 15 15 16 16 17	Feb 16, 2022 Mar 1, 2022 Mar 1, 2022 Mar 16, 2022 Apr 4, 2022 Apr 4, 2022 Apr 18, 2022 Apr 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$13.00) \$26.00 (\$26.00) \$26.00 (\$26.00) \$26.00 (\$26.00)	Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 57 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	0390	DOWEL BAR (FURNISH AND INSTALL WITH BASK	Material		19	May 16, 2022	SYSTEM	\$26.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schirj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
		DASK			19	May 16, 2022	SYSTEM	(\$26.00)	
					20	Jun 2, 2022	SYSTEM	\$26.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$26.00)	
					21	Jun 16, 2022	SYSTEM	\$26.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$26.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0390 -	- Total						\$0.00	
	0430	MISC.	Material		6	Nov 2, 2021	SYSTEM	\$37,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					6	Nov 2, 2021	SYSTEM	(\$37,500.00)	
					7	Nov 15, 2021	SYSTEM	\$37,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$37,500.00)	
					8	Dec 2, 2021	SYSTEM	\$37,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$37,500.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0430 -	- Total						\$0.00	
	0660				20	I 0			This adjustment offsets the original system-generated Material Payment
	0000	SEPARATION GEOTEXTILE	Material		20	Jun 2, 2022	SYSTEM	\$2,484.40	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
	0000		Material		20		SYSTEM	\$2,484.40 (\$2,484.40)	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment
	0000		Material			2022 Jun 2,			Estimate Item Adjustment (0022) due to user schirj1 overridding Payment
	0000		Material		20	Jun 2, 2022 Jun 16,	SYSTEM	(\$2,484.40)	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment
	0000		Material	- Total	20	Jun 2, 2022 Jun 16, 2022 Jun 16,	SYSTEM	(\$2,484.40) \$2,484.40	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment
	0000		Material - To		20	Jun 2, 2022 Jun 16, 2022 Jun 16,	SYSTEM	(\$2,484.40) \$2,484.40 (\$2,484.40)	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment
					20	Jun 2, 2022 Jun 16, 2022 Jun 16,	SYSTEM	(\$2,484.40) \$2,484.40 (\$2,484.40) \$0.00	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment
		GEOTEXTILE	Material - To		20	Jun 2, 2022 Jun 16, 2022 Jun 16,	SYSTEM	(\$2,484.40) \$2,484.40 (\$2,484.40) \$0.00	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment
	0660 -	GEOTEXTILE  - Total  CURB INLET	Material - To		20 21 21	2022 Jun 2, 2022 Jun 16, 2022 Jun 16, 2022	SYSTEM SYSTEM SYSTEM	(\$2,484.40) \$2,484.40 (\$2,484.40) \$0.00 \$0.00	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment
	0660 -	GEOTEXTILE  - Total  CURB INLET	Material - To		20 21 21 17	2022 Jun 2, 2022 Jun 16, 2022 Jun 16, 2022 Apr 18, 2022	SYSTEM SYSTEM SYSTEM	(\$2,484.40) \$2,484.40 (\$2,484.40) \$0.00 \$0.00 \$183.00	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment
	0660 -	GEOTEXTILE  - Total  CURB INLET	Material - To		20 21 21 17	2022 Jun 2, 2022 Jun 16, 2022 Jun 16, 2022 Apr 18, 2022 Apr 18, 2022 May 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,484.40) \$2,484.40 (\$2,484.40) \$0.00 \$0.00 \$183.00	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schirj1 overridding Payment Estimate Item Adjustment (0032) due to user schirj1 overridding Payment
	0660 -	GEOTEXTILE  - Total  CURB INLET	Material - To		20 21 21 17 17 18	2022 Jun 2, 2022 Jun 16, 2022 Jun 16, 2022  Apr 18, 2022  Apr 18, 2022  May 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,484.40) \$2,484.40 (\$2,484.40) \$0.00 \$0.00 \$183.00 (\$183.00) \$183.00	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schirj1 overridding Payment Estimate Item Adjustment (0032) due to user schirj1 overridding Payment
	0660 -	GEOTEXTILE  - Total  CURB INLET	Material - To		20 21 21 17 17 18	2022 Jun 2, 2022 Jun 16, 2022  Jun 16, 2022  Apr 18, 2022  Apr 18, 2022  May 2, 2022  May 16, May 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,484.40) \$2,484.40 (\$2,484.40) \$0.00 \$0.00 \$183.00 (\$183.00) (\$183.00)	Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schirj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 75 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	0740	CURB INLET	Material						Estimate Exception 41 on the current Payment Estimate.
		CHECK			20	Jun 2, 2022	SYSTEM	(\$183.00)	
					21	Jun 16, 2022	SYSTEM	\$183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$183.00)	
					22	Jul 1, 2022	SYSTEM	\$183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user steppr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$183.00)	
					23	Jul 18, 2022	SYSTEM	\$183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$183.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0740 -	- Total						\$0.00	
	0780	TYPE C BERM	Material		20	Jun 2, 2022	SYSTEM	\$6,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$6,050.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0780 -	- Total						\$0.00	
	0800	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$17,847.84	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$17,847.84	
			Construction	n Stockpile STMI - Total				\$17,847.84	
	0800 -							\$17,847.84	
	0810	BRACKET ARM, 15 FT. OR 4.6 M	Construction Stockpile STMI	- Total	23	Jul 18, 2022	SYSTEM	\$7,576.68	Payment Estimate Item Adjustment generated Stockpile Transaction
			Canaturation		This Total			\$7,576.68	
	0040	Total	Construction	Stockpile S	I WII - TOtal			\$7,576.68	
	0810 -		Construction		22	Jul 40	CVCTEM	\$7,576.68	Decimant Cation stall have Adjustment generated Stackwills Transposition
	0990	SIGNAL SIGN, MOUNTING HARDWARE	Stockpile	Total	23	Jul 18, 2022	SYSTEM	\$5,625.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total Stockpile S1	[MI_Total			\$5,625.00 \$5,625.00	
	0990 -	Total	Construction	-Stockhile S	-wii - Total			\$5,625.00	
	1000	POST, SIGNAL 8	Construction		23	Jul 18,	SYSTEM	\$5,625.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		FT. OR 2.4 M	Stockpile STMI	- Total		2022		\$11,718.31	
			Construction	Stockpile S	「MI - Total			\$11,718.31	
	1000	· Total	201101101					\$11,718.31	
	1010	POST, SIGNAL 15	Construction		23	Jul 18,	SYSTEM	\$2,047.64	Payment Estimate Item Adjustment generated Stockpile Transaction
	.010	FT. OR 4.6 M	Stockpile STMI	- Total		2022	J. J. LIVI	\$2,047.64	
			Construction	Stockpile S	「MI - Total			\$2,047.64	
	1010	- Total	- Johnstituction	- Jedenpile 6	Total			\$2,047.64	
	1030	POST, TYPE CL,	Construction		23	Jul 18,	SYSTEM	\$10,473.04	Payment Estimate Item Adjustment generated Stockpile Transaction
	1030	25 FT. ARM OR 7.6 M ARM	Stockpile	- Total	20	2022	CIGIEIN	\$10,473.04	aymont Estimate form Aujustinent generated Stockpile Hallsaction
			Construction		TAIL Total				
	4000	Tabel	Construction	Stockpile S	IVII - Total			\$10,473.04	
	1030 -	- Total						\$10,473.04	



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
718	1040	POST, TYPE CL, 30 FT. ARM OR 9.1	Construction Stockpile		23	Jul 18, 2022	SYSTEM	\$12,695.78	Payment Estimate Item Adjustment generated Stockpile Transaction
		M ARM	STMI	- Total				\$12,695.78	
			Construction	Stockpile S	TMI - Total			\$12,695.78	
	1040 -	Total						\$12,695.78	
	1050	POST, TYPE CL,	Construction		23	Jul 18,	SYSTEM	\$6,554.92	Payment Estimate Item Adjustment generated Stockpile Transaction
	1030	35 FT. ARM OR 10.7 M ARM	Stockpile STMI	- Total	23	2022	STSTEM	\$6,554.92	r ayment Estimate nem Aujustment generated Stockpile Transaction
			Construction		TML Total			\$6,554.92	
	4050	T-4-1	Construction	otockpile 3	TIVII - TOLA				
		Total						\$6,554.92	
	1060	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	Construction Stockpile STMI	- Total	23	Jul 18, 2022	SYSTEM	\$34,285.61 \$34,285.61	Payment Estimate Item Adjustment generated Stockpile Transaction
			0 1 1						
			Construction	Stockpile S	IMI - Iota			\$34,285.61	
	1060 -	Total						\$34,285.61	
	1070	POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$9,703.63	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$9,703.63	
			Construction	Stockpile S1	TMI - Tota			\$9,703.63	
	1070 -	Total						\$9,703.63	
	1075	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$7,599.34	Payment Estimate Item Adjustment generated Stockpile Transaction
			0.1111	- Total				\$7,599.34	
			Construction	Stockpile S	TMI - Tota			\$7,599.34	
	1075 -	Total						\$7,599.34	
	1077	POST, TYPE B, LONGEST ARM 20 FT. OR 6.1	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$5,339.52	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$5,339.52	
			Construction	Stockpile S	TMI - Tota			\$5,339.52	
	1077 -	Total						\$5,339.52	
	1080	POST, TYPE BL, LONGEST ARM 35 FT. OR 10.	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$10,737.75	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$10,737.75	
			Construction	Stockpile S	TMI - Tota			\$10,737.75	
	1080 -	Total						\$10,737.75	
	1090	POST, TYPE BL, LONGEST ARM 55 FT.	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$15,812.56	Payment Estimate Item Adjustment generated Stockpile Transaction
			3	- Total				\$15,812.56	
			Construction	Stockpile S	TMI - Tota			\$15,812.56	
	1090 -	Total						\$15,812.56	
	1320	MISC.	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$23,505.66	Payment Estimate Item Adjustment generated Stockpile Transaction
			O I IVII	- Total				\$23,505.66	
			Construction	Stockpile S	TMI - Tota			\$23,505.66	
	1320 -	Total						\$23,505.66	
	1340	MISC.	Construction Stockpile		19	May 16, 2022	SYSTEM	(\$7.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$7.00)	
			Construction	Stockpile - 1	Γotal			(\$7.00)	
			Construction Stockpile		18	May 2, 2022	SYSTEM	\$7.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI		19	May 16, 2022	SYSTEM	\$51,460.89	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$51,467.89	
			Construction	Stockpile S	TMI - Total			\$51,467.89	
	1340 -	Total						\$51,460.89	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	1550	MISC. METAL PIPE	Overrun	Overrun	22	Jul 1, 2022	SYSTEM	(\$1,482.00)	
				Overrun - T	otal			(\$1,482.00)	
			Overrun - To	tal				(\$1,482.00)	
	1550 -	Total						(\$1,482.00)	
	1590	15 IN. PIPE GROUP A	Overrun	Overrun	23	Jul 18, 2022	SYSTEM	(\$2,079.00)	
				Overrun - T	otal			(\$2,079.00)	
			Overrun - To	tal				(\$2,079.00)	
	1590 -	Total						(\$2,079.00)	
	1670	MISC. MANHOLES AND DROP INLETS	Material		14	Mar 1, 2022	SYSTEM	\$5,886.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					14	Mar 1, 2022	SYSTEM	(\$5,886.00)	
					15	Mar 16, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$7,848.00)	
					16	Apr 4, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 64 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$7,848.00)	
					17	Apr 18, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment Estimate Exception 70 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$7,848.00)	
					18	May 2, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$7,848.00)	
					19	May 16, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$7,848.00)	
					20	Jun 2, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$7,848.00)	
					21	Jun 16, 2022	SYSTEM	\$9,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$9,810.00)	
					22	Jul 1, 2022	SYSTEM	\$9,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user steppr1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$9,810.00)	
					23	Jul 18, 2022	SYSTEM	\$9,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0071) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$9,810.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1670 -	Total						\$0.00	
	1690	MISC. MANHOLES AND DROP INLETS	Material		22	Jul 1, 2022	SYSTEM	\$15,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user steppr1 overridding Payment Estimate Exception 35 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6S1718	1690	MISC. MANHOLES AND DROP	Material		22	Jul 1, 2022	SYSTEM	(\$15,771.00)												
		INLETS			23	Jul 18, 2022	SYSTEM	\$15,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.											
					23	Jul 18, 2022	SYSTEM	(\$15,771.00)												
				- Total				\$0.00												
			Material - Tot	tal				\$0.00												
	1690 -	Total						\$0.00												
	1850	WATER - UTILITY ITEM	Material		7	Nov 15, 2021	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
					7	Nov 15, 2021	SYSTEM	(\$100.00)												
					8	Dec 2, 2021	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
					8	Dec 2, 2021	SYSTEM	(\$100.00)												
					9	Dec 16, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.											
					9	Dec 16, 2021	SYSTEM	(\$400.00)												
							10	Jan 3, 2022	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.									
					10	Jan 3, 2022	SYSTEM	(\$500.00)												
					- Total		\$0.00													
			Material - Tot	tal				\$0.00												
	1850 -	Total						\$0.00												
	1860	WATER - UTILITY ITEM	Material		16	Apr 4, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.											
														16	Apr 4, 2022	SYSTEM	(\$4,859.00)			
					17	Apr 18, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.											
					17	Apr 18, 2022	SYSTEM	(\$4,859.00)												
					18	May 2, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.											
					18	May 2, 2022	SYSTEM	(\$4,859.00)												
					_											19	May 16, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
							19	May 16, 2022	SYSTEM	(\$4,859.00)										
																20	Jun 2, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$4,859.00)												
					21	Jun 16, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
					21	Jun 16, 2022	SYSTEM	(\$4,859.00)												
					22	Jul 1, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user steppr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.											
					22	Jul 1,	SYSTEM	(\$4,859.00)												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	1860	WATER - UTILITY ITEM	Material		23	2022 Jul 18,	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment
						2022			Estimate Item Adjustment (0073) due to user schirj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$4,859.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1860 -	Total MISC.	O a madema atia m		00	lul 40	SYSTEM	\$0.00 \$9.984.32	Description of the Adjustment approach of the dual to Towns of the
	1910	IVIISC.	Construction Stockpile STMI		23	Jul 18, 2022	STSTEM	, , , , , ,	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$9,984.32	
			Construction	1 Stockpile S1	TMI - Total			\$9,984.32	
	1910 -		:		00	1.1.10	0)/07514	\$9,984.32	
	1920	MISC.	Construction Stockpile STMI	pile 2022			SYSTEM	\$10,856.20	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$10,856.20	
			Construction	1 Stockpile S	MI - Total			\$10,856.20	
		Total					2) (2===	\$10,856.20	
	2110	110 MISC.	Construction Stockpile STMI		18	May 2, 2022	SYSTEM	\$3,610.00	Payment Estimate Item Adjustment generated Stockpile Transaction
					19	May 16, 2022	SYSTEM	\$1,290.79	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$4,900.79	
			Construction	n Stockpile Si	TMI - Total			\$4,900.79	
	2110 -							\$4,900.79	
	2210		Material		20	Jun 2, 2022	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$18,900.00)	
					21	Jun 16, 2022	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$37,940.00)	
					22	Jul 1, 2022	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user steppr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$37,940.00)	
					23	Jul 18, 2022	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0074) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$37,940.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2210 -	Total						\$0.00	
	2220	SIDEWALK (BRIDGES)	Material		19	May 16, 2022	SYSTEM	\$19,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user schirj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$19,125.00)	
					20	Jun 2, 2022	SYSTEM	\$19,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$19,125.00)	
					21	Jun 16, 2022	SYSTEM	\$38,403.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					21	Jun 16,	SYSTEM	(\$38,403.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J6S1718	2220	SIDEWALK	Material			2022						
		(BRIDGES)			22	Jul 1, 2022	SYSTEM	\$38,403.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user steppr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.			
					22	Jul 1, 2022	SYSTEM	(\$38,403.00)				
					23	Jul 18, 2022	SYSTEM	\$38,403.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0075) due to user schirj1 overridding Payment			
					23	Jul 18,	SYSTEM	(\$38,403.00)	Estimate Exception 20 on the current Payment Estimate.			
				- Total		2022		\$0.00				
			Material - Tot					\$0.00				
	2220 -	· Total	Material - 10	tai				\$0.00				
	2230	HALF-SOLE REPAIR	Material		19	May 16, 2022	SYSTEM	\$487.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user schirj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.			
					19	May 16, 2022	SYSTEM	(\$487.50)	Estimate Exception 51 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - Tot					\$0.00				
			Overrun	Overrun	21	Jun 16, 2022	SYSTEM	(\$7,150.00)				
		Total			Overrun - Total			(\$7,150.00)				
			Overrun - To	un - Total				(\$7,150.00)				
	2230 -	Total						(\$7,150.00)				
	2240	OPEN CELL FOAM JOINT SEAL	Material		20	Jun 2, 2022	SYSTEM	\$6,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.			
					20	Jun 2, 2022	SYSTEM	(\$6,930.00)				
								21	Jun 16, 2022	SYSTEM	\$10,318.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
							21	Jun 16, 2022	SYSTEM	(\$10,318.00)		
				- Total				\$0.00				
			Material - Tot	tal				\$0.00				
	2240 -	Total						\$0.00				
	2290	GALVANIZED STRUCTURAL STEEL PILES (12	Construction Stockpile		21	Jun 16, 2022	SYSTEM	(\$17,993.50)	Payment Estimate Item Adjustment generated Stockpile Transaction			
		IN		- Total				(\$17,993.50)				
				Stockpile - 1				(\$17,993.50)				
			Construction Stockpile STMI		12	Feb 1, 2022	SYSTEM	\$17,993.50	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				\$17,993.50				
			Construction	Stockpile S				\$17,993.50				
			Material		21	Jun 16, 2022	SYSTEM	\$52,026.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.			
					21	Jun 16, 2022	SYSTEM	(\$52,026.00)				
				22	Jul 1, 2022	SYSTEM	\$52,026.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user steppr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					22	Jul 1, 2022	SYSTEM	(\$52,026.00)				
					23	Jul 18, 2022	SYSTEM	\$52,026.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
				23	23	Jul 18, 2022	SYSTEM	(\$52,026.00)				
				- Total				\$0.00				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	2290	GALVANIZED STRUCTURAL STEEL PILES (12 IN	Material - Tot	al				\$0.00	
	2290 -	· Total						\$0.00	
	2310	PILE POINT REINFORCEMENT	Construction Stockpile		21	Jun 16, 2022	SYSTEM	(\$1,050.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,050.00)	
			Construction	Stockpile - T	otal			(\$1,050.00)	
			Construction Stockpile STMI		12	Feb 1, 2022	SYSTEM	\$1,050.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$1,050.00	
			Construction	Stockpile S1	ΓMI - Total			\$1,050.00	
			Material		21	Jun 16, 2022	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$4,200.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	2310 -	· Total						\$0.00	
	2320	CLASS B CONCRETE (SUBSTRUCTURE)	Material		22	Jul 1, 2022	SYSTEM	\$65,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user steppr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$65,884.00)	
					23	Jul 18, 2022	SYSTEM	\$65,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0077) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$65,884.00)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
	2320 -	Total						\$0.00	
	2410	LAMINATED NEOPRENE BEARING PAD	Construction Stockpile STMI		12	Feb 1, 2022	SYSTEM	\$6,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(TAPERED)	0 1 11	- Total				\$6,600.00	
			Construction	Stockpile S1	MI - Total			\$6,600.00	
1004740		Total						\$6,600.00	
J6S1718 - 3		REMOVAL OF MISCELLANEOUS	Overrun	Overrun	1	Aug 16, 2021	SYSTEM	\$254,614.48 (\$215.00)	
		ACM NON- FRIABLE			2	Sep 1, 2021	SYSTEM	(\$4,868.89)	
					4	Oct 1, 2021	SYSTEM	\$5,083.89	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4.30000 - 4.30000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - To					\$0.00	
	2450 -	· Total						\$0.00	
	2470	REMOVAL OF FLOOR SHEETING	Overrun	Overrun	1	Aug 16, 2021	SYSTEM	(\$780.00)	
		ACM ON WOOD			4	Oct 1, 2021	SYSTEM	\$780.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.50000 - 19.50000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	2470 -	· Total						\$0.00	
	2590	TYPE 5 AGGREGATE FOR BASE	Material		10	Jan 3, 2022	SYSTEM	\$1,328.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6S1718B	2590	TYPE 5 AGGREGATE FOR	Material		10	Jan 3, 2022	SYSTEM	(\$1,328.04)		
		BASE			11	Jan 18, 2022	SYSTEM	\$3,194.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					11	Jan 18, 2022	SYSTEM	(\$3,194.73)		
					12	Feb 1, 2022	SYSTEM	\$7,126.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					12	Feb 1, 2022	SYSTEM	(\$7,126.56)		
					13	Feb 16, 2022	SYSTEM	\$7,126.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					13	Feb 16, 2022	SYSTEM	(\$7,126.56)		
					14	Mar 1, 2022	SYSTEM	\$7,126.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					14	Mar 1, 2022	SYSTEM	(\$7,126.56)		
					15	Mar 16, 2022	SYSTEM	\$7,126.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					15	Mar 16, 2022	SYSTEM	(\$7,126.56)		
					16	Apr 4, 2022	SYSTEM	\$11,266.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					16	Apr 4, 2022	SYSTEM	(\$11,266.42)		
					17	Apr 18, 2022	SYSTEM	\$12,498.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					17	Apr 18, 2022	SYSTEM	(\$12,498.44)		
					18	May 2, 2022	SYSTEM	\$14,427.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					18	May 2, 2022	SYSTEM	(\$14,427.38)		
						19	May 16, 2022	SYSTEM	\$15,278.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
						19	May 16, 2022	SYSTEM	(\$15,278.51)	
					20	Jun 2, 2022	SYSTEM	\$18,088.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					20	Jun 2, 2022	SYSTEM	(\$18,088.75)		
					21	Jun 16, 2022	SYSTEM	\$21,935.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					21	Jun 16, 2022	SYSTEM	(\$21,935.91)		
			Material - To	- Total				\$0.00 \$0.00		
	2590 -	Total	material - 10					\$0.00		
	2680	CONCRETE PAVEMENT ( 7 IN. NON-REINF)	Material		17	Apr 18, 2022	SYSTEM	\$2,689.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					17	Apr 18, 2022	SYSTEM	(\$2,689.28)		
					18	May 2, 2022	SYSTEM	\$2,689.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718B	2680	CONCRETE PAVEMENT ( 7 IN.	Material		18	May 2, 2022	SYSTEM	(\$2,689.28)	
		NON-RÈINF)			19	May 16, 2022	SYSTEM	\$6,704.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$6,704.72)	
					20	Jun 2, 2022	SYSTEM	\$6,704.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$6,704.72)	
					21	Jun 16, 2022	SYSTEM	\$28,585.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$28,585.04)	
					22	Jul 1, 2022	SYSTEM	\$45,776.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$45,776.72)	
					23	Jul 18, 2022	SYSTEM	\$45,776.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$45,776.72)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2680 -	Total						\$0.00	
	2690	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material		16	Apr 4, 2022	SYSTEM	\$13,236.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$13,236.44)	
						17	Apr 18, 2022	SYSTEM	\$13,236.44
					17	Apr 18, 2022	SYSTEM	(\$13,236.44)	
					18	May 2, 2022	SYSTEM	\$13,236.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$13,236.44)	
					19	May 16, 2022	SYSTEM	\$13,236.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$13,236.44)	
						20	Jun 2, 2022	SYSTEM	\$38,815.52
					20	Jun 2, 2022	SYSTEM	(\$38,815.52)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2690 - Total							\$0.00	
	2770	2770 TRUNCATED DOMES	Overrun	Overrun		Apr 4, 2022	SYSTEM	(\$219.60)	
					18	May 2, 2022	SYSTEM	(\$540.00)	
					19	May 16, 2022	SYSTEM	(\$360.00)	
			Overrun - Total					(\$1,119.60)	
				tal				(\$1,119.60)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718B	2770 -	Total						(\$1,119.60)	
	2820	MISC. CONCRETE	Material		10	Jan 3, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					10	Jan 3, 2022	SYSTEM	(\$5,000.00)	
					11	Jan 18, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					11	Jan 18, 2022	SYSTEM	(\$5,000.00)	
					12	Feb 1, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					12	Feb 1, 2022	SYSTEM	(\$5,000.00)	
					13	Feb 16, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					13	Feb 16, 2022	SYSTEM	(\$5,000.00)	
					14	Mar 1, 2022	SYSTEM	\$7,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					14	Mar 1, 2022	SYSTEM	(\$7,500.00)	
					15	Mar 16, 2022	SYSTEM	\$7,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$7,500.00)	
					16	Apr 4, 2022	SYSTEM	\$17,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$17,500.00)	
					17	Apr 18, 2022	SYSTEM	\$17,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$17,500.00)	
					18	May 2, 2022	SYSTEM	\$20,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$20,000.00)	
					19	May 16, 2022	SYSTEM	\$22,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$22,500.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	2820 -	Total						\$0.00	
	2880	MISC. CONCRETE	Material		16	Apr 4, 2022	SYSTEM	\$57,453.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$57,453.54)	
					17	Apr 18, 2022	SYSTEM	\$63,063.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$63,063.54)	
					18	May 2, 2022	SYSTEM	\$73,473.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6S1718B	2880	MISC. CONCRETE	Material		18	May 2, 2022	SYSTEM	(\$73,473.66)													
					19	May 16, 2022	SYSTEM	\$76,515.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.												
					19	May 16, 2022	SYSTEM	(\$76,515.64)													
					20	Jun 2, 2022	SYSTEM	\$24,211.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.												
					20	Jun 2, 2022	SYSTEM	(\$24,211.50)													
					21	Jun 16, 2022	SYSTEM	\$24,211.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.												
					21	Jun 16, 2022	SYSTEM	(\$24,211.50)													
					22	Jul 1, 2022	SYSTEM	\$25,250.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.												
					22	Jul 1, 2022	SYSTEM	(\$25,250.20)													
					23	Jul 18, 2022	SYSTEM	\$25,250.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.												
					23	Jul 18, 2022	SYSTEM	(\$25,250.20)													
				- Total				\$0.00													
			Material - Tot	tal				\$0.00													
	2880 -	- Total						\$0.00													
	2910			Material	17	Apr 18, 2022	SYSTEM	\$1,134.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.												
					17	Apr 18, 2022	SYSTEM	(\$1,134.00)													
						18	May 2, 2022	SYSTEM	\$1,134.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.											
					18	May 2, 2022	SYSTEM	(\$1,134.00)													
						1								19	May 16, 2022	SYSTEM	\$1,134.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.			
					19	May 16, 2022	SYSTEM	(\$1,134.00)													
				- Total				\$0.00													
			Material - Tot	tal				\$0.00													
	2910 -	- Total						\$0.00													
	2930	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		16	Apr 4, 2022	SYSTEM	\$1,165.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.												
					16	Apr 4, 2022	SYSTEM	(\$1,165.50)													
																	17	Apr 18, 2022	SYSTEM	\$1,165.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$1,165.50)													
					18	May 2, 2022	SYSTEM	\$1,165.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.												
					18	May 2, 2022	SYSTEM	(\$1,165.50)													
				2	20	20	20	20	20	Jun 2, 2022	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.								
				20	Jun 2,	SYSTEM	(\$3,108.00)														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J6S1718B	2930	INTEGRAL CURB (6 IN. HEIGHT AND	Material			2022						
		UNDER)		- Total				\$0.00				
			Material - To	tal				\$0.00				
	2930 -	Total						\$0.00				
	2940	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		21	Jun 16, 2022	SYSTEM	\$3,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
					21	Jun 16, 2022	SYSTEM	(\$3,895.00)				
					22	Jul 1, 2022	SYSTEM	\$4,968.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
					22	Jul 1, 2022	SYSTEM	(\$4,968.50)				
					23	Jul 18, 2022	SYSTEM	\$4,968.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.			
					23	Jul 18,	SYSTEM	(\$4,968.50)	Example Exception to on the salient Expired Example.			
				- Total		2022		\$0.00				
			Material - To					\$0.00				
	2940 -	Total	material - 10					\$0.00				
	3060	CLASS B CONCRETE (SUBSTRUCTURE)	Material		22	Jul 1, 2022	SYSTEM	\$14,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.			
					22	Jul 1, 2022	SYSTEM	(\$14,300.00)				
					23	Jul 18, 2022	SYSTEM	\$14,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
					23	Jul 18, 2022	SYSTEM	(\$14,300.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	3060 -	Total						\$0.00				
	3130	REINFORCING STEEL (EPOXY COATED)	Material		22	Jul 1, 2022	SYSTEM	\$2,835.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.			
					22	Jul 1, 2022	SYSTEM	(\$2,835.00)				
					23	Jul 18, 2022	SYSTEM	\$2,835.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.			
					23	Jul 18, 2022	SYSTEM	(\$2,835.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	3130 -	Total						\$0.00				
	3160	MECHANICALLY STABILIZED EARTH WALL SYS	Material		14	Mar 1, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.			
					14	Mar 1, 2022	SYSTEM	(\$20,695.50)				
					15	Mar 16, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.			
					15	Mar 16, 2022	SYSTEM	(\$20,695.50)				
					16	Apr 4, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.			
							16	Apr 4, 2022	SYSTEM	(\$20,695.50)		
								17	Apr 18,	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6S1718B	3160	MECHANICALLY STABILIZED	Material			2022			Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.											
		EARTH WALL SYS			17	Apr 18, 2022	SYSTEM	(\$20,695.50)												
					18	May 2, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.											
					18	May 2, 2022	SYSTEM	(\$20,695.50)												
					19	May 16, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.											
					19	May 16, 2022	SYSTEM	(\$20,695.50)												
					20	Jun 2, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.											
					20	Jun 2, 2022	SYSTEM	(\$20,695.50)												
					21	Jun 16, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
				21	Jun 16, 2022	SYSTEM	(\$20,695.50)													
				22	Jul 1, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment Estimate Exception 25 on the current Payment Estimate.												
				22	Jul 1, 2022	SYSTEM	(\$20,695.50)													
				T	23	Jul 18, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.											
					23	Jul 18, 2022	SYSTEM	(\$20,695.50)												
				- Total				\$0.00												
	3160 -	Total	Material - To	tal				\$0.00 \$0.00												
	3610	CABLE-CONDUIT,	Construction	Construction		Jul 18,	SYSTEM	\$18,692.09	Payment Estimate Item Adjustment generated Stockpile Transaction											
	00.0	1 IN., 2 CONDUCTORS	Stockpile STMI	- Total	23	2022	0.0.2	\$18,692.09	y syman zamiec nom rejection gonizació costipilo manadation											
			Construction		TMI - Total			\$18,692.09												
			Material	- Сестрис-О	15	Mar 16, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.											
					15	Mar 16, 2022	SYSTEM	(\$1,782.90)												
					16	Apr 4, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.											
			1	1											16	Apr 4, 2022	SYSTEM	(\$1,782.90)		
																				17
													18	May 2, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.			
						18	May 2, 2022	SYSTEM	(\$1,782.90)											
					19	May 16, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.											
					19	May 16,	SYSTEM	\$1,782.90 (\$1,782.90)	Estimate Item Adjustment (0011) due to user schirj1 overridding Payment											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6S1718B	3610	CABLE-CONDUIT, 1 IN., 2	Material			2022			Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.													
		CONDUCTORS			20	Jun 2, 2022	SYSTEM	(\$1,782.90)														
					21	Jun 16, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user schirj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.													
					21	Jun 16, 2022	SYSTEM	(\$1,782.90)														
					22	Jul 1, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user steppr1 overridding Payment Estimate Exception 37 on the current Payment Estimate.													
					22	Jul 1, 2022	SYSTEM	(\$1,782.90)														
					23	Jul 18, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.													
					23	Jul 18, 2022	SYSTEM	(\$1,782.90)														
				- Total				\$0.00														
			Material - Tot	al				\$0.00														
	3610 -	- Total						\$18,692.09														
	3680	MISC.	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$512.00	Payment Estimate Item Adjustment generated Stockpile Transaction													
				- Total				\$512.00														
			Construction	Stockpile S1	MI - Total			\$512.00														
		- Total					0) (0 === 1.4	\$512.00														
	3700	MISC.	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$5,417.80	Payment Estimate Item Adjustment generated Stockpile Transaction													
			Construction	- Total	IMI Total			\$5,417.80 \$5,417.80														
	3700 -	Total	Construction	зтоскрие 5 і	IVII - TOtal			\$5,417.80 \$5,417.80														
	3710	MISC.	Construction Stockpile		23	Jul 18, 2022	SYSTEM	\$1,941.55	Payment Estimate Item Adjustment generated Stockpile Transaction													
			STMI	- Total																		
			Construction	Stockpile S1	MI - Total			\$1,941.55														
	3710 -	- Total						\$1,941.55														
	3840	340 SEWER - UTILITY	- UTILITY Construction ITEM Stockpile	Construction Stockpile																	100	
		IIEM			15	Mar 16, 2022	SYSTEM	(\$49,088.16)	Payment Estimate Item Adjustment generated Stockpile Transaction													
		ITEM			15		SYSTEM SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction													
		HEM	Stockpile	- Total	16	2022 Apr 4,		(\$49,088.16) (\$10,419.66) (\$59,507.82)														
		ПЕМ	Stockpile		16 otal	2022 Apr 4, 2022	SYSTEM	(\$49,088.16) (\$10,419.66) (\$59,507.82)	Payment Estimate Item Adjustment generated Stockpile Transaction													
		HEM	Stockpile	Stockpile - T	16	2022 Apr 4,		(\$49,088.16) (\$10,419.66) (\$59,507.82) (\$59,507.82) \$59,507.82														
		ΠEM	Construction Construction Stockpile STMI	Stockpile - T	16 Total	2022 Apr 4, 2022 Nov 15, 2021	SYSTEM	(\$49,088.16) (\$10,419.66) (\$59,507.82) (\$59,507.82) \$59,507.82	Payment Estimate Item Adjustment generated Stockpile Transaction													
		HEM	Construction Construction Stockpile STMI	Stockpile - T	16  otal  7  otal  TMI - Total	2022 Apr 4, 2022 Nov 15, 2021	SYSTEM	(\$49,088.16) (\$10,419.66) (\$59,507.82) (\$59,507.82) \$59,507.82 \$59,507.82	Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction													
		HEM	Construction Construction Stockpile STMI	Stockpile - T	16 Total	2022 Apr 4, 2022 Nov 15, 2021	SYSTEM	(\$49,088.16) (\$10,419.66) (\$59,507.82) (\$59,507.82) \$59,507.82	Payment Estimate Item Adjustment generated Stockpile Transaction													
		HEM	Construction Construction Stockpile STMI	Stockpile - T	16  otal  7  otal  TMI - Total	2022 Apr 4, 2022 Nov 15, 2021	SYSTEM	(\$49,088.16) (\$10,419.66) (\$59,507.82) (\$59,507.82) \$59,507.82 \$59,507.82	Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment													
		HEM	Construction Construction Stockpile STMI	Stockpile - T	16  Total 7  TMI - Total 15	2022 Apr 4, 2022 Nov 15, 2021 Mar 16, 2022	SYSTEM	(\$49,088.16) (\$10,419.66) (\$59,507.82) (\$59,507.82) \$59,507.82 \$59,507.82 \$59,507.82 \$175,324.00	Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment													
		HEM	Construction Construction Stockpile STMI	Stockpile - T	16  Total 7  TMI - Total 15	2022 Apr 4, 2022 Nov 15, 2021 Mar 16, 2022 Apr 4,	SYSTEM  SYSTEM  SYSTEM	(\$49,088.16) (\$10,419.66) (\$59,507.82) (\$59,507.82) \$59,507.82 \$59,507.82 \$175,324.00	Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment													
		HEM	Construction Construction Stockpile STMI	Stockpile - T	16 7 TMI - Total 15 15	2022 Apr 4, 2022  Nov 15, 2021  Mar 16, 2022  Apr 4, 2022  Apr 4, 2022	SYSTEM  SYSTEM  SYSTEM  SYSTEM	(\$49,088.16) (\$10,419.66) (\$59,507.82) (\$59,507.82) \$59,507.82 \$59,507.82 \$175,324.00 (\$175,324.00)	Payment Estimate Item Adjustment generated Stockpile Transaction  Payment Estimate Item Adjustment generated Stockpile Transaction  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment													



	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
1	J6S1718B	3840		Material	.,,,,,	18		SYSTEM	\$212,539.00	Estimate Item Adjustment (0012) due to user schirj1 overridding Payment			
2022   Section   Beautiful   Provided   Pr						18		SYSTEM	(\$212,539.00)				
20						19		SYSTEM	\$212,539.00	Estimate Item Adjustment (0012) due to user schirj1 overridding Payment			
2022   SYSTEM   (\$212,539.00)   So the current Payment Elemants   System						19		SYSTEM	(\$212,539.00)				
20						20		SYSTEM	\$212,539.00	Estimate Item Adjustment (0008) due to user schirj1 overridding Payment			
21						20		SYSTEM	(\$212,539.00)				
21						21	Jun 16,	SYSTEM	\$212,539.00	Estimate Item Adjustment (0045) due to user schirj1 overridding Payment			
2						21		SYSTEM	(\$212,539.00)	Estimate Exception to on the edition of all the edition of the edi			
23						22	Jul 1,	SYSTEM	\$212,539.00	Estimate Item Adjustment (0009) due to user steppr1 overridding Payment			
2022   Editimate Hem Adjustment (0059) due to user schirly overridding Payment Editimate Exception 8 on the current Payment Editimate Exception 9 on the current Payment Editimate Exception 10 on the current Payme						22		SYSTEM	(\$212,539.00)				
10   10   10   10   10   10   10   10						23		SYSTEM	\$212,539.00	Estimate Item Adjustment (0059) due to user schirj1 overridding Payment			
Sava - Total   Sewer - UTILITY   Sewer - UTILI						23		SYSTEM	(\$212,539.00)				
Sewer - Utility   Material   15					- Total				\$0.00				
SEWER - UTILITY   Material   15				Material - To	tal				\$0.00				
Estimate Item Adjustment (0007) due to user schipt overridding Payment Estimate Exception 17 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Payment Estimate Exception 17 on the current Payment Estimate Payment Estimate Estimate Item Adjustment (0011) due to user schipt overridding Payment Estimate Item Adjustment (0011) due to user schipt overridding Payment Estimate Exception 23 on the current Payment Estimate.    Apr 18,		3840 -	- Total						\$0.00				
16 Apr 4, 2022 SYSTEM \$52,850.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  17 Apr 18, SYSTEM \$79,275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate Exception 16 on the current Payment Estimate Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Item Adjustment (0046) due to user schirj1 overri		3850		Material		15		SYSTEM	\$52,850.00	Estimate Item Adjustment (0007) due to user schirj1 overridding Payment			
Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  Apr 18, SYSTEM 2022  17 Apr 18, SYSTEM \$52,850.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 29 on the current Payment Estimate.  17 Apr 18, SYSTEM (\$52,850.00)  18 May 2, 2022 SYSTEM \$79,275.00 This adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  18 May 2, SYSTEM (\$79,275.00)  19 May 16, 2022 SYSTEM \$79,275.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 29 on the current Payment Estimate.  19 May 16, SYSTEM \$79,275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  20 Jun 2, SYSTEM \$79,275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  20 Jun 2, SYSTEM \$79,275.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment (0006) due to user schirj1 overridding Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate						15		SYSTEM	(\$52,850.00)				
2022   Apr 18,   SYSTEM   \$52,850.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 29 on the current Payment Estimate.						16		SYSTEM	\$52,850.00	Estimate Item Adjustment (0011) due to user schirj1 overridding Payment			
Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  17						16		SYSTEM	(\$52,850.00)				
18 May 2, 2022 SYSTEM \$79,275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  18 May 2, 2022 SYSTEM (\$79,275.00)  19 May 16, 2022 SYSTEM \$79,275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  19 May 16, 2022 SYSTEM (\$79,275.00)  20 Jun 2, 2022 SYSTEM \$79,275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  20 Jun 2, 2022 SYSTEM (\$79,275.00)  21 Jun 16, 2022 SYSTEM \$115,213.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						17		SYSTEM	\$52,850.00	Estimate Item Adjustment (0011) due to user schirj1 overridding Payment			
Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  18 May 2, 2022  19 May 16, 2022  20 Jun 2, 2022  20 Jun 2, 2022  20 Jun 2, 2022  20 Jun 2, 2022  21 Jun 16, 2022  21 Jun 16, 2022  22 SYSTEM \$115,213.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  20 Jun 2, 2022  21 Jun 16, 2022  315,213.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate.  20 Jun 2, 2022  315,213.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						17		SYSTEM	(\$52,850.00)				
19 May 16, 2022 SYSTEM \$79,275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  19 May 16, 2022 SYSTEM (\$79,275.00)  20 Jun 2, 2022 SYSTEM \$79,275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  20 Jun 2, 2022 SYSTEM (\$79,275.00)  21 Jun 16, SYSTEM \$115,213.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						18		SYSTEM	\$79,275.00	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment			
Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  19 May 16, 2022  20 Jun 2, 2022  SYSTEM \$79,275.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate.  20 Jun 2, 2022  SYSTEM (\$79,275.00)  21 Jun 16, 2022  SYSTEM \$115,213.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						18	May 2, 2022	SYSTEM	(\$79,275.00)				
2022 SYSTEM \$79,275.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  20 Jun 2, 2022 SYSTEM (\$79,275.00)  21 Jun 16, 2022 SYSTEM \$115,213.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						19		SYSTEM	\$79,275.00	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment			
2022 Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  20 Jun 2, 2022  21 Jun 16, 2022 \$YSTEM (\$79,275.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						19		SYSTEM	(\$79,275.00)				
2022  21 Jun 16, 2022  SYSTEM \$115,213.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						20		SYSTEM	\$79,275.00	Estimate Item Adjustment (0009) due to user schirj1 overridding Payment			
2022 Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						2	20						
						20		SYSTEM	(\$79,275.00)				
2022							2022 Jun 16,			Estimate Item Adjustment (0046) due to user schirj1 overridding Payment			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J6S1718B	3850	SEWER - UTILITY ITEM	Material		22	Jul 1, 2022	SYSTEM	\$115,213.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user steppr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.										
					22	Jul 1, 2022	SYSTEM	(\$115,213.00)											
					23	Jul 18, 2022	SYSTEM	\$115,213.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
					23	Jul 18, 2022	SYSTEM	(\$115,213.00)											
				- Total				\$0.00											
			Material - Tot	tal				\$0.00											
	3850 -	Total						\$0.00											
	3870	SEWER - UTILITY ITEM	Construction Stockpile		16	Apr 4, 2022	SYSTEM	(\$28,971.11)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					18	May 2, 2022	SYSTEM	(\$20,933.96)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					21	Jun 16, 2022	SYSTEM	(\$12,523.00)	Payment Estimate Item Adjustment generated Stockpile Transaction										
				- Total				(\$62,428.07)											
			Construction	Stockpile - 1	Total			(\$62,428.07)											
			Construction Stockpile		10	Jan 3, 2022	SYSTEM	\$79,250.00	Payment Estimate Item Adjustment generated Stockpile Transaction										
			STMI	- Total				\$79,250.00											
			Construction Material	Stockpile S	TMI - Tota			\$79,250.00											
				Material		16	Apr 4, 2022	SYSTEM	\$66,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.									
								16	Apr 4, 2022	SYSTEM	(\$66,960.00)								
					17	Apr 18, 2022	SYSTEM	\$66,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.										
												17	Apr 18, 2022	SYSTEM	(\$66,960.00)				
								18	May 2, 2022	SYSTEM	\$115,344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.							
					18	May 2, 2022	SYSTEM	(\$115,344.00)											
					19	May 16, 2022	SYSTEM	\$115,344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.										
					19		SYSTEM	(\$115,344.00)	Estimate exception 27 on the current rayment estimate.										
												20	Jun 2, 2022	SYSTEM	\$115,344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.			
					20	Jun 2, 2022	SYSTEM	(\$115,344.00)	Zamace Zacopies II of the carrotter synthetic Zamace.										
					21	Jun 16, 2022	SYSTEM	\$144,288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.										
									21	Jun 16, 2022	SYSTEM	(\$144,288.00)							
					22	Jul 1, 2022	SYSTEM	\$144,288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user steppr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.										
					22	Jul 1, 2022	SYSTEM	(\$144,288.00)											
														2	23	Jul 18, 2022	SYSTEM	\$144,288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
																	23	Jul 18, 2022	SYSTEM
				- Total		2022		\$0.00											
				- Total															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6S1718B	3870	SEWER - UTILITY ITEM	Material - To	tal				\$0.00		
	3870 -	- Total						\$16,821.93		
	4110	SEWER - RIGID PIPE	Material		21	Jun 16, 2022	SYSTEM	\$3,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	
					21	Jun 16, 2022	SYSTEM	(\$3,380.00)		
					22	Jul 1, 2022	SYSTEM	\$3,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
					22	Jul 1, 2022	SYSTEM	(\$3,380.00)		
					23	Jul 18, 2022	SYSTEM	\$3,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
					23	Jul 18, 2022	SYSTEM	(\$3,380.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	4110 -	Total						\$0.00		
	4130	SEWER - RIGID PIPE	Material		21	Jun 16, 2022	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
					21	Jun 16, 2022	SYSTEM	(\$4,189.50)		
					22	Jul 1, 2022	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user steppr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	
						22	Jul 1, 2022	SYSTEM	(\$4,189.50)	
					23	Jul 18, 2022	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
					23	Jul 18, 2022	SYSTEM	(\$4,189.50)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	4130 -	Total						\$0.00		
	4140	SEWER - RIGID PIPE	Material		21	Jun 16, 2022	SYSTEM	\$29,866.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	
					21	Jun 16, 2022	SYSTEM	(\$29,866.00)		
					22	Jul 1, 2022	SYSTEM	\$29,866.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user steppr1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	
					22	Jul 1, 2022	SYSTEM	(\$29,866.00)		
					23	Jul 18, 2022	SYSTEM	\$29,866.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	
					23	Jul 18, 2022	SYSTEM	(\$29,866.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	4140 -	Total						\$0.00		
	4150	SEWER - RIGID PIPE	Material		18	May 2, 2022	SYSTEM	\$7,750.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 70 on the current Payment Estimate.	
					18	May 2, 2022	SYSTEM	(\$7,750.60)		
					19	May 16, 2022	SYSTEM	\$7,750.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6S1718B	4150	SEWER - RIGID PIPE	Material		19	May 16, 2022	SYSTEM	(\$7,750.60)												
					20	Jun 2, 2022	SYSTEM	\$7,750.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.											
					20	Jun 2, 2022	SYSTEM	(\$7,750.60)												
					21	Jun 16, 2022	SYSTEM	\$32,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.											
					21	Jun 16, 2022	SYSTEM	(\$32,890.00)												
					22	Jul 1, 2022	SYSTEM	\$32,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user steppr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.											
					22	Jul 1, 2022	SYSTEM	(\$32,890.00)	Estimate Exception 32 on the current rayment Estimate.											
					23	Jul 18, 2022	SYSTEM	\$32,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.											
					23	Jul 18, 2022	SYSTEM	(\$32,890.00)												
				- Total				\$0.00												
			Material - Tot	tal				\$0.00												
	4150 -	Total						\$0.00												
	4180	MISC. MANHOLES AND DROP	Construction Stockpile		21	Jun 16, 2022	SYSTEM	\$4,188.79	Payment Estimate Item Adjustment generated Stockpile Transaction											
		INLETS	STMI	- Total				\$4,188.79												
			Construction	Stockpile S	MI - Tota			\$4,188.79												
	4180 -	Total						\$4,188.79												
	4220	MISC. MANHOLES AND DROP INLETS	Construction Stockpile STMI		21	Jun 16, 2022	SYSTEM	\$13,675.84	Payment Estimate Item Adjustment generated Stockpile Transaction											
		INLETS	STIVII	- Total				\$13,675.84												
			Construction	Stockpile S	MI - Tota			\$13,675.84												
		Total						\$13,675.84												
J6S1718B								\$60,130.40												
J6S1718C	4810	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	Material		15	Mar 16, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.											
					15	Mar 16, 2022	SYSTEM	(\$3,159.45)												
					16	Apr 4, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schirj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.											
					16	Apr 4, 2022	SYSTEM	(\$3,159.45)												
					17	Apr 18, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schirj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.											
					17	Apr 18, 2022	SYSTEM	(\$3,159.45)												
					18	May 2, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schirj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.											
					18	May 2, 2022	SYSTEM	(\$3,159.45)												
					19	May 16, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schirj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.											
					1!	19	May 16, 2022	SYSTEM	(\$3,159.45)											
													2'		2	20	Jun 2, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schirj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
							20	Jun 2,	SYSTEM	(\$3,159.45)										



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J6S1718C	4810	CABLE-CONDUIT,	Material			2022			
		1 IN., 2 CONDUCTORS			21	Jun 16, 2022	SYSTEM	\$11,793.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$11,793.60)	
					22	Jul 1, 2022	SYSTEM	\$11,793.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user steppr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$11,793.60)	
					23	Jul 18, 2022	SYSTEM	\$11,793.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0078) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$11,793.60)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
	4810 -	· Total						\$0.00	
	4830	MISC. HIGHWAY LIGHTING	Construction Stockpile		19	May 16, 2022	SYSTEM	(\$52.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					21	Jun 16, 2022	SYSTEM	(\$4,522.88)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$4,574.88)	
			Construction	Stockpile - 1	otal			(\$4,574.88)	
			Construction Stockpile		23	Jul 18, 2022	SYSTEM	\$63,321.30	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMA	- Total				\$63,321.30	
			Construction	Stockpile S	ΓMA - Tota	ıl		\$63,321.30	
			Construction Stockpile		18	May 2, 2022	SYSTEM	\$52.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI		19	May 16, 2022	SYSTEM	\$78,397.80	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$78,449.80	
			Construction	Stockpile S	ΓMI - Total			\$78,449.80	
			Material		21	Jun 16, 2022	SYSTEM	\$11,589.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$11,589.00)	
					22	Jul 1, 2022	SYSTEM	\$11,589.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user steppr1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$11,589.00)	
					23	Jul 18, 2022	SYSTEM	\$11,589.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0079) due to user schirj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$11,589.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	4830 -	· Total						\$137,196.22	
J6S1718C	- Total							\$137,196.22	
Overall - To	otal						\$451,941.10		