

Pay Estimate Created Date: June 16, 2022

Progress Estim 14	ate Number	Contract ID Prime Contractor	210521-F02 KCI Construction C		Pay Period Star Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$3,899,000.00 (\$58,814.80) \$3,840,185.20
Approval Date								By User
June 16, 2022		Generated and Approved (and should be considered Draft) at the Project Office Level by						dukesm1
June 16, 2022		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by						lewisj1
June 17, 2022		Reviewed and Approved at the Central Office Controllers Office Level by						
Original Comp	letion Date	Current Con	pletion Date	Actual	Completion Da	te	6 of Current Contract Amoun	t Complete

Jun	e 30, 2022		June 30, 2022			8	3.94%					
Contr	act Information	al Dates		Milestones								
Date Description	Original Completion Date	Current Completio Date		e Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days				
Acceptance Date			Milestone - Calendar T open to traffic JSP-13-	ime Bridge A5093 and A5097 01B section 4.2.1	May 12, 2022	May 12, 2022	-36					
Awarded Date	June 2, 2021	June 2, 202	Milestone - Calendar T open to traffic JSP-13-	ime Bridges A5091 and A5092 01B section 4.1.1	November 21, 2021	November 21, 2021	Milestone Complete					
Letting Date	May 21, 2021	May 21, 202	1									
Notice to Proceed Date	July 6, 2021	July 6, 2021										
Open to Traffic Date												
Work Began Date	September 23, 2021	September 23, 2021										

Contract Total Pay For Estimate No. 14			
	This Estimate	Previous	To Date
210521-F02			
Total Posted Items Pay	\$466,324.92	\$2,756,977.37	\$3,223,302.29
Gross Item Adjustments	(\$33.50)	(\$33,677.17)	(\$33,710.67)
Incentive	\$0.00	\$2,906.30	\$2,906.30
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	(\$10,000.00)	(\$10,000.00)
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		<mark>\$2,716,206.50</mark>	\$3,182,497.92
Contract Total Payable This Estimate:	\$466,291.42		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3494	0250	6161005	CONSTRUCTION SIGNS	SQFT	\$7.000	340.5	\$2,383.50
	0300	6161040	FLASHING ARROW PANEL	EA	\$850.000	4	\$3,400.00
	0390	6178001	TRAFFIC BARRIER DELINEATOR, WHITE	EA	\$20.000	90	\$1,800.00
	0400	6178002A	TRAFFIC BARRIER DELINEATOR, YELLOW	EA	\$25.000	36	\$900.00
	0430	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.300	5,715	\$1,714.50
	0440	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.300	4,185	\$1,255.50
	0450	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$1.000	39,759	\$39,759.00
	0460	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.500	3,330	\$1,665.00
	0470	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.700	674	\$471.80
	0570	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	LF	\$25.000	50	\$1,250.00
	0590	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$3,100.000	1	\$3,100.00
	0600	6061074	MGS HEIGHT AND BLOCK TRANSITION	EA	\$700.000	1	\$700.00



Pay Estimate Created Date: June 16, 2022

Progress I	Estimate N 14	lumber	Contract ID Prime Contractor	210521-F02 KCI Construction Company	Pay Period Start Jun Pay Period End Jun		2 Net Chang		t (\$58,814.80)
Project Number	Line Number	Item Code		Item Description		Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3494	5003	6233000	EPOXY POLYME	R WEARING SURFACE		SQYD	\$35.000	3,520	\$123,200.00
	5004	6233000	EPOXY POLYME	R WEARING SURFACE		SQYD	\$34.520	4,756	\$164,177.12
	5005	6233000	EPOXY POLYME	R WEARING SURFACE		SQYD	\$36.000	2,182	\$78,552.00
	5007	6233000	EPOXY POLYME	R WEARING SURFACE		SQYD	\$35.500	1,183	\$41,996.50
Project J6I3	494 - Tota	l i i							\$466,324.92
Overall - Tot	tal								\$466,324.92

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3494	0390	TRAFFIC BARRIER DELINEATOR, WHITE	Material			-90	\$20.00	(\$1,800.00)
	0400	TRAFFIC BARRIER DELINEATOR, YELLOW	Material			-36	\$25.00	(\$900.00)
	0490	FLOWABLE BACKFILL	MaterialCredit			72	\$170.00	\$12,240.00
	0490	FLOWABLE BACKFILL	Material			-72	\$170.00	(\$12,240.00)
	0570	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,015.50)
	0590	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,978.00)
	0600	MGS HEIGHT AND BLOCK TRANSITION	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$440.00)
	1160	HALF-SOLE REPAIR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 167.000; Overrun Quantity Balance 17.00.	17	\$165.00	\$2,805.00
	1160	HALF-SOLE REPAIR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-17	\$165.00	(\$2,805.00)
	1160	HALF-SOLE REPAIR	MaterialCredit			167	\$165.00	\$27,555.00
	1160	HALF-SOLE REPAIR	Material			-167	\$165.00	(\$27,555.00)
	1350	MISC.	MaterialCredit			4	\$1,100.00	\$4,400.00
	1360	REINFORCING STEEL (EPOXY COATED)	MaterialCredit			640	\$4.25	\$2,720.00
	1360	REINFORCING STEEL (EPOXY COATED)	Material			-640	\$4.25	(\$2,720.00)
	1430	PREFORMED COMPRESSION SEAL	Material			-43	\$120.00	(\$5,160.00)
	1430	PREFORMED COMPRESSION SEAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	43	\$120.00	\$5,160.00
	1480	HALF-SOLE REPAIR	MaterialCredit			14	\$350.00	\$4,900.00
	1480	HALF-SOLE REPAIR	Material			-14	\$350.00	(\$4,900.00)
	1500	MISC.	MaterialCredit			2	\$850.00	\$1,700.00
	1530	PREFORMED	Material			-101	\$85.00	(\$8,585.00)

Pay Estimate Created Date: June 16, 2022

Progr		imate Number 4	Contract ID Prime Cont		210521-F02 Pay Period Start June 2, 2022 Original Contract Amount \$3,6 ctor KCI Construction Company Pay Period End June 15, 2022 Net Change Order Amount Current Contract Amount \$3,6						
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount		
J6I3494	COMPRESSION SEA										
	1530 PREFORMED COMPRESSION SEAL		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user dukesm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	101	\$85.00	\$8,585.00			
	1560		MISC.	MaterialCredit			10	\$1,500.00	\$15,000.00		
	1560		MISC.	Material			-10	\$1,500.00	(\$15,000.00)		
Total									(\$33.50)		



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J6I3494	l 70-5(348)	Bridge rehabilitation and guardrail improvements	70/370	ST CHARLES	at the I-70 and Rte. 370 Interchange

Totals by Job Numbers

94		This Estimate	Previous	To Date
Posted Item Pay		\$466,324.92	\$2,756,977.37	\$3,223,302.29
Gross Item Adjustments		(\$33.50)	(\$33,677.17)	(\$33,710.67)
Gro	ss Item Pay	\$466,291.42	\$2,723,300.20	\$3,189,591.62
Incentive		\$0.00	\$2.906.30	\$2.906.30
Disincentive		\$0.00	\$0.00	\$0.00
Liquidated Damages		\$0.00	(\$10,000.00)	(\$10,000.00)
Other Contract Adjustmer	nts	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

DetectByEstimate Exception Type: Insufficient Materials: Project J6i3494, Item 2169903, Project Item Line Number 1560, Material 255 CMMLDST2 is insufficient.Waiting on PAL approval from Jeff City. White Pavement- Bridge Dissipating Curedukesm1AcknowleLestimate Exception Type: Insufficient Materials: Project J6i3494, Item 6178001, Project Item Line Number 103500, Material 256 17800196, Material 1056DE - Delineators, Acceptance Action Generic 1065DE is insufficient.Waiting on PAL approval from Jeff City. Delineatorsdukesm1AcknowleIssufficient.Set 617800196, Material Project J6i3494, Item 61780012A, Project Item Line Number 0400, Material 266 178001296, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.Waiting on PAL approval from Jeff City. Delineatorsdukesm1AcknowleIssufficient.Set 617800196, Material Project J6i3494, Item 6178002A, Project Item Line Number 0400, Material 266 178001296, Material 0621FB - Delineators, Acceptance Action Generic 1065DE is insufficient.Waiting on 3 strength QC CRE20 reports to resolve the exception.dukesm1AcknowleIssufficient.Set 6178002496, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient.Waiting on the QC CRE20 reports to resolve the exception.dukesm1AcknowleIssufficient.Set 6178001496, Material 052FCCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception.dukesm1Acknowle Material 205 10.0000000000000000000000000000000000				
Number 1560, Material Set 216990396, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Bridge Dissipating Bridge Dissipating Bridge Dissipating Cure Q. Acceptance Action Generic 1055CMMLDST2 is insufficient. Estimate Exception Type: Insufficient Materials: Project J813494, Item 6178001, Project Item Line Number 0390, Material Set 6178002A96, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient. Waiting on PAL approval from Jeff City. Delineators dukesm1 Acknowle Setimate Exception Type: Insufficient Materials: Project J813494, Item 6178002A, Project Item Line Number 0400, Material Set 6178002A96, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient. Waiting on PAL approval from Jeff City. Delineators dukesm1 Acknowle Estimate Exception Type: Insufficient Materials: Project J813494, Item 6178002A, Project Item Line Number 0490, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient. Waiting on 3 strength QC CRE20 reports to resolve the exception. dukesm1 Acknowle Setimate Exception Type: Insufficient Materials: Project J813494, Item 7040104, Project Item Line Number 1160, Material Set 704010496, Material 10057ACCNS. CA - Natural Sand for Conc Class A, Acceptance Action Generic 10057ACCNS. CA is insufficient. Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. dukesm1 Acknowle Number 1400, Material Set 704010496, Material 106510. CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic	Exceptions / Discrepencies	Explanation	Entered By	Status
Number 0390, Material Set 617800196, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient. Waiting on PAL approval from Jeff City. Delineators dukesm1 Acknowle Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 6178002A, Project Item Line Number 0400, Material Set 6178002A96, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient. Waiting on PAL approval from Jeff City. Delineators dukesm1 Acknowle Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 6214600A, Project Item Line Number 0490, Material Set 62146000A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient. Waiting on 3 strength QC CRE20 reports to resolve the exception. dukesm1 Acknowle Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7040104, Project Item Line Number 1160, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 10005FACCNSCA is insufficient. Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. dukesm1 Acknowle Number 1480, Material Set 704010496, Material 100510. CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510. CPCMLD is insufficient. Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. dukesm1 Acknowle Number 1480, Material Set 704010496, Material 100510. CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510. CPCMLD is insufficient. Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve	Number 1560, Material Set 216990396, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating		dukesm1	Acknowledged
Number 0400, Material Set 6178002A96, Material 1065DE - Delineators, Acceptance Action Generic Waiting on 3 strength QC CRE20 reports to resolve the exception. dukesm1 Estimate Exception Type: Insufficient Materials: Project J6l3494, Item 6214600A, Project Item Line Number 0400, Material Set 6214600A96, Material 1005FACCNS.CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. dukesm1 Acknowle Estimate Exception Type: Insufficient Materials: Project J6l3494, Item 7040104, Project Item Line Number 1160, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. Acknowle Estimate Exception Type: Insufficient Materials: Project J6l3494, Item 7040104, Project Item Line Number 1480, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. Acknowle Estimate Exception Type: Insufficient Materials: Project J6l3494, Item 7040104, Project Item Line Number 1480, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. Waiting on th	Number 0390, Material Set 617800196, Material 1065DE - Delineators, Acceptance Action Generic	Waiting on PAL approval from Jeff City. Delineators	dukesm1	Acknowledged
Number 0490, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action exception. exception. Generic 0621FB is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7040104, Project Item Line Waiting on the QC CRE20 sand report to resolve the dukesm1 Acknowle Number 1160, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the dukesm1 Acknowle Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7040104, Project Item Line Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve dukesm1 Acknowle Number 1480, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve dukesm1 Acknowle Number 1480, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve dukesm1 Acknowle Number 1480, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve dukesm1 Acknowle Number 1480, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acception. waiting on the QC CRE20 sand report to resolve the dukesm1 Acknowle Estimate Exception Type: Insuffic	Number 0400, Material Set 6178002A96, Material 1065DE - Delineators, Acceptance Action Generic	Waiting on PAL approval from Jeff City. Delineators	dukesm1	Acknowledged
Number 1160, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, exception. exception. Acceptance Action Generic 1005FACCNSCA is insufficient. Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. dukesm1 Acknowle Stimate Exception Type: Insufficient Materials: Project J6I3494, Item 7040104, Project Item Line Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. dukesm1 Acknowle Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7040104, Project Item Line Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. dukesm1 Acknowle Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7040104, Project Item Line Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. dukesm1 Acknowle Number 1480, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. Waiting on the QC CRE20 1" max LS/DO reports to resolve the exception. Acknowle Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7040104, Project Item Line Waiting on the QC CRE20 sand report to resolve the exception. Acknowle Number 1480, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Waiting on the QC CRE20 sand report to resolve the exception. Ackno	Number 0490, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action		dukesm1	Acknowledged
Number 1160, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, the exception. Acceptance Action Generic 100510CPCMLD is insufficient. the exception. Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7040104, Project Item Line Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. Number 1480, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Waiting on the 3 QC CRE20 1" max LS/DO reports to resolve the exception. Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7040104, Project Item Line Waiting on the QC CRE20 sand report to resolve the exception. dukesm1 Acknowle Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7040104, Project Item Line Waiting on the QC CRE20 sand report to resolve the exception. dukesm1 Acknowle Number 1480, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. dukesm1 dukesm1 Acknowle Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7101000, Project Item Line Working with a material rep to resolve the exception. No dukesm1 Overridde Number 1190, Material Set 710100096, Material 1036RSSRECAB - Epoxy Cld SprI Stl Rein for Anch Working with a material rep to resolve the exception. No overridde	Number 1160, Material Set 704010496, Material 1005FACCNS. CA - Natural Sand for Conc Class A,		dukesm1	Acknowledged
Number 1480, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. the exception. Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7040104, Project Item Line Number 1480, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. Waiting on the QC CRE20 sand report to resolve the exception. dukesm1 Acknowle Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7101000, Project Item Line Number 1190, Material as Project J6I3494, Item 7101000, Project Item Line exception. Working with a material rep to resolve the exception. No anchor bolts were used on this line dukesm1 Overridde	Number 1160, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,		dukesm1	Acknowledged
Number 1480, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, exception. Acceptance Action Generic 1005FACCNSCA is insufficient. exception. Estimate Exception Type: Insufficient Materials: Project J6l3494, Item 7101000, Project Item Line Working with a material rep to resolve the exception. No Number 1190, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Working with a material rep to resolve the exception. No	Number 1480, Material Set 704010496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,		dukesm1	Acknowledged
Number 1190, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch anchor bolts were used on this line	Number 1480, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A,		dukesm1	Acknowledged
	Number 1190, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch		dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7101000, Project Item Line Number 1360, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Ancho Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Number 1360, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch		dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7101000, Project Item Line Number 1600, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Number 1600, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch		dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7171002, Project Item Line Number 1430, Material Set 717100296, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	Number 1430, Material Set 717100296, Material 1080BRM - Bridge Material, Acceptance Action	Working with a material rep to resolve the exception	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3494, Item 7171002, Project Item Line Number 1530, Material Set 717100296, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	Number 1530, Material Set 717100296, Material 1080BRM - Bridge Material, Acceptance Action	Working with a material rep to resolve the exception	dukesm1	Overridden
Estimate Exception Type: Item Overrun: Contract 210521-F02, Contract Project J6I3494, Project Item Line Number 1160, Contract Line Item Number 1160, Item 7040104, Minor Item.			dukesm1	Overridden

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
10521-F02	J6I3494	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$30,000.00	\$22,500.0
		0001	0020	2063000	CLASS 3 EXCAVATION	15.00	0.00	15.00	CUYD	15.00	\$0.01	\$0.1
		0001	0030	2153000	SHAPING SLOPES, CLASS III	4.00	0.00	4.00	100F	4.00	\$900.00	\$3,600.0
		0001	0040	4039910	MISC.3" SP125CLP (PG76-22)	635.40	228.60	864.00	TONS	864.00	\$112.00	\$96,768.0
		0001	0050	4071005	TACK COAT	390.00	0.00	390.00	GAL	390.00	\$2.50	\$975.0
		0001	0060	4136000	PCCP JOINT/CRACK SEALING	8,780.00	0.00	8,780.00	LF	0.00	\$2.00	\$0.0
		0001	0070	6044012	PIPE COLLAR, TYPE B	1.00	0.00	1.00	EA	1.00	\$4,500.00	\$4,500.0
		0001	0080	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	70.00	0.00	70.00	LF	70.00	\$64.00	\$4,480.0
		0001	0090	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	18.00	0.00	18.00	CUYD	18.00	\$40.00	\$720.0
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	18.00	0.00	18.00	CUYD	18.00	\$200.00	\$3,600.0
		0001	0110	6113010	FURNISHING TYPE 1 ROCK BLANKET	5.00	0.00	5.00	CUYD	5.00	\$47.00	\$235.0
		0001	0120	6113030	PLACING TYPE 1 ROCK BLANKET	5.00	0.00	5.00	CUYD	5.00	\$0.01	\$0.0
		0001	0130	6122009	IMPACT ATTENUATOR 45 MPH (SAND BARREL ARRAY)	2.00	-1.00	1.00	EA	1.00	\$2,178.00	\$2,178.0
		0001	0140	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$3,726.00	\$7,452.0
		0001	0150	6122020	REPLACEMENT SAND BARREL	5.00	0.00	5.00	EA	0.00	\$402.00	\$0.0
		0001	0160	6122030	IMPACT ATTENUATOR (RELOCATION)	8.00	0.00	8.00	EA	8.00	\$761.00	\$6,088.0
		0001	0170	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$11,200.00	\$22,400.0
		0001	0180	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	41.40	0.00	41.40	SQYD	0.00	\$400.00	\$0.0
		0001	0190	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	4.00	0.00	4.00	SQYD	0.00	\$0.01	\$0.0
		0001	0200	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	41.00	0.00	41.00	SQYD	20.50	\$55.00	\$1,127.5
		0001 0210 0001 0220 0001 0230	0210	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	174.00	0.00	174.00	LF	0.00	\$12.25	\$0.0
			0220	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	62.00	0.00	62.00	EA	0.00	\$50.00	\$0.0
			0230	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	6.00	0.00	6.00	EA	0.00	\$8.00	\$0.0
		0001	0240	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	1.00	0.00	1.00	EA	1.00	\$700.00	\$700.0
		0001	0250	6161005	CONSTRUCTION SIGNS	1,914.00	0.00	1,914.00	SQFT	1,914.00	\$7.00	\$13,398.0
		0001	0260	6161008	ADVANCED WARNING RAIL SYSTEM	24.00	0.00	24.00	EA	16.00	\$20.00	\$320.0
		0001	0270	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	200.00	\$18.00	\$3,600.0
		0001	0280	6161030	TYPE III MOVEABLE BARRICADE	8.00	0.00	8.00	EA	8.00	\$145.00	\$1,160.0
		0001	0290	6161033	DIRECTIONAL INDICATOR BARRICADE	56.00	0.00	56.00	EA	56.00	\$65.00	\$3,640.0
		0001	0300	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$850.00	\$3,400.0
		0001	0310	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$8,525.00	\$8,525.0
		0001	0320	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	19.00	0.00	19.00	EA	19.00	\$850.00	\$16,150.0
		0001	0330	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN CONTRACTOR FURNISHED/RETAINED	6.00	0.00	6.00	EA	6.00	\$2,400.00	\$14,400.0
		0001	0340	6171000	CONCRETE TRAFFIC BARRIER, TYPE A	25.00	4.00	29.00	LF	29.00	\$350.00	\$10,150.0
		0001	0350	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	925.00	0.00	925.00	LF	300.00	\$21.06	\$6,318.0
		0001	0360	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	3,400.00	0.00	3,400.00	LF	3,400.00	\$24.23	\$82,382.0
		0001	0370	6175010A		925.00	0.00	925.00	LF	250.00	\$8.90	\$2,225.0
		0001	0380	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	5,800.00	0.00	5,800.00	LF	5,800.00	\$11.14	\$64,612.0
		0001	0390	6178001	TRAFFIC BARRIER DELINEATOR, WHITE	90.00	0.00	90.00	EA	90.00	\$20.00	\$1,800.0
		0001	0400	6178002A	TRAFFIC BARRIER DELINEATOR, YELLOW	50.00	0.00	50.00	EA	36.00	\$25.00	\$900.0
		0001	0410	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$181,817.13	\$136,362.8
		0001	0420	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	24.00	0.00	24.00	LF	24.00	\$25.00	\$600.0
		0001	0430	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	9,075.00	0.00	9,075.00	LF	5,715.00	\$0.30	\$1,714.5
		0001	0440	6205903A		6,425.00	0.00	6,425.00	LF	4,185.00	\$0.30	\$1,255.5

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)	
210521-F02	J6I3494	0001	0450	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,999.00	37,760.00	39,759.00	LF	39,759.00	\$1.00	\$39,759.0	
		0001	0460	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3,330.00	0.00	3,330.00	LF	3,330.00	\$0.50	\$1,665.0	
		0001	0470	6207001	PAVEMENT MARKING REMOVAL	50,249.00	0.00	50,249.00	LF	50,249.00	\$0.70	\$35,174.3	
		0001	0480	6209903	MISC.TEMPORARY REMOVABLE CONTRAST MARKING TAPE	37,760.00	-37,760.00	0.00	LF	0.00	\$2.50	\$0.0	
		0001	0490	6214600A	FLOWABLE BACKFILL	270.00	0.00	270.00	CUYD	72.00	\$170.00	\$12,240.	
		0001	0500	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	3,855.00	900.00	4,755.00	SQYD	4,755.00	\$5.00	\$23,775.	
		0001	0510	6240104A	SEPARATION GEOTEXTILE	90.00	0.00	90.00	SQYD	90.00	\$12.00	\$1,080.	
		0001	0520	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	29.30	0.00	29.30	STA	0.00	\$374.94	\$0.	
		0001	0530	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$12,000.00	\$12,000	
		0001	0540	7261012	12 IN. PIPE GROUP A	10.00	0.00	10.00	LF	10.00	\$350.00	\$3,500	
		0001	0550	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	6.00	0.00	6.00	FT	6.00	\$1,500.00	\$9,000	
		0001	0560	8061019	SILT FENCE	40.00	0.00	40.00	LF	0.00	\$30.00	\$0.	
		0010	0570	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,700.00	0.00	1,700.00	LF	1,662.50	\$25.00	\$41,562.	
		0010	0580	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	7.00	0.00	7.00	EA	7.00	\$3,200.00	\$22,400	
		0010	0590	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	8.00	0.00	8.00	EA	8.00	\$3,100.00	\$24,800	
		0010	0600	6061074	MGS HEIGHT AND BLOCK TRANSITION	2.00	0.00	2.00	EA	2.00	\$700.00	\$1,400	
		0010	0610	6061080	MGS END ANCHOR	3.00	0.00	3.00	EA	3.00	\$1,200.00	\$3,600	
		0010	0620	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	8.00	\$2,800.00	\$22,400	
		0010 0	0630	6063018	TYPE D CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	0.00	\$38,880.00	\$0	
			0640	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	400.00	0.00	400.00	LF	0.00	\$17.10	\$0	
		0020	0650	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	400.00	0.00	400.00	LF	0.00	\$6.78	\$0	
		0020	0660	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	400.00	0.00	400.00	LF	0.00	\$5.88	\$0	
		0040	0670	9039902	MISC.COVER EXISTING OVERHEAD SIGNS	1.00	0.00	1.00	EA	0.00	\$1,200.00	\$0	
		0050	0680	9109903	MISC.MODOT ITS ASSETS RELOCATION	137.00	0.00	137.00	LF	0.00	\$25.00	\$0	
		0070	0690	2065500	TEMPORARY SHORING	1.00	1.00 0.	0.00	1.00	LS	1.00	\$50,000.00	\$50,000
		0070	0700	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	1.00	\$75,000.00	\$75,000	
		0070	0710	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	227.00	0.00	227.00	LF	227.00	\$527.00	\$119,629	
		0070	0720	2169903	MISC.REMOVE AND REPLACE CURB	28.00	0.00	28.00	LF	28.00	\$2,000.00	\$56,000	
		0070	0730	2169904	MISC.REMOVAL OF EXISTING APPROACH SLAB	1,347.00	0.00	1,347.00	SQFT	1,347.00	\$19.00	\$25,593	
		0070	0740	5031010A	BRIDGE APPROACH SLAB (MAJOR)	150.00	0.00	150.00	SQYD	150.00	\$600.00	\$90,000	
		0070	0750	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	2,565.00	-2,565.00	0.00	SQYD	0.00	\$37.99	\$0	
		0070	0760	7034001	CLASS B-1 CONCRETE	40.00	0.00	40.00	CUYD	40.00	\$2,000.00	\$80,000	
		0070	0770	7034214	CLASS B-2 CONCRETE	43.40	0.00	43.40	CUYD	43.40	\$2,000.00	\$86,800	
		0070	0780	7040104	HALF-SOLE REPAIR	50.00	-50.00	0.00	SQFT	0.00	\$350.00	\$0	
		0070	0790	7061070	MECHANICAL BAR SPLICE	84.00	0.00	84.00	EA	84.00	\$52.49	\$4,409	
		0070	0800	7101000	REINFORCING STEEL (EPOXY COATED)	6,360.00	0.00	6,360.00	LB	6,360.00	\$2.10	\$13,350	
		0070	0810	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$13,000.00	\$13,000	
		0070	0820	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,600.00	0.00	1,600.00	SQFT	1,600.00	\$40.00	\$64,00	
		0070	0830	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,600.00	0.00	1,600.00	SQFT	1,600.00	\$1.00	\$1,600	
		0070	0840	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,600.00	0.00	1,600.00	SQFT	1,600.00	\$1.00	\$1,600	
		0070	0850	7125370A	FINISH FIELD COAT (SYSTEM G)	1,600.00	0.00	1,600.00	SQFT	1,600.00	\$1.00	\$1,600	
		0070	0860	7129902	MISC.REPAIR SLAB DRAIN BRACKET	1.00	0.00	1.00	EA	1.00	\$315.00	\$315	
		0070	0870	7151001	VERTICAL DRAIN AT END BENTS	1.00	0.00	1.00	EA	1.00	\$7,000.00	\$7,000	
		0070	0880	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	114.00	0.00	114.00	LF	114.00	\$375.00	\$42,750	

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	ies are l	based on F	Report Generated date and can differ from the posted am	ount at the	e time the E	stimate was	Genera	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F02	J6I3494	0070	0890	7172054	OPEN CELL FOAM JOINT SEAL	114.00	0.00	114.00	LF	114.00	\$59.00	\$6,726.00
		0071	0900	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	1.00	\$40,000.00	\$40,000.00
		0071	0910	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	1.00	\$75,000.00	\$75,000.00
		0071	0920	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	227.00	0.00	227.00	LF	227.00	\$525.00	\$119,175.00
		0071	0930	2169903	MISC.REMOVE AND REPLACE CURB	31.00	0.00	31.00	LF	31.00	\$2,250.00	\$69,750.00
		0071	0940	2169904	MISC.REMOVAL OF EXISTING APPROACH SLAB	1,336.00	0.00	1,336.00	SQFT	1,336.00	\$19.00	\$25,384.00
		0071	0950	5031010A	BRIDGE APPROACH SLAB (MAJOR)	149.00	0.00	149.00	SQYD	149.00	\$610.00	\$90,890.00
		0071	0960	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	2,565.00	-2,565.00	0.00	SQYD	0.00	\$39.00	\$0.00
		0071	0970	7034001	CLASS B-1 CONCRETE	41.00	0.00	41.00	CUYD	41.00	\$2,000.00	\$82,000.00
		0071	0980	7034214	CLASS B-2 CONCRETE	44.70	0.00	44.70	CUYD	44.70	\$2,000.00	\$89,400.00
		0071	0990	7040104	HALF-SOLE REPAIR	50.00	-50.00	0.00	SQFT	0.00	\$350.00	\$0.00
		0071	1000	7061070	MECHANICAL BAR SPLICE	84.00	0.00	84.00	EA	84.00	\$52.49	\$4,409.16
		0071	1010	7101000	REINFORCING STEEL (EPOXY COATED)	6,360.00	0.00	6,360.00	LB	6,360.00	\$2.10	\$13,356.00
		0071	1020	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$13,000.00	\$13,000.00
		0071	1030	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,600.00	0.00	1,600.00	SQFT	1,600.00	\$40.00	\$64,000.00
		0071	1040	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,600.00	0.00	1,600.00	SQFT	1,600.00	\$1.00	\$1,600.00
		0071	1050	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,600.00	0.00	1,600.00	SQFT	1,600.00	\$1.00	\$1,600.00
		0071	1060	7125370A	FINISH FIELD COAT (SYSTEM G)	1,600.00	0.00	1,600.00	SQFT	1,600.00	\$1.00	\$1,600.00
		0071	1070	7151001	VERTICAL DRAIN AT END BENTS	1.00	0.00	1.00	EA	1.00	\$7,000.00	\$7,000.00
		0071	1080	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	114.00	0.00	114.00	LF	114.00	\$375.00	\$42,750.00
		0071	1090	7172054	OPEN CELL FOAM JOINT SEAL	114.00	0.00	114.00	LF	114.00	\$59.00	\$6,726.00
		0072	1100	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	55.00	0.00	55.00	LF	55.00	\$480.00	\$26,400.00
		0072	1110	2169902	MISC.REMOVE AND REPLACE BEARING STOPPER PLATES	4.00	0.00	4.00	EA	0.00	\$1,150.00	\$0.00
		0072	1120	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	19.00	0.00	19.00	LF	19.00	\$2,500.00	\$47,500.00
		0072	1130	6233000	EPOXY POLYMER WEARING SURFACE	3,520.00	-3,520.00	0.00	SQYD	0.00	\$35.00	\$0.00
		0072	1140	7034214	CLASS B-2 CONCRETE	8.00	0.00	8.00	CUYD	8.00	\$2,400.00	\$19,200.00
		0072	1150	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	55.00	0.00	55.00	SQFT	0.00	\$315.00	\$0.00
		0072	1160	7040104	HALF-SOLE REPAIR	150.00	0.00	150.00	SQFT	167.00	\$165.00	\$27,555.00
		0072	1170	7040113	CLEANING AND EPOXY COATING	5,472.00	0.00	5,472.00	SQFT	5,472.00	\$3.00	\$16,416.00
		0072	1180	7049903	MISC.BARRIER CURB REPAIR (UNFORMED)	8.00	0.00	8.00	LF	0.00	\$625.00	\$0.00
		0072	1190	7101000	REINFORCING STEEL (EPOXY COATED)	680.00	0.00	680.00	LB	680.00	\$2.80	\$1,904.00
		0072	1200	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$22,700.00	\$0.00
		0072	1210	7120915	EXPANSION DEVICE (FLAT PLATE)	55.00	0.00	55.00	LF	55.00	\$815.00	\$44,825.00
		0072	1220	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	1.00	\$4,900.00	\$4,900.00
		0072	1230	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	1.00	\$4,900.00	\$4,900.00
		0072	1240	7129902	MISC.SLAB DRAIN EXTENSION	1.00	0.00	1.00	EA	0.00	\$1,150.00	\$0.00
		0072	1250	7173002	SILICONE EXPANSION JOINT SEALANT	168.00	0.00	168.00	LF	168.00	\$40.00	\$6,720.00
		0073	1260	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	43.00	0.00	43.00	LF	43.00	\$650.00	\$27,950.00
		0073	1270	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	43.00	0.00	43.00	LF	43.00	\$85.00	\$3,655.00
		0073	1280	2169902	MISC.REMOVE AND REPLACE BEARING STOPPER PLATES	18.00	0.00	18.00	EA	12.00	\$3,800.00	\$45,600.00
		0073	1290	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	6.00	0.00	6.00	LF	6.00	\$3,200.00	\$19,200.00
		0073	1300	6233000	EPOXY POLYMER WEARING SURFACE	4,756.00	-4,756.00	0.00	SQYD	0.00	\$34.52	\$0.00
		0073	1310	7034214	CLASS B-2 CONCRETE	6.70	0.00	6.70	CUYD	6.70	\$4,400.00	\$29,480.00
		0073	1320	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	268.00	0.00	268.00	SQFT	22.00	\$175.00	\$3,850.00

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Post Advisition of the second second

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
521-F02	J6I3494	0073	1330	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$190.00	\$0.00
		0073	1340	7040113	CLEANING AND EPOXY COATING	8,557.00	0.00	8,557.00	SQFT	0.00	\$3.00	\$0.00
		0073	1350	7049903	MISC.BARRIER CURB REPAIR (UNFORMED)	4.00	0.00	4.00	LF	4.00	\$1,100.00	\$4,400.00
		0073	1360	7101000	REINFORCING STEEL (EPOXY COATED)	640.00	0.00	640.00	LB	640.00	\$4.25	\$2,720.00
		0073	1370	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$22,700.00	\$22,700.0
		0073	1380	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	700.00	0.00	700.00	SQFT	700.00	\$40.00	\$28,000.0
		0073	1390	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	700.00	0.00	700.00	SQFT	700.00	\$1.00	\$700.0
		0073	1400	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	700.00	0.00	700.00	SQFT	700.00	\$1.00	\$700.0
		0073	1410	7125370A	FINISH FIELD COAT (SYSTEM G)	700.00	0.00	700.00	SQFT	700.00	\$1.00	\$700.0
		0073	1420	7129901	MISC.FLUSHING OF EXISTING EXPANSION TROUGH	1.00	0.00	1.00	LS	1.00	\$4,000.00	\$4,000.0
		0073	1430	7171002	PREFORMED COMPRESSION SEAL	43.00	0.00	43.00	LF	43.00	\$120.00	\$5,160.0
		0073	1440	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	43.00	0.00	43.00	LF	43.00	\$430.00	\$18,490.0
		0073	1450	7173002	SILICONE EXPANSION JOINT SEALANT	154.00	0.00	154.00	LF	154.00	\$30.00	\$4,620.0
		0074	1460	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	101.00	0.00	101.00	LF	101.00	\$35.00	\$3,535.0
		0074	1470	6233000	EPOXY POLYMER WEARING SURFACE	2,182.00	-2,182.00	0.00	SQYD	0.00	\$36.00	\$0.0
		0074	1480	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	14.00	\$350.00	\$4,900.0
		0074	1490	7040113	CLEANING AND EPOXY COATING	1,457.00	0.00	1,457.00	SQFT	0.00	\$3.00	\$0.0
		0074	1500	7049903	MISC.BARRIER CURB REPAIR (UNFORMED)	5.00	0.00	5.00	LF	2.00	\$850.00	\$1,700.0
		0074	1510	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$12,900.00	\$0.0
		0074	1520	7123100	CLEANING AND COATING EXISTING BEARINGS	6.00	0.00	6.00	EA	0.00	\$500.00	\$0.0
		0074	1530	7171002	PREFORMED COMPRESSION SEAL	101.00	0.00	101.00	LF	101.00	\$85.00	\$8,585.0
		0074	1540	7173002	SILICONE EXPANSION JOINT SEALANT	143.00	0.00	143.00	LF	143.00	\$32.00	\$4,576.0
		0075	1550	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	31.00	0.00	31.00	LF	31.00	\$725.00	\$22,475.0
		0075	1560	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	10.00	0.00	10.00	LF	10.00	\$1,500.00	\$15,000.0
		0075	1570	6233000	EPOXY POLYMER WEARING SURFACE	1,183.00	-1,183.00	0.00	SQYD	0.00	\$35.50	\$0.0
		0075	1580	7034214	CLASS B-2 CONCRETE	4.40	0.00	4.40	CUYD	4.40	\$4,100.00	\$18,040.0
		0075	1590	7040113	CLEANING AND EPOXY COATING	1,016.00	0.00	1,016.00	SQFT	0.00	\$3.00	\$0.0
		0075	1600	7101000	REINFORCING STEEL (EPOXY COATED)	350.00	0.00	350.00	LB	350.00	\$3.50	\$1,225.0
		0075	1610	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$12,900.00	\$0.0
		0075	1620	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	31.00	0.00	31.00	LF	31.00	\$430.00	\$13,330.0
		0075	1630	7173002	SILICONE EXPANSION JOINT SEALANT	133.00	0.00	133.00	LF	133.00	\$35.00	\$4,655.0
		0070	5001	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	0.00	2,565.00	2,565.00	SQYD	0.00	\$37.99	\$0.0
		0071	5002	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	0.00	2,565.00	2,565.00	SQYD	0.00	\$39.00	\$0.0
		0072	5003	6233000	EPOXY POLYMER WEARING SURFACE	0.00	3,520.00	3,520.00	SQYD	3,520.00	\$35.00	\$123,200.0
		0073	5004	6233000	EPOXY POLYMER WEARING SURFACE	0.00	4,756.00	4,756.00	SQYD	4,756.00	\$34.52	\$164,177.1
		0074	5005	6233000	EPOXY POLYMER WEARING SURFACE	0.00	2,182.00	2,182.00	SQYD	2,182.00	\$36.00	\$78,552.0
		0073	5006	6122040	WORK ZONE CRASH CUSHION (NARROW)	0.00	1.00	1.00	EA	1.00	\$3,500.00	\$3,500.0
		0075	5007	6233000	EPOXY POLYMER WEARING SURFACE	0.00	1,183.00	1,183.00	SQYD	1,183.00	\$35.50	\$41,996.5
	Project J	1613494 - To	otal Value	Posted to D	Date as of Report Generated Date							\$3,223,302.29
521-F02 Ove	rall - Tota	Value Pos	sted to Da	te as of Rep	ort Generated Date							\$3,223,302.2



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6I3494

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0250	6161005	CONSTRUCTION SIGNS	6/10/22	6/14/22	340.50	SQFT	WB 370	164+40			123+00	
0300	6161040	FLASHING ARROW PANEL	6/10/22	6/14/22	4.00	EA	I-70 WB & EB	1060+54		1082+90		
0390	6178001	TRAFFIC BARRIER DELINEATOR, WHITE	6/10/22	6/14/22	7.00	EA	Ramp 1 RT Bridge A5097	3+62		7+21		
				6/14/22	7.00	EA	SB 370	116+49		119+41		
				6/14/22	9.00	EA	I-70 EB	1067+42		1071+81		
				6/14/22	9.00	EA		1069+92		1074+17		
				6/14/22	18.00	EA	N.O.R RT	1073+71		1082+90		
				6/14/22	19.00	EA	N.O.R LT	1073+71		1082+90		
				6/14/22	21.00	EA	Ramp 1 RT	17+75		28+00		
0400	6178002A	TRAFFIC BARRIER DELINEATOR, YELLOW	6/10/22	6/14/22	7.00	EA	370 SB	116+49		119+99		
				6/14/22	7.00	EA	Bridge A5097Ramp 1 RT	3+48		7+04		
				6/14/22	22.00	EA		17+68		28+99		
0430	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	6/10/22	6/14/22	64.00	LF	Bridge A5097	3+50		4+14		
				6/14/22	170.00	LF	bridge A5096	116+50		119+90		
				6/14/22	339.00	LF	Bridge A5096	116+45		119+84		
				6/14/22	360.00	LF	Bridge A5097	3+58		7+18		
				6/14/22	1,053.00	LF	Bridge A5093	17+69		28+22		
				6/14/22	1,243.00	LF		1059+00		1083+86		
				6/14/22	2,486.00	LF	EB I-70	1059+00		1083+86		
0440	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	6/10/22	6/14/22	295.00	LF		4+14		7+07		
				6/14/22	340.00	LF	Bridge A5096	116+56		119+96		
				6/14/22	1,064.00	LF	Bridge A5093	17+68		28+55		
				6/14/22	2,486.00	LF	Bridge A5091	1059+00		108386		
0450	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	6/7/22	6/8/22	37,760.00	LF	EB and WB I-70 stage 1 - 4 Temp striping white tape	1059+02		1083+82		
			6/10/22	6/14/22	984.00	LF	Bridge A5094	1073+30		1083+24		
				6/14/22	1,015.00	LF	Bridge A5094	1073+30		1083+24		
0460	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	6/10/22	6/14/22	1,300.00	LF	Bridge A5094	1073+30		1083+24		
				6/14/22	2,030.00	LF	Bridge A5094	1073+30		1083+24		
0470	6207001	PAVEMENT MARKING REMOVAL	6/10/22	6/14/22	674.00	LF	N.O.R Bridge A5094	1067+00		1080+00		
0570	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	6/7/22	6/8/22	50.00	LF	WB 370 RT shoulder	115+37		116+49		
0590	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	6/7/22	6/8/22	1.00	EA		116+49				
0600	6061074	MGS HEIGHT AND BLOCK TRANSITION	6/7/22	6/8/22	1.00	EA		116+49				
5003	6233000	EPOXY POLYMER WEARING SURFACE	6/8/22	6/10/22	3,520.00	SQYD	Ramp 1 Flyover Bridge A5093	17+68		28+50		
5004	6233000	EPOXY POLYMER WEARING SURFACE	6/8/22	6/10/22	4,756.00	SQYD	N.O.R Bridge A5094	1073+65		1082+90		
5005	6233000	EPOXY POLYMER WEARING SURFACE	6/8/22	6/10/22	2,182.00	SQYD	WB I-370 Bridge A5096	116+50		120+00		
5007	6233000	EPOXY POLYMER WEARING SURFACE	6/8/22	6/10/22	1,183.00	SQYD	Ramp 1 Bridge A5097	3+62		7+21		

The information below this line are details for Construction Signs (if applicable). No Data Available



Jun 18, 2022

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3494	0040	MISC.	Other Item Adjustment	ACAD	4	Nov 2, 2021	spurlt2	\$590.34	AC Adjustments: Line Item 0040 864.97 tons with 3.9% VAC, mix ID SP125 19-7
				ACAD - Tot	al			\$590.34	
			Other Item Adj	ustment - To	otal			\$590.34	
			Overrun	Overrun	2	Oct 4, 2021	SYSTEM	(\$25,618.38)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Nov 2, 2021	SYSTEM	\$25,618.38	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',112.06640 - 112.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	l				\$0.00	
			Price FUEL		2	Oct 4, 2021	SYSTEM	\$57.37	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$57.37	
			Price FUEL - T	otal				\$57.37	
	0040 -	Total						\$647.71	
	0070	PIPE COLLAR, TYPE B	Material		6	Nov 24, 2021	SYSTEM	(\$4,500.00)	
				- Total				(\$4,500.00)	
			Material - Tota	I				(\$4,500.00)	
			MaterialCredit		7	Dec 17, 2021	SYSTEM	\$4,500.00	
				- Total				\$4,500.00	
			MaterialCredit	- Total				\$4,500.00	
	0070 -	Total						\$0.00	
	0080	INTEGRAL CURB (6 IN.	Material		6	Nov 24, 2021	SYSTEM	(\$640.00)	
		HEIGHT AND UNDER)			7	Dec 17, 2021	SYSTEM	(\$640.00)	
					8	Jan 3, 2022	SYSTEM	(\$640.00)	
				- Total				(\$1,920.00)	
			Material - Tota	l				(\$1,920.00)	
			MaterialCredit		7	Dec 17, 2021	SYSTEM	\$640.00	
					8	Jan 3, 2022	SYSTEM	\$640.00	
				Tetal	9	Apr 4, 2022	SYSTEM	\$640.00	
			MaterialCredit	- Total				\$1,920.00 \$1,920.00	
	0080 -	Total	WaterialCreuit	- 10(a)				\$1,920.00	
	0110	FURNISHING TYPE 1 ROCK	Material		6	Nov 24, 2021	SYSTEM	(\$235.00)	
		BLANKET		- Total				(\$235.00)	
			Material - Tota					(\$235.00)	
			MaterialCredit		7	Dec 17, 2021	SYSTEM	\$235.00	
				- Total				\$235.00	
			MaterialCredit	- Total				\$235.00	
	0110 -	Total						\$0.00	
	0200	TYPE 1 OR 5 AGGREGATE	Material		4	Nov 2, 2021	SYSTEM	(\$1,127.50)	
		FOR BASE (4 IN. TH		- Total				(\$1,127.50)	
			Material - Tota	I				(\$1,127.50)	
			MaterialCredit		5	Nov 16, 2021	SYSTEM	\$1,127.50	
				- Total				\$1,127.50	



Jun 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3494	0200	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	MaterialCredit	- Total				\$1,127.50	
	0200 -							\$0.00	
	0340	CONCRETE TRAFFIC BARRIER, TYPE	Material		3	Oct 19, 2021	SYSTEM	\$8,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dukesm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		A			3	Oct 19, 2021	SYSTEM	(\$8,750.00)	
					4	Nov 2, 2021	SYSTEM	(\$10,150.00)	
					5	Nov 16, 2021	SYSTEM	(\$10,150.00)	
					6	Nov 24, 2021	SYSTEM	(\$10,150.00)	
					7	Dec 17, 2021	SYSTEM	(\$10,150.00)	
					8	Jan 3, 2022	SYSTEM	(\$10,150.00)	
					9	Apr 4, 2022	SYSTEM	(\$10,150.00)	
					10	Apr 18, 2022	SYSTEM	(\$10,150.00)	
					11	May 2, 2022	SYSTEM	\$10,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user spurtt2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	May 2, 2022	SYSTEM	(\$10,150.00)	
					12	May 16, 2022	SYSTEM	\$10,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user spurlt2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	May 16, 2022	SYSTEM	(\$10,150.00)	
					13	Jun 2, 2022	SYSTEM	\$10,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user spurIt2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Jun 2, 2022	SYSTEM	(\$10,150.00)	
				- Total				(\$71,050.00)	
			Material - Tota	l				(\$71,050.00)	
			MaterialCredit		5	Nov 16, 2021	SYSTEM	\$10,150.00	
					6	Nov 24, 2021	SYSTEM	\$10,150.00	
					7	Dec 17, 2021	SYSTEM	\$10,150.00	
					8	Jan 3, 2022	SYSTEM	\$10,150.00	
					9	Apr 4, 2022	SYSTEM	\$10,150.00	
					10	Apr 18, 2022 May 2,	SYSTEM	\$10,150.00	
						2022			
				- Total				\$71,050.00	
			MaterialCredit					\$71,050.00	
			Overrun	Overrun	4	Nov 2, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 32 on the current Payment Estimate. Material Insufficiency Quantity 29.000; Overrun Quantity Balance 4.00.
					4	Nov 2, 2021	SYSTEM	(\$1,400.00)	
					5	Nov 16, 2021	SYSTEM	(\$1,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
4	0340	CONCRETE TRAFFIC BARRIER, TYPE A	Overrun	Overrun	5	Nov 16, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 1 on the current Payment Estimate. Material Insufficiency Quantity 29.000; Overrun Quantity Balance 4.00.
					6	Nov 24, 2021	SYSTEM	(\$1,400.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Nov 24, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 1 on the current Payment Estimate. Material Insufficiency Quantity 29.000; Overrun Quantity Balance 4.00.
					7	Dec 17, 2021	SYSTEM	(\$1,400.00)	Averaged Price Adjustment from this item on all previous payment estimate of '0.00000' is applied (if non-zero).
					7	Dec 17, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception on the current Payment Estimate. Material Insufficiency Quantity 29.000; Overrun Quantity Balance 4.00.
					8	Jan 3, 2022	SYSTEM	(\$1,400.00)	Averaged Price Adjustment from this item on all previous payment estimate of '0.00000' is applied (if non-zero).
					8	Jan 3, 2022	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception on the current Payment Estimate. Material Insufficiency Quantity 29.000; Overrun Quantity Balance 4.00.
					9	Apr 4, 2022	SYSTEM	(\$1,400.00)	Averaged Price Adjustment from this item on all previous payment estimate of '0.00000' is applied (if non-zero).
					9	Apr 4, 2022	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception on the current Payment Estimate. Material Insufficiency Quantity 29.000; Overrun Quantity Balance 4.00.
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0340 -							\$0.00	
	0390	TRAFFIC BARRIER DELINEATOR,	Material		14	Jun 16, 2022	SYSTEM	(\$1,800.00)	
		WHITE		- Total				(\$1,800.00)	
			Material - Tota	al				(\$1,800.00)	
	0390 -							(\$1,800.00)	
	0400	TRAFFIC BARRIER	Material		14	Jun 16, 2022	SYSTEM	(\$900.00)	
		DELINEATOR, YELLOW		- Total				(\$900.00)	
		DELINEATOR, YELLOW	Material - Tota					(\$900.00) (\$900.00)	
	0400 -	DELINEATOR, YELLOW							
	0400 - 0420	DELINEATOR, YELLOW Total TEMPORARY REMOVABLE	Material - Tota Material		9	Apr 4, 2022	SYSTEM	(\$900.00)	
		DELINEATOR, YELLOW Total TEMPORARY			9 10		SYSTEM	(\$900.00) (\$900.00)	
		DELINEATOR, YELLOW Total TEMPORARY REMOVABLE MARKING TAPE,				2022 Apr 18,		(\$900.00) (\$900.00) (\$600.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user spurIt2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		DELINEATOR, YELLOW Total TEMPORARY REMOVABLE MARKING TAPE,			10	2022 Apr 18, 2022 May 2,	SYSTEM	(\$900.00) (\$900.00) (\$600.00) (\$600.00)	Estimate Item Adjustment (0019) due to user spurIt2 overridding Payment
		DELINEATOR, YELLOW Total TEMPORARY REMOVABLE MARKING TAPE,			10	2022 Apr 18, 2022 May 2, 2022 May 2,	SYSTEM SYSTEM	(\$900.00) (\$900.00) (\$600.00) (\$600.00) \$600.00	Estimate Item Adjustment (0019) due to user spurIt2 overridding Payment
		DELINEATOR, YELLOW Total TEMPORARY REMOVABLE MARKING TAPE,		al - Total	10	2022 Apr 18, 2022 May 2, 2022 May 2,	SYSTEM SYSTEM	(\$900.00) (\$900.00) (\$600.00) (\$600.00) \$600.00 (\$600.00)	Estimate Item Adjustment (0019) due to user spurIt2 overridding Payment
		DELINEATOR, YELLOW Total TEMPORARY REMOVABLE MARKING TAPE,	Material	al - Total	10	2022 Apr 18, 2022 May 2, 2022 May 2,	SYSTEM SYSTEM	(\$900.00) (\$900.00) (\$600.00) (\$600.00) \$600.00 (\$600.00) (\$600.00)	Estimate Item Adjustment (0019) due to user spurIt2 overridding Payment
		DELINEATOR, YELLOW Total TEMPORARY REMOVABLE MARKING TAPE,	Material Material - Tota	al - Total	10 11 11	2022 Apr 18, 2022 May 2, 2022 May 2, 2022 Apr 18,	SYSTEM SYSTEM SYSTEM	(\$900.00) (\$900.00) (\$600.00) (\$600.00) (\$600.00) (\$600.00) (\$1,200.00) (\$1,200.00)	Estimate Item Adjustment (0019) due to user spurIt2 overridding Payment
		DELINEATOR, YELLOW Total TEMPORARY REMOVABLE MARKING TAPE,	Material Material - Tota	al - Total	10 11 11 10	2022 Apr 18, 2022 May 2, 2022 May 2, 2022 Apr 18, 2022 May 2, May 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$900.00) (\$900.00) (\$600.00) (\$600.00) (\$600.00) (\$600.00) (\$1,200.00) (\$1,200.00) \$600.00	Estimate Item Adjustment (0019) due to user spurIt2 overridding Payment
		DELINEATOR, YELLOW Total TEMPORARY REMOVABLE MARKING TAPE,	Material Material - Tota	al - Total al	10 11 11 10	2022 Apr 18, 2022 May 2, 2022 May 2, 2022 Apr 18, 2022 May 2, May 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$900.00) (\$900.00) (\$600.00) (\$600.00) (\$600.00) (\$1,200.00) (\$1,200.00) (\$1,200.00) \$600.00	Estimate Item Adjustment (0019) due to user spurIt2 overridding Payment
		DELINEATOR, YELLOW Total TEMPORARY REMOVABLE MARKING TAPE, 24 IN.	Material Material - Tota MaterialCredit	al - Total al	10 11 11 10	2022 Apr 18, 2022 May 2, 2022 May 2, 2022 Apr 18, 2022 May 2, May 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$900.00) (\$900.00) (\$600.00) (\$600.00) (\$600.00) (\$1,200.00) (\$1,200.00) \$600.00 \$600.00	Estimate Item Adjustment (0019) due to user spurIt2 overridding Payment
	0420	DELINEATOR, YELLOW Total TEMPORARY REMOVABLE MARKING TAPE, 24 IN.	Material Material - Tota MaterialCredit	al - Total al	10 11 11 10	2022 Apr 18, 2022 May 2, 2022 May 2, 2022 Apr 18, 2022 May 2, May 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$900.00) (\$900.00) (\$600.00) (\$600.00) (\$600.00) (\$1,200.00) (\$1,200.00) \$600.00 \$1,200.00 \$1,200.00	Estimate Item Adjustment (0019) due to user spurIt2 overridding Payment



Jun 18, 2022

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3494	0490	FLOWABLE BACKFILL	Material		14	Jun 16, 2022	SYSTEM	(\$12,240.00)	
				- Total				(\$32,980.00)	
			Material - Tota	l.				(\$32,980.00)	
			MaterialCredit		13	Jun 2, 2022	SYSTEM	\$8,500.00	
					14	Jun 16, 2022	SYSTEM	\$12,240.00	
				- Total				\$20,740.00	
			MaterialCredit	- Total				\$20,740.00	
	0490 -	Total						(\$12,240.00)	
	0500	COLDMILLING BIT. PAVT FOR	Overrun	Overrun	2	Oct 4, 2021	SYSTEM	(\$4,500.00)	
		REM OF SURF.			4	Nov 2, 2021	SYSTEM	\$4,500.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0500 -	Total						\$0.00	
	0570	MGS GUARDRAIL, 8	Construction Stockpile		9	Apr 4, 2022	SYSTEM	(\$19,548.38)	Payment Estimate Item Adjustment generated Stockpile Transaction
		FT. POSTS, 6 FT 3 IN			12	May 16, 2022	SYSTEM	(\$13,201.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
					14	Jun 16, 2022	SYSTEM	(\$1,015.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$33,765.38)	
			Construction	Stockpile - To	otal			(\$33,765.38)	
			Construction Stockpile STMI		1	Sep 15, 2021	SYSTEM	\$34,527.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			31101	- Total				\$34,527.00	
			Construction	Stockpile STI	MI - Total			\$34,527.00	
	0570 -	Total						\$761.62	
	0580	MGS BRIDGE APP. TRANS SEC (EXT	Construction Stockpile		6	Nov 24, 2021	SYSTEM	(\$2,076.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		CURB)			9	Apr 4, 2022	SYSTEM	(\$4,152.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					12	May 16, 2022	SYSTEM	(\$8,304.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$14,532.00)	
			Construction	Stockpile - To	otal			(\$14,532.00)	
			Construction Stockpile STMI		1	Sep 15, 2021	SYSTEM	\$14,532.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$14,532.00	
			Construction	Stockpile STI	MI - Total			\$14,532.00	
	0580 -	Total						\$0.00	
	0590	MGS BRIDGE APP. TRANS	Construction Stockpile		6	Nov 24, 2021	SYSTEM	(\$5,934.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		SEC (REG/NO CURB)			9	Apr 4, 2022	SYSTEM	(\$3,956.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					12	May 16, 2022	SYSTEM	(\$3,956.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					14	Jun 16, 2022	SYSTEM	(\$1,978.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$15,824.00)	
			Construction	Stockpile - To	otal			(\$15,824.00)	
			Construction Stockpile STMI		1	Sep 15, 2021	SYSTEM	\$15,824.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			3 TIVIT	- Total				\$15,824.00	



Jun 18, 2022

last	Line	Description	A diverte ent	Other	Eat	Created	Created	Amount	Demerice
ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
494	0590	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction	Stockpile STI	MI - Total			\$15,824.00	
	0590 -	Total						\$0.00	
	0600	MGS HEIGHT AND BLOCK	Construction Stockpile		12	May 16, 2022	SYSTEM	(\$440.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		TRANSITION			14	Jun 16, 2022	SYSTEM	(\$440.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$880.00)	
			Construction	Stockpile - To	otal			(\$880.00)	
			Construction Stockpile STMI		1	Sep 15, 2021	SYSTEM	\$880.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			51111	- Total				\$880.00	
			Construction	Stockpile STI	MI - Total			\$880.00	
	0600 -	Total						\$0.00	
	0610	MGS END ANCHOR	Construction Stockpile		12	May 16, 2022	SYSTEM	(\$2,175.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$2,175.00)	
			Construction	Stockpile - To	otal			(\$2,175.00)	
			Construction Stockpile STMI		1	Sep 15, 2021	SYSTEM	\$2,175.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			51101	- Total				\$2,175.00	
			Construction	Stockpile STI	MI - Total			\$2,175.00	
	0610 -	Total						\$0.00	
	0620	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		9	Apr 4, 2022	SYSTEM	(\$10,650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)			12	May 16, 2022	SYSTEM	(\$3,550.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$14,200.00)	
			Construction	Stockpile - To	otal			(\$14,200.00)	
			Construction Stockpile STMI		1	Sep 15, 2021	SYSTEM	\$14,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$14,200.00	
			Construction	Stockpile STI	MI - Total			\$14,200.00	
	0620 - 0630	TYPE D	Construction		3	Oct 19,	SYSTEM	\$0.00 \$29,995.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		CRASHWORTHY END TERMINAL	Stockpile No Transaction Type	- Total		2021		\$29,995.00	
			Construction	Stockpile No	Transacti	on Type - `	Total	\$29,995.00	
	0630 -	Total						\$29,995.00	
	0720	MISC. REMOVALS	Material		3	Oct 19, 2021	SYSTEM	\$56,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dukesm1 overridding Payment
					3	Oct 19, 2021	SYSTEM	(\$56,000.00)	Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0720 -	Total	- Tota					\$0.00	
	0740	BRIDGE APPROACH	Material		3	Oct 19, 2021	SYSTEM	\$22,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment
		SLAB (MAJOR ROAD)			3	Oct 19, 2021	SYSTEM	(\$22,500.00)	Estimate Exception 5 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$45,000.00)	
					5	Nov 16, 2021	SYSTEM	(\$67,500.00)	
					6	Nov 24,	SYSTEM	(\$67,500.00)	
						· ·		/	



Jun 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
613494	0740	BRIDGE	Material			2021			
		APPROACH SLAB (MAJOR		- Total				(\$180,000.00)	
		ROAD)	Material - Tota	I				(\$180,000.00)	
			MaterialCredit		5	Nov 16, 2021	SYSTEM	\$45,000.00	
					6	Nov 24, 2021	SYSTEM	\$67,500.00	
					7	Dec 17, 2021	SYSTEM	\$67,500.00	
				- Total				\$180,000.00	
			MaterialCredit	- Total				\$180,000.00	
	0740 -	Total						\$0.00	
	0760	CLASS B-1 CONCRETE	Material		3	Oct 19, 2021	SYSTEM	\$20,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					3	Oct 19, 2021	SYSTEM	(\$20,000.00)	
					4	Nov 2, 2021	SYSTEM	(\$40,000.00)	
					5	Nov 16, 2021	SYSTEM	(\$40,000.00)	
				- Total				(\$80,000.00)	
			Material - Tota	1				(\$80,000.00)	
			MaterialCredit		5	Nov 16, 2021	SYSTEM	\$40,000.00	
					6	Nov 24, 2021	SYSTEM	\$40,000.00	
				- Total				\$80,000.00	
			MaterialCredit	- Total				\$80,000.00	
	0760 -	Total						\$0.00	
	0770	CLASS B-2 CONCRETE	Material		3	Oct 19, 2021	SYSTEM	\$21,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					3	Oct 19, 2021	SYSTEM	(\$21,640.00)	
					4	Nov 2, 2021	SYSTEM	(\$43,280.00)	
					5	Nov 16, 2021	SYSTEM	(\$43,280.00)	
				- Total	5	Nov 16,	SYSTEM	(\$43,280.00) (\$86,560.00)	
			Material - Tota		5	Nov 16,	SYSTEM		
			Material - Tota MaterialCredit		5	Nov 16,	SYSTEM	(\$86,560.00)	
						Nov 16, 2021 Nov 16,		(\$86,560.00) (\$86,560.00)	
					5	Nov 16, 2021 Nov 16, 2021 Nov 24,	SYSTEM	(\$86,560.00) (\$86,560.00) \$43,280.00	
				l - Total	5	Nov 16, 2021 Nov 16, 2021 Nov 24,	SYSTEM	(\$86,560.00) (\$86,560.00) \$43,280.00 \$43,280.00	
	0770 -	Total	MaterialCredit	l - Total	5	Nov 16, 2021 Nov 16, 2021 Nov 24,	SYSTEM	(\$86,560.00) (\$86,560.00) \$43,280.00 \$43,280.00 \$86,560.00	
	0770 - 0800	Total REINFORCING STEEL (EPOXY COATED)	MaterialCredit MaterialCredit	l - Total	5	Nov 16, 2021 Nov 16, 2021 Nov 24,	SYSTEM	(\$86,560.00) (\$86,560.00) \$43,280.00 \$43,280.00 \$86,560.00 \$86,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
		REINFORCING STEEL (EPOXY	MaterialCredit MaterialCredit	l - Total	5	Nov 16, 2021 Nov 16, 2021 Nov 24, 2021 Oct 19,	SYSTEM SYSTEM	(\$86,560.00) (\$86,560.00) \$43,280.00 \$43,280.00 \$86,560.00 \$86,560.00 \$0.00	Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment
		REINFORCING STEEL (EPOXY	MaterialCredit MaterialCredit	l - Total	5 6 3	Nov 16, 2021 Nov 16, 2021 Nov 24, 2021 Oct 19, Oct 19,	SYSTEM SYSTEM SYSTEM	(\$86,560.00) (\$86,560.00) \$43,280.00 \$43,280.00 \$86,560.00 \$86,560.00 \$80.00 \$3,339.00	Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment
		REINFORCING STEEL (EPOXY	MaterialCredit MaterialCredit	l - Total	5 6 3 3	Nov 16, 2021 Nov 16, 2021 Nov 24, 2021 Oct 19, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$86,560.00) (\$86,560.00) \$43,280.00 \$43,280.00 \$86,560.00 \$86,560.00 \$3,339.00 (\$3,339.00)	Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment
		REINFORCING STEEL (EPOXY	MaterialCredit MaterialCredit	- Total - Total	5 6 3 3	Nov 16, 2021 Nov 16, 2021 Nov 24, 2021 Oct 19, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$86,560.00) (\$86,560.00) \$43,280.00 \$43,280.00 \$86,560.00 \$86,560.00 \$3,339.00 (\$3,339.00) (\$6,678.00)	Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment
		REINFORCING STEEL (EPOXY	MaterialCredit MaterialCredit	- Total - Total	5 6 3 3	Nov 16, 2021 Nov 16, 2021 Nov 24, 2021 Oct 19, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$86,560.00) (\$86,560.00) \$43,280.00 \$43,280.00 \$86,560.00 \$86,560.00 \$3,339.00 (\$3,339.00) (\$6,678.00) (\$6,678.00)	Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment



Jun 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3494	0800	REINFORCING STEEL (EPOXY COATED)	MaterialCredit	- Total				\$6,678.00	
	0800 -	Total						\$0.00	
	0830	FIELD APPLICATION	Material		7	Dec 17, 2021	SYSTEM	(\$1,600.00)	
		OF INORGANIC ZINC			8	Jan 3, 2022	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Jan 3, 2022	SYSTEM	(\$1,600.00)	
					9	Apr 4, 2022	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Apr 4, 2022	SYSTEM	(\$1,600.00)	
				- Total				(\$1,600.00)	
			Material - Tota	I				(\$1,600.00)	
			MaterialCredit		8	Jan 3, 2022	SYSTEM	\$1,600.00	
				- Total				\$1,600.00	
			MaterialCredit	- Total				\$1,600.00	
	0830 -	Total			_			\$0.00	
	0870	VERTICAL DRAIN AT END BENTS	Material		3	Oct 19, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					3	Oct 19, 2021	SYSTEM	(\$1,750.00)	
				- Total				\$0.00	
			Material - Tota	I				\$0.00	
	0870 -							\$0.00	
	0890	OPEN CELL FOAM JOINT SEAL	Material		3	Oct 19, 2021	SYSTEM	\$1,681.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					3	Oct 19, 2021	SYSTEM	(\$1,681.50)	
					4	Nov 2, 2021	SYSTEM	(\$3,363.00)	
					5	Nov 16, 2021	SYSTEM	\$3,363.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$3,363.00)	
					6	Nov 24, 2021	SYSTEM	(\$3,363.00)	
					7	Dec 17, 2021	SYSTEM	(\$6,726.00)	
					8	Jan 3, 2022	SYSTEM	(\$6,726.00)	
					9	Apr 4, 2022	SYSTEM	(\$6,726.00)	
			Material Tate	- Total				(\$26,904.00)	
			Material - Tota		5	Nov 10	OVOTEM	(\$26,904.00)	
			MaterialCredit		5	Nov 16, 2021	SYSTEM	\$3,363.00	
					8	Dec 17, 2021 Jan 3,	SYSTEM	\$3,363.00	
					9	2022 Apr 4,	SYSTEM	\$6,726.00	
					10	Apr 4, 2022 Apr 18,	SYSTEM	\$6,726.00	
					10	2022	STOTLIN	ψυ, / 20.00	



Jun 18, 2022

	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
613494	0890	OPEN CELL	MaterialCredit	- Total				\$26,904.00	
		FOAM JOINT SEAL	MaterialCredit	- Total				\$26,904.00	
	0890 -	Total						\$0.00	
	0930	MISC. REMOVALS	Material		3	Oct 19, 2021	SYSTEM	\$69,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Oct 19, 2021	SYSTEM	(\$69,750.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0930 -	Total						\$0.00	
	0950	BRIDGE APPROACH SLAB (MAJOR	Material		3	Oct 19, 2021	SYSTEM	\$22,722.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		ROAD)			3	Oct 19, 2021	SYSTEM	(\$22,722.50)	
					4	Nov 2, 2021	SYSTEM	(\$45,445.00)	
					5	Nov 16, 2021	SYSTEM	(\$68,167.50)	
					6	Nov 24, 2021	SYSTEM	(\$68,167.50)	
				- Total				(\$181,780.00)	
			Material - Tota	al				(\$181,780.00)	
			MaterialCredit		5	Nov 16, 2021	SYSTEM	\$45,445.00	
					6	Nov 24, 2021	SYSTEM	\$68,167.50	
					7	Dec 17, 2021	SYSTEM	\$68,167.50	
				- Total				\$181,780.00	
			MaterialCredit	t - Total				\$181,780.00	
	0950 -	Total	MaterialCredit	t - Total				\$181,780.00 \$0.00	
	0950 - 0970	Total CLASS B-1 CONCRETE	MaterialCredit	t - Total	3	Oct 19, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
		CLASS B-1		t - Total	3 3		SYSTEM	\$0.00	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment
		CLASS B-1		- Total		2021 Oct 19,		\$0.00 \$20,500.00	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment
		CLASS B-1		- Total	3	2021 Oct 19, 2021 Nov 2,	SYSTEM	\$0.00 \$20,500.00 (\$20,500.00)	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment
		CLASS B-1		- Total	3	2021 Oct 19, 2021 Nov 2, 2021 Nov 16,	SYSTEM SYSTEM	\$0.00 \$20,500.00 (\$20,500.00) (\$41,000.00)	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment
		CLASS B-1		- Total	3	2021 Oct 19, 2021 Nov 2, 2021 Nov 16,	SYSTEM SYSTEM	\$0.00 \$20,500.00 (\$20,500.00) (\$41,000.00) (\$41,000.00)	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment
		CLASS B-1	Material	- Total	3	2021 Oct 19, 2021 Nov 2, 2021 Nov 16,	SYSTEM SYSTEM	\$0.00 \$20,500.00 (\$20,500.00) (\$41,000.00) (\$41,000.00) (\$82,000.00)	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment
		CLASS B-1	Material Material - Tota	- Total	3 4 5	2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 \$20,500.00 (\$20,500.00) (\$41,000.00) (\$41,000.00) (\$82,000.00) (\$82,000.00)	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment
		CLASS B-1	Material Material - Tota	- Total	3 4 5 5	2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Nov 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$20,500.00 (\$20,500.00) (\$41,000.00) (\$41,000.00) (\$82,000.00) \$41,000.00	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment
	0970	CLASS B-1 CONCRETE	Material Material - Tota	- Total	3 4 5 5	2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Nov 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$20,500.00 (\$20,500.00) (\$41,000.00) (\$41,000.00) (\$82,000.00) \$41,000.00 \$41,000.00	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment
		CLASS B-1 CONCRETE	Material Material - Tota MaterialCredit	- Total	3 4 5 5 6	2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Nov 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$20,500.00 (\$20,500.00) (\$41,000.00) (\$41,000.00) (\$82,000.00) \$41,000.00 \$41,000.00 \$41,000.00	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment
	0970	CLASS B-1 CONCRETE	Material Material - Tota MaterialCredit	- Total	3 4 5 5	2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Nov 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$20,500.00 (\$20,500.00) (\$41,000.00) (\$41,000.00) (\$82,000.00) \$41,000.00 \$41,000.00 \$82,000.00	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment
	0970 -	CLASS B-1 CONCRETE	Material - Tota MaterialCredit	- Total	3 4 5 5 6	2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021 Nov 24, 2021 Oct 19,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$20,500.00 (\$20,500.00) (\$41,000.00) (\$41,000.00) (\$82,000.00) \$41,000.00 \$41,000.00 \$41,000.00 \$82,000.00 \$82,000.00	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
	0970 -	CLASS B-1 CONCRETE	Material - Tota MaterialCredit	- Total	3 4 5 5 6 8	2021 Oct 19, 2021 Nov 2, 2021 Nov 16, 2021 Nov 24, 2021 Oct 19, Oct 19,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$20,500.00 (\$20,500.00) (\$41,000.00) (\$41,000.00) (\$82,000.00) \$41,000.00 \$41,000.00 \$41,000.00 \$41,000.00 \$22,350.00	Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate.



Jun 18, 2022

ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
94	0980	CLASS B-2	Material	- Total				(\$89,420.00)	
		CONCRETE	Material - Tota	I				(\$89,420.00)	
			MaterialCredit		5	Nov 16, 2021	SYSTEM	\$44,710.00	
					6	Nov 24, 2021	SYSTEM	\$44,710.00	
				- Total				\$89,420.00	
			MaterialCredit	- Total				\$89,420.00	
	0980 -	Total						\$0.00	
	1000	MECHANICAL BAR SPLICE	Material		3	Oct 19, 2021	SYSTEM	\$1,102.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					3	Oct 19, 2021	SYSTEM	(\$1,102.29)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	1000 -	Total						\$0.00	
	1010	REINFORCING STEEL (EPOXY COATED)	Material		3	Oct 19, 2021	SYSTEM	\$3,339.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user dukesm1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					3	Oct 19, 2021	SYSTEM	(\$3,339.00)	
					4	Nov 2, 2021	SYSTEM	(\$6,678.00)	
				- Total				(\$6,678.00)	
			Material - Tota	d				(\$6,678.00)	
			MaterialCredit		5	Nov 16, 2021	SYSTEM	\$6,678.00	
				- Total				\$6,678.00	
			MaterialCredit	- Total				\$6,678.00	
	1010 -	Total						\$0.00	
	1040	FIELD APPLICATION OF INORGANIC ZINC	Material		9	Apr 4, 2022	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		ZINC			9	Apr 4, 2022	SYSTEM	(\$1,600.00)	
				- Total				\$0.00	
			Material - Tota	d				\$0.00	
	1040 -	Total						\$0.00	
	1070	VERTICAL DRAIN AT END	Material		3	Oct 19, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user dukesm1 overridding Payment
		BENTS							Estimate Exception 44 on the current Payment Estimate.
		BENIS			3	Oct 19, 2021	SYSTEM	(\$1,750.00)	Estimate Exception 44 on the current Payment Estimate.
		BENTS		- Total	3		SYSTEM	(\$1,750.00) \$0.00	Estimate Exception 44 on the current Payment Estimate.
		BENTS	Material - Tota		3		SYSTEM		Estimate Exception 44 on the current Payment Estimate.
	1070 -		Material - Tota		3		SYSTEM	\$0.00	Estimate Exception 44 on the current Payment Estimate.
- 5	1070 - 1090				3		SYSTEM	\$0.00 \$0.00	Estimate Exception 44 on the current Payment Estimate.
- 5		Total OPEN CELL FOAM JOINT				2021 Oct 19,		\$0.00 \$0.00 \$0.00	Estimate Exception 44 on the current Payment Estimate.
		Total OPEN CELL FOAM JOINT			3	2021 Oct 19, 2021 Oct 19,	SYSTEM	\$0.00 \$0.00 \$0.00 \$1,681.50	Estimate Exception 44 on the current Payment Estimate.
- 5		Total OPEN CELL FOAM JOINT			3	2021 Oct 19, 2021 Oct 19, 2021 Nov 2,	SYSTEM	\$0.00 \$0.00 \$1,681.50 (\$1,681.50)	Estimate Exception 44 on the current Payment Estimate.
		Total OPEN CELL FOAM JOINT			3 3 4	2021 2021 2021 0ct 19, 2021 Nov 2, 2021 Nov 2, 2021 Nov 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,681.50 (\$1,681.50) (\$3,363.00)	Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user dukesm1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user dukesm1 overridding Payment



Jun 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1613494	1090	OPEN CELL FOAM JOINT SEAL	Material			2021			
					7	Dec 17, 2021	SYSTEM	(\$6,726.00)	
					8	Jan 3, 2022	SYSTEM	(\$6,726.00)	
					9	Apr 4, 2022	SYSTEM	(\$6,726.00)	
				- Total				(\$26,904.00)	
			Material - Tota	1				(\$26,904.00)	
			MaterialCredit		5	Nov 16, 2021	SYSTEM	\$3,363.00	
					7	Dec 17, 2021	SYSTEM	\$3,363.00	
					8	Jan 3, 2022	SYSTEM	\$6,726.00	
					9	Apr 4, 2022	SYSTEM	\$6,726.00	
					10	Apr 18, 2022	SYSTEM	\$6,726.00	
				- Total				\$26,904.00	
			MaterialCredit	- Total				\$26,904.00	
	1090 -							\$0.00	
	1120	MISC. REMOVALS	Material		11	May 2, 2022	SYSTEM	(\$47,500.00)	
				- Total				(\$47,500.00)	
			Material - Tota		40	N4 40	OVOTEN	(\$47,500.00)	
			MaterialCredit	Tetel	12	May 16, 2022	SYSTEM	\$47,500.00	
			MatarialOnadit	- Total				\$47,500.00 \$47,500.00	
	1120	MaterialCredit - Total 120 - Total							
	1140	CLASS B-2 CONCRETE	Material		11	May 2, 2022	SYSTEM	\$0.00 (\$12,000.00)	
				- Total				(\$12,000.00)	
			Material - Tota					(\$12,000.00)	
			MaterialCredit		12	May 16, 2022	SYSTEM	\$12,000.00	
				- Total				\$12,000.00	
			MaterialCredit	- Total				\$12,000.00	
	1140 -	Total						\$0.00	
	1160	HALF-SOLE REPAIR			12	May 16, 2022	SYSTEM	(\$27,555.00)	
					13	Jun 2, 2022	SYSTEM	(\$27,555.00)	
					14	Jun 16, 2022	SYSTEM	(\$27,555.00)	
				- Total				(\$82,665.00)	
			Material - Tota	1				(\$82,665.00)	
			MaterialCredit		13	Jun 2, 2022	SYSTEM	\$27,555.00	
					14	Jun 16, 2022	SYSTEM	\$27,555.00	
				- Total				\$55,110.00	
			MaterialCredit					\$55,110.00	
			Overrun	Overrun	12	May 16, 2022	SYSTEM	\$2,805.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 167.000; Overrun Quantity Balance 17.00.
					12	May 16,	SYSTEM	(\$2,805.00)	
								(+2,000.00)	



Contract ID:190215-D05

ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
94	1160	HALF-SOLE	Overrun	Overrun		2022			
		REPAIR			13	Jun 2, 2022	SYSTEM	(\$2,805.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					13	Jun 2, 2022	SYSTEM	\$2,805.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 167.000; Overrun Quantity Balance 17.00.
					14	Jun 16, 2022	SYSTEM	(\$2,805.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					14	Jun 16, 2022	SYSTEM	\$2,805.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 167.000; Overrun Quantity Balance 17.00.
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	1160 -	Total						(\$27,555.00)	
	1170	CLEANING AND EPOXY	Material		11	May 2, 2022	SYSTEM	(\$16,416.00)	
		COATING		- Total				(\$16,416.00)	
			Material - Tota	al				(\$16,416.00)	
			MaterialCredit		12	May 16, 2022	SYSTEM	\$16,416.00	
				- Total				\$16,416.00	
			MaterialCredit	- Total				\$16,416.00	
	1170 -	Total						\$0.00	
	1190	REINFORCING STEEL (EPOXY COATED)	Material		11	May 2, 2022	SYSTEM	(\$1,904.00)	
				- Total				(\$1,904.00)	
			Material - Total					(\$1,904.00)	
			MaterialCredit		12	May 16, 2022	SYSTEM	\$1,904.00	
				- Total				\$1,904.00	
			MaterialCredit	t - Total				\$1,904.00	
	1190 - 1230	GRAY EPOXY- MASTIC PRIMER	Material		11	May 2, 2022	SYSTEM	\$0.00 \$4,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user spurlt2 overridding Payment
					11	May 2,	SYSTEM	(\$4,900.00)	Estimate Exception 27 on the current Payment Estimate.
						2022			
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	1230 - 1290	MISC.	Material		9	Apr 4,	SYSTEM	\$0.00 (\$9,600.00)	
		REMOVALS			10	2022 Apr 18, 2022	SYSTEM	(\$19,200.00)	
					11	May 2, 2022	SYSTEM	(\$19,200.00)	
				- Total				(\$48,000.00)	
			Material - Tota						
			MaterialCredit		10	Apr 18, 2022	SYSTEM	(\$48,000.00) \$9,600.00	
					11	May 2, 2022	SYSTEM	\$19,200.00	
					12	May 16, 2022	SYSTEM	\$19,200.00	
								\$48,000.00	
				- Total				\$40,000.00	
			MaterialCredit					\$48,000.00	

21



Jun 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
613494	1310	CLASS B-2 CONCRETE	Material		10	Apr 18, 2022	SYSTEM	(\$29,480.00)	
					11	May 2, 2022	SYSTEM	(\$29,480.00)	
				- Total				(\$58,960.00)	
			Material - Tota	I				(\$58,960.00)	
			MaterialCredit		11	May 2, 2022	SYSTEM	\$29,480.00	
					12	May 16, 2022	SYSTEM	\$29,480.00	
				- Total				\$58,960.00	
			MaterialCredit	- Total				\$58,960.00	
	1310 -	Total						\$0.00	
	1350	MISC.	Material		10	Apr 18, 2022	SYSTEM	(\$4,400.00)	
					12	May 16, 2022	SYSTEM	(\$4,400.00)	
					13	Jun 2, 2022	SYSTEM	(\$4,400.00)	
				- Total				(\$13,200.00)	
			Material - Tota	1				(\$13,200.00)	
			MaterialCredit		11	May 2, 2022	SYSTEM	\$4,400.00	
					13	Jun 2, 2022	SYSTEM	\$4,400.00	
					14	Jun 16, 2022	SYSTEM	\$4,400.00	
				- Total				\$13,200.00	
			MaterialCredit - Total					\$13,200.00	
	1350 -							\$0.00	
	1360	REINFORCING STEEL (EPOXY COATED)	Material		9	Apr 4, 2022	SYSTEM	(\$1,360.00)	
					12	May 16, 2022	SYSTEM	(\$2,720.00)	
					13	Jun 2, 2022	SYSTEM	(\$2,720.00)	
					14	Jun 16, 2022	SYSTEM	(\$2,720.00)	
				- Total				(\$9,520.00)	
			Material - Tota		10		0)(0777)	(\$9,520.00)	
			MaterialCredit		10	Apr 18, 2022	SYSTEM	\$1,360.00	
					13	Jun 2, 2022 Jun 16,	SYSTEM	\$2,720.00	
				- Total	14	2022	STOTEM	\$6,800.00	
			MaterialCredit					\$6,800.00	
	1360 -	Total	MaterialCredit - Total					(\$2,720.00)	
	1390	FIELD APPLICATION OF INORGANIC ZINC	Material		8	Jan 3, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Jan 3, 2022	SYSTEM	(\$700.00)	Loumano Exception 5 on the current r dynnent Estimate.
					9	Apr 4, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user dukesm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Apr 4, 2022	SYSTEM	(\$700.00)	
				- Total				\$0.00	



Jun 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3494	1390	FIELD APPLICATION OF INORGANIC ZINC	Material - Tota					\$0.00	
	1390 -	Total						\$0.00	
	1430	PREFORMED COMPRESSION	Material		10	Apr 18, 2022	SYSTEM	(\$5,160.00)	
		SEAL			11	May 2, 2022	SYSTEM	(\$5,160.00)	
					12	May 16, 2022	SYSTEM	\$5,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user spurIt2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					12	May 16, 2022	SYSTEM	(\$5,160.00)	
					13	Jun 2, 2022	SYSTEM	\$5,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user peterr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					13	Jun 2, 2022	SYSTEM	(\$5,160.00)	
					14	Jun 16, 2022	SYSTEM	\$5,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					14	Jun 16, 2022	SYSTEM	(\$5,160.00)	
				- Total				(\$10,320.00)	
			Material - Tota					(\$10,320.00)	
			MaterialCredit		11	May 2, 2022	SYSTEM	\$5,160.00	
					12	May 16, 2022	SYSTEM	\$5,160.00	
				- Total				\$10,320.00	
			MaterialCredit - Total					\$10,320.00	
	1430 -	Total						\$0.00	
	1480	HALF-SOLE REPAIR	Material		13	Jun 2, 2022	SYSTEM	(\$4,900.00)	
					14	Jun 16, 2022	SYSTEM	(\$4,900.00)	
				- Total				(\$9,800.00)	
			Material - Total MaterialCredit	d				(\$9,800.00)	
					14	Jun 16, 2022	SYSTEM	\$4,900.00	
				- Total				\$4,900.00	
		MaterialCredit - Total						\$4,900.00	
	1480 -							(\$4,900.00)	
	1500	MISC.	Material		13	Jun 2, 2022	SYSTEM	(\$1,700.00)	
				- Total				(\$1,700.00)	
			Material - Tota	I				(\$1,700.00)	
			MaterialCredit		14	Jun 16, 2022	SYSTEM	\$1,700.00	
				- Total				\$1,700.00	
			MaterialCredit	- Total				\$1,700.00	
	1500 -	Total						\$0.00	
	1530	PREFORMED COMPRESSION SEAL	Material		13	Jun 2, 2022	SYSTEM	\$8,585.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user spurIt2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					13	Jun 2, 2022	SYSTEM	(\$8,585.00)	
					14	Jun 16, 2022	SYSTEM	\$8,585.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user dukesm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.



Jun 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3494	1530	PREFORMED COMPRESSION	Material		14	Jun 16, 2022	SYSTEM	(\$8,585.00)	
		SEAL		- Total				\$0.00	
			Material - Tota	I				\$0.00	
	1530 -	Total						\$0.00	
	1560	MISC. REMOVALS	Material		11	May 2, 2022	SYSTEM	(\$15,000.00)	
					12	May 16, 2022	SYSTEM	(\$15,000.00)	
					13	Jun 2, 2022	SYSTEM	(\$15,000.00)	
					14	Jun 16, 2022	SYSTEM	(\$15,000.00)	
				- Total				(\$60,000.00)	
			Material - Tota	I				(\$60,000.00)	
			MaterialCredit		12	May 16, 2022	SYSTEM	\$15,000.00	
					13	Jun 2, 2022	SYSTEM	\$15,000.00	
					14	Jun 16, 2022	SYSTEM	\$15,000.00	
				- Total				\$45,000.00	
			MaterialCredit	- Total				\$45,000.00 (\$15,000.00)	
		1560 - Total							
	1580	CLASS B-2 CONCRETE	Material		11	May 2, 2022	SYSTEM	(\$16,400.00)	
				- Total				(\$16,400.00)	
			Material - Tota	I				(\$16,400.00)	
			MaterialCredit		12	May 16, 2022	SYSTEM	\$16,400.00	
				- Total				\$16,400.00	
			MaterialCredit	- Total				\$16,400.00	
	1580 -							\$0.00	
	1600	REINFORCING STEEL (EPOXY COATED)	Material		11	May 2, 2022	SYSTEM	(\$1,225.00)	
				- Total				(\$1,225.00)	
			Material - Tota					(\$1,225.00)	
			MaterialCredit		12	May 16, 2022	SYSTEM	\$1,225.00	
				- Total				\$1,225.00	
			MaterialCredit	- Total				\$1,225.00	
	1600 -	Total						\$0.00	
J6I3494 -								(\$33,710.67)	
Overall -	Total							(\$33,710.67)	