

Pay Estimate Created Date: September 2, 2022

Progress Estimate Number	Contract ID	211015-C03	Pay Period Start	August 16, 2022	<b>Original Contract Amount</b>	\$5,861,477.94
12	Prime Contractor	Pyramid Contractors, Inc.	Pay Period End	September 1, 2022	Net Change Order Amount	. ,
					Current Contract Amount	\$5,894,396.05

Approval Date		By User
September 2, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	vohsr1
September 2, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	kneibr1
September 6, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
February 18, 2023	February 18, 2023		85.26%

#### **Contract Informational Dates**

Date Description	Original Completion Date	Current Completion Date	Date Description	
Acceptance Date			Milestone - Calendar Time - Day Count	
Awarded Date	November 3, 2021	November 3, 2021	Milestone - Calendar Time - Phase 2	
Letting Date	October 15, 2021	October 15, 2021	Milestone - Completion Date -	
Notice to Proceed Date	January 3, 2022	January 3, 2022	Phase 2 Incentive	
Open to Traffic Date				
Work Began Date	March 28, 2022	March 28, 2022		

Milestones									
Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days					
Milestone - Calendar Time - Day Count	January 20, 2023	January 20, 2023	136						
Milestone - Calendar Time - Phase 2	September 14, 2022	September 14, 2022	8						
Milestone - Completion Date - Phase 2 Incentive	October 15, 2022	October 15, 2022	39						

#### Contract Total Pay For Estimate No. 12 This Estimate Previous To Date 211015-C03 \$4,696,339.60 \$75,061.56 \$0.00 \$5,025,400.57 \$75,061.56 \$0.00 Total Posted Items Pay \$329,060.97 **\$0.00 \$0.00** Gross Item Adjustments Incentive \$0.00 \$0.00 \$0.00 Disincentive Liquidated Damage \$0.00 \$0.00 \$0.00 Other Contract Adjustments \$0.00 \$0.00 \$0.00 \$4,771,401.16 \$5,100,462.13 **Contract Total Payable This Estimate:** \$329,060.97

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3009	0010	2013000	CLEARING AND GRUBBING	ACRE	\$5,500.000	1	\$5,500.00
	0070	2063000	CLASS 3 EXCAVATION	CUYD	\$12.000	30	\$360.00
	0170	4071005	TACK COAT	GAL	\$2.500	213	\$532.50
	0260	6097000	ROCK LINING	CUYD	\$85.000	12	\$1,020.00
	0500	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$6.250	1,965	\$12,281.25
	0550	7261018	18 IN. PIPE GROUP A	LF	\$110.000	18	\$1,980.00
	0570	7261030	30 IN. PIPE GROUP A	LF	\$160.000	19	\$3,040.00
	0580	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	EA	\$1,500.000	1	\$1,500.00
	0600	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	EA	\$1,850.000	2	\$3,700.00
	0650	8061016	SEDIMENT REMOVAL	CUYD	\$20.000	10	\$200.00
	0750	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$75.000	150	\$11,250.00
	0770	9031010	CONCRETE FOOTINGS, EMBEDDED	CUYD	\$1,300.000	0.56	\$728.00

Revision 4/1/2020 Page 1 of 45



Pay Estimate Created Date: September 2, 2022

Progress	Estimate 12	Number	Contract ID 211015-C03 Pay Period Start Augus Prime Contractor Pyramid Contractors, Inc. Pay Period End Septe		22 Net Chang	e Order Amour	t \$5,861,477.94 ht \$32,918.11 \$5,894,396.05
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed
J4P3009	0780	9031210	STRUCTURAL STEEL POSTS	LB	\$4.250	564.75	\$2,400.19
	1060	7034221	SLAB ON CONCRETE NU-GIRDER	SQYD	\$398.000	60.4	\$24,039.20
Project J4F	2 <mark>3009 - To</mark>	tal					\$68,531.14
J4P3009B	1480	2022010	REMOVAL OF IMPROVEMENTS	LS \$85,000.000 0.2		0.25	\$21,250.0
	1520	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$17.000	268	\$4,556.0
	1530	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$16.000	265	\$4,240.0
	1540	4019905	MISC.OPTIONAL PAVEMENT - CHIPMAN	SQYD	\$192.000	251	\$48,192.0
	1600	6081000	CONCRETE MEDIAN	SQYD	\$65.550	342.8	\$22,470.5
	1650	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$34.650	545	\$18,884.2
	1700	6099903	MISC.CURB AND GUTTER TYPE CG-1	LF	\$30.900	242	\$7,477.8
	1940	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$3.000	12,278	\$36,834.0
	2110	9011010	RELOCATED POLE	EA	\$800.000	4	\$3,200.0
	2180	9016110	PULL BOX, PREFORMED CLASS 1	EA	\$355.000	2	\$710.0
	2200	9017008	CABLE, 8 AWG 1 CONDUCTOR	LF	\$2.500	309	\$772.5
	2250	9019902	MISC.LUMINAIRE, LED-A WALL PACK (INCLUDING HOUSING)	EA	\$1,200.000	2	\$2,400.0
	2270	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	LF	\$25.000	319	\$7,975.0
	2320	9020833	SH-FLAT SHEET - SIGNAL SIGN	SQFT	\$80.000	42	\$3,360.0
	2330	9020834	SIGNAL SIGN, MOUNTING HARDWARE	EA	\$60.000	21	\$1,260.0
	2360	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	EA	\$15,000.000	1	\$15,000.0
	2390	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$17.500	162	\$2,835.0
	2410	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	LF	\$32.000	475	\$15,200.0
	2420	9028308	CABLE, 16 AWG 2 CONDUCTOR	LF	\$1.500	1,970	\$2,955.0
	2430	9028310	CABLE, 16 AWG 5 CONDUCTOR	LF	\$2.000	1,990	\$3,980.0
	2440	9028311	CABLE, 16 AWG 7 CONDUCTOR	LF	\$2.500	1,335	\$3,337.5
	2450	9028811	PULL BOX, PREFORMED CLASS 2	EA	\$1,750.000	8	\$14,000.0
	2470	9029100	BASE, CONCRETE	CUYD	\$2,500.000	5.2	\$13,000.0
	5013	9029901	MISC.PULL BOX HEIGHT ADJUSTMENT	LS	\$1,001.740	1	\$1,001.7
	5014	9039902	MISC.SIGN RELOCATION	EA	\$246.750	6	\$1,480.5
	5015	9019902	MISC.PULL BOX REMOVAL AND REPLACEMENT	EA	\$2,079.000	2	\$4,158.0
roject J4F	<mark>23009В - Т</mark>	otal					\$260,529.8
Overall - To	otal						\$329,060.9

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item A	<u>djustm</u>	ents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3009	0040	EMBANKMENT IN PLACE	Material			-3,626	\$20.00	(\$72,520.00)
	0040	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	3,626	\$20.00	\$72,520.00
	0050	COMPACTING EMBANKMENT	Material			-5,294	\$2.50	(\$13,235.00)
	0050	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	5,294	\$2.50	\$13,235.00

Revision 4/1/2020 Page 2 of 45



Pay Estimate Created Date: September 2, 2022

Progress Estimate Number
12

Contract ID 211015-C03 Pay Period Start August 16, 2022 Original Contract Amount \$5,861,477.94
Prime Contractor Pyramid Contractors, Inc. Pay Period End September 1, 2022 Original Contract Amount \$32,918.11
Current Contract Amount \$5,894,396.05

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
4P3009					Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
	0060	COMPACTING IN CUT	Material			-32	\$350.00	(\$11,200.00
	0060	COMPACTING IN CUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	32	\$350.00	\$11,200.00
	0180	CONCRETE APPROACH PAVEMENT	Material			-379.8	\$108.60	(\$41,246.28
	0180	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	379.8	\$108.60	\$41,246.28
	0210	MODIFIED CONCRETE GUTTER TYPE B	Material			-490	\$48.00	(\$23,520.00)
	0210	MODIFIED CONCRETE GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	490	\$48.00	\$23,520.00
	0220	MISC.	Material			-331	\$135.00	(\$44,685.00
	0220	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	331	\$135.00	\$44,685.00
	0370	CONCRETE TRAFFIC BARRIER, TYPE C	Material			-177	\$200.00	(\$35,400.00
	0370	CONCRETE TRAFFIC BARRIER, TYPE C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	177	\$200.00	\$35,400.00
	0520	SEPARATION GEOTEXTILE	Material			-838	\$4.50	(\$3,771.00
	0520	SEPARATION GEOTEXTILE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	838	\$4.50	\$3,771.00
	0690	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material			-1,438	\$31.50	(\$45,297.00)
	0690	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	1,438	\$31.50	\$45,297.00
	0700	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Material			-5	\$3,000.00	(\$15,000.00)
	0700	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	5	\$3,000.00	\$15,000.00
	0710	MGS END ANCHOR	Material			-1	\$950.00	(\$950.00)

Revision 4/1/2020 Page 3 of 45



Pay Estimate Created Date: September 2, 2022

Progress Estimate Number
12 Contract ID 211015-C03 Pay Period Start August 16, 2022 Original Contract Amount Spetember 1, 2022 Pay Period End September 1, 2022 Original Contract Amount Spetember 2, 2022 Original Contract Amount Spetember 2,

oject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
<sup>2</sup> 3009	0710	MGS END ANCHOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1	\$950.00	\$950.00
	0720	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material			-4	\$2,700.00	(\$10,800.00
	0720	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	4	\$2,700.00	\$10,800.00
	0730	MISC.	Material			-4	\$5,000.00	(\$20,000.00
	0730	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	4	\$5,000.00	\$20,000.00
	0740	MISC.	Material			-1,256	\$24.00	(\$30,144.00
	0740	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	1,256	\$24.00	\$30,144.00
	0750	SUBSTRUCTURE REPAIR (FORMED)	Material			-150	\$75.00	(\$11,250.00
	0750	SUBSTRUCTURE REPAIR (FORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 60 on the current Payment Estimate.	150	\$75.00	\$11,250.00
	0770	CONCRETE FOOTINGS, EMBEDDED	Material			-0.56	\$1,300.00	(\$728.00
	0770	CONCRETE FOOTINGS, EMBEDDED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 72 on the current Payment Estimate.	0.56	\$1,300.00	\$728.00
	0840	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	Material			-1	\$8,500.00	(\$8,500.00
	0840	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 74 on the current Payment Estimate.	1	\$8,500.00	\$8,500.00
	0960	BRIDGE APPROACH SLAB (MAJOR)	Material			-182	\$249.10	(\$45,336.20
	0960	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	182	\$249.10	\$45,336.20
	0970	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material			-52	\$985.00	(\$51,220.00)
	0970	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	52	\$985.00	\$51,220.00

Revision 4/1/2020 Page 4 of 45



Pay Estimate Created Date: September 2, 2022

Progress Estimate Number
12

Contract ID 211015-C03 Pay Period Start August 16, 2022 Original Contract Amount September 1, 2022 Prime Contractor Pyramid Contractors, Inc. Pay Period End September 1, 2022 Current Contract Amount September 2, 2022 Current Contract Amount September 2,

ect	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
009	0980	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material			-32	\$642.00	(\$20,544.00
	0980	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.	32	\$642.00	\$20,544.00
	1040	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-93.4	\$860.00	(\$80,324.00
	1040	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.	93.4	\$860.00	\$80,324.00
	1050	TYPE D BARRIER	Material			-306	\$170.00	(\$52,020.00
	1050	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	306	\$170.00	\$52,020.00
	1060	SLAB ON CONCRETE NU- GIRDER	Material			-604	\$398.00	(\$240,392.00
	1060	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	604	\$398.00	\$240,392.00
	1200	BRIDGE APPROACH SLAB (MAJOR)	Material			-182	\$249.10	(\$45,336.20
	1200	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	182	\$249.10	\$45,336.20
	1210	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material			-44	\$985.00	(\$43,340.00
	1210	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 42 on the current Payment Estimate.	44	\$985.00	\$43,340.00
	1220	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material			-32	\$642.00	(\$20,544.00
	1220	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 46 on the current Payment Estimate.	32	\$642.00	\$20,544.00
	1280	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-92.1	\$870.00	(\$80,127.00
	1280	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	92.1	\$870.00	\$80,127.00
	1290	TYPE D BARRIER	Material			-306	\$170.00	(\$52,020.00
	1290	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 54	306	\$170.00	\$52,020.00

Revision 4/1/2020 Page 5 of 45



Pay Estimate Created Date: September 2, 2022

Progress Estimate Number
12 Contract ID 211015-C03 Pay Period Start August 16, 2022 Original Contract Amount Spetember 1, 2022 Pay Period End September 1, 2022 Original Contract Amount Spetember 2, 2022 Original Contract Amount Spetember 2,

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3009					on the current Payment Estimate.			
	1300	SLAB ON CONCRETE NU- GIRDER	Material			-604	\$398.00	(\$240,392.00
	1300	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 58 on the current Payment Estimate.	604	\$398.00	\$240,392.00
	1440	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-3,786	\$74.00	(\$280,164.00)
	1440	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 61 on the current Payment Estimate.	3,786	\$74.00	\$280,164.00
	1470	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-3,422	\$75.00	(\$256,650.00)
	1470	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 63 on the current Payment Estimate.	3,422	\$75.00	\$256,650.00
J4P3009B	1520	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-268	\$17.00	(\$4,556.00)
	1520	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	268	\$17.00	\$4,556.00
	1530	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-434	\$16.00	(\$6,944.00)
	1530	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	434	\$16.00	\$6,944.00
	1600	CONCRETE MEDIAN	Material			-342.8	\$65.55	(\$22,470.54)
	1600	CONCRETE MEDIAN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	342.8	\$65.55	\$22,470.54
	1640	CONCRETE SIDEWALK, 4 IN.	Material			-404	\$38.55	(\$15,574.20)
	1640	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	404	\$38.55	\$15,574.20
	1650	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-896	\$34.65	(\$31,046.40)
	1650	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	896	\$34.65	\$31,046.40
	1660	CURB AND GUTTER TYPE B	Material			-563	\$35.05	(\$19,733.15)

Revision 4/1/2020 Page 6 of 45



Pay Estimate Created Date: September 2, 2022

Progress Estimate Number
12

Contract ID 211015-C03 Pay Period Start August 16, 2022 Original Contract Amount \$5,861,477.94
Prime Contractor Pyramid Contractors, Inc. Pay Period End September 1, 2022 Current Contract Amount \$32,918.11
September 1, 2022 Current Contract Amount \$5,894,396.05

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3009B	1660	CURB AND GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0037) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	563	\$35.05	\$19,733.15
	1700	MISC.	Material			-242	\$30.90	(\$7,477.80)
	1700	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0038) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	242	\$30.90	\$7,477.80
	2250	MISC.	Material			-4	\$1,200.00	(\$4,800.00)
	2250	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user vohsr1 overridding Payment Estimate Exception 65 on the current Payment Estimate.	4	\$1,200.00	\$4,800.00
	2320	SH-FLAT SHEET - SIGNAL SIGN	Material			-42	\$80.00	(\$3,360.00)
	2320	SH-FLAT SHEET - SIGNAL SIGN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0040) due to user vohsr1 overridding Payment Estimate Exception 67 on the current Payment Estimate.	42	\$80.00	\$3,360.00
	2360	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material			-1	\$15,000.00	(\$15,000.00)
	2360	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user vohsr1 overridding Payment Estimate Exception 68 on the current Payment Estimate.	1	\$15,000.00	\$15,000.00
	2470	BASE, CONCRETE	Material			-5.2	\$2,500.00	(\$13,000.00)
	2470	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0042) due to user vohsr1 overridding Payment Estimate Exception 70 on the current Payment Estimate.	5.2	\$2,500.00	\$13,000.00
	5013	MISC.	Material			-1	\$1,001.74	(\$1,001.74)
	5013	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0045) due to user vohsr1 overridding Payment Estimate Exception 71 on the current Payment Estimate.	1	\$1,001.74	\$1,001.74
	5014	MISC.	Material			-6	\$246.75	(\$1,480.50)
	5014	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0043) due to user vohsr1 overridding Payment Estimate Exception 73 on the current Payment Estimate.	6	\$246.75	\$1,480.50
	5015	MISC.	Material			-2	\$2,079.00	(\$4,158.00)
	5015	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0044) due to user vohsr1 overridding Payment Estimate Exception 66 on the current Payment Estimate.	2	\$2,079.00	\$4,158.00
Total					•			\$0.00

Revision 4/1/2020 Page 7 of 45



						Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3009	FAF 50-1(54)	Bridge replacement	50	JACKSON	over Chipman Road nea	ar Lee's Summit	
J4P3009B	FAF 50-1(55)	Grading and paving	50	JACKSON	from w/o Murray Road t	o w/ Blue Parkway	
Totals by Jo	b Number	s					
J4P3009		l Item Pay Item Adjustme		Item Pay	This Estimate \$68,531.14 \$0.00 \$68,531.14	Previous \$4,349,393.60 \$66,736.11 <b>\$4,416,129.71</b>	To Date \$4,417,924.74 \$66,736.11 \$4,484,660.85
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J4P3009B		l Item Pay Item Adjustme		Item Pay	This Estimate \$260,529.83 \$0.00 \$260,529.83	Previous \$346,946.00 \$8,325.45 \$355,271.45	To Date \$607,475.83 \$8,325.45 \$615,801.28
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 8 of 45



**Exceptions (Discrepancies) This Estimate Period** 

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Waiting on contractor QC testing results for soil compaction.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Waiting on contractor QC testing results for soil compaction.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 2037075, Project Item Line Number 0060, Material Set 203707596, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Waiting on contractor QC testing results for soil compaction.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 3040504, Project Item Line Number 1520, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting for base rock compaction results	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 3040506, Project Item Line Number 1530, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting for Base rock compaction results.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5031010A, Project Item Line Number 0960, Material Set 5031010A96, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5031010A, Project Item Line Number 0960, Material Set 5031010A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5031010A, Project Item Line Number 0960, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 Day Break Test Results	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5031010A, Project Item Line Number 1200, Material Set 5031010A96, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5031010A, Project Item Line Number 1200, Material Set 5031010A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5041000, Project Item Line Number 0180, Material Set 504100096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5041000, Project Item Line Number 0180, Material Set 504100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5041000, Project Item Line Number 0180, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL for reinforcing steel	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6061061, Project Item Line Number 0690, Material Set 606106196, Material 1040GRSRCAT1 - Steel Beam for Class A Type 1 Guard Rail, Acceptance Action Generic 1040GRSRCAT1 is insufficient.	Waiting for guardrail shipping reports.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6061069, Project Item Line Number 0700, Material Set 606106996, Material 1040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient.	Waiting for guardrail shipping reports.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6061080, Project Item Line Number 0710, Material Set 606108096, Material 1040GRBEESCAT2 - Breakaway End Anchor End Sect Cl A Typ 2, Acceptance Action Generic 1040GRBEESCAT2 is insufficient.	Waiting for guardrail shipping reports.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6063014, Project Item Line Number 0720, Material Set 606301496, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient.	Waiting for guardrail shipping reports.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6069902, Project Item Line Number 0730, Material Set 6069902, Material 1040GUAAZC - Guard Cable Galv Anchor Assembly, Acceptance Action Generic 1040GUAAZC is insufficient.	Waiting for guard cable shipping reports.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6069903, Project Item Line Number 0740, Material Set 606990396, Material 1040GUCBZC - Guard Cable Galvanized, Acceptance Action Generic 1040GUCBZC is insufficient.	Waiting for guard cable shipping reports.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6071102, Project Item Line Number 0210, Material Set 607110296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6071102, Project Item Line Number 0210, Material Set 607110296, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6079903, Project Item Line Number 0220, Material Set 6079903, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6081000, Project Item Line Number 1600, Material Set 608100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6081000, Project Item Line Number 1600, Material Set 608100096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden

Revision 4/1/2020 Page 9 of 45



**Exceptions (Discrepancies) This Estimate Period** 

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Action Generic 1005GDCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6081000, Project Item Line Number 1600, Material Set 608100096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 Day Break Test Results	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6086004, Project Item Line Number 1640, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6086004, Project Item Line Number 1640, Material Set 608600496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6086004, Project Item Line Number 1640, Material Set 608600496, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting for 28 day breaks.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6091010, Project Item Line Number 1650, Material Set 609101096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6091010, Project Item Line Number 1650, Material Set 609101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6091010, Project Item Line Number 1650, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day breaks.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6091052, Project Item Line Number 1660, Material Set 609105296, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6091052, Project Item Line Number 1660, Material Set 609105296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6099903, Project Item Line Number 1700, Material Set 6099903, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6099903, Project Item Line Number 1700, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6099903, Project Item Line Number 1700, Material Set 6099903, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 Day breaks	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6173000, Project Item Line Number 0370, Material Set 617300096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6173000, Project Item Line Number 0370, Material Set 617300096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6240104A, Project Item Line Number 0520, Material Set 6240104A96, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient.	Waiting for Geotextile Cert	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 0970, Material Set 701110696, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 0970, Material Set 701110696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 1210, Material Set 701110696, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 1210, Material Set 701110696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 0980, Material Set 701120596, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 0980, Material Set 701120596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 1220, Material Set 701120596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 1220, Material Set 701120596, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number	Waiting for QC concrete aggregate tests	vohsr1	Overridden
		_	

Revision 4/1/2020 Page 10 of 45



**Exceptions (Discrepancies) This Estimate Period** 

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
1040, Material Set 703200396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1040, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1280, Material Set 703200396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1280, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034219A, Project Item Line Number 1050, Material Set 7034219A96, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034219A, Project Item Line Number 1050, Material Set 7034219A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034219A, Project Item Line Number 1290, Material Set 7034219A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034219A, Project Item Line Number 1290, Material Set 7034219A96, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1060, Material Set 703422196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1060, Material Set 703422196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1300, Material Set 703422196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1300, Material Set 703422196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7040101, Project Item Line Number 0750, Material Set 704010196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 Day breaks.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1440, Material Set 720100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1440, Material Set 720100096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1470, Material Set 720100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1470, Material Set 720100096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting for QC concrete aggregate tests	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 9019902, Project Item Line Number 2250, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 9019902, Project Item Line Number 5015, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 9020833, Project Item Line Number 2320, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 9023250, Project Item Line Number 2360, Material Set 902325096, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 9023250, Project Item Line Number 2360, Material Set 902325096, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 9029100, Project Item Line Number 2470, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 9029901, Project Item Line Number 5013, Material Set 9029901, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden

Revision 4/1/2020 Page 11 of 45



### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031010, Project Item Line Number 0770, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 Day Breaks.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 9039902, Project Item Line Number 5014, Material Set 9039902, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9103714, Project Item Line Number 0840, Material Set 910371496, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden

Revision 4/1/2020 Page 12 of 45



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amo Description	Bid Quantity	Net Change	Total Current	Unit	Total Posted	Unit Price	Total Value POSTED To Date (See report
							Order	Quantity		Approved Qty		generated date)
211015-C03	J4P3009	0001	0010	2013000	CLEARING AND GRUBBING	5.00	0.00	5.00	ACRE	2.50	\$5,500.00	\$13,750.0
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$250,000.00	\$250,000.0
		0001	0030	2031000	CLASS A EXCAVATION	6,088.00	0.00	6,088.00	CUYD	6,088.00	\$17.00	\$103,496.0
		0001	0040	2035500	EMBANKMENT IN PLACE	3,626.00	0.00	3,626.00	CUYD	3,626.00	\$20.00	\$72,520.0
		0001	0050	2036000	COMPACTING EMBANKMENT	5,294.00	0.00	5,294.00	CUYD	5,294.00	\$2.50	\$13,235.0
		0001	0060	2037075	COMPACTING IN CUT	32.00	0.00	32.00	STA	32.00	\$350.00	\$11,200.0
		0001	0070	2063000	CLASS 3 EXCAVATION	117.00	0.00	117.00	CUYD	117.00	\$12.00	\$1,404.0
		0001	0080	2063500	CULVERT CLEANOUT	3.00	0.00	3.00	EA	0.00	\$2,000.00	\$0.0
		0001	0090	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,718.00	38.00	1,756.00	SQYD	1,756.00	\$16.50	\$28,974.0
		0001	0100	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	466.00	0.00	466.00	SQYD	466.00	\$15.00	\$6,990.0
		0001	0110	3049905	MISC.OPTIONAL BASE	11,716.00	0.00	11,716.00	SQYD	11,716.00	\$11.00	\$128,876.0
		0001	0120	4010150	TYPE A2 SHOULDER	2,721.10	0.00	2,721.10	SQYD	2,721.10	\$27.00	\$73,469.7
		0001	0130	4019905	MISC.CHIPMAN ROAD OPTIONAL PAVEMENT	466.00	0.00	466.00	SQYD	466.00	\$100.00	\$46,600.0
		0001	0140	4019905	MISC.RAMP OPTIONAL PAVEMENT	1,718.00	38.00	1,756.00	SQYD	1,756.00	\$60.00	\$105,360.0
		0001	0150	4019905	MISC.US-50 OPTIONAL PAVEMENT	8,995.00	0.00	8,995.00	SQYD	8,995.00	\$52.00	\$467,740.0
		0001	0160	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	421.70	0.00	421.70	TONS	421.70	\$115.00	\$48,495.5
		0001	0170	4071005	TACK COAT	213.00	0.00	213.00	GAL	213.00	\$2.50	\$532.5
		0001	0180	5041000	CONCRETE APPROACH PAVEMENT	379.80	0.00	379.80	SQYD	379.80	\$108.60	\$41,246.2
		0001	0190	6044011	PIPE COLLAR, TYPE A	3.00	0.00	3.00	EA	3.00	\$1,100.00	\$3,300.0
		0001	0200	6064500	AGGREGATE BEDDING FOR 3 - STRAND GUARD CABLE	93.00	0.00	93.00	CUYD	93.00	\$40.00	\$3,720.0
		0001	0210	6071102	MODIFIED CONCRETE GUTTER TYPE B	490.00	0.00	490.00	LF	490.00	\$48.00	\$23,520.0
		0001	0220	6079903	MISC.ORNAMENTAL PEDESTRIAN FENCE (48") (RETAINING	331.00	0.00	331.00	LF	331.00	\$135.00	\$44,685.0
			0000	0004000	WALLS)		0.00	0.00	001/0	0.00	******	
		0001	0230	6081000	CONCRETE MEDIAN	2.80	0.00	2.80	SQYD	0.00	\$399.25	\$0.0
		0001	0240	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	34.00	0.00	34.00	CUYD	0.00	\$65.00	\$0.0
		0001	0250	6096041	PLACING TYPE 1 ROCK DITCH LINER	34.00	0.00	34.00	CUYD	0.00	\$60.00	\$0.0
		0001	0260	6097000	ROCK LINING	15.00	0.00	15.00	CUYD	15.00	\$85.00	\$1,275.0
		0001	0270	6113010	FURNISHING TYPE 1 ROCK BLANKET	143.00	0.00	143.00	CUYD	143.00	\$65.00	\$9,295.0
		0001	0280	6113030	PLACING TYPE 1 ROCK BLANKET	143.00	0.00	143.00	CUYD	143.00	\$20.00	\$2,860.0
		0001	0290	6161005	CONSTRUCTION SIGNS	1,610.00	0.00	1,610.00	SQFT	1,610.00	\$6.50	\$10,465.0
		0001	0300	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	0.00	8.00	EA	8.00	\$100.00	\$800.0
		0001	0310	6161025	CHANNELIZER (TRIM LINE)	222.00	0.00	222.00	EA	222.00	\$31.00	\$6,882.0
		0001	0320	6161030	TYPE III MOVEABLE BARRICADE	50.00	0.00	50.00	EA	50.00	\$185.00	\$9,250.0
		0001	0330	6161033	DIRECTIONAL INDICATOR BARRICADE	37.00	0.00	37.00	EA	14.00	\$135.00	\$1,890.0
		0001	0340	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.0
		0001	0350	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$9,500.00	\$19,000.0
		0001	0360	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.0
		0001	0370	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	177.00	0.00	177.00	LF	177.00	\$200.00	\$35,400.0
		0001	0380	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$195,000.00	\$0.0
		0001	0381	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$141,674.00	\$141,674.0
		0001	0390	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.0
		0001	0400	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	168.00	0.00	168.00	LF	0.00	\$20.00	\$0.0
		0001	0410	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	16.00	0.00	16.00	EA	0.00	\$250.00	\$0.0
		0001	0420	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	13,609.00	-13,609.00	0.00	LF	0.00	\$1.55	\$0.0
		0001	0430	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	13,273.00	-13,273.00	0.00	LF	0.00	\$1.55	\$0.0
		0001	0440	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	8.00	0.00	8.00	EA	0.00	\$115.00	\$0.0

Revision 4/1/2020 Page 13 of 45



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
11015-C03	J4P3009	0001	0450	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	15,875.00	0.00	15,875.00	LF	0.00	\$0.55	\$0.0
		0001	0460	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	11,706.00	0.00	11,706.00	LF	0.00	\$0.55	\$0.0
		0001	0470	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,840.00	0.00	1,840.00	LF	0.00	\$0.90	\$0.0
		0001	0480	6207001	PAVEMENT MARKING REMOVAL	2,376.00	0.00	2,376.00	LF	2,376.00	\$0.55	\$1,306.8
		0001	0490	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	16.00	0.00	16.00	EA	16.00	\$55.00	\$880.0
		0001	0500	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,646.00	0.00	2,646.00	SQYD	2,646.00	\$6.25	\$16,537.5
		0001	0510	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	319.00	0.00	319.00	SQYD	215.00	\$5.00	\$1,075.0
		0001	0520	6240104A	SEPARATION GEOTEXTILE	838.00	0.00	838.00	SQYD	838.00	\$4.50	\$3,771.0
		0001	0530	6269909	MISC.OPTIONAL PAVEMENT RUMBLE STRIP	56.60	0.00	56.60	STA	56.60	\$158.85	\$8,990.9
		0001	0540	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.
		0001	0550 0560	7261018 7261024	18 IN. PIPE GROUP A 24 IN. PIPE GROUP A	18.00	0.00	18.00 73.00	LF	73.00	\$110.00 \$105.00	\$1,980.
		0001	0570	7261024	30 IN. PIPE GROUP A	73.00	0.00	28.00	LF	19.00	\$160.00	\$7,665.0 \$3,040.0
		0001	0580	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	1.00	0.00	1.00	EA	1.00	\$1,500.00	\$1,500.
					SECTION							
		0001	0590	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,700.00	\$3,400.0
		0001	0600	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,850.00	\$3,700.0
		0001	0610	8051000A	SEEDING - COOL SEASON GRASSES	5.30	0.00	5.30	ACRE	0.90	\$1,600.00	\$1,440.
		0001	0620	8061004	SEDIMENT TRAP ROCK	29.80	0.00	29.80	CUYD	0.00	\$100.00	\$0.
		0001	0630	8061005	ROCK DITCH CHECK	140.00	0.00	140.00	LF	89.00	\$45.00	\$4,005.
		0001	0640	8061006	ALTERNATE DITCH CHECK	976.00	0.00	976.00	LF	0.00	\$4.35	\$0.
		0001	0650	8061016	SEDIMENT REMOVAL	189.00	0.00	189.00	CUYD	10.00	\$20.00	\$200
		0001	0660	8061019	SILT FENCE	3,187.00	0.00	3,187.00	LF	1,475.00	\$1.35	\$1,991
		0001	0670	8064128	TYPE 1 TURF REINFORCEMENT MAT	729.00	0.00	729.00	SQYD	0.00	\$1.95	\$0.
		0001	0680	8064138	TYPE 2D EROSION CONTROL BLANKET	3,973.00	0.00	3,973.00	SQYD	3,000.00	\$4.25	\$12,750
		0010	0690	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,463.00	0.00	1,463.00	LF	1,438.00	\$31.50	\$45,297
		0010	0700	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	5.00	0.00	5.00	EA	5.00	\$3,000.00	\$15,000
		0010	0710	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$950.00	\$950
		0010	0720	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,700.00	\$10,800
		0010	0730	6069902	MISC.HTGC ANCHOR ASSEMBLY	2.00	2.00	4.00	EA	4.00	\$5,000.00	\$20,000
		0010	0740	6069903	MISC.HIGH TENSION GUARD CABLE	1,256.00	0.00	1,256.00	LF	1,256.00	\$24.00	\$30,144
		0040	0750	7040101	SUBSTRUCTURE REPAIR (FORMED)	150.00	0.00	150.00	SQFT	150.00	\$75.00	\$11,250
		0040	0760	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$1,762.00	\$0.
		0040	0770	9031010	CONCRETE FOOTINGS, EMBEDDED	1.00	0.50	1.50	CUYD	0.56	\$1,300.00	\$728.
		0040	0780	9031210	STRUCTURAL STEEL POSTS	650.00	-85.00	565.00	LB	564.75	\$4.25	\$2,400.
		0040	0790	9031270A	2 IN. PSST POST - 12 GA.	75.00	-46.00	29.00	LF	0.00	\$20.50	\$0.
		0040	0800	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	18.00	-18.00	0.00	LF	0.00	\$40.00	\$0
		0040	0810	9035004A	SH-FLAT SHEET	27.00	0.00	27.00	SQFT	0.00	\$23.50	\$0.
		0040	0820	9035011A	ST-STRUCTURAL	80.00	0.00	80.00	SQFT	0.00	\$21.50	\$0.
		0040	0830	9035069A	SHF-FLAT SHEET FLUORESCENT	18.00	0.00	18.00	SQFT	0.00	\$37.50	\$0
		0050	0840	9103714	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	1.00	0.00	1.00	EA	1.00	\$8,500.00	\$8,500.
		0050	0850	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	227.00	0.00	227.00	LF	227.00	\$13.50	\$3,064
		0050	0860	9108206	CABLE, 6 AWG, 1 CONDUCTOR, POWER	3,390.00	0.00	3,390.00	LF	0.00	\$2.50	\$0.
		0050	0870	9108353	FIBER OPTIC CABLE, 12-STRAND, SINGLE MODE	1,130.00	0.00	1,130.00	LF	0.00	\$2.50	\$0.
		0050	0880	9108811	PULL BOX, PREFORMED CLASS 2	3.00	0.00	3.00	EA	0.00	\$1,575.00	\$0.0
		0050	0890	9109901	MISC.Fiber Optic Splicing, Testing, & Documentation	1.00	0.00	1.00	LS	1.00	\$5,500.00	\$5,500.

Page 14 of 45 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	J4P3009	0050	0900	9109902	MISC.CCTV Pole Relocation	1.00	0.00	1.00	EA	1.00	\$6,000.00	\$6,000.00
		0050	0910	9109902	MISC.Scout Fiber Optic Pull Box	3.00	0.00	3.00	EA	0.00	\$3,500.00	\$0.00
		0050	0920	9109903	MISC."CONDUIT, TWO 2 IN., PUSHED"	181.00	0.00	181.00	LF	181.00	\$30.00	\$5,430.00
		0050	0930	9109903	MISC."CONDUIT, TWO 2 IN., RIGID, IN SAME TRENCH"	692.00	0.00	692.00	LF	672.00	\$20.00	\$13,440.00
		0070	0940	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	17.00	0.00	17.00	SQFT	17.00	\$275.00	\$4,675.00
		0070	0950	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$68,000.00	\$68,000.00
		0070	0960	5031010A	BRIDGE APPROACH SLAB (MAJOR)	182.00	0.00	182.00	SQYD	182.00	\$249.10	\$45,336.20
		0070	0970	7011106	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	52.00	0.00	52.00	LF	52.00	\$985.00	\$51,220.00
		0070	0980	7011205	ROCK SOCKETS (3 FT 6 IN. DIA.)	32.00	0.00	32.00	LF	32.00	\$642.00	\$20,544.00
		0070	0990	7011300	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$200.00	\$800.00
		0070	1000	7011400	FOUNDATION INSPECTION HOLES	72.00	0.00	72.00	LF	72.00	\$105.00	\$7,560.00
		0070	1010	7011600	SONIC LOGGING TESTING	4.00	0.00	4.00	EA	4.00	\$1,200.00	\$4,800.00
		0070	1020	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	525.00	0.00	525.00	LF	450.00	\$109.00	\$49,050.00
		0070	1030	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$125.00	\$1,750.00
		0070	1040	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	93.40	0.00	93.40	CUYD	93.40	\$860.00	\$80,324.00
		0070	1050	7034219A	TYPE D BARRIER	306.00	0.00	306.00	LF	306.00	\$170.00	\$52,020.00
		0070	1060	7034221	SLAB ON CONCRETE NU-GIRDER	604.00	0.00	604.00	SQYD	604.00	\$398.00	\$240,392.00
		0070	1070	7034620	FORM LINERS	197.00	0.00	197.00	SQYD	197.00	\$90.00	\$17,730.00
		0070	1080	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	491.00	0.00	491.00	LF	491.00	\$360.00	\$176,760.00
		0070	1090	7061060	REINFORCING STEEL (BRIDGES)	7,860.00	0.00	7,860.00	LB	7,860.00	\$1.70	\$13,362.00
		0070	1100	7101000	REINFORCING STEEL (EPOXY COATED)	11,140.00	0.00	11,140.00	LB	11,140.00	\$2.25	\$25,065.00
		0070	1110	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,860.00	\$1,860.00
		0070	1120	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,860.00	\$1,860.00
		0070	1130	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$4,000.00	\$0.00
		0070	1140	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0070	1150	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$200.00	\$1,600.00
		0070	1160	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$385.00	\$3,080.00
		0070	1170	7201300	PIPE PILE SPACERS	18.00	0.00	18.00	EA	18.00	\$1,525.00	\$27,450.00
		0071	1180	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	17.00	0.00	17.00	SQFT	17.00	\$275.00	\$4,675.00
		0071	1190	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$68,000.00	\$68,000.00
		0071	1200	5031010A	BRIDGE APPROACH SLAB (MAJOR)	182.00	0.00	182.00	SQYD	182.00	\$249.10	\$45,336.20
		0071	1210	7011106	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	44.00	0.00	44.00	LF	44.00	\$985.00	\$43,340.00
		0071	1220	7011205	ROCK SOCKETS (3 FT 6 IN. DIA.)	32.00	0.00	32.00	LF	32.00	\$642.00	\$20,544.00
		0071	1230	7011300	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$200.00	\$800.00
		0071	1240	7011400	FOUNDATION INSPECTION HOLES	72.00	0.00	72.00	LF	72.00	\$105.00	\$7,560.00
		0071	1250	7011600	SONIC LOGGING TESTING	4.00	0.00	4.00	EA	4.00	\$1,200.00	\$4,800.00
		0071	1260	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	497.00	0.00	497.00	LF	412.00	\$109.00	\$44,908.00
		0071	1270	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$125.00	\$1,750.00
		0071	1280	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	92.10	0.00	92.10	CUYD	92.10	\$870.00	\$80,127.00
		0071	1290	7034219A	TYPE D BARRIER	306.00	0.00	306.00	LF	306.00	\$170.00	\$52,020.00
		0071	1300	7034221	SLAB ON CONCRETE NU-GIRDER	604.00	0.00	604.00	SQYD	604.00	\$398.00	\$240,392.00
		0071	1310	7034620	FORM LINERS	194.00	0.00	194.00	SQYD	194.00	\$90.00	\$17,460.00
		0071	1320	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	491.00	0.00	491.00	LF	491.00	\$360.00	\$176,760.00
		0071	1330	7061060	REINFORCING STEEL (BRIDGES)	7,230.00	0.00	7,230.00	LB	7,230.00	\$1.75	\$12,652.50
		0071	1340	7101000	REINFORCING STEEL (EPOXY COATED)	11,070.00	0.00	11,070.00	LB	11,070.00	\$2.10	\$23,247.00
		0071	1350	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,860.00	\$1,860.00
		0071	1360	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,860.00	\$1,860.00
Revision 4/1/202	20											Page 15 of 45



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
11015-C03	J4P3009	0071	1370	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$4,000.00	\$0.0
		0071	1380	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.0
		0071	1390	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$200.00	\$1,600.0
		0071	1400	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$385.00	\$3,080.0
		0071	1410	7201300	PIPE PILE SPACERS	18.00	0.00	18.00	EA	18.00	\$1,525.00	\$27,450.0
		0072	1420	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,367.50	\$3,367.5
		0072	1430	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,367.50	\$3,367.5
		0072	1440	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,786.00	0.00	3,786.00	SQFT	3,786.00	\$74.00	\$280,164.0
		0073	1450	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,115.00	\$3,115.0
		0073	1460	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,115.00	\$3,115.0
		0073	1470	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,422.00	0.00	3,422.00	SQFT	3,422.00	\$75.00	\$256,650.0
		0001	5001	6189901	MISC.CONTRACT BOND PAYMENT	0.00	1.00	1.00	LS	1.00	\$53,326.00	\$53,326.0
		0001	5002	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	0.00	26,882.00	26,882.00	LF	16,704.00	\$1.05	\$17,539.2
		0001	5003	1046002	VALUE ENGINEERING	0.00	6,720.50	6,720.50	EA	6,720.50	\$1.00	\$6,720.
		0072	5004	7209901	MISC.FLOWABLE FILL FOR GAS LINE REMOVAL	0.00	1.00	1.00	LS	1.00	\$12,459.01	\$12,459.0
		0040	5005	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	0.00	6.00	6.00	LF	0.00	\$65.63	\$0.0
		0040	5006	9031280	2.5 IN. PSST POST - 12 GA.	0.00	92.00	92.00	LF	0.00	\$33.60	\$0.0
		0040	5007	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	0.00	24.00	24.00	LF	0.00	\$78.49	\$0.0
		0040	5008	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL	0.00	8.00	8.00	EA	0.00	\$540.75	\$0.0
	Project J4I	P3009 - Tot	al Value I	Posted to Da	TUBE) te as of Report Generated Date							\$4,417,924.
	J4P3009B	0001	1480	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$85,000.00	\$63,750.0
		0001	1490	2031000	CLASS A EXCAVATION	637.00	0.00	637.00	CUYD	0.00	\$22.00	\$0.
		0001	1500	2036000	COMPACTING EMBANKMENT	260.00	0.00	260.00	CUYD	0.00	\$18.00	\$0.
		0001	1510	2063000	CLASS 3 EXCAVATION	109.00	0.00	109.00	CUYD	51.00	\$20.00	\$1,020.
		0001	1520	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	268.00	0.00	268.00	SQYD	268.00	\$17.00	\$4,556.
		0001	1530	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	822.00	0.00	822.00	SQYD	434.00	\$16.00	\$6,944.
		0001	1540	4019905	MISC.OPTIONAL PAVEMENT - CHIPMAN	434.00	0.00	434.00	SQYD	434.00	\$192.00	\$83,328.
		0001	1550	4019905	MISC.OPTIONAL PAVEMENT - MURRAY	388.00	0.00	388.00	SQYD	0.00	\$110.00	\$0.0
		0001	1560	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	1,688.10	0.00	1,688.10	TONS	0.00	\$95.00	\$0.0
		0001	1570	4071005	TACK COAT	1,459.00	0.00	1,459.00	GAL	0.00	\$2.50	\$0.0
		0001	1580	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	92.00	0.00	92.00	GAL	0.00	\$3.00	\$0.0
		0001	1590	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	0.00	\$1,400.00	\$0.
		0001	1600	6081000	CONCRETE MEDIAN	430.80	0.00	430.80	SQYD	342.80	\$65.55	\$22,470.
		0001	1610	6081010	CONCRETE CURB RAMP	229.30	0.00	229.30	SQYD	0.00	\$127.27	\$0.
		0001	1620	6081012	TRUNCATED DOMES	396.00	0.00	396.00	SQFT	0.00	\$17.65	\$0.0
		0001	1630	6083006	6 IN. CONCRETE MEDIAN STRIP	67.70	0.00	67.70	SQYD	0.00	\$161.45	\$0.
		0001	1640	6086004	CONCRETE SIDEWALK, 4 IN.	1,484.60	0.00	1,484.60	SQYD	404.00	\$38.55	\$15,574.
		0001	1650	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	896.00	0.00	896.00	LF	896.00	\$34.65	\$31,046.
		0001	1660	6091052	CURB AND GUTTER TYPE B	802.00	0.00	802.00	LF	563.00	\$35.05	\$19,733.
		0001	1670		FURNISHING TYPE 1 ROCK DITCH LINER	3.00	0.00	3.00	CUYD	0.00	\$75.00	\$0.
		0001	1680	6096041	PLACING TYPE 1 ROCK DITCH LINER	3.00	0.00	3.00	CUYD	0.00	\$75.00	\$0.
		0001	1690	6097000	ROCK LINING	7.00	0.00	7.00	CUYD	2.00	\$95.00	\$190.
		0001	1700	6099903	MISC.CURB AND GUTTER TYPE CG-1	522.00	0.00	522.00	LF	242.00	\$30.90	\$7,477.8
			1710	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X	1.00	0.00	1.00	EA	0.00	\$1,050.00	\$0.0
		0001			600MM)							
		0001	1720	6143014	MANHOLE FRAME AND COVER, TYPE 4	1.00	0.00	1.00	EA	0.00	\$750.00	\$0.0
			1730	6161005	CONSTRUCTION SIGNS	339.00	0.00	339.00	SQFT	249.00	\$6.50	\$1,618.5

Revision 4/1/2020 Page 16 of 45



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	J4P3009B	0001	1740	6161025	CHANNELIZER (TRIM LINE)	189.00	0.00	189.00	EA	160.00	\$31.00	\$4,960.00
		0001	1750	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$185.00	\$1,850.00
		0001	1760	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	1.00	\$2,500.00	\$2,500.00
		0001	1770	6169902	MISC.TYPE II PEDESTRIAN BARRICADE	5.00	0.00	5.00	EA	0.00	\$150.00	\$0.00
		0001	1780	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$110,000.00	\$110,000.00
		0001	1790	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.00
		0001	1800	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	141.00	0.00	141.00	LF	0.00	\$4.50	\$0.00
		0001	1810	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	462.00	0.00	462.00	LF	0.00	\$20.00	\$0.00
		0001	1820	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	96.00	0.00	96.00	LF	0.00	\$14.00	\$0.00
		0001	1830	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	23.00	0.00	23.00	EA	0.00	\$275.00	\$0.00
		0001	1840	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	1.00	0.00	1.00	EA	0.00	\$450.00	\$0.00
		0001	1850	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	78.00	0.00	78.00	EA	0.00	\$185.00	\$0.00
		0001	1860	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	5,606.00	0.00	5,606.00	LF	0.00	\$2.00	\$0.00
		0001	1870	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,561.00	0.00	2,561.00	LF	0.00	\$2.00	\$0.00
		0001	1880	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	8.00	0.00	8.00	EA	8.00	\$115.00	\$920.00
		0001	1890	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,951.00	0.00	3,951.00	LF	0.00	\$0.55	\$0.00
		0001	1900	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,361.00	0.00	2,361.00	LF	0.00	\$0.55	\$0.00
		0001	1910	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	333.00	0.00	333.00	LF	0.00	\$0.90	\$0.00
		0001	1920	6207001	PAVEMENT MARKING REMOVAL	630.00	0.00	630.00	LF	252.00	\$1.00	\$252.00
		0001	1930	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	10.00	0.00	10.00	EA	3.00	\$115.00	\$345.00
		0001	1940	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	15,347.00	0.00	15,347.00	SQYD	12,278.00	\$3.00	\$36,834.00
		0001	1950	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	8.00	0.00	8.00	SQYD	0.00	\$5.00	\$0.00
		0001	1960	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$24,000.00	\$24,000.00
		0001	1970	7261015	15 IN. PIPE GROUP A	97.00	0.00	97.00	LF	57.00	\$80.00	\$4,560.00
		0001	1980	7261030	30 IN. PIPE GROUP A	15.00	0.00	15.00	LF	0.00	\$160.00	\$0.00
		0001	1990	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	7.00	0.00	7.00	FT	0.00	\$625.00	\$0.00
		0001	2000	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	6.00	0.00	6.00	FT	0.00	\$775.00	\$0.00
		0001	2010	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,950.00	\$1,950.00
		0001	2020	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.00
		0001	2030	8031000A	TURF TYPE TALL FESCUE SODDING	1,064.00	0.00	1,064.00	SQYD	0.00	\$5.65	\$0.00
		0001	2040	8051000A	SEEDING - COOL SEASON GRASSES	0.40	0.00	0.40	ACRE	0.00	\$1,600.00	\$0.00
		0001	2050	8061004	SEDIMENT TRAP ROCK	18.00	0.00	18.00	CUYD	0.00	\$90.00	\$0.00
		0001	2060	8061005	ROCK DITCH CHECK	188.00	0.00	188.00	LF	0.00	\$55.00	\$0.00
		0001	2070	8061007A	CURB INLET CHECK	5.00	0.00	5.00	EA	0.00	\$63.00	\$0.00
		0001	2080	8061016	SEDIMENT REMOVAL	53.00	0.00	53.00	CUYD	0.00	\$25.00	\$0.00
		0001	2090	8061019	SILT FENCE	793.00	0.00	793.00	LF	0.00	\$1.35	\$0.00
		0001	2100	8064128	TYPE 1 TURF REINFORCEMENT MAT	593.00	0.00	593.00	SQYD	0.00	\$1.95	\$0.00
		0020	2110	9011010	RELOCATED POLE	6.00	0.00	6.00	EA	4.00	\$800.00	\$3,200.00
		0020	2120	9011060	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 1	1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0.00
		0020	2130	9011115	BRACKET ARM, 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$1,200.00	\$0.00
		0020	2140	9011312	LUMINAIRE, LED-B	7.00	0.00	7.00	EA	0.00	\$200.00	\$0.00
		0020	2150	9014004	CONDUIT, 4 IN. RIGID, PUSHED	136.00	0.00	136.00	LF	136.00	\$35.00	\$4,760.00
		0020	2160	9014502	CONDUIT, 2 IN. RIGID, EXTERNAL ON STRUCTURE	322.00	0.00	322.00	LF	322.00	\$60.00	\$19,320.00
		0020	2170	9015010	TRENCHING TYPE I	795.00	0.00	795.00	LF	53.00	\$6.00	\$318.00

Revision 4/1/2020 Page 17 of 45



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	J4P3009B	0020	2180	9016110	PULL BOX, PREFORMED CLASS 1	5.00	0.00	5.00	EA	4.00	\$355.00	\$1,420.00
		0020	2190	9017004	CABLE, 4 AWG 1 CONDUCTOR	1,110.00	0.00	1,110.00	LF	0.00	\$3.00	\$0.00
		0020	2200	9017008	CABLE, 8 AWG 1 CONDUCTOR	1,700.00	0.00	1,700.00	LF	765.00	\$2.50	\$1,912.50
		0020	2210	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	120.00	0.00	120.00	LF	0.00	\$2.00	\$0.00
		0020	2220	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	920.00	0.00	920.00	LF	0.00	\$12.50	\$0.00
		0020	2230	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	0.00	\$1,400.00	\$0.00
		0020	2240	9019902	MISC.LEE'S SUMMIT 40 FT. POLE FOUNDATION B40D SCREW-	3.00	0.00	3.00	EA	0.00	\$1,500.00	\$0.00
		0020	2250	9019902	IN  MISC.LUMINAIRE, LED-A WALL PACK (INCLUDING HOUSING)	4.00	0.00	4.00	EA	4.00	\$1,200.00	\$4,800.00
		0020	2260	9019902	MISC.PULL BOX LID REPLACEMENT	1.00	0.00	1.00	EA	0.00	\$900.00	\$0.00
		0020	2270	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	410.00	0.00	410.00	LF	410.00	\$25.00	\$10,250.00
		0030	2280	9020211	SIGNAL HEAD, TYPE 1S	18.00	0.00	18.00	EA	0.00	\$175.00	\$0.00
		0030	2290	9020215	SIGNAL HEAD, TYPE 5S	1.00	0.00	1.00	EA	0.00	\$1,500.00	\$0.00
		0030	2300	9020513	SIGNAL HEAD, TYPE 3B	9.00	0.00	9.00	EA	0.00	\$975.00	\$0.00
		0030	2310	9020514	SIGNAL HEAD, TYPE 4B	3.00	0.00	3.00	EA	0.00	\$1,275.00	\$0.00
		0030	2320	9020833	SH-FLAT SHEET - SIGNAL SIGN	42.00	0.00	42.00	SQFT	42.00	\$80.00	\$3,360.00
		0030	2330	9020834	SIGNAL SIGN, MOUNTING HARDWARE	21.00	0.00	21.00	EA	21.00	\$60.00	\$1,260.00
		0030	2340	9022708	POST, SIGNAL 8 FT. OR 2.4 M	11.00	0.00	11.00	EA	0.00	\$1,325.00	\$0.00
		0030	2350	9022715	POST, SIGNAL 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$1,750.00	\$0.00
	0030	0030	2360	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	1.00	\$15,000.00	\$15,000.00
		0030	2370	9024920	DETECTOR, PUSHBUTTON	18.00	0.00	18.00	EA	0.00	\$1,250.00	\$0.00
		0030	2380	9024975	VIDEO DETECTION SYSTEM	3.00	0.00	3.00	EA	1.00	\$24,000.00	\$24,000.00
		0030	2390	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	267.00	0.00	267.00	LF	162.00	\$17.50	\$2,835.00
		0030	2400	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	37.00	0.00	37.00	LF	0.00	\$13.00	\$0.00
		0030	2410	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	789.00	0.00	789.00	LF	789.00	\$32.00	\$25,248.00
		0030	2420	9028308	CABLE, 16 AWG 2 CONDUCTOR	3,450.00	0.00	3,450.00	LF	1,970.00	\$1.50	\$2,955.00
		0030	2430	9028310	CABLE, 16 AWG 5 CONDUCTOR	3,460.00	0.00	3,460.00	LF	1,990.00	\$2.00	\$3,980.00
		0030	2440	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,110.00	0.00	2,110.00	LF	1,335.00	\$2.50	\$3,337.50
		0030	2450	9028811	PULL BOX, PREFORMED CLASS 2	13.00	-2.00	11.00	EA	8.00	\$1,750.00	\$14,000.00
		0030	2460	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	0.00	\$1,825.00	\$0.00
		0030	2470	9029100	BASE, CONCRETE	11.80	0.00	11.80	CUYD	5.20	\$2,500.00	\$13,000.00
		0030	2480	9029902	MISC.POST, SIGNAL 4 FT.	3.00	0.00	3.00	EA	0.00	\$985.00	\$0.00
		0030	2490	9029902	MISC.PULL BOX CLASS 3 LID REPLACEMENT	1.00	0.00	1.00	EA	0.00	\$250.00	\$0.00
		0030	2500	9109902	MISC.CCTV CAMERA ASSEMBLY, INSTALLED	2.00	0.00	2.00	EA	0.00	\$8,000.00	\$0.00
		0040	2510	9031010	CONCRETE FOOTINGS, EMBEDDED	1.70	0.20	1.90	CUYD	0.00	\$1,300.00	\$0.00
		0040	2520	9031210	STRUCTURAL STEEL POSTS	1,520.00	0.00	1,520.00	LB	0.00	\$4.25	\$0.00
		0040	2530	9031270A	2 IN. PSST POST - 12 GA.	236.00	-53.00	183.00	LF	0.00	\$20.50	\$0.00
		0040	2540	9035004A	SH-FLAT SHEET	67.00	0.00	67.00	SQFT	0.00	\$23.50	\$0.00
		0040	2550	9035011A	ST-STRUCTURAL	318.00	0.00	318.00	SQFT	0.00	\$21.50	\$0.00
		0040	2560	9035069A	SHF-FLAT SHEET FLUORESCENT	18.00	0.00	18.00	SQFT	0.00	\$37.50	\$0.00
		0040	5009	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	0.00	21.00	21.00	LF	0.00	\$42.00	\$0.00
		0040	5010	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	0.00	21.00	21.00	LF	0.00	\$65.63	\$0.00
		0040	5011	9031280	2.5 IN. PSST POST - 12 GA.	0.00	27.00	27.00	LF	0.00	\$33.60	\$0.00
		0040	5012	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	0.00	6.00	6.00	LF	0.00	\$78.49	\$0.00
		0030	5013	9029901	MISC.PULL BOX HEIGHT ADJUSTMENT	0.00	1.00	1.00	LS	1.00	\$1,001.74	\$1,001.74
		0040	5014	9039902	MISC.SIGN RELOCATION	0.00	6.00	6.00	EA	6.00	\$246.75	\$1,480.50
		0020	5015	9019902	MISC.PULL BOX REMOVAL AND REPLACEMENT	0.00	2.00	2.00	EA	2.00	\$2,079.00	\$4,158.00

Revision 4/1/2020 Page 18 of 45



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generat ated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	Project J4F	23009B - To	tal Value	Posted to D	ate as of Report Generated Date							\$607,475.83
211015-C03 Ove	rall - Total V	/alue Poste	d to Date	as of Repor	t Generated Date							\$5,025,400.57

Revision 4/1/2020 Page 19 of 45



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3009

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2013000	CLEARING AND GRUBBING	8/18/22	9/2/22	1.00	ACRE	Cleanup around sign truss footings and general locations	560+00		570+00		
0070	2063000	CLASS 3 EXCAVATION	8/18/22	9/2/22	3.00	CUYD	US - 50	568+07.53	Rt	568+08.37	rt	
				9/2/22	10.00	CUYD	EB US 50	570+55.66	Rt	570+64.51	Rt	
				9/2/22	17.00	CUYD	US - 50	568+30.84	Lt	568+32.68	Lt	
0170	4071005	TACK COAT	8/18/22	9/2/22	89.00	GAL	WB Detour (Missed from previous estimate)	10+40		13+30		
				9/2/22	124.00	GAL	EB Detour (Missed from previous estimate)	11+00		14+90		
0260	6097000	ROCK LINING	8/18/22	9/2/22	2.00	CUYD		570+55.66	rt	570+64.51	rt	
				9/2/22	4.00	CUYD		568+07.53		568+07.53		
				9/2/22	6.00	CUYD		568+30.84		568+32.68		
0500	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	8/18/22	9/2/22	838.00	SQYD	WB detour	10+40		13+30		
				9/2/22	1,127.00	SQYD	EB Detour	11+00		14+90		
0550	7261018	18 IN. PIPE GROUP A	8/18/22	9/2/22	18.00	LF		570+55.66	rt	570+64.51	rt	
0570	7261030	30 IN. PIPE GROUP A	8/18/22	9/2/22	19.00	LF		568+30.84	Lt	568+32.68	It	
0580	7320618A	18 IN. GROUP A FLARED END SECT	8/18/22	9/2/22	1.00	EA		570+55.66	rt	570+55.66	rt	
0600	7320630A	30 IN. GROUP A FLARED END SECT	8/18/22	9/2/22	1.00	EA		568+07.53	RT	568+08.37	RT	
				9/2/22	1.00	EA		568+30.84	LT	568+32.68	LT	
0650	8061016	SEDIMENT REMOVAL	8/18/22	9/2/22	10.00	CUYD	Inlet cleanout at NW side of Chipman by ramp 2	1+78		1+78		
0750	7040101	SUBSTRUCTURE REPAIR (FORMED)	8/30/22	9/2/22	150.00	SQFT	Paid to plan. Additional QTY needed on CO	554+00		554+00		
0770	9031010	CONCRETE FOOTINGS, EMBEDDED	8/30/22	9/2/22	0.28	CUYD	eb exit sign	561+13		561+13		
				9/2/22	0.28	CUYD	wb exit sign	576+60		576+60		
0780	9031210	STRUCTURAL STEEL POSTS	8/30/22	9/2/22	276.75	LB	WB exit sign	576+60		576+60		
				9/2/22	288.00	LB	eb exit sign	561+13		561+13		
1060	7034221	SLAB ON CONCRETE NU-GIRDER	8/30/22	9/2/22	60.40	SQYD		568+94.03		570+18.98		

#### Project: J4P3009B

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1480	2022010	REMOVAL OF IMPROVEMENTS	8/30/22	9/2/22	0.25	LS		4+00		17+40		
1520	3040504	TYPE 5 AGGREGATE FOR BASE	8/31/22	9/2/22	134.00	SQYD		11+06		14+60		
				9/2/22	134.00	SQYD		11+52		14+97		
1530	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	8/31/22	9/2/22	265.00	SQYD	Ramps 1, 2, 3, and 4	0+00		10+00		
1540	4019905	MISC.	8/31/22	9/2/22	251.00	SQYD	ramps 1, 2, 3, and 4	0+00		10+00		
1600	6081000	CONCRETE MEDIAN	8/31/22	9/2/22	169.50	SQYD		5+93.69		7+23.5		
				9/2/22	173.30	SQYD		8+44.72		10+65.53		
1650	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	8/31/22	9/2/22	545.00	LF		7+23		15+54		
1700	6099903	MISC. PAVED DRAINAGE	8/31/22	9/2/22	113.00	LF		10+33.86		11+25.19		
				9/2/22	129.00	LF		14+82.99		15+91.88		
1940	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	8/18/22	9/2/22	12,278.00	SQYD	Chipman road 80%	4+00		17+40		
2110	9011010	RELOCATED POLE	9/1/22	9/2/22	1.00	EA	1-01	7+17	21.5' rt	7+17	21.5' Rt	
				9/2/22	1.00	EA	1-02	8+70	7.2' Lt	8+70	7.2' Lt	
				9/2/22	1.00	EA	1-03	10+10	2' It	10+10	2' Lt	
				9/2/22	1.00	EA	2-01	7+36	44.6' Rt	7+36	44.6' RT	
2180	9016110	PULL BOX, PREFORMED CLASS 1	9/1/22	9/2/22	1.00	EA	PB1	7+00	23' Rt	7+00		
				9/2/22	1.00	EA	PB2	8+56	7.7' rt	8+56	7.7' Rt	
2200	9017008	CABLE, 8 AWG 1 CONDUCTOR	9/1/22	9/2/22	309.00	LF	3-02 to EX PB	15+41		11+75		
2250	9019902	MISC. HIGHWAY LIGHTING	9/1/22	9/2/22	1.00	EA	2-02	12+86	51' rt	12+86	51' rt	
				9/2/22	1.00	EA	2-03	13+40	51' rt	13+40	51' rt	
2270	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	9/1/22	9/2/22	319.00	LF	PB1 to 1-01, 1-01 to PB2, PB2 to 1-02, 1-02 to 1-03	10+00		13+19		
2320	9020833	SH-FLAT SHEET - SIGNAL SIGN	9/1/22	9/2/22	42.00	SQFT		14+43	58.4' It	14+43	58.4' Lt	
2330	9020834	SIGNAL SIGN, MOUNTING HARDWARE	9/1/22	9/2/22	21.00	EA		14+43	58.4' It	14+43	58.4' It	
2360	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	9/1/22	9/2/22	1.00	EA		14+43	58.4' Lt	14+43	58.4' It	
2390	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	9/1/22	9/2/22	62.00	LF	Chipman Rd and US 50 EB Ramps	8+00		11+00		
				9/2/22	100.00	LF	Chipman and Murry rd	4+00	8+00			
2410	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	9/1/22	9/2/22	475.00	LF		4+00		17+40		
2420	9028308	CABLE, 16 AWG 2 CONDUCTOR	9/1/22	9/2/22	1,970.00	LF		4+00		12+00		
2430	9028310	CABLE, 16 AWG 5 CONDUCTOR	9/1/22	9/2/22	1,990.00	LF		4+00		11+00		
2440	9028311	CABLE, 16 AWG 7 CONDUCTOR	9/1/22	9/2/22	1,335.00	LF		4+00		11+00		
2450	9028811	PULL BOX, PREFORMED CLASS 2	9/1/22	9/2/22	8.00	EA		4+00		11+00		
2470	9029100	BASE, CONCRETE	9/1/22	9/2/22	5.20	CUYD	Signal base and controller base	14+00		14+50		
5013	9029901	MISC.	8/31/22	9/2/22	1.00	LS		13+97		13+97		
5014	9039902	MISC.	8/31/22	9/2/22	6.00	EA		4+00		17+40		
5015	9019902	MISC. HIGHWAY LIGHTING	8/31/22	9/2/22	2.00	EA		13+97		11+62		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 20 of 45



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3009	0040	EMBANKMENT IN PLACE	Material		3	Apr 18, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$12,020.00)	
					4	May 2, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$12,020.00)	
					5	May 16, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$12,020.00)	
					6	Jun 1, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$12,020.00)	
					7	Jun 16, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$12,020.00)	
					8	Jul 1, 2022	SYSTEM	\$63,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$63,400.00)	
					9	Jul 18, 2022	SYSTEM	\$72,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$72,520.00)	
					10	Aug 2, 2022	SYSTEM	\$72,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$72,520.00)	
					11	Aug 16, 2022	SYSTEM	\$72,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$72,520.00)	
					12	Sep 2, 2022	SYSTEM	\$72,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$72,520.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0040 -	· Total						\$0.00	
	0050	COMPACTING EMBANKMENT	Material		3	Apr 18, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$272.50)	
					4	May 2, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$272.50)	
					5	May 16, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	May 16,	SYSTEM	(\$272.50)	



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J4P3009	0050	COMPACTING EMBANKMENT	Material		6	Jun 1, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$272.50)	
					7	Jun 16, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$272.50)	
					8	Jul 1, 2022	SYSTEM	\$4,010.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$4,010.00)	
					9	Jul 18, 2022	SYSTEM	\$7,222.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$7,222.50)	
					10	Aug 2, 2022	SYSTEM	\$13,235.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$13,235.00)	
					11	Aug 16, 2022	SYSTEM	\$13,235.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$13,235.00)	
					12	Sep 2, 2022	SYSTEM	\$13,235.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$13,235.00)	
				- Total				\$0.00	
	2050		Material - Tota	<u> </u>				\$0.00	
	0050 - 0060	COMPACTING IN	Material		8	Jul 1,	SYSTEM	\$0.00 \$5,600.00	This adjustment offsets the original system-generated Material Payment
		CUT				2022			Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$5,600.00)	
					9	Jul 18, 2022	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$8,400.00)	
					10	Aug 2, 2022	SYSTEM	\$11,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$11,200.00)	
					11	Aug 16, 2022	SYSTEM	\$11,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$11,200.00)	
					12	Sep 2, 2022	SYSTEM	\$11,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$11,200.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0060 -		Material					\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0090	AGGREGATE FOR BASE	Material			2022			Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$10,271.25)	
					3	Apr 18, 2022	SYSTEM	\$23,941.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$23,941.50)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0090 -	· Total						\$0.00	
	0100	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		5	May 16, 2022	SYSTEM	\$6,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		THICK			5	May 16, 2022	SYSTEM	(\$6,990.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0100 -							\$0.00	
	0110	MISC. AGGREGATE FOR BASE	Material		7	Jun 16, 2022	SYSTEM	(\$51,007.00)	
		BASE			8	Jul 1, 2022	SYSTEM	\$51,007.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$51,007.00)	
					9	Jul 18, 2022	SYSTEM	\$51,007.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$51,007.00)	
					10	Aug 2, 2022	SYSTEM	\$128,876.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$128,876.00)	
					11	Aug 16, 2022	SYSTEM	\$128,876.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$128,876.00)	
				- Total				(\$51,007.00)	
			Material - Tota					(\$51,007.00)	
			MaterialCredit		8	Jul 1, 2022	SYSTEM	\$51,007.00	
				- Total				\$51,007.00	
			MaterialCredit	- Total				\$51,007.00	
	0110 -							\$0.00	
	0120	TYPE A2 SHOULDER	Other Item Adjustment	ACAD	8	Jul 1, 2022	vohsr1	\$1,787.70	This Adjustment is being made for the Bit Base lift for the Type A2 Shoulder for the pavement South of the bridge.
					11	Aug 17, 2022	vohsr1	\$2,827.28	AC Adjustment for BB JUL-22 Period 2.
					11	Aug 17, 2022	vohsr1	\$1,627.42	Corrected AC adjustment for BB E JUN-22 Period 2
					11	Aug 16, 2022	vohsr1	(\$1,787.70)	This adjustment is being made to correct the adjustment made on Estimate 8.
				ACAD - Tot	al			\$4,454.70	
			Other Item Adj	ustment - To	tal			\$4,454.70	
	0120 -	· Total						\$4,454.70	
	0130	MISC.	Material		4	May 2, 2022	SYSTEM	\$24,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	May 2,	SYSTEM	(\$24,000.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4P3009	0130	MISC.	Material			2022															
					5	May 16, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
					5	May 16, 2022	SYSTEM	(\$46,600.00)													
					6	Jun 1, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					6	Jun 1, 2022	SYSTEM	(\$46,600.00)													
					7	Jun 16, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
					7	Jun 16, 2022	SYSTEM	(\$46,600.00)													
					8	Jul 1, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					8	Jul 1, 2022	SYSTEM	(\$46,600.00)													
					9	Jul 18, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					9	Jul 18, 2022	SYSTEM	(\$46,600.00)													
				- Total				\$0.00													
		0 - Total	Material - Tota					\$0.00													
	0130 -		Material					\$0.00													
	0140	MISC.	Material		2	Apr 4, 2022	SYSTEM	\$37,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.												
					2	Apr 4, 2022	SYSTEM	(\$37,350.00)													
					3	Apr 18, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
																3	Apr 18, 2022	SYSTEM	(\$103,080.00)		
					4	May 2, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.												
																	4	May 2, 2022	SYSTEM	(\$103,080.00)	
					5	May 16, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.												
					5	May 16, 2022	SYSTEM	(\$103,080.00)													
					6	Jun 1, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					6	Jun 1, 2022	SYSTEM	(\$103,080.00)													
										7		7	Jun 16, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					7	Jun 16, 2022	SYSTEM	(\$103,080.00)	•												
		8	8	Jul 1, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.														
				8	Jul 1, 2022	SYSTEM	(\$103,080.00)														
			9	Jul 18, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.														
					9	Jul 18,	SYSTEM	(\$103,080.00)													



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
IP3009	0140	MISC.	Material			2022						
				- Total				\$0.00				
			Material - Tota	ı				\$0.00				
	0140 -	Total						\$0.00				
	0150	MISC.	Other Item Adjustment	ACAD	8	Jul 1, 2022	vohsr1	\$11,167.45	This adjustment is being made for the SP 190 C asphalt placed on the south side of the bridge.			
					8	Jul 1, 2022	vohsr1	\$4,209.06	This adjustment is being made for the SP 190 C asphalt placed on the south side of the bridge.			
					11	Aug 17, 2022	vohsr1	\$8,621.83	AC Adjustment for AUG-22 First Period SP-190B.			
					11	Aug 17, 2022	vohsr1	\$21,106.92	AC Adjustment for JUL-22 Second Period SP-190C.			
					11	Aug 16, 2022	vohsr1	\$8,960.71	AC Adjustment for SP-125C AUG-22 First Period			
					11	Aug 17, 2022	vohsr1	(\$4,209.06)	AC Ajustment for SP190B was incorrectly Labeled as SP190C on Estimate 8. This adjustment is correcting that comment.			
					11	Aug 17, 2022	vohsr1	(\$11,167.45)	AC Ajustment for SP190C was incorrectly calculated on Estimate 8. This adjustment is correcting that adjustment.			
					11	Aug 17, 2022	vohsr1	\$4,209.06	Corrected AC Adjustment for JUN-22 Second Period SP-190B From Estimate 8.			
					11	Aug 17, 2022	vohsr1	\$11,601.34	Corrected AC Adjustment for JUN-22 Second Period SP-190C.			
				ACAD - Tot	al			\$54,499.86				
			Other Item Ad	justment - To	otal			\$54,499.86				
	0150 -	Total						\$54,499.86				
	0160	ASPHALTIC CONCRETE	Other Item Adjustment	ACAD	4	May 2, 2022	vohsr1	\$1,167.05	Asphalt Cement Price Adjustment for Line 0180, April 2022			
		MIXTURE PG 70-22 (SP125C		ACAD - Tot	al			\$1,167.05				
		MIX)	Other Item Ad	justment - To	otal			\$1,167.05				
	0160 -		- Total						\$1,167.05			
	0180	CONCRETE APPROACH PAVEMENT	Material		9	Jul 18, 2022	SYSTEM	\$41,246.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.			
						9	Jul 18, 2022	SYSTEM	(\$41,246.28)			
					10	Aug 2, 2022	SYSTEM	\$41,246.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
					10	Aug 2, 2022	SYSTEM	(\$41,246.28)				
					11	Aug 16, 2022	SYSTEM	\$41,246.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
					11	Aug 16, 2022	SYSTEM	(\$41,246.28)				
								12	Sep 2, 2022	SYSTEM	\$41,246.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$41,246.28)				
				- Total				\$0.00				
			Material - Tota	ı				\$0.00				
	0180 -	Total						\$0.00				
	0190	PIPE COLLAR, TYPE A	Material		4	May 2, 2022	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
					4	May 2, 2022	SYSTEM	(\$3,300.00)				
					5	May 16, 2022	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment			
						2022			Estimate Exception 10 on the current Payment Estimate.			
					5	May 16, 2022	SYSTEM	(\$3,300.00)				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0190	PIPE COLLAR, TYPE A	Material - Tota					\$0.00	
	0190 -	· Total						\$0.00	
	0200	AGGR. BEDDING FOR 3 - STRAND GUARD CABLE	Material		11	Aug 16, 2022	SYSTEM	\$3,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user vohsr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$3,720.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0200 -	· Total						\$0.00	
	0210	MODIFIED CONCRETE GUTTER TYPE B	Material		6	Jun 1, 2022	SYSTEM	\$14,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$14,064.00)	
					7	Jun 16, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$23,520.00)	
					8	Jul 1, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$23,520.00)	
					9	Jul 18, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$23,520.00)	
					10	Aug 2, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$23,520.00)	
					11	Aug 16, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user vohsr1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$23,520.00)	
					12	Sep 2, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$23,520.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0210 -	· Total						\$0.00	
	0220	MISC. FENCING	Material		11	Aug 16, 2022	SYSTEM	\$44,685.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user vohsr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$44,685.00)	
					12	Sep 2, 2022	SYSTEM	\$44,685.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$44,685.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0220 -	· Total						\$0.00	
	0350	CMS W/O COMMUNICATION INTERFACE,	Material		1	Mar 18, 2022	SYSTEM	\$19,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		CONT F/			1	Mar 18,	SYSTEM	(\$19,000.00)	•



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J4P3009	0350	CMS W/O	Material			2022													
		COMMUNICATION INTERFACE,		- Total				\$0.00											
		CONT F/	Material - Tota	l				\$0.00											
	0350 -	· Total						\$0.00											
	0370	CONCRETE TRAFFIC BARRIER, TYPE C	Material		8	Jul 1, 2022	SYSTEM	\$29,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.										
					8	Jul 1, 2022	SYSTEM	(\$29,800.00)											
					9	Jul 18, 2022	SYSTEM	\$29,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.										
					9	Jul 18, 2022	SYSTEM	(\$29,800.00)											
					10	Aug 2, 2022	SYSTEM	\$35,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.										
					10	Aug 2, 2022	SYSTEM	(\$35,400.00)											
					11	Aug 16, 2022	SYSTEM	\$35,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user vohsr1 overridding Payment Estimate Exception 33 on the current Payment Estimate.										
					11	Aug 16, 2022	SYSTEM	(\$35,400.00)											
								12	Sep 2, 2022	SYSTEM	\$35,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 37 on the current Payment Estimate.							
					12	Sep 2, 2022	SYSTEM	(\$35,400.00)											
				- Total				\$0.00											
			Material - Tota	1				\$0.00											
	0370 -	· Total						\$0.00											
	0520	SEPARATION GEOTEXTILE	Material		11	Aug 16, 2022	SYSTEM	\$3,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user vohsr1 overridding Payment Estimate Exception 35 on the current Payment Estimate.										
															11	Aug 16, 2022	SYSTEM	(\$3,771.00)	
								12	Sep 2, 2022	SYSTEM	\$3,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 39 on the current Payment Estimate.							
					12	Sep 2, 2022	SYSTEM	(\$3,771.00)											
				- Total				\$0.00											
			Material - Tota	I				\$0.00											
	0520 -	· Total						\$0.00											
	0660	SILT FENCE	Material		4	May 2, 2022	SYSTEM	\$850.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.										
					4	May 2, 2022	SYSTEM	(\$850.50)											
				- Total				\$0.00											
			Material - Tota					\$0.00											
	0660 -	· Total						\$0.00											
	0690	MGS GUARDRAIL, 8 FT. POSTS, 6 FT.	Construction Stockpile		11	Aug 16, 2022	SYSTEM	(\$33,387.55)	Payment Estimate Item Adjustment generated Stockpile Transaction										
		- 3 IN		- Total				(\$33,387.55)											
			Construction S	Stockpile - To	otal			(\$33,387.55)											
			Construction Stockpile		4	May 2, 2022	SYSTEM	\$33,968.00	Payment Estimate Item Adjustment generated Stockpile Transaction										
			STMI	- Total				\$33,968.00											
			Construction S	Stockpile STI	VII - Total			\$33,968.00											
			Material		11	Aug 16, 2022	SYSTEM	\$45,297.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.										



Duringt	Line	December	A .!!	Other	F-4	0	0	A	Devento			
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J4P3009	0690	MGS GUARDRAIL, 8 FT. POSTS, 6 FT.	Material		11	Aug 16, 2022	SYSTEM	(\$45,297.00)				
		- 3 IN			12	Sep 2, 2022	SYSTEM	\$45,297.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
					12	Sep 2, 2022	SYSTEM	(\$45,297.00)				
				- Total				\$0.00				
			Material - Tota	ı				\$0.00				
	0690 -	Total						\$580.45				
	0700	MGS BRIDGE APP. TRANS SEC	Construction Stockpile		11	Aug 16, 2022	SYSTEM	(\$1,851.85)	Payment Estimate Item Adjustment generated Stockpile Transaction			
		(REG/NO CURB)		- Total				(\$1,851.85)				
			Construction	Stockpile - To	otal			(\$1,851.85)				
			Construction		4	May 2,	SYSTEM	\$1,851.85	Payment Estimate Item Adjustment generated Stockpile Transaction			
			Stockpile STMI			2022						
				- Total				\$1,851.85				
			Construction	Stockpile STI	VII - Total			\$1,851.85				
			Material		11	Aug 16, 2022	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
					11	Aug 16, 2022	SYSTEM	(\$15,000.00)				
					12	Sep 2, 2022	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
					12	Sep 2, 2022	SYSTEM	(\$15,000.00)				
				- Total				\$0.00				
			Material - Tota					\$0.00				
	0700 -	Total						\$0.00				
	0710	MGS END ANCHOR	Construction Stockpile		11	Aug 16, 2022	SYSTEM	(\$830.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				(\$830.00)				
			Construction	Stockpile - To	otal			(\$830.00)				
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$830.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				\$830.00				
			Construction	Stockpile STI	VII - Total			\$830.00				
			Material		11	Aug 16, 2022	SYSTEM	\$950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0071) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.			
					11	Aug 16, 2022	SYSTEM	(\$950.00)				
								12	Sep 2, 2022	SYSTEM	\$950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$950.00)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	0710 -	Total						\$0.00				
	0720	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		11	Aug 16, 2022	SYSTEM	(\$7,520.00)	Payment Estimate Item Adjustment generated Stockpile Transaction			
		(MASH)		- Total				(\$7,520.00)				
			Construction	Stockpile - To	otal			(\$7,520.00)				
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$7,520.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				\$7,520.00				
			Construction	Stockpile STI	VII - Total			\$7,520.00				
			Material		11	Aug 16,	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment			



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J4P3009	0720	TYPE A CRASHWORTHY END TERMINAL	Material			2022			Estimate Item Adjustment (0072) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
		(MASH)			11	Aug 16, 2022	SYSTEM	(\$10,800.00)	
					12	Sep 2, 2022	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$10,800.00)	
				- Total				\$0.00	
			Material - Tota	I				\$0.00	
	0720 -	Total						\$0.00	
	0730	MISC. GUARDRAIL ITEM	Construction Stockpile		8	Jul 1, 2022	SYSTEM	(\$3,300.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$3,300.00)	
			Construction S	Stockpile - To	otal			(\$3,300.00)	
			Construction Stockpile STMI		2	Apr 4, 2022	SYSTEM	\$3,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$3,300.00	
			Construction S	Stockpile STI	VII - Total			\$3,300.00	
			Material		8	Jul 1, 2022	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$10,000.00)	
					9	Jul 18, 2022	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$10,000.00)	
					10	Aug 2, 2022	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$10,000.00)	
					11	Aug 16, 2022	SYSTEM	\$20,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0073) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$20,000.00)	
					12	Sep 2, 2022	SYSTEM	\$20,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$20,000.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0730 -	Total						\$0.00	
	0740	MISC. GUARDRAIL ITEM	Construction Stockpile		11	Aug 16, 2022	SYSTEM	(\$21,968.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$21,968.00)	
			Construction S	Stockpile - To	otal			(\$21,968.00)	
			Construction Stockpile		2	Apr 4, 2022	SYSTEM	\$21,968.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$21,968.00	
			Construction S	Stockpile STI	VII - Total			\$21,968.00	
			Material		11	Aug 16, 2022	SYSTEM	\$30,144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0074) due to user vohsr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$30,144.00)	
					12	Sep 2, 2022	SYSTEM	\$30,144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3009	0740	MISC. GUARDRAIL ITEM	Material	. 7	12	Sep 2, 2022	SYSTEM	(\$30,144.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0740 -	Total						\$0.00	
	0750	SUBSTRUCTURE REPAIR (FORMED)	Material		12	Sep 2, 2022	SYSTEM	\$11,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$11,250.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0750 -	Total						\$0.00	
	0770	CONCRETE FOOTINGS, EMBEDDED	Material		12	Sep 2, 2022	SYSTEM	\$728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 72 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$728.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
J	0770 -	Total						\$0.00	
	0790	2 IN. PSST POST - 12 GA.	Construction Stockpile STMI		11	Aug 16, 2022	SYSTEM	\$311.75	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$311.75	
	0700	Total	Construction	Stockpile STI	MI - Total			\$311.75	
	0790 -		O t ti		44	A 40	OVOTEM	\$311.75	Down and Entire stall have Adjusted and consented Otacles in Towns at the
	0810	SH-FLAT SHEET	Construction Stockpile STMI	- Total	11	Aug 16, 2022	SYSTEM	\$240.30 \$240.30	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction S		MI - Total			\$240.30	
	0810 -	Total						\$240.30	
	0820	ST-STRUCTURAL	Construction Stockpile		11	Aug 16, 2022	SYSTEM	\$1,072.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$1,072.00	
			Construction	Stockpile STI	MI - Total			\$1,072.00	
	0820 -	Total						\$1,072.00	
	0830	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile STMI		11	Aug 16, 2022	SYSTEM	\$196.20	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$196.20	
			Construction	Stockpile STI	MI - Total			\$196.20	
	0830 - 0840	CCTV POLE FOUNDATION, 45	Material		4	May 2, 2022	SYSTEM	\$196.20 \$8,500.00	This adjustment offsets the original system-generated Material Payment
		FT OR 13.7M MOU			4	May 2,	SYSTEM	(\$8,500.00)	Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	2022 May 16,	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment
					_	2022	OVOTELA	(00.500.00)	Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					6	May 16, 2022 Jun 1,	SYSTEM	(\$8,500.00)	This adjustment offsets the original system-generated Material Payment
						2022	SISIEW	φο,συυ.υυ	Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$8,500.00)	
					7	Jun 16, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$8,500.00)	



P3009	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
F3009	0840	CCTV POLE		Туре	8	Jul 1,	SYSTEM	\$8,500.00	This adjustment effects the original system generated Material Downsont
	0640	FOUNDATION, 45 FT OR 13.7M MOU	Material		0	2022	STSTEIN	\$6,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$8,500.00)	
					9	Jul 18, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 71 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$8,500.00)	
					10	Aug 2, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$8,500.00)	
					11	Aug 16, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0075) due to user vohsr1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$8,500.00)	
					12	Sep 2, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 74 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$8,500.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0840 -	- Total						\$0.00	
	0850	60 CONDUIT, 2 IN., RIGID, IN TRENCH	Material		2	Apr 4, 2022	SYSTEM	\$3,064.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$3,064.50)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0850 -	- Total	Material - Tota					\$0.00 \$0.00	
	<b>0850</b> - 0890	- Total MISC. ITS			4	May 2, 2022	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4		SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment
						2022 May 2,		<b>\$0.00</b> \$5,500.00	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment
				l - Total		2022 May 2,		\$0.00 \$5,500.00 (\$5,500.00)	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment
		MISC. ITS	Material	l - Total		2022 May 2,		\$0.00 \$5,500.00 (\$5,500.00)	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment
	0890	MISC. ITS	Material  Material - Tota	l - Total		2022 May 2,		\$0.00 \$5,500.00 (\$5,500.00) \$0.00	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment
	0890	MISC. ITS	Material  Material - Tota	l - Total	4	May 2, 2022	SYSTEM	\$0.00 \$5,500.00 (\$5,500.00) \$0.00 \$0.00	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment
	0890	MISC. ITS	Material  Material - Tota	l - Total	4	May 2, 2022  May 2, 2022  May 2, 2022	SYSTEM	\$0.00 \$5,500.00 (\$5,500.00) \$0.00 \$0.00 \$6,000.00	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment
	0890	MISC. ITS	Material  Material - Tota	- Total	4	May 2, 2022  May 2, 2022  May 2, 2022	SYSTEM	\$0.00 \$5,500.00 (\$5,500.00) \$0.00 \$0.00 \$6,000.00	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment
	0890	MISC. ITS  Total  MISC. ITS	Material  Material - Tota	- Total	4	May 2, 2022  May 2, 2022  May 2, 2022	SYSTEM	\$0.00 \$5,500.00 (\$5,500.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment
	0890 0890 - 0900	MISC. ITS  Total  MISC. ITS	Material - Tota  Material - Tota	- Total	4	May 2, 2022  May 2, 2022  May 2, 2022	SYSTEM	\$0.00 \$5,500.00 (\$5,500.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment
	0890 - 0900 -	MISC. ITS  Total  MISC. ITS	Material - Tota  Material - Tota  Material - Tota	- Total	4	May 2, 2022  May 2, 2022  May 2, 2022  May 2, 2022	SYSTEM SYSTEM SYSTEM	\$0.00 \$5,500.00 (\$5,500.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment
	0890 - 0900 -	MISC. ITS  Total  MISC. ITS	Material - Tota  Material - Tota  Material - Tota	- Total	4 4 2	2022 May 2, 2022 May 2, 2022 May 2, 2022 Apr 4, 2022	SYSTEM  SYSTEM  SYSTEM	\$0.00 \$5,500.00 (\$5,500.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00) \$0.00 \$0.00 \$13,440.00	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment
	0890 - 0900 -	MISC. ITS  Total  MISC. ITS	Material - Tota  Material - Tota  Material - Tota	- Total	4 4 2	2022 May 2, 2022 May 2, 2022 May 2, 2022 Apr 4, 2022	SYSTEM  SYSTEM  SYSTEM	\$0.00 \$5,500.00 (\$5,500.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00) \$0.00 \$0.00 \$13,440.00	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment
	0890 - 0900 -	MISC. ITS  Total  MISC. ITS	Material - Tota  Material - Tota  Material - Tota  Material - Tota	- Total	4 4 2	2022 May 2, 2022 May 2, 2022 May 2, 2022 Apr 4, 2022	SYSTEM  SYSTEM  SYSTEM	\$0.00 \$5,500.00 (\$5,500.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00) \$0.00 \$13,440.00 (\$13,440.00)	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment
	0890 - 0890 - 0900 - 0930 - 09	MISC. ITS  Total  MISC. ITS	Material - Tota  Material - Tota  Material - Tota  Material - Tota	- Total	4 4 2	2022 May 2, 2022 May 2, 2022 May 2, 2022 Apr 4, 2022	SYSTEM  SYSTEM  SYSTEM	\$0.00 \$5,500.00 (\$5,500.00) \$0.00 \$0.00 \$6,000.00 (\$6,000.00) \$0.00 \$0.00 \$13,440.00 (\$13,440.00)	Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
009	0960	BRIDGE	Material			2022			
		APPROACH SLAB (MAJOR ROAD)			10	Aug 2, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$45,336.20)	
					11	Aug 16, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0076) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$45,336.20)	
					12	Sep 2, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$45,336.20)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0960 -	Total						\$0.00	
	0970	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$51,220.00)	
					6	Jun 1, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$51,220.00)	
					7	Jun 16, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$51,220.00)	
					8	Jul 1, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$51,220.00)	
					9	Jul 18, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$51,220.00)	
					10	Aug 2, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$51,220.00)	
					11	Aug 16, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0077) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$51,220.00)	
					12	Sep 2, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$51,220.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0970 -	Total						\$0.00	
	0980	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					5	May 16,	SYSTEM		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0980	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		6	Jun 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$20,544.00)	
					7	Jun 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$20,544.00)	
					8	Jul 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$20,544.00)	
					9	Jul 18, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$20,544.00)	
					10	Aug 2, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$20,544.00)	
					11	Aug 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0078) due to user vohsr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$20,544.00)	
					12	Sep 2, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$20,544.00)	
				- Total				\$0.00	
	0980 -	Total	Material - Tota					\$0.00 \$0.00	
	1040	CLASS B CONCRETE (SUBSTRUCTURE)	Material		5	May 16, 2022	SYSTEM	\$13,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$13,760.00)	
					6	Jun 1, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
									Estimate Exception 20 on the current raymont Estimate.
					6	Jun 1, 2022	SYSTEM	(\$80,324.00)	Edulate Exception 20 of the darker dynamic Edulate.
					7		SYSTEM	(\$80,324.00) \$80,324.00	This adjustment offsets the original system-generated Material Payment
						2022 Jun 16,			This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment
					7	Jun 16, 2022 Jun 16,	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment
					7	Jun 16, 2022 Jun 16, 2022 Jun 16, 2022 Jul 1,	SYSTEM SYSTEM	\$80,324.00 (\$80,324.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment
					7 7 8	Jun 16, 2022 Jun 16, 2022 Jul 1, 2022 Jul 1,	SYSTEM SYSTEM	\$80,324.00 (\$80,324.00) \$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment
					7 7 8 8	Jun 16, 2022 Jun 16, 2022 Jul 1, 2022 Jul 1, 2022 Jul 1, 2022 Jul 18,	SYSTEM SYSTEM SYSTEM SYSTEM	\$80,324.00 (\$80,324.00) \$80,324.00 (\$80,324.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment
					7 7 8 8	2022 Jun 16, 2022 Jun 16, 2022 Jul 1, 2022 Jul 1, 2022 Jul 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$80,324.00 (\$80,324.00) \$80,324.00 (\$80,324.00) \$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment



CONCRETE (SUBSTRUCTURE)	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
2022   12   Sap 2   SYSTEM   \$80,324.00   This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0021) due to user vohert overridding Paym Estimate Item Adjustment (0021) due to user vohert overridding Paym Estimate Item Adjustment (0021) due to user vohert overridding Paym Estimate Item Adjustment (0021) due to user vohert overridding Paym Estimate Item Adjustment (0021) due to user vohert overridding Paym Estimate Item Adjustment generated Stockpile Transaction Stockpile	J4P3009	1040	CONCRETE	Material		11		SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0079) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.									
2022   Estimate Item Adjustment (0021) due to user vohsr1 overridding Payme Estimate Exception 48 on the current Payment Estimate.						11		SYSTEM	(\$80,324.00)										
Total   So.00   Material - Total   So.00						12		SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.									
Material - Total   S0.00						12		SYSTEM	(\$80,324.00)										
Type D BARRIER   Construction   Stockpile   -Total   (\$6,593.71)   Payment Estimate Item Adjustment generated Stockpile Transaction   Stockpile   -Total   (\$6,593.71)					- Total				\$0.00										
TYPE D BARRIER Construction Stockpile  Total  Construction Stockpile - Total  Construction Stockpile STMI - Total  Construction Stockpile STMI - Total  Material  9 Jul 18, 2022  SYSTEM \$6,593.71  Construction Stockpile STMI - Total  SYSTEM \$52,020.00  This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.  9 Jul 18, 2022  10 Aug 2, 2022  SYSTEM \$52,020.00  This adjustment offsets the original system-generated Material Payme Estimate Exception 36 on the current Payment Estimate.  10 Aug 16, 2022  11 Aug 16, 2022  SYSTEM \$52,020.00  This adjustment offsets the original system-generated Material Payme Estimate Exception 36 on the current Payment Estimate.  11 Aug 16, 2022  SYSTEM \$52,020.00  This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.  11 Aug 16, 2022  SYSTEM \$52,020.00  This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.  12 Sep 2, SYSTEM \$52,020.00  This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.				Material - Tota	al				\$0.00										
Construction Stockpile				:			1.140	0)/0751/		B 45 5 4 5 4 5 4 5 4 5 5 5									
Construction Stockpile - Total  Construction Stockpile STMI		1050	TYPE D BARRIER			9		SYSTEM	(\$6,593.71)	Payment Estimate Item Adjustment generated Stockpile Transaction									
Construction Stockpile STMI  Total  Se,593.71  Construction Stockpile STMI - Total  9 Jul 18, 2022  10 Aug 2, 2022  11 Aug 16, 2022  11 Aug 16, 2022  12 Sep 2, 12 Sep 2, 12 Sep 2, 2022  12 Sep 2, 2022  13 Se,593.71  Payment Estimate Item Adjustment generated Stockpile Transaction Section of Section and Item Adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0002) due to user voher1 overridding Paym Estimate Exception 48 on the current Payment Estimate.  Payment Estimate Item Adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0014) due to user voher1 overridding Paym Estimate Exception 38 on the current Payment Estimate.  System (\$52,020.00)  This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0080) due to user voher1 overridding Paym Estimate Exception 48 on the current Payment Estimate.  System (\$52,020.00)  This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0080) due to user voher1 overridding Paym Estimate Item Adjustment (0022) due to user voher1 overridding Payme Estimate Item Adjustment (0022) due to user voher1 overridding Payme Estimate Item Adjustment (0022) due to user voher1 overridding Payme Estimate Item Adjustment (0022) due to user voher1 overridding Payme Estimate Item Adjustment (0022) due to user voher1 overridding Payme Estimate Item Adjustment (0022) due to user voher1 overridding Payme Estimate Item Adjustment (0022) due to user voher1 overridding Payme Estimate Item Adjustment (0022) due to user voher1 overridding Payme Estimate Item Adjustment (0022) due to u					- Total				(\$6,593.71)										
Stockpile   STMI   -Total   \$6,593.71					Stockpile - To														
Construction Stockpile STMI - Total    9				Stockpile		4		SYSTEM	\$6,593.71	Payment Estimate Item Adjustment generated Stockpile Transaction									
Material  9 Jul 18, 2022 SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0002) due to user vohsr1 overridding Payme Estimate Exception 48 on the current Payment Estimate.  9 Jul 18, 2022 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0014) due to user vohsr1 overridding Payme Estimate Exception 38 on the current Payment Estimate.  10 Aug 2, 2022 SYSTEM (\$52,020.00)  11 Aug 16, 2022 SYSTEM \$52,020.00  12 Sep 2, SYSTEM (\$52,020.00)  13 Aug 16, 2022 SYSTEM (\$52,020.00)  14 Aug 16, 2022 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0080) due to user vohsr1 overridding Payme Estimate Exception 48 on the current Payment Estimate.  11 Aug 16, 2022 SYSTEM (\$52,020.00)  12 Sep 2, SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.  12 Sep 2, SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym				SIMI	- Total				\$6,593.71										
Estimate Item Adjustment (0002) due to user vohsr1 overridding Paym Estimate Exception 48 on the current Payment Estimate.  9 Jul 18, 2022 10 Aug 2, 2022 SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payme Estimate Exception 38 on the current Payment Estimate.  10 Aug 2, 2022 SYSTEM (\$52,020.00)  11 Aug 16, 2022 SYSTEM \$52,020.00 This adjustment (0014) due to user vohsr1 overridding Paym Estimate Exception 38 on the current Payment Estimate.  11 Aug 16, 2022 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0080) due to user vohsr1 overridding Paym Estimate Exception 48 on the current Payment Estimate.  11 Aug 16, 2022 This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.  12 Sep 2, 2022 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to use				Construction	Stockpile STI	VII - Total			\$6,593.71										
2022  10 Aug 2, 2022  10 Aug 2, 2022  10 Aug 2, 2022  10 Aug 2, 2022  11 Aug 16, 2022  12 Sep 2, 2022  12 Sep 2, 2022  13 Aug 2, SYSTEM \$52,020.00  14 This adjustment offsets the original system-generated Material Payme Estimate Exception 38 on the current Payment Estimate.  17 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0080) due to user vohsr1 overridding Payme Estimate Exception 48 on the current Payment Estimate.  18 Sep 2, SYSTEM \$52,020.00  19 This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.  10 Aug 16, 2022  11 Aug 16, 2022  12 Sep 2, SYSTEM \$52,020.00  13 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022)				Material		9		SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.									
Estimate Item Adjustment (0014) due to user vohsr1 overridding Paym Estimate Exception 38 on the current Payment Estimate.  10 Aug 2, 2022  11 Aug 16, 2022  12 Sep 2, 2022  Estimate Item Adjustment (0014) due to user vohsr1 overridding Payme Estimate Item Adjustment (0080) due to user vohsr1 overridding Payme Estimate Exception 48 on the current Payment Estimate.  11 Aug 16, 2022  12 Sep 2, SYSTEM \$52,020.00  This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.								9		SYSTEM	(\$52,020.00)								
2022  11 Aug 16, 2022  12 Aug 16, SYSTEM \$52,020.00  13 Aug 16, SYSTEM \$52,020.00  14 Aug 16, SYSTEM \$52,020.00  15 System \$52,020.00  16 System \$52,020.00  17 This adjustment offsets the original system-generated Material Payme Estimate Exception 48 on the current Payment Estimate.  12 Sep 2, System \$52,020.00  13 System \$52,020.00  14 Sep 2, System \$52,020.00  15 System \$52,020.00  16 System \$52,020.00  17 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Payme Estimate Item Adjustment (0020) due to user vohsr1 overridding Payme Estimate Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr1 overridding Payme Item Adjustment (0020) due to user vohsr2 overridding Payme Item Adjustment (0020) due to user vohsr2 overridding Payme Item Adjustment (0020) due to user vohsr2 overridding Payme Item Adjustment (0020) due to user vohsr2 overridding Payme Item Adjustment (0020) due to user vohsr2 overridding Payme Item Adjustment (0020) due to user vohsr2 overridding								10		SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.							
20Ž2 Estimate Item Adjustment (0080) due to user vohsr1 overridding Paym Estimate Exception 48 on the current Payment Estimate.  11 Aug 16, 2022 (\$52,020.00)  12 Sep 2, SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym								10		SYSTEM	(\$52,020.00)								
2022  12 Sep 2, SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym						11		SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0080) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.									
2022 Estimate Item Adjustment (0022) due to user vohsr1 overridding Paym						11		SYSTEM	(\$52,020.00)										
Estimate Exception 32 on the current Payment Estimate.						12		SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate.									
12 Sep 2, SYSTEM (\$52,020.00)						12		SYSTEM	(\$52,020.00)										
- Total \$0.00									\$0.00										
Material - Total \$0.00				Material - Tota	al														
1050 - Total \$0.00		1050 -	Total						\$0.00										
		1060	CONCRETE NU-	Material		7		SYSTEM	\$144,235.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.									
7 Jun 16, SYSTEM (\$144,235.20)						7		SYSTEM	(\$144,235.20)										
						8		SYSTEM	\$186,303.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment Estimate Exception 33 on the current Payment Estimate									
8 Jul 1, 2022 (\$186,303.80)														8			SYSTEM	(\$186,303.80)	Estimate Exception 55 on the current rayment Estimate.
					9 10	9		SYSTEM	\$186,303.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 56 on the current Payment Estimate.									
9 Jul 18, 2022 (\$186,303.80)						9		SYSTEM	(\$186,303.80)										
						10	10	10		SYSTEM	\$186,303.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.							
10 Aug 2, SYSTEM (\$186,303.80)						10		SYSTEM	(\$186,303.80)										
						11		SYSTEM	\$216,352.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0081) due to user vohsr1 overridding Payment									



		5	A 11	6						
	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
9 ′	1060	SLAB ON	Material						Estimate Exception 52 on the current Payment Estimate.	
		CONCRETE NU- GIRDER			11	Aug 16,	SYSTEM	(\$216,352.80)		
					12	2022 Sep 2,	SYSTEM	\$240,392.00	This adjustment offsets the original system-generated Material Payment	
						2022			Estimate Item Adjustment (0023) due to user voher1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	
					12	Sep 2, 2022	SYSTEM	(\$240,392.00)		
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
1	1060 -	Total						\$0.00		
,	1080	NU 35, PRESTRESSED	Construction Stockpile		7	Jun 16, 2022	SYSTEM	(\$36,307.98)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		CONC NU-GIRDER		- Total				(\$36,307.98)		
			Construction	Stockpile - To	otal			(\$36,307.98)		
			Construction Stockpile		4	May 2, 2022	SYSTEM	\$36,307.98	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STMI	- Total				\$36,307.98		
			Construction	Stockpile STI	VII - Total			\$36,307.98		
-	1080 -	Total						\$0.00		
•	1090	REINFORCING STEEL (BRIDGES)	Construction Stockpile		6	Jun 1, 2022	SYSTEM	(\$6,607.60)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total						
			Construction	Stockpile - To	otal			(\$6,607.60)		
			Construction Stockpile		4	May 2, 2022	SYSTEM	\$6,607.60	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STMI	- Total				\$6,607.60		
			Construction	Stockpile STI	VII - Total			\$6,607.60		
1	1090 -	Total						\$0.00		
•	1100	REINFORCING STEEL (EPOXY	REINFORCING C	Construction Stockpile		5	May 16, 2022	SYSTEM	(\$5,333.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
		COATED)				6	Jun 1, 2022	SYSTEM	(\$11,868.91)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$17,202.66)		
			Construction	onstruction Stockpile - Total						
				Construction Stockpile		4	May 2, 2022	SYSTEM	\$17,202.66	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$17,202.66		
			Construction	Stockpile STI	MI - Total			\$17,202.66		
•	1100 -	Total						\$0.00		
•	1140	VERTICAL DRAIN AT END BENTS	Material		8	Jul 1, 2022	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user vohsr1 overridding Payment Estimate Exception 42 on the current Payment Estimate.	
					8	Jul 1, 2022	SYSTEM	(\$6,000.00)		
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
ŀ	1140 -	Total						\$0.00		
•	1200	APPROACH SLAB	Material		9	Jul 18, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user voher1 overridding Payment	
		(MAJOR ROAD)			9	Jul 18,	SYSTEM	(\$45,336.20)	Estimate Exception 15 on the current Payment Estimate.	
					10	2022 Aug 2	QVCTFM	¢4E 226 20	This adjustment offsets the original austern generated Metarial Payment	
				10	Aug 2, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
					10 Aug 2, 2022					
					10		SYSTEM	(\$45,336.20)		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
4P3009	1200	BRIDGE APPROACH SLAB	Material		11	Aug 16, 2022	SYSTEM	(\$45,336.20)										
		(MAJOR ROAD)			12	Sep 2, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
					12	Sep 2, 2022	SYSTEM	(\$45,336.20)										
				- Total				\$0.00										
			Material - Tota	ı				\$0.00										
	1200 -	Total						\$0.00										
	1210	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.									
					5	May 16, 2022	SYSTEM	(\$43,340.00)										
					6	Jun 1, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.									
					6	Jun 1, 2022	SYSTEM	(\$43,340.00)										
					7	Jun 16, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.									
					7	Jun 16, 2022	SYSTEM	(\$43,340.00)										
					8	Jul 1, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
					8	Jul 1, 2022	SYSTEM	(\$43,340.00)										
														9	Jul 18, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
									9	Jul 18, 2022	SYSTEM	(\$43,340.00)						
						10	Aug 2, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.								
					10	Aug 2, 2022	SYSTEM	(\$43,340.00)										
					11	Aug 16, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0083) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.									
					11	Aug 16, 2022	SYSTEM	(\$43,340.00)										
					12	Sep 2, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 42 on the current Payment Estimate.									
					12	Sep 2, 2022	SYSTEM	(\$43,340.00)										
				- Total				\$0.00										
			Material - Tota	ı				\$0.00										
	1210 -	Total						\$0.00										
	1220	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
					5	May 16, 2022	SYSTEM	(\$20,544.00)										
					6	Jun 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
					6	Jun 1, 2022	SYSTEM	(\$20,544.00)										
					7	Jun 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.									
					7	Jun 16,	SYSTEM	(\$20,544.00)										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	1220	ROCK SOCKETS	Material	. ,,,,,		2022			
		(3 FT 6 IN. DIA.)			8	Jul 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$20,544.00)	
					9	Jul 18, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$20,544.00)	
					10	Aug 2, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$20,544.00)	
					11	Aug 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0084) due to user vohsr1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$20,544.00)	
					12	Sep 2, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$20,544.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	1220 -	· Total						\$0.00	
	1280	80 CLASS B CONCRETE (SUBSTRUCTURE)	Material		5	May 16, 2022	SYSTEM	\$13,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$13,920.00)	
					6	Jun 1, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$80,127.00)	
					7	Jun 16, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$80,127.00)	
					8	Jul 1, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user vohsr1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$80,127.00)	
					9	Jul 18, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$80,127.00)	
					10	Aug 2, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$80,127.00)	
					11	Aug 16, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0085) due to user vohsr1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$80,127.00)	
					12	Sep 2, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					12	Sep 2,	SYSTEM	(\$80,127.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4P3009	1280	CLASS B	Material			2022					
		CONCRETE (SUBSTRUCTURE)		- Total				\$0.00			
			Material - Tota	I				\$0.00			
	1280 -	Total						\$0.00			
	1290	TYPE D BARRIER	Construction Stockpile		9	Jul 18, 2022	SYSTEM	(\$6,593.71)	Payment Estimate Item Adjustment generated Stockpile Transaction		
				- Total				(\$6,593.71)			
			Construction S	Stockpile - To	otal			(\$6,593.71)			
			Construction		4	May 2,	SYSTEM	\$6,593.71	Payment Estimate Item Adjustment generated Stockpile Transaction		
			Stockpile STMI			2022					
				- Total				\$6,593.71			
			Construction S	Stockpile STI	VII - Total			\$6,593.71			
			Material		9	Jul 18, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate.		
					9	Jul 18, 2022	SYSTEM	(\$52,020.00)			
					10	Aug 2, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 41 on the current Payment Estimate.		
							10	Aug 2, 2022	SYSTEM	(\$52,020.00)	
					11	Aug 16, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0086) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.		
					11	Aug 16, 2022	SYSTEM	(\$52,020.00)			
							12	Sep 2, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$52,020.00)			
				- Total				\$0.00			
			Material - Tota	1				\$0.00			
	1290 -	Total						\$0.00			
	1300	SLAB ON CONCRETE NU-	RETE NU- Stockpile		7	Jun 16, 2022	SYSTEM	(\$16,335.42)	Payment Estimate Item Adjustment generated Stockpile Transaction		
		GIRDER			8	Jul 1, 2022	SYSTEM	(\$18,150.47)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					11	Aug 16, 2022	SYSTEM	(\$1,815.05)	Payment Estimate Item Adjustment generated Stockpile Transaction		
				- Total				(\$36,300.94)			
			Construction S	Stockpile - <u>T</u> c	otal			(\$36,300.94)			
			Construction Stockpile		4	May 2, 2022	SYSTEM	\$36,300.94	Payment Estimate Item Adjustment generated Stockpile Transaction		
			STMI	- Total				\$36,300.94			
			Construction S		MI - Total			\$36,300.94			
			Material		7	Jun 16, 2022	SYSTEM	\$108,176.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.		
					7	Jun 16, 2022	SYSTEM	(\$108,176.40)			
					8	Jul 1, 2022	SYSTEM	\$228,372.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.		
					8	Jul 1, 2022	SYSTEM	(\$228,372.40)			
					9	Jul 18, 2022	SYSTEM	\$228,372.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 61 on the current Payment Estimate.		
					9	Jul 18, 2022	SYSTEM	(\$228,372.40)			
					10	Aug 2, 2022	SYSTEM	\$228,372.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment		



J4P3009 1300 SLAB ON CONCRETE NU-GIRDER 10 Aug 2, 2022 SYSTEM (\$228,372.40) Estimate Exception 47 on the current Payment Estimate.  10 Aug 2, 2022 This adjustment offsets the original system-generated Material Parameter (0087) due to user vohsr1 overridding Fastimate Exception 54 on the current Payment Estimate.  11 Aug 16, 2022 SYSTEM (\$240,392.00) Estimate Exception 54 on the current Payment Estimate.  11 Aug 16, 2022 SYSTEM (\$240,392.00) This adjustment offsets the original system-generated Material Parameter (0087) due to user vohsr1 overridding Fastimate (1088) due to user vohsr1 overridding Fa	
GIRDER  10 Aug 2, 2022  11 Aug 16, 2022  11 Aug 16, 2022  12 Sep 2, SYSTEM (\$240,392.00 This adjustment offsets the original system-generated Material Pa Estimate Exception 54 on the current Payment Estimate.  11 Aug 16, 2022  12 Sep 2, SYSTEM \$240,392.00 This adjustment offsets the original system-generated Material Pa Estimate Exception 54 on the current Payment Estimate.	
2022 Estimate Item Adjustment (0087) due to user vohsr1 overridding F Estimate Exception 54 on the current Payment Estimate.  11 Aug 16, 2022  12 Sep 2, SYSTEM \$240,392.00 This adjustment offsets the original system-generated Material Pa	
2022  12 Sep 2, SYSTEM \$240,392.00 This adjustment offsets the original system-generated Material Pa	
Estimate Exception 58 on the current Payment Estimate.	
12 Sep 2, 2022 SYSTEM (\$240,392.00)	
- Total \$0.00	
Material - Total \$0.00	
1300 - Total \$0.00	
1330 REINFORCING Construction STEEL (BRIDGES) Stockpile 6 Jun 1, 2022 (\$5,063.80) Payment Estimate Item Adjustment generated Stockpile Transact	on
- Total (\$5,063.80)	
Construction Stockpile - Total (\$5,063.80)	
Construction 4 May 2, SYSTEM \$5,063.80 Payment Estimate Item Adjustment generated Stockpile Transact STMI	on
- Total \$5,063.80	
Construction Stockpile STMI - Total \$5,063.80	
1330 - Total \$0.00	
1380 VERTICAL DRAIN AT END BENTS  8 Jul 1, 2022  8 SySTEM \$6,000.00 This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0042) due to user vohsr1 overridding Festimate Exception 43 on the current Payment Estimate.	
8 Jul 1, 2022 (\$6,000.00)	
- Total \$0.00	
Material - Total \$0.00	
1380 - Total \$0.00	
1440 MECHANICALLY Construction 5 May 16, SYSTEM (\$777.26) Payment Estimate Item Adjustment generated Stockpile Transact 2022 EARTH WALL SYS	
6 Jun 1, 2022 (\$86.36) Payment Estimate Item Adjustment generated Stockpile Transact	on
- Total (\$863.62)	
Construction Stockpile - Total (\$863.62)  Construction 4 May 2, SYSTEM \$863.62 Payment Estimate Item Adjustment generated Stockpile Transact Stockpile No	on
Transaction Type - Total \$863.62	
Construction Stockpile No Transaction Type - Total \$863.62	
Material 5 May 16, SYSTEM \$252,147.60 This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0032) due to user vohsr1 overridding F Estimate Exception 29 on the current Payment Estimate.	
2022 Estimate Item Adjustment (0032) due to user vohsr1 overridding F	
2022 Estimate Item Adjustment (0032) due to user vohsr1 overridding F Estimate Exception 29 on the current Payment Estimate.  5 May 16, SYSTEM (\$252,147.60)	
2022 Estimate Item Adjustment (0032) due to user vohsr1 overridding F Estimate Exception 29 on the current Payment Estimate.  5 May 16, 2022  6 Jun 1, SYSTEM \$280,164.00 This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0030) due to user vohsr1 overridding F	
Estimate Item Adjustment (0032) due to user vohsr1 overridding F Estimate Exception 29 on the current Payment Estimate.  May 16, 2022  May 16, 2022  System (\$252,147.60)  Jun 1, 2022  System \$280,164.00  This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0030) due to user vohsr1 overridding F Estimate Exception 29 on the current Payment Estimate.	yment
Estimate Item Adjustment (0032) due to user vohsr1 overridding F Estimate Exception 29 on the current Payment Estimate.  5 May 16, 2022  6 Jun 1, 2022  8 SYSTEM \$280,164.00 This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0030) due to user vohsr1 overridding F Estimate Exception 29 on the current Payment Estimate.  6 Jun 1, 2022  7 Jun 16, 2022  7 Jun 16, 2022  7 Jun 16, SYSTEM \$280,164.00 This adjustment offsets the original system-generated Material Pa Estimate Item Adjustment (0032) due to user vohsr1 overridding F Estimate Item Adjustment (0032) due to user vohsr1 overridding F Estimate Exception 38 on the current Payment Estimate.	wment
Estimate Item Adjustment (0032) due to user vohsr1 overridding F.  May 16, 2022  May 16, 2022  SYSTEM (\$252,147.60)  This adjustment offsets the original system-generated Material Patestimate Exception 29 on the current Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding F.  Jun 1, 2022  SYSTEM (\$280,164.00)  Jun 16, 2022  This adjustment offsets the original system-generated Material Patestimate Exception 29 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Patestimate Item Adjustment (0032) due to user vohsr1 overridding F.  SYSTEM (\$280,164.00)  This adjustment offsets the original system-generated Material Patestimate Item Adjustment (0032) due to user vohsr1 overridding F.  SYSTEM (\$280,164.00)  This adjustment offsets the original system-generated Material Patestimate Item Adjustment (0032) due to user vohsr1 overridding F.	/ment ayment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J4P3009	1440	MECHANICALLY STABILIZED EARTH WALL SYS	Material		9	Jul 18, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 65 on the current Payment Estimate.					
					9	Jul 18, 2022	SYSTEM	(\$280,164.00)						
					10	Aug 2, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.					
					10	Aug 2, 2022	SYSTEM	(\$280,164.00)						
					11	Aug 16, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0088) due to user vohsr1 overridding Payment Estimate Exception 56 on the current Payment Estimate.					
					11	Aug 16, 2022	SYSTEM	(\$280,164.00)	, ,					
					12	Sep 2, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 61 on the current Payment Estimate.					
					12	Sep 2,	SYSTEM	(\$280,164.00)	Estimate Exception of on the current Payment Estimate.					
				- Total		2022		\$0.00						
			Material - Tota					\$0.00						
	1440 -	Total						\$0.00						
	1470	MECHANICALLY STABILIZED	Construction Stockpile		5	May 16, 2022	SYSTEM	(\$863.61)	Payment Estimate Item Adjustment generated Stockpile Transaction					
		EARTH WALL SYS	Construction S	- Total				(\$863.61)						
			Construction S	Stockpile - To	otal			(\$863.61)						
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$863.61	Payment Estimate Item Adjustment generated Stockpile Transaction					
				- Total				\$863.61						
			Construction Material		Stockpile STI	MI - Total			\$863.61					
			Material		5	May 16, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.					
					5	May 16, 2022	SYSTEM	(\$256,650.00)						
					6	Jun 1, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.					
					6	Jun 1, 2022	SYSTEM	(\$256,650.00)						
					7	Jun 16, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.					
					7	Jun 16, 2022	SYSTEM	(\$256,650.00)						
					8	Jul 1, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user vohsr1 overridding Payment Estimate Exception 47 on the current Payment Estimate.					
					8	Jul 1, 2022	SYSTEM	(\$256,650.00)	,					
			9						9	9	Jul 18, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
				9	Jul 18, 2022	SYSTEM	(\$256,650.00)							
					10	Aug 2, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate.					
					10	Aug 2,	SYSTEM	(\$256,650.00)						
					11	2022 Aug 16, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0089) due to user vohsr1 overridding Payment					
					11	Aug 16,	SYSTEM	(\$256,650.00)	Estimate Exception 58 on the current Payment Estimate.					
						2022		(+===,000.00)						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	1470	MECHANICALLY STABILIZED EARTH WALL SYS	Material		12	Sep 2, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$256,650.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	1470 -	Total						\$0.00	
	5005	POST ANCHOR FOR 2 IN. PSST - 7 GA.	Construction Stockpile STMI	- Total	11	Aug 16, 2022	SYSTEM	\$151.20 \$151.20	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction S		/II Total			\$151.20	
	5005 -	Total	Construction	otockpile o i i	m - Total			\$151.20	
	5006	2.5 IN. PSST POST - 12 GA.	Construction Stockpile		11	Aug 16, 2022	SYSTEM	\$1,163.80	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$1,163.80	
			Construction S	Stockpile STI	/II - Total			\$1,163.80	
	5006 -	Total						\$1,163.80	
	5007	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Construction Stockpile STMI		11	Aug 16, 2022	SYSTEM	\$681.60	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$681.60	
			Construction S	Stockpile STI	/II - Total			\$681.60	
	5007 -		-					\$681.60	
	5008	BREAKAWAY ASSEMBLY (PERFORATED	Construction Stockpile STMI	- Total	11	Aug 16, 2022	SYSTEM	\$2,217.20 \$2,217.20	Payment Estimate Item Adjustment generated Stockpile Transaction
		SQUARE STEEL TUBE)	Construction S		/II - Total			\$2,217.20	
	5008 -	Total						\$2,217.20	
J4P3009 -	Total							\$66,736.11	
J4P3009B	1520	TYPE 5 AGGREGATE FOR BASE	Material		12	Sep 2, 2022	SYSTEM	\$4,556.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		B/IOE			12	Sep 2, 2022	SYSTEM	(\$4,556.00)	
				- Total				\$0.00	
			Material - Tota	<u> </u>				\$0.00	
	1520 -	Total						\$0.00	
	1530	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		11	Aug 16, 2022	SYSTEM	\$2,704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0090) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		THICK)			11	Aug 16, 2022	SYSTEM	(\$2,704.00)	
					12	Sep 2, 2022	SYSTEM	\$6,944.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$6,944.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1530 -	***						\$0.00	
	1540	MISC.	Material		4	May 2, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$2,688.00)	
					5	May 16, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$2,688.00)	
					6	Jun 1,	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009B	1540	MISC.	Material			2022			Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$2,688.00)	
					7	Jun 16, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$2,688.00)	
					8	Jul 1, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$2,688.00)	
					9	Jul 18, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$2,688.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1540 -	· Total						\$0.00	
	1600	CONCRETE MEDIAN	Material		12	Sep 2, 2022	SYSTEM	\$22,470.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$22,470.54)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1600 -	· Total						\$0.00	
	1640	CONCRETE SIDEWALK, 4 IN.	Material		11	Aug 16, 2022	SYSTEM	\$15,574.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0091) due to user vohsr1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$15,574.20)	
					12	Sep 2, 2022	SYSTEM	\$15,574.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$15,574.20)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1640 -	· Total						\$0.00	
	1650	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	Material		11	Aug 16, 2022	SYSTEM	\$12,162.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0092) due to user vohsr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$12,162.15)	
					12	Sep 2, 2022	SYSTEM	\$31,046.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$31,046.40)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1650 -	· Total						\$0.00	
	1660	CURB AND GUTTER TYPE B	Material		9	Jul 18, 2022	SYSTEM	\$19,733.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$19,733.15)	
					10	Aug 2, 2022	SYSTEM	\$19,733.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					10	Aug 2,	SYSTEM	(\$19,733.15)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3009B	1660	CURB AND	Material			2022				
		GUTTER TYPE B			11	Aug 16, 2022	SYSTEM	\$19,733.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0093) due to user vohsr1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	
					11	Aug 16, 2022	SYSTEM	(\$19,733.15)		
					12	Sep 2, 2022	SYSTEM	\$19,733.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user vohsr1 overridding Payment	
					12	Sep 2, 2022	SYSTEM	(\$19,733.15)	Estimate Exception 32 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1660 -	· Total						\$0.00		
	1700	MISC. PAVED DRAINAGE	Material		12	Sep 2, 2022	SYSTEM	\$7,477.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
					12	Sep 2, 2022	SYSTEM	(\$7,477.80)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1700 -	·Total						\$0.00		
	1880	TEMPORARY NON-REMOVABLE TAPE LT/RT ARROW	Material		4	May 2, 2022	SYSTEM	\$920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					4	May 2, 2022	SYSTEM	(\$920.00)		
			- Total					\$0.00		
			Material - Tota					\$0.00		
	1880 -	· Total						\$0.00		
	2200	CABLE, 8 AWG 1 CONDUCTOR	Material		6	Jun 1, 2022	SYSTEM	\$1,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	
					6	Jun 1, 2022	SYSTEM	(\$1,140.00)		
				- Total				\$0.00 \$0.00		
	0000		Material - Total							
	2200 -	MISC. HIGHWAY LIGHTING	Material		11	Aug 16, 2022	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0094) due to user vohsr1 overridding Payment Estimate Exception 60 on the current Payment Estimate.	
					11	Aug 16, 2022	SYSTEM	(\$2,400.00)		
						12	Sep 2, 2022	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user vohsr1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$4,800.00)		
				- Total				\$0.00		
			Material - Total					\$0.00		
	2250 -	250 - Total								
	2320	SH-FLAT SHEET - SIGNAL SIGN			12	Sep 2, 2022	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user vohsr1 overridding Payment Estimate Exception 67 on the current Payment Estimate.	
					12	Sep 2, 2022	SYSTEM	(\$3,360.00)		
				- Total				\$0.00		
	Material - Total							\$0.00		
							a. ( = =	\$0.00		
	2360	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material		12	Sep 2, 2022	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user vohsr1 overridding Payment Estimate Exception 68 on the current Payment Estimate.	
					12	Sep 2,	SYSTEM	(\$15,000.00)		



Type Type	narks
3009B 2360 POST, TYPE C, 50 Material 2022 FT. ARM OR 15.2	
- Total \$0.00	
Material - Total \$0.00	
2360 - Total \$0.00	
2470 BASE, CONCRETE Material  12 Sep 2, 2022  SYSTEM \$13,000.00 This adjustment offsets the original system Estimate Item Adjustment (0042) due to Estimate Exception 70 on the current Particular Systems (10042) and the current Systems (1004	user vohsr1 overridding Payment
12 Sep 2, 2022 SYSTEM (\$13,000.00)	
- Total \$0.00	
Material - Total \$0.00	
2470 - Total \$0.00	
2530 2 IN. PSST POST - Construction 11 Aug 16, SYSTEM \$1,967.25 Payment Estimate Item Adjustment gen 2022	erated Stockpile Transaction
- Total \$1,967.25	
Construction Stockpile STMI - Total \$1,967.25	
2530 - Total \$1,967.25	
2540 SH-FLAT SHEET Construction Stockpile 2022 \$596.30 Payment Estimate Item Adjustment gen	erated Stockpile Transaction
- Total \$596.30	
Construction Stockpile STMI - Total \$596.30	
2540 - Total \$596.30	
2550 ST-STRUCTURAL Construction Stockpile STMI 11 Aug 16, 2022 SYSTEM \$4,261.00 Payment Estimate Item Adjustment gen	erated Stockpile Transaction
- Total \$4,261.00	
Construction Stockpile STMI - Total \$4,261.00	
2550 - Total \$4,261.00	
2560 SHF-FLAT SHEET Construction FLUORESCENT Stockpile STMI 11 Aug 16, SYSTEM \$196.20 Payment Estimate Item Adjustment gen	erated Stockpile Transaction
- Total \$196.20	
Construction Stockpile STMI - Total \$196.20	
2560 - Total \$196.20	
5009 POST ANCHOR Construction 11 Aug 16, SYSTEM \$263.55 Payment Estimate Item Adjustment gen FOR 2 IN. PSST - Stockpile 12 GA. STMI	erated Stockpile Transaction
- Total \$263.55	
Construction Stockpile STMI - Total \$263.55	
5009 - Total \$263.55	
5010 POST ANCHOR Construction FOR 2 IN. PSST - 7 Stockpile 2022 Payment Estimate Item Adjustment gen 2022 Payment Estimate Item Adjustment gen 2022	erated Stockpile Transaction
- Total \$529.20	
Construction Stockpile STMI - Total \$529.20	
5010 - Total \$529.20	
5011 2.5 IN. PSST POST - 12 GA. STOCK STMI STATE	erated Stockpile Transaction
- Total \$341.55	
Construction Stockpile STMI - Total \$341.55	
5011 - Total \$341.55	
	erated Stockpile Transaction
5012 POST ANCHOR Construction FOR 2.5 IN. PSST - Stockpile 7 GA. STMI STMI	
FOR 2.5 IN. PSST - 7 GA. STMI - Total \$170.40	
FOR 2.5 IN. PSST - 7 GA. STMI - Total \$170.40  Construction Stockpile STMI - Total \$170.40	
FOR 2.5 IN. PSST - 7 GA. STMI - Total \$170.40  Construction Stockpile STMI - Total \$170.40  5012 - Total \$170.40	
FOR 2.5 IN. PSST - 7 GA. STMI - Total \$170.40  Construction Stockpile STMI - Total \$170.40	user vohsr1 overridding Payment
FOR 2.5 IN. PSST - 7 GA. Stockpile STMI - Total \$170.40  Construction Stockpile STMI - Total \$170.40  5012 - Total \$170.40  MISC. Material 12 Sep 2, 2022 SYSTEM \$1,001.74 This adjustment offsets the original systematic Estimate Item Adjustment (0045) due to	user vohsr1 overridding Payment

Sep 7, 2022



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009B	5013	MISC.	Material - Tota	I				\$0.00	
	5013 -	5013 - Total							
	5014	MISC.	Material		12	Sep 2, 2022	SYSTEM	\$1,480.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user vohsr1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$1,480.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5014 - Total							\$0.00	
	5015	MISC. HIGHWAY LIGHTING	Material		12	Sep 2, 2022	SYSTEM	\$4,158.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user vohsr1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$4,158.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	5015 -	Total						\$0.00	
J4P3009B - Total								\$8,325.45	
Overall - Total								\$75,061.56	