\$750,754.60



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2022

Progress Est		Contract ID Prime Contractor	211015-C03 Pyramid Contrac		ay Period Start June ay Period End June	15, 2022 Net Chan	ge Order Amount (\$5,861,477.94 \$6,720.50) \$5,854,757.44		
Approval Date								By User		
June 16, 2022			Generated and	d Approved (a	nd should be conside	red Draft) at the Proje	ect Office Level by	vohsr		
June 17, 2022		R	eviewed and App	wed and Approved (and should be considered Draft) at the Resident Engineer Level by						
June 17, 2022		Reviewed and Approved at the Central Office Controllers Office Level by								
Original Cor	npletion Date	Current Comp	oletion Date	Actual	Completion Date	pletion Date % of Current Contract Amou				
February	/ 18, 2023	February 1	18, 2023	23 48.03%						
Co	ontract Information	al Dates				Milestones				
Date Description	Original Completion Date	Current Completion Da		Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days		
Acceptance Date			Milestone - Time - Pha		September 14, 2022	September 14, 2022	88)		
Awarded Date	November 3, 202	November 3, 202	21							
Letting Date	October 15, 2021	October 15, 202	1							
Notice to	January 3, 2022	January 3, 2022								

Contract Total P	ay For Estimate No. 7			
		This Estimate	Previous	To Date
211015-C03				
	Total Posted Items Pay	\$750,754.60	\$2,061,019.25	\$2,811,773.85
	Gross Item Adjustments	(\$103,650.40)	\$156,401.24	\$52,750.84
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·		\$2,217,420.49	\$2,864,524.69
Contract Total Pa	ayable This Estimate:	\$647.104.20		

Items Paid This Estimate Period

March 28, 2022

March 28, 2022

Proceed Date Open to Traffic Date Work Began

Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3009	0020	2022010	REMOVAL OF IMPROVEMENTS	LS	\$250,000.000	0.3	\$75,000.00
	0110	3049905	MISC.OPTIONAL BASE	SQYD	\$11.000	4,637	\$51,007.00
	0210	6071102	MODIFIED CONCRETE GUTTER TYPE B	LF	\$48.000	197	\$9,456.00
	1060	7034221	SLAB ON CONCRETE NU-GIRDER	SQYD	\$398.000	362.4	\$144,235.20
	1080	7056021	NU 35, PRESTRESSED CONCRETE NU- GIRDER	LF	\$360.000	491	\$176,760.00
	1150	7161000	PLAIN NEOPRENE BEARING PAD	EA	\$200.000	8	\$1,600.00
	1160	7161002	LAMINATED NEOPRENE BEARING PAD	EA	\$385.000	8	\$3,080.00
	1300	7034221	SLAB ON CONCRETE NU-GIRDER	SQYD	\$398.000	271.8	\$108,176.40
	1320	7056021	NU 35, PRESTRESSED CONCRETE NU- GIRDER	LF	\$360.000	491	\$176,760.00
	1390	7161000	PLAIN NEOPRENE BEARING PAD	EA	\$200.000	8	\$1,600.00
	1400	7161002	LAMINATED NEOPRENE BEARING PAD	EA	\$385.000	8	\$3,080.00
Project J4P300	9 - Total						\$750,754.60

Contract Adjustments This Estimate

Overall - Total

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2022

Progress Estimate Number 7

Contract ID 211015-C03 Pay Period Start June 2, 2022 Original Contract Amount (\$5,861,477.94)
Prime Contractor Pyramid Contractors, Inc. Pay Period End June 15, 2022 Original Contract Amount (\$6,720.50)
Current Contract Amount (\$6,720.50)
\$5,854,757.44\$

								55,654,757.44
ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3009	0040	EMBANKMENT IN PLACE	Material			-601	\$20.00	(\$12,020.00
	0040	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	601	\$20.00	\$12,020.00
	0050	COMPACTING EMBANKMENT	Material			-109	\$2.50	(\$272.50
	0050	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	109	\$2.50	\$272.50
	0110	MISC.	Material			-4,637	\$11.00	(\$51,007.00)
	0130	MISC.	Material			-466	\$100.00	(\$46,600.00
	0130	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	466	\$100.00	\$46,600.00
	0140	MISC.	Material			-1,718	\$60.00	(\$103,080.00)
	0140	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1,718	\$60.00	\$103,080.00
	0210	MODIFIED CONCRETE GUTTER TYPE B	Material			-490	\$48.00	(\$23,520.00)
	0210	MODIFIED CONCRETE GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	490	\$48.00	\$23,520.00
	0840	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	Material			-1	\$8,500.00	(\$8,500.00
	0840	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.	1	\$8,500.00	\$8,500.00
	0970	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material			-52	\$985.00	(\$51,220.00
	0970	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	52	\$985.00	\$51,220.00
	0980	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material			-32	\$642.00	(\$20,544.00
	0980	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	32	\$642.00	\$20,544.00
	1040	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-93.4	\$860.00	(\$80,324.00
	1040	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1	93.4	\$860.00	\$80,324.00

Revision 4/1/2020 Page 2 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2022

Progress Estimate Number 7

Contract ID 211015-C03 Pay Period Start June 2, 2022 Original Contract Amount (\$5,861,477.94 Pay Period End June 15, 2022 Original Contract Amount (\$6,720.50) Current Contract Amount Current Contract Amount (\$6,720.50) \$5,854,757.44

					Guilo	iii Contract F		\$5,654,757.44
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3009					overridding Payment Estimate Exception 24 on the current Payment Estimate.			
	1060	SLAB ON CONCRETE NU- GIRDER	Material			-362.4	\$398.00	(\$144,235.20
	1060	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	362.4	\$398.00	\$144,235.20
	1080	NU 35, PRESTRESSED CONCRETE NU-GIRDER	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$36,307.98
	1210	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material			-44	\$985.00	(\$43,340.00
	1210	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	44	\$985.00	\$43,340.00
	1220	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material			-32	\$642.00	(\$20,544.00)
	1220	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	32	\$642.00	\$20,544.00
	1280	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-92.1	\$870.00	(\$80,127.00)
	1280	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	92.1	\$870.00	\$80,127.00
	1300	SLAB ON CONCRETE NU- GIRDER	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$16,335.42)
	1300	SLAB ON CONCRETE NU- GIRDER	Material			-271.8	\$398.00	(\$108,176.40
	1300	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	271.8	\$398.00	\$108,176.40
	1440	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-3,786	\$74.00	(\$280,164.00)
	1440	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	3,786	\$74.00	\$280,164.00
	1470	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-3,422	\$75.00	(\$256,650.00
	1470	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.	3,422	\$75.00	\$256,650.00
J4P3009B	1540	MISC.	Material			-14	\$192.00	(\$2,688.00)
	1540	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	14	\$192.00	\$2,688.00

Revision 4/1/2020 Page 3 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2022

Progress Estimate Number 7 Contract ID 211015-C03 Prime Contractor Pyramid Contractors,							Amount (\$5,861,477.94 \$6,720.50) \$5,854,757.44	
Project Number	Line No.	Item Desc	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3009B						Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
Total									(\$103,650.40)

Revision 4/1/2020 Page 4 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information	2			
						John act Froject Information	ı			
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J4P3009	FAF 50-1(54)	Bridge replacement	50	JACKSON	over Chipman Road near Lee's Summit					
J4P3009B	FAF 50-1(55)	Grading and paving	50	JACKSON	from w/o Murray Road to w/ Blue Parkway					
Totals by Jo	b Number	's								
J4P3009		l Item Pay Item Adjustme		Item Pay	This Estimate \$750,754.60 (\$103,650.40) \$647,104.20	Previous \$1,889,314.75 \$156,401.24 \$2,045,715.99	To Date \$2,640,069.35 \$52,750.84 \$2,692,820.19			
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J4P3009B		l Item Pay Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$171,704.50 \$0.00 \$171,704.50	To Date \$171,704.50 \$0.00 \$171,704.50			
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 5 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepancies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Waiting on contractor QC testing results for soil compaction.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Waiting on contractor QC testing results for soil compaction.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 3049905, Project Item Line Number 0110, Material Set 304990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting on contractor base rock compaction results.	vohsr1	Unresolved
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 4019905, Project Item Line Number 0130, Material Set 401990596, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL for reinforcing steel (Realm)	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 4019905, Project Item Line Number 0130, Material Set 401990596, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL for reinforcing steel (Realm)	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 4019905, Project Item Line Number 0140, Material Set 401990596, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL for reinforcing steel (Realm)	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 4019905, Project Item Line Number 1540, Material Set 401990596, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL for reinforcing steel (Realm)	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 4019905, Project Item Line Number 1540, Material Set 401990596, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL for reinforcing steel (Realm)	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6071102, Project Item Line Number 0210, Material Set 607110296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6071102, Project Item Line Number 0210, Material Set 607110296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6071102, Project Item Line Number 0210, Material Set 607110296, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 0970, Material Set 701110696, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 0970, Material Set 701110696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 0970, Material Set 701110696, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 1210, Material Set 701110696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 1210, Material Set 701110696, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 1210, Material Set 701110696, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 0980, Material Set 701120596, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 0980, Material Set 701120596, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 0980, Material Set 701120596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 1220, Material Set 701120596, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 1220, Material Set 701120596, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 1220, Material Set 701120596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1040, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden

Revision 4/1/2020 Page 6 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Action Generic 1005FACCNSCA is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1040, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1040, Material Set 703200396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1280, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1280, Material Set 703200396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1280, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1060, Material Set 703422196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1060, Material Set 703422196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1060, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Concrete for the bridge deck has not been poured yet, so no tests have been taken.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1060, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on concrete sealer PAL.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1300, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on concrete sealer PAL.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1300, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Concrete for the bridge deck has not been poured yet, so no tests have been taken.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1300, Material Set 703422196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1300, Material Set 703422196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1440, Material Set 720100096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1440, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Waiting on QC Test results for select granular backfill.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1440, Material Set 720100096, Material 1052MSEWLGFP - Face Panels for Large Block MSE wall sys, Acceptance Action Generic 1052MSEWLGFP is insufficient.	Waiting on MoDOT Materials for MSE Wall face panel reporting	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1440, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on QC Concrete results for MSE wall coping.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1440, Material Set 720100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1470, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on QC concrete test for MSE wall coping.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1470, Material Set 720100096, Material 1052MSEWLGFP - Face Panels for Large Block MSE wall sys, Acceptance Action Generic 1052MSEWLGFP is insufficient.	Waiting on MoDOT Materials for MSE Wall face panel reporting	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1470, Material Set 720100096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1470, Material Set 720100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1470, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Waiting on QC testing results for select granular backfill.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9103714, Project Item Line Number	Waiting on PAL for reinforcing steel.	vohsr1	Overridden

Revision 4/1/2020 Page 7 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
0840, Material Set 910371496, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.			

Revision 4/1/2020 Page 8 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	J4P3009	0001	0010	2013000	CLEARING AND GRUBBING	5.00	0.00	5.00	ACRE	1.50	\$5,500.00	\$8,250.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.64	\$250,000.00	\$160,000.00
		0001	0030	2031000	CLASS A EXCAVATION	6,088.00	0.00	6,088.00	CUYD	49.00	\$17.00	\$833.00
		0001	0040	2035500	EMBANKMENT IN PLACE	3,626.00	0.00	3,626.00	CUYD	601.00	\$20.00	\$12,020.00
		0001	0050	2036000	COMPACTING EMBANKMENT	5,294.00	0.00	5,294.00	CUYD	109.00	\$2.50	\$272.50
		0001	0060	2037075	COMPACTING IN CUT	32.00	0.00	32.00	STA	0.00	\$350.00	\$0.00
		0001	0070	2063000	CLASS 3 EXCAVATION	117.00	0.00	117.00	CUYD	87.00	\$12.00	\$1,044.00
		0001	0800	2063500	CULVERT CLEANOUT	3.00	0.00	3.00	EA	0.00	\$2,000.00	\$0.00
		0001	0090	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,718.00	0.00	1,718.00	SQYD	1,718.00	\$16.50	\$28,347.00
		0001	0100	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	466.00	0.00	466.00	SQYD	466.00	\$15.00	\$6,990.00
		0001	0110	3049905	MISC.OPTIONAL BASE	11,716.00	0.00	11,716.00	SQYD	4,637.00	\$11.00	\$51,007.00
		0001	0120	4010150	TYPE A2 SHOULDER	2,721.10	0.00	2,721.10	SQYD	0.00	\$27.00	\$0.00
		0001	0130	4019905	MISC.CHIPMAN ROAD OPTIONAL PAVEMENT	466.00	0.00	466.00	SQYD	466.00	\$100.00	\$46,600.00
		0001	0140	4019905	MISC.RAMP OPTIONAL PAVEMENT	1,718.00	0.00	1,718.00	SQYD	1,718.00	\$60.00	\$103,080.00
		0001	0150	4019905	MISC.US-50 OPTIONAL PAVEMENT	8,995.00	0.00	8,995.00	SQYD	0.00	\$52.00	\$0.00
		0001	0160	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	421.70	0.00	421.70	TONS	421.70	\$115.00	\$48,495.50
		0001	0170	4071005	TACK COAT	213.00	0.00	213.00	GAL	0.00	\$2.50	\$0.00
		0001	0180	5041000	CONCRETE APPROACH PAVEMENT	379.80	0.00	379.80	SQYD	0.00	\$108.60	\$0.00
		0001	0190	6044011	PIPE COLLAR, TYPE A	3.00	0.00	3.00	EA	3.00	\$1,100.00	\$3,300.00
		0001	0200	6064500	AGGREGATE BEDDING FOR 3 - STRAND GUARD CABLE	93.00	0.00	93.00	CUYD	0.00	\$40.00	\$0.00
		0001	0210	6071102	MODIFIED CONCRETE GUTTER TYPE B	490.00	0.00	490.00	LF	490.00	\$48.00	\$23,520.00
		0001	0220	6079903	MISC.ORNAMENTAL PEDESTRIAN FENCE (48") (RETAINING	331.00	0.00	331.00	LF	0.00	\$135.00	\$0.00
		0001	0230	6081000	WALLS) CONCRETE MEDIAN	2.80	0.00	2.80	SQYD	0.00	\$399.25	\$0.00
		0001	0240	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	34.00	0.00	34.00	CUYD	0.00	\$65.00	\$0.00
		0001	0250	6096041	PLACING TYPE 1 ROCK DITCH LINER	34.00	0.00	34.00	CUYD	0.00	\$60.00	\$0.00
		0001	0260	6097000	ROCK LINING	15.00	0.00	15.00	CUYD	3.00	\$85.00	\$255.00
		0001	0270	6113010	FURNISHING TYPE 1 ROCK BLANKET	143.00	0.00	143.00	CUYD	0.00	\$65.00	\$0.00
			0280	6113030	PLACING TYPE 1 ROCK BLANKET	143.00	0.00	143.00	CUYD	0.00	\$20.00	\$0.00
		0001	0290	6161005	CONSTRUCTION SIGNS	1,610.00	0.00	1,610.00	SQFT	1,610.00	\$6.50	\$10,465.00
		0001	0300	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	0.00	8.00	EA	8.00	\$100.00	\$10,465.00
		0001	0300			222.00	0.00	222.00	EA	222.00	\$31.00	
		0001	0320	6161025 6161030	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	50.00	\$185.00	\$6,882.00
		0001			TYPE III MOVEABLE BARRICADE							\$9,250.00
		0001	0330	6161033	DIRECTIONAL INDICATOR BARRICADE	37.00	0.00	37.00	EA	14.00	\$135.00	\$1,890.00
		0001	0340	6161040 6161098A	FLASHING ARROW PANEL CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	2.00	0.00	2.00	EA EA	2.00	\$2,500.00 \$9,500.00	\$5,000.00 \$19,000.00
		0001	0360	6162002	RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.00
		0001	0370	6173000	CONCRETE TRAFFIC BARRIER. TYPE C	177.00	0.00	177.00	LF	0.00	\$200.00	\$0.00
		0001	0380	6181000	MOBILIZATION	1.00	-1.00	0.00	LS		\$195,000.00	\$0.00
		0001	0381	6181000	MOBILIZATION	0.00	1.00	1.00	LS		\$141,674.00	\$106,255.50
			0390	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.00
		0001	0400	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	168.00	0.00	168.00	LF	0.00	\$20.00	\$0.00
		0001			WHITE							
		0001	0410	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	16.00	0.00	16.00	EA	0.00	\$250.00	\$0.00
		0001	0420	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	13,609.00	-13,609.00	0.00	LF	0.00	\$1.55	\$0.00
		0001	0430	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	13,273.00	-13,273.00	0.00	LF	0.00	\$1.55	\$0.00
		0001	0440	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	8.00	0.00	8.00	EA	0.00	\$115.00	\$0.00

Revision 4/1/2020 Page 9 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
11015-C03	J4P3009	0001	0450	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	15,875.00	0.00	15,875.00	LF	0.00	\$0.55	\$0.0
		0001	0460	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	11,706.00	0.00	11,706.00	LF	0.00	\$0.55	\$0.0
		0001	0470	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,840.00	0.00	1,840.00	LF	0.00	\$0.90	\$0.0
		0001	0480	6207001	PAVEMENT MARKING REMOVAL	2,376.00	0.00	2,376.00	LF	2,376.00	\$0.55	\$1,306.8
		0001	0490	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	16.00	0.00	16.00	EA	0.00	\$55.00	\$0.0
		0001	0500	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,646.00	0.00	2,646.00	SQYD	681.00	\$6.25	\$4,256.2
		0001	0510	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	319.00	0.00	319.00	SQYD	0.00	\$5.00	\$0.0
		0001	0520	6240104A	SEPARATION GEOTEXTILE	838.00	0.00	838.00	SQYD	0.00	\$4.50	\$0.0
		0001	0530	6269909	MISC.OPTIONAL PAVEMENT RUMBLE STRIP	56.60	0.00	56.60	STA	0.00	\$158.85	\$0.
		0001	0540	6274000 7261018	CONTRACTOR FURNISHED SURVEYING AND STAKING 18 IN. PIPE GROUP A	1.00	0.00	1.00	LS	0.75	\$5,000.00 \$110.00	\$3,750. \$0.
		0001	0560	7261024	24 IN. PIPE GROUP A	73.00	0.00	73.00	LF	73.00	\$105.00	\$7,665.
		0001	0570	7261030	30 IN. PIPE GROUP A	28.00	0.00	28.00	LF	0.00	\$160.00	\$0.
		0001	0580	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	1.00	0.00	1.00	EA	0.00	\$1,500.00	\$0.
			0590	7320624A	SECTION 24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	2.00	0.00	2.00	EA	2.00	\$1,700.00	\$3,400.0
		0001			SECTION							
		0001	0600	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$1,850.00	\$0.
		0001	0610	8051000A	SEEDING - COOL SEASON GRASSES	5.30	0.00	5.30	ACRE	0.00	\$1,600.00	\$0.
		0001	0620	8061004	SEDIMENT TRAP ROCK	29.80	0.00	29.80	CUYD	0.00	\$100.00	\$0.
		0001	0630	8061005	ROCK DITCH CHECK	140.00	0.00	140.00	LF	89.00	\$45.00	\$4,005
		0001	0640	8061006	ALTERNATE DITCH CHECK	976.00	0.00	976.00	LF	0.00	\$4.35	\$0
		0001	0650	8061016	SEDIMENT REMOVAL	189.00	0.00	189.00	CUYD	0.00	\$20.00	\$0
		0001	0660	8061019	SILT FENCE	3,187.00	0.00	3,187.00	LF	630.00	\$1.35	\$850
		0001	0670	8064128	TYPE 1 TURF REINFORCEMENT MAT	729.00	0.00	729.00	SQYD	0.00	\$1.95	\$0
		0001	0680	8064138	TYPE 2D EROSION CONTROL BLANKET	3,973.00	0.00	3,973.00	SQYD	0.00	\$4.25	\$0
		0010	0690	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,463.00	0.00	1,463.00	LF	0.00	\$31.50	\$0
		0010	0700	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	5.00	0.00	5.00	EA	0.00	\$3,000.00	\$0
		0010	0710	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	0.00	\$950.00	\$0
		0010	0720	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,700.00	\$0
		0010	0730	6069902	MISC.HTGC ANCHOR ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$5,000.00	\$0
		0010	0740	6069903	MISC.HIGH TENSION GUARD CABLE	1,256.00	0.00	1,256.00	LF	0.00	\$24.00	\$0
		0040	0750	7040101	SUBSTRUCTURE REPAIR (FORMED)	150.00	0.00	150.00	SQFT	0.00	\$75.00	\$0
		0040	0760	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$1,762.00	\$0
		0040	0770	9031010	CONCRETE FOOTINGS, EMBEDDED	1.00	0.00	1.00	CUYD	0.00	\$1,300.00	\$0
		0040	0780	9031210	STRUCTURAL STEEL POSTS	650.00	0.00	650.00	LB	0.00	\$4.25	\$0
		0040	0790	9031270A	2 IN. PSST POST - 12 GA.	75.00	0.00	75.00	LF	0.00	\$20.50	\$0
		0040	0800	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	18.00	0.00	18.00	LF	0.00	\$40.00	\$0
		0040	0810	9035004A	SH-FLAT SHEET	27.00	0.00	27.00	SQFT	0.00	\$23.50	\$0
		0040	0820	9035011A	ST-STRUCTURAL	80.00	0.00	80.00	SQFT	0.00	\$21.50	\$0
		0040	0830		SHF-FLAT SHEET FLUORESCENT	18.00	0.00	18.00	SQFT	0.00	\$37.50	\$0
		0050	0840	9103714	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	1.00	0.00	1.00	EA	1.00	\$8,500.00	\$8,500
		0050	0850	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	227.00	0.00	227.00	LF	227.00	\$13.50	\$3,064
		0050	0860	9108206	CABLE, 6 AWG, 1 CONDUCTOR, POWER	3,390.00	0.00	3,390.00	LF	0.00	\$2.50	\$0
		0050	0870	9108353	FIBER OPTIC CABLE, 12-STRAND, SINGLE MODE	1,130.00	0.00	1,130.00	LF	0.00	\$2.50	\$0.
		0050	0880	9108811	PULL BOX, PREFORMED CLASS 2	3.00	0.00	3.00	EA	0.00	\$1,575.00	\$0.
		0050	0890	9109901	MISC.Fiber Optic Splicing, Testing, & Documentation	1.00	0.00	1.00	LS	1.00	\$5,500.00	\$5,500.

Page 10 of 24 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	J4P3009	0050	0900	9109902	MISC.CCTV Pole Relocation	1.00	0.00	1.00	EA	1.00	\$6,000.00	\$6,000.00
		0050	0910	9109902	MISC.Scout Fiber Optic Pull Box	3.00	0.00	3.00	EA	0.00	\$3,500.00	\$0.00
		0050	0920	9109903	MISC."CONDUIT, TWO 2 IN., PUSHED"	181.00	0.00	181.00	LF	181.00	\$30.00	\$5,430.00
		0050	0930	9109903	MISC."CONDUIT, TWO 2 IN., RIGID, IN SAME TRENCH"	692.00	0.00	692.00	LF	672.00	\$20.00	\$13,440.00
		0070	0940	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	17.00	0.00	17.00	SQFT	17.00	\$275.00	\$4,675.00
		0070	0950	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$68,000.00	\$68,000.00
		0070	0960	5031010A	BRIDGE APPROACH SLAB (MAJOR)	182.00	0.00	182.00	SQYD	0.00	\$249.10	\$0.00
		0070	0970	7011106	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	52.00	0.00	52.00	LF	52.00	\$985.00	\$51,220.00
		0070	0980	7011205	ROCK SOCKETS (3 FT 6 IN. DIA.)	32.00	0.00	32.00	LF	32.00	\$642.00	\$20,544.00
		0070	0990	7011300	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$200.00	\$800.00
		0070	1000	7011400	FOUNDATION INSPECTION HOLES	72.00	0.00	72.00	LF	72.00	\$105.00	\$7,560.00
		0070	1010	7011600	SONIC LOGGING TESTING	4.00	0.00	4.00	EA	0.00	\$1,200.00	\$0.00
		0070	1020	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	525.00	0.00	525.00	LF	450.00	\$109.00	\$49,050.00
		0070	1030	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$125.00	\$1,750.00
		0070	1040	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	93.40	0.00	93.40	CUYD	93.40	\$860.00	\$80,324.00
		0070	1050	7034219A	TYPE D BARRIER	306.00	0.00	306.00	LF	0.00	\$170.00	\$0.00
		0070	1060	7034221	SLAB ON CONCRETE NU-GIRDER	604.00	0.00	604.00	SQYD	362.40	\$398.00	\$144,235.20
		0070	1070	7034620	FORM LINERS	197.00	0.00	197.00	SQYD	0.00	\$90.00	\$0.00
		0070	1080	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	491.00	0.00	491.00	LF	491.00	\$360.00	\$176,760.00
		0070	1090	7061060	REINFORCING STEEL (BRIDGES)	7,860.00	0.00	7,860.00	LB	7,860.00	\$1.70	\$13,362.00
		0070	1100	7101000	REINFORCING STEEL (EPOXY COATED)	11,140.00	0.00	11,140.00	LB	11,140.00	\$2.25	\$25,065.00
		0070	1110	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,860.00	\$0.00
		0070	1120	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,860.00	\$0.00
		0070	1130	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$4,000.00	\$0.00
		0070	1140	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$3,000.00	\$0.00
		0070	1150	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$200.00	\$1,600.00
		0070	1160	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$385.00	\$3,080.00
		0070	1170	7201300	PIPE PILE SPACERS	18.00	0.00	18.00	EA	18.00	\$1,525.00	\$27,450.00
		0070	1180	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	17.00	0.00	17.00	SQFT	17.00	\$275.00	\$4,675.00
		0071	1190	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$68,000.00	\$68,000.00
		0071	1200	5031010A	BRIDGE APPROACH SLAB (MAJOR)	182.00	0.00	182.00	SQYD	0.00	\$249.10	\$0.00
		0071	1210	7011106	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	44.00	0.00	44.00	LF	44.00	\$985.00	\$43.340.00
		0071	1220	7011205	ROCK SOCKETS (3 FT 6 IN. DIA.)	32.00	0.00	32.00	LF	32.00	\$642.00	\$20,544.00
			1230	7011203	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$200.00	\$800.00
		0071	1240	7011400	FOUNDATION INSPECTION HOLES	72.00	0.00	72.00	LF	72.00	\$105.00	
		0071		7011600	SONIC LOGGING TESTING			4.00				\$7,560.00 \$4,800.00
		0071	1250			4.00	0.00		EA LF	4.00	\$1,200.00	
		0071	1260	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	497.00	0.00	497.00		412.00	\$109.00	\$44,908.00
		0071	1270	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$125.00	\$1,750.00
		0071	1280	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	92.10	0.00	92.10	CUYD	92.10	\$870.00	\$80,127.00
		0071	1290		TYPE D BARRIER	306.00	0.00	306.00	LF	0.00	\$170.00	\$0.00
		0071	1300	7034221	SLAB ON CONCRETE NU-GIRDER	604.00	0.00	604.00	SQYD	271.80	\$398.00	\$108,176.40
		0071	1310	7034620	FORM LINERS	194.00	0.00	194.00	SQYD	0.00	\$90.00	\$0.00
		0071	1320	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	491.00	0.00	491.00	LF	491.00	\$360.00	\$176,760.00
		0071	1330	7061060	REINFORCING STEEL (BRIDGES)	7,230.00	0.00	7,230.00	LB	7,230.00	\$1.75	\$12,652.50
		0071	1340	7101000	REINFORCING STEEL (EPOXY COATED)	11,070.00	0.00	11,070.00	LB	11,070.00	\$2.10	\$23,247.00
		0071	1350	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,860.00	\$0.00
		0071	1360	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,860.00	\$0.00



Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
1015-C03	J4P3009	0071	1370	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$4,000.00	\$0.
		0071	1380	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$3,000.00	\$0
		0071	1390	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$200.00	\$1,600
		0071	1400	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$385.00	\$3,080
		0071	1410	7201300	PIPE PILE SPACERS	18.00	0.00	18.00	EA	18.00	\$1,525.00	\$27,450
		0072	1420	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$3,367.50	\$(
		0072	1430	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$3,367.50	\$
		0072	1440	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,786.00	0.00	3,786.00	SQFT	3,786.00	\$74.00	\$280,16
		0073	1450	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$3,115.00	\$
		0073	1460	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$3,115.00	\$
		0073	1470	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,422.00	0.00	3,422.00	SQFT	3,422.00	\$75.00	\$256,65
		0001	5001	6189901	MISC.CONTRACT BOND PAYMENT	0.00	1.00	1.00	LS	1.00	\$53,326.00	\$53,32
		0001	5002	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	0.00	26,882.00	26,882.00	LF	16,704.00	\$1.05	\$17,53
		0001	5003	1046002	VALUE ENGINEERING	0.00	6,720.50	6,720.50	EA	6,720.50	\$1.00	\$6,72
	Project J4F	23009 - Tota	al Value I	Posted to Da	te as of Report Generated Date							\$2,640,06
	J4P3009B	0001	1480	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.06	\$85,000.00	\$5,10
		0001	1490	2031000	CLASS A EXCAVATION	637.00	0.00	637.00	CUYD	0.00	\$22.00	S
		0001	1500	2036000	COMPACTING EMBANKMENT	260.00	0.00	260.00	CUYD	0.00	\$18.00	\$
		0001	1510	2063000	CLASS 3 EXCAVATION	109.00	0.00	109.00	CUYD	51.00	\$20.00	\$1,02
		0001	1520	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	268.00	0.00	268.00	SQYD	0.00	\$17.00	5
		0001	1530	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	822.00	0.00	822.00	SQYD	0.00	\$16.00	5
		0001	1540	4019905	MISC.OPTIONAL PAVEMENT - CHIPMAN	434.00	0.00	434.00	SQYD	14.00	\$192.00	\$2,68
		0001	1550	4019905	MISC.OPTIONAL PAVEMENT - MURRAY	388.00	0.00	388.00	SQYD	0.00	\$110.00	
		0001	1560	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	1,688.10	0.00	1,688.10	TONS	0.00	\$95.00	\$
		0001	1570	4071005	TACK COAT	1,459.00	0.00	1,459.00	GAL	0.00	\$2.50	\$
		0001	1580	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	92.00	0.00	92.00	GAL	0.00	\$3.00	\$
		0001	1590	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	0.00	\$1,400.00	\$
		0001	1600	6081000	CONCRETE MEDIAN	430.80	0.00	430.80	SQYD	0.00	\$65.55	5
		0001	1610	6081010	CONCRETE CURB RAMP	229.30	0.00	229.30	SQYD	0.00	\$127.27	\$
		0001	1620	6081012	TRUNCATED DOMES	396.00	0.00	396.00	SQFT	0.00	\$17.65	\$
		0001	1630	6083006	6 IN. CONCRETE MEDIAN STRIP	67.70	0.00	67.70	SQYD	0.00	\$161.45	
		0001	1640	6086004	CONCRETE SIDEWALK, 4 IN.	1,484.60	0.00	1,484.60	SQYD	0.00	\$38.55	5
		0001	1650	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	896.00	0.00	896.00	LF	0.00	\$34.65	
		0001	1660	6091052	CURB AND GUTTER TYPE B	802.00	0.00	802.00	LF	0.00	\$35.05	\$
		0001	1670		FURNISHING TYPE 1 ROCK DITCH LINER	3.00	0.00	3.00	CUYD	0.00	\$75.00	
		0001	1680	6096041	PLACING TYPE 1 ROCK DITCH LINER	3.00	0.00	3.00	CUYD	0.00	\$75.00	
		0001	1690	6097000	ROCK LINING	7.00	0.00	7.00	CUYD	2.00	\$95.00	\$19
		0001	1700	6099903	MISC.CURB AND GUTTER TYPE CG-1	522.00	0.00	522.00	LF	0.00	\$30.90	9.5
		0001	1710	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X	1.00	0.00	1.00	EA	0.00	\$1,050.00	
		0001	1710		600MM)	1.00	0.00	1.00	LA	0.00		
		0001	1720	6143014	MANHOLE FRAME AND COVER, TYPE 4	1.00	0.00	1.00	EA	0.00	\$750.00	\$
		0001	1730	6161005	CONSTRUCTION SIGNS	339.00	0.00	339.00	SQFT	249.00	\$6.50	\$1,61
	0001 1740 6161025 CHANNELIZER (TRIM LINE)				CHANNELIZER (TRIM LINE)	189.00	0.00	189.00	EA	160.00	\$31.00	\$4,96
		0001	1750	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$185.00	\$1,85
	0001 1760 6161040 FLASHING ARROW PANEL					2.00	0.00	2.00	EA	1.00	\$2,500.00	\$2,50
		0001	1770	6169902	MISC.TYPE II PEDESTRIAN BARRICADE	5.00	0.00	5.00	EA	0.00	\$150.00	\$
		0001	1780	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$110,000.00	\$82,50
		0001	1790	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	

Revision 4/1/2020 Page 12 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	port Generated date and can differ from the posted amo Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED
lm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
11015-C03	J4P3009B	0001	1800	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, $ 6 $ IN. WHITE	141.00	0.00	141.00	LF	0.00	\$4.50	\$0.00
		0001	1810	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	462.00	0.00	462.00	LF	0.00	\$20.00	\$0.00
		0001	1820	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	96.00	0.00	96.00	LF	0.00	\$14.00	\$0.00
		0001	1830	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	23.00	0.00	23.00	EA	0.00	\$275.00	\$0.00
		0001	1840	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	1.00	0.00	1.00	EA	0.00	\$450.00	\$0.00
		0001	1850	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	78.00	0.00	78.00	EA	0.00	\$185.00	\$0.00
		0001	1860	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	5,606.00	0.00	5,606.00	LF	0.00	\$2.00	\$0.00
		0001	1870	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,561.00	0.00	2,561.00	LF	0.00	\$2.00	\$0.00
		0001	1880	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	8.00	0.00	8.00	EA	8.00	\$115.00	\$920.00
		0001	1890	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,951.00	0.00	3,951.00	LF	0.00	\$0.55	\$0.00
		0001	1900	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,361.00	0.00	2,361.00	LF	0.00	\$0.55	\$0.00
		0001	1910	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	333.00	0.00	333.00	LF	0.00	\$0.90	\$0.00
		0001	1920	6207001	PAVEMENT MARKING REMOVAL	630.00	0.00	630.00	LF	252.00	\$1.00	\$252.00
		0001	1930	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	10.00	0.00	10.00	EA	3.00	\$115.00	\$345.00
		0001	1940	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	15,347.00	0.00	15,347.00	SQYD	0.00	\$3.00	\$0.00
		0001	1950	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	8.00	0.00	8.00	SQYD	0.00	\$5.00	\$0.00
		0001	1960	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.75	\$24,000.00	\$18,000.00
		0001	1970	7261015	15 IN. PIPE GROUP A	97.00	0.00	97.00	LF	57.00	\$80.00	\$4,560.00
		0001	1980	7261030	30 IN. PIPE GROUP A	15.00	0.00	15.00	LF	0.00	\$160.00	\$0.00
		0001	1990	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	7.00	0.00	7.00	FT	0.00	\$625.00	\$0.0
		0001	2000	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	6.00	0.00	6.00	FT	0.00	\$775.00	\$0.0
		0001	2010	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,950.00	\$1,950.0
		0001	2020	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.0
		0001	2030	8031000A	TURF TYPE TALL FESCUE SODDING	1,064.00	0.00	1,064.00	SQYD	0.00	\$5.65	\$0.0
		0001	2040	8051000A	SEEDING - COOL SEASON GRASSES	0.40	0.00	0.40	ACRE	0.00	\$1,600.00	\$0.0
		0001	2050	8061004	SEDIMENT TRAP ROCK	18.00	0.00	18.00	CUYD	0.00	\$90.00	\$0.0
		0001	2060	8061005	ROCK DITCH CHECK	188.00	0.00	188.00	LF	0.00	\$55.00	\$0.0
		0001	2070	8061007A	CURB INLET CHECK	5.00	0.00	5.00	EA	0.00	\$63.00	\$0.0
		0001	2080	8061016	SEDIMENT REMOVAL	53.00	0.00	53.00	CUYD	0.00	\$25.00	\$0.0
		0001	2090	8061019	SILT FENCE	793.00	0.00	793.00	LF	0.00	\$1.35	\$0.00
		0001	2100	8064128	TYPE 1 TURF REINFORCEMENT MAT	593.00	0.00	593.00	SQYD	0.00	\$1.95	\$0.0
		0020	2110	9011010	RELOCATED POLE	6.00	0.00	6.00	EA	0.00	\$800.00	\$0.0
		0020	2120	9011060	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 1	1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0.00
		0020	2130	9011115	BRACKET ARM, 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$1,200.00	\$0.00
		0020	2140	9011312	LUMINAIRE, LED-B	7.00	0.00	7.00	EA	0.00	\$200.00	\$0.00
		0020	2150	9014004	CONDUIT, 4 IN. RIGID, PUSHED	136.00	0.00	136.00	LF	136.00	\$35.00	\$4,760.0
		0020	2160	9014502	CONDUIT, 2 IN. RIGID, EXTERNAL ON STRUCTURE	322.00	0.00	322.00	LF	0.00	\$60.00	\$0.0
		0020	2170	9015010	TRENCHING TYPE I	795.00	0.00	795.00	LF	53.00	\$6.00	\$318.0
		0020	2180	9016110	PULL BOX, PREFORMED CLASS 1	5.00	0.00	5.00	EA	2.00	\$355.00	\$710.0
		0020	2190	9017004	CABLE, 4 AWG 1 CONDUCTOR	1,110.00	0.00	1,110.00	LF	0.00	\$3.00	\$0.0
		0020	2200	9017008	CABLE, 8 AWG 1 CONDUCTOR	1,700.00	0.00	1,700.00	LF	456.00	\$2.50	\$1,140.0
		0020	2210	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	120.00	0.00	120.00	LF	0.00	\$2.00	\$0.0
		0020	2220	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	920.00	0.00	920.00	LF	0.00	\$12.50	\$0.00
		0020	2230	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	0.00	\$1,400.00	\$0.00

Revision 4/1/2020 Page 13 of 24



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

NTRACT N		tegory	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
-C03 J4P30	J4P3009B 0020 2240 9019902 MISC.LEE'S SUMMIT 40 FT. POLE FOUNDATION B40D SCI 0020 2250 9019902 MISC.LUMINAIRE, LED-A WALL PACK (INCLUDING HOUSI						0.00	3.00	EA	0.00	\$1,500.00	\$0.0
	00	020	2250	9019902	MISC.LUMINAIRE, LED-A WALL PACK (INCLUDING HOUSING)	4.00	0.00	4.00	EA	0.00	\$1,200.00	\$0.0
	00	020	2260	9019902	MISC.PULL BOX LID REPLACEMENT	1.00	0.00	1.00	EA	0.00	\$900.00	\$0.0
	00	020	2270	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	410.00	0.00	410.00	LF	91.00	\$25.00	\$2,275.0
	00	030	2280	9020211	SIGNAL HEAD, TYPE 1S	18.00	0.00	18.00	EA	0.00	\$175.00	\$0.0
	00	030	2290	9020215	SIGNAL HEAD, TYPE 5S	1.00	0.00	1.00	EA	0.00	\$1,500.00	\$0.0
	00	030	2300	9020513	SIGNAL HEAD, TYPE 3B	9.00	0.00	9.00	EA	0.00	\$975.00	\$0.0
	00	030	2310	9020514	SIGNAL HEAD, TYPE 4B	3.00	0.00	3.00	EA	0.00	\$1,275.00	\$0.
	00	030	2320	9020833	SH-FLAT SHEET - SIGNAL SIGN	42.00	0.00	42.00	SQFT	0.00	\$80.00	\$0.
	00	030	2330	9020834	SIGNAL SIGN, MOUNTING HARDWARE	21.00	0.00	21.00	EA	0.00	\$60.00	\$0.
	00	030	2340	9022708	POST, SIGNAL 8 FT. OR 2.4 M	11.00	0.00	11.00	EA	0.00	\$1,325.00	\$0.0
	00	030	2350	9022715	POST, SIGNAL 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$1,750.00	\$0.
	00	030	2360	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	0.00	\$15,000.00	\$0.
	00	030	2370	9024920	DETECTOR, PUSHBUTTON	18.00	0.00	18.00	EA	0.00	\$1,250.00	\$0.
	00	030	2380	9024975	VIDEO DETECTION SYSTEM	3.00	0.00	3.00	EA	1.00	\$24,000.00	\$24,000
	00	030	2390	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	267.00	0.00	267.00	LF	0.00	\$17.50	\$0
	00	030	2400	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	37.00	0.00	37.00	LF	0.00	\$13.00	\$0.
	00	030	2410	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	789.00	0.00	789.00	LF	314.00	\$32.00	\$10,048
	00	030	2420	9028308	CABLE, 16 AWG 2 CONDUCTOR	3,450.00	0.00	3,450.00	LF	0.00	\$1.50	\$0
	00	030	2430	9028310	CABLE, 16 AWG 5 CONDUCTOR	3,460.00	0.00	3,460.00	LF	0.00	\$2.00	\$0.
	00	030	2440	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,110.00	0.00	2,110.00	LF	0.00	\$2.50	\$0
	00	030	2450	9028811	PULL BOX, PREFORMED CLASS 2	13.00	0.00	13.00	EA	0.00	\$1,750.00	\$0
	00	030	2460	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	0.00	\$1,825.00	\$0
	00	030	2470	9029100	BASE, CONCRETE	11.80	0.00	11.80	CUYD	0.00	\$2,500.00	\$0
	00	030	2480	9029902	MISC.POST, SIGNAL 4 FT.	3.00	0.00	3.00	EA	0.00	\$985.00	\$0
	00	030	2490	9029902	MISC.PULL BOX CLASS 3 LID REPLACEMENT	1.00	0.00	1.00	EA	0.00	\$250.00	\$0
	00	030	2500	9109902	MISC.CCTV CAMERA ASSEMBLY, INSTALLED	2.00	0.00	2.00	EA	0.00	\$8,000.00	\$0
	00	040	2510	9031010	CONCRETE FOOTINGS, EMBEDDED	1.70	0.00	1.70	CUYD	0.00	\$1,300.00	\$0
	00	040	2520	9031210	STRUCTURAL STEEL POSTS	1,520.00	0.00	1,520.00	LB	0.00	\$4.25	\$0
	00	040	2530	9031270A	2 IN. PSST POST - 12 GA.	236.00	0.00	236.00	LF	0.00	\$20.50	\$0
	00	040	2540	9035004A	SH-FLAT SHEET	67.00	0.00	67.00	SQFT	0.00	\$23.50	\$0
	00	040	2550	9035011A	ST-STRUCTURAL	0.00	318.00	SQFT	0.00	\$21.50	\$0	
	00	040	2560	9035069A	SHF-FLAT SHEET FLUORESCENT	18.00	0.00	18.00	SQFT	0.00	\$37.50	\$0
		OD To	tal Malus	Booted to F	Date as of Report Generated Date							\$171,704

Revision 4/1/2020 Page 14 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3009

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2022010	REMOVAL OF IMPROVEMENTS	6/15/22	6/16/22	0.30	LS	Removal of pavement south of the bridges15 for EB and .15 for WB	568+80.51		576+50		
0110	3049905	MISC. AGGREGATE FOR BASE	6/15/22	6/16/22	2,141.00	SQYD	EB 50	570+44.95		575+50		
				6/16/22	2,496.00	SQYD	WB 50	570+60.88		576+50		
0210	6071102	MODIFIED CONCRETE GUTTER TYPE B	6/6/22	6/16/22	40.00	LF	8922 Sloped Portion	13+86		14+26		
				6/16/22	46.00	LF	8921 Sloped Portion	13+55		14+01		
				6/16/22	54.00	LF	8922 Sloped Portion	11+86		12+40		
				6/16/22	57.00	LF	8921 sloped portion	11+51		12+08		
1060	7034221	SLAB ON CONCRETE NU-GIRDER	6/9/22	6/16/22	120.80	SQYD	20% for precast panel placement	568+94.03		570+18.98		
			6/15/22	6/16/22	90.60	SQYD	15% for rebar tied in place	568+94.03		570+18.98		
				6/16/22	151.00	SQYD	25% for Deck forming	568+94.03		570+18.98		
1080	7056021	NU 35, PRESTRESSED CONC NU-GIRDER	6/2/22	6/16/22	491.00	LF	Bridge 8919 Spans 1-2 and 2-3	568+95.88		570+18.40		
1150	7161000	PLAIN NEOPRENE BEARING PAD	6/2/22	6/16/22	8.00	EA	Bridge 8919 Spans 1-2 and 2-3	568+95.88		570+18.40		
1160	7161002	LAMINATED NEOPRENE BEARING PAD	6/2/22	6/16/22	8.00	EA	Bridge 8919 spans 1-2 and 2-3	568+95.88		570+18.40		
1300	7034221	SLAB ON CONCRETE NU-GIRDER	6/9/22	6/16/22	120.80	SQYD	20% for precast panel placement	568+79.11		570+04.39		
			6/15/22	6/16/22	151.00	SQYD	25% for deck forming	568+79.11		570+04.39		
1320	7056021	NU 35, PRESTRESSED CONC NU-GIRDER	6/2/22	6/16/22	491.00	LF	Bridge 8920 Spans 1-2 and 2-3	568+80.51		570+03.70		
1390	7161000	PLAIN NEOPRENE BEARING PAD	6/2/22	6/16/22	8.00	EA	Bridge 8920 Spans 1-2 and 2-3	568+80.51		570+03.70		
1400	7161002	LAMINATED NEOPRENE BEARING PAD	6/2/22	6/16/22	8.00	EA	Bridge 8920 Spans 1-2 and 2-3	568+80.51		570+03.70		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 15 of 24



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0040	EMBANKMENT IN PLACE	Material		3	Apr 18, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$12,020.00)	
					4	May 2, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$12,020.00)	
					5	May 16, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$12,020.00)	
					6	Jun 1, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$12,020.00)	
					7	Jun 16, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$12,020.00)	
				- Total		2022		\$0.00	
			Material - To	tal				\$0.00	
	0040 -	Total						\$0.00	
	0050	COMPACTING EMBANKMENT	Material		3	Apr 18, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$272.50)	
					4	May 2, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$272.50)	
					5	May 16, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$272.50)	
					6	Jun 1, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$272.50)	
					7	Jun 16, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$272.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0050 -	Total						\$0.00	
	0090	TYPE 5 AGGREGATE FOR BASE	Material		2	Apr 4, 2022	SYSTEM	\$10,271.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$10,271.25)	
					3	Apr 18, 2022	SYSTEM	\$23,941.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$23,941.50)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0090	TYPE 5 AGGREGATE FOR BASE	Material - To	tal				\$0.00	
	0090 -	Total						\$0.00	
	0100	AGGREGATE FOR BASE (6 IN.	Material		5	May 16, 2022	SYSTEM	\$6,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		THICK)			5	May 16, 2022	SYSTEM	(\$6,990.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0100 -							\$0.00	
	0110	MISC. AGGREGATE FOR BASE	Material		7	Jun 16, 2022	SYSTEM	(\$51,007.00)	
				- Total				(\$51,007.00)	
			Material - To	tal				(\$51,007.00)	
	0110 -							(\$51,007.00)	
	0130	MISC.	Material		4	May 2, 2022	SYSTEM	\$24,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$24,000.00)	
					5	May 16, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$46,600.00)	Examples Exception 4 of the Selfont Taylor Example.
					6	Jun 1, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$46,600.00)	
					7	Jun 16, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$46,600.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0130 -	Total						\$0.00	
	0140	MISC.	Material		2	Apr 4, 2022	SYSTEM	\$37,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$37,350.00)	
					3	Apr 18, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$103,080.00)	
					4	May 2, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$103,080.00)	
					5	May 16, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$103,080.00)	
					6	Jun 1, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$103,080.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0140	MISC.	Material		7	Jun 16, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$103,080.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0140 -	Total						\$0.00	
	0160	ASPHALTIC CONCRETE MIXTURE PG	Other Item Adjustment	ACAD	4	May 2, 2022	vohsr1	\$1,167.05	Asphalt Cement Price Adjustment for Line 0180, April 2022
		70-22 (SP125C		ACAD - Tota	al			\$1,167.05	
		MIX)	Other Item A	djustment - T	otal			\$1,167.05	
	0160 -	Total						\$1,167.05	
	0190	PIPE COLLAR, TYPE A	Material		4	May 2, 2022	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$3,300.00)	
					5	May 16, 2022	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$3,300.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0190 -	Total						\$0.00	
	0210	MODIFIED CONCRETE GUTTER TYPE B	Material		6	Jun 1, 2022	SYSTEM	\$14,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$14,064.00)	
					7	Jun 16, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$23,520.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0210 -	Total						\$0.00	
	0350	CMS W/O COMMUNICATION INTERFACE,	Material		1	Mar 18, 2022	SYSTEM	\$19,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		CONT F/			1	Mar 18, 2022	SYSTEM	(\$19,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0350 -	Total						\$0.00	
	0660	SILT FENCE	Material		4	May 2, 2022	SYSTEM	\$850.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$850.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0660 -	Total						\$0.00	
	0690	MGS GUARDRAIL, 8 FT. POSTS, 6 FT. - 3 IN	Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$33,968.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		5 114		- Total				\$33,968.00	
			Construction	Stockpile S	TMI - Total			\$33,968.00	
	0690 -	Total						\$33,968.00	
	0700	MGS BRIDGE	Construction		4	May 2,	SYSTEM	\$1,851.85	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0700	APP. TRANS SEC (REG/NO CURB)	Stockpile STMI			2022			
		(1120/110 00112)	0.1111	- Total				\$1,851.85	
			Construction	Stockpile S1	MI - Total			\$1,851.85	
	0700 -	· Total						\$1,851.85	
	0710	MGS END ANCHOR	Construction Stockpile		4	May 2, 2022	SYSTEM	\$830.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$830.00	
			Construction	Stockpile S1	ΓMI - Total			\$830.00	
	0710 -	· Total						\$830.00	
	0720	TYPE A CRASHWORTHY	Construction Stockpile		4	May 2, 2022	SYSTEM	\$7,520.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL (MASH)	STMI	- Total				\$7,520.00	
			Construction	Stockpile S1	ΓΜΙ - Total			\$7,520.00	
	0720 -	· Total						\$7,520.00	
	0730	MISC. GUARDRAIL ITEM	Construction Stockpile		2	Apr 4, 2022	SYSTEM	\$3,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$3,300.00	
			Construction	Stockpile S1	ΓΜΙ - Total			\$3,300.00	
	0730 -	· Total						\$3,300.00	
		MISC. GUARDRAIL ITEM	Construction Stockpile		2	Apr 4, 2022	SYSTEM	\$21,968.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$21,968.00	
			Construction	Stockpile S1	ΓΜΙ - Total			\$21,968.00	
	0740 -	· Total						\$21,968.00	
	0840	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOU	Material		4	May 2, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$8,500.00)	
					5	May 16, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$8,500.00)	
					6	Jun 1, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$8,500.00)	
					7	Jun 16, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$8,500.00)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
	0840 -	· Total						\$0.00	
	0850	CONDUIT, 2 IN., RIGID, IN TRENCH	Material		2	Apr 4, 2022	SYSTEM	\$3,064.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$3,064.50)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
	0850 -	· Total						\$0.00	
	0890	MISC. ITS	Material		4	May 2, 2022	SYSTEM	\$5,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user volhsr1 overridding Payment
					4	May 2,	SYSTEM	(\$5,500.00)	Estimate Exception 15 on the current Payment Estimate.
				Total		2022		- 0.00	
				- Total				\$0.00	



Material - Total System	nt ent
Material 4	nt ent
Estimate Item Adjustment (0036) due to user vohsr1 overridding Payn Estimate Exception 16 on the current Payment Estimate. A	nt ent
2022 S0.00 Material - Total S0.00 S0.00 S0.00 S0.00 S0.00	ent
Material - Total S0.00	ent
Source S	ent
Misc. its Material 2	ent
2022 Estimate Item Adjustment (0006) due to user vohsr1 overridding Paym Estimate Exception 8 on the current Payment Estimate. 2 Apr 4, 2022 \$0.00 Material - Total \$0.00 0930 - Total \$0.00 DRILLED SHAFTS (4 FT. 0 IN. DIA.) Material \$5 May 16, 2022 \$7 SYSTEM \$51,220.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0026) due to user vohsr1 overridding Paym Estimate Exception 11 on the current Payment Estimate. 5 May 16, SYSTEM (\$51,220.00) Estimate Exception 11 on the current Payment Estimate. 5 May 16, SYSTEM (\$51,220.00) This adjustment offsets the original system-generated Material Payme Estimate Exception 11 on the current Payment Estimate.	ent
- Total \$0.00 Material - Total \$0.00 0930 - Total \$0.00 0970 DRILLED SHAFTS (4 FT. 0 IN. DIA.) Material \$5 May 16, 2022 SYSTEM \$51,220.00 Estimate Item Adjustment (0026) due to user vohsr1 overridding Payme Estimate Exception 11 on the current Payment Estimate. 5 May 16, SYSTEM (\$51,220.00) Estimate Exception 11 on the current Payment Estimate. 5 May 16, SYSTEM (\$51,220.00) Estimate Exception 11 on the current Payment Estimate. 6 Jun 1, SYSTEM \$51,220.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjus	
Material - Total \$0.00	
Solution	
DRILLED SHAFTS (4 FT. 0 IN. DIA.) Material 5 May 16, 2022 5 May 16, 2022 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0026) due to user vohsr1 overridding Paym Estimate Exception 11 on the current Payment Estimate. 5 May 16, 2022 6 Jun 1, 2022 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0024) due to user vohsr1 overridding Paym Estimate Item Adjustment (0024) due to user vohsr1 overridding Paym	
(4 FT. 0 IN. DIA.) 2022 Estimate Item Adjustment (0026) due to user vohsr1 overridding Paym Estimate Exception 11 on the current Payment Estimate. 5 May 16, 2022 6 Jun 1, SYSTEM \$51,220.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0024) due to user vohsr1 overridding Paym Estimate Item Adjustment (0024) due to user vohsr1 overridding Paym	
2022 6 Jun 1, SYSTEM \$51,220.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0024) due to user vohsr1 overridding Paym	
2022 Estimate Item Adjustment (0024) due to user vohsr1 overridding Paym	
Estimate Exception 11 on the current Payment Estimate.	
6 Jun 1, SYSTEM (\$51,220.00)	
7 Jun 16, SYSTEM \$51,220.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0024) due to user vohsr1 overridding Paym Estimate Exception 12 on the current Payment Estimate.	
7 Jun 16, SYSTEM (\$51,220.00)	
- Total \$0.00	
Material - Total \$0.00	
0970 - Total \$0.00	
0980 ROCK SOCKETS (3 FT 6 IN. DIA.) Material 5 May 16, SYSTEM 2022 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0027) due to user vohsr1 overridding Paym Estimate Exception 17 on the current Payment Estimate.	
5 May 16, SYSTEM (\$20,544.00)	
6 Jun 1, SYSTEM \$20,544.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0025) due to user vohsr1 overridding Paym Estimate Exception 17 on the current Payment Estimate.	
6 Jun 1, SYSTEM (\$20,544.00)	
7 Jun 16, SYSTEM \$20,544.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0025) due to user vohsr1 overridding Paym Estimate Exception 18 on the current Payment Estimate.	
7 Jun 16, SYSTEM (\$20,544.00)	
- Total \$0.00	
Material - Total \$0.00	
0980 - Total \$0.00	
1040 CLASS B CONCRETE (SUBSTRUCTURE) 5 May 16, 2022 SYSTEM \$13,760.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0028) due to user vohsr1 overridding Paym Estimate Exception 23 on the current Payment Estimate.	
5 May 16, SYSTEM (\$13,760.00)	
6 Jun 1, 2022 SYSTEM \$80,324.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0026) due to user vohsr1 overridding Paym Estimate Exception 23 on the current Payment Estimate.	
6 Jun 1, SYSTEM (\$80,324.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	1040	CLASS B CONCRETE (SUBSTRUCTURE)	Material		7	Jun 16, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$80,324.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1040 -	Total						\$0.00	
	1050	TYPE D BARRIER	Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$6,593.71	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$6,593.71	
			Construction	Stockpile S1	「MI - Total			\$6,593.71	
	1050 -							\$6,593.71	
	1060	SLAB ON CONCRETE NU- GIRDER	Material		7	Jun 16, 2022	SYSTEM	\$144,235.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$144,235.20)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1060 -	Total						\$0.00	
	1080	NU 35, PRESTRESSED CONC NU-GIRDER	Construction Stockpile		7	Jun 16, 2022	SYSTEM	(\$36,307.98)	Payment Estimate Item Adjustment generated Stockpile Transaction
		CONC NO-GINDER		- Total				(\$36,307.98)	
			Construction	Stockpile - 1	Total .			(\$36,307.98)	
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$36,307.98	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$36,307.98	
			Construction	Stockpile S1	ΓΜΙ - Total			\$36,307.98	
	1080 -	Total						\$0.00	
	1090	REINFORCING STEEL (BRIDGES)	Construction Stockpile		6	Jun 1, 2022	SYSTEM	(\$6,607.60)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$6,607.60)	
				Stockpile - 1			a) (a===1	(\$6,607.60)	
			Construction Stockpile STMI	Takal	4	May 2, 2022	SYSTEM	\$6,607.60	Payment Estimate Item Adjustment generated Stockpile Transaction
			Canaturation	- Total	TML Total			\$6,607.60	
	1090 -	Total	Construction	Stockpile S1	iwii - Total			\$6,607.60 \$0.00	
	1100	REINFORCING STEEL (EPOXY	Construction Stockpile		5	May 16, 2022	SYSTEM	<u> </u>	Payment Estimate Item Adjustment generated Stockpile Transaction
		COATED)			6	Jun 1, 2022	SYSTEM	(\$11,868.91)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$17,202.66)	
			Construction	Stockpile - 1	「otal			(\$17,202.66)	
			Construction Stockpile		4	May 2, 2022	SYSTEM	\$17,202.66	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$17,202.66	
			Construction	Stockpile S1	ΓΜΙ - Total			\$17,202.66	
	1100 -	Total						\$0.00	
	1210	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$43,340.00)	
					6	Jun 1, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$43,340.00)	



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J4P3009	1210	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		7	Jun 16, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$43,340.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1210 -	Total						\$0.00	
	1220	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$20,544.00)	
					6	Jun 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$20,544.00)	
					7	Jun 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$20,544.00)	
				- Total		2022		\$0.00	
			Material - Tot					\$0.00	
	1220 -	Total						\$0.00	
	1280	CLASS B CONCRETE (SUBSTRUCTURE)	Material		5	May 16, 2022	SYSTEM	\$13,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$13,920.00)	
					6	Jun 1, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$80,127.00)	
					7	Jun 16, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$80,127.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1280 -	Total						\$0.00	
	1290	TYPE D BARRIER	Stockpile		4	May 2, 2022	SYSTEM	\$6,593.71	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$6,593.71	
			Construction	Stockpile S	ГМI - Total			\$6,593.71	
	1290 -	Total						\$6,593.71	
	1300	SLAB ON CONCRETE NU- GIRDER	Construction Stockpile		7	Jun 16, 2022	SYSTEM	(\$16,335.42)	Payment Estimate Item Adjustment generated Stockpile Transaction
		GIRDER		- Total				(\$16,335.42)	
			Construction	Stockpile - 1				(\$16,335.42)	
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$36,300.94	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$36,300.94	
			Construction	Stockpile S				\$36,300.94	
			Material		7	Jun 16, 2022	SYSTEM	\$108,176.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$108,176.40)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	1300	SLAB ON CONCRETE NU- GIRDER	Material - Tot	al				\$0.00	
	1300 -	Total						\$19,965.52	
	1330	REINFORCING STEEL (BRIDGES)	Construction Stockpile		6	Jun 1, 2022	SYSTEM	(\$5,063.80)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$5,063.80)	
			Construction	Stockpile - 1	Total			(\$5,063.80)	
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$5,063.80	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$5,063.80	
			Construction	Stockpile STMI - Total				\$5,063.80	
		Total						\$0.00	
	1440	MECHANICALLY STABILIZED EARTH WALL SYS	Construction Stockpile		5	May 16, 2022	SYSTEM	(\$777.26)	Payment Estimate Item Adjustment generated Stockpile Transaction
					6	Jun 1, 2022	SYSTEM	(\$86.36)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$863.62)	
			Construction	Stockpile - 1	Total .			(\$863.62)	
			Construction Stockpile No		4	May 2, 2022	SYSTEM	\$863.62	Payment Estimate Item Adjustment generated Stockpile Transaction
			Transaction Type	- Total				\$863.62	
			Construction	Stockpile No	Transact	tion Type	- Total	\$863.62	
			Material		5	May 16, 2022	SYSTEM	\$252,147.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$252,147.60)	
					6	Jun 1, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$280,164.00)	
					7	Jun 16, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$280,164.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1440 -	Total	tal					\$0.00	
	1470				5	May 16, 2022	SYSTEM	(\$863.61)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$863.61)	
			Construction	Stockpile - 1	Total .			(\$863.61)	
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$863.61	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$863.61	
			Construction Stockpile STMI - Total					\$863.61	
			Material		5	May 16, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$256,650.00)	
					6	Jun 1, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$256,650.00)	
					7	Jun 16, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.

Jun 18, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	1470	MECHANICALLY STABILIZED EARTH WALL SYS	Material		7	Jun 16, 2022	SYSTEM	(\$256,650.00)	
				- Total				\$0.00	
		Material - Total						\$0.00	
	1470 -	Total						\$0.00	
J4P3009 - 1	Γotal							\$52,750.84	
J4P3009B	1540	MISC.	Material		4	May 2, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$2,688.00)	
					5	May 16, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$2,688.00)	
					6	Jun 1, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$2,688.00)	
					7	Jun 16, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$2,688.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1540 -	Total	al						
	1880	TEMPORARY NON-REMOVABLE TAPE LT/RT ARROW	Material		4	May 2, 2022	SYSTEM	\$920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$920.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1880 -	Total						\$0.00	
	2200	CABLE, 8 AWG 1 CONDUCTOR	Material		6	Jun 1, 2022	SYSTEM	\$1,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$1,140.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	2200 -	Total						\$0.00	
J4P3009B -	- Total							\$0.00	
Overall - To	otal					\$52,750.84			