

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 16, 2022

Progress Esti	mate Number 2	Contract ID Prime Contractor	211119-C05 Ideker, Inc.	Pay Period Start Pay Period End	May 2, 2022 May 15, 2022	Original Contract Amount Net Change Order Amount Current Contract Amount	\$7,952,654.65 \$3,960.53 \$7,956,615.18		
Approval Date							By User		
May 16, 2022		Ger	nerated and Ap	proved (and should b	e considered Dr	raft) at the Project Office Level by	woodwj1		
May 16, 2022		Reviewe	ed and Approve	ed (and should be co	nsidered Draft) a	t the Resident Engineer Level by	warrem1		
May 17, 2022	7, 2022 Reviewed and Approved at the Central Office Controllers Office Level by								
Original Comp	letion Date	Current Completi	on Date	Actual Completic	on Date	% of Current Contract Amou	int Complete		

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 4, 2022	November 4, 2022		1.83%

	Milestones					
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract			
Acceptance Date						
Awarded Date	December 1, 2021	December 1, 2021				
Letting Date	November 19, 2021	November 19, 2021				
Notice to Proceed Date	January 31, 2022	January 31, 2022				
Open to Traffic Date						
Work Began Date						

Contract Total Pa	Contract Total Pay For Estimate No. 2									
		This Estimate	Previous	To Date						
211119-C05										
	Total Posted Items Pay	\$0.00	\$145,290.73	\$145,290.73						
	Gross Item Adjustments	\$11,528.53	\$1,055.47	\$12,584.00						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
			\$146,346.20	\$157,874.73						
Contract Total Pa	yable This Estimate:	\$11,528.53								

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		stments Exist on Contract tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3333	0800	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-379.2	\$312.65	(\$118,556.88)
	0800	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	379.2	\$312.65	\$118,556.88
	0800	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Overrun	Overrun	Returning manual adjustment now that the Overrun has been resolved on CO 0001			\$11,005.28
	0110	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero).	350	\$1.45	\$507.50
	0120	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-951	\$5.25	(\$4,992.75)

Revision 4/1/2020 Page 1 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 16, 2022

Pro	gress l	Estimate Number 2	Contract ID 211119-C05 Prime Contractor Ideker, Inc.			Pay Period Start Pay Period End	May 2, 2022 May 15, 2022	Net Char	Contract Am nge Order An Contract Am	nount \$3	7,952,654.65 3,960.53 7,956,615.18	
Project Number	Line No.	Item Description	Item Description Adjustment Type Adjustment Type Comments Adjustment Type		Comments			Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount		
J4I3333	0120	DOWEL BAR (DI FURNISHI INSTALLATION) FC DEPTH PAVEMENT	ING AND OR FULL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			951	\$5.25	\$4,992.75	
	0120	DOWEL BAR (DEFURNISHIED INSTALLATION) FOR DEPTH PAVEMENT	ING AND	Overrun	Overrun		ual adjustment no been resolved or				\$15.75	
	0150	COMMUNI INTERFACE, CONTE FURNISHED, CONTE	/ITHOUT ICATION RACTOR	Material					-4	\$4,500.00	(\$18,000.00)	
	0150	COMMUNI INTERFACE, CONTE FURNISHED, CONTE	/ITHOUT ICATION RACTOR	Material		Adjustment (overridding Payme	rial Payment Esti 0004) due to use	mate Item r woodwj1 ption 5 on	4	\$4,500.00	\$18,000.00	
	0170		MISC.	Material					-0.25	\$5,000.00	(\$1,250.00)	
	0170		MISC.	Material		Adjustment (overridding Payme	rial Payment Esti 0005) due to use	mate Item r woodwj1 ption 6 on	0.25	\$5,000.00	\$1,250.00	
Total											\$11,528.53	

Revision 4/1/2020 Page 2 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	on				
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J4I3333	I 435-1(331)	Coldmill and resurface	435	PLATTE	from Platte County line to I-29						
Totals by .	Job Numbers	3									
J4I3333					This Estimate	Previous	To Date				
		Item Pay			\$0.00	\$145,290.73	\$145,290.73				
	Gross I	tem Adjustme			\$11,528.53	\$1,055.47	\$12,584.00				
			Gross	Item Pay	\$11,528.53	\$146,346.20	\$157,874.73				
	Incentiv	/e			\$0.00	\$0.00	\$0.00				
	Disince	ntive			\$0.00	\$0.00	\$0.00				
	Liquida	ted Damages			\$0.00	\$0.00	\$0.00				
	Liquidated Damages										

Revision 4/1/2020 Page 3 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4l3333, Item 6131010, Project Item Line Number 0080, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3333, Item 6131010, Project Item Line Number 0080, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Material testing results will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3333, Item 6131015, Project Item Line Number 0120, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Material certification and PAL form will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3333, Item 6131015, Project Item Line Number 0120, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Material certification and PAL form will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3333, Item 6161098A, Project Item Line Number 0150, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Material certification will be added at a later date	woodwj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3333, Item 6169901, Project Item Line Number 0170, Material Set 6169901, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Material certification will be added at a later date	woodwj1	Overridden

Revision 4/1/2020 Page 4 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bild Net Total Unit Total Contract Project Category Line Item Description Right Net Total Unit Total Contract Project Category Line Item Description Right Net Total Unit Total Contract Project Category Line Item Description Right Net Total Contract Right Net

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211119-C05	J4I3333	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$825.00	\$0.00
		0001	0020	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	21,517.00	0.00	21,517.00	TONS	0.00	\$65.21	\$0.00
		0001	0030	4011213	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-3)	226.00	0.00	226.00	TONS	0.00	\$166.48	\$0.00
		0001	0040	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	50,535.00	0.00	50,535.00	TONS	0.00	\$85.32	\$0.00
		0001	0050	4071005	TACK COAT	19,047.00	0.00	19,047.00	GAL	0.00	\$2.50	\$0.00
		0001	0060	4079912	MISC.Polymer Modified Emulsion Membrane	87,735.00	0.00	87,735.00	GAL	0.00	\$2.50	\$0.00
		0001	0070	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.00
		0001	0080	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	344.00	35.20	379.20	SQYD	379.20	\$312.65	\$118,556.88
		0001	0090	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	344.00	-344.00	0.00	SQYD	0.00	\$8.00	\$0.00
		0001	0100	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	344.00	-344.00	0.00	SQYD	0.00	\$14.00	\$0.00
		0001	0110	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,368.00	350.00	1,718.00	LF	1,718.00	\$1.45	\$2,491.10
		0001	0120	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	948.00	3.00	951.00	EA	951.00	\$5.25	\$4,992.75
		0001	0130	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	53.00	0.00	53.00	TONS	0.00	\$386.16	\$0.00
		0001	0140	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	320.00	0.00	320.00	SQYD	0.00	\$205.41	\$0.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,500.00	\$18,000.00
		0001	0160	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,300.00	\$0.00
		0001	0170	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.25	\$5,000.00	\$1,250.00
		0001	0180	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$619,041.39	\$0.00
		0001	0190	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	192.00	0.00	192.00	LF	0.00	\$0.25	\$0.00
		0001	0200	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	0.00	\$350.00	\$0.00
		0001	0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	176,453.00	0.00	176,453.00	LF	0.00	\$0.25	\$0.00
		0001	0220	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	141,832.00	0.00	141,832.00	LF	0.00	\$0.25	\$0.00
		0001	0230	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	9,766.00	0.00	9,766.00	LF	0.00	\$0.50	\$0.00
		0001	0240	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	653,694.00	0.00	653,694.00	SQYD	0.00	\$1.41	\$0.00
		0001	0250	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	271.00	0.00	271.00	SQYD	0.00	\$107.02	\$0.00
		0001	0260	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,192.00	0.00	2,192.00	STA	0.00	\$9.26	\$0.00
		0010	0270	6061060	MGS GUARDRAIL	475.00	0.00	475.00	LF	0.00	\$30.00	\$0.00
		0010	0280	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	0.00	\$1,175.00	\$0.00
		0010	0290	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	0.00	\$2,825.00	\$0.00
					Date as of Report Generated Date							\$145,290.73
11119-C05 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	port Generated Date							\$145,290.73

Revision 4/1/2020 Page 5 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Page 6 of 8 Revision 4/1/2020



Line Item Adjustments by Estimate

Contract ID:190215-D05

	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3333	0800	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		1	May 3, 2022	SYSTEM	\$118,556.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	May 3, 2022	SYSTEM	(\$118,556.88)	
					2	May 16, 2022	SYSTEM	\$118,556.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	May 16, 2022	SYSTEM	(\$118,556.88)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	1	May 3, 2022	woodwj1	(\$11,005.28)	Manual adjustment removing overrun quantity. This will be returned when the overrun is resolved on a change order or the material exceptions are resolved
					1	May 3, 2022	SYSTEM	\$11,005.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 379.200; Overrun Quantity Balance 35.20.
					1	May 3, 2022	SYSTEM	(\$11,005.28)	
					2	May 16, 2022	woodwj1	\$11,005.28	Returning manual adjustment now that the Overrun has been resolved on CO 0001
				Overrun - To	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0080 -	Total						\$0.00	
	0110	10 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	Overrun	Overrun	1	May 3, 2022	SYSTEM	(\$507.50)	
	F				2	May 16, 2022	SYSTEM	\$507.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.45000 - 1.45000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0110 -	Total							
	0110 - T 0120							\$0.00	
	0120	(DRILLING, FURNISHING AND	Material		1	May 3, 2022	SYSTEM	\$0.00 \$4,992.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	0120	(DRILLING,	Material		1		SYSTEM		Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment
	0120	(DRILLING, FURNISHING AND	Material			2022 May 3,		\$4,992.75	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment
	0120	(DRILLING, FURNISHING AND	Material		1	2022 May 3, 2022 May 16,	SYSTEM	\$4,992.75 (\$4,992.75)	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment
	0120	(DRILLING, FURNISHING AND	Material	- Total	1 2	2022 May 3, 2022 May 16, 2022	SYSTEM	\$4,992.75 (\$4,992.75) \$4,992.75	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment
	0120	(DRILLING, FURNISHING AND	Material Material - To		1 2	2022 May 3, 2022 May 16, 2022	SYSTEM	\$4,992.75 (\$4,992.75) \$4,992.75 (\$4,992.75)	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment
	0120	(DRILLING, FURNISHING AND			1 2 2	2022 May 3, 2022 May 16, 2022	SYSTEM	\$4,992.75 (\$4,992.75) \$4,992.75 (\$4,992.75)	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Manual adjustment removing overrun quantity. This will be returned when the
	0120	(DRILLING, FURNISHING AND	Material - To	tal	1 2 2	2022 May 3, 2022 May 16, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM	\$4,992.75 (\$4,992.75) \$4,992.75 (\$4,992.75) \$0.00	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment
	0120	(DRILLING, FURNISHING AND	Material - To	tal	1 2 2	2022 May 3, 2022 May 16, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM woodwj1	\$4,992.75 (\$4,992.75) \$4,992.75 (\$4,992.75) \$0.00 \$0.00 (\$15.75)	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Manual adjustment removing overrun quantity. This will be returned when the overrun is resolved on a change order or the material exceptions are resolved. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 951.000;
	0120	(DRILLING, FURNISHING AND	Material - To	tal	1 2 2 1 1 1	2022 May 3, 2022 May 16, 2022 May 16, 2022 May 3, 2022 May 3, 2022	SYSTEM SYSTEM SYSTEM woodwj1 SYSTEM	\$4,992.75 (\$4,992.75) \$4,992.75 (\$4,992.75) \$0.00 \$0.00 (\$15.75)	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Manual adjustment removing overrun quantity. This will be returned when the overrun is resolved on a change order or the material exceptions are resolved. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 951.000;
	0120	(DRILLING, FURNISHING AND	Material - To	tal	1 2 2 1 1 1 2 2	2022 May 3, 2022 May 16, 2022 May 16, 2022 May 3, 2022 May 3, 2022 May 3, 2022 May 4, May 3,	SYSTEM SYSTEM woodwj1 SYSTEM SYSTEM	\$4,992.75 (\$4,992.75) \$4,992.75 (\$4,992.75) \$0.00 \$0.00 (\$15.75)	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Manual adjustment removing overrun quantity. This will be returned when the overrun is resolved on a change order or the material exceptions are resolved. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 951.000; Overrun Quantity Balance 3.00.
	0120	(DRILLING, FURNISHING AND	Material - To	tal Overrun Overrun - To	1 2 2 1 1 1 2 2	2022 May 3, 2022 May 16, 2022 May 16, 2022 May 3, 2022 May 3, 2022 May 3, 2022 May 4, May 3,	SYSTEM SYSTEM woodwj1 SYSTEM SYSTEM	\$4,992.75 (\$4,992.75) \$4,992.75 (\$4,992.75) \$0.00 \$0.00 (\$15.75) \$15.75	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Manual adjustment removing overrun quantity. This will be returned when the overrun is resolved on a change order or the material exceptions are resolved. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 951.000; Overrun Quantity Balance 3.00.
	0120	(DRILLING, FURNISHING AND INST	Material - To Overrun	tal Overrun Overrun - To	1 2 2 1 1 1 2 2	2022 May 3, 2022 May 16, 2022 May 16, 2022 May 3, 2022 May 3, 2022 May 3, 2022 May 4, May 3,	SYSTEM SYSTEM woodwj1 SYSTEM SYSTEM	\$4,992.75 (\$4,992.75) \$4,992.75 (\$4,992.75) \$0.00 (\$15.75) \$15.75 \$15.75	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Manual adjustment removing overrun quantity. This will be returned when the overrun is resolved on a change order or the material exceptions are resolved. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 951.000; Overrun Quantity Balance 3.00.
		(DRILLING, FURNISHING AND INST	Material - To Overrun	tal Overrun Overrun - To	1 2 2 1 1 1 2 2	2022 May 3, 2022 May 16, 2022 May 16, 2022 May 3, 2022 May 3, 2022 May 3, 2022 May 4, May 3,	SYSTEM SYSTEM woodwj1 SYSTEM SYSTEM	\$4,992.75 (\$4,992.75) \$4,992.75 (\$4,992.75) \$0.00 (\$15.75) \$15.75 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodwj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Manual adjustment removing overrun quantity. This will be returned when the overrun is resolved on a change order or the material exceptions are resolved. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 951.000; Overrun Quantity Balance 3.00.





Line Item Adjustments by Estimate

Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3333	0150	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		2	May 16, 2022	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		CONT F/			2	May 16, 2022	SYSTEM	(\$18,000.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0150 -	Total						\$0.00	
	0170	MISC.	Material		1	May 3, 2022	SYSTEM	\$1,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodwj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					1	May 3, 2022	SYSTEM	(\$1,250.00)	
					2	May 16, 2022	SYSTEM	\$1,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodwj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	May 16, 2022	SYSTEM	(\$1,250.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0170 -	Total						\$0.00	
	0270	MGS GUARDRAIL	Construction Stockpile STMA		1	May 3, 2022	SYSTEM	\$9,842.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STWA	- Total				\$9,842.00	
			Construction	Stockpile S	TMA - Tota	al		\$9,842.00	
	0270 -	Total						\$9,842.00	
	0280	MGS END ANCHOR	Construction Stockpile STMA		1	May 3, 2022	SYSTEM	\$842.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVIA	- Total				\$842.00	
			Construction	Stockpile S	TMA - Tota	al		\$842.00	
	0280 -	Total						\$842.00	
	0290	TYPE A CRASHWORTHY	Construction Stockpile		1	May 3, 2022	SYSTEM	\$1,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL (MASH)	STMA	- Total				\$1,900.00	
			Construction	Stockpile S	TMA - Tota	al		\$1,900.00	
	0290 -	Total						\$1,900.00	
J4I3333 -	Total							\$12,584.00	
Overall -	Total							\$12,584.00	