

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 2, 2022

Progress Estimate Number 5		Contract ID Prime Contractor	211217-H05 Apex Paving Co.	ving Co. Pay Period End June 1, 2022 Net Change Order Amo		Original Contract Amount Net Change Order Amount Current Contract Amount	\$10,080,771.09 \$0.00 \$10,080,771.09
Approval Date							By User
June 2, 2022		G	enerated and Appr	oved (and should be	considered Dra	ft) at the Project Office Level by	woodsk1
June 3, 2022		Revie	wed and Approved	(and should be cons	idered Draft) at	the Resident Engineer Level by	bollis1
June 6, 2022			Revi	ewed and Approved	at the Central C	Office Controllers Office Level by	ramses1
Original Comp	letion Date	Current Comple	Current Completion Date Actual Completion Date % of Current Contract Ame				unt Complete
July 31,	2023	July 31, 2023 7.82%					

	Milestones		
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	January 5, 2022	January 5, 2022	
Letting Date	December 17, 2021	December 17, 2021	
Notice to Proceed Date	March 7, 2022	March 7, 2022	
Open to Traffic Date			
Work Began Date			

Contract Total Pay For Estimate No. 5											
		This Estimate	Previous	To Date							
211217-H05											
	Total Posted Items Pay	\$128,623.20	\$659,921.46	\$788,544.66							
	Gross Item Adjustments	\$0.00	\$14,349.26	\$14,349.26							
	Incentive	\$0.00	\$0.00	\$0.00							
	Disincentive	\$0.00	\$0.00	\$0.00							
	Liquidated Damage	\$0.00	\$0.00	\$0.00							
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00							
	•		\$674,270.72	\$802,893.92							
Contract Total Pag	yable This Estimate:	\$128,623.20									

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J9I3597	0190	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$225.000	88	\$19,800.00			
	0200	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	SQYD	\$6.000	8.8	\$52.80			
	0210	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	SQYD	\$8.000	8.8	\$70.40			
	0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$10.000	396	\$3,960.00			
	0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$8.000	110	\$880.00			
	0260	6134001	DOWEL BAR RETROFIT	EA	\$90.000	1,146	\$103,140.00			
	0270	6139903	MISC.TYPE E EXPANSION JOINT	LF	\$30.000	24	\$720.00			
Project J9l3597 - Total										
Overall - T	Overall - Total									

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3597	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)				-258.1	\$12.00	(\$3,097.20)
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)			This adjustment offsets the original system- generated Material Payment Estimate Item	258.1	\$12.00	\$3,097.20

Revision 4/1/2020 Page 1 of 13



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 2, 2022

Progress Estimate Number
5

Contract ID 211217-H05 Pay Period Start May 16, 2022 Original Contract Amount Superior Start May 16, 2022 Original Contract Amount Superior Superi

ect per	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
97					Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
	0800	TYPE A3 SHOULDER	Material			-117.33	\$37.51	(\$4,401.05
	0800	TYPE A3 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	117.33	\$37.51	\$4,401.05
	0150	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material			-140.8	\$90.00	(\$12,672.00
	0150	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	140.8	\$90.00	\$12,672.00
	0160	PIPE AGGREGATE PAVEMENT EDGE DRAIN	Material			-955.7	\$15.00	(\$14,335.50
	0160	PIPE AGGREGATE PAVEMENT EDGE DRAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	955.7	\$15.00	\$14,335.50
	0170	OUTLET PIPES AND SPLASH PADS	Material			-8	\$1,350.00	(\$10,800.00
	0170	OUTLET PIPES AND SPLASH PADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	8	\$1,350.00	\$10,800.00
	0190	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-176	\$225.00	(\$39,600.00
	0190	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	176	\$225.00	\$39,600.00
	0200	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-17.8	\$6.00	(\$106.80
	0200	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	17.8	\$6.00	\$106.80
	0230	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-220	\$8.00	(\$1,760.00
	0230	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	220	\$8.00	\$1,760.00
	0260	DOWEL BAR RETROFIT	Material			-1,596	\$90.00	(\$143,640.00
	0260	DOWEL BAR RETROFIT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	1,596	\$90.00	\$143,640.00

Revision 4/1/2020 Page 2 of 13



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 2, 2022

Progress Estimate Number 5 Contract ID 211217-H05 Prime Contractor Apex Paving 0						Pay Period Start Pay Period End	nount \$0	\$10,080,771.09 \$0.00 \$10,080,771.09			
Project Number	Line No.	Item Descript	ion	Adjustment Type	Other Item Adjustment Type	Comn	ments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3597						Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.					
	0270		MISC.	Material					-24	\$30.00	(\$720.00)
	0270 MISC. Material			This adjustment offs generated Material I Adjustment (000 <sup>o</sup> overridding Payment on the curr	Payment Estin 1) due to user	nate Item woodsk1 eption 25	24	\$30.00	\$720.00		
Total											\$0.00

Revision 4/1/2020 Page 3 of 13



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Informati	on						
Project Number													
J9I3597	I 155-1(123	Resurface	155	PEMISCOT	from Rte. 412 to Tenn	om Rte. 412 to Tennessee State line							
Totals by J	Job Numbe	rs											
J9l3597		d Item Pay Item Adjustme		Item Pay	This Estimate \$128,623.20 \$0.00 <b>\$128,623.20</b>	Previous \$659,921.46 \$14,349.26 <b>\$674,270.72</b>	To Date \$788,544.66 \$14,349.26 \$802,893.92						
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						

Revision 4/1/2020 Page 4 of 13



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6053030A, Project Item Line Number 0160, Material Set 6053030A96, Material 1011GXT1 - Geotextile Fabric for SubsrfDrainage(T1), Acceptance Action Generic 1011GXT1 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6053030A, Project Item Line Number 0160, Material Set 6053030A96, Material 1009G5DRLS - Agg for Drainage Gr5 Limestone, Acceptance Action Generic 1009G5DRLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6053030A, Project Item Line Number 0160, Material Set 6053030A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6054020, Project Item Line Number 0170, Material Set 605402096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6054020, Project Item Line Number 0170, Material Set 605402096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6054020, Project Item Line Number 0170, Material Set 605402096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6054020, Project Item Line Number 0170, Material Set 605402096, Material 1013DMPVSC4.04 - Underdrain Sch40 PVC 4" (102mm), Acceptance Action Generic 1013DMPVSC4.04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 6131010, Project Item Line Number 0190, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6131010, Project Item Line Number 0190, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6131010, Project Item Line Number 0190, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6131012, Project Item Line Number 0200, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6131015, Project Item Line Number 0230, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6134001, Project Item Line Number 0260, Material Set 613400196, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6134001, Project Item Line Number 0260, Material Set 613400196, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6134001, Project Item Line Number 0260, Material Set 613400196, Material 0704CMRP - Rapid Set Concrete Patching Material, Acceptance	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 5 of 13



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Action Generic 0704CMRP is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 6139903, Project Item Line Number 0270, Material Set 6139903, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6139903, Project Item Line Number 0270, Material Set 6139903, Material 1057JMJCSSEX - Silicon Sealant for Expansion Jnts @, Acceptance Action Generic 1057JMJCSSEX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 6 of 13



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211217-H05	J9I3597	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.80	\$76,208.14	\$60,966.5
		0001	0020	2039907	MISC.TRENCHING FOR PIPE AGGREGATE EDGE DRAIN	100.00	0.00	100.00	CUYD	23.60	\$190.00	\$4,484.0
		0001	0030	2129900	MISC.SHOULDER GRADING	46.00	0.00	46.00	100F	0.00	\$227.95	\$0.0
		0001	0035	2159903	MISC.Modified Shaping Slopes Class III	1,760.00	0.00	1,760.00	LF	0.00	\$10.00	\$0.0
		0001	0040	3030600	FURNISHING ROCK BASE MATERIAL	977.00	0.00	977.00	SQYD	398.90	\$25.00	\$9,972.5
		0001	0050	3030610A	PLACING ROCK BASE	977.00	0.00	977.00	SQYD	398.90	\$10.00	\$3,989.0
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,081.00	0.00	1,081.00	SQYD	258.10	\$12.00	\$3,097.2
		0001	0070	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	9,357.00	0.00	9,357.00	TONS	0.00	\$44.27	\$0.
		0001	0800	4010151	TYPE A3 SHOULDER	9,827.30	0.00	9,827.30	SQYD	117.33	\$37.51	\$4,401.
		0001	0090	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	22,548.10	0.00	22,548.10	TONS	49.00	\$78.78	\$3,860.
		0001	0095	4019901	MISC.NRRA SUPPLEMENTARY TEST SECTIONS	1.00	0.00	1.00	LS	0.00	\$144,283.66	\$0.
		0001	0120	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	42,848.90	0.00	42,848.90	TONS	0.00	\$93.78	\$0.
		0001	0124	4031058	INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	0.00	\$40,470.36	\$0.
		0001	0125	4031059	PAVER-MOUNTED THERMAL PROFILES	1.00	0.00	1.00	LS	0.00	\$4,855.28	\$0.
		0001	0130	4071005	TACK COAT	12,646.00	0.00	12,646.00	GAL	0.00	\$2.33	\$0.
		0001	0135	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	73,357.00	0.00	73,357.00	GAL	0.00	\$2.60	\$0.
		0001	0140	4134000	BITUMINOUS FOG SEAL	14,167.00	0.00	14,167.00	GAL	0.00	\$3.39	\$0.
		0001	0150	5021109	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	345.00	0.00	345.00	SQYD	140.80	\$90.00	\$12,672
		0001 0	0160	6053030A	PIPE AGGREGATE PAVEMENT EDGE DRAIN	4,034.00	0.00	4,034.00	LF	955.70	\$15.00	\$14,335.
			0170	6054020	OUTLET PIPES AND SPLASH PADS	34.00	0.00	34.00	EA	8.00	\$1,350.00	\$10,800
		0001	0180	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	0.00	\$0.00	\$0
		0001	0190	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	1,144.00	0.00	1,144.00	SQYD	176.00	\$225.00	\$39,600
		0001 020		6131012	DEPTH PAVEMENT REPAIR  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	114.00	0.00	114.00	SQYD	17.80	\$6.00	\$106
				6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	114.00	0.00	114.00	SQYD	17.80	\$8.00	\$142.
		0001	0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	4,724.00	0.00	4,724.00	LF	790.00	\$10.00	\$7,900
		0001	0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	2,100.00	0.00	2,100.00	EA	220.00	\$8.00	\$1,760
		0001	0240	6132018	FURNISHING AND PLACING CONCRETE MATERIAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	49.40	0.00	49.40	CUYD	0.00	\$1,650.00	\$0
		0001	0250	6132019	REMOVAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	395.60	0.00	395.60	SQYD	0.00	\$115.00	\$0
		0001	0260	6134001	DOWEL BAR RETROFIT	10,680.00	0.00	10,680.00	EA	1,596.00	\$90.00	\$143,640
		0001	0270	6139903	MISC.TYPE E EXPANSION JOINT	456.00	0.00	456.00	LF	48.00	\$30.00	\$1,440
		0001	0280	6161005	CONSTRUCTION SIGNS	4,196.00	0.00	4,196.00	SQFT	696.00	\$8.00	\$5,568
		0001	0290	6161008	ADVANCED WARNING RAIL SYSTEM	12.00	0.00	12.00	EA	12.00	\$35.00	\$420
		0001	0300	6161025	CHANNELIZER (TRIM LINE)	962.00	0.00	962.00	EA	150.00	\$20.00	\$3,000
		0001	0310	6161030	TYPE III MOVEABLE BARRICADE	4.00	0.00	4.00	EA	0.00	\$150.00	\$0
		0001	0320	6161033	DIRECTIONAL INDICATOR BARRICADE	178.00	0.00	178.00	EA	32.00	\$0.00	\$0
		0001	0330	6161040	FLASHING ARROW PANEL	9.00	0.00	9.00	EA	2.00	\$1,000.00	\$2,000
		0001	0340	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	2.00	\$3,200.00	\$6,400
		0001	0350	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	0.00	\$10,000.00	\$0
		0001	0360	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	0.00	\$0.00	\$0
		0001	0370	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	160.00	0.00	160.00	LF	0.00	\$178.29	\$0
		0001	0380	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$263,893.91	\$65,973
		0001	0390	6200039	PREFORMED THERMOPLASTIC PAVEMENT MARKING, OFF RAMP WRONG WAY ARROW	4.00	0.00	4.00	EA	0.00	\$1,500.00	\$0
		0001	0400	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,200.00	0.00	1,200.00	LF	0.00	\$2.00	\$0
		0001	0410	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,000.00	0.00	2,000.00	LF	0.00	\$2.00	\$0.

Page 7 of 13 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211217-H05	J9I3597	0001	0420	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	60.00	0.00	60.00	LF	0.00	\$10.00	\$0.00
		0001	0430	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	151,103.00	0.00	151,103.00	LF	0.00	\$0.22	\$0.00
		0001	0440	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	123,088.00	0.00	123,088.00	LF	0.00	\$0.22	\$0.00
		0001	0450	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,530.00	0.00	7,530.00	LF	0.00	\$1.00	\$0.00
		0001	0460	6207001	PAVEMENT MARKING REMOVAL	4,060.00	0.00	4,060.00	LF	0.00	\$2.00	\$0.00
		0001	0470	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$16,769.52	\$0.00
		0001	0480	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	49,344.00	0.00	49,344.00	SQYD	0.00	\$2.15	\$0.00
		0001	0490	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	22,967.00	0.00	22,967.00	SQYD	0.00	\$6.20	\$0.00
		0001	0500	6252001	UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	10,022.00	0.00	10,022.00	LB	0.00	\$3.85	\$0.00
		0001	0510	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	2,274.00	0.00	2,274.00	LB	0.00	\$3.85	\$0.00
		0001	0520	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,109.70	0.00	2,109.70	STA	0.00	\$24.50	\$0.00
		0010	0530	6061060	MGS GUARDRAIL	8,588.00	0.00	8,588.00	LF	8,388.00	\$32.00	\$268,416.00
		0010	0540	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	10.00	0.00	10.00	EA	8.00	\$3,700.00	\$29,600.00
		0010	0550	6061080	MGS END ANCHOR	18.00	0.00	18.00	EA	16.00	\$1,500.00	\$24,000.00
		0010	0560	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	22.00	0.00	22.00	EA	20.00	\$3,000.00	\$60,000.00
		0070	0570	7034600	CURB BLOCKOUT	611.00	0.00	611.00	LF	0.00	\$125.07	\$0.00
Project J9l3597 - Total Value Posted to Date as of Report Generated Date											\$788,544.66	
211217-H05 Ove	erall - Tota	I Value Pos	ted to Da	ate as of Rep	port Generated Date							\$788,544.66

Revision 4/1/2020 Page 8 of 13



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: .1913597

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0190	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	5/26/22	6/2/22	88.00	SQYD	I-155 NB DL Only Estimated Quantities. DL Only.	2.672		4.911		I-155 NB DL Only Estimated Quantities. DL Only.
0200	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	5/26/22	6/2/22	8.80	SQYD	I-155 NB DL Only Estimated Quantities. DL Only.	2.672		4.911		I-155 NB DL Only Estimated Quantities. DL Only.
0210	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	5/26/22	6/2/22	8.80	SQYD	I-155 NB DL Only Estimated Quantities. DL Only.	2.672		4.911		I-155 NB DL Only Estimated Quantities. DL Only.
0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	5/26/22	6/2/22	396.00	LF	I-155 NB DL Only Estimated Quantities. DL Only.	2.672		4.911		I-155 NB DL Only Estimated Quantities. DL Only.
0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	5/26/22	6/2/22	110.00	EA	I-155 NB DL Only Estimated Quantities. DL Only.	2.672		4.911		I-155 NB DL Only Estimated Quantities. DL Only.
0260	6134001	DOWEL BAR RETROFIT	5/26/22	6/2/22	1,146.00	EA	I-155 NB DL Only Estimated Quantities. DL Only.	2.672		4.911		I-155 NB DL Only Estimated Quantities. DL Only.
0270	6139903	MISC. PAVEMENT REPAIR	5/26/22	6/2/22	24.00	LF	Two (2) NB DL Placed this period. MM 7 & MM 6 Approximately.	2.672 (7)		4.911 (6)		Two (2) NB DL Placed this period. MM 7 & MM 6 Approximately.

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Pos
13597	0280	April 14, 2022	156	CONST-7 72x36 18.00 RATE OUR WORK ZONE		2	Route I-155	2.00	18		18.00	
				GO20-2 48x24 8.00 END ROAD WORK		1.5	Route I-155	2.00	8		8.00	
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		0.474	Route I-155	2.00	10		10.00	
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		.972	Route I-155	2.00	10		10.00	
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		2.5	Route I-155	4.00	12		12.00	
		April 26, 2022	540	WO4-1aR 48x48 16.00 MERGE (ARROW SYMBOL)		0.474	I-155 NBL	4.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.474	I-155 NBL	4.00	16			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.474	I-155 NBL	4.00	16			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		0.474	I-155 NBL	6.00	16			
				WO4-1aL 48x48 16.00 MERGE (ARROW SYMBOL)		0.474	I-155 NBL	4.00	16			
				R4-1 36x48 12.00 DO NOT PASS		0.474	I-155 NBL	4.00	12			
				See Special Sign Details	0.		I-155 NBL					
				CONST-3A 60x48 20.00 FINE SIGN		0.474	I-155 NBL	3.00	20			
				WO4-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		0.474	I-155 NBL	2.00	16			
				R2-1 36x48 12.00 SPEED LIMIT XX		0.474	I-155 NBL	4.00	12			

Revision 4/1/2020 Page 9 of 13



# Line Item Adjustments by Estimate

				2.1								
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J9I3597	0060	TYPE 5 AGGREGATE FOR BASE	Material		3	May 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					3	May 2, 2022	SYSTEM	(\$3,097.20)				
								4	May 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$3,097.20)				
					5	Jun 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					5	Jun 2, 2022	SYSTEM	(\$3,097.20)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
			Price FUEL		3	May 2, 2022	SYSTEM	\$50.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				- Total				\$50.33				
			Price FUEL -					\$50.33				
	0060 -	Total		- Juli								
					4		0)/0==-	\$50.33				
	0800	TYPE A3 SHOULDER	Material		4	May 16, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					4	May 16, 2022	SYSTEM	(\$4,401.05)				
					5	Jun 2, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					5	Jun 2, 2022	SYSTEM	(\$4,401.05)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0080 -	Total						\$0.00				
	0090	BIT. PAVEMENT MIXTURE	Price FUEL		4	May 16, 2022	SYSTEM	\$312.35	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
		PG64-22 (BP-1)		- Total				\$312.35				
			Price FUEL -	Total				\$312.35				
	0090 -	Total						\$312.35				
	0150	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material	Material	Material		3	May 2, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					3	May 2, 2022	SYSTEM	(\$12,672.00)				
					4	May 16, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
						4	May 16, 2022	SYSTEM	(\$12,672.00)			
												5
					5	Jun 2, 2022	SYSTEM	(\$12,672.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
			Price FUEL		3	May 2, 2022	SYSTEM	\$120.81	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				- Total				\$120.81				
			Price FUEL -	Total				\$120.81				



# Line Item Adjustments by Estimate

	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
97	0150 -	Total						\$120.81		
	0160	PIPE AGGREGATE PAVEMENT EDGE DRAIN	Material		4	May 16, 2022	SYSTEM	\$14,335.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
		EDGE DIVAIN			4	May 16, 2022	SYSTEM	(\$14,335.50)		
					5	Jun 2, 2022	SYSTEM	\$14,335.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					5	Jun 2, 2022	SYSTEM	(\$14,335.50)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0160 -	Total						\$0.00		
	0170	OUTLET PIPES AND SPLASH PADS	Material		4	May 16, 2022	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					4	May 16, 2022	SYSTEM	(\$10,800.00)		
					5	Jun 2, 2022	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					5	Jun 2, 2022	SYSTEM	(\$10,800.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0170 -	Total						\$0.00		
	0190	FURN & PLACE CONC MATL FOR FULL DEPTH	CONC MATL FOR FULL	Material		4	May 16, 2022	SYSTEM	\$19,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$19,800.00)		
					5	Jun 2, 2022	SYSTEM	\$39,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					5	Jun 2, 2022	SYSTEM	(\$39,600.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0190 -	Total						\$0.00		
	0200	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	Material		4	May 16, 2022	SYSTEM	\$54.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
			(PAVEM			4	May 16,	SYSTEM		
						2022	0.0.2	(\$54.00)		
					5		SYSTEM	(\$54.00) \$106.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					5	2022 Jun 2,			Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment	
				- Total		Jun 2, 2022 Jun 2, 2022	SYSTEM	\$106.80	Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment	
			Material - To			Jun 2, 2022 Jun 2, 2022	SYSTEM	\$106.80 (\$106.80)	Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment	
	0200 -	Total	Material - To			Jun 2, 2022 Jun 2, 2022	SYSTEM	\$106.80 (\$106.80)	Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment	
	<b>0200</b> - 0230	DOWEL BAR (DRILLING, FURNISHING				Jun 2, 2022 Jun 2, 2022	SYSTEM	\$106.80 (\$106.80) \$0.00	Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment	
		DOWEL BAR (DRILLING,			5	Jun 2, 2022 Jun 2, 2022 Jun 2, 2022	SYSTEM	\$106.80 (\$106.80) \$0.00 \$0.00	Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment	
		DOWEL BAR (DRILLING, FURNISHING			5	2022 Jun 2, 2022 Jun 2, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM	\$106.80 (\$106.80) \$0.00 \$0.00 \$0.00 \$880.00	Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment	



# Line Item Adjustments by Estimate

ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
597	0230	DOWEL BAR (DRILLING,	Material	- Total				\$0.00	
		FURNISHING AND INST						\$0.00	
	0230 -	Total						\$0.00	
	0260	DOWEL BAR RETROFIT	Material		4	May 16, 2022	SYSTEM	\$40,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$40,500.00)	
					5	Jun 2, 2022	SYSTEM	\$143,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$143,640.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0260 -	Total						\$0.00	
	0270	MISC. PAVEMENT	Material		5	Jun 2, 2022	SYSTEM	\$720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
		REPAIR			5	Jun 2, 2022	SYSTEM	(\$720.00)	Estimate Exception 25 on the current Payment Estimate.
				Total		2022		60.00	
				- Total				\$0.00	
			Material - To	tai				\$0.00	
	0270 -							\$0.00	
	0530	MGS GUARDRAIL	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$116,280.48)	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	May 2, 2022	SYSTEM	(\$52,979.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$169,259.98)	
			Construction	n Stockpile - 1	Total			(\$169,259.98)	
			Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$173,295.75	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$173,295.75	
			Construction	n Stockpile S	TMI - Tota			\$173,295.75	
	0530 -	Total						\$4,035.77	
	0540	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$16,880.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$16,880.00)	
			Construction	n Stockpile - 1	Total			(\$16,880.00)	
			Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$21,100.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$21,100.00	
			Construction	n Stockpile S	TMI - Tota			\$21,100.00	
	0540 -	Total						\$4,220.00	
	0550	MGS END ANCHOR	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$5,130.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	May 2, 2022	SYSTEM	(\$8,550.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$13,680.00)	
			Construction	n Stockpile - 1	Total			(\$13,680.00)	
			Construction Stockpile		1	Mar 16, 2022	SYSTEM	\$15,390.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$15,390.00	
			Construction	n Stockpile S	TMI - Total			\$15,390.00	
								\$1,710.00	
	0550 -	otal							
	<b>0550</b> - 0560	TYPE A	Construction		2	Apr 18,	SYSTEM	(\$19,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction

Jun 7, 2022



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0560	END TERMINAL (MASH)	Construction Stockpile		3	May 2, 2022	SYSTEM	(\$19,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$39,000.00)	
			Construction	Stockpile - 1	Γotal			(\$39,000.00)	
			Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$42,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$42,900.00	
		Construction Stockpile STMI - Total							
	0560 - Total								
J9I3597 -	J9I3597 - Total								
Overall -	Overall - Total								