

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 1, 2022

Progress Estimate Number 7		Contract ID Prime Contractor	211217-H05 Apex Paving Co.	Pay Period Start Pay Period End	June 16, 2022 June 30, 2022	Original Contract Amount Net Change Order Amount Current Contract Amount	\$10,080,771.09 \$0.00 \$10,080,771.09
Approval Date							By User
July 1, 2022		Ge	enerated and Appro	oved (and should be	considered Dra	ft) at the Project Office Level by	woodsk1
July 1, 2022		Review	ved and Approved	(and should be cons	idered Draft) at	the Resident Engineer Level by	bollis1
July 5, 2022			Revi	ewed and Approved	at the Central O	ffice Controllers Office Level by	ramses1
Original Comp	letion Date	Current Comple	etion Date	Actual Completion	n Date	% of Current Contract Amou	unt Complete
July 31, 2	2023	July 31, 20	023			11.25%	

	Contract Informational Dates										
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract								
Acceptance Date											
Awarded Date	January 5, 2022	January 5, 2022									
Letting Date	December 17, 2021	December 17, 2021									
Notice to Proceed Date	March 7, 2022	March 7, 2022									
Open to Traffic Date											
Work Began Date											

Contract Total Pa	ay For Estimate No. 7				
		This Estimate	Previous	To Date	
211217-H05					
	Total Posted Items Pay	\$244,977.95	\$888,738.14	\$1,133,716.09	
	Gross Item Adjustments	\$0.00	\$14,349.26	\$14,349.26	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$903,087.40	\$1,148,065.35	
Contract Total Pa	avable This Estimate:	\$244,977,95			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3597	0190	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$225.000	320	\$72,000.00
	0200	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	SQYD	\$6.000	32	\$192.00
	0210	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	SQYD	\$8.000	32	\$256.00
	0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$10.000	1,076	\$10,760.00
	0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$8.000	598	\$4,784.00
	0260	6134001	DOWEL BAR RETROFIT	EA	\$90.000	786	\$70,740.00
	0270	6139903	MISC.TYPE E EXPANSION JOINT	LF	\$30.000	12	\$360.00
	0300	6161025	CHANNELIZER (TRIM LINE)	EA	\$20.000	20	\$400.00
	0500	6252001	UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	LB	\$3.850	10,022	\$38,584.70
	0510	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	LB	\$3.850	2,274	\$8,754.90
	0570	7034600	CURB BLOCKOUT	LF	\$125.070	305	\$38,146.35
Project J9I	3597 - Tot	al					\$244,977.95
Overall - T	otal						\$244,977.95

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 1, 2022

Progress Estimate Number 7 Contract ID 211217-H05 Pay Period Start June 16, 2022 Original Contract Amount Sune 30, 2022 Net Change Order Amount Current Contract Amount Sune 30, 2022 Su

ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3597	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-258.1	\$12.00	(\$3,097.2
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	258.1	\$12.00	\$3,097.20
	0800	TYPE A3 SHOULDER	Material			-117.33	\$37.51	(\$4,401.0
	0800	TYPE A3 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	117.33	\$37.51	\$4,401.0
	0150	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material			-140.8	\$90.00	(\$12,672.00
	0150	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	140.8	\$90.00	\$12,672.00
	0200	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-49.8	\$6.00	(\$298.80
	0200	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	49.8	\$6.00	\$298.80
	0420	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material			-60	\$10.00	(\$600.00
	0420	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	60	\$10.00	\$600.00
	0500	UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	Material			-10,022	\$3.85	(\$38,584.70
	0500	UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	10,022	\$3.85	\$38,584.70
	0510	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	Material			-2,274	\$3.85	(\$8,754.90
	0510	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	2,274	\$3.85	\$8,754.90
	0570	CURB BLOCKOUT	Material			-305	\$125.07	(\$38,146.35
	0570	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	305	\$125.07	\$38,146.3

Revision 4/1/2020 Page 2 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	١							
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work								
J9I3597	I 155-1(123)	Resurface	155	PEMISCOT	from Rte. 412 to Tenn	essee State line								
Totals by	Job Number	s												
J9I3597					This Estimate	Previous	To Date							
	Posted	Item Pay			\$244,977.95	\$888,738.14	\$1,133,716.09							
	Gross I	tem Adjustme			\$0.00	\$14,349.26	\$14,349.26							
			Gross	Item Pay	\$244,977.95	\$903,087.40	\$1,148,065.35							
	Incenti	ve			\$0.00	\$0.00	\$0.00							
	Disince	entive			\$0.00	\$0.00	\$0.00							
		ted Damages			\$0.00	\$0.00	\$0.00							
	Other C	Contract Adjus	tments		\$0.00	\$0.00	\$0.00							

Revision 4/1/2020 Page 3 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6053030A, Project Item Line Number 0160, Material Set 6053030A96, Material 1009G5DRLS - Agg for Drainage Gr5 Limestone, Acceptance Action Generic 1009G5DRLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 6131010, Project Item Line Number 0190, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 6131010, Project Item Line Number 0190, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 6131012, Project Item Line Number 0200, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6205309, Project Item Line Number 0420, Material Set 620530996, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 6252001, Project Item Line Number 0500, Material Set 625200196, Material 0625PLUTUS - Polyurethane for UnderSealing of PVMT, Acceptance Action Generic 0625PLUTUS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 6252003, Project Item Line Number 0510, Material Set 625200396, Material 0625PLUTUS - Polyurethane for UnderSealing of PVMT, Acceptance Action Generic 0625PLUTUS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100507CPCMLD - PCCP or Masonry 0-3/4" Max LS/DO, Acceptance Action Generic 100507CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 4 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211217-H05	J9I3597	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.80	\$76,208.14	\$60,966.5
		0001	0020	2039907	MISC.TRENCHING FOR PIPE AGGREGATE EDGE DRAIN	100.00	0.00	100.00	CUYD	23.60	\$190.00	\$4,484.00
		0001	0030	2129900	MISC.SHOULDER GRADING	46.00	0.00	46.00	100F	0.00	\$227.95	\$0.00
		0001	0035	2159903	MISC.Modified Shaping Slopes Class III	1,760.00	0.00	1,760.00	LF	0.00	\$10.00	\$0.00
		0001	0040	3030600	FURNISHING ROCK BASE MATERIAL	977.00	0.00	977.00	SQYD	398.90	\$25.00	\$9,972.50
		0001	0050	3030610A	PLACING ROCK BASE	977.00	0.00	977.00	SQYD	398.90	\$10.00	\$3,989.00
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,081.00	0.00	1,081.00	SQYD	258.10	\$12.00	\$3,097.2
		0001	0070	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	9,357.00	0.00	9,357.00	TONS	0.00	\$44.27	\$0.00
		0001	0800	4010151	TYPE A3 SHOULDER	9,827.30	0.00	9,827.30	SQYD	117.33	\$37.51	\$4,401.0
		0001	0090	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	22,548.10	0.00	22,548.10	TONS	49.00	\$78.78	\$3,860.2
		0001	0095	4019901	MISC.NRRA SUPPLEMENTARY TEST SECTIONS	1.00	0.00	1.00	LS	0.00	\$144,283.66	\$0.0
		0001	0120	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	42,848.90	0.00	42,848.90	TONS	0.00	\$93.78	\$0.0
		0001	0124	4031058	INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	0.00	\$40,470.36	\$0.0
		0001	0125	4031059	PAVER-MOUNTED THERMAL PROFILES	1.00	0.00	1.00	LS	0.00	\$4,855.28	\$0.0
		0001	0130	4071005	TACK COAT	12,646.00	0.00	12,646.00	GAL	0.00	\$2.33	\$0.0
		0001	0135	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	73,357.00	0.00	73,357.00	GAL	0.00	\$2.60	\$0.00
		0001	0140	4134000	BITUMINOUS FOG SEAL	14,167.00	0.00	14,167.00	GAL	0.00	\$3.39	\$0.00
		0001	0150	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	345.00	0.00	345.00	SQYD	140.80	\$90.00	\$12,672.0
		0001	0160	6053030A	PIPE AGGREGATE PAVEMENT EDGE DRAIN	4,034.00	0.00	4,034.00	LF	955.70	\$15.00	\$14,335.5
		0001	0170	6054020	OUTLET PIPES AND SPLASH PADS	34.00	0.00	34.00	EA	8.00	\$1,350.00	\$10,800.0
		0001	0180	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	2.00	\$0.00	\$0.0
		0001	0190	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	1,144.00	0.00	1,144.00	SQYD	496.00	\$225.00	\$111,600.0
		0001	0200	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	114.00	0.00	114.00	SQYD	49.80	\$6.00	\$298.8
		0001	0210	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	114.00	0.00	114.00	SQYD	49.80	\$8.00	\$398.4
		0001	0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	4,724.00	0.00	4,724.00	LF	1,866.00	\$10.00	\$18,660.0
		0001	0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	2,100.00	0.00	2,100.00	EA	818.00	\$8.00	\$6,544.0
		0001	0240	6132018	FURNISHING AND PLACING CONCRETE MATERIAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	49.40	0.00	49.40	CUYD	0.00	\$1,650.00	\$0.0
		0001	0250	6132019	REMOVAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	395.60	0.00	395.60	SQYD	0.00	\$115.00	\$0.0
		0001	0260	6134001	DOWEL BAR RETROFIT	10,680.00	0.00	10,680.00	EA	2,382.00	\$90.00	\$214,380.0
		0001	0270	6139903	MISC.TYPE E EXPANSION JOINT	456.00	0.00	456.00	LF	60.00	\$30.00	\$1,800.0
		0001	0280	6161005	CONSTRUCTION SIGNS	4,196.00	0.00	4,196.00	SQFT	1,321.00	\$8.00	\$10,568.0
		0001	0290	6161008	ADVANCED WARNING RAIL SYSTEM	12.00	0.00	12.00	EA	12.00	\$35.00	\$420.0
		0001	0300	6161025	CHANNELIZER (TRIM LINE)	962.00	0.00	962.00	EA	245.00	\$20.00	\$4,900.0
		0001	0310	6161030	TYPE III MOVEABLE BARRICADE	4.00	0.00	4.00	EA	4.00	\$150.00	\$600.0
		0001	0320	6161033	DIRECTIONAL INDICATOR BARRICADE	178.00	0.00	178.00	EA	32.00	\$0.00	\$0.0
		0001	0330	6161040	FLASHING ARROW PANEL	9.00	0.00	9.00	EA	4.00	\$1,000.00	\$4,000.0
		0001	0340	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	4.00	0.00	4.00	EA	2.00	\$3,200.00	\$6,400.0
		0001	0350	6162000A	RETAINED WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$10,000.00	\$10,000.0
		0001	0360	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	0.00	\$0.00	\$0.0
		0001	0370	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	160.00	0.00	160.00	LF	0.00	\$178.29	\$0.0
		0001	0380	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50		\$131,946.9
		0001	0390	6200039	PREFORMED THERMOPLASTIC PAVEMENT MARKING, OFF	4.00	0.00	4.00	EA	0.00	\$1,500.00	\$0.0
			0400	6205301B	RAMP WRONG WAY ARROW TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,200.00	0.00	1,200.00	LF	1,200.00	\$2.00	\$2,400.0
		0001	U-+UU	020000 IB	TENT ORART REMOVABLE MARRING TAPE 4 IN., WHITE	1,200.00	0.00	1,200.00	LF	1,200.00	φ2.00	\$Z,4UU.UI

Page 5 of 13 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211217-H05	J9I3597	0001	0420	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	60.00	0.00	60.00	LF	60.00	\$10.00	\$600.00
		0001	0430	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	151,103.00	0.00	151,103.00	LF	0.00	\$0.22	\$0.00
		0001	0440	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	123,088.00	0.00	123,088.00	LF	0.00	\$0.22	\$0.00
		0001	0450	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,530.00	0.00	7,530.00	LF	0.00	\$1.00	\$0.00
		0001	0460	6207001	PAVEMENT MARKING REMOVAL	4,060.00	0.00	4,060.00	LF	4,060.00	\$2.00	\$8,120.00
		0001	0470	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$16,769.52	\$0.00
		0001	0480	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	49,344.00	0.00	49,344.00	SQYD	0.00	\$2.15	\$0.00
		0001	0490	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	22,967.00	0.00	22,967.00	SQYD	0.00	\$6.20	\$0.00
		0001	0500	6252001	UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	10,022.00	0.00	10,022.00	LB	10,022.00	\$3.85	\$38,584.70
		0001	0510	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	2,274.00	0.00	2,274.00	LB	2,274.00	\$3.85	\$8,754.90
		0001	0520	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,109.70	0.00	2,109.70	STA	0.00	\$24.50	\$0.00
		0010	0530	6061060	MGS GUARDRAIL	8,588.00	0.00	8,588.00	LF	8,388.00	\$32.00	\$268,416.00
		0010	0540	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	10.00	0.00	10.00	EA	8.00	\$3,700.00	\$29,600.00
		0010	0550	6061080	MGS END ANCHOR	18.00	0.00	18.00	EA	16.00	\$1,500.00	\$24,000.00
		0010	0560	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	22.00	0.00	22.00	EA	20.00	\$3,000.00	\$60,000.00
		0070	0570	7034600	CURB BLOCKOUT	611.00	0.00	611.00	LF	305.00	\$125.07	\$38,146.35
	Project J	J9I3597 - To	otal Value	Posted to D	late as of Report Generated Date							\$1,133,716.09
211217-H05 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$1,133,716.09

Revision 4/1/2020 Page 6 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: 1913597

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0190	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	6/16/22	7/1/22	100.00	SQYD	Exit 1A Ramp	0.0		0.2		Exit 1A Ramp. Poured on June 15th.
			6/20/22	6/30/22	24.00	SQYD	WB DL	4.94		5.12		WB DL
			6/21/22	6/30/22	24.00	SQYD	WB DL	5.18		5.342		WB DL
			6/22/22	6/30/22	32.00	SQYD	WB DL	5.363		5.5		WB DL
			6/27/22	6/30/22	70.00	SQYD	WB DL and Exit 4 RT Side	6.185		6.251		WB DL and Exit 4 RT Side
			6/30/22	7/1/22	70.00	SQYD	WB DL and Exit 4 Off Ramp	6.27		6.75		WB DL and Exit 4 Off Ramp
0200	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	6/16/22	7/1/22	10.00	SQYD	Exit 1A Ramp	0.0		0.2		Exit 1A Ramp. Poured on June 15th.
			6/20/22	6/30/22	2.40	SQYD	WB DL	4.94		5.12		WB DL
			6/21/22	6/30/22	2.40	SQYD	WB DL		5.18		5.342	WB DL
			6/22/22	6/30/22	3.20	SQYD	WB DL	5.363		5.5		WB DL
			6/27/22	6/30/22	7.00	SQYD	WB DL and Exit 4 RT Side	6.185		6.251		WB DL and Exit 4 RT Side
			6/30/22	7/1/22	7.00	SQYD	WB DL and Exit 4 Off Ramp	6.27		6.75		WB DL and Exit 4 Off Ramp
0210	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	6/16/22	7/1/22	10.00	SQYD	Exit 1A Ramp	0.0		0.2		Exit 1A Ramp. Poured on June 15th.
			6/20/22	6/30/22	2.40	SQYD	WB DL	4.94		5.12		WB DL
			6/21/22	6/30/22	2.40	SQYD	WB DL	5.18		5.342		WB DL
			6/22/22	6/30/22	3.20	SQYD	WB DL	5.363		5.5		WB DL
			6/27/22	6/30/22	7.00	SQYD	WB DL and Exit 4 RT Side	6.185		6.251		WB DL and Exit 4 RT Side
			6/30/22	7/1/22	7.00	SQYD	WB DL and Exit 4 Off Ramp	6.27		6.75		WB DL and Exit 4 Off Ramp
0220	0 6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	6/16/22	7/1/22	260.00	LF	Exit 1A Ramp	0.0		0.2		Exit 1A Ramp. Poured on June 15th.
			6/20/22	6/30/22	108.00	LF	WB DL	4.94		5.12		WB DL
			6/21/22	6/30/22	108.00	LF	WB DL	5.18		5.342		WB DL
			6/22/22	6/30/22	144.00	LF	WB DL	5.363		5.5		WB DL
			6/27/22	6/30/22	228.00	LF	WB DL and Exit 4 RT Side	6.185		6.251		WB DL and Exit 4 RT Side
			6/30/22	7/1/22	228.00	LF	WB DL and Exit 4 Off Ramp	6.27		6.75		WB DL and Exit 4 Off Ramp
0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	6/16/22	7/1/22	144.00	EA	Exit 1A Ramp.	0.0		0.2		Exit 1A Ramp. Poured on June 15th.
			6/20/22	6/30/22	66.00	EA	WBDL	4.94		5.12		WB DL
			6/21/22	6/30/22	64.00	EA	WB DL	5.18		5.342		WB DL
			6/22/22	6/30/22	91.00	EA	WB DL	5.363		5.5		WB DL
			6/27/22	6/30/22	123.00	EA	WB DL and Exit 4 RT Side	6.185		6.251		WB DL and Exit 4 RT Side
			6/30/22	7/1/22	110.00	EA	WB DL and Exit 4 Off Ramp	6.27		6.75		WB DL and Exit 4 Off Ramp
0260	6134001	DOWEL BAR RETROFIT	6/16/22	7/1/22	150.00	EA	WB DL	4.65		5.127		WB DL
			6/21/22	6/30/22	348.00	EA	WB DL	5.145		5.755		WB DL
			6/28/22	6/30/22	138.00	EA	WB DL	5.78		6.0		WB DL
			6/29/22	6/30/22	150.00	EA	WB DL	6.1		6.635		WB DL
0270	6139903	MISC. PAVEMENT REPAIR	6/22/22	6/30/22	12.00	LF	WB DL	5.363		5.363		WB DL
0300	6161025	CHANNELIZER (TRIM LINE)	6/29/22	6/30/22	20.00	EA	WB DL and Exit 1A	5.0		7.0		Extended Lane drop and had Exit 1A closed and had lar drop at Exit 6
0500	6252001	UNDERSEAL MATL HIGH DENSITY POLYURETHANE	6/22/22	6/30/22	10,022.00	LB	Exit 1A	0.0		0.2		Ramp Exit 1A. There will be more. Waiting for final amount used to put in change order.
0510	6252003	SLAB JACKING MATL HIGH DENSITY POLYURETH	6/22/22	6/30/22	2,274.00	LB	Exit 1A	0.0		0.2		Ramp at Exit 1A. There will be more. Waiting for total amount used to put in change order.
0570	7034600	CURB BLOCKOUT	6/17/22	6/30/22	305.00	LF	East wall on Rt Y	6.0		6.0		East wall on Rt Y. Paying half quantity.

The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post																		
13597	0280	April 14, 2022	156	CONST-7 72x36 18.00 RATE OUR WORK ZONE		2	Route I-155	2.00	18		18.00	36																		
				GO20-2 48x24 8.00 END ROAD WORK		1.5	Route I-155	2.00	8		8.00	1																		
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		0.474	Route I-155	2.00	10		10.00	2																		
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		.972	Route I-155	2.00	10		10.00	2																		
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		2.5	Route I-155	4.00	12		12.00	4																		
		April 26, 2022	540	WO4-1aR 48x48 16.00 MERGE (ARROW SYMBOL)		0.474	I-155 NBL	4.00	16			6																		
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.474	I-155 NBL	4.00	16			6																		
								WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.474	I-155 NBL	4.00	16			6														
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		0.474	I-155 NBL	6.00	16			5																		
			WO4-1aL 48x48 16.00 MERGE (ARROW SYMBOL)		0.474	I-155 NBL	4.00	16																						
				R4-1 36x48 12.00 DO NOT PASS		0.474	I-155 NBL	4.00	12																					
				R2-1 36x48 12.00 SPEED LIMIT XX		0.474	I-155 NBL	4.00	12																					
				CONST-3A 60x48 20.00 FINE SIGN		0.474	I-155 NBL	3.00	20																					
				WO4-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		0.474	I-155 NBL	2.00	16																					
				See Special Sign Details	0.		I-155 NBL																							
		June 10, 2022		c v c			2 625	625	625	. 625	. 625	625			625	R11-2 48x30 10.00 ROAD CLOSED		0.1	Exit 1A Ramp 3	2.00	10									
																						WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.2	Exit 1A Ramp 3	1.00	16			
																		WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.4	Exit 1A Ramp 3	1.00	16							
							MO4-8a 24x18 3.00 END DETOUR		18.5	Route I-55	2.00	3																		
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		29.531	Route 84 / Route U & Ramps	4.00	16																						
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		29.631	Route 84 / Route U & Ramps	2.00	16																					
		R10-6 24x36 6.00 STOP HERE ON RED (45 DEGREE ARROW		30.061	Route 84 / Route U & Ramps	4.00	6																							

Revision 4/1/2020 Page 7 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

ject Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Pos	
597 0280	June 10, 2022	625	R1-2 48 TRI 6.93 YIELD		29.741	Route 84 / Route U & Ramps	2.00	6.93			13.8	
				R2-1 36x48 12.00 SPEED LIMIT XX		29.741	Route 84 / Route U & Ramps	2.00	12			2
			WO3-4 8x48 16.00 BE PREPARED TO STOP		29.814	Route 84 / Route U & Ramps	4.00	16			6	
			WO20-2 48x48 16.00 DETOUR AHEAD		3.2	Exit 1A Ramp 3	1.00	16			1	
			Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		3.2	Exit 1A Ramp 3	253.50	1			253	
			Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		3.2	Exit 1A Ramp 3	64.00	1			6	
			GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		29.741	Route 84 / Route U & Ramps	2.00	6			1	

Revision 4/1/2020 Page 8 of 13



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0060	TYPE 5 AGGREGATE FOR BASE	Material		3	May 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$3,097.20)	
					4	May 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$3,097.20)	
					5	Jun 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$3,097.20)	
					6	Jun 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$3,097.20)	
					7	Jul 1, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$3,097.20)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Price FUEL		3	May 2, 2022	SYSTEM	\$50.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$50.33	
			Price FUEL -	Total				\$50.33	
	0060 -	Total						\$50.33	
	0800	TYPE A3 SHOULDER	Material		4	May 16, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$4,401.05)	
					5	Jun 2, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$4,401.05)	
					6	Jun 16, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$4,401.05)	
					7	Jul 1, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$4,401.05)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0080 -	Total						\$0.00	
	0090	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Price FUEL		4	May 16, 2022	SYSTEM	\$312.35	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$312.35	
			Price FUEL -	Total				\$312.35	
	0090 -	Total						\$312.35	
	0150	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material		3	May 2, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
J9I3597	0150	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material		3	May 2, 2022	SYSTEM	(\$12,672.00)																						
					4	May 16, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																					
					4	May 16, 2022	SYSTEM	(\$12,672.00)																						
					5	Jun 2, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																					
					5	Jun 2, 2022	SYSTEM	(\$12,672.00)																						
					6	Jun 16, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																					
					6	Jun 16, 2022	SYSTEM	(\$12,672.00)																						
					7	Jul 1, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																					
					7	Jul 1, 2022	SYSTEM	(\$12,672.00)																						
				- Total				\$0.00																						
			Material - Tot	tal				\$0.00																						
			Price FUEL		3	May 2, 2022	SYSTEM	\$120.81	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																					
				- Total				\$120.81																						
			Price FUEL -	Total				\$120.81																						
	0150 -							\$120.81																						
	0160	PIPE AGGREGATE PAVEMENT EDGE DRAIN	Material		4	May 16, 2022	SYSTEM	\$14,335.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																					
					4	May 16, 2022	SYSTEM	(\$14,335.50)																						
					5	Jun 2, 2022	SYSTEM	\$14,335.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																					
					5	Jun 2, 2022	SYSTEM	(\$14,335.50)																						
				- Total				\$0.00																						
			Material - Tot	tal				\$0.00																						
	0160 -	Total						\$0.00																						
	0170	OUTLET PIPES AND SPLASH PADS	Material		4	May 16, 2022	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																					
																										4	May 16, 2022	SYSTEM	(\$10,800.00)	
						5	Jun 2, 2022	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																				
					5	Jun 2, 2022	SYSTEM	(\$10,800.00)																						
				- Total				\$0.00																						
			Material - Tot	tal				\$0.00																						
	0170 -	Total						\$0.00																						
	0190	FURN & PLACE CONC MATL FOR FULL DEPTH	-		4	May 16, 2022	SYSTEM	\$19,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																					
					4	May 16, 2022	SYSTEM	(\$19,800.00)																						
					5	Jun 2, 2022	SYSTEM	\$39,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																					



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
7 (0190	FURN & PLACE CONC MATL FOR FULL	Material		5	Jun 2, 2022	SYSTEM	(\$39,600.00)		
		DEPTH		- Total				\$0.00		
L			Material - To	tal				\$0.00		
0	0190 -	Total						\$0.00		
0:	0200	SUBGRADE COMPACTION (6 IN. DEPTH)	Material		4	May 16, 2022	SYSTEM	\$54.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payme Estimate Exception 20 on the current Payment Estimate.	
		(PAVEM			4	May 16, 2022	SYSTEM	(\$54.00)		
					5	Jun 2, 2022	SYSTEM	\$106.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payme Estimate Exception 20 on the current Payment Estimate.	
					5	Jun 2, 2022	SYSTEM	(\$106.80)		
					6	Jun 16, 2022	SYSTEM	\$106.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payme Estimate Exception 12 on the current Payment Estimate.	
					6	Jun 16, 2022	SYSTEM	(\$106.80)		
					7	Jul 1, 2022	SYSTEM	\$298.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Paym Estimate Exception 12 on the current Payment Estimate.	
					7	Jul 1, 2022	SYSTEM	(\$298.80)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
d	0200 -	Total						\$0.00		
02	0230	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		4	May 16, 2022	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payme Estimate Exception 21 on the current Payment Estimate.	
					4	May 16, 2022	SYSTEM	(\$880.00)		
						5	Jun 2, 2022	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Paym Estimate Exception 21 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$1,760.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
0	0230 -	Total						\$0.00		
(0260	DOWEL BAR RETROFIT	Material		4	May 16, 2022	SYSTEM	\$40,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payme Estimate Exception 22 on the current Payment Estimate.	
						4	May 16, 2022	SYSTEM	(\$40,500.00)	
						5	Jun 2, 2022	SYSTEM	\$143,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payme Estimate Exception 22 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$143,640.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
d	0260 -	Total						\$0.00		
(0270) MISC. PAVEMENT REPAIR	Material		5	Jun 2, 2022	SYSTEM	\$720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payme Estimate Exception 25 on the current Payment Estimate.	
					5	Jun 2, 2022	SYSTEM	(\$720.00)		
								60.00		
				- Total				\$0.00		
			Material - To					\$0.00		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0420	TEMPORARY REMOVABLE MARKING TAPE, 24 IN.	Material		6	Jun 16, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$600.00)	
					7	Jul 1, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$600.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0420 -	Total							
	0500	UNDERSEAL MATL HIGH DENSITY	Material		7	Jul 1, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
		POLYURETHANE			7	Jul 1, 2022	SYSTEM	(\$38,584.70)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0500 -	Total						\$0.00	
	0510	SLAB JACKING MATL HIGH DENSITY POLYURETH	Material		7	Jul 1, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$8,754.90)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0510 -	Total						\$0.00	
	0530	MGS GUARDRAIL	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$116,280.48)	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	May 2, 2022	SYSTEM	(\$52,979.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$169,259.98)	
			Construction Construction Stockpile STMI	Stockpile - 1				(\$169,259.98)	
				Total	1	Mar 16, 2022	SYSTEM	\$173,295.75	Payment Estimate Item Adjustment generated Stockpile Transaction
			0	- Total	FRAL Total			\$173,295.75	
	0530	Total	Construction	Зтоскрпе 5	rwii - Total			\$173,295.75 \$4,035.77	
	0540	- Total MGS BRIDGE APP. TRANS SEC (REG/NO CURB)			2	Apr 18, 2022	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$16,880.00)	
			Construction	Stockpile - 1	Total			(\$16,880.00)	
			Construction Stockpile		1	Mar 16, 2022	SYSTEM	\$21,100.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$21,100.00	
			Construction	Stockpile S	ГМI - Total			\$21,100.00	
	0540 -	0540 - Total							
	0550	MGS END ANCHOR	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$5,130.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	May 2, 2022	SYSTEM	(\$8,550.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$13,680.00)	
			Construction	Stockpile - 1				(\$13,680.00)	
			Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$15,390.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$15,390.00	
			Construction	Stockpile S	MI - Total			\$15,390.00	

Jul 6, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0550 -	Total						\$1,710.00	
	0560	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$19,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	May 2, 2022	SYSTEM	(\$19,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$39,000.00)	
			Construction	Stockpile - 1	Γotal			(\$39,000.00)	
			Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$42,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$42,900.00	
			Construction	Stockpile S	TMI - Total			\$42,900.00	
	0560 -	Total						\$3,900.00	
	0570	CURB BLOCKOUT	Material		7	Jul 1, 2022	SYSTEM	\$38,146.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$38,146.35)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0570 -	Total						\$0.00	
J9l3597 -	Total							\$14,349.26	
Overall -	Total							\$14,349.26	