\$185,430.62



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 18, 2022

Progress Estin	nate Number	Contract ID Prime Contractor	211217-H05 Apex Paving Co.	Pay Period Start Pay Period End	July 1, 2022 July 15, 2022	Original Contract Amount Net Change Order Amount Current Contract Amount	\$10,080,771.09 \$0.00 \$10,080,771.09		
Approval Date	proval Date								
July 18, 2022		Generated and Approved (and should be considered Draft) at the Project Office Level by							
July 18, 2022		Review	ved and Approved	(and should be cons	idered Draft) at	the Resident Engineer Level by	bollis1		
July 19, 2022			Revie	ewed and Approved	at the Central C	office Controllers Office Level by	ramses1		
Original Comp	letion Date	Current Comple	tion Date	Actual Completion	Date	% of Current Contract Amou	unt Complete		
July 31, 2023 July 31, 2023						13.09%			

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	January 5, 2022	January 5, 2022	
Letting Date	December 17, 2021	December 17, 2021	
Notice to Proceed Date	March 7, 2022	March 7, 2022	
Open to Traffic Date			
Work Began Date			

Contract Total Pa	ay For Estimate No. 8			
		This Estimate	Previous	To Date
211217-H05				
	Total Posted Items Pay	\$185,430.62	\$1,133,716.09	\$1,319,146.71
	Gross Item Adjustments	\$0.00	\$14,349.26	\$14,349.26
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$1,148,065.35	\$1,333,495.97
Contract Total Pa	ayable This Estimate:	\$185,430,62		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3597	0190	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$225.000	343	\$77,175.00
	0200	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	SQYD	\$6.000	34.3	\$205.80
	0210	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	SQYD	\$8.000	34.3	\$274.40
	0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$10.000	1,416	\$14,160.00
	0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$8.000	843	\$6,744.00
	0260	6134001	DOWEL BAR RETROFIT	EA	\$90.000	540	\$48,600.00
	0570	7034600	CURB BLOCKOUT	LF	\$125.070	306	\$38,271.42
Project J9	<mark>3597 - Tot</mark>	al					\$185,430.62

Contract Adjustments This Estimate

Overall - Total

No Contract Adjustments Exist on Contract

Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3597	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-258.1	\$12.00	(\$3,097.20)
	0060	TYPE 5 AGGREGATE FOR	Material		This adjustment offsets the original system-	258.1	\$12.00	\$3,097.20

Revision 4/1/2020 Page 1 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 18, 2022

Progress Estimate Number
8 Contract ID 211217-H05 Pay Period Start July 1, 2022 Original Contract Amount \$10,080,771.09 Pay Period End July 15, 2022 Original Contract Amount \$0.00 \$0.00 \$10,080,771.09

008 008 018 018 020	TYPE A3 SHOULDER 50 CONCRETE PAVEMENT (9 IN. NON-REINF) 50 CONCRETE PAVEMENT (9 IN. NON-REINF)	Material Material Material	generated Material Payment Estimate Item Adjustment (0001) due to user george2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user george2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	-117.33 117.33	\$37.51 \$37.51	(\$4,401.05 \$4,401.05
008 018 018 020	TYPE A3 SHOULDER 50 CONCRETE PAVEMENT (9 IN. NON-REINF) 50 CONCRETE PAVEMENT (9 IN. NON-REINF)	Material Material	generated Material Payment Estimate Item Adjustment (0002) due to user george2 overridding Payment Estimate Exception 2 on			
018 018 020	50 CONCRETE PAVEMENT (9 IN. NON-REINF) 50 CONCRETE PAVEMENT (9 IN. NON-REINF)	Material	generated Material Payment Estimate Item Adjustment (0002) due to user george2 overridding Payment Estimate Exception 2 on	117.33	\$37.51	\$4,401.05
020	IN. NON-REINF) 50 CONCRETE PAVEMENT (9 IN. NON-REINF)					
020	IN. NON-REINF)	Material		-140.8	\$90.00	(\$12,672.00
020			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user george2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	140.8	\$90.00	\$12,672.00
	OO SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		-84.1	\$6.00	(\$504.60
042	00 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user george2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	84.1	\$6.00	\$504.60
	20 TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		-60	\$10.00	(\$600.00
042	20 TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user george2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	60	\$10.00	\$600.00
050	00 UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	Material		-10,022	\$3.85	(\$38,584.70
050	00 UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	Material	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user george2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	10,022	\$3.85	\$38,584.70
05	10 SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	Material		-2,274	\$3.85	(\$8,754.90
05	10 SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	Material	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Exception 15 on the current Payment Estimate.	2,274	\$3.85	\$8,754.90
057	70 CURB BLOCKOUT	Material		-611	\$125.07	(\$76,417.77
057	70 CURB BLOCKOUT	Material	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user george2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	611	\$125.07	\$76,417.77

Revision 4/1/2020 Page 2 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9I3597	I 155-1(123)	Resurface	155	PEMISCOT	from Rte. 412 to Tenn	nessee State line	
Totals by J	Job Number	s					
J9I3597		Item Pay Item Adjustme		Item Pay	This Estimate \$185,430.62 \$0.00 \$185,430.62	Previous \$1,133,716.09 \$14,349.26 \$1,148,065.35	To Date \$1,319,146.71 \$14,349.26 \$1,333,495.97
	Incenti		0.000		\$0.00	\$0.00	\$0.00
		entive ated Damages Contract Adjus	4		\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 6053030A, Project Item Line Number 0160, Material Set 6053030A96, Material 1009G5DRLS - Agg for Drainage Gr5 Limestone, Acceptance Action Generic 1009G5DRLS is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 6131010, Project Item Line Number 0190, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6131010, Project Item Line Number 0190, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6131012, Project Item Line Number 0200, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6205309, Project Item Line Number 0420, Material Set 620530996, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6252001, Project Item Line Number 0500, Material Set 625200196, Material 0625PLUTUS - Polyurethane for UnderSealing of PVMT, Acceptance Action Generic 0625PLUTUS is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 6252003, Project Item Line Number 0510, Material Set 625200396, Material 0625PLUTUS - Polyurethane for UnderSealing of PVMT, Acceptance Action Generic 0625PLUTUS is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100507CPCMLD - PCCP or Masonry 0-3/4" Max LS/DO, Acceptance Action Generic 100507CPCMLD is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	george2	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	george2	Overridden

Revision 4/1/2020 Page 4 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract lm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
11217-H05	J9I3597	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.80	\$76,208.14	\$60,966.
		0001	0020	2039907	MISC.TRENCHING FOR PIPE AGGREGATE EDGE DRAIN	100.00	0.00	100.00	CUYD	23.60	\$190.00	\$4,484.
		0001	0030	2129900	MISC.SHOULDER GRADING	46.00	0.00	46.00	100F	0.00	\$227.95	\$0.
		0001	0035	2159903	MISC.Modified Shaping Slopes Class III	1,760.00	0.00	1,760.00	LF	0.00	\$10.00	\$0.
		0001	0040	3030600	FURNISHING ROCK BASE MATERIAL	977.00	0.00	977.00	SQYD	398.90	\$25.00	\$9,972.
		0001	0050	3030610A	PLACING ROCK BASE	977.00	0.00	977.00	SQYD	398.90	\$10.00	\$3,989.
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,081.00	0.00	1,081.00	SQYD	258.10	\$12.00	\$3,097
		0001	0070	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	9,357.00	0.00	9,357.00	TONS	0.00	\$44.27	\$0
		0001	0800	4010151	TYPE A3 SHOULDER	9,827.30	0.00	9,827.30	SQYD	117.33	\$37.51	\$4,401
		0001	0090	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	22,548.10	0.00	22,548.10	TONS	49.00	\$78.78	\$3,860
		0001	0095	4019901	MISC.NRRA SUPPLEMENTARY TEST SECTIONS	1.00	0.00	1.00	LS	0.00	\$144,283.66	\$0
		0001	0120	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	42,848.90	0.00	42,848.90	TONS	0.00	\$93.78	\$0
		0001	0124	4031058	INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	0.00	\$40,470.36	\$0
		0001	0125	4031059	PAVER-MOUNTED THERMAL PROFILES	1.00	0.00	1.00	LS	0.00	\$4,855.28	\$0
		0001	0130	4071005	TACK COAT	12,646.00	0.00	12,646.00	GAL	0.00	\$2.33	\$0
		0001	0135	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	73,357.00	0.00	73,357.00	GAL	0.00	\$2.60	\$0
		0001	0140	4134000	BITUMINOUS FOG SEAL	14,167.00	0.00	14,167.00	GAL	0.00	\$3.39	\$0
		0001	0150	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	345.00	0.00	345.00	SQYD	140.80	\$90.00	\$12,672
		0001	0160	6053030A	PIPE AGGREGATE PAVEMENT EDGE DRAIN	4,034.00	0.00	4,034.00	LF	955.70	\$15.00	\$14,335
		0001	0170	6054020	OUTLET PIPES AND SPLASH PADS	34.00	0.00	34.00	EA	8.00	\$1,350.00	\$10,80
		0001	0180	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	2.00	\$0.00	\$
		0001	0190	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	1,144.00	0.00	1,144.00	SQYD	839.00	\$225.00	\$188,77
		0001	0200	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	114.00	0.00	114.00	SQYD	84.10	\$6.00	\$50-
		0001	0210	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	114.00	0.00	114.00	SQYD	84.10	\$8.00	\$67
		0001	0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	4,724.00	0.00	4,724.00	LF	3,282.00	\$10.00	\$32,82
		0001	0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	2,100.00	0.00	2,100.00	EA	1,661.00	\$8.00	\$13,28
		0001	0240	6132018	FURNISHING AND PLACING CONCRETE MATERIAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	49.40	0.00	49.40	CUYD	0.00	\$1,650.00	\$
		0001	0250	6132019	REMOVAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	395.60	0.00	395.60	SQYD	0.00	\$115.00	\$
		0001	0260	6134001	DOWEL BAR RETROFIT	10,680.00	0.00	10,680.00	EA	2,922.00	\$90.00	\$262,98
		0001	0270	6139903	MISC.TYPE E EXPANSION JOINT	456.00	0.00	456.00	LF	60.00	\$30.00	\$1,80
		0001	0280	6161005	CONSTRUCTION SIGNS	4,196.00	0.00	4,196.00	SQFT	1,321.00	\$8.00	\$10,56
		0001	0290	6161008	ADVANCED WARNING RAIL SYSTEM	12.00	0.00	12.00	EA	12.00	\$35.00	\$42
		0001	0300	6161025	CHANNELIZER (TRIM LINE)	962.00	0.00	962.00	EA	245.00	\$20.00	\$4,90
		0001	0310	6161030	TYPE III MOVEABLE BARRICADE	4.00	0.00	4.00	EA	4.00	\$150.00	\$60
		0001	0320	6161033	DIRECTIONAL INDICATOR BARRICADE	178.00	0.00	178.00	EA	32.00	\$0.00	\$
		0001	0330	6161040	FLASHING ARROW PANEL	9.00	0.00	9.00	EA	4.00	\$1,000.00	\$4,00
		0001	0340	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	2.00	\$3,200.00	\$6,40
		0001	0350	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$10,000.00	\$10,00
		0001	0360	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	0.00	\$0.00	\$
		0001	0370	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	160.00	0.00	160.00	LF	0.00	\$178.29	\$
		0001	0380	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$263,893.91	\$131,94
		0001	0390	6200039	PREFORMED THERMOPLASTIC PAVEMENT MARKING, OFF	4.00	0.00	4.00	EA	0.00	\$1,500.00	\$
		0001	0400	6205301B	RAMP WRONG WAY ARROW TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,200.00	0.00	1,200.00	LF	1,200.00	\$2.00	\$2,40
		0001	0410	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,000.00	0.00	2,000.00	LF	2,000.00	\$2.00	\$4,00

Revision 4/1/2020 Page 5 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211217-H05	J9I3597	0001	0420	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	60.00	0.00	60.00	LF	60.00	\$10.00	\$600.00
		0001	0430	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	151,103.00	0.00	151,103.00	LF	0.00	\$0.22	\$0.00
		0001	0440	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	123,088.00	0.00	123,088.00	LF	0.00	\$0.22	\$0.00
		0001	0450	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,530.00	0.00	7,530.00	LF	0.00	\$1.00	\$0.00
		0001	0460	6207001	PAVEMENT MARKING REMOVAL	4,060.00	0.00	4,060.00	LF	4,060.00	\$2.00	\$8,120.00
		0001	0470	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$16,769.52	\$0.00
		0001	0480	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	49,344.00	0.00	49,344.00	SQYD	0.00	\$2.15	\$0.00
		0001	0490	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	22,967.00	0.00	22,967.00	SQYD	0.00	\$6.20	\$0.00
		0001	0500	6252001	UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	10,022.00	0.00	10,022.00	LB	10,022.00	\$3.85	\$38,584.70
		0001	0510	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	2,274.00	0.00	2,274.00	LB	2,274.00	\$3.85	\$8,754.90
		0001	0520	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,109.70	0.00	2,109.70	STA	0.00	\$24.50	\$0.00
		0010	0530	6061060	MGS GUARDRAIL	8,588.00	0.00	8,588.00	LF	8,388.00	\$32.00	\$268,416.00
		0010	0540	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	10.00	0.00	10.00	EA	8.00	\$3,700.00	\$29,600.00
		0010	0550	6061080	MGS END ANCHOR	18.00	0.00	18.00	EA	16.00	\$1,500.00	\$24,000.00
		0010	0560	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	22.00	0.00	22.00	EA	20.00	\$3,000.00	\$60,000.00
		0070	0570	7034600	CURB BLOCKOUT	611.00	0.00	611.00	LF	611.00	\$125.07	\$76,417.77
	Project J	1913597 - To	tal Value	Posted to D	late as of Report Generated Date							\$1,319,146.71
211217-H05 Ove	erall - Tota	l Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$1,319,146.71

Revision 4/1/2020 Page 6 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9I3597

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0190	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	7/5/22	7/8/22	51.00	SQYD	NB DL	6.787		6.965		NB DL
			7/7/22	7/8/22	61.00	SQYD	NB DL	7.022		7.219		NB DL
			7/11/22	7/13/22	48.00	SQYD	NB DL	7.314		7.684		NB DL
			7/13/22	7/18/22	44.00	SQYD	Exit 17B. NBI55 Off Ramp to NB I155	.186		10.512		Exit 17B. NBI55 Off Ramp to NB I155
			7/15/22	7/18/22	139.00	SQYD	Exit Ramp 17B NB I55 to NB I155. Also NB DL LM 7.726 to 8.135	.186		10.512		Exit Ramp 17B NB I55 to NB I155. Also NB DL LM 7.726 to 8.135
0200	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	7/5/22	7/8/22	5.10	SQYD	NB DL	6.787		6.965		NB DL
			7/7/22	7/8/22	6.10	SQYD	NB DL	7.022		7.219		NB DL
			7/11/22	7/13/22	4.80	SQYD	NB DL	7.314		7.684		NB DL
			7/13/22	7/18/22	4.40	SQYD	Exit 17B. NBI55 Off Ramp to NB I155	.186		10.512		Exit 17B. NBI55 Off Ramp to NB I155
			7/15/22	7/18/22	13.90	SQYD	Exit Ramp 17B NB I55 to NB I155. Also NB DL LM 7.726 to 8.135	.186		10.512		Exit Ramp 17B NB I55 to NB I155. Also NB DL LM 7.726 to 8.135
0210	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	7/5/22	7/8/22	5.10	SQYD	NBDL	6.787		6.965		NB DL
			7/7/22	7/8/22	6.10	SQYD	NB DL	7.022		7.219		NB DL
			7/11/22	7/13/22	4.80	SQYD	NB DL	7.314		7.684		NB DL
			7/13/22	7/18/22	4.40	SQYD	Exit 17B. NBI55 Off Ramp to NB I155	.186		10.512		Exit 17B. NBI55 Off Ramp to NB I155
			7/15/22	7/18/22	13.90	SQYD	Exit Ramp 17B NB I55 to NB I155. Also NB DL LM 7.726 to 8.135	.186		10.512		Exit Ramp 17B NB I55 to NB I155. Also NB DL LM 7.726 to 8.135
0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	7/5/22	7/8/22	186.00	LF	NB DL	6.787		6.965		NB DL
			7/7/22	7/8/22	188.00	LF	NB DL	7.022		7.219		NB DL
			7/11/22	7/13/22	216.00	LF	NB DL	7.314		7.684		NB DL
			7/13/22	7/18/22	204.00	LF	Exit 17B. NBI55 Off Ramp to NB I155	.186		10.512		Exit 17B. NBI55 Off Ramp to NB I155
			7/15/22	7/18/22	622.00	LF	Exit Ramp 17B NB I55 to NB I155. Also NB DL LM 7.726 to 8.135	.186		10.512		Exit Ramp 17B NB I55 to NB I155. Also NB DL LM 7.726 to 8.135
0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	7/5/22	7/8/22	113.00	EA	NB DL	6.787		6.965		NB DL
			7/7/22	7/8/22	111.00	EA	NB DL	7.022		7.219		NB DL
			7/11/22	7/13/22	142.00	EA	NB DL	7.314		7.684		NB DL
			7/13/22	7/18/22	120.00	EA	Exit 17B. NBI55 Off Ramp to NB I155	.186		10.512		Exit 17B. NBI55 Off Ramp to NB I155
			7/15/22	7/18/22	357.00	EA	Exit Ramp 17B NB I55 to NB I155. Also NB DL LM 7.726 to 8.135	.186		10.512		Exit Ramp 17B NB I55 to NB I155. Also NB DL LM 7.726 to 8.135
0260	6134001	DOWEL BAR RETROFIT	7/6/22	7/8/22	144.00	EA	NB DL	6.44		7.17		NB DL
			7/8/22	7/13/22	174.00	EA	NB DL	7.18		7.522		NB DL
			7/12/22	7/13/22	222.00	EA	NB DL	7.532		8.019		NB DL
0570	7034600	CURB BLOCKOUT	7/6/22	7/8/22	306.00	LF	Exit 6. West Wall of Y overpass	6.0		6.1		West wall of Y overpass. Paying the remainder.

The information below this line are details for Construction Signs (if applicable).

oject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Pos		
597	0280	April 14, 2022	156	CONST-7 72x36 18.00 RATE OUR WORK ZONE		2	Route I-155	2.00	18		18.00	3		
				GO20-2 48x24 8.00 END ROAD WORK		1.5	Route I-155	2.00	8		8.00	1		
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		0.474	Route I-155	2.00	10		10.00	-		
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		.972	Route I-155	2.00	10		10.00	:		
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		2.5	Route I-155	4.00	12		12.00			
		April 26, 2022	540	WO4-1aR 48x48 16.00 MERGE (ARROW SYMBOL)		0.474	I-155 NBL	4.00	16					
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.474	I-155 NBL	4.00	16					
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.474	I-155 NBL	4.00	16					
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		0.474	I-155 NBL	6.00	16			!		
				WO4-1aL 48x48 16.00 MERGE (ARROW SYMBOL)		0.474	I-155 NBL	4.00	16					
				R4-1 36x48 12.00 DO NOT PASS		0.474	I-155 NBL	4.00	12					
				R2-1 36x48 12.00 SPEED LIMIT XX		0.474	I-155 NBL	4.00	12			2		
				CONST-3A 60x48 20.00 FINE SIGN		0.474	I-155 NBL	3.00	20					
				WO4-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		0.474	I-155 NBL	2.00	16					
				See Special Sign Details	0.		I-155 NBL							
		June 10, 2022	625	R11-2 48x30 10.00 ROAD CLOSED		0.1	Exit 1A Ramp 3	2.00	10			1		
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.2	Exit 1A Ramp 3	1.00	16					
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.4	Exit 1A Ramp 3	1.00	16					
				MO4-8a 24x18 3.00 END DETOUR		18.5	Route I-55	2.00	3					
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		29.531	Route 84 / Route U & Ramps	4.00	16			6		
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		29.631	Route 84 / Route U & Ramps	2.00	16			;		
				R10-6 24x36 6.00 STOP HERE ON RED (45 DEGREE ARROW		30.061	Route 84 / Route U & Ramps	4.00	6			:		
				R1-2 48 TRI 6.93 YIELD		29.741	Route 84 / Route U & Ramps	2.00	6.93			13.		
				R2-1 36x48 12.00 SPEED LIMIT XX		29.741	Route 84 / Route U & Ramps	2.00	12			:		
				WO3-4 8x48 16.00 BE PREPARED TO STOP		29.814	Route 84 / Route U & Ramps	4.00	16			6		
						WO20-2 48x48 16.00 DETOUR AHEAD		3.2	Exit 1A Ramp 3	1.00	16			
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		3.2	Exit 1A Ramp 3	253.50	1			253		
				Variable ??x?? 1.00 SPECIAL SIGN		3.2	Exit 1A Ramp 3	64.00	1			6		

Revision 4/1/2020 Page 7 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

e information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J913597	0280	June 10, 2022	625	BY QUANTITY OF SQUARE FEET								
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		29.741	Route 84 / Route U & Ramps	2.00	6			12
	0280 - Total											

Revision 4/1/2020 Page 8 of 13



	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks		
			Type	Adjustment Type	Number	Date	Ву				
J9I3597	0060	TYPE 5 AGGREGATE FOR BASE	Material		3	May 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					3	May 2, 2022	SYSTEM	(\$3,097.20)			
					4	May 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					4	May 16, 2022	SYSTEM	(\$3,097.20)			
					5	Jun 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					5	Jun 2, 2022	SYSTEM	(\$3,097.20)			
					6	Jun 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					6	Jun 16, 2022	SYSTEM	(\$3,097.20)			
					7	Jul 1, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					7	Jul 1, 2022	SYSTEM	(\$3,097.20)			
					8	Jul 18, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user george2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
							8	Jul 18, 2022	SYSTEM	(\$3,097.20)	
				- Total				\$0.00			
			Material - To	tal				\$0.00			
			Price FUEL		3	May 2, 2022	SYSTEM	\$50.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total				\$50.33			
			Price FUEL -	· Total				\$50.33			
	0060 -							\$50.33			
	0800	TYPE A3 SHOULDER			4	May 16,	CVCTEM				
			Material		4	2022	STOTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
			Material		4	2022 May 16, 2022	SYSTEM	\$4,401.05 (\$4,401.05)	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment		
			Material			2022 May 16,			Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment		
			Material		4	2022 May 16, 2022 Jun 2,	SYSTEM	(\$4,401.05)	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment		
			Material		5	2022 May 16, 2022 Jun 2, 2022 Jun 2,	SYSTEM SYSTEM	(\$4,401.05) \$4,401.05	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment		
			Material		5	May 16, 2022 Jun 2, 2022 Jun 2, 2022 Jun 16,	SYSTEM SYSTEM SYSTEM	(\$4,401.05) \$4,401.05 (\$4,401.05)	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment		
			Material		4 5 5	2022 May 16, 2022 Jun 2, 2022 Jun 2, 2022 Jun 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,401.05) \$4,401.05 (\$4,401.05) \$4,401.05	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment		
			Material		45566	2022 May 16, 2022 Jun 2, 2022 Jun 16, 2022 Jun 16, 2022 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,401.05) \$4,401.05 (\$4,401.05) \$4,401.05	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment		
			Material		4 5 5 6 6 7 7	2022 May 16, 2022 Jun 2, 2022 Jun 16, 2022 Jun 16, 2022 Jul 1, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,401.05) \$4,401.05 (\$4,401.05) \$4,401.05 (\$4,401.05)	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment		
			Material		4 5 5 6 6 7 7 7	2022 May 16, 2022 Jun 2, 2022 Jun 16, 2022 Jun 16, 2022 Jul 1, 2022 Jul 1, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,401.05) \$4,401.05 (\$4,401.05) \$4,401.05 (\$4,401.05) \$4,401.05	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.		
			Material	- Total	4 5 5 6 6 7 7 8 8	2022 May 16, 2022 Jun 2, 2022 Jun 16, 2022 Jun 16, 2022 Jul 1, 2022 Jul 1, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,401.05) \$4,401.05 (\$4,401.05) \$4,401.05 (\$4,401.05) \$4,401.05 (\$4,401.05)	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.		



1909	ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
Price FUEL Total	97	0080 -	Total						\$0.00										
Price USA 1531-258 15		0090	MIXTURE	Price FUEL		4		SYSTEM	·	Reference Item Price Adjustment Index Adjustment Type applied is FUEL									
COUNTRIEST Material Section			()																
Section				Price FUEL -	Total														
PAVEMENT 6		0090 -	Total						\$312.35										
2022 4 May 16, SYSTEM \$12,672.00 This adjustment offsets the original system-generated Material Payment Estimate Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment offsets the original system-generated Material Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Estimate Ibm. Adjustment (0004) due to user woodskt overridding Payment Ibm. Adjustment (0004) due to user woodskt overridding Payment Ibm. Adjustment (0004) due to user woodskt overridding Payment Ibm. Adjustment Ibm.		0150	PAVEMENT (9	Material		3	May 2, 2022	SYSTEM	\$12,672.00	Estimate Item Adjustment (0004) due to user woodsk1 overridding Payme									
2022 SYSTEM \$12,672.00						3		SYSTEM	(\$12,672.00)										
2022 SYSTEM \$12,672.00 This adjustment offsets the original system-generated Material Payment Estimate Leading Designation Payment Leading Designation						4		SYSTEM	\$12,672.00	Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment									
2022 SYSTEM S12,672.00						4		SYSTEM	(\$12,672.00)										
2022 6 Jun 16, SYSTEM \$12,672.00 This adjustment offsets the original system-generated Material Payment Estimate lem Adjustment (0003) due to user woodsk1 overridding Payment Estimate lem Adjustment (0003) due to user woodsk1 overridding Payment Estimate lem Adjustment (0003) due to user woodsk1 overridding Payment Estimate lem Adjustment (0003) due to user woodsk1 overridding Payment Estimate lem Adjustment (0003) due to user woodsk1 overridding Payment Estimate lem Adjustment (0003) due to user woodsk1 overridding Payment Estimate lem Adjustment (0003) due to user woodsk1 overridding Payment Estimate lem Adjustment (0003) due to user woodsk1 overridding Payment Estimate lem Adjustment (0003) due to user georgac overridding Payment Estimate lem Adjustment (0003) due to user georgac overridding Payment Estimate lem Adjustment (0003) due to user georgac overridding Payment Estimate lem Adjustment (0003) due to user georgac overridding Payment Estimate lem Adjustment (0003) due to user georgac overridding Payment Estimate lem Adjustment (0003) due to user georgac overridding Payment Estimate lem Adjustment Index Adjustment Type applied is FUEL Total						5		SYSTEM	\$12,672.00	Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment									
2022 Stimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Payment Estimate Exception 5 on the current Payment Estimate Payment Estimate Exception 5 on the current Payment Estimate Payment Pay						5		SYSTEM	(\$12,672.00)										
2022 7						6		SYSTEM	\$12,672.00	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment									
2022						6		SYSTEM	(\$12,672.00)										
2022 8							7		SYSTEM	\$12,672.00	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment								
2022 System Estimate lem Adjustment (0003) due to user george2 overridding Payment																7		SYSTEM	(\$12,672.00)
Naterial - Total \$0.00							8		SYSTEM	\$12,672.00	Estimate Item Adjustment (0003) due to user george2 overridding Payment								
Material - Total S0.00						8		SYSTEM	(\$12,672.00)										
Price FUEL 3 May 2, 2022 SYSTEM \$120.81 Reference Item Price Adjustment Index Adjustment Type applied is FUEL					- Total				\$0.00										
Price FUEL - Total \$120.81					tal				\$0.00										
Price FUEL - Total						3		SYSTEM	\$120.81	Reference Item Price Adjustment Index Adjustment Type applied is FUEL									
D150 - Total					- Total				\$120.81										
D160				Price FUEL -	· Total				\$120.81										
AGGREGATE PAVEMENT EDGE DRAIN 4 May 16, SYSTEM (\$14,335.50) 5 Jun 2, 2022 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 1 Total 1 May 16, SYSTEM (\$14,335.50) 5 Jun 2, 2022 SYSTEM (\$14,335.50) 1 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 1 So.00 1 OUTLET PIPES AND SPLASH PADS 1 Material 4 May 16, SYSTEM (\$10,800.00) 4 May 16, 2022 SYSTEM (\$10,800.00) 1 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		0150 -	Total						\$120.81										
4		0160	AGGREGATE PAVEMENT	Material		4		SYSTEM	\$14,335.50	Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment									
Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 5 Jun 2, 2022 - Total S0.00 Material - Total \$0.00 OUTLET PIPES AND SPLASH PADS AND SPLASH PADS 4 May 16, 2022 4 May 16, SYSTEM (\$10,800.00) Way 16, SYSTEM (\$10,800.00) Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.			EDGE DRAIN		N	1			4	May 16, 2022	SYSTEM	(\$14,335.50)							
Comparison of the content of the c							5		SYSTEM	\$14,335.50	Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment								
Material - Total S0.00 OUTLET PIPES AND SPLASH PADS Material 4 May 16, 2022 SYSTEM \$10,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.						5		SYSTEM	(\$14,335.50)										
OUTLET PIPES AND SPLASH PADS OUTLET PIPES AND SPLASH PADS Material 4 May 16, 2022 SYSTEM \$10,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.				- Total					\$0.00										
OUTLET PIPES AND SPLASH PADS Material 4 May 16, 2022 \$10,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Paymen Estimate Exception 13 on the current Payment Estimate.				Material - To	tal				\$0.00										
AND SPLASH PADS 2022 Estimate Item Adjustment (0006) due to user woodsk1 overridding Paymen Estimate Exception 13 on the current Payment Estimate. 4 May 16, 2022 (\$10,800.00)		0160 -	Total						\$0.00										
2022		0170	AND SPLASH	Material		4		SYSTEM	\$10,800.00	Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment									
F I O OVOTEN AND OD O THE WAY OF THE STATE O						4	May 16, 2022	SYSTEM	(\$10,800.00)										
						5	Jun 2, 2022	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J9I3597	0170	OUTLET PIPES AND SPLASH	Material						Estimate Exception 13 on the current Payment Estimate.	
		PADS			5	Jun 2, 2022	SYSTEM	(\$10,800.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0170 -	Total						\$0.00		
	0190	FURN & PLACE CONC MATL FOR FULL	Material		4	May 16, 2022	SYSTEM	\$19,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
		DEPTH			4	May 16, 2022	SYSTEM	(\$19,800.00)		
					5	Jun 2, 2022	SYSTEM	\$39,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					5	Jun 2, 2022	SYSTEM	(\$39,600.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0190 -	Total						\$0.00		
	0200	SUBGRADE COMPACTION (6 IN. DEPTH)	Material		4	May 16, 2022	SYSTEM	\$54.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
		(PAVEM			4	May 16, 2022	SYSTEM	(\$54.00)		
					5	Jun 2, 2022	SYSTEM	\$106.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					5	Jun 2, 2022	SYSTEM	(\$106.80)		
					6	Jun 16, 2022	SYSTEM	\$106.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					6	Jun 16, 2022	SYSTEM	(\$106.80)		
					7	Jul 1, 2022	SYSTEM	\$298.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					7	Jul 1, 2022	SYSTEM	(\$298.80)		
					8	Jul 18, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user george2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					8	Jul 18, 2022	SYSTEM	(\$504.60)		
				- Total				\$0.00		
			Material - To	Material - Total				\$0.00		
	0200 -	Total						\$0.00		
	0230	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		4	May 16, 2022	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
		I GNII UNN			4	May 16, 2022	SYSTEM	(\$880.00)		
						5	Jun 2, 2022	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$1,760.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0230 -	Total						\$0.00		
	0260	DOWEL BAR RETROFIT	Material		4	May 16, 2022	SYSTEM	\$40,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
Line	Dosonption	Type	Adjustment Type	Number	Date	By	Amount	Rollano	
0260	DOWEL BAR RETROFIT	Material		4	May 16, 2022	SYSTEM	(\$40,500.00)		
				5	Jun 2, 2022	SYSTEM	\$143,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payme Estimate Exception 22 on the current Payment Estimate.	
				5	Jun 2, 2022	SYSTEM	(\$143,640.00)		
			- Total				\$0.00		
		Material - To	tal				\$0.00		
0260	0260 - Total						\$0.00		
0270	MISC. PAVEMENT REPAIR	Material		5	Jun 2, 2022	SYSTEM	\$720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payme Estimate Exception 25 on the current Payment Estimate.	
				5	Jun 2, 2022	SYSTEM	(\$720.00)		
			- Total				\$0.00		
		Material - To	tal				\$0.00		
0 <u>270</u>	- Total						\$0.00		
0420	TEMPORARY REMOVABLE MARKING TAPE,	Material		6	Jun 16, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payme Estimate Exception 13 on the current Payment Estimate.	
	24 IN.			6	Jun 16, 2022	SYSTEM	(\$600.00)		
				7	Jul 1, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payme Estimate Exception 13 on the current Payment Estimate.	
					7	Jul 1, 2022	SYSTEM	(\$600.00)	
					8	Jul 18, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user george2 overridding Payme Estimate Exception 13 on the current Payment Estimate.
				8	Jul 18, 2022	SYSTEM	(\$600.00)		
			- Total				\$0.00		
		Material - To	Material - Total				\$0.00		
0420	- Total						\$0.00		
0500	MATL HIGH DENSITY	Material		7	Jul 1, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Paym Estimate Exception 14 on the current Payment Estimate.	
	POLYURETHANI		-		7	Jul 1,	SYSTEM	(000 504 70)	
					2022		(\$38,584.70)		
				8	Jul 18, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user george2 overridding Payme Estimate Exception 14 on the current Payment Estimate.	
				8	Jul 18,		\$38,584.70 (\$38,584.70)	Estimate Item Adjustment (0006) due to user george2 overridding Payme	
			- Total		Jul 18, 2022 Jul 18,	SYSTEM	\$38,584.70 (\$38,584.70) \$0.00	Estimate Item Adjustment (0006) due to user george2 overridding Payme	
		Material - To			Jul 18, 2022 Jul 18,	SYSTEM	\$38,584.70 (\$38,584.70)	Estimate Item Adjustment (0006) due to user george2 overridding Payme	
0500	- Total	Material - To			Jul 18, 2022 Jul 18,	SYSTEM	\$38,584.70 (\$38,584.70) \$0.00	Estimate Item Adjustment (0006) due to user george2 overridding Payme	
0500	SLAB JACKING MATL HIGH DENSITY				Jul 18, 2022 Jul 18,	SYSTEM	\$38,584.70 (\$38,584.70) \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user george2 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment	
	SLAB JACKING MATL HIGH			8	Jul 18, 2022 Jul 18, 2022 Jul 1,	SYSTEM	\$38,584.70 (\$38,584.70) \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user george2 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment	
	SLAB JACKING MATL HIGH DENSITY			7	Jul 18, 2022 Jul 18, 2022 Jul 11, 2022 Jul 1,	SYSTEM SYSTEM SYSTEM	\$38,584.70 (\$38,584.70) \$0.00 \$0.00 \$0.00 \$8,754.90	Estimate Item Adjustment (0006) due to user george2 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payme Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment	
	SLAB JACKING MATL HIGH DENSITY			7	Jul 18, 2022 Jul 18, 2022 Jul 1, 2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022	SYSTEM SYSTEM SYSTEM	\$38,584.70 (\$38,584.70) \$0.00 \$0.00 \$0.00 \$8,754.90	Estimate Item Adjustment (0006) due to user george2 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment	
	SLAB JACKING MATL HIGH DENSITY			7 7 8	Jul 18, 2022 Jul 18, 2022 Jul 1, 2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2012	SYSTEM SYSTEM SYSTEM SYSTEM	\$38,584.70 (\$38,584.70) \$0.00 \$0.00 \$8,754.90 (\$8,754.90) \$8,754.90	Estimate Item Adjustment (0006) due to user george2 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payme Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment	
	SLAB JACKING MATL HIGH DENSITY		tal - Total	7 7 8	Jul 18, 2022 Jul 18, 2022 Jul 1, 2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2012	SYSTEM SYSTEM SYSTEM SYSTEM	\$38,584.70 (\$38,584.70) \$0.00 \$0.00 \$8,754.90 (\$8,754.90) \$8,754.90	Estimate Item Adjustment (0006) due to user george2 overridding Payme Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payme Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment	



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
597	0530	MGS GUARDRAIL	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$116,280.48)	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	May 2, 2022	SYSTEM	(\$52,979.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$169,259.98)	
			Construction	Stockpile - 1	Total			(\$169,259.98)	
			Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$173,295.75	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$173,295.75	
			Construction	Stockpile S	ГМI - Total			\$173,295.75	
	0530 -	Total						\$4,035.77	
	0540	MGS BRIDGE APP. TRANS SEC (REG/NO	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$16,880.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		CURB)		- Total				(\$16,880.00)	
			Construction	Stockpile - 1	Total			(\$16,880.00)	
			Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$21,100.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$21,100.00	
			Construction	Stockpile S	ΓMI - Total			\$21,100.00	
	0540 -	Total						\$4,220.00	
	0550	MGS END ANCHOR	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$5,130.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					3	May 2, 2022	SYSTEM	(\$8,550.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$13,680.00)	
			Construction	Stockpile - 1	Total			(\$13,680.00)	
			Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$15,390.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$15,390.00	
			Construction	Stockpile S	ΓMI - Total			\$15,390.00	
	0550 -							\$1,710.00	
	0560	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$19,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)			3	May 2, 2022	SYSTEM	(\$19,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$39,000.00)	
			Construction	Stockpile - 1	Total			(\$39,000.00)	
			Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$42,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$42,900.00	
			Construction	Stockpile S	MI - Total			\$42,900.00	
	0560 -							\$3,900.00	
	0570	CURB BLOCKOUT	Material		7	Jul 1, 2022	SYSTEM	\$38,146.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$38,146.35)	
					8	Jul 18, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user george2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$76,417.77)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0570 -	570 - Total							
597 -	Total							\$14,349.26	
erall -	Total							\$14,349.26	