

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 16, 2022

Progress Estimate 3	Number	Contract ID Prime Contract			Pay Period Start Pay Period End	May 2, 2 May 15,		Original Contract Amount Net Change Order Amount Current Contract Amount	\$555,000.00 \$0.00 \$555,000.00	
Approval Date									By User	
May 17, 2022	ay 17, 2022 Generated and Approved (and should be considered Draft) at the Project Office Le									
May 17, 2022		R	eviewed and Appro	oved (and	should be consider	ed Draft)	at the	Resident Engineer Level by	washas	
May 18, 2022				Reviewed and Approved at the Central Office Controllers Office Leve						
Original Completio	n Date	Current Con	pletion Date	Actu	al Completion Da	te	%	of Current Contract Amount	t Complete	
August 1, 2022	2	August	1, 2022					70.29%		
	Contract	Informational Date	es		Milesto					
Date Description	Original (Completion Date	Current Complet	ion Date	No Milestones Ex	ist for Co	ontract			
Acceptance Date										
Awarded Date	February	2, 2022	February 2, 2022							
Letting Date	January 2	21, 2022 January 21, 2022								
Notice to Proceed Date	March 7	2022	March 7, 2022							

Contract Total Pay	y For Estimate No. 3			
		This Estimate	Previous	To Date
220121-F04				
	Total Posted Items Pay	\$240,850.00	\$149,280.00	\$390,130.00
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	,		\$149,280.00	\$390,130.00
Contract Total Pay	yable This Estimate:	\$240,850.00		

Items Paid This Estimate Period

Open to Traffic Date

Work Began Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6M3414	0110	6169901	MISC.Temporary Traffic Control	LS	\$120,000.000	0.75	\$90,000.00
	0120	6169901	MISC.Traffic Signal Maintenance and Programming	LS	\$14,700.000	0.5	\$7,350.00
	0130	6169902	MISC.NTCIP Compliant Changeable Message Sign (Contractor Furnished and Retain)	\$5,000.00			
	0140	6181000	MOBILIZATION	LS	\$40,000.000	1	\$40,000.00
	0230	7129901	MISC.Heat Straightening	LS	\$98,500.000	1	\$98,500.00
Project J6M	3414 - Tota	I					\$240,850.00
Overall - To	tal						\$240,850.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		nents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6M3413	0010	MISC.	Material			-1	\$25,180.00	(\$25,180.00)
	0010	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1	\$25,180.00	\$25,180.00
	0050	SUBSTRUCTURE REPAIR (FORMED)	Material			-50	\$250.00	(\$12,500.00)
	0050	SUBSTRUCTURE REPAIR	Material		This adjustment offsets the original system-	50	\$250.00	\$12,500.00

Revision 4/1/2020 Page 1 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 16, 2022

Progress Estimate Number 3	Contract ID Prime Contractor	220121-F04 Kozeny-Wagner, Inc.	 , ,	Original Contract Amount Net Change Order Amount	\$555,000.00 \$0.00
				Current Contract Amount	\$555,000.00

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6M3413		(FORMED)			generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
	0060	CLEANING AND EPOXY COATING	Material			-4	\$100.00	(\$400.00)
	0060	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	4	\$100.00	\$400.00
	0070	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material			-1	\$74,000.00	(\$74,000.00)
	0070	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	1	\$74,000.00	\$74,000.00
	0800	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material			-1	\$4,000.00	(\$4,000.00)
	0800	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	1	\$4,000.00	\$4,000.00
	0090	INTERMEDIATE FIELD COAT (SYSTEM G)	Material			-1	\$4,000.00	(\$4,000.00)
	0090	INTERMEDIATE FIELD COAT (SYSTEM G)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	1	\$4,000.00	\$4,000.00
	0100	FINISH FIELD COAT (SYSTEM G)	Material			-1	\$4,000.00	(\$4,000.00)
	0100	FINISH FIELD COAT (SYSTEM G)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	1	\$4,000.00	\$4,000.00
J6M3414	0110	MISC.	Material			-0.75	\$120,000.00	(\$90,000.00)
	0110	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	0.75	\$120,000.00	\$90,000.00
	0130	MISC.	Material			-5	\$1,000.00	(\$5,000.00)
	0130	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	5	\$1,000.00	\$5,000.00
Total								\$0.00

Revision 4/1/2020 Page 2 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J6M3413		Bridge rehabilitation	I-70	ST LOUIS CITY	over Grand Blvd.
J6M3414		Bridge rehabilitation	I-70	ST LOUIS CITY	at Taylor Ave.

N3413	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$149,280.00	\$149,280.00
Gross Item Adjustments	\$0.00	\$0.00	\$0.00
Gross Item Pay	\$0.00	\$149,280.00	\$149,280.00
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
6M3414	This Estimate	Previous	To Date
Posted Item Pay	\$240.850.00	\$0.00	\$240.850.00
Gross Item Adjustments	\$240,650.00	\$0.00 \$0.00	\$240,650.00 \$0.00
Gross Item Pay	\$240,850.00	\$0.00	\$240,850.00
Gross item Fay	\$240,030.00	φυ.υυ	\$240,030.00
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 3 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6M3414, Item 6169901, Project Item Line Number 0110, Material Set 6169901, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Will be resolved by next estimate.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 6169901, Project Item Line Number 0010, Material Set 6169901, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Will be resolved by next estimate	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3414, Item 6169902, Project Item Line Number 0130, Material Set 616990296, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Will be resolved by next estimate	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7040101, Project Item Line Number 0050, Material Set 704010196, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Will be resolved by next estimate	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7040101, Project Item Line Number 0050, Material Set 704010196, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Will be resolved by next estimate	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7040113, Project Item Line Number 0060, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient.	Will meet with MoDOT Materials Department to resolve discrepancy.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7125100, Project Item Line Number 0070, Material Set 712510096, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	Will meet with MoDOT Materials Department to resolve discrepancy.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7125110, Project Item Line Number 0080, Material Set 712511096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Will meet with MoDOT Materials Department to resolve discrepancy.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7125111, Project Item Line Number 0090, Material Set 712511196, Material 1045PTEP - High Solids Epoxy System G Intrmdte Coat, Acceptance Action Generic 1045PTEP is insufficient.	Will meet with MoDOT Materials Department to resolve discrepancy.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6M3413, Item 7125112, Project Item Line Number 0100, Material Set 712511296, Material 1045PTAP - Polyurethane System G Finish Coating, Acceptance Action Generic 1045PTAP is insufficient.	Will be resolved by next estimate	washid1	Overridden

Revision 4/1/2020 Page 4 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Project J6M J6M3414	0001	0040 0050 0060 0070 0080 0090	7040101 7040113 7125100 7125110 7125111 7125112 Posted to 6169901	MISC.Temporary Traffic Control MISC.Traffic Signal Maintenance and Programming MISC.NTCIP Compliant Changeable Message Sign (Contractor Furnished and Retained) MOBILIZATION SUBSTRUCTURE REPAIR (FORMED) CLEANING AND EPOXY COATING SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER INTERMEDIATE FIELD COAT (SYSTEM G) PINISH FIELD COAT (SYSTEM G) Date as of Report Generated Date MISC.Temporary Traffic Control	1.00 1.00 2.00 1.00 50.00 4.00 1.00 1.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	1.00 1.00 2.00 1.00 50.00 4.00 1.00 1.00	LS LS EA LS SQFT SQFT LS LS LS	1.00 1.00 0.00 1.00 50.00 4.00 1.00	\$74,000.00 \$4,000.00 \$4,000.00	\$0.00 \$15,000.00 \$12,500.00 \$400.00 \$74,000.00 \$4,000.00
	0001 0001 0070 0070 0070 0070 0070 0070	0030 0040 0050 0060 0070 0080 0090 0100 tal Value	6169902 6181000 7040101 7040113 7125100 7125110 7125111 7125112 Posted to 6169901	MISC.NTCIP Compliant Changeable Message Sign (Contractor Furnished and Retained) MOBILIZATION SUBSTRUCTURE REPAIR (FORMED) CLEANING AND EPOXY COATING SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER INTERMEDIATE FIELD COAT (SYSTEM G) FINISH FIELD COAT (SYSTEM G) Date as of Report Generated Date	2.00 1.00 50.00 4.00 1.00 1.00	0.00 0.00 0.00 0.00 0.00 0.00	2.00 1.00 50.00 4.00 1.00	EA LS SQFT SQFT LS LS	0.00 1.00 50.00 4.00 1.00	\$1,000.00 \$15,000.00 \$250.00 \$100.00 \$74,000.00 \$4,000.00	\$10,200.00 \$0.00 \$15,000.00 \$12,500.00 \$400.00 \$4,000.00
	0001 0070 0070 0070 0070 0070 0070 0070	0040 0050 0060 0070 0080 0090 0100 tal Value	6181000 7040101 7040101 7125100 7125110 7125111 7125112 Posted to 6169901	Furnished and Retained) MOBILIZATION SUBSTRUCTURE REPAIR (FORMED) CLEANING AND EPOXY COATING SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER INTERMEDIATE FIELD COAT (SYSTEM G) FINISH FIELD COAT (SYSTEM G) Date as of Report Generated Date	1.00 50.00 4.00 1.00 1.00	0.00 0.00 0.00 0.00 0.00	1.00 50.00 4.00 1.00 1.00	LS SQFT SQFT LS LS	1.00 50.00 4.00 1.00 1.00	\$15,000.00 \$250.00 \$100.00 \$74,000.00 \$4,000.00	\$15,000.00 \$12,500.00 \$400.00 \$74,000.00 \$4,000.00
	0070 0070 0070 0070 0070 0070 0070 0001	0050 0060 0070 0080 0090 0100 ttal Value 0110	7040101 7040113 7125100 7125110 7125111 7125112 Posted to 6169901	SUBSTRUCTURE REPAIR (FORMED) CLEANING AND EPOXY COATING SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER INTERMEDIATE FIELD COAT (SYSTEM G) FINISH FIELD COAT (SYSTEM G) Date as of Report Generated Date	50.00 4.00 1.00 1.00 1.00	0.00 0.00 0.00 0.00 0.00	50.00 4.00 1.00 1.00	SQFT SQFT LS LS LS	50.00 4.00 1.00 1.00	\$250.00 \$100.00 \$74,000.00 \$4,000.00	\$12,500.00 \$400.00 \$74,000.00 \$4,000.00
	0070 0070 0070 0070 0070 0070 0001	0060 0070 0080 0090 0100 tal Value	7040113 7125100 7125110 7125111 7125111 Posted to 6169901	CLEANING AND EPOXY COATING SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER INTERMEDIATE FIELD COAT (SYSTEM G) FINISH FIELD COAT (SYSTEM G) Date as of Report Generated Date	4.00 1.00 1.00 1.00 1.00	0.00 0.00 0.00 0.00	4.00 1.00 1.00	SQFT LS LS	4.00 1.00 1.00 1.00	\$100.00 \$74,000.00 \$4,000.00 \$4,000.00	\$400.00 \$74,000.00 \$4,000.00
	0070 0070 0070 0070 0070 0001	0070 0080 0090 0100 tal Value I	7125100 7125110 7125111 7125112 Posted to 6169901	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER INTERMEDIATE FIELD COAT (SYSTEM G) FINISH FIELD COAT (SYSTEM G) Date as of Report Generated Date	1.00 1.00 1.00	0.00	1.00 1.00 1.00	LS LS	1.00 1.00 1.00	\$74,000.00 \$4,000.00 \$4,000.00	\$74,000.00 \$4,000.00 \$4,000.00
	0070 0070 0070 0070 M3413 - To 0001	0080 0090 0100 otal Value I	7125110 7125111 7125112 Posted to 6169901	STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER INTERMEDIATE FIELD COAT (SYSTEM G) FINISH FIELD COAT (SYSTEM G) Date as of Report Generated Date	1.00 1.00 1.00	0.00	1.00	LS LS	1.00	\$4,000.00	\$4,000.00
	0070 0070 M3413 - To 0001	0090 0100 otal Value I	7125111 7125112 Posted to 6169901	INTERMEDIATE FIELD COAT (SYSTEM G) FINISH FIELD COAT (SYSTEM G) Date as of Report Generated Date	1.00	0.00	1.00	LS	1.00	\$4,000.00	\$4,000.00
	0070 M3413 - To 0001	0100 otal Value I 0110	7125112 Posted to 6169901	FINISH FIELD COAT (SYSTEM G) Date as of Report Generated Date	1.00						
	M3413 - To	otal Value I	Posted to 6169901	Date as of Report Generated Date		0.00	1.00	LS		A15	
	0001	0110	6169901	•					1.00	\$4,000.00	\$4,000.00
J6M3414	0001			MISC.Temporary Traffic Control							\$149,280.0
		0120			1.00	0.00	1.00	LS	0.75	\$120,000.00	\$90,000.0
			6169901	MISC.Traffic Signal Maintenance and Programming	1.00	0.00	1.00	LS	0.50	\$14,700.00	\$7,350.0
	0001	0130	6169902	MISC.NTCIP Compliant Changeable Message Sign (Contractor Furnished and Retain)	6.00	0.00	6.00	EA	5.00	\$1,000.00	\$5,000.0
	0001	0140	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$40,000.00	\$40,000.0
	0070	0150	2169902	MISC.Removal of Diaphragm	2.00	0.00	2.00	EA	0.00	\$1,700.00	\$0.0
	0070	0160	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	1,260.00	0.00	1,260.00	LB	0.00	\$42.00	\$0.0
	0070	0170	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.00	\$43,600.00	\$0.00
	0070	0180	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	0.00	1.00	LS	0.00	\$2,000.00	\$0.0
	0070	0190	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$2,000.00	\$0.0
	0070	0200	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$2,000.00	\$0.0
	0070	0210	7126000	NON-DESTRUCTIVE TESTING	39.00	0.00	39.00	LF	0.00	\$200.00	\$0.0
	0070	0220	7129901	MISC.Grind Surface Deformities	1.00	0.00	1.00	LS	0.00	\$3,600.00	\$0.00
	0070	0230	7129901	MISC.Heat Straightening	1.00	0.00	1.00	LS	1.00	\$98,500.00	\$98,500.0
	0070	0240	7129902	MISC.Crack Repairs	2.00	0.00	2.00	EA	0.00	\$3,600.00	\$0.0
Project J6N	M3414 - <u>To</u>	tal Value I	Posted to	Date as of Report Generated Date							\$240,850.00

Revision 4/1/2020 Page 5 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0110	6169901	MISC.	5/15/22	5/16/22	0.75	LS	I-70 and Taylor Ave.					Taylor Ave. Phase 1
0120	6169901	MISC.	5/15/22	5/16/22	0.50	LS	I-70 and Taylor Ave.					Carrie Ave., Broadway Ave., W. Florissant Ave. and Taylor Ave.
0130	6169902	MISC. TRAFFIC CONTROL DEVICES	5/15/22	5/16/22	5.00	EA	1-70					Project limits
0140	6181000	MOBILIZATION	5/15/22	5/16/22	1.00	LS	I-70					Project limits
0230	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	5/15/22	5/16/22	1.00	LS	I-70 and Taylor Ave.					Taylor Ave. (A59863)

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 8



Line Item Adjustments by Estimate

Contract ID:190215-D05

roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
M3413	0010	MISC.	Material		1	Apr 18, 2022	SYSTEM	\$18,885.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Apr 18, 2022	SYSTEM	(\$18,885.00)	
					2	May 2, 2022	SYSTEM	\$25,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	May 2, 2022	SYSTEM	(\$25,180.00)	
					3	May 16, 2022	SYSTEM	\$25,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	May 16, 2022	SYSTEM	(\$25,180.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0010 -	· Total						\$0.00	
	0050	SUBSTRUCTURE REPAIR (FORMED)	Material		2	May 2, 2022	SYSTEM	\$12,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	May 2, 2022	SYSTEM	(\$12,500.00)	
					3	May 16, 2022	SYSTEM	\$12,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	May 16, 2022	SYSTEM	(\$12,500.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0050 -	Total						\$0.00	
	0060	CLEANING AND EPOXY COATING	Material		2	May 2, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	May 2, 2022	SYSTEM	(\$400.00)	
					3	May 16, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	May 16, 2022	SYSTEM	(\$400.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0060 -	Total						\$0.00	
	0070	SURFACE PREPARATION FOR	Material		1	Apr 18, 2022	SYSTEM	\$37,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		RECOATING STRUC			1	Apr 18, 2022	SYSTEM	(\$37,000.00)	
					2	May 2, 2022	SYSTEM	\$74,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	May 2, 2022	SYSTEM	(\$74,000.00)	
					3	May 16, 2022	SYSTEM	\$74,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	May 16, 2022	SYSTEM	(\$74,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
								الفنفذ	



Line Item Adjustments by Estimate

Contract ID:190215-D05

1985 1985	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
	J6M3413	0080	APPLICATION OF INORGANIC	Material	,	2		SYSTEM	\$4,000.00	Estimate Item Adjustment (0005) due to user washid1 overridding Payment
2022 SYSTEM (\$4,000.00)						2		SYSTEM	(\$4,000.00)	
Part						3		SYSTEM	\$4,000.00	Estimate Item Adjustment (0007) due to user washid1 overridding Payment
Material - Total						3		SYSTEM	(\$4,000.00)	
					- Total				\$0.00	
Note				Material - To	otal				\$0.00	
FIELD COAT (SYSTEM G)		0080 -	080 - Total						\$0.00	
		0090	FIELD COAT	Material		2		SYSTEM	\$4,000.00	Estimate Item Adjustment (0006) due to user washid1 overridding Payment
2022 Estimate Item Adjustment (0008) due to user washird overridding Paymer Estimate Exception 9 on the current Payment Estimate.						2		SYSTEM	(\$4,000.00)	
1-7-total						3		SYSTEM	\$4,000.00	Estimate Item Adjustment (0008) due to user washid1 overridding Payment
Material - Total Sound S						3		SYSTEM	(\$4,000.00)	
1009 - Total					- Total				\$0.00	
0100 FINISH FIELD COAT (SYSTEM COAT (SYSTEM G) 2				Material - To	otal				\$0.00	
COAT (SYSTEM COAT		0090 -	Total						\$0.00	
2022 3		0100	COAT (SYSTEM	Material		2		SYSTEM	\$4,000.00	Estimate Item Adjustment (0007) due to user washid1 overridding Payment
2022 SYSTEM SYSTEM SURPLIFIED SUBJECT SUBJEC						2		SYSTEM	(\$4,000.00)	
Total \$0.00						3		SYSTEM	\$4,000.00	Estimate Item Adjustment (0009) due to user washid1 overridding Payment
Material - Total \$0.00						3		SYSTEM	(\$4,000.00)	
Solid Soli					- Total				\$0.00	
J6M3414 O110 MISC. Material 3 May 16, 2022 SYSTEM \$90,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate. - Total O130 MISC. TRAFFIC CONTROL DEVICES Material - Total 3 May 16, SYSTEM \$5,000.00 This adjustment offsets the original system-generated Material Payment Estimate. 50.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate. - Total - Tota			Material - Total						\$0.00	
J6M3414 0110 MISC. Material Misc. Material System 4000000 Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. Amay 16, 2022 SySTEM \$90,000.00 -Total \$0.00		0100 - Total							\$0.00	
Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 3 May 16, SYSTEM (\$90,000.00) - Total \$0.00	J6M3413 -	· Total							\$0.00	
2022 Substituting	J6M3414	0110	MISC.	Material		3		SYSTEM	\$90,000.00	Estimate Item Adjustment (0001) due to user washid1 overridding Payment
Material - Total 0110 - Total 0130 MISC. TRAFFIC CONTROL DEVICES 0130 May 16, 2022 SYSTEM \$5,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 3 May 16, SYSTEM (\$5,000.00) - Total \$0.00 Material - Total \$0.00 0130 - Total \$0.00						3		SYSTEM	(\$90,000.00)	
O110 - Total MISC. TRAFFIC CONTROL DEVICES Material - Total Material - Total S0.00 System \$5,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Su.00 Material - Total S0.00 O130 - Total S0.00					- Total				\$0.00	
0130 MISC. TRAFFIC CONTROL DEVICES Material - Total Superior System Solution System Sy				Material - Total					\$0.00	
CONTROL DEVICES 2022 Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 3 May 16, 2022 SYSTEM (\$5,000.00) - Total \$0.00 Material - Total \$0.00		0110 -	Total						\$0.00	
2022		0130	CONTROL	Material		3		SYSTEM	\$5,000.00	Estimate Item Adjustment (0002) due to user washid1 overridding Payment
Material - Total \$0.00 0130 - Total \$0.00						3		SYSTEM	(\$5,000.00)	
0130 - Total \$0.00					- Total				\$0.00	
				Material - Total					\$0.00	
J6M3414 - Total \$0.00		0130 -	Total						\$0.00	
	J6M3414 -	- Total							\$0.00	
Overall - Total \$0.00	Overall - Total							\$0.00		