

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 17, 2022

Progress Estimate Number	Contract ID	220121-H01	Pay Period Start	October 1, 2022	Original Contract Amount	\$3,635,384.06
14	Prime Contractor	Robertson Contractors, Inc.	Pay Period End	October 15, 2022	Net Change Order Amount	\$90,555.83
17					Current Contract Amount	\$3,725,939.89

Approval Date		By User
October 17, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	woodsk1
October 18, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	bollis1
October 19, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
May 1, 2023	May 1, 2023		56.65%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	February 2, 2022	February 2, 2022	
Letting Date	January 21, 2022	January 21, 2022	
Notice to Proceed Date	April 4, 2022	April 4, 2022	
Open to Traffic Date			
Work Began Date	April 11, 2022	April 11, 2022	

Contract Total Pa	ay For Estimate No. 14			
		This Estimate	Previous	To Date
220121-H01				
	Total Posted Items Pay Gross Item Adjustments	\$131,629.00 \$0.00	\$1,979,254.42 \$0.00	\$2,110,883.42 \$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$1,979,254.42	\$2,110,883.42
Contract Total Pa	ayable This Estimate:	\$131.629.00		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3643	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$15,000.000	0.25	\$3,750.00
	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	CUYD	\$40.000	425	\$17,000.00
	0120	6113040	PLACING TYPE 2 ROCK BLANKET	CUYD	\$25.000	425	\$10,625.00
	0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	EA	\$800.000	8	\$6,400.00
	0310	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	LF	\$2.000	1,414	\$2,828.00
	0380	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.500	16,852	\$8,426.00
	0610	2162500	REMOVAL OF EXISTING BRIDGE DECK	SQFT	\$14.000	5,900	\$82,600.00
Project J9I364	3 - Total						\$131,629.00
Overall - Total							\$131,629.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	ine Item Adjustments This Estimate										
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
J9I3643	0060	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)				-587	\$95.00	(\$55,765.00)			
	0060	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on	587	\$95.00	\$55,765.00			

Revision 4/1/2020 Page 1 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 17, 2022

Progress Estimate Number 14

Contract ID220121-H01Pay Period StartOctober 1, 2022Original Contract Amount\$3,635,384.06Prime ContractorRobertson Contractors, Inc.Pay Period EndOctober 15, 2022Net Change Order Amount\$90,555.83Current Contract Amount\$3,725,939.89

					Gu	irienii Contrat	LI AIIIOUIII	\$3,725,939.89
oject mber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3643					the current Payment Estimate.			
	0070	CONCRETE APPROACH PAVEMENT	Material			-202.4	\$105.00	(\$21,252.00
	0070	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	202.4	\$105.00	\$21,252.00
	0800	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-175	\$20.00	(\$3,500.00
	0800	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	175	\$20.00	\$3,500.00
	0110	FURNISHING TYPE 2 ROCK BLANKET	Material			-425	\$40.00	(\$17,000.00
	0110	FURNISHING TYPE 2 ROCK BLANKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	425	\$40.00	\$17,000.00
	0160	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material			-1	\$5,000.00	(\$5,000.00
	0160	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1	\$5,000.00	\$5,000.00
	0450	MGS GUARDRAIL	Material			-200	\$40.00	(\$8,000.00
	0450	MGS GUARDRAIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	200	\$40.00	\$8,000.00
	0460	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Material			-3	\$4,000.00	(\$12,000.00
	0460	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	3	\$4,000.00	\$12,000.00
	0490	BRIDGE APPROACH SLAB (MAJOR)	Material			-188	\$415.00	(\$78,020.00
	0490	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	188	\$415.00	\$78,020.00
	0500	SLAB ON STEEL	Material			-1,353	\$525.00	(\$710,325.00
	0500	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	1,353	\$525.00	\$710,325.00
	0510	TYPE D BARRIER	Material		-	-558	\$115.00	(\$64,170.00
	14 1000							

Page 2 of 16 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 17, 2022

	Contract ID				Original Contract Amount	
14	Prime Contractor	Robertson Contractors, Inc.	Pay Period End	October 15, 2022	Net Change Order Amount	\$90,555.83
14					Current Contract Amount	\$3,725,939.89

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3643	0510	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	558	\$115.00	\$64,170.00
Total								\$0.00

Revision 4/1/2020 Page 3 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informatio	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9I3643	I 55-1(176)	2 bridge deck replacement	I-55	SCOTT	over Route 62		
Totals by .	Job Numbe	rs					
J9I3643		d Item Pay Item Adjustm		Item Pay	This Estimate \$131,629.00 \$0.00 \$131,629.00	Previous \$1,979,254.42 \$0.00 \$1,979,254.42	To Date \$2,110,883.42 \$0.00 \$2,110,883.42
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 4 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 4019905, Project Item Line Number 0050, Material Set 401990596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5021334, Project Item Line Number 0060, Material Set 502133496, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5021334, Project Item Line Number 0060, Material Set 502133496, Material 1057JMDAEC6.12 - Dowel Assemblies Epoxy Ctd Gr60 1 1/2" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE I" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Jumber 0490, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5031010A, Project Item Line Jumber 0490, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5031010A, Project Item Line Illumber 0490, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl	No Remark was entered by Engineer	woodsk1	Overridden
stimate Exception Type: Insufficient Materials: Project J9I3643, Item 5041000, Project Item Line Number 070, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
stimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 070, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, cceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 1070, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5041000, Project Item Line Number 1070, Material Set 504100096, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6061060, Project Item Line Number 1450, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6061068, Project Item Line Number 1460, Material Set 606106896, Material 1040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6091010, Project Item Line Number 080, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 6113020, Project Item Line Number 1110, Material Set 611302096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6123000A, Project Item Line Jumber 0160, Material Set 6123000A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913643, Item 7034212, Project Item Line Number 1500, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
stimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 500, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 7034219A, Project Item Line Number 0510, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 5 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-H01	J9I3643	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$15,000.00	\$11,250.00
		0001	0020	2071000	LINEAR GRADING CLASS 1	4.40	0.00	4.40	STA	0.00	\$2,600.00	\$0.00
		0001	0030	2072000	LINEAR GRADING CLASS 2	32.40	0.00	32.40	STA	32.40	\$3,850.00	\$124,740.00
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,174.00	0.00	1,174.00	SQYD	587.00	\$15.00	\$8,805.00
		0001	0050	4019905	MISC.Optional Pavement	2,932.00	791.00	3,723.00	SQYD	3,723.00	\$50.53	\$188,123.19
		0001	0060	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	1,173.60	0.00	1,173.60	SQYD	587.00	\$95.00	\$55,765.00
		0001	0070	5041000	CONCRETE APPROACH PAVEMENT	404.80	0.00	404.80	SQYD	202.40	\$105.00	\$21,252.00
		0001	0080	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	349.00	0.00	349.00	LF	175.00	\$20.00	\$3,500.00
		0001	0090	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$45.00	\$0.00
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$80.00	\$0.00
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	425.00	\$40.00	\$17,000.00
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	425.00	\$25.00	\$10,625.00
		0001	0130	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	2.00	1.00	3.00	EA	3.00	\$2,000.00	\$6,000.00
		0001	0140	6122020	REPLACEMENT SAND BARREL	6.00	6.00	12.00	EA	6.00	\$250.00	\$1,500.00
		0001	0150	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	1.00	3.00	EA	3.00	\$1,000.00	\$3,000.00
		0001	0160	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	1.00	\$5,000.00	\$5,000.00
		0001	0170	6161005	CONSTRUCTION SIGNS	2,140.00	0.00	2,140.00	SQFT	1,560.00	\$6.50	\$10,140.00
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	18.00	0.00	18.00	EA	8.00	\$25.00	\$200.00
		0001	0190	6161025	CHANNELIZER (TRIM LINE)	500.00	0.00	500.00	EA	407.00	\$17.00	\$6,919.00
		0001	0200	6161030	TYPE III MOVEABLE BARRICADE	21.00	0.00	21.00	EA	15.00	\$145.00	\$2,175.00
		0001	0210	6161033	DIRECTIONAL INDICATOR BARRICADE	100.00	0.00	100.00	EA	74.00	\$65.00	\$4,810.00
		0001	0220	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$1,500.00	\$4,500.00
		0001	0230	6161052	WARNING LIGHT, TYPE B	50.00	0.00	50.00	EA	0.00	\$15.00	\$0.00
		0001	0240	6161070	TUBULAR MARKER	650.00	0.00	650.00	EA	370.00	\$35.00	\$12,950.00
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,800.00	\$19,200.00
		0001	0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	16.00	\$800.00	\$12,800.00
		0001	0270	6173600D 6175010A	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED RELOCATING TEMPORARY TRAFFIC BARRIER	451.00 451.00	100.00	551.00 551.00	LF	551.00 551.00	\$40.00 \$35.00	\$22,040.00 \$19,285.00
		0001	0290	6181000	MOBILIZATION	1.00	-1.00	0.00	LS		\$225,000.00	\$0.00
		0001	0291	6181000	MOBILIZATION	0.00	1.00	1.00	LS		\$200,165.00	\$200,165.00
		0001	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	10.00	0.00	10.00	EA	0.00		\$0.00
					LEFT/RIGHT ARROW							
		0001	0310		TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,645.00	0.00	3,645.00 8.590.00	LF	3,645.00	\$2.00	\$7,290.00 \$17,180.00
		0001	0320	6205902A	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	6,090.00 2,705.00	2,500.00	30,365.00	LF	8,590.00	\$2.00	\$0.00
		0001	0340	6205903A		1,774.00	19,126.00	20,900.00	LF	0.00	\$0.30	\$0.00
		0001	0350	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	13,177.00	-13,177.00	0.00	LF	0.00	\$0.15	\$0.00
		0001	0360	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,704.00	-6,704.00	0.00	LF	0.00	\$0.15	\$0.00
		0001	0370	6206125A		75.00	-75.00	0.00	LF	0.00	\$5.00	\$0.00
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	50,359.00	0.00	50,359.00	LF	25,180.00	\$0.50	\$12,590.00
		0001	0390	6208063	TEMPORARY PAVEMENT MARKING	34,359.00	0.00	34,359.00	EA	34,359.00	\$0.25	\$8,589.75
		0001	0400	6240102A	TEMPORARY SILT FENCE GEOTEXTILE	1,040.00	0.00	1,040.00	SQYD	0.00	\$1.50	\$0.00
		0001	0410	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,689.00	0.00	1,689.00	SQYD	0.00	\$4.00	\$0.00
		0001	0420	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$20,000.00	\$10,000.00
		0001	0430	7250312A	12 IN. PIPE GROUP B	1,100.00	0.00	1,100.00	LF	1,100.00	\$50.00	\$55,000.00

Revision 4/1/2020 Page 6 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-H01	J9I3643	0001	0440	8061016	SEDIMENT REMOVAL	10.00	0.00	10.00	CUYD	3.00	\$1.00	\$3.00
		0010	0450	6061060	MGS GUARDRAIL	100.00	315.00	415.00	LF	200.00	\$40.00	\$8,000.00
		0010	0460	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	6.00	0.00	6.00	EA	3.00	\$4,000.00	\$12,000.00
		0010	0470	6069901	MISC.Remove and Reinstall High-Tension Gurad Cable	1.00	0.00	1.00	LS	0.50	\$55,000.00	\$27,500.00
		0070	0480	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	11,771.00	\$14.00	\$164,794.00
		0070	0490	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	188.00	\$415.00	\$78,020.00
		0070	0500	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	1,353.00	\$525.00	\$710,325.00
		0070	0510	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	558.00	\$115.00	\$64,170.00
		0070	0520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0070	0530	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	1,800.00	\$15.50	\$27,900.00
		0070	0540	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	20.00	\$450.00	\$9,000.00
		0070	0550	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0070	0560	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0070	0570	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0070	0580	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0070	0590	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	109.00	\$45.00	\$4,905.00
		0070	0600	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	87.00	\$80.00	\$6,960.00
		0071	0610	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	5,900.00	\$14.00	\$82,600.00
		0071	0620	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	0.00	\$415.00	\$0.00
		0071	0630	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	0.00	\$525.00	\$0.00
		0071	0640	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	0.00	\$115.00	\$0.00
		0071	0650	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0071	0660	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	0.00	\$15.50	\$0.00
		0071	0670	7123610	SLAB DRAIN	18.00	0.00	18.00	EA	0.00	\$450.00	\$0.00
		0071	0680	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0071	0690	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0071	0700	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0071	0710	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0071	0720	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	0.00	\$45.00	\$0.00
		0071	0730	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	0.00	\$80.00	\$0.00
		0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$24,835.00	\$24,835.00
		0001	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	36.00	36.00	EA	36.00	\$120.75	\$4,347.00
		0001	5003	8061017	TEMPORARY SEEDING	0.00	1.00	1.00	ACRE	0.50	\$5,660.95	\$2,830.48
		0001	5004	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	0.00	6.00	6.00	EA	6.00	\$50.00	\$300.00
					late as of Report Generated Date							\$2,110,883.42
220121-H01 Ove	rall - Tota	I Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$2,110,883.42

Revision 4/1/2020 Page 7 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9I3643

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	10/14/22	10/17/22	0.25	LS	Southbound Bridge Phase II. Estimated Percentage Payment.	1360		1367		Southbound Bridge Phase II. Estimated Percentage Payment.
0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	10/14/22	10/17/22	425.00	CUYD	Southbound Bridge Phase II. Estimated Percentage Payment.	1360		1367		Southbound Bridge Phase II. Estimated Percentage Payment.
0120	6113040	PLACING TYPE 2 ROCK BLANKET	10/14/22	10/17/22	425.00	CUYD	Southbound Bridge Phase II. Estimated Percentage Payment.	1360		1367		Southbound Bridge Phase II. Estimated Percentage Payment.
0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	10/14/22	10/17/22	8.00	EA	Southbound Bridge Phase II. Estimated Percentage Payment.	1360		1367		Southbound Bridge Phase II. Estimated Percentage Payment.
0310	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	10/14/22	10/17/22	1,414.00	LF	Southbound Bridge Phase II. Estimated Percentage Payment.	1360		1367		Southbound Bridge Phase II. Estimated Percentage Payment.
0380	6207001	PAVEMENT MARKING REMOVAL	10/14/22	10/17/22	16,852.00	LF	Southbound Bridge Phase II. Estimated Percentage Payment.	1360		1367		Southbound Bridge Phase II. Estimated Percentage Payment.
0610	2162500	REMOVAL OF EXISTING BRIDGE DECK	10/14/22	10/17/22	5,900.00	SQFT	Southbound Bridge Phase II. Estimated Percentage Payment.	1360		1367		Southbound Bridge Phase II. Estimated Percentage Payment.

			re details for Construction S												
oject Lin			Total Quantity Posted For DWR Date		ormation		Station	Log Mile	Location	Number of Items		Sp	ecial Sign	SF Each Special Sign	Total SF to F
643 017	0	April 11, 2022	666	WO20-1 48x48 ROAD/BRIDGE/RA	16.00 MP WORK AH	IEAD		65.227	NB	2.00	16				
				CONST-3A 60x48	20.00 FINE	SIGN		65.501	NB	2.00	20				
				CONST-3X 56x12 SPEEDING/PASSIN	4.67			65.501	NB	2.00	4.67				
				GO20-5aP 36x24	. (,	ZONE		65.713	NB	2.00	6				
				(PLAQUE)	0.00 WORK	ZONE		05.715	IND	2.00	0				
				R4-1 36x48 12	.00 DO NOT F	PASS		65.713	NB	2.00	12				
				WO20-5 48x48 RIGHT/CENTER/LE AHEAD		OSED		65.976	NB	2.00	16				
				WO4-1aR 48x48 (ARROW SYMBOL)	16.00 MERG	E		66.107	NB	1.00	16				
				WO20-6a 48x48 RIGHT/CENTER/LE	FT LANE CLO			66.107	NB	1.00	16				
				GO20-5aP 36x24 (PLAQUE)	6.00 WORK	ZONE		66.489	NB	2.00	6				
				R2-1 36x48 12 XX	.00 SPEED LI	MIT		66.489	NB	2.00	12				
				R2-1 36x48 12 XX	.00 SPEED LI	MIT		66.491	SB	2.00	12				
				R2-1 36x48 12 XX	.00 SPEED LI	MIT		68.153	NB	2.00	12				
				GO20-5aP 36x24 (PLAQUE)	6.00 WORK	ZONE		68.396	SB	2.00	6				
				R2-1 36x48 12 XX	.00 SPEED LI	MIT		68.396	SB	2.00	12				
				WO4-1aR 48x48 (ARROW SYMBOL)	16.00 MERG	E		68.598	SB	1.00	16				
				WO20-6a 48x48 RIGHT/CENTER/LE		SED		68.598	SB	1.00	16				
				WO20-5 48x48 RIGHT/CENTER/LE AHEAD	16.00 FT LANE CLO	OSED		68.796	SB	2.00	16				
				GO20-5aP 36x24 (PLAQUE)	6.00 WORK	ZONE		68.997	SB	2.00	6				
				R2-1 36x48 12 XX	.00 SPEED LI	MIT		68.997	SB	2.00	12				
				CONST-3A 60x48	20.00 FINE	SIGN		69.213	SB	2.00	20				
				CONST-3X 56x12 SPEEDING/PASSIN	4.67 IG (PLATE)			69.213	SB	2.00	4.67				
				WO20-1 48x48 ROAD/BRIDGE/RAI	16.00 MP WORK AH	IFAD		69.403	SB	2.00	16				
					.00 SPEED LI				62 to 55 SB Ramp	1.00	12				
				R4-1 36x48 12	.00 DO NOT F	PASS			57 NB to 55 NB Ramp	1.00	12				
					.00 DO NOT F				57 SB to 55 NB Ramp	1.00	12				
				WO20-1 48x48	16.00				57 NB to 55 NB Ramp	1.00	16				
				ROAD/BRIDGE/RAI WO20-1 48x48		IEAD			57 SB to 55 NB Ramp	1.00	16				
				ROAD/BRIDGE/RAI WO20-1 48x48	MP WORK AF	IEAD			62 to 55 SB Ramp	1.00	16				
				ROAD/BRIDGE/RAI WO20-5 48x48	MP WORK AF	IEAD			57 NB to 55 NB Ramp	1.00	16				
				RIGHT/CENTER/LE AHEAD	FT LANE CLO	DSED									
				WO20-5 48x48 RIGHT/CENTER/LE AHEAD	16.00 FT LANE CLO	SED			57 SB to 55 NB Ramp	1.00	16				
				CONST-3A 60x48	20.00 FINE	SIGN			57 NB to 55 NB Ramp	1.00	20				
				CONST-3A 60x48	20.00 FINE	SIGN			57 SB to 55 NB Ramp	1.00	20				
				CONST-3X 56x12 SPEEDING/PASSIN	IG (PLATE)				57 NB to 55 NB Ramp	1.00	4.67				
				CONST-3X 56x12 SPEEDING/PASSIN	IG (PLATE)				57 SB to 55 NB Ramp	1.00	4.67				
				GO20-5aP 36x24 (PLAQUE)					57 NB to 55 NB Ramp	1.00	6				
				GO20-5aP 36x24 (PLAQUE)					57 SB to 55 NB Ramp	1.00	6				
				GO20-5aP 36x24 (PLAQUE)	6.00 WORK	ZONE			62 to 55 SB Ramp	1.00	6				
		April 19, 2022	7	R1-2 48 TRI 6.	93 YIELD			67.450	US 62 Ramp to I-55 NB	1.00	6.93				
		June 2, 2022	126	WO20-2 48x48 AHEAD	16.00 DETOU	R		61.540	Rte 62 EB	1.00	16				
				WO20-1 48x48 ROAD/BRIDGE/RA	16.00 MP WORK AH	IEAD		61.912	Rte 62 EB	1.00	16				
				WO20-5 48x48 RIGHT/CENTER/LE AHEAD	16.00 FT LANE CLO	SED		61.988	Rte 62 EB	1.00	16				

Revision 4/1/2020 Page 8 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

			re details for Construction Sig. Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to
3 0	170	June 2, 2022	126	WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		62.087	Rte 62 EB	1.00	16			
				R11-2 48x30 10.00 ROAD CLOSED		62.281	Rte 62 at I-55 NB Ramp	3.00	10			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		62.676	Rte 62 WB	1.00	16			
				WO20-2 48x48 16.00 DETOUR AHEAD		62.909	Rte 62 WB	1.00	16			
			249	special ??x?? ??.00 NO PASSING ZONE		0.149	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	
				special ??x?? ??.00 NO PASSING		69.377	Rt HH at I-55 NB On Ramp	1.00		I-55 North Detour Signage 50C	27.69	
				Special ??x?? ??.00 NO PASSING		62.391	Rte 62 WB	1.00		I-55 North Detour Signage 50B	27.69	
				Special ??x?? ??.00 NO PASSING		61.988	Rte 62 WB	1.00		I-55 North Detour Signage 50A	27.69	
				ZONE special ??x?? ??.00 NO PASSING		1.070	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	
				ZONE special ??x?? ??.00 NO PASSING		61.789	Rte 62 EB	1.00		I-55 North Detour Signage 50E	27.69	
				ZONE special ??x?? ??.00 NO PASSING		1.847	Rt H NB	1.00		I-55 North Detour Signage 50A	27.69	
				ZONE special ??x?? ??.00 NO PASSING		1.699	Rt H NB	1.00		I-55 North Detour Signage 50D	27.69	
				ZONE		61.854	Rte 62 EB	1.00				
			400	ZONE					40	I-55 North Detour Signage 50C	27.09	
			488	EO5-1 36x48 12.00 GORE EXIT special ??x?? ??.00 NO PASSING		67.173 67.015	I-55 NB to Rte 62 Ramp	2.00	12	Ramp Exit 500 FT Sign 61	16.00	
				ZONE WO1-6 60x30 12.50 HORIZONTAL		66.991	I-55 NB	2.00	12.5			
				ARROW (SYMBOL) R11-2 48x30 10.00 ROAD		66.991	I-55 NB	1.00	10			
				WO13-1 30x30 6.25 ADVISORY		66.804	I-55 NB	1.00	6.25			
				SPEED (PLAQUE) WO1-4L 48x48 16.00 REVERSE		66.804	I-55 NB	1.00	16			
				CURVE (SYMBOL LEFT ARROW) GO20-2 48x24 8.00 END ROAD		65.730	I-55 SB	2.00	8			
				WORK CONST-8 48x36 12.00 WORK		64.654	I-55 NB	2.00	12			
				ZONE NO PHONE ZONE GO20-1 60x24 10.00 ROAD WORK		64.552	I-55 NB	2.00	10			
				NEXT XX MILES								
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		64.454	I-55 NB	1.00	18			
				R11-2 48x30 10.00 ROAD CLOSED		67.253	I-55 NB	1.00	10			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		70.251	I-55 SB	1.00	18			
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		67.253	I-55 NB	2.00	12.5			
				R11-2 48x30 10.00 ROAD CLOSED		67.289	I-55 NB	2.00	10			
				R4-1 36x48 12.00 DO NOT PASS WO6-3 48x48 16.00 TWO WAY		67.429 67.429	I-55 NB	1.00	12 16			
				TRAFFIC (SYMBOL)								
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		67.429	I-55 NB	1.00	6			
				R4-1 36x48 12.00 DO NOT PASS WO6-3 48x48 16.00 TWO WAY		67.647 67.647	I-55 NB I-55 SB	1.00	12			
				TRAFFIC (SYMBOL) GO20-5aP 36x24 6.00 WORK ZONE		67.647	I-55 NB	1.00	6			
				(PLAQUE) WO1-4R 48x48 16.00 REVERSE CURVE (SYMBOL RIGHT ARROW)		67.800	I-55 NB	1.00	16			
				WO13-1 30x30 6.25 ADVISORY		67.800	I-55 NB	1.00	6.25			
				SPEED (PLAQUE) WO1-6 60x30 12.50 HORIZONTAL		67.887		2.00	12.5			
				ARROW (SYMBOL) R5-1 30x30 6.25 DO NOT ENTER			I-55 NB	2.00	6.25			
				WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.890	I-55 SB	2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		69.286	Rt HH Ramp to I-55 SB	1.00	16			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		69.825	I-55 SB	2.00	12			
				GO20-1 60x24 10.00 ROAD WORK		70.031	I-55 SB	2.00	10			
		June 13, 2022	24	NEXT XX MILES R2-1 36x48 12.00 SPEED LIMIT		62.117	Rt 62 EB	1.00	12			
				XX R2-1 36x48 12.00 SPEED LIMIT		62.428	Rt 62 WB	1.00	12			
	170 - Total			XX								15

Revision 4/1/2020 Page 9 of 16



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
13643	0050	MISC.	Material		4	May 16, 2022	SYSTEM	\$118,523.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$118,523.17)	
					5	Jun 2, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$148,153.96)	
					6	Jun 16, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$148,153.96)	
					7	Jul 1, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$148,153.96)	
					8	Jul 19, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$148,153.96)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0050 -	Total						\$0.00	
	0060	CONCRETE PAVEMENT (10 1/2 IN. NON- REINF,	Material		11	Sep 2, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		, ,			11	Sep 2, 2022	SYSTEM	(\$55,765.00)	
					12	Sep 16, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$55,765.00)	
					13	Sep 30, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$55,765.00)	
					14	Oct 17, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$55,765.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0060 -							\$0.00	
	0070	CONCRETE APPROACH PAVEMENT	Material		11	Sep 2, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Sep 2, 2022	SYSTEM	(\$21,252.00)	
					12	Sep 16, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$21,252.00)	
					13	Sep 30, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					13	Sep 30,	SYSTEM	(\$21,252.00)	



2022 14	verridding Payment aterial Payment verridding Payment
14	verridding Payment aterial Payment verridding Payment
Total \$0.00	verridding Payment
Material - Total \$0.00	verridding Payment
CONCRETE CURB (6 IN. HEIGHT AND UNDER) 12 Sep 16, 2022 SYSTEM \$3,500.00 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0003) due to user woodsk1 over Estimate Exception 15 on the current Payment Estimate. 12 Sep 16, 2022 SYSTEM (\$3,500.00) SYSTEM (\$3,500.00) This adjustment offsets the original system-generated Material Estimate Item Adjustment offsets the original system-generated Material Estimate Item Adjustment (0003) due to user woodsk1 over Woodsk1 ov	verridding Payment
O080 CONCRETE CURB (6 IN. HEIGHT AND UNDER) 12 Sep 16, 2022 13 Sep 30, 2022 14 SySTEM \$3,500.00 This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0003) due to user woodsk1 ov Estimate Exception 15 on the current Payment Estimate. 15 Sep 16, 2022 16 SySTEM (\$3,500.00) This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0003) due to user woodsk1 ov Estimate Item Adjustment (0003) due to user woodsk1 ov	verridding Payment
CURB (6 IN. HEIGHT AND UNDER) 12 Sep 16, 2022 13 Sep 30, SYSTEM (\$3,500.00) 14 Sep 30, SYSTEM (\$3,500.00) 15 Sep 30, SYSTEM (\$3,500.00) 2022 2022 Estimate Item Adjustment (0003) due to user woodsk1 over the current Payment Estimate. (\$3,500.00) This adjustment offsets the original system-generated Mean Estimate Item Adjustment (0003) due to user woodsk1 over the current Payment Estimate.	verridding Payment
12 Sep 16, 2022 (\$3,500.00) 13 Sep 30, SYSTEM (\$3,500.00) This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0003) due to user woodsk1 ov	
2022 Estimate Item Adjustment (0003) due to user woodsk1 ov	
	verridding Payment
13 Sep 30, SYSTEM (\$3,500.00)	
14 Oct 17, 2022 SYSTEM \$3,500.00 This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0003) due to user woodsk1 ov Estimate Exception 14 on the current Payment Estimate.	
14 Oct 17, 2022 (\$3,500.00)	
- Total \$0.00	
Material - Total \$0.00	
0080 - Total \$0.00	
0110 FURNISHING TYPE 2 ROCK BLANKET 14 Oct 17, 2022 \$17,000.00 This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0004) due to user woodsk1 ov Estimate Exception 15 on the current Payment Estimate.	
14 Oct 17, 2022 (\$17,000.00)	
- Total \$0.00	
Material - Total \$0.00	
0110 - Total \$0.00	
0130 IMPACT Material 5 Jun 2, SYSTEM \$4,000.00 This adjustment offsets the original system-generated Material ATTENUATOR 70 MPH (SAND BARREL ARRAY) 5 Jun 2, SYSTEM \$4,000.00 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0002) due to user lee21 overring Estimate Exception 3 on the current Payment Estimate.	
5 Jun 2, SYSTEM (\$4,000.00)	
- Total \$0.00	
Material - Total \$0.00	
0130 - Total \$0.00	
0160 TRUCK OR TRAILER 13 Sep 30, SYSTEM \$5,000.00 This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0004) due to user woodsk1 ov	verridding Payment
MOUNTED ATTEN Estimate Exception 15 on the current Payment Estimate.	
MOUNTED ATTEN (TMA) 13 Sep 30, 2022 SYSTEM (\$5,000.00)	
(TMA) 13 Sep 30, SYSTEM (\$5,000.00)	verridding Payment
(TMA) 13 Sep 30, 2022 14 Oct 17, 2022 15 SYSTEM \$5,000.00 This adjustment offsets the original system-generated Marketimate Item Adjustment (0005) due to user woodsk1 over the stimate Exception 16 on the current Payment Estimate. 16 System \$5,000.00 17 System \$5,000.00 18 System \$5,000.00 19 System \$5,000.00 10 System \$5,000.00	verridding Payment
(TMA) 13 Sep 30, 2022 (\$5,000.00) 14 Oct 17, 2022 (\$5,000.00) This adjustment offsets the original system-generated Ma Estimate Item Adjustment (0005) due to user woodsk1 ov Estimate Exception 16 on the current Payment Estimate. 14 Oct 17, SYSTEM (\$5,000.00)	verridding Payment
(TMA) 13 Sep 30, 2022 14 Oct 17, 2022 15 SYSTEM \$5,000.00 This adjustment offsets the original system-generated Marketimate Item Adjustment (0005) due to user woodsk1 over Estimate Exception 16 on the current Payment Estimate. 14 Oct 17, 2022 SYSTEM \$5,000.00)	verridding Payment
(TMA) 13	verridding Payment
13	verridding Payment



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
43	0180	ADVANCED WARNING RAIL SYSTEM	Material		3	May 2, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$100.00)	
					4	May 16, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$100.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0180 -	Total						\$0.00	
	0190	CHANNELIZER (TRIM LINE)	Material		2	Apr 15, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$2,244.00)	
					3	May 2, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$2,244.00)	
					4	May 16, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$2,244.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0190 -	Total						\$0.00	
	0210	DIRECTIONAL INDICATOR BARRICADE	Material		2	Apr 15, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$2,340.00)	
					3	May 2, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$2,340.00)	
								(+=,= : : : :)	
					4	May 16, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	, , ,	Estimate Item Adjustment (0004) due to user leez1 overridding Payment
				- Total		May 16, 2022 May 16,		\$2,340.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment
			Material - To			May 16, 2022 May 16,		\$2,340.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment
	0210 -	Total	Material - To		4	May 16, 2022 May 16,	SYSTEM	\$2,340.00 (\$2,340.00)	Estimate Item Adjustment (0004) due to user leez1 overridding Payment
	0210 - 0220	Total FLASHING ARROW PANEL	Material - To			May 16, 2022 May 16,		\$2,340.00 (\$2,340.00) \$0.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment
		FLASHING			4	May 16, 2022 May 16, 2022 Apr 15,	SYSTEM	\$2,340.00 (\$2,340.00) \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment
		FLASHING			2	May 16, 2022 May 16, 2022 Apr 15, 2022	SYSTEM	\$2,340.00 (\$2,340.00) \$0.00 \$0.00 \$3,000.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment
		FLASHING			2 2	May 16, 2022 May 16, 2022 Apr 15, 2022 Apr 15, 2022 May 2,	SYSTEM SYSTEM	\$2,340.00 (\$2,340.00) \$0.00 \$0.00 \$3,000.00 (\$3,000.00)	Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment
		FLASHING			2 2 3	May 16, 2022 May 16, 2022 Apr 15, 2022 Apr 15, 2022 May 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,340.00 (\$2,340.00) \$0.00 \$0.00 \$3,000.00 (\$3,000.00) \$3,000.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0220	FLASHING ARROW PANEL	Material	- Total				\$0.00	
			Material - To	otal				\$0.00	
	0220 -						0)/0==1/	\$0.00	
	0250	CMS W/O COMMUNICATION INTERFACE,	Material		2	Apr 15, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		CONT F/			2	Apr 15, 2022	SYSTEM	(\$9,600.00)	
					3	May 2, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$9,600.00)	
					4	May 16, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$9,600.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0250 -	Total						\$0.00	
	0270	TEMPORARY TRAFFIC BARRIER, CONT.	Material		5	Jun 2, 2022	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		FURN/RE			5	Jun 2, 2022	SYSTEM	(\$11,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0270 -	Total						\$0.00	
	0310	TEMPORARY REMOVABLE MARKING TAPE 4	Material		6	Jun 16, 2022	SYSTEM	\$2,706.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		IN.,			6	Jun 16, 2022	SYSTEM	(\$2,706.00)	
					7	Jul 1, 2022	SYSTEM	\$4,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$4,462.00)	
					8	Jul 19, 2022	SYSTEM	\$4,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$4,462.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0310 -	Total						\$0.00	
	0320	TEMPORARY REMOVABLE MARKING TAPE	Material		6	Jun 16, 2022	SYSTEM	\$7,416.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$7,416.00)	
					7	Jul 1, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$12,180.00)	
					8	Jul 19, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$12,180.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0320	TEMPORARY REMOVABLE MARKING TAPE	Material - To	otal				\$0.00	
	0320 -	Total						\$0.00	
	0390	TEMPORARY PAVEMENT MARKING	Material		6	Jun 16, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$6,062.25)	
					7	Jul 1, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$6,062.25)	
					8	Jul 19, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$6,062.25)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0390 -	Total						\$0.00	
	0450	MGS GUARDRAIL	Material		12	Sep 16, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$8,000.00)	
					13	Sep 30, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$8,000.00)	
					14	Oct 17, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$8,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0450 -							\$0.00	
	0460	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Material		12	Sep 16, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$12,000.00)	
					13	Sep 30, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$12,000.00)	
					14	Oct 17, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$12,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0460 -							\$0.00	
	0490	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		11	Sep 2, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Sep 2, 2022	SYSTEM	(\$78,020.00)	
					12	Sep 16,	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0490	BRIDGE APPROACH SLAB	Material			2022			Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		(MAJOR ROAD)			12	Sep 16, 2022	SYSTEM	(\$78,020.00)	
					13	Sep 30, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$78,020.00)	
					14	Oct 17, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$78,020.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0490 -	Total						\$0.00	
	0500	SLAB ON STEEL	Material		10	Aug 17, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Aug 17, 2022	SYSTEM	(\$710,325.00)	
					11	Sep 2, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					11	Sep 2, 2022	SYSTEM	(\$710,325.00)	
					12	Sep 16, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$710,325.00)	
					13	Sep 30, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$710,325.00)	
					14	Oct 17, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$710,325.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0500 -	Total						\$0.00	
	0510	TYPE D BARRIER	Material		12	Sep 16, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$64,170.00)	
					13	Sep 30, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$64,170.00)	
					14	Oct 17, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$64,170.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0510 -	Total						\$0.00	
	0540	SLAB DRAIN	Material		9	Aug 2,	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment

Oct 20, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Toject	LINE	Description	Type	Adjustment Type		Date	By	Amount	Remains
J9I3643	0540	SLAB DRAIN	Material			2022			Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 2, 2022	SYSTEM	(\$9,000.00)	
					10	Aug 17, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Aug 17, 2022	SYSTEM	(\$9,000.00)	
					11	Sep 2, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Sep 2, 2022	SYSTEM	(\$9,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0540 -	Total						\$0.00	
	5002	SEQUENTIAL FLASHING WARNING LIGHT	Material		4	May 16, 2022	SYSTEM	\$4,347.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$4,347.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5002 -	Total	Material - To	otal				\$0.00 \$0.00	
	5002 - 5003	Total TEMPORARY SEEDING	Material - To	otal	5	Jun 2, 2022	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		TEMPORARY		otal	5		SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0003) due to user leez1 overridding Payment
1		TEMPORARY		otal		2022 Jun 2,		\$0.00 \$2,830.48	Estimate Item Adjustment (0003) due to user leez1 overridding Payment
		TEMPORARY		otal	5	Jun 2, 2022 Jun 16,	SYSTEM	\$0.00 \$2,830.48 (\$2,830.48)	Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment
		TEMPORARY		otal - Total	5	Jun 2, 2022 Jun 16, 2022 Jun 16,	SYSTEM	\$0.00 \$2,830.48 (\$2,830.48) \$2,830.48	Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment
		TEMPORARY		- Total	5	Jun 2, 2022 Jun 16, 2022 Jun 16,	SYSTEM	\$0.00 \$2,830.48 (\$2,830.48) \$2,830.48	Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment
		TEMPORARY SEEDING	Material	- Total	5	Jun 2, 2022 Jun 16, 2022 Jun 16,	SYSTEM	\$0.00 \$2,830.48 (\$2,830.48) \$2,830.48 (\$2,830.48)	Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment
J9I3643 -	5003 -	TEMPORARY SEEDING	Material	- Total	5	Jun 2, 2022 Jun 16, 2022 Jun 16,	SYSTEM	\$0.00 \$2,830.48 (\$2,830.48) \$2,830.48 (\$2,830.48) \$0.00	Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment