

Pay Estimate Created Date: November 2, 2022

Progress Estimate I 15	lumber	Contract ID Prime Contractor	220121-H01 Robertson Contrac				Original Contract Amount Net Change Order Amount Current Contract Amount	
Approval Date								By User
November 2, 2022			Generated and	Approved	(and should be considered	d Draft) at f	the Project Office Level by	woodsk1
November 2, 2022		F	ft) at the R	esident Engineer Level by	bollis1			
November 3, 2022			I and Approved at the Cen	tral Office (Controllers Office Level by	ramses1		
Original Completion	on Date	Current Cor	npletion Date	Actu	al Completion Date	of Current Contract Amount	unt Complete	
May 1, 2023		May	1, 2023				60.07%	
	Contrac	ct Informational Dat	tes		Milestones			
Date Description	Origina	I Completion Date	Current Complet	ion Date	No Milestones Exist for	Contract		
Acceptance Date								
Awarded Date	Februar	y 2, 2022	February 2, 2022					
Letting Date	January	21, 2022	January 21, 2022					
Notice to Proceed Date	April 4,	2022	April 4, 2022					
Open to Traffic Date								
Work Began Date	April 11	, 2022	April 11, 2022					

Contract Total Pag	y For Estimate No. 15			
		This Estimate	Previous	To Date
220121-H01				
	Total Posted Items Pay	\$127,299.00	\$2,110,883.42	\$2,238,182.42
	Gross Item Adjustments	\$60,113.00	\$0.00	\$60,113.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$2,110,883.42	\$2,298,295.42
Contract Total Pag	yable This Estimate:	\$187,412.00		

Contract Total Payable This Estimate:

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3643	0140	6122020	REPLACEMENT SAND BARREL	EA	\$250.000	6	\$1,500.00
	0420	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$20,000.000	0.5	\$10,000.00
	0450	6061060	MGS GUARDRAIL	LF	\$40.000	20	\$800.00
	0610	2162500	REMOVAL OF EXISTING BRIDGE DECK	SQFT	\$14.000	5,871	\$82,194.00
	0660	7121159	SHEAR CONNECTORS	EA	\$15.500	1,800	\$27,900.00
	0720	7126000	NON-DESTRUCTIVE TESTING	LF	\$45.000	109	\$4,905.00
Project J9I36	43 - Total						\$127,299.00
Overall - Tota	1						\$127,299.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3643	0060	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)				-587	\$95.00	(\$55,765.00)
	0060	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	587	\$95.00	\$55,765.00



Pay Estimate Created Date: November 2, 2022

Progr		timate Number 15	Contract ID Prime Contr	220121- actor Roberts		Pay Period Start October 16, 2022 Ori s, Inc. Pay Period End November 1, 2022 Ne Cu	t Change Ord	der Amount	
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
913643	0070	CONCRETE	APPROACH PAVEMENT	Material			-202.4	\$105.00	(\$21,252.00
	0070	CONCRETE	APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	202.4	\$105.00	\$21,252.00
	0080	CONCRETE HEIGHT AND UI	CURB (6 IN. NDER) TYPE S	Material			-175	\$20.00	(\$3,500.00
	0080	CONCRETE HEIGHT AND UI	CURB (6 IN. NDER) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	175	\$20.00	\$3,500.00
	0110	FURNISHING T	YPE 2 ROCK BLANKET	Material			-425	\$40.00	(\$17,000.00
	0110	FURNISHING T	YPE 2 ROCK BLANKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	425	\$40.00	\$17,000.00
	0160	TRUCK MOUNTED A	OR TRAILER ITENUATOR (TMA)	Material			-1	\$5,000.00	(\$5,000.00
	0160	TRUCK MOUNTED A	OR TRAILER ITENUATOR (TMA)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1	\$5,000.00	\$5,000.00
	0450	MGS	GUARDRAIL	Material			-220	\$40.00	(\$8,800.0
	0450	MGS	GUARDRAIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	220	\$40.00	\$8,800.0
	0460		APPROACH ON SECTION IDED CURB)	Material			-3	\$4,000.00	(\$12,000.0
	0460		APPROACH ON SECTION IDED CURB)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	3	\$4,000.00	\$12,000.00
	0490	BRIDGE APPR	ROACH SLAB (MAJOR)	Material			-188	\$415.00	(\$78,020.0
	0490	BRIDGE APPR	COACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	188	\$415.00	\$78,020.00
	0500	SLA	B ON STEEL	Material			-1,353	\$525.00	(\$710,325.0
	0500	SLA	B ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	1,353	\$525.00	\$710,325.00
	0510	TYPE	D BARRIER	Material			-558	\$115.00	(\$64,170.00
	0510	TYPE	D BARRIER	Material		This adjustment offsets the original system-	558	\$115.00	\$64,170.00

Pay Estimate Created Date: November 2, 2022

Progr		imate Number 15	Contract ID Prime Contr			Pay Period Start October 16, 2022 Ori s, Inc. Pay Period End November 1, 2022 Net Cur	Change Ord	ler Amount	
Project Number	Line No.	Item Desc	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3643						generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
	0630	SLA	B ON STEEL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$60,113.00
Total									\$60,113.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information							
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J9I3643	l 55-1(176)	2 bridge deck replacement	I-55	SCOTT	over Route 62							
Totals by	Fotals by Job Numbers											

J9I3643		This Estimate	Previous	To Date
	Posted Item Pay Gross Item Adjustments	\$127,299.00 \$60,113.00	\$2,110,883.42 \$0.00	\$2,238,182.42 \$60,113.00
	Gross Item Pay	\$187,412.00	\$2,110,883.42	\$2,298,295.42
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Periou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 4019905, Project Item Line Number 0050, Material Set 401990596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5021334, Project Item Line Number 0060, Material Set 502133496, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5021334, Project Item Line Number 0060, Material Set 502133496, Material 1057JMDAEC6.12 - Dowel Assemblies Epoxy Ctd Gr60 1 1/2" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 6061060, Project Item Line Number 0450, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 6061068, Project Item Line Number 0460, Material Set 606106896, Material 1040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6091010, Project Item Line Number 0080, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6113020, Project Item Line Number 0110, Material Set 611302096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 6123000A, Project Item Line Number 0160, Material Set 6123000A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 7034212, Project Item Line Number 0500, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 7034212, Project Item Line Number 0500, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 7034219A, Project Item Line Number 0510, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

ed date and can differ from the posted amount at the time the Estimate was Generated. Note: Posted (

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
20121-H01	J9I3643	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$15,000.00	\$11,250.0
		0001	0020	2071000	LINEAR GRADING CLASS 1	4.40	0.00	4.40	STA	0.00	\$2,600.00	\$0.0
		0001	0030	2072000	LINEAR GRADING CLASS 2	32.40	0.00	32.40	STA	32.40	\$3,850.00	\$124,740.0
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,174.00	0.00	1,174.00	SQYD	587.00	\$15.00	\$8,805.0
		0001	0050	4019905	MISC.Optional Pavement	2,932.00	791.00	3,723.00	SQYD	3,723.00	\$50.53	\$188,123.
		0001	0060	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	1,173.60	0.00	1,173.60	SQYD	587.00	\$95.00	\$55,765.
		0001	0070	5041000	CONCRETE APPROACH PAVEMENT	404.80	0.00	404.80	SQYD	202.40	\$105.00	\$21,252.
		0001	0080	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	349.00	0.00	349.00	LF	175.00	\$20.00	\$3,500.
		0001	0090	6096010A	DA FURNISHING TYPE 1 ROCK DITCH LINER		0.00	47.00	CUYD	0.00	\$45.00	\$0.
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$80.00	\$0.
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	425.00	\$40.00	\$17,000.
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	425.00	\$25.00	\$10,625.
		0001	0130	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	2.00	1.00	3.00	EA	3.00	\$2,000.00	\$6,000.
		0001	0140	6122020	REPLACEMENT SAND BARREL	6.00	6.00	12.00	EA	12.00	\$250.00	\$3,000.
		0001	0150	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	1.00	3.00	EA	3.00	\$1,000.00	\$3,000
		0001	0160	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	1.00	\$5,000.00	\$5,000.
		0001	0170	6161005	CONSTRUCTION SIGNS	2,140.00	0.00	2,140.00	SQFT	1,560.00	\$6.50	\$10,140
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	18.00	0.00	18.00	EA	8.00	\$25.00	\$200.
		0001	0190	6161025	CHANNELIZER (TRIM LINE)	500.00	0.00	500.00	EA	407.00	\$17.00	\$6,919
		0001	0200	6161030	TYPE III MOVEABLE BARRICADE	21.00	0.00	21.00	EA	15.00	\$145.00	\$2,175
		0001 0210 6161033			DIRECTIONAL INDICATOR BARRICADE	100.00	0.00	100.00	EA	74.00	\$65.00	\$4,810
			0220	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$1,500.00	\$4,500
		0001	0230	6161052	WARNING LIGHT, TYPE B	50.00	0.00	50.00	EA	0.00	\$15.00	\$0
		0001	0240	6161070	TUBULAR MARKER		0.00	650.00	EA	370.00	\$35.00	\$12,950
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,800.00	\$19,200
		0001	0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	16.00	\$800.00	\$12,800
		0001	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	451.00	100.00	551.00	LF	551.00	\$40.00	\$22,040
		0001	0280	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	451.00	100.00	551.00	LF	551.00	\$35.00	\$19,285
		0001	0290	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$225,000.00	\$0
		0001	0291	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$200,165.00	\$200,165
		0001	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	10.00	0.00	10.00	EA	0.00	\$250.00	\$0
		0001	0310	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,645.00	0.00	3,645.00	LF	3,645.00	\$2.00	\$7,290
		0001	0320	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	6,090.00	2,500.00	8,590.00	LF	8,590.00	\$2.00	\$17,180
		0001	0330	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,705.00	27,660.00	30,365.00	LF	0.00	\$0.30	\$0
		0001	0340	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,774.00	19,126.00	20,900.00	LF	0.00	\$0.30	\$0
		0001	0350	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	13,177.00	-13,177.00	0.00	LF	0.00	\$0.15	\$0
		0001	0360	6206001C		6,704.00	-6,704.00	0.00	LF	0.00	\$0.15	\$0
		0001	0370	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	75.00	-75.00	0.00	LF	0.00	\$5.00	\$0
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	50,359.00	0.00	50,359.00	LF	25,180.00	\$0.50	\$12,590
		0001	0390	6208063	TEMPORARY PAVEMENT MARKING	34,359.00	0.00	34,359.00	EA	34,359.00	\$0.25	\$8,589
		0001	0400	6240102A	TEMPORARY SILT FENCE GEOTEXTILE	1,040.00	0.00	1,040.00	SQYD	0.00	\$1.50	\$C
		0001	0410	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,689.00	0.00	1,689.00	SQYD	0.00	\$4.00	\$0
		0001	0420	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract	Project	Category	Line	Item	Report Generated date and can differ from the posted am Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.	Category	No.	Code	Description	Quantity	Change Order	Current Quantity	Unit	Posted Approved Qty	Unit Price	To Date (See report generated date)
220121-H01	J9I3643	0001	0440	8061016	SEDIMENT REMOVAL	10.00	0.00	10.00	CUYD	3.00	\$1.00	\$3.00
		0010	0450	6061060	MGS GUARDRAIL	100.00	315.00	415.00	LF	220.00	\$40.00	\$8,800.00
		0010	0460	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	6.00	0.00	6.00	EA	3.00	\$4,000.00	\$12,000.00
		0010	0470	6069901	MISC.Remove and Reinstall High-Tension Gurad Cable	1.00	0.00	1.00	LS	0.50	\$55,000.00	\$27,500.00
		0070	0480	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	11,771.00	\$14.00	\$164,794.00
		0070	0490	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	188.00	\$415.00	\$78,020.00
		0070	0500	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	1,353.00	\$525.00	\$710,325.00
		0070	0510	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	558.00	\$115.00	\$64,170.00
		0070	0520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0070	0530	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	1,800.00	\$15.50	\$27,900.00
		0070	0540	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	20.00	\$450.00	\$9,000.00
		0070	0550	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0070	0560	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0070	0570	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0070	0580	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0070	0590	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	109.00	\$45.00	\$4,905.00
		0070	0600	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	87.00	\$80.00	\$6,960.00
		0071	0610	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	11,771.00	\$14.00	\$164,794.00
		0071	0620	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	0.00	\$415.00	\$0.00
		0071	0630	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	0.00	\$525.00	\$0.00
		0071	0640	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	0.00	\$115.00	\$0.00
		0071	0650	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0071	0660	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	1,800.00	\$15.50	\$27,900.00
		0071	0670	7123610	SLAB DRAIN	18.00	0.00	18.00	EA	0.00	\$450.00	\$0.00
		0071	0680	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0071	0690	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0071	0700	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0071	0710	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0071	0720	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	109.00	\$45.00	\$4,905.00
		0071	0730	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	0.00	\$80.00	\$0.00
		0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$24,835.00	\$24,835.00
		0001	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	36.00	36.00	EA	36.00	\$120.75	\$4,347.00
		0001	5003	8061017	TEMPORARY SEEDING	0.00	1.00	1.00	ACRE	0.50	\$5,660.95	\$2,830.48
		0001	5004	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	0.00	6.00	6.00	EA	6.00	\$50.00	\$300.00
					bate as of Report Generated Date							\$2,238,182.42
220121-H01 Ove	erall - Tota	Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$2,238,182.42



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	ltem Code		Description	DWR Date	DWR Approval Date	Quantity Posted	Units		Location		From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance		Comments	
0140	6122020	REPLACEMENT S	AND BARREL	10/31/22	11/2/22	6.00	EA	Southbound Bridg Payment.	e Phase II. Estimated Percenta	age	1360		1367		Southbound Bri Payment.	dge Phase II. Estimated Pe	ercentage
0420	6274000	CONTRACTOR FU	JRNISHED SURVEYING AND STAKI	10/31/22	11/2/22	0.50	LS	Southbound Bridg Payment.	e Phase II. Estimated Percenta	age	1360		1367		Southbound Bri Payment.	dge Phase II. Estimated Pe	ercentage
0450	6061060	MGS GUARDRAIL		10/20/22	10/26/22	20.00	LF		pertaining to line item payment.		1360		1367			e pertaining to line item pa	
								not at contract qu	ardrail numbers and I see that v antity right now. I will pay the 2 g to get you to the installed am	20' that					not at contract of	uardrail numbers and I se quantity right now. I will pa ing to get you to the install	ay the 20' that
								need to do a char	ge order at the moment for tha oday's work report and be den	at.					need to do a ch	ange order at the moment	for that.
	0400500			10/01/00	44/0/00	5 074 00	0.057	payment for 0450	in place payment.		4000		40.07		payment for 048	n today's work report and t 50 in place payment.	
			ISTING BRIDGE DECK	10/31/22		5,871.00		Payment.	e Phase II. Estimated Percenta		1360		1367		Payment.	dge Phase II. Estimated Po	
		SHEAR CONNEC		10/31/22		1,800.00		Payment.	e Phase II. Estimated Percenta		1360		1367		Payment.	dge Phase II. Estimated Po	
		NON-DESTRUCTI		10/31/22		109.00	LF	Payment.	e Phase II. Estimated Percenta	age	1360		1367		Payment.	dge Phase II. Estimated Pe	ercentage
	Line Numb		Total Quantity Posted For DWR Date	ins (if ap	Sign Info			Station Log Mi	e Location	Numbe	r of Items	SF Each	Sign	Spec	ial Sign	SF Each Special Sign	Total SF to
13643	0170	April 11, 2022	666	WO20-1 ROAD/BR	48x48 10 IDGE/RAM	6.00 IP WORK /	AHEAD	65.227	NB	2.00		16					
					A 60x48 X 56x12		E SIGN	65.501 65.501	NB	2.00 2.00		20 4.67					
				SPEEDIN	G/PASSING 9 36x24	G (PLATE)		65.713	NB	2.00		6					
				(PLAQUE				65.713	NB	2.00		12					
				WO20-5	48x48 10 ENTER/LEF	6.00		65.976	NB	2.00		16					
				AHEAD	48x48			66.107	NB	1.00		16					
				(ARROW				66.107	NB	1.00		16					
				RIGHT/CE	ENTER/LEF 9 36x24	T LANE C		66.489	NB	2.00		6					
				(PLAQUE) 36x48 12.0			66.489	NB	2.00		12					
				XX	36x48 12.0			66.491	SB	2.00		12					
					36x48 12.0	0 SPEED	LIMIT	68.153	NB	2.00		12					
				XX GO20-5aF	P 36x24	6.00 WOR	K ZONE	68.396	SB	2.00		6					
) 36x48 12.0	0 SPEED	LIMIT	68.396	SB	2.00		12					
				XX WO4-1aR	48x48	16.00 MER	GE	68.598	SB	1.00		16					
					48x48 1			68.598	SB	1.00		16					
				WO20-5	48x48 10 NTER/LEF	6.00		68.796	SB	2.00		16					
				AHEAD	9 36x24			68.997	SB	2.00		6					
				(PLAQUE R2-1 3) 36x48 12.0	0 SPEED	LIMIT	68.997	SB	2.00		12					
				XX CONST-3	A 60x48	20.00 FINE	E SIGN	69.213	SB	2.00		20					
					X 56x12 G/PASSIN(69.213	SB	2.00		4.67					
					48x48 1		AHEAD	69.403	SB	2.00		16					
				R2-1 3 XX	36x48 12.0	00 SPEED	LIMIT		62 to 55 SB Ramp	1.00		12					
					36x48 12.0				57 NB to 55 NB Ramp	1.00		12					
				WO20-1	36x48 12.0 48x48 10	6.00			57 SB to 55 NB Ramp 57 NB to 55 NB Ramp	1.00		12 16					
				WO20-1	48x48 1	6.00			57 SB to 55 NB Ramp	1.00		16					
				WO20-1	48x48 1	6.00			62 to 55 SB Ramp	1.00		16					
				WO20-5	48x48 1 A8x48 1	6.00			57 NB to 55 NB Ramp	1.00		16					
				AHEAD	48x48 1		LUSED		57 SB to 55 NB Ramp	1.00		16					
					46x46 II		LOSED		or ob to so the ramp	1.00		10					
					A 60x48 A 60x48				57 NB to 55 NB Ramp 57 SB to 55 NB Ramp	1.00		20 20					
					A 60x46 X 56x12 G/PASSIN(57 NB to 55 NB Ramp	1.00		4.67					
				CONST-3	X 56x12 G/PASSING	4.67			57 SB to 55 NB Ramp	1.00		4.67					
					9 36x24				57 NB to 55 NB Ramp	1.00		6					
					9 36x24	6.00 WOR	K ZONE		57 SB to 55 NB Ramp	1.00		6					
					9 36x24	6.00 WOR	K ZONE		62 to 55 SB Ramp	1.00		6					
		April 19, 2022		R1-2 4	8 TRI 6.9			67.450	US 62 Ramp to I-55 NB	1.00		6.93					
		June 2, 2022	126	WO20-2 AHEAD	48x48 1	6.00 DETC	UR	61.540	Rte 62 EB	1.00		16					



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

	Line Number		Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items		Special Sign	SF Each Special Sign	rotal SF to P
	0170	June 2, 2022	126	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		61.912	Rte 62 EB	1.00	16			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		61.988	Rte 62 EB	1.00	16			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		62.087	Rte 62 EB	1.00	16			
				R11-2 48x30 10.00 ROAD CLOSED		62.281	Rte 62 at I-55 NB Ramp	3.00	10			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		62.676	Rte 62 WB	1.00	16			
				WO20-2 48x48 16.00 DETOUR AHEAD		62.909	Rte 62 WB	1.00	16			
			249	special ??x?? ??.00 NO PASSING ZONE		0.149	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		69.377	Rt HH at I-55 NB On Ramp	1.00		I-55 North Detour Signage 50C	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		62.391	Rte 62 WB	1.00		I-55 North Detour Signage 50B	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		61.988	Rte 62 WB	1.00		I-55 North Detour Signage 50A	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		1.070	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		61.789	Rte 62 EB	1.00		I-55 North Detour Signage 50E	27.69	2
				special ??x?? ??.00 NO PASSING		1.847	Rt H NB	1.00		I-55 North Detour Signage 50A	27.69	2
				ZONE special ??x?? ??.00 NO PASSING		1.699	Rt H NB	1.00		I-55 North Detour Signage 50D	27.69	2
				ZONE special ??x?? ??.00 NO PASSING		61.854	Rte 62 EB	1.00		I-55 North Detour Signage 50C	27.69	2
			488	ZONE EO5-1 36x48 12.00 GORE EXIT		67.173	I-55 NB to Rte 62 Ramp	1.00	12			
				special ??x?? ??.00 NO PASSING ZONE		67.015	I-55 NB	2.00		Ramp Exit 500 FT Sign 61	16.00	
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		66.991	I-55 NB	2.00	12.5			
				R11-2 48x30 10.00 ROAD CLOSED		66.991	I-55 NB	1.00	10			
				WO13-1 30x30 6.25 ADVISORY SPEED (PLAQUE)		66.804	I-55 NB	1.00	6.25			
				WO1-4L 48x48 16.00 REVERSE CURVE (SYMBOL LEFT ARROW)		66.804	I-55 NB	1.00	16			
				GO20-2 48x24 8.00 END ROAD WORK		65.730	I-55 SB	2.00	8			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		64.654	I-55 NB	2.00	12			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		64.552	I-55 NB	2.00	10			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		64.454	I-55 NB	1.00	18			
				R11-2 48x30 10.00 ROAD CLOSED		67.253	I-55 NB	1.00	10			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		70.251	I-55 SB	1.00	18			
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		67.253	I-55 NB	2.00	12.5			
				R11-2 48x30 10.00 ROAD CLOSED		67.289	I-55 NB	2.00	10			
				R4-1 36x48 12.00 DO NOT PASS		67.429	I-55 NB	1.00	12			
				WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.429	I-55 SB	1.00	16			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		67.429	I-55 NB	1.00	6			
				R4-1 36x48 12.00 DO NOT PASS WO6-3 48x48 16.00 TWO WAY		67.647 67.647	I-55 NB I-55 SB	1.00	12 16			
				TRAFFIC (SYMBOL) GO20-5aP 36x24 6.00 WORK ZONE			1-55 NB	1.00	6			
				(PLAQUE)								
				WO1-4R 48x48 16.00 REVERSE CURVE (SYMBOL RIGHT ARROW)		67.800	1-55 NB	1.00	16			
				WO13-1 30x30 6.25 ADVISORY SPEED (PLAQUE)		67.800	1-55 NB	1.00	6.25			
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		67.887	1-55 NB	2.00	12.5			
				R5-1 30x30 6.25 DO NOT ENTER WO6-3 48x48 16.00 TWO WAY		67.890 67.890	I-55 NB I-55 SB	2.00 2.00	6.25 16			
				TRAFFIC (SYMBOL) WO20-1 48x48 16.00		69.286	Rt HH Ramp to I-55 SB	1.00	16			
				ROAD/BRIDGE/RAMP WORK AHEAD CONST-8 48x36 12.00 WORK		69.825	I-55 SB	2.00	12			
				ZONE NO PHONE ZONE GO20-1 60x24 10.00 ROAD WORK		70.031	1-55 SB	2.00	10			
		June 13, 2022	24	NEXT XX MILES R2-1 36x48 12.00 SPEED LIMIT		62.117	Rt 62 EB	1.00	12			
		JULIE 13, 2022	27	xx								
	0170 - Total			R2-1 36x48 12.00 SPEED LIMIT XX		62.428	Rt 62 WB	1.00	12			



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
913643	0050	MISC.	Material		4	May 16, 2022	SYSTEM	\$118,523.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$118,523.17)	
					5	Jun 2, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$148,153.96)	
					6	Jun 16, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$148,153.96)	
					7	Jul 1, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$148,153.96)	
					8	Jul 19, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$148,153.96)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0050 -	Total						\$0.00	
	0060	CONCRETE PAVEMENT (10 1/2 IN. NON- REINF,			11	Sep 2, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		iteliti,			11	Sep 2, 2022	SYSTEM	(\$55,765.00)	
					12	Sep 16, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12		SYSTEM	\$55,765.00 (\$55,765.00)	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
						2022 Sep 16,			Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
					12	2022 Sep 16, 2022 Sep 30,	SYSTEM	(\$55,765.00)	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
					12	2022 Sep 16, 2022 Sep 30, 2022 Sep 30,	SYSTEM SYSTEM	(\$55,765.00) \$55,765.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12 13 13	2022 Sep 16, 2022 Sep 30, 2022 Sep 30, 2022 Oct 17,	SYSTEM SYSTEM SYSTEM	(\$55,765.00) \$55,765.00 (\$55,765.00)	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
					12 13 13 14	2022 Sep 16, 2022 Sep 30, 2022 Sep 30, 2022 Oct 17, 2022 Oct 17,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$55,765.00) \$55,765.00 (\$55,765.00) \$55,765.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
					12 13 13 14 14	2022 Sep 16, 2022 Sep 30, 2022 Oct 17, 2022 Oct 17, 2022 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$55,765.00) \$55,765.00 (\$55,765.00) \$55,765.00 (\$55,765.00)	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
				- Total	12 13 13 14 14 15	2022 Sep 16, 2022 Sep 30, 2022 Sep 30, 2022 Oct 17, 2022 Oct 17, 2022 Nov 2, Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$55,765.00) \$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00)	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
			Material - To		12 13 13 14 14 15	2022 Sep 16, 2022 Sep 30, 2022 Sep 30, 2022 Oct 17, 2022 Oct 17, 2022 Nov 2, Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$55,765.00) \$55,765.00 (\$55,765.00) \$55,765.00 (\$55,765.00) \$55,765.00 (\$55,765.00) \$0.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
	0060 -				12 13 13 14 14 15 15	2022 Sep 16, 2022 Sep 30, 2022 Sep 30, 2022 Oct 17, 2022 Oct 17, 2022 Nov 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$55,765.00) \$55,765.00 (\$55,765.00) \$55,765.00 (\$55,765.00) \$55,765.00 (\$55,765.00) (\$55,765.00) \$0.00 \$0.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
	0060 - 0070	Total CONCRETE APPROACH PAVEMENT			12 13 13 14 14 15 15 11	2022 Sep 16, 2022 Sep 30, 2022 Oct 17, 2022 Oct 17, 2022 Nov 2, 2022 Nov 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$55,765.00) \$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00) \$0.00 \$0.00 \$0.00 \$21,252.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
		CONCRETE APPROACH			12 13 13 14 14 15 15	2022 Sep 16, 2022 Sep 30, 2022 Oct 17, 2022 Oct 17, 2022 Nov 2, 2022 Nov 2, 2022 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$55,765.00) \$55,765.00 (\$55,765.00) \$55,765.00 (\$55,765.00) \$55,765.00 (\$55,765.00) (\$55,765.00) \$0.00 \$0.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		CONCRETE APPROACH			12 13 13 14 14 15 15 11	2022 Sep 16, 2022 Sep 30, 2022 Oct 17, 2022 Oct 17, 2022 Nov 2, 2022 Nov 2, 2022 Sep 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$55,765.00) \$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00) (\$55,765.00) \$0.00 \$0.00 \$0.00 \$21,252.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
913643	0070	CONCRETE APPROACH PAVEMENT	Material		13	Sep 30, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					13	Sep 30, 2022	SYSTEM	(\$21,252.00)		
						Oct 17, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					14	Oct 17, 2022	SYSTEM	(\$21,252.00)		
					15	Nov 2, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					15	Nov 2, 2022	SYSTEM	(\$21,252.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0070 -	Total						\$0.00		
	0080	CONCRETE CURB (6 IN. HEIGHT AND	Material		12	Sep 16, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
		UNDER)	UNDER)			12	Sep 16, 2022	SYSTEM	(\$3,500.00)	
					13	Sep 30, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
						13	Sep 30, 2022	SYSTEM	(\$3,500.00)	
					14	Oct 17, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					14	Oct 17, 2022	SYSTEM	(\$3,500.00)		
					15	Nov 2, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					15	Nov 2, 2022	SYSTEM	(\$3,500.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0080 -	Total						\$0.00		
	0110	FURNISHING TYPE 2 ROCK BLANKET	Material		14	Oct 17, 2022	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					14	Oct 17, 2022	SYSTEM	(\$17,000.00)		
					15	Nov 2, 2022	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					15	Nov 2, 2022	SYSTEM	(\$17,000.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0110 -	Total						\$0.00		
	0130	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	Material		5	Jun 2, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					5	Jun 2, 2022	SYSTEM	(\$4,000.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0130 -	Total						\$0.00		
	0160	TRUCK OR TRAILER	Material		13	Sep 30, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0160	MOUNTED ATTEN	Material						Estimate Exception 15 on the current Payment Estimate.
		(TMA)			13	Sep 30, 2022	SYSTEM	(\$5,000.00)	
					14	Oct 17, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$5,000.00)	
					15	Nov 2, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$5,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0160 -	Total						\$0.00	
	0180	ADVANCED WARNING RAIL SYSTEM	Material		2	Apr 15, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$100.00)	
					3	May 2, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$100.00)	
					4	May 16, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$100.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0180 -	Total						\$0.00	
	0190	CHANNELIZER (TRIM LINE)			2	Apr 15, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$2,244.00)	
					3	May 2, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$2,244.00)	
					4	May 16, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$2,244.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0190 -	Total						\$0.00	
	0210	DIRECTIONAL INDICATOR BARRICADE	Material		2	Apr 15, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$2,340.00)	
					3	May 2, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$2,340.00)	



Nov 4, 2022

ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
8643	0210	DIRECTIONAL	Material						Estimate Exception 4 on the current Payment Estimate.
		INDICATOR BARRICADE			4	May 16, 2022	SYSTEM	(\$2,340.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0210 -	Total						\$0.00	
	0220	FLASHING ARROW PANEL	Material		2	Apr 15, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$3,000.00)	
					3	May 2, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$3,000.00)	
					4	May 16, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$3,000.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0220 -	Total						\$0.00	
	0250	CMS W/O COMMUNICATION INTERFACE, CONT F/	E,		2	Apr 15, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$9,600.00)	
					3	May 2, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$9,600.00)	
					4	May 16, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$9,600.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0250 -	Total						\$0.00	
	0270	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		5	Jun 2, 2022	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		FURIWRE			5	Jun 2, 2022	SYSTEM	(\$11,000.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0270 -	Total						\$0.00	
	0310	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	Material		6	Jun 16, 2022	SYSTEM	\$2,706.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		IIN.,			6	Jun 16, 2022	SYSTEM	(\$2,706.00)	
					7	Jul 1, 2022	SYSTEM	\$4,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$4,462.00)	
					8	Jul 19, 2022	SYSTEM	\$4,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.



Nov 4, 2022

ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks									
643	0310	TEMPORARY	Material	Туре	8	Jul 19,	SYSTEM	(\$4,462.00)										
		REMOVABLE MARKING TAPE 4				2022		(, , , , , , , , , , , , , , , , , , ,										
		IN.,		- Total				\$0.00 \$0.00										
	0040	Material - Total 0310 - Total																
					0	1 10	OVOTEN	\$0.00										
	0320	TEMPORARY REMOVABLE MARKING TAPE	Material		6	Jun 16, 2022	SYSTEM	\$7,416.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.									
					6	Jun 16, 2022	SYSTEM	(\$7,416.00)										
					7	Jul 1, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.									
					7	Jul 1, 2022	SYSTEM	(\$12,180.00)										
					8	Jul 19, 2022	SYSTEM	\$12,180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.									
					8	Jul 19, 2022	SYSTEM	(\$12,180.00)										
				- Total				\$0.00										
			Material - To	Total				\$0.00										
	0320 -							\$0.00										
	0390	TEMPORARY PAVEMENT MARKING	VEMENT		6	Jun 16, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.									
					6	Jun 16, 2022	SYSTEM	(\$6,062.25)										
					7	Jul 1, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.									
														7	Jul 1, 2022	SYSTEM	(\$6,062.25)	
					8	Jul 19, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.									
					8	Jul 19, 2022	SYSTEM	(\$6,062.25)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	0390 -	Total						\$0.00										
	0450	MGS GUARDRAIL	Material		12	Sep 16, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.									
							12	Sep 16, 2022	SYSTEM	(\$8,000.00)								
							13	Sep 30, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.							
					13	Sep 30, 2022	SYSTEM	(\$8,000.00)										
					14	Oct 17, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					14	Oct 17, 2022	SYSTEM	(\$8,000.00)										
					15	Nov 2, 2022	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					15	Nov 2, 2022	SYSTEM	(\$8,800.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
			material - 10	tai				\$0.00										



Image: Constraint of the second of	dding Payment al Payment dding Payment al Payment
APP. TRANS SEC (EXT CURB) APP. TRANS SEC (EXT CURB) 2022 Sep 16, 2022 SYSTEM (\$12,000.00) 12 Sep 30, 2022 SYSTEM (\$12,000.00) This adjustment offsets the original system-generated Materia Estimate ltem Adjustment (0006) due to user woodsk1 overri Estimate ltem Adjustment (0006) due to user woodsk1 overri Estimate ltem Adjustment (0007) due to user woodsk1 overri Estimate ltem Adjustment (0007) due to user woodsk1 overri Estimate Exception 13 on the current Payment Estimate. 13 Sep 30, 2022 SYSTEM (\$12,000.00) 14 Oct 17, 2022 SYSTEM \$12,000.00 14 Oct 17, 2022 SYSTEM (\$12,000.00) 15 Nov 2, 2022 SYSTEM \$12,000.00 15 Nov 2, 2022 SYSTEM \$12,000.00	dding Payment al Payment dding Payment al Payment
13 Sep 30, 2022 SYSTEM \$12,000.00 This adjustment offsets the original system-generated Materiestimate Exception 13 on the current Payment Estimate. 13 Sep 30, 2022 SYSTEM \$12,000.00 This adjustment (0006) due to user woodsk1 overriestimate. 13 Sep 30, 2022 SYSTEM \$12,000.00 This adjustment offsets the original system-generated Materiestimate. 14 Oct 17, 2022 SYSTEM \$12,000.00 This adjustment (0007) due to user woodsk1 overriestimate. 14 Oct 17, 2022 SYSTEM \$12,000.00 This adjustment (0007) due to user woodsk1 overriestimate. 14 Oct 17, 2022 SYSTEM \$12,000.00 This adjustment (0007) due to user woodsk1 overriestimate. 15 Nov 2, 2022 SYSTEM \$12,000.00 This adjustment (0008) due to user woodsk1 overriestimate.	dding Payment
2022 2022 Estimate Item Adjustment (0006) due to user woodsk1 overri 13 Sep 30, 2022 SYSTEM (\$12,000.00) 14 Oct 17, 2022 SYSTEM \$12,000.00 14 Oct 17, 2022 SYSTEM \$12,000.00 14 Oct 17, 2022 SYSTEM \$12,000.00 15 Nov 2, 2022 SYSTEM \$12,000.00 15 Nov 2, SYSTEM \$12,000.00 This adjustment (0008) due to user woodsk1 overri 15 Nov 2, SYSTEM \$12,000.00 This adjustment (0008) due to user woodsk1 overri	dding Payment
14 Oct 17, 2022 SYSTEM \$12,000.00 This adjustment offsets the original system-generated Materi Estimate Item Adjustment (0007) due to user woodsk1 overri Estimate Exception 13 on the current Payment Estimate. 14 Oct 17, 2022 SYSTEM \$12,000.00 This adjustment (0007) due to user woodsk1 overri Estimate Exception 13 on the current Payment Estimate. 14 Oct 17, 2022 SYSTEM (\$12,000.00) This adjustment offsets the original system-generated Materi Estimate. 15 Nov 2, 2022 SYSTEM \$12,000.00 This adjustment (0008) due to user woodsk1 overri Estimate. 15 Nov 2, SYSTEM (\$12,000.00) State Exception 13 on the current Payment Estimate.	
2022 2022 Estimate Item Adjustment (0007) due to user woodsk1 overri 14 Oct 17, 2022 SYSTEM (\$12,000.00) 15 Nov 2, 2022 SYSTEM \$12,000.00 15 Nov 2, SYSTEM \$12,000.00 This adjustment (0008) due to user woodsk1 overri 15 Nov 2, SYSTEM \$12,000.00 Stimate Exception 13 on the current Payment Estimate.	
2022 2022 2022 15 Nov 2, 2022 SYSTEM \$12,000.00 This adjustment offsets the original system-generated Materi Estimate Item Adjustment (0008) due to user woodsk1 overri Estimate Exception 13 on the current Payment Estimate. 15 Nov 2, 15 SYSTEM (\$12,000.00)	
15 Nov 2, 2022 SYSTEM \$12,000.00 This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0008) due to user woodsk1 over in Estimate Exception 13 on the current Payment Estimate. 15 Nov 2, SYSTEM (\$12,000.00)	
15 Nov 2, SYSTEM (\$12,000.00)	
- Total \$0.00	
Material - Total \$0.00	
0460 - Total \$0.00	
0490 BRIDGE Material APPROACH SLAB (MAJOR ROAD) 11 Sep 2, 2022 SYSTEM 2022 SYSTEM 2022 State the original system-generated Material 2022 System 2022 System 2022 System 2020 S	
11 Sep 2, 2022 SYSTEM (\$78,020.00)	
12 Sep 16, 2022 SYSTEM \$78,020.00 This adjustment offsets the original system-generated Materi Estimate Item Adjustment (0006) due to user woodsk1 overni Estimate Exception 4 on the current Payment Estimate.	
12 Sep 16, SYSTEM (\$78,020.00) 2022	
13 Sep 30, 2022 SYSTEM \$78,020.00 This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0007) due to user woodsk1 overria Estimate Exception 4 on the current Payment Estimate.	
13 Sep 30, SYSTEM (\$78,020.00) 2022	
14 Oct 17, 2022 SYSTEM \$78,020.00 This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0008) due to user woodsk1 overria Estimate Exception 4 on the current Payment Estimate.	
14 Oct 17, 2022 SYSTEM (\$78,020.00)	
15 Nov 2, 2022 SYSTEM \$78,020.00 This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0009) due to user woodsk1 overring Estimate Item Adjustment (0009) due to user woodsk1 overring	
15 Nov 2, 2022 SYSTEM (\$78,020.00)	
- Total \$0.00	
Material - Total \$0.00	
0490 - Total \$0.00	
0500SLAB ON STEELMaterial10Aug 17, 2022SYSTEM\$710,325.00This adjustment offsets the original system-generated Materi Estimate Item Adjustment (0001) due to user woodsk1 overri Estimate Exception 2 on the current Payment Estimate.	
10 Aug 17, SYSTEM (\$710,325.00)	
11Sep 2, 2022SYSTEM\$710,325.00This adjustment offsets the original system-generated Materi Estimate Item Adjustment (0004) due to user woodsk1 overri Estimate Exception 13 on the current Payment Estimate.	
11 Sep 2, 2022 SYSTEM (\$710,325.00)	
12 Sep 16, SYSTEM \$710,325.00 This adjustment offsets the original system-generated Materia	
2022 Sep 10, STSTEM 2710,325.00 This adjustment onsets the original system-generated watern Estimate term Adjustment (0007) due to user woodsk1 overri Estimate Exception 16 on the current Payment Estimate.	aanig raymoni



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3643	0500	SLAB ON STEEL	Material		13	Sep 30, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$710,325.00)	
					14	Oct 17, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$710,325.00)	
					15	Nov 2, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$710,325.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0500 -	Total						\$0.00	
	0510	TYPE D BARRIER	Material		12	Sep 16, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$64,170.00)	
					13	Sep 30, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$64,170.00)	
					14	Oct 17, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$64,170.00)	
					15	Nov 2, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$64,170.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0510 -	Total		_				\$0.00	
	0540	SLAB DRAIN	Material		9	Aug 2, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 2, 2022	SYSTEM	(\$9,000.00)	
					10	Aug 17, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Aug 17, 2022	SYSTEM	(\$9,000.00)	
					11	Sep 2, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment
									Estimate Exception 16 on the current Payment Estimate.
					11	Sep 2, 2022	SYSTEM	(\$9,000.00)	Estimate Exception 16 on the current Payment Estimate.
				- Total	11		SYSTEM	(\$9,000.00) \$0.00	Estimate Exception 16 on the current Payment Estimate.
			Material - To		11		SYSTEM		Estimate Exception 16 on the current Payment Estimate.
	0540 -	Total	Material - To		11		SYSTEM	\$0.00	Estimate Exception 16 on the current Payment Estimate.
	0540 - 0630	Total SLAB ON STEEL	Construction Stockpile		11		SYSTEM	\$0.00 \$0.00	Estimate Exception 16 on the current Payment Estimate.
			Construction			2022 Nov 2,		\$0.00 \$0.00 \$0.00	
			Construction Stockpile STMI	tal	15	2022 Nov 2, 2022		\$0.00 \$0.00 \$0.00 \$60,113.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	5002	SEQUENTIAL FLASHING WARNING LIGHT	Material		4	May 16, 2022	SYSTEM	\$4,347.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$4,347.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5002 -	Total						\$0.00	
	5003	TEMPORARY SEEDING	Material		5	Jun 2, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$2,830.48)	
					6	Jun 16, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$2,830.48)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5003 -	Total						\$0.00	
J9I3643 -	Total							\$60,113.00	
Overall -	Total							\$60,113.00	