

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 16, 2022

Progress Estimate Number	Contract ID	220121-H01	Pay Period	Start N	lovember '	16, 2022	Original Contract Amount	\$3,635,384.06
17	Prime Contractor	Robertson Contractors, Inc.	Pay Period	I End D	ecember '	15, 2022	Net Change Order Amount	\$90,555.83
17							Current Contract Amount	\$3,725,939.89

Approval Date		By User
December 16, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	woodsk1
December 16, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	bollis1
December 19, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
May 1, 2023	May 1, 2023		70.97%

	Milestones							
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract					
Acceptance Date								
Awarded Date	February 2, 2022	February 2, 2022						
Letting Date	January 21, 2022	January 21, 2022						
Notice to Proceed Date	April 4, 2022	April 4, 2022						
Open to Traffic Date								
Work Began Date	April 11, 2022	April 11, 2022						

Contract Total Pay For Estimate No. 17										
		This Estimate	Previous	To Date						
220121-H01										
	Total Posted Items Pay	\$156,810.00	\$2,487,557.42	\$2,644,367.42						
	Gross Item Adjustments	(\$11,995.95)	\$39,009.03	\$27,013.08						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	·		\$2,526,566.45	\$2,671,380.50						
Contract Total Pa	avable This Estimate:	\$144.814.05								

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount				
J9I3643	0630	7034212	SLAB ON STEEL	SQYD	\$525.000	270	\$141,750.00				
	0670	7123610	SLAB DRAIN	EA	\$450.000	18	\$8,100.00				
	0730	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$80.000	87	\$6,960.00				
Project J9I3643 -	Project J9I3643 - Total										
Overall - Total	Overall - Total										

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3643	0060	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-587	\$95.00	(\$55,765.00)
	0060	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	587	\$95.00	\$55,765.00
	0070	CONCRETE APPROACH PAVEMENT	Material			-202.4	\$105.00	(\$21,252.00)
	0070	CONCRETE APPROACH	Material		This adjustment offsets the original system-	202.4	\$105.00	\$21,252.00

Revision 4/1/2020 Page 1 of 19

Missouri Department of Transportation Contractor's Pay Estimate Summary



Pay Estimate Created Date: December 16, 2022

Progress Estimate Number
17

Contract ID 220121-H01 Pay Period Start November 16, 2022 Original Contract Amount \$3,635,384.06
Prime Contractor Robertson Contractors, Inc. Pay Period End December 15, 2022 Net Change Order Amount \$90,555.83
Current Contract Amount \$3,725,939.89

	_ine No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
13		PAVEMENT		,	generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
0	080	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-175	\$20.00	(\$3,500.00
0	080	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	175	\$20.00	\$3,500.00
0	110	FURNISHING TYPE 2 ROCK BLANKET	Material			-425	\$40.00	(\$17,000.00
0)110	FURNISHING TYPE 2 ROCK BLANKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	425	\$40.00	\$17,000.00
0	160	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material			-1	\$5,000.00	(\$5,000.00
0	160	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1	\$5,000.00	\$5,000.00
	450	MGS GUARDRAIL	Material			-220	\$40.00	(\$8,800.00
)450	MGS GUARDRAIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	220	\$40.00	\$8,800.00
0	460	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Material			-3	\$4,000.00	(\$12,000.00
0)460	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	3	\$4,000.00	\$12,000.00
0	1490	BRIDGE APPROACH SLAB (MAJOR)	Material			-188	\$415.00	(\$78,020.00
0)490	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	188	\$415.00	\$78,020.00
0	500	SLAB ON STEEL	Material			-1,353	\$525.00	(\$710,325.00
050	500	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	1,353	\$525.00	\$710,325.00
0	510	TYPE D BARRIER	Material			-558	\$115.00	(\$64,170.00
0	510	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	558	\$115.00	\$64,170.00

Revision 4/1/2020 Page 2 of 19

(\$11,995.95)



Total

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 16, 2022

Progr		timate Number 17	Contract ID Prime Contr	220121-H01 Pay Period Start November 16, 2022 Original Contract Amount \$3,635,384.06 ctor Robertson Contractors, Inc. Pay Period End December 15, 2022 Net Change Order Amount \$90,555.83 Current Contract Amount \$3,725,939.89							
Project Number	Line No.	Item Description		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount		
J9I3643	0630	SLAB ON STEEL		Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$11,995.95)		
	0630	SLA	B ON STEEL	Material			-745	\$525.00	(\$391,125.00)		
	0630	SLAB ON STEEL		SLAB ON STEEL		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	745	\$525.00	\$391,125.00

Page 3 of 19 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information						
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J9I3643	I 55-1(176)	2 bridge deck replacement	I-55	SCOTT	over Route 62	ver Route 62						
Totals by .	Job Numbe	rs										
J9I3643		d Item Pay Item Adjustm		Item Pay	This Estimate \$156,810.00 (\$11,995.95) \$144,814.05	Previous \$2,487,557.42 \$39,009.03 \$2,526,566.45	To Date \$2,644,367.42 \$27,013.08 \$2,671,380.50					
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 4/1/2020 Page 4 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 4019905, Project Item Line Number 0050, Material Set 401990596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5021334, Project Item Line Number 0060, Material Set 502133496, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5021334, Project Item Line Number 0060, Material Set 502133496, Material 1057JMDAEC6.12 - Dowel Assemblies Epoxy Ctd Gr60 1 1/2" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6061060, Project Item Line Number 0450, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6061068, Project Item Line Number 0460, Material Set 606106896, Material 1040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6091010, Project Item Line Number 0080, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6113020, Project Item Line Number 0110, Material Set 611302096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 6123000A, Project Item Line Number 0160, Material Set 6123000A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0500, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0500, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 7034212, Project Item Line Number 0630, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0630, Material Set 703421296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 7034212, Project Item Line Number 0630, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034219A, Project Item Line Number 0510, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 5 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-H01	J9I3643	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$15,000.00	\$11,250.00
		0001	0020	2071000	LINEAR GRADING CLASS 1	4.40	0.00	4.40	STA	0.00	\$2,600.00	\$0.00
		0001	0030	2072000	LINEAR GRADING CLASS 2	32.40	0.00	32.40	STA	32.40	\$3,850.00	\$124,740.00
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,174.00	0.00	1,174.00	SQYD	587.00	\$15.00	\$8,805.00
		0001	0050	4019905	MISC.Optional Pavement	2,932.00	791.00	3,723.00	SQYD	3,723.00	\$50.53	\$188,123.19
		0001	0060	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	1,173.60	0.00	1,173.60	SQYD	587.00	\$95.00	\$55,765.00
		0001	0070	5041000	CONCRETE APPROACH PAVEMENT	404.80	0.00	404.80	SQYD	202.40	\$105.00	\$21,252.00
		0001	0080	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	349.00	0.00	349.00	LF	175.00	\$20.00	\$3,500.00
		0001	0090	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$45.00	\$0.00
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$80.00	\$0.00
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	425.00	\$40.00	\$17,000.00
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	425.00	\$25.00	\$10,625.00
		0001	0130	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	2.00	1.00	3.00	EA	3.00	\$2,000.00	\$6,000.00
		0001	0140	6122020	REPLACEMENT SAND BARREL	6.00	6.00	12.00	EA	12.00	\$250.00	\$3,000.00
		0001	0150	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	1.00	3.00	EA	3.00	\$1,000.00	\$3,000.00
		0001	0160	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	1.00	\$5,000.00	\$5,000.00
		0001	0170	6161005	CONSTRUCTION SIGNS	2,140.00	0.00	2,140.00	SQFT	1,560.00	\$6.50	\$10,140.00
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	18.00	0.00	18.00	EA	8.00	\$25.00	\$200.00
		0001	0190	6161025	CHANNELIZER (TRIM LINE)	500.00	0.00	500.00	EA	407.00	\$17.00	\$6,919.00
	0001 0200 6161030			6161030	TYPE III MOVEABLE BARRICADE	21.00	0.00	21.00	EA	15.00	\$145.00	\$2,175.00
		0001	0210	6161033	DIRECTIONAL INDICATOR BARRICADE	100.00	0.00	100.00	EA	74.00	\$65.00	\$4,810.00
		0001	0220	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$1,500.00	\$4,500.00
		0001	0230	6161052	WARNING LIGHT, TYPE B	50.00	0.00	50.00	EA	0.00	\$15.00	\$0.00
		0001	0240	6161070	TUBULAR MARKER	650.00	0.00	650.00	EA	370.00	\$35.00	\$12,950.00
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,800.00	\$19,200.00
		0001	0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	16.00	\$800.00	\$12,800.00
		0001	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	451.00	100.00	551.00	LF	551.00	\$40.00	\$22,040.00
		0001 0280 617501			RELOCATING TEMPORARY TRAFFIC BARRIER	451.00	100.00	551.00	LF	551.00	\$35.00	\$19,285.00
		0001	0290	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$225,000.00	\$0.00
		0001	0291	6181000	MOBILIZATION	0.00	1.00	1.00	LS		\$200,165.00	\$200,165.00
		0001	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	10.00	0.00	10.00	EA	0.00	\$250.00	\$0.00
		0001	0310	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,645.00	0.00	3,645.00	LF	3,645.00	\$2.00	\$7,290.00
		0001	0320	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	6,090.00	2,500.00	8,590.00	LF	8,590.00	\$2.00	\$17,180.00
		0001	0330	6205902A	PAINT, TYPE L BEADS	2,705.00	27,660.00	30,365.00	LF	0.00	\$0.30	\$0.00
		0001	0340	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,774.00	19,126.00	20,900.00	LF	0.00	\$0.30	\$0.00
		0001	0350	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	13,177.00	-13,177.00	0.00	LF	0.00	\$0.15	\$0.00
		0001	0360	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,704.00	-6,704.00	0.00	LF	0.00	\$0.15	\$0.00
		0001	0370	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	75.00	-75.00	0.00	LF	0.00	\$5.00	\$0.00
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	50,359.00	0.00	50,359.00	LF	25,180.00	\$0.50	\$12,590.00
		0001	0390	6208063	TEMPORARY PAVEMENT MARKING	34,359.00	0.00	34,359.00	EA	34,359.00	\$0.25	\$8,589.75
		0001	0400	6240102A	TEMPORARY SILT FENCE GEOTEXTILE	1,040.00	0.00	1,040.00	SQYD	0.00	\$1.50	\$0.00
		0001	0410	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,689.00	0.00	1,689.00	SQYD	0.00	\$4.00	\$0.00
		0001	0420	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.00
		0001	0430	7250312A	12 IN. PIPE GROUP B	1,100.00	0.00	1,100.00	LF	1,100.00	\$50.00	\$55,000.00

Page 6 of 19 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-H01	J9I3643	0001	0440	8061016	SEDIMENT REMOVAL	10.00	0.00	10.00	CUYD	3.00	\$1.00	\$3.00
		0010	0450	6061060	MGS GUARDRAIL	100.00	315.00	415.00	LF	220.00	\$40.00	\$8,800.00
		0010	0460	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	6.00	0.00	6.00	EA	3.00	\$4,000.00	\$12,000.00
		0010	0470	6069901	MISC.Remove and Reinstall High-Tension Gurad Cable	1.00	0.00	1.00	LS	0.50	\$55,000.00	\$27,500.00
		0070	0480	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	11,771.00	\$14.00	\$164,794.00
		0070	0490	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	188.00	\$415.00	\$78,020.00
		0070	0500	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	1,353.00	\$525.00	\$710,325.00
		0070	0510	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	558.00	\$115.00	\$64,170.00
		0070	0520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0070	0530	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	1,800.00	\$15.50	\$27,900.00
		0070	0540	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	20.00	\$450.00	\$9,000.00
		0070	0550	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0070	0560	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0070	0570	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0070	0580	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0070	0590	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	109.00	\$45.00	\$4,905.00
		0070	0600	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	87.00	\$80.00	\$6,960.00
		0071	0610	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	11,771.00	\$14.00	\$164,794.00
		0071	0620	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	0.00	\$415.00	\$0.00
		0071	0630	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	745.00	\$525.00	\$391,125.00
		0071	0640	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	0.00	\$115.00	\$0.00
		0071	0650	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0071	0660	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	1,800.00	\$15.50	\$27,900.00
		0071	0670	7123610	SLAB DRAIN	18.00	0.00	18.00	EA	18.00	\$450.00	\$8,100.00
		0071	0680	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0071	0690	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0071	0700	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0071	0710	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0071	0720	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	109.00	\$45.00	\$4,905.00
		0071	0730	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	87.00	\$80.00	\$6,960.00
		0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$24,835.00	\$24,835.00
		0001	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	36.00	36.00	EA	36.00	\$120.75	\$4,347.00
		0001	5003	8061017	TEMPORARY SEEDING	0.00	1.00	1.00	ACRE	0.50	\$5,660.95	\$2,830.48
		0001	5004	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	0.00	6.00	6.00	EA	6.00	\$50.00	\$300.00
					late as of Report Generated Date							\$2,644,367.42
220121-H01 Ove	rall - Tota	I Value Pos	ted to Da	ate as of Rep	ort Generated Date							\$2,644,367.42

Page 7 of 19 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J9I3643

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0630	7034212	SLAB ON STEEL	12/15/22	12/15/22	270.00	SQYD	Southbound Bridge Phase II. Approximate Bridge Deck Estimated Percentage Per Guideline.	1360		1367		Southbound Bridge Phase II. Approximate Bridge Deck Estimated Percentage Per Guideline.
0670	7123610	SLAB DRAIN	12/15/22	12/15/22	18.00	EA	Southbound Bridge Phase II. Approximate Bridge Deck Estimated Percentage Per Guideline.	1360		1367		Southbound Bridge Phase II. Approximate Bridge Deck Estimated Percentage Per Guideline.
0730	7172054	OPEN CELL FOAM JOINT SEAL	12/15/22	12/15/22	87.00	LF	Southbound Bridge Phase II. Approximate Bridge Deck Estimated Percentage Per Guideline.	1360		1367		Southbound Bridge Phase II. Approximate Bridge Deck Estimated Percentage Per Guideline.

									ge Per Guideline.				ercentage Per Guideline.	
0730	7172054	OPEN CELL FOAM	IJOINT SEAL	12/15/22 12/15/22	87.00	LF	Estimate	und Bridge d Percenta	Phase II. Approximate Bridge ge Per Guideline.	e Deck 1360		1367 Southbound Estimated P	Bridge Phase II. Approxima ercentage Per Guideline.	e Bridge Deck
			re details for Construction Signature Total Quantity Posted For DWR Date				Ct-ti	1 143-	Location	Niverbas of Hanna	CE Eh Ci	n Special Sign	OF Freeh Constitution	T-4-1 0F 4- D-
Project 913643	Line Number 0170	April 11, 2022		Sign Info WO20-1 48x48 1	6.00		Station	Log Mile 65.227	NB	Number of Items 2.00	16	n Special Sign	SF Each Special Sign	Total SF to Po
				ROAD/BRIDGE/RAN	IP WORK									
				CONST-3A 60x48 CONST-3X 56x12		E SIGN		65.501 65.501	NB NB	2.00	20 4.67			9.:
				SPEEDING/PASSING	G (PLATE)				NO.					
				GO20-5aP 36x24 (PLAQUE)	6.00 WOF	RK ZONE		65.713	NB	2.00	6			
				R4-1 36x48 12.0	00 DO NO	T PASS		65.713	NB	2.00	12			
				WO20-5 48x48 1 RIGHT/CENTER/LEF AHEAD		CLOSED		65.976	NB	2.00	16			
				WO4-1aR 48x48 (ARROW SYMBOL)	16.00 MEF	RGE		66.107	NB	1.00	16			
				WO20-6a 48x48 1 RIGHT/CENTER/LEF		CLOSED		66.107	NB	1.00	16			
				GO20-5aP 36x24				66.489	NB	2.00	6			
				(PLAQUE) R2-1 36x48 12.0	nn Speen	LIMIT		66.489	NB	2.00	12			
				XX 30.40 12.0	JO OI LLD	LIIVIII		00.403	NO	2.00	12			
				R2-1 36x48 12.0 XX	00 SPEED	LIMIT		66.491	SB	2.00	12			
				R2-1 36x48 12.0 XX	00 SPEED	LIMIT		68.153	NB	2.00	12			
				GO20-5aP 36x24 (PLAQUE)	6.00 WOF	RK ZONE		68.396	SB	2.00	6			
				R2-1 36x48 12.0	00 SPEED	LIMIT		68.396	SB	2.00	12			
				WO4-1aR 48x48	16.00 MEF	RGE		68.598	SB	1.00	16			
				(ARROW SYMBOL) WO20-6a 48x48 1	16 00			68.598	SB	1.00	16			
				RIGHT/CENTER/LEF	T LANE C	CLOSED								
				WO20-5 48x48 1 RIGHT/CENTER/LEF AHEAD	6.00 FT LANE C	CLOSED		68.796	SB	2.00	16			
				GO20-5aP 36x24 (PLAQUE)	6.00 WOF	RK ZONE		68.997	SB	2.00	6			
				R2-1 36x48 12.0	00 SPEED	LIMIT		68.997	SB	2.00	12			
				CONST-3A 60x48	20.00 FIN	E SIGN		69.213	SB	2.00	20			
				CONST-3X 56x12 SPEEDING/PASSING)		69.213	SB	2.00	4.67			9
				WO20-1 48x48 1 ROAD/BRIDGE/RAN	6.00			69.403	SB	2.00	16			
				R2-1 36x48 12.0	00 SPEED	LIMIT			62 to 55 SB Ramp	1.00	12			
				R4-1 36x48 12.0	00 DO NO	T PASS			57 NB to 55 NB Ramp	1.00	12			
				R4-1 36x48 12.0	00 DO NO	T PASS			57 SB to 55 NB Ramp	1.00	12			
				WO20-1 48x48 1 ROAD/BRIDGE/RAN	6.00 IP WORK	AHFAD			57 NB to 55 NB Ramp	1.00	16			
				WO20-1 48x48 1 ROAD/BRIDGE/RAM	6.00				57 SB to 55 NB Ramp	1.00	16			
				WO20-1 48x48 1 ROAD/BRIDGE/RAM		AUEAD			62 to 55 SB Ramp	1.00	16			
				WO20-5 48x48 1		AHEAD			57 NB to 55 NB Ramp	1.00	16			
				RIGHT/CENTER/LEF AHEAD	T LANE C	CLOSED								
				WO20-5 48x48 1/ RIGHT/CENTER/LEF AHEAD	6.00 FT LANE C	CLOSED			57 SB to 55 NB Ramp	1.00	16			
				CONST-3A 60x48					57 NB to 55 NB Ramp	1.00	20			
				CONST-3A 60x48		E SIGN			57 SB to 55 NB Ramp	1.00	20			
				CONST-3X 56x12 SPEEDING/PASSING)			57 NB to 55 NB Ramp	1.00	4.67			4
				CONST-3X 56x12 SPEEDING/PASSING	4.67 G (PLATE))			57 SB to 55 NB Ramp	1.00	4.67			4
				GO20-5aP 36x24 (PLAQUE)					57 NB to 55 NB Ramp	1.00	6			
				GO20-5aP 36x24 (PLAQUE)	6.00 WOF	RK ZONE			57 SB to 55 NB Ramp	1.00	6			
				GO20-5aP 36x24 (PLAQUE)	6.00 WOF	RK ZONE			62 to 55 SB Ramp	1.00	6			
		April 19, 2022	7	(PLAQUE) R1-2 48 TRI 6.9	3 YIELD			67.450	US 62 Ramp to I-55 NB	1.00	6.93			6
			126	WO20-2 48x48 1		OUR		61.540	Rte 62 EB	1.00	16			
				AHEAD WO20-1 48x48 1	6 00			61.912	Rte 62 EB	1.00	16			
				ROAD/BRIDGE/RAN	IP WORK	AHEAD								
				WO20-5 48x48 1 RIGHT/CENTER/LEF AHEAD		CLOSED		61.988	Rte 62 EB	1.00	16			
				WO20-6a 48x48 1 RIGHT/CENTER/LER	16.00 FT LANE C	CLOSED		62.087	Rte 62 EB	1.00	16			
				R11-2 48x30 10. CLOSED	00 ROAD			62.281	Rte 62 at I-55 NB Ramp	3.00	10			
				WO20-1 48x48 1 ROAD/BRIDGE/RAN	6.00 IP WORK	AHEAD		62.676	Rte 62 WB	1.00	16			

Revision 4/1/2020 Page 8 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail. location and quantity of work. The information below this line are details for Construction Signs (if applicable).

	ine Number		Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items		Special Sign	SF Each Special Sign	Total SF to F
0	170	June 2, 2022	126	WO20-2 48x48 16.00 DETOUR AHEAD		62.909	Rte 62 WB	1.00	16			
			249	special ??x?? ??.00 NO PASSING ZONE		0.149	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		69.377	Rt HH at I-55 NB On Ramp	1.00		I-55 North Detour Signage 50C	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		62.391	Rte 62 WB	1.00		I-55 North Detour Signage 50B	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		61.988	Rte 62 WB	1.00		I-55 North Detour Signage 50A	27.69	2
				special ??x?? ??.00 NO PASSING		1.070	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	2
				Special ??x?? ??.00 NO PASSING		61.789	Rte 62 EB	1.00		I-55 North Detour Signage 50E	27.69	2
				ZONE special ??x?? ??.00 NO PASSING		1.847	Rt H NB	1.00		I-55 North Detour Signage 50A	27.69	
				ZONE special ??x?? ??.00 NO PASSING		1.699	Rt H NB	1.00		I-55 North Detour Signage 50D	27.69	
				ZONE special ??x?? ??.00 NO PASSING		61.854	Rte 62 EB	1.00		I-55 North Detour Signage 50C		
			488	ZONE EO5-1 36x48 12.00 GORE EXIT		67.173	I-55 NB to Rte 62 Ramp	1.00	12	0 0		
				special ??x?? ??.00 NO PASSING ZONE		67.015	I-55 NB	2.00	12	Ramp Exit 500 FT Sign 61	16.00	
				WO1-6 60x30 12.50 HORIZONTAL		66.991	I-55 NB	2.00	12.5			
				ARROW (SYMBOL) R11-2 48x30 10.00 ROAD		66.991	I-55 NB	1.00	10			
				WO13-1 30x30 6.25 ADVISORY		66.804	I-55 NB	1.00	6.25			
				SPEED (PLAQUE) WO1-4L 48x48 16.00 REVERSE		66.804	I-55 NB	1.00	16			
				CURVE (SYMBOL LEFT ARROW)								
				GO20-2 48x24 8.00 END ROAD WORK		65.730	I-55 SB	2.00	8			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		64.654	I-55 NB	2.00	12			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		64.552	I-55 NB	2.00	10			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		64.454	I-55 NB	1.00	18			
				R11-2 48x30 10.00 ROAD CLOSED		67.253	I-55 NB	1.00	10			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		70.251	I-55 SB	1.00	18			
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		67.253	I-55 NB	2.00	12.5			
				R11-2 48x30 10.00 ROAD CLOSED		67.289	I-55 NB	2.00	10			
				R4-1 36x48 12.00 DO NOT PASS		67.429	I-55 NB	1.00	12			
				WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.429	I-55 SB	1.00	16			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		67.429	I-55 NB	1.00	6			
				R4-1 36x48 12.00 DO NOT PASS		67.647	I-55 NB	1.00	12			
				WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.647	I-55 SB	1.00	16			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		67.647	I-55 NB	1.00	6			
				WO1-4R 48x48 16.00 REVERSE CURVE (SYMBOL RIGHT ARROW)		67.800	I-55 NB	1.00	16			
				WO13-1 30x30 6.25 ADVISORY SPEED (PLAQUE)		67.800	I-55 NB	1.00	6.25			
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		67.887	I-55 NB	2.00	12.5			
				R5-1 30x30 6.25 DO NOT ENTER		67.890	I-55 NB	2.00	6.25			
				WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.890	I-55 SB	2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		69.286	Rt HH Ramp to I-55 SB	1.00	16			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		69.825	I-55 SB	2.00	12			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		70.031	I-55 SB	2.00	10			
		June 13, 2022	24	R2-1 36x48 12.00 SPEED LIMIT XX		62.117	Rt 62 EB	1.00	12			
				R2-1 36x48 12.00 SPEED LIMIT		62.428	Rt 62 WB	1.00	12			
	170 - Total			XX								15

Revision 4/1/2020 Page 9 of 19



May 16, SYSTEM 1416,3523 SYSTEM 1416,3523 This adjustment offsets the original system-generated Material Payment Edinate Exception 1 on the current Payment Edinate Exception 2 on the curr	ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2022 SYSTEM S148,153.96 This adjustment offices the original system-generated Material Payment Editarials from Adjustment (2014) see to user four coverriding Payment Editarials from Adjustment (2014) see to user four coverriding Payment Editarials from Adjustment (2014) see to user four coverriding Payment Editarials from Adjustment (2014) see to user four coverriding Payment Editarials from Adjustment (2014) see to user four coverriding Payment Editarials from Adjustment (2014) see to user four coverriding Payment Editarials from Adjustment (2014) see to user four coverriding Payment Editarials from Adjustment (2014) see to user four coverriding Payment Editarials from Adjustment (2014) see to user four coverriding Payment Editarials from Adjustment (2014) see to user four coverriding Payment Editarials from Adjustment (2014) see to user four coverriding Payment Editarials (2014) see to user seconds of coverriding Payment Editarials (2014) see to user seconds of coverriding Payment Editarials (2014) see to user seconds of coverriding Payment Editarials (2014) see to user seconds of coverriding Payment Editarials (2014) see to user seconds of coverriding Payment Editarials (2014) see to user seconds of coverriding Payment Editarials (2014) see to user seconds of coverriding Payment Editarials (2014) see to user seconds of coverriding Payment Editarials (2014) see to user seconds of coverriding Payment Editarials (2014) see to user seconds of coverriding Payment Editarials (2014) see to user seconds of coverriding Payment Editarials (2014) see to user seconds of coverridin	3643	0050	MISC.	Material		4		SYSTEM	\$118,523.17	Estimate Item Adjustment (0001) due to user leez1 overridding Payment
2022 SySTEM (\$148,153.96) This adjustment (\$00.91) also be user level overridding Payment Estimate Exception 1 on the current Payment Estimate Payment Payment Estimate Payment Payment Payment Estimate Payment Payment Payment Estimate Payment Paym						4		SYSTEM	(\$118,523.17)	
2002 0						5		SYSTEM	\$148,153.96	Estimate Item Adjustment (0001) due to user leez1 overridding Payment
2022 STSTEM SSS,765.00						5		SYSTEM	(\$148,153.96)	
2022 7 2014 329						6		SYSTEM	\$148,153.96	Estimate Item Adjustment (0001) due to user leez1 overridding Payment
2022 SysTeM St44, 153, 365						6		SYSTEM	(\$148,153.96)	
2022 8 3ul 19, 2022 97 STEM \$148,153.96 This adjustment offsets the original system-generated Material Payment Estimate Recognition 2 on the current Payment Estimate. 100						7		SYSTEM	\$148,153.96	Estimate Item Adjustment (0001) due to user leez1 overridding Payment
Section Sect						7		SYSTEM	(\$148,153.96)	
CONCRETE Material - Total Sep 2, SYSTEM S55,765.00 This adjustment offsets the original system-generated Material Payment Estimate term Adjustment (0001) due to user woodskt overridding Paym Estimate term Adjustment (0001) due to user woodskt overridding Paym Estimate term Adjustment (0001) due to user woodskt overridding Paym Estimate term Adjustment (0001) due to user woodskt overridding Paym Estimate term Adjustment (0001) due to user woodskt overridding Paym Estimate term Adjustment (0001) due to user woodskt overridding Paym Estimate Exception 2 on the current Payment Estimate Exc						8		SYSTEM	\$148,153.96	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
Material - Total So.00						8		SYSTEM	(\$148,153.96)	
11 Sep 2, 2 SYSTEM S55,765.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.					- Total				\$0.00	
CONCRETE PAVEMENT (10 12 12 13 13 15 15 15 15 16 16 16 16				Material - To	tal				\$0.00	
PAVEMENT (10 172 IN NON-REINF.		0050 -	Total						\$0.00	
11 Sep 2, 2022 SYSTEM \$55,765.00		0060	PAVEMENT (10 1/2 IN. NON-	Material		11		SYSTEM	\$55,765.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
2022 Sep 16, SYSTEM (\$55,765.00) Setimate Exception 2 on the current Payment Estimate.			,			11		SYSTEM	(\$55,765.00)	
13						12		SYSTEM	\$55,765.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
Sep 30, 2022 Estimate Item Adjustment (0001) due to user woodsk1 overridding Paym Estimate Exception 2 on the current Payment Estimate.						12		SYSTEM	(\$55,765.00)	
14						13		SYSTEM	\$55,765.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
2022 Estimate Item Adjustment (0001) due to user woodsk1 overridding Paym Estimate Exception 2 on the current Payment Estimate.						13		SYSTEM	(\$55,765.00)	
15						14		SYSTEM	\$55,765.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment
2022 Estimate Item Adjustment (0002) due to user woodsk1 overridding Paym Estimate Exception 2 on the current Payment Estimate.						14		SYSTEM	(\$55,765.00)	
2022 16 Nov 16, 2022 16 Nov 16, 2022 16 Nov 16, 2022 17 Dec 16, 2022 17 Dec 16, 2022 18 System \$55,765.00 19 System \$55,765.00 2022 19 System \$55,765.00 2022 2022 2022 2022 3020						15		SYSTEM	\$55,765.00	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment
Estimate Item Adjustment (0003) due to user woodsk1 overridding Paym Estimate Exception 2 on the current Payment Estimate. 16 Nov 16, 2022 17 Dec 16, 2022 18 System \$55,765.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Paym Estimate Exception 2 on the current Payment Estimate. 17 Dec 16, 2022 System \$55,765.00 This adjustment (0003) due to user woodsk1 overridding Paym Estimate Exception 2 on the current Payment Estimate. 18 System \$55,765.00 This adjustment (0003) due to user woodsk1 overridding Paym Estimate Exception 2 on the current Payment Estimate. 19 Dec 16, 2022 Total \$0.00						15		SYSTEM	(\$55,765.00)	
2022 17 Dec 16, 2022 18 System \$55,765.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 17 Dec 16, 2022 - Total \$0.00 Material - Total \$0.00						16		SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
2022 Estimate Item Adjustment (0003) due to user woodsk1 overridding Paym Estimate Exception 2 on the current Payment Estimate. 17 Dec 16, 2022 \$\text{SYSTEM}\$ (\$55,765.00) - Total \$0.00 Material - Total \$0.00						16		SYSTEM	(\$55,765.00)	
2022 \$ \$ \$ \$ \$ \$ \$ \$ \$						17		SYSTEM	\$55,765.00	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment
Material - Total \$0.00						17		SYSTEM	(\$55,765.00)	
					- Total				\$0.00	
0.00 Total				Material - To	tal				\$0.00	
50.00 - Total		0060 -	Total						\$0.00	





Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks					
J9I3643	0070	CONCRETE	Material	Туре	11	Sep 2,	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment					
		APPROACH PAVEMENT				2022			Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
					11	Sep 2, 2022	SYSTEM	(\$21,252.00)						
					12	Sep 16, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
					12	Sep 16, 2022	SYSTEM	(\$21,252.00)						
					13	Sep 30, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					13	Sep 30, 2022	SYSTEM	(\$21,252.00)						
					14	Oct 17, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					14	Oct 17, 2022	SYSTEM	(\$21,252.00)						
					15	Nov 2, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
						15	Nov 2, 2022	SYSTEM	(\$21,252.00)					
					16	Nov 16, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					16	Nov 16, 2022	SYSTEM	(\$21,252.00)						
						17	Dec 16, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					17	Dec 16, 2022	SYSTEM	(\$21,252.00)						
				- Total				\$0.00						
	0070 -	Total	Material - To	tal				\$0.00 \$0.00						
	0080	CONCRETE CURB (6 IN. HEIGHT AND	Material	Material	Material		12	Sep 16, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
		UNDER)			12	Sep 16, 2022	SYSTEM	(\$3,500.00)						
									13	Sep 30, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					13	Sep 30, 2022	SYSTEM	(\$3,500.00)						
					14	Oct 17, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
					14	Oct 17, 2022	SYSTEM	(\$3,500.00)						
										15	Nov 2, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
							15	Nov 2, 2022	SYSTEM	(\$3,500.00)				
					16	Nov 16, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
					16	Nov 16, 2022	SYSTEM	(\$3,500.00)						
					17	Dec 16, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.					



ct L	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
43 0	080	CONCRETE CURB (6 IN.	Material		17	Dec 16, 2022	SYSTEM	(\$3,500.00)	
		HEIGHT AND UNDER)		- Total				\$0.00	
		·	Material - To	tal				\$0.00	
0	080 -	Total						\$0.00	
0	0110	FURNISHING TYPE 2 ROCK BLANKET	Material		14	Oct 17, 2022	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$17,000.00)	
					15	Nov 2, 2022	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$17,000.00)	
					16	Nov 16, 2022	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$17,000.00)	
					17	Dec 16, 2022	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$17,000.00)	
				- Total				\$0.00	
	0110 - To		Material - To	tal				\$0.00	
0		Total						\$0.00	
	0130	IMPACT ATTENUATOR 70 MPH (SAND	Material		5	Jun 2, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		MPH (SAND BARREL ARRAY)			5	Jun 2, 2022	SYSTEM	(\$4,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0130 - 0160	TRUCK OR TRAILER MOUNTED ATTEN	Material		13	Sep 30, 2022	SYSTEM	\$0.00 \$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
		(TMA)			13	Sep 30, 2022	SYSTEM	(\$5,000.00)	
					14	Oct 17, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$5,000.00)	
					15	Nov 2, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$5,000.00)	
					16	Nov 16, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$5,000.00)	
					17	Dec 16, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
						Dec 16	SYSTEM	(\$5,000.00)	
					17	Dec 16, 2022	OTOTEM	(ψο,σσσ.σσ)	
				- Total	17		OTOTEW	\$0.00	
	0160 -		Material - To		17		OTOTEM		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J9I3643	0180	ADVANCED WARNING RAIL SYSTEM	Material		2	Apr 15, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					2	Apr 15, 2022	SYSTEM	(\$100.00)					
					3	May 2, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					3	May 2, 2022	SYSTEM	(\$100.00)					
					4	May 16, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					4	May 16, 2022	SYSTEM	(\$100.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0180 -	Total						\$0.00					
	0190	CHANNELIZER (TRIM LINE)	Material		2	Apr 15, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					2	Apr 15, 2022	SYSTEM	(\$2,244.00)					
					3	May 2, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lee21 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
						3	May 2, 2022	SYSTEM	(\$2,244.00)				
							4	May 16, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					4	May 16, 2022	SYSTEM	(\$2,244.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0190 -	Total						\$0.00					
	0210	DIRECTIONAL INDICATOR BARRICADE	Material		2	Apr 15, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
					2	Apr 15, 2022	SYSTEM	(\$2,340.00)					
					3	May 2, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
								3	May 2,	OVOTERA			
													o .
					4		SYSTEM	(\$2,340.00) \$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
						2022 May 16,			Estimate Item Adjustment (0004) due to user leez1 overridding Payment				
				- Total	4	2022 May 16, 2022 May 16,	SYSTEM	\$2,340.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment				
			Material - To		4	2022 May 16, 2022 May 16,	SYSTEM	\$2,340.00 (\$2,340.00)	Estimate Item Adjustment (0004) due to user leez1 overridding Payment				
	0210 -	Total	Material - To		4	2022 May 16, 2022 May 16,	SYSTEM	\$2,340.00 (\$2,340.00)	Estimate Item Adjustment (0004) due to user leez1 overridding Payment				
	0210 - 0220	Total FLASHING ARROW PANEL			4	2022 May 16, 2022 May 16,	SYSTEM	\$2,340.00 (\$2,340.00) \$0.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment				
		FLASHING			4	2022 May 16, 2022 May 16, 2022	SYSTEM	\$2,340.00 (\$2,340.00) \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment				
		FLASHING			4	2022 May 16, 2022 May 16, 2022 Apr 15, 2022	SYSTEM SYSTEM SYSTEM	\$2,340.00 (\$2,340.00) \$0.00 \$0.00 \$3,000.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment				



APRICAL PARTICAL PARTICAL April	oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
Total	3643	0220		Material		4		SYSTEM	\$3,000.00	Estimate Item Adjustment (0005) due to user leez1 overridding Payment		
						4		SYSTEM	(\$3,000.00)			
1920 Total					- Total				\$0.00			
2				Material - To	tal				\$0.00			
COMM.NICATION		0220 -	Total						\$0.00			
2		0250	COMMUNICATION INTERFACE,	Material		2		SYSTEM	\$9,600.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment		
2022 SysTeM (39,600,00)			CONT F/			2		SYSTEM	(\$9,600.00)			
2022 4 May 16, SYSTEM \$3,600.00 This adjustment offsets the original system-generated Material Payment Estimate Item Applications of the Current Payment Estimate Item Item Item Item Item Item Item It						3		SYSTEM	\$9,600.00	Estimate Item Adjustment (0005) due to user leez1 overridding Payment		
2022 System Sys						3		SYSTEM	(\$9,600.00)			
2020 Total S0.00						4		SYSTEM	\$9,600.00	Estimate Item Adjustment (0006) due to user leez1 overridding Payment		
Naterial - Total						4	May 16, 2022	SYSTEM	(\$9,600.00)			
1					- Total				\$0.00			
TEMPORARY TAFFIC BARRIER COINT TOTAL				Material - To	tal				\$0.00			
TAFFIC BARRIER, CONT. 5 Jun 2, 2022 SYSTEM (\$11,000.00) Summer Statistical Estimate Statistical Estimate Statistical Statistic		0250 -	Total						\$0.00			
SySTEM SySTEM Sum		0270	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		5		SYSTEM	\$11,000.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment		
Material - Total S0.00				FURN/RE	FURN/RE	FURN/RE			5		SYSTEM	(\$11,000.00)
					- Total				\$0.00			
TEMPORARY REMOVABLE MARKING TAPE 4 Material Review Materia				Material - To	tal				\$0.00			
REMOVABLE MARKING TAPE MARKING		0270 -	Total						\$0.00			
6 Jun 16, SYSTEM (\$2,706.00)		0310	REMOVABLE MARKING TAPE 4	Material		6		SYSTEM	\$2,706.00	Estimate Item Adjustment (0003) due to user leez1 overridding Payment		
Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 7			IIV.,			6		SYSTEM	(\$2,706.00)			
2022 8						7		SYSTEM	\$4,462.00	Estimate Item Adjustment (0002) due to user leez1 overridding Payment		
Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 8 Jul 19, 2022 \$0.00 Material - Total \$0.00 0310 - Total \$0.00 0320 TEMPORARY REMOVABLE MARKING TAPE 6 Jun 16, 2022 \$7,416.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 7 Jul 1, SYSTEM \$12,180.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 7 Jul 1, SYSTEM \$12,180.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate Estimate Exception 4 on the current Payment Estimate. 7 Jul 1, SYSTEM (\$12,180.00) 8 Jul 19, SYSTEM \$12,180.00 This adjustment offsets the original system-generated Material Payment						7		SYSTEM	(\$4,462.00)			
Total S0.00 0310 - Total S0.00 TEMPORARY REMOVABLE MARKING TAPE Material 6 Jun 16, 2022 7 Jul 1, 2022 8 Jul 19, SYSTEM \$12,180.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 7 Jul 1, SYSTEM (\$12,180.00) This adjustment offsets the original system-generated Material Payment Item Adjustment offsets the original system-generated Material Payment Item Adjustment I						8	Jul 19, 2022	SYSTEM	\$4,462.00	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment		
Material - Total \$0.00						8		SYSTEM	(\$4,462.00)			
Solution					- Total				\$0.00			
TEMPORARY REMOVABLE MARKING TAPE A				Material - To	tal				\$0.00			
REMOVABLE MARKING TAPE 2022 Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 6 Jun 16, 2022 7 Jul 1, 2022 SYSTEM \$12,180.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate. 7 Jul 1, 2022 SYSTEM (\$12,180.00) 8 Jul 19, SYSTEM \$12,180.00 This adjustment offsets the original system-generated Material Payment		0310 -	Total						\$0.00			
7 Jul 1, 2022 SYSTEM \$12,180.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 7 Jul 1, 2022 SYSTEM (\$12,180.00) 8 Jul 19, SYSTEM \$12,180.00 This adjustment offsets the original system-generated Material Payment			REMOVABLE	Material		6		SYSTEM	\$7,416.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment		
Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 7 Jul 1, 2022 8 Jul 19, SYSTEM \$12,180.00 This adjustment offsets the original system-generated Material Payment						6		SYSTEM	(\$7,416.00)			
2022 8 Jul 19, SYSTEM \$12,180.00 This adjustment offsets the original system-generated Material Payment						7		SYSTEM	\$12,180.00	Estimate Item Adjustment (0003) due to user leez1 overridding Payment		
						7		SYSTEM	(\$12,180.00)			
						8		SYSTEM	\$12,180.00			



-4	Line	Description	A -1:	041	F-4	0	0	A t	Demode
ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
43	0320	TEMPORARY REMOVABLE	Material						Estimate Exception 4 on the current Payment Estimate.
		MARKING TAPE			8	Jul 19, 2022	SYSTEM	(\$12,180.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
J	0320 -	Total						\$0.00	
	0390	TEMPORARY PAVEMENT MARKING	Material		6	Jun 16, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$6,062.25)	
					7	Jul 1, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$6,062.25)	
					8	Jul 19, 2022	SYSTEM	\$6,062.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$6,062.25)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0390 -	Total						\$0.00	
	0450	MGS GUARDRAIL	Material		12	Sep 16, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$8,000.00)	
					13	Sep 30, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$8,000.00)	
					14	Oct 17, 2022	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$8,000.00)	
					15	Nov 2, 2022	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$8,800.00)	
					16	Nov 16, 2022	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$8,800.00)	
					17	Dec 16, 2022	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$8,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0450 -	Total						\$0.00	
	0460	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Material		12	Sep 16, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$12,000.00)	
					13	Sep 30, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0460	MGS BRIDGE	Material						Estimate Exception 13 on the current Payment Estimate.
		APP. TRANS SEC (EXT CURB)			13	Sep 30, 2022	SYSTEM	(\$12,000.00)	
					14	Oct 17, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$12,000.00)	
					15	Nov 2, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$12,000.00)	
					16	Nov 16, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$12,000.00)	
					17	Dec 16, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$12,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0460 -	Total						\$0.00	
	0490	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		11	Sep 2, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Sep 2, 2022	SYSTEM	(\$78,020.00)	
					12	Sep 16, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$78,020.00)	
					13	Sep 30, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$78,020.00)	
					14	Oct 17, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$78,020.00)	
					15	Nov 2, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$78,020.00)	
					16	Nov 16, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$78,020.00)	
					17	Dec 16, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$78,020.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0490 -	Total						\$0.00	
	0500	SLAB ON STEEL	Material		10	Aug 17,	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J9I3643	0500	SLAB ON STEEL	Material			2022			Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					10	Aug 17, 2022	SYSTEM	(\$710,325.00)					
					11	Sep 2, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.				
					11	Sep 2, 2022	SYSTEM	(\$710,325.00)					
					12	Sep 16, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					12	Sep 16, 2022	SYSTEM	(\$710,325.00)					
					13	Sep 30, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					13	Sep 30, 2022	SYSTEM	(\$710,325.00)					
					14	Oct 17, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					14	Oct 17, 2022	SYSTEM	(\$710,325.00)					
								15	Nov 2, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					15	Nov 2, 2022	SYSTEM	(\$710,325.00)					
					16	Nov 16, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					16	Nov 16, 2022	SYSTEM	(\$710,325.00)					
					17	Dec 16, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					17	Dec 16, 2022	SYSTEM	(\$710,325.00)					
				- Total				\$0.00					
	0.500		Material - To	tal				\$0.00					
	0500 - 0510	TYPE D BARRIER	Material		12	Sep 16, 2022	SYSTEM	\$0.00 \$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.				
					12	Sep 16, 2022	SYSTEM	(\$64,170.00)					
						13	Sep 30, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
					13	Sep 30, 2022	SYSTEM	(\$64,170.00)					
			1.	1					14	Oct 17, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				14	Oct 17, 2022	SYSTEM	(\$64,170.00)						
				1:		15	Nov 2, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
					15	Nov 2, 2022	SYSTEM	(\$64,170.00)					
					16	Nov 16, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.				
					16	Nov 16,	SYSTEM	(\$64,170.00)					





t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
43	0510	TYPE D BARRIER	Material			2022			
					17	Dec 16, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$64,170.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0510 -	Total						\$0.00	
(0540	SLAB DRAIN	Material		9	Aug 2, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 2, 2022	SYSTEM	(\$9,000.00)	
					10	Aug 17, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Aug 17, 2022	SYSTEM	(\$9,000.00)	
					11	Sep 2, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Sep 2, 2022	SYSTEM	(\$9,000.00)	
				- Total				\$0.00	
			Material - To	Material - Total				\$0.00	
	0540 -	Total						\$0.00	
0	0630	SLAB ON STEEL	Construction Stockpile		16	Nov 16, 2022	SYSTEM	(\$21,103.97)	Payment Estimate Item Adjustment generated Stockpile Transaction
					17	Dec 16, 2022	SYSTEM	(\$11,995.95)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$33,099.92)	
			Construction	Stockpile - 1	Γotal			(\$33,099.92)	
			Construction Stockpile STMI		15	Nov 2, 2022	SYSTEM	\$60,113.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$60,113.00	
			Construction	Stockpile S	ГМI - Total			\$60,113.00	
			Material		16	Nov 16, 2022	SYSTEM	\$249,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$249,375.00)	
					17	Dec 16, 2022	SYSTEM	\$391,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$391,125.00)	
			- Total					\$0.00	
			Material - Total					\$0.00	
	0630 -							\$27,013.08	
5	5002	SEQUENTIAL FLASHING WARNING LIGHT	Material		4	May 16, 2022	SYSTEM	\$4,347.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$4,347.00)	
			- Total					\$0.00	
			Material - Total					\$0.00	
			Material - 10	lai					
	5002 -	Total	Material - 10	lai				\$0.00	

Dec 20, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9l3643	5003	TEMPORARY SEEDING	Material		5	Jun 2, 2022	SYSTEM	(\$2,830.48)	
					6	Jun 16, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$2,830.48)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5003 -	Total					\$0.00		
J9I3643	- Total							\$27,013.08	
Overall -	Total						\$27,013.08		