

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 17, 2023

Progress Estimate Number 18	Contract ID 220121-H01 Prime Contractor Robertson Contractors, Inc.	Pay Period Start December 16, 2022 Original Contract Amou. Pay Period End January 15, 2023 Net Change Order Amou. Current Contract Amou.	unt \$97,055.83
Approval Date			By User

By 0001		7 tpprovai Bato
woodsk1	Generated and Approved (and should be considered Draft) at the Project Office Level by	January 17, 2023
bollis1	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	January 17, 2023
ramses1	Reviewed and Approved at the Central Office Controllers Office Level by	January 18, 2023

Original Completion Date	<b>Current Completion Date</b>	Actual Completion Date	% of Current Contract Amount Complete				
May 1, 2023	May 1, 2023		74.65%				

	Milestones		
Date Description	Original Completion Date	No Milestones Exist for Contract	
Acceptance Date			
Awarded Date	February 2, 2022	February 2, 2022	
Letting Date	January 21, 2022	January 21, 2022	
Notice to Proceed Date	April 4, 2022	April 4, 2022	
Open to Traffic Date			
Work Began Date	April 11, 2022	April 11, 2022	

Contract Total P	ay For Estimate No. 18				
		This Estimate	Previous	To Date	
220121-H01					
	Total Posted Items Pay	\$141,750.00	\$2,644,367.42	\$2,786,117.42	
	Gross Item Adjustments	(\$11,995.94)	\$27,013.08	\$15,017.14	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$2,671,380.50	\$2,801,134.56	
Contract Total Page 1	avable This Estimate:	\$129 754 06			

#### Items Paid This Estimate Period

Project Number Line Number Itel		t Number Line Number Item Code Item Description				Current Installed Qty	Current Installed Amount				
J9I3643	0630	7034212	SLAB ON STEEL	SQYD	\$525.000	270	\$141,750.00				
Project J9I3643 - To	Project J9l3643 - Total										
Overall - Total							\$141.750.00				

#### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract

		tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3643	0060	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-587	\$95.00	(\$55,765.00)
	0060	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	587	\$95.00	\$55,765.00
	0070	CONCRETE APPROACH PAVEMENT	Material			-202.4	\$105.00	(\$21,252.00)
	0070	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	202.4	\$105.00	\$21,252.00
	0800	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE	Material			-175	\$20.00	(\$3,500.00)

Revision 4/1/2020 Page 1 of 20



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 17, 2023

Progress Estimate Number
18 Contract ID 220121-H01 Pay Period Start December 16, 2022 Original Contract Amount \$3,635,384.06
Prime Contractor Robertson Contractors, Inc. Pay Period End January 15, 2023 Original Contract Amount \$97,055.83
Current Contract Amount \$3,732,439.89

ct	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
43		S						
	0800	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	175	\$20.00	\$3,500.00
	0110	FURNISHING TYPE 2 ROCK BLANKET	Material			-425	\$40.00	(\$17,000.00
	0110	FURNISHING TYPE 2 ROCK BLANKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	425	\$40.00	\$17,000.00
	0160	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material			-1	\$5,000.00	(\$5,000.00
	0160	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1	\$5,000.00	\$5,000.00
	0450	MGS GUARDRAIL	Material			-220	\$40.00	(\$8,800.00
	0450	MGS GUARDRAIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	220	\$40.00	\$8,800.00
	0460	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Material			-3	\$4,000.00	(\$12,000.00
	0460	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	3	\$4,000.00	\$12,000.00
	0490	BRIDGE APPROACH SLAB (MAJOR)	Material			-188	\$415.00	(\$78,020.00
	0490	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	188	\$415.00	\$78,020.00
	0500	SLAB ON STEEL	Material			-1,353	\$525.00	(\$710,325.00
	0500	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	1,353	\$525.00	\$710,325.00
	0510	TYPE D BARRIER	Material			-558	\$115.00	(\$64,170.00)
	0510	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	558	\$115.00	\$64,170.00
	0630	SLAB ON STEEL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$11,995.94
	0630	SLAB ON STEEL	Material			-1,015	\$525.00	(\$532,875.00
	0630	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	1,015	\$525.00	\$532,875.00

Revision 4/1/2020 Page 2 of 20



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 17, 2023

Progre		timate Number 18	Contract ID Prime Contr	220121- actor Robertso			t Change Or	der Amount	
Project Number	Line No.	Item Description		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3643						Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
Total									(\$11,995.94)

Revision 4/1/2020 Page 3 of 20



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9I3643	I 55-1(176)	2 bridge deck replacement	I-55	SCOTT	over Route 62		
Totals by .	Job Numbe	rs					
J9I3643		d Item Pay Item Adjustm		Item Pay	This Estimate \$141,750.00 (\$11,995.94) \$129,754.06	Previous \$2,644,367.42 \$27,013.08 \$2,671,380.50	To Date \$2,786,117.42 \$15,017.14 <b>\$2,801,134.56</b>
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 4 of 20



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9I3643, Item 4019905, Project Item Line Number 0050, Material Set 401990596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5021334, Project Item Line Number 0060, Material Set 502133496, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5021334, Project Item Line Number 0060, Material Set 502133496, Material 1057JMDAEC6.12 - Dowel Assemblies Epoxy Ctd Gr60 1 1/2" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5031010A, Project Item Line Number 0490, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 5041000, Project Item Line Number 0070, Material Set 504100096, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6061060, Project Item Line Number 0450, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6061068, Project Item Line Number 0460, Material Set 606106896, Material 1040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6091010, Project Item Line Number 0080, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6113020, Project Item Line Number 0110, Material Set 611302096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 6123000A, Project Item Line Number 0160, Material Set 6123000A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0500, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0500, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0630, Material Set 703421296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0630, Material Set 703421296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034212, Project Item Line Number 0630, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3643, Item 7034219A, Project Item Line Number 0510, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 5 of 20



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted an Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-H01	J9I3643	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$15,000.00	\$11,250.00
		0001	0020	2071000	LINEAR GRADING CLASS 1	4.40	0.00	4.40	STA	0.00	\$2,600.00	\$0.00
		0001	0030	2072000	LINEAR GRADING CLASS 2	32.40	0.00	32.40	STA	32.40	\$3,850.00	\$124,740.00
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,174.00	0.00	1,174.00	SQYD	587.00	\$15.00	\$8,805.00
		0001	0050	4019905	MISC.Optional Pavement	2,932.00	791.00	3,723.00	SQYD	3,723.00	\$50.53	\$188,123.19
		0001	0060	5021334	CONCRETE PAVEMENT (10 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	1,173.60	0.00	1,173.60	SQYD	587.00	\$95.00	\$55,765.00
		0001	0070	5041000	CONCRETE APPROACH PAVEMENT	404.80	0.00	404.80	SQYD	202.40	\$105.00	\$21,252.00
		0001	0080	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	349.00	0.00	349.00	LF	175.00	\$20.00	\$3,500.00
		0001	0090	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$45.00	\$0.00
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	47.00	0.00	47.00	CUYD	0.00	\$80.00	\$0.00
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	425.00	\$40.00	\$17,000.00
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	853.00	0.00	853.00	CUYD	425.00	\$25.00	\$10,625.00
		0001	0130	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	2.00	2.00	4.00	EA	3.00	\$2,000.00	\$6,000.00
		0001	0140	6122020	REPLACEMENT SAND BARREL	6.00	24.00	30.00	EA	12.00	\$250.00	\$3,000.00
		0001	0150	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	1.00	3.00	EA	3.00	\$1,000.00	\$3,000.00
		0001	0160	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	1.00	\$5,000.00	\$5,000.00
		0001	0170	6161005	CONSTRUCTION SIGNS	2,140.00	0.00	2,140.00	SQFT	1,560.00	\$6.50	\$10,140.00
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	18.00	0.00	18.00	EA	8.00	\$25.00	\$200.00
		0001	0190	6161025	CHANNELIZER (TRIM LINE)	500.00	0.00	500.00	EA	407.00	\$17.00	\$6,919.00
		0001	0200	6161030	TYPE III MOVEABLE BARRICADE	21.00	0.00	21.00	EA	15.00	\$145.00	\$2,175.00
		0001	0210	6161033	DIRECTIONAL INDICATOR BARRICADE	100.00	0.00	100.00	EA	74.00	\$65.00	\$4,810.00
		0001	0220	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	3.00	\$1,500.00	\$4,500.00
		0001	0230	6161052	WARNING LIGHT, TYPE B	50.00	0.00	50.00	EA	0.00	\$15.00	\$0.00
		0001	0240	6161070	TUBULAR MARKER	650.00	0.00	650.00	EA	370.00	\$35.00	\$12,950.00
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,800.00	\$19,200.00
		0001	0260	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	16.00	\$800.00	\$12,800.00
		0001	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	451.00	100.00	551.00	LF	551.00	\$40.00	\$22,040.00
		0001	0280	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	451.00	100.00	551.00	LF	551.00	\$35.00	\$19,285.00
		0001	0290	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$225,000.00	\$0.00
		0001	0291	6181000	MOBILIZATION	0.00	1.00	1.00	LS		\$200,165.00	\$200,165.00
		0001	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	10.00	0.00	10.00	EA	0.00	\$250.00	\$0.00
		0001	0310	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,645.00	0.00	3,645.00	LF	3,645.00	\$2.00	\$7,290.00
		0001	0320	6205303B 6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	6,090.00 2,705.00	2,500.00 27,660.00	8,590.00 30,365.00	LF LF	8,590.00	\$2.00 \$0.30	\$17,180.00 \$0.00
		0001	0340	6205903A		1,774.00	19,126.00	20,900.00	LF	0.00	\$0.30	\$0.00
		0001	0350	6206000C		13,177.00	-13,177.00	0.00	LF	0.00	\$0.15	\$0.00
		0001	0360	6206001C	PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	6,704.00	-6,704.00	0.00	LF	0.00	\$0.15	\$0.00
		0001	0370	6206125A	MARKING PAINT, TYPE P BEADS  24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	75.00	-75.00	0.00	LF	0.00	\$5.00	\$0.00
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	50,359.00	0.00	50,359.00	LF	25,180.00	\$0.50	\$12,590.00
		0001	0390	6208063	TEMPORARY PAVEMENT MARKING	34,359.00	0.00	34,359.00	EA	34,359.00	\$0.25	\$8,589.75
		0001	0400	6240102A	TEMPORARY SILT FENCE GEOTEXTILE	1,040.00	0.00	1,040.00	SQYD	0.00	\$1.50	\$0.00
		0001	0410	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,689.00	0.00	1,689.00	SQYD	0.00	\$4.00	\$0.00
		0001	0420	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.00
		0001	0430		12 IN. PIPE GROUP B	1,100.00	0.00	1,100.00	LF	1,100.00	\$50.00	\$55,000.00

Page 6 of 20 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-H01	J9I3643	0001	0440	8061016	SEDIMENT REMOVAL	10.00	0.00	10.00	CUYD	3.00	\$1.00	\$3.00
		0010	0450	6061060	MGS GUARDRAIL	100.00	315.00	415.00	LF	220.00	\$40.00	\$8,800.00
		0010	0460	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	6.00	0.00	6.00	EA	3.00	\$4,000.00	\$12,000.00
		0010	0470	6069901	MISC.Remove and Reinstall High-Tension Gurad Cable	1.00	0.00	1.00	LS	0.50	\$55,000.00	\$27,500.00
		0070	0480	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	11,771.00	\$14.00	\$164,794.00
		0070	0490	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	188.00	\$415.00	\$78,020.00
		0070	0500	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	1,353.00	\$525.00	\$710,325.00
		0070	0510	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	558.00	\$115.00	\$64,170.00
		0070	0520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0070	0530	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	1,800.00	\$15.50	\$27,900.00
		0070	0540	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	20.00	\$450.00	\$9,000.00
		0070	0550	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0070	0560	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0070	0570	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0070	0580	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0070	0590	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	109.00	\$45.00	\$4,905.00
		0070	0600	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	87.00	\$80.00	\$6,960.00
		0071	0610	2162500	REMOVAL OF EXISTING BRIDGE DECK	11,771.00	0.00	11,771.00	SQFT	11,771.00	\$14.00	\$164,794.00
		0071	0620	5031010A	BRIDGE APPROACH SLAB (MAJOR)	188.00	0.00	188.00	SQYD	0.00	\$415.00	\$0.00
		0071	0630	7034212	SLAB ON STEEL	1,353.00	0.00	1,353.00	SQYD	1,015.00	\$525.00	\$532,875.00
		0071	0640	7034219A	TYPE D BARRIER	558.00	0.00	558.00	LF	0.00	\$115.00	\$0.00
		0071	0650	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0071	0660	7121159	SHEAR CONNECTORS	1,800.00	0.00	1,800.00	EA	1,800.00	\$15.50	\$27,900.00
		0071	0670	7123610	SLAB DRAIN	18.00	0.00	18.00	EA	18.00	\$450.00	\$8,100.00
		0071	0680	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	12,100.00	0.00	12,100.00	SQFT	0.00	\$9.50	\$0.00
		0071	0690	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	12,100.00	0.00	12,100.00	SQFT	0.00	\$2.50	\$0.00
		0071	0700	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	12,100.00	0.00	12,100.00	SQFT	0.00	\$1.50	\$0.00
		0071	0710	7125370A	FINISH FIELD COAT (SYSTEM G)	2,700.00	0.00	2,700.00	SQFT	0.00	\$3.00	\$0.00
		0071	0720	7126000	NON-DESTRUCTIVE TESTING	109.00	0.00	109.00	LF	109.00	\$45.00	\$4,905.00
		0071	0730	7172054	OPEN CELL FOAM JOINT SEAL	87.00	0.00	87.00	LF	87.00	\$80.00	\$6,960.00
		0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$24,835.00	\$24,835.00
		0001	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	36.00	36.00	EA	36.00	\$120.75	\$4,347.00
		0001	5003	8061017	TEMPORARY SEEDING	0.00	1.00	1.00	ACRE	0.50	\$5,660.95	\$2,830.48
		0001	5004	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	0.00	6.00	6.00	EA	6.00	\$50.00	\$300.00
					late as of Report Generated Date							\$2,786,117.42
220121-H01 Ove	rall - Tota	I Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$2,786,117.42

Revision 4/1/2020 Page 7 of 20

27.69



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J9I3643

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0630	7034212	SLAB ON STEEL	1/11/23	1/17/23	270.00	SQYD	Southbound Bridge Phase II. Estimated Pay Percentage.	1360		1367		Southbound Bridge Phase II. Estimated Pay Percentage.
0660	7121159	SHEAR CONNECTORS	12/19/22	1/17/23	0.00	EA	Southbound Bridge Phase II. Estimated Pay Percentage.	1360		1367		Southbound Bridge Phase II. Estimated Pay Percentage.
0670	7123610	SLAB DRAIN	12/19/22	1/17/23	0.00	EA	Southbound Bridge Phase II. Estimated Pay Percentage.	1360		1367		Southbound Bridge Phase II. Estimated Pay Percentage.

		HEAR CONNECT	FORS	12/19/22 1/17/23				Phase II. Estimated Pay Per				lge Phase II. Estimated P	
	7123610 SI			12/19/22 1/17/23		Southbou	und Bridge	Phase II. Estimated Pay Per	centage. 1360	1:	367 Southbound Brid	lge Phase II. Estimated P	'ay Percentage.
			re details for Construction Signature Total Quantity Posted For DWR Date	ns (if applicable) Sign Info		Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SE to Do
13643		April 11, 2022		WO20-1 48x48 16		Station		NB	2.00	16	Special Sign	or Each opedar oigh	Total SF to F
		, , ,		ROAD/BRIDGE/RAM	IP WORK AHEAD								
				CONST-3A 60x48			65.501	NB	2.00	20			
				CONST-3X 56x12 SPEEDING/PASSING	4.67 G (PLATE)		65.501	NB	2.00	4.67			9
				GO20-5aP 36x24 (PLAQUE)	6.00 WORK ZONE		65.713	NB	2.00	6			
				R4-1 36x48 12.0	00 DO NOT PASS		65.713	NB	2.00	12			
				WO20-5 48x48 16	6.00		65.976	NB	2.00	16			
				RIGHT/CENTER/LEF AHEAD	T LANE CLOSED								
				WO4-1aR 48x48 1 (ARROW SYMBOL)	16.00 MERGE		66.107	NB	1.00	16			
				WO20-6a 48x48 1	6.00		66.107	NB	1.00	16			
				RIGHT/CENTER/LEF	T LANE CLOSED								
				GO20-5aP 36x24 (PLAQUE)	6.00 WORK ZONE		66.489	NB	2.00	6			
				R2-1 36x48 12.0	00 SPEED LIMIT		66.489	NB	2.00	12			
				XX R2-1 36x48 12.0	00 SPEED LIMIT		66.491	SB	2.00	12			
				XX									
				R2-1 36x48 12.0 XX	00 SPEED LIMIT		68.153	NB	2.00	12			
				GO20-5aP 36x24	6.00 WORK ZONE		68.396	SB	2.00	6			
				(PLAQUE) R2-1 36x48 12.0	00 SPEED LIMIT		68.396	SB	2.00	12			
				XX									
				WO4-1aR 48x48 1 (ARROW SYMBOL)	16.00 MERGE		68.598	SB	1.00	16			
				WO20-6a 48x48 1	6.00		68.598	SB	1.00	16			
				RIGHT/CENTER/LEF WO20-5 48x48 16			68.796	SB	2.00	16			
				RIGHT/CENTER/LEF	T LANE CLOSED		00.730	36	2.00	10			
				GO20-5aP 36x24	6.00 WORK ZONE		68.997	SB	2.00	6			
				(PLAQUE)									
				R2-1 36x48 12.0 XX	00 SPEED LIMIT		68.997	SB	2.00	12			
				CONST-3A 60x48	20.00 FINE SIGN		69.213	SB	2.00	20			
				CONST-3X 56x12 SPEEDING/PASSING	4.67 3 (PLATE)		69.213	SB	2.00	4.67			9
				WO20-1 48x48 16	6.00		69.403	SB	2.00	16			
				ROAD/BRIDGE/RAM	IP WORK AHEAD								
				R2-1 36x48 12.0 XX	00 SPEED LIMIT			62 to 55 SB Ramp	1.00	12			
				R4-1 36x48 12.0	00 DO NOT PASS			57 NB to 55 NB Ramp	1.00	12			
					00 DO NOT PASS			57 SB to 55 NB Ramp	1.00	12			
				WO20-1 48x48 16 ROAD/BRIDGE/RAM				57 NB to 55 NB Ramp	1.00	16			
				WO20-1 48x48 16	6.00			57 SB to 55 NB Ramp	1.00	16			
				ROAD/BRIDGE/RAM WO20-1 48x48 16				62 to 55 SB Ramp	1.00	16			
				ROAD/BRIDGE/RAM	IP WORK AHEAD			02 to 55 SB Namp	1.00	10			
				WO20-5 48x48 16 RIGHT/CENTER/LEF	6.00 T LANE CLOSED			57 NB to 55 NB Ramp	1.00	16			
				AHEAD									
				WO20-5 48x48 16 RIGHT/CENTER/LEF	6.00 FT LANE CLOSED			57 SB to 55 NB Ramp	1.00	16			
				AHEAD	00 00 FINE 010N			EZANDA SEANDO	4.00				
				CONST-3A 60x48 CONST-3A 60x48				57 NB to 55 NB Ramp 57 SB to 55 NB Ramp	1.00	20			
				CONST-3X 56x12	4.67			57 NB to 55 NB Ramp	1.00	4.67			4
				SPEEDING/PASSING	G (PLATE)								
				CONST-3X 56x12 SPEEDING/PASSING	4.67 G (PLATE)			57 SB to 55 NB Ramp	1.00	4.67			4
				GO20-5aP 36x24	6.00 WORK ZONE			57 NB to 55 NB Ramp	1.00	6			
				(PLAQUE) GO20-5aP 36x24	6 00 WORK 70NE			57 SB to 55 NB Ramp	1.00	6			
				(PLAQUE)				·					
				GO20-5aP 36x24 (PLAQUE)	6.00 WORK ZONE			62 to 55 SB Ramp	1.00	6			
		April 19, 2022	7	R1-2 48 TRI 6.9	3 YIELD		67.450	US 62 Ramp to I-55 NB	1.00	6.93			6
		June 2, 2022	126	WO20-2 48x48 16 AHEAD	6.00 DETOUR		61.540	Rte 62 EB	1.00	16			
				WO20-1 48x48 16	6.00		61.912	Rte 62 EB	1.00	16			
				ROAD/BRIDGE/RAM	IP WORK AHEAD								
				WO20-5 48x48 16 RIGHT/CENTER/LEF	6.00 FT LANE CLOSED		61.988	Rte 62 EB	1.00	16			
				AHEAD				DL 00 FD	100	10			
				WO20-6a 48x48 1 RIGHT/CENTER/LEF	6.00 T LANE CLOSED		62.087	Rte 62 EB	1.00	16			
				R11-2 48x30 10.	00 ROAD		62.281	Rte 62 at I-55 NB Ramp	3.00	10			
				CLOSED WO20-1 48x48 16	6.00		62.676	Rte 62 WB	1.00	16			
				WO20-1 48x48 16 ROAD/BRIDGE/RAM									
				WO20-2 48x48 16 AHEAD	6.00 DETOUR		62.909	Rte 62 WB	1.00	16			
			040		OO NO BASSING		0.140	D+ LI NID	1.00		LEE North Datour Signage EOR	07.00	27

0.149 Rt H NB 1.00 I-55 North Detour Signage 50B 27.69 249 special ??x?? ??.00 NO PASSING Revision 4/1/2020 Page 8 of 20



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

			Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	I otal SF to P
3	0170	June 2, 2022	249	ZONE special ??x?? ??.00 NO PASSING		69.377	Rt HH at I-55 NB On Ramp	4.00		LEE North Date of Cinese 200	07.00	27
				ZONE						I-55 North Detour Signage 50C		
				special ??x?? ??.00 NO PASSING ZONE		62.391	Rte 62 WB	1.00		I-55 North Detour Signage 50B	27.69	27
				special ??x?? ??.00 NO PASSING ZONE		61.988	Rte 62 WB	1.00		I-55 North Detour Signage 50A	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		1.070	Rt H NB	1.00		I-55 North Detour Signage 50B	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		61.789	Rte 62 EB	1.00		I-55 North Detour Signage 50E	27.69	2
				special ??x?? ??.00 NO PASSING ZONE		1.847	Rt H NB	1.00		I-55 North Detour Signage 50A	27.69	2
				special ??x?? ??.00 NO PASSING		1.699	Rt H NB	1.00		I-55 North Detour Signage 50D	27.69	2
				ZONE special ??x?? ??.00 NO PASSING		61.854	Rte 62 EB	1.00		I-55 North Detour Signage 50C	27.69	2
			488	ZONE E05-1 36x48 12.00 GORE EXIT		67.173	I-55 NB to Rte 62 Ramp	1.00	12			
			100	special ??x?? ??.00 NO PASSING		67.015	I-55 NB	2.00		Ramp Exit 500 FT Sign 61	16.00	
				ZONE WO1-6 60x30 12.50 HORIZONTAL		66.991	I-55 NB	2.00	12.5			
				ARROW (SYMBOL) R11-2 48x30 10.00 ROAD		66.991	I-55 NB	1.00	10			
				CLOSED								
				WO13-1 30x30 6.25 ADVISORY SPEED (PLAQUE)		66.804	I-55 NB	1.00	6.25			
				WO1-4L 48x48 16.00 REVERSE CURVE (SYMBOL LEFT ARROW)		66.804	I-55 NB	1.00	16			
				GO20-2 48x24 8.00 END ROAD WORK		65.730	I-55 SB	2.00	8			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		64.654	I-55 NB	2.00	12			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		64.552	I-55 NB	2.00	10			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		64.454	I-55 NB	1.00	18			
				R11-2 48x30 10.00 ROAD CLOSED		67.253	I-55 NB	1.00	10			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		70.251	I-55 SB	1.00	18			
				WO1-6 60x30 12.50 HORIZONTAL		67.253	I-55 NB	2.00	12.5			
				ARROW (SYMBOL) R11-2 48x30 10.00 ROAD		67.289	I-55 NB	2.00	10			
				CLOSED  R4-1 36x48 12.00 DO NOT PASS		67 429	I-55 NB	1.00	12			
				WO6-3 48x48 16.00 TWO WAY		67.429	I-55 SB	1.00	16			
				TRAFFIC (SYMBOL)  GO20-5aP 36x24 6.00 WORK ZONE		67.429	I-55 NB	1.00	6			
				(PLAQUE)								
				R4-1 36x48 12.00 DO NOT PASS WO6-3 48x48 16.00 TWO WAY		67.647 67.647	I-55 NB I-55 SB	1.00	12			
				TRAFFIC (SYMBOL)								
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		67.647	I-55 NB	1.00	6			
				WO1-4R 48x48 16.00 REVERSE CURVE (SYMBOL RIGHT ARROW)		67.800	I-55 NB	1.00	16			
				WO13-1 30x30 6.25 ADVISORY SPEED (PLAQUE)		67.800	I-55 NB	1.00	6.25			
				WO1-6 60x30 12.50 HORIZONTAL ARROW (SYMBOL)		67.887	I-55 NB	2.00	12.5			
				R5-1 30x30 6.25 DO NOT ENTER		67.890	I-55 NB	2.00	6.25			
				WO6-3 48x48 16.00 TWO WAY TRAFFIC (SYMBOL)		67.890	I-55 SB	2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		69.286	Rt HH Ramp to I-55 SB	1.00	16			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		69.825	I-55 SB	2.00	12			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		70.031	I-55 SB	2.00	10			
		June 13, 2022	24	R2-1 36x48 12.00 SPEED LIMIT		62.117	Rt 62 EB	1.00	12			
				XX R2-1 36x48 12.00 SPEED LIMIT		62.428	Rt 62 WB	1.00	12			
	0170 - Total			xx								154

Revision 4/1/2020 Page 9 of 20





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0050	MISC.	Material		4	May 16, 2022	SYSTEM	\$118,523.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$118,523.17)	
					5	Jun 2, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$148,153.96)	
					6	Jun 16, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$148,153.96)	
					7	Jul 1, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$148,153.96)	
					8	Jul 19, 2022	SYSTEM	\$148,153.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jul 19, 2022	SYSTEM	(\$148,153.96)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0050 -	Total						\$0.00	
	0060	CONCRETE PAVEMENT (10 1/2 IN. NON- REINF,	Material		11	Sep 2, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		, ,			11	Sep 2, 2022	SYSTEM	(\$55,765.00)	
					12	Sep 16, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$55,765.00)	
					13	Sep 30, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$55,765.00)	
					14	Oct 17, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$55,765.00)	
					15	Nov 2, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$55,765.00)	
					16	Nov 16, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$55,765.00)	
					17	Dec 16, 2022	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$55,765.00)	
					18	Jan 17, 2023	SYSTEM	\$55,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J9I3643	0060	CONCRETE PAVEMENT (10 1/2 IN. NON-	Material		18	Jan 17, 2023	SYSTEM	(\$55,765.00)		
		REINF,		- Total				\$0.00		
			Material - To	tal				\$0.00		
	0060 -	Total						\$0.00		
	0070	CONCRETE APPROACH PAVEMENT	Material		11	Sep 2, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					11	Sep 2, 2022	SYSTEM	(\$21,252.00)		
					12	Sep 16, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					12	Sep 16, 2022	SYSTEM	(\$21,252.00)		
					13	Sep 30, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					13	Sep 30, 2022	SYSTEM	(\$21,252.00)		
					14	Oct 17, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					14	Oct 17, 2022	SYSTEM	(\$21,252.00)		
						15	Nov 2, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
							15	Nov 2, 2022	SYSTEM	(\$21,252.00)
					16	Nov 16, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					16	Nov 16, 2022	SYSTEM	(\$21,252.00)		
					17	Dec 16, 2022	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					17	Dec 16, 2022	SYSTEM	(\$21,252.00)		
					18	Jan 17, 2023	SYSTEM	\$21,252.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					18	Jan 17, 2023	SYSTEM	(\$21,252.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0070 -	Total						\$0.00		
	0800	CONCRETE CURB (6 IN. HEIGHT AND	Material		12	Sep 16, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
		UNDER)			12	Sep 16, 2022	SYSTEM	(\$3,500.00)		
					13 Sep 30, SYSTEM \$3,500.00 This adjustment offsets the original sy Estimate Item Adjustment (0003) due	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.				
					13	Sep 30, 2022	SYSTEM	(\$3,500.00)		
				14		14	Oct 17, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$3,500.00)		
					15	Nov 2, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	



2022   16								
CURB (6 IN. N. HEIGHT AND UNIVERS)   16	t Lin	e Description		Adjustment			Amount	Remarks
UNDER!   16	3 008	CURB (6 IN.	Material		15	SYSTEM	(\$3,500.00)	
1002   1002					16	SYSTEM	\$3,500.00	Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment
2022   Estrande llem Adjustment (1005) due to user woodski overridding Payment Estrande Escreption 14 on the current Payment Estrande Escreption 14 on the current Payment Estrande E					16	SYSTEM	(\$3,500.00)	
19   2022   18   24m 17, SYSTEM   \$3,500.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate Estimate Broadput 14 on the current Payment Estimate Es					17	SYSTEM	\$3,500.00	Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment
2023   18					17	SYSTEM	(\$3,500.00)	
1-Total   1-To					18	SYSTEM	\$3,500.00	Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment
					18	SYSTEM	(\$3,500.00)	
14				- Total			\$0.00	
14			Material - To	tal			\$0.00	
Public	008	0 - Total						
15		0 FURNISHING TYPE 2 ROCK	Material		14	SYSTEM		Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment
2022   Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006) due to user woodsk1 overridding Payment Item Adjustment (0006)					14	SYSTEM	(\$17,000.00)	
16					15	SYSTEM	\$17,000.00	Estimate Item Adjustment (0005) due to user woodsk1 overridding Paymen
2022   Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate Payment Estimate Exception 15 on the current Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate Estimate Item Adjustment (0002) due to user level of the current Payment Estimate Exception 15 on the current Payment Estimate Estimate Exception 15 on the current Pa					15	SYSTEM	(\$17,000.00)	
2022   17					16	SYSTEM	\$17,000.00	Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment
2022   Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.					16	SYSTEM	(\$17,000.00)	
2022   18					17	SYSTEM	\$17,000.00	Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment
2023   Estimate Item Adjustment (0006) due to user woodsk1 overridding Paymen Estimate Exception 15 on the current Payment Estimate.					17	SYSTEM	(\$17,000.00)	
Total   S0.00					18	SYSTEM	\$17,000.00	Estimate Item Adjustment (0006) due to user woodsk1 overridding Paymen
Material - Total   \$0.00					18	SYSTEM	(\$17,000.00)	
Solid   Soli				- Total			\$0.00	
Discrimination of the current Payment Estimate   Discriminate			Material - To	tal			\$0.00	
ATTENUATOR 70 MPH (SAND BARREL ARRAY)	011	0 - Total					\$0.00	
Total   \$0.00	013	ATTENUATOR 70 MPH (SAND	Material		5	SYSTEM	\$4,000.00	Estimate Item Adjustment (0002) due to user leez1 overridding Payment
Material - Total   \$0.00		BARKEL ARRAY)			5	SYSTEM	(\$4,000.00)	
Substitute				- Total			\$0.00	
TRUCK OR TRAILER MOUNTED ATTEN (TMA)  13 Sep 30, 2022  14 Oct 17, 2022  15,000.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  15 Sep 30, 2YSTEM (\$5,000.00)  16 SySTEM (\$5,000.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjustment (0005) due to user woodsk1 overridding Payment Item Adjus			Material - To	tal			\$0.00	
TRAILER MOUNTED ATTEN (TMA)  2022  Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  13 Sep 30, 2022  14 Oct 17, SYSTEM \$5,000.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment	013	0 - Total					\$0.00	
13 Sep 30, 2022 (\$5,000.00)  14 Oct 17, SYSTEM \$5,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Paymer	016	TRAILER MOUNTED ATTEN	Material		13	SYSTEM	\$5,000.00	Estimate Item Adjustment (0004) due to user woodsk1 overridding Paymer
2022 Estimate Item Adjustment (0005) due to user woodsk1 overridding Paymer		(TMA)			13	SYSTEM	(\$5,000.00)	
					14	SYSTEM	\$5,000.00	Estimate Item Adjustment (0005) due to user woodsk1 overridding Paymen



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
43	0160	TRUCK OR TRAILER	Material		14	Oct 17, 2022	SYSTEM	(\$5,000.00)	
		MOUNTED ATTEN (TMA)			15	Nov 2, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Paymen Estimate Exception 16 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$5,000.00)	
					16	Nov 16, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Paymen Estimate Exception 16 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$5,000.00)	
					17	Dec 16, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payme Estimate Exception 16 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$5,000.00)	
					18	Jan 17, 2023	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payme Estimate Exception 16 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$5,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0160 -	Total						\$0.00	
	0180	ADVANCED WARNING RAIL SYSTEM	Material		2	Apr 15, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$100.00)	
					3	May 2, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$100.00)	
					4	May 16, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$100.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0180 -	Total						\$0.00	
	0190	CHANNELIZER (TRIM LINE)	Material		2	Apr 15, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$2,244.00)	
					3	May 2, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$2,244.00)	
					4	May 16, 2022	SYSTEM	\$2,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$2,244.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0190 -	Total						\$0.00	
	0210	DIRECTIONAL INDICATOR BARRICADE	Material		2	Apr 15, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.



	ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
13 02	210	DIRECTIONAL INDICATOR	Material		2	Apr 15, 2022	SYSTEM	(\$2,340.00)	
		BARRICADE			3	May 2, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$2,340.00)	
					4	May 16, 2022	SYSTEM	\$2,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$2,340.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
02	210 - To	otal						\$0.00	
02	220	FLASHING ARROW PANEL	Material		2	Apr 15, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Apr 15, 2022	SYSTEM	(\$3,000.00)	
					3	May 2, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$3,000.00)	
					4	May 16, 2022	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$3,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
02									
	220 - To	otal						\$0.00	
	250	CMS W/O COMMUNICATION INTERFACE,	Material		2	Apr 15, 2022	SYSTEM	<b>\$0.00</b> \$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	250	CMS W/O	Material		2	Apr 15, 2022 Apr 15, 2022	SYSTEM SYSTEM		Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment
	250	CMS W/O COMMUNICATION INTERFACE,	Material			2022 Apr 15,		\$9,600.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment
	250	CMS W/O COMMUNICATION INTERFACE,	Material		2	2022 Apr 15, 2022 May 2,	SYSTEM	\$9,600.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment
	250	CMS W/O COMMUNICATION INTERFACE,	Material		2	2022  Apr 15, 2022  May 2, 2022  May 2,	SYSTEM	\$9,600.00 (\$9,600.00) \$9,600.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment
	250	CMS W/O COMMUNICATION INTERFACE,	Material		3	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16,	SYSTEM SYSTEM	\$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00)	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment
	250	CMS W/O COMMUNICATION INTERFACE,	Material	- Total	3 3 4	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022 May 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00)	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment
	250	CMS W/O COMMUNICATION INTERFACE,	Material - To		3 3 4	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022 May 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment
022	250	CMS W/O COMMUNICATION INTERFACE, CONT F/			2 3 4 4	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022 May 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00)	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment
02	250 C(	CMS W/O COMMUNICATION INTERFACE, CONT F/  TEMPORARY TRAFFIC BARRIER, CONT.			3 3 4	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 May 16, 2022 May 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00)	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment
02	250 C(	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material - To	tal	2 3 4 4	2022 Apr 15, 2022 May 2, 2022 May 16, 2022 May 16, 2022 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$9,600.00 (\$9,600.00) \$9,600.00) (\$9,600.00) (\$9,600.00)  \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment
02	250 C(	CMS W/O COMMUNICATION INTERFACE, CONT F/  TEMPORARY TRAFFIC BARRIER, CONT.	Material - To	tal - Total	2 3 3 4 4	2022 Apr 15, 2022 May 2, 2022 May 16, 2022 May 16, 2022 Jun 2, 2022 Jun 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 \$0.00 \$0.00 \$11,000.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment
02	2250 C/	CMS W/O COMMUNICATION INTERFACE, CONT F/  TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material - To	tal - Total	2 3 3 4 4	2022 Apr 15, 2022 May 2, 2022 May 16, 2022 May 16, 2022 Jun 2, 2022 Jun 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$0.00 \$0.00 \$11,000.00 (\$11,000.00)	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment
02 02 02	250 Ci	CMS W/O COMMUNICATION INTERFACE, CONT F/  TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material - To	tal - Total	2 3 4 4 5 5	2022 Apr 15, 2022 May 2, 2022 May 16, 2022 May 16, 2022 Jun 2, 2022 Jun 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$0.00 \$11,000.00 (\$11,000.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
02 02 02	250 C(	CMS W/O COMMUNICATION INTERFACE, CONT F/  TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material - To	tal - Total	2 3 3 4 4	2022 Apr 15, 2022 May 2, 2022 May 16, 2022 May 16, 2022 Jun 2, 2022 Jun 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$9,600.00 (\$9,600.00) \$0.00 \$0.00 \$11,000.00 (\$11,000.00)	Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.





Type Adjustment Type Date By															
	ect L	Line	Description		Adjustment			Amount	Remarks						
7	43 0	0310	REMOVABLE MARKING TAPE 4	Material		7	SYSTEM	\$4,462.00	Estimate Item Adjustment (0002) due to user leez1 overridding Payment						
2022   System   Federate Registrates (1000) due to such recorded phyment Estimate.			IN.,			7	SYSTEM	(\$4,462.00)							
Solid						8	SYSTEM	\$4,462.00	Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment						
						8	SYSTEM	(\$4,462.00)							
1					- Total			\$0.00							
Part				Material - To	tal			\$0.00							
REMOVABLE	0	0310 -	Total					\$0.00							
2022   7	0	0320	REMOVABLE	Material		6	SYSTEM	\$7,416.00	Estimate Item Adjustment (0004) due to user leez1 overridding Payment						
2022   SYSTEM   SYS						6	SYSTEM	(\$7,416.00)							
2022   8						7	SYSTEM	\$12,180.00	Estimate Item Adjustment (0003) due to user leez1 overridding Payment						
2022   Estimate Exception 4 on the current Payment Estimate.						7	SYSTEM	(\$12,180.00)							
Company						8	SYSTEM	\$12,180.00	Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment						
						8	SYSTEM	(\$12,180.00)							
					- Total			\$0.00							
TEMPORARY   PAVEMENT   Material				Material - To	tal			\$0.00							
PAVEMENT   MARKING	0	)320 -	Total					\$0.00							
2022   7	0	0390	PAVEMENT	Material		6	SYSTEM	\$6,062.25	Estimate Item Adjustment (0005) due to user leez1 overridding Payment						
2022   Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						6	SYSTEM	(\$6,062.25)							
2022   8								7	SYSTEM	\$6,062.25	Estimate Item Adjustment (0004) due to user leez1 overridding Payment				
Sep 16, SYSTEM   Sep 30, 2022   SySTEM   Sep 30, 202								7	SYSTEM	(\$6,062.25)					
Total   \$0.00						8	SYSTEM	\$6,062.25	Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment						
Material - Total   S0.00						8	SYSTEM	(\$6,062.25)							
Solution					- Total			\$0.00							
Material    12   Sep 16, 2022   SYSTEM   \$8,000.00   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.    12   Sep 16, 2022   SYSTEM   \$8,000.00				Material - To	tal			\$0.00							
Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  12 Sep 16, 2022  13 Sep 30, 2022  SYSTEM \$8,000.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  13 Sep 30, 2022  14 Oct 17, 2022  SYSTEM \$8,000.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	0	390 -	Total					\$0.00							
2022  13 Sep 30, 2022  13 Sep 30, 2022  14 Oct 17, 2022  15 System  \$8,000.00  \$8,000.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  18 Sep 30, 2022  19 System  \$8,000.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	0		MGS GUARDRAIL	GUARDRAIL Material	Material	Material	Material	Material	Material	Material		12	SYSTEM	\$8,000.00	Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment
Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  Sep 30, 2022  System (\$8,000.00)  Cot 17, 2022  \$8,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.					12	SYSTEM	(\$8,000.00)								
2022  14 Oct 17, 2022  \$8,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  14 Oct 17, SYSTEM (\$8,000.00)						13	SYSTEM	\$8,000.00	Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment						
2022 Estimate Item Adjustment (0006) dué to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  14 Oct 17, SYSTEM (\$8,000.00)						13	SYSTEM	(\$8,000.00)							
						14	SYSTEM	\$8,000.00	Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment						
2022						14	SYSTEM	(\$8,000.00)							



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
643	0450	MGS GUARDRAIL	Material		15	Nov 2, 2022	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$8,800.00)	
					16	Nov 16, 2022	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$8,800.00)	
					17	Dec 16, 2022	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Paymer Estimate Exception 12 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$8,800.00)	
					18	Jan 17, 2023	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Paymer Estimate Exception 12 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$8,800.00)	
				- Total				\$0.00	
	0.450-	Tabel	Material - To	tal				\$0.00	
	0450 - 0460	Total  MGS BRIDGE	Material		12	Sen 16	SYSTEM	\$12,000.00	This adjustment offsets the original system generated Material Designant
	0460	APP. TRANS SEC (EXT CURB)	матепа			Sep 16, 2022			This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payme Estimate Exception 14 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$12,000.00)	
					13	Sep 30, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$12,000.00)	
					14	Oct 17, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$12,000.00)	
					15	Nov 2, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$12,000.00)	
					16	Nov 16, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payme Estimate Exception 13 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$12,000.00)	
					17	Dec 16, 2022	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payme Estimate Exception 13 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$12,000.00)	
					18	Jan 17, 2023	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payme Estimate Exception 13 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$12,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0460 -						0.40==:	\$0.00	
	0490	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		11	Sep 2, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payme Estimate Exception 4 on the current Payment Estimate.
					11	Sep 2, 2022	SYSTEM	(\$78,020.00)	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	0490	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		12	Sep 16, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$78,020.00)	
					13	Sep 30, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$78,020.00)	
					14	Oct 17, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$78,020.00)	
					15	Nov 2, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$78,020.00)	
					16	Nov 16, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$78,020.00)	
					17	Dec 16, 2022	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$78,020.00)	
					18	Jan 17, 2023	SYSTEM	\$78,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$78,020.00)	
				- Total				\$0.00	
	0490 -	Total	Material - To	tal				\$0.00 \$0.00	
	0500	SLAB ON STEEL	Material		10	Aug 17, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Aug 17, 2022	SYSTEM	(\$710,325.00)	Estimate Exception 2 on the editor of their Estimate.
					11	Sep 2, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					11	Sep 2, 2022	SYSTEM	(\$710,325.00)	
					12	Sep 16, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$710,325.00)	
					13	Sep 30, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$710,325.00)	
					14	Oct 17, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$710,325.00)	
					15	Nov 2, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
13	0500	SLAB ON STEEL	Material		15	Nov 2, 2022	SYSTEM	(\$710,325.00)	
					16	Nov 16, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$710,325.00)	
					17	Dec 16, 2022	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$710,325.00)	
					18	Jan 17, 2023	SYSTEM	\$710,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$710,325.00)	
				- Total				\$0.00	
			Material - To	tal	al			\$0.00	
	0500 -	Total						\$0.00	
ľ	0510	TYPE D BARRIER	Material		12	Sep 16, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$64,170.00)	
					13	Sep 30, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					13	Sep 30, 2022	SYSTEM	(\$64,170.00)	
					14	Oct 17, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					14	Oct 17, 2022	SYSTEM	(\$64,170.00)	
					15	Nov 2, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$64,170.00)	
					16	Nov 16, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$64,170.00)	
					17	Dec 16, 2022	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					17	Dec 16, 2022	SYSTEM	(\$64,170.00)	
					18	Jan 17, 2023	SYSTEM	\$64,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					18	Jan 17, 2023	SYSTEM	(\$64,170.00)	
				- Total				\$0.00	
	Material - Total  0510 - Total							\$0.00	
	0510 - T 0540	SLAB DRAIN	Material		9	Aug 2, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Paymen
					9	Aug 2,	SYSTEM	(\$9,000.00)	Estimate Exception 2 on the current Payment Estimate.
						2022	2. 01 LIVI	(40,000.00)	
					10	Aug 17, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.





Lir	ne Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3 054	40 SLAB DRAIN	Material		10	Aug 17, 2022	SYSTEM	(\$9,000.00)	
				11	Sep 2, 2022	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				11	Sep 2, 2022	SYSTEM	(\$9,000.00)	
			- Total				\$0.00	
		Material - Total					\$0.00	
054	10 - Total							
063	SLAB ON STEEL	Construction Stockpile		16	Nov 16, 2022	SYSTEM	(\$21,103.97)	Payment Estimate Item Adjustment generated Stockpile Transaction
				17	Dec 16, 2022	SYSTEM	(\$11,995.95)	Payment Estimate Item Adjustment generated Stockpile Transaction
				18	Jan 17, 2023	SYSTEM	(\$11,995.94)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				(\$45,095.86)	
		Construction	Stockpile - 1	Stockpile - Total				
		Construction Stockpile STMI		15	Nov 2, 2022	SYSTEM	\$60,113.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$60,113.00	
		Construction	Construction Stockpile STMI - Total					
		Material		16	Nov 16, 2022	SYSTEM	\$249,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				16	Nov 16, 2022	SYSTEM	(\$249,375.00)	
				17	Dec 16, 2022	SYSTEM	\$391,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				17	Dec 16, 2022	SYSTEM	(\$391,125.00)	
				18	Jan 17, 2023	SYSTEM	\$532,875.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				18	Jan 17, 2023	SYSTEM	(\$532,875.00)	
			- Total				\$0.00	
		Material - Total					\$0.00	
06	30 - Total						\$15,017.14	
500	SEQUENTIAL FLASHING WARNING LIGHT	Material		4	May 16, 2022	SYSTEM	\$4,347.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				4	May 16, 2022	SYSTEM	(\$4,347.00)	
			- Total				\$0.00	
		Material - Total					\$0.00	
50	02 - Total						\$0.00	
500	TEMPORARY SEEDING	Material		5	Jun 2, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Jun 2, 2022	SYSTEM	(\$2,830.48)	
				6	Jun 16, 2022	SYSTEM	\$2,830.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	Jun 16, 2022	SYSTEM	(\$2,830.48)	
			- Total				\$0.00	
		Material - Total					\$0.00	
50	03 - Total						\$0.00	



Jan 19, 2023

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3643	- Total							\$15,017.14	
Overall -	Total						\$15,017.14		