

Progress Estimate N 18	umber	Contract ID Prime Contractor	220218-F06 KCI Construction Co	ompany			Original Contract Amount 2 Net Change Order Amount Current Contract Amount	
Approval Date								By User
December 16, 2022	16, Generated and Approved (and should be considered Draft) at the Project Office Lev							kloepj1
December 19, 2022		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by						
December 19, 2022	er 19, Reviewed and Approved at the Central Office Controllers Office Level by							
Original Completio	n Date	Current Co	mpletion Date	A	tual Completion Date	%	6 of Current Contract Amoun	t Complete
December 1, 20	24	Decem	ber 1, 2024 19.39%				19.39%	
	Contrac	t Informational Dat	es		Milestones			
Date Description	Original	Completion Date	Current Completio	n Date	No Milestones Exist fo	r Contract		
Acceptance Date								
Awarded Date	March 1,	2022	March 1, 2022					
Letting Date	February	/ 18, 2022	February 18, 2022					
Notice to Proceed Date	March 16	6, 2022	March 16, 2022					
Open to Traffic Date								

#### Contract Total Pay For Estimate No. 18 Previous To Date This Estimate 220218-F06 <mark>\$935,606.68</mark> Total Posted Items Pay \$11,298,073.10 \$12,233,679.78 (**\$33,551.31)** \$0.00 Gross Item Adjustments \$509,462.05 \$475,910.74 \$0.00 \$0.00 Incentive Disincentive \$0.00 \$0.00 \$0.00 Liquidated Damage \$0.00 \$0.00 \$0.00 Other Contract Adjustments \$0.00 \$0.00 \$0.00 \$11,807,535.15 \$12,709,590.52 Contract Total Payable This Estimate: \$902,055.37

April 3, 2022

### Items Paid This Estimate Period

Work Began Date

April 3, 2022

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3149	0070	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	TONS	\$157.000	653.31	\$102,569.67
	0090	4071005	TACK COAT	GAL	\$2.500	340	\$850.00
	0110	5041000	CONCRETE APPROACH PAVEMENT	SQYD	\$117.000	458.3	\$53,621.10
	0150	6099903	MISC.Concrete Curb Under Guardrail	LF	\$42.250	13	\$549.25
	0160	6116010A	SLOPE PROTECTION	SQYD	\$95.000	12	\$1,140.00
	0210	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$230.000	39	\$8,970.00
	0230	6139905	MISC.Type 1 or 5 Aggregate for Base (Var. Thick) (Pavement Repair)	SQYD	\$19.000	39	\$741.00
	0270	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	LF	\$185.000	34	\$6,290.00
	0280	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	LF	\$72.000	336	\$24,192.00
	0390	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$2.520	3,721	\$9,376.92
	0490	6061060	MGS GUARDRAIL	LF	\$33.000	525	\$17,325.00
	0510	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	EA	\$3,800.000	1	\$3,800.00
	0520	6061080	MGS END ANCHOR	EA	\$1,500.000	2	\$3,000.00
	0540	6063019	TYPE E CRASHWORTHY END TERMINAL	EA	\$29,500.000	1	\$29,500.00
	0550	6069903	MISC.MGS Concrete Barrier Transition (Thrie Beam Rail)	LF	\$84.000	124	\$10,416.00
	0560	9011070	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE B DESIGN 3	EA	\$3,301.000	2	\$6,602.00
	0570	9011104	BRACKET ARM, 4 FT. OR 1.2 M	EA	\$415.000	2	\$830.00
	0580	9011313	LUMINAIRE, LED-C	EA	\$452.000	2	\$904.00



Progress	s Estimate 18	Number	Contract ID         220218-F06         Pay Period Start         December 2, 2022         Original Contract Amount           Prime Contractor         KCI Construction Company         Pay Period End         December 15, 2022         Net Change Order Amount           Contract ID         Construction Company         Pay Period End         December 15, 2022         Net Change Order Amount						
Project Number	Line Number	ltem Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J6I3149	0590	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	LF	\$21.000	37	\$777.00		
	0600	9015010	TRENCHING TYPE I	LF	\$12.000	37	\$444.00		
	0610	9016110	PULL BOX, PREFORMED CLASS 1	EA	\$2,000.000	2	\$4,000.00		
	0620	9017006	CABLE, 6 AWG 1 CONDUCTOR	LF	\$2.000	1,530	\$3,060.00		
	0640	9017206	WIRE, 6 AWG, BARE NEUTRAL	LF	\$2.000	770	\$1,540.00		
	0720	5031010A	BRIDGE APPROACH SLAB (MAJOR)	SQYD	\$280.000	123.6	\$34,608.00		
	0770	7034214	CLASS B-2 CONCRETE	CUYD	\$4,500.000	1.7	\$7,650.00		
	0980	7034214	CLASS B-2 CONCRETE	CUYD	\$4,500.000	1.7	\$7,650.00		
	1060	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$2.000	440	\$880.00		
	1180	7034214	CLASS B-2 CONCRETE	CUYD	\$4,500.000	1.7	\$7,650.00		
	1340	5031010A	BRIDGE APPROACH SLAB (MAJOR)	SQYD	\$300.000	108	\$32,400.00		
	1390	7034214	CLASS B-2 CONCRETE	CUYD	\$4,500.000	1.7	\$7,650.00		
	2410	7031004	DIAMOND GRINDING	SQYD	\$10.500	237	\$2,488.50		
2420 7033013 PE		7033013	PENETRATING CONCRETE SEALER	SY	\$5.000	131	\$655.00		
	2440	7034215	TYPE B BARRIER	LF	\$220.000	4.3	\$946.00		
	2520	7049903	MISC.Curb Repair (Formed)	LF	\$147.500	5	\$737.50		
	2780	7034212	SLAB ON STEEL	SQYD	\$425.000	428.5	\$182,112.50		
	2790	7034219A	TYPE D BARRIER	LF	\$115.000	1,260	\$144,900.00		
	2800	7039907	MISC.Ultra-High Performance Concrete	CUYD	\$10,000.000	8	\$80,000.00		
	3190	7031004	DIAMOND GRINDING	SQYD	\$10.250	158	\$1,619.50		
	3200	7033013	PENETRATING CONCRETE SEALER	SY	\$5.000	137	\$685.00		
Project J6	13149 - To	tal					\$803,129.94		
J6I3187	3610	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	TONS	\$102.000	424.1	\$43,258.20		
	3620	4030105	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125C MIX)	TONS	\$107.000	370.91	\$39,687.37		
	3650	4071005	TACK COAT	GAL	\$2.500	1,020	\$2,550.00		
	3820	6122030	IMPACT ATTENUATOR (RELOCATION)	EA	\$678.000	1	\$678.00		
	3940	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	LF	\$21.750	600	\$13,050.00		
	4050	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$6.300	2,007	\$12,644.10		
	4060	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	SQYD	\$2.790	5,642	\$15,741.18		
	6101	9039901	MISC.Overhead Sign Repair	LS	\$4,867.890	1	\$4,867.89		
Project J6	13187 - To	tal					\$132,476.74		
Overall - 1	Fotal						\$935,606.68		

### No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3149	0070	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Other Item Adjustment		SP125BSM. 12/6/22. Current Index: 631.25, Base Index: 531.25, Index Difference: 100			\$4,246.52
	0110	CONCRETE APPROACH PAVEMENT	Material			-2,810.2	\$117.00	(\$328,793.40)
	0110	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	2,810.2	\$117.00	\$328,793.40

Progr		timate Number 18	ate Number Contract ID Prime Contra		606 Struction Com	Pay Period Start December 2, 2022 Or pany Pay Period End December 15, 2022 Ne Cu		der Amount	\$106,533.84
oject Imber	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
13149						Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.			
	0120	6 IN. CONCRE	ETE MEDIAN STRIP	Material			-11	\$155.00	(\$1,705.0
	0120	6 IN. CONCRE	ETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.	11	\$155.00	\$1,705.0
	0150		MISC.	Material			-102	\$42.25	(\$4,309.5
	0150		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.	102	\$42.25	\$4,309.5
	0210	FURNISHING AN CONCRETE MA FULL DEPTH	TERIAL FOR	Material			-39	\$230.00	(\$8,970.00
	0210	FURNISHING AN CONCRETE MA FULL DEPTH	TERIAL FOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.	39	\$230.00	\$8,970.00
	0270		TE TRAFFIC IER, TYPE B	Material			-34	\$185.00	(\$6,290.0
	0270		TE TRAFFIC IER, TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 64 on the current Payment Estimate.	34	\$185.00	\$6,290.00
	0450		MISC.	Material			-6	\$2,600.00	(\$15,600.0
	0450		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 140 on the current Payment Estimate.	6	\$2,600.00	\$15,600.0
	0490	MGS	GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$10,610.2
	0510		APPROACH ON SECTION IDED CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$2,200.0
	0520	MGS EI	ND ANCHOR	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,700.0
	0540	TYPE E CRA ENI	SHWORTHY D TERMINAL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$21,780.0
	0550		MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$3,586.1
	0560	LIGHTING POL 13.5 M, TYPE		Material			-2	\$3,301.00	(\$6,602.0
	0560	LIGHTING POL 13.5 M, TYPE		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 141 on the current Payment Estimate.	2	\$3,301.00	\$6,602.0
	0570	BRACKET AF	RM, 4 FT. OR 1.2 M	Material			-2	\$415.00	(\$830.0
	0570	BRACKET AF	RM, 4 FT. OR 1.2 M	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	2	\$415.00	\$830.0



Progr		timate Number 18	Contract ID Prime Contr	220218-F ractor KCI Cons		Pay Period Start December 2, 2022 Or pany Pay Period End December 15, 2022 Ne Cu	t Change Oro	der Amount	\$62,989,894.14 \$106,533.84 \$63,096,427.98
Project Number	Line No.	Item Desc	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
1613149						Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 144 on the current Payment Estimate.			
	0590	CONDUIT, 3	IN. RIGID, IN TRENCH	Material			-37	\$21.00	(\$777.00
	0590	CONDUIT, 3	IN. RIGID, IN TRENCH	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 146 on the current Payment Estimate.	37	\$21.00	\$777.00
	0610	PULL BOX, F	PREFORMED CLASS 1	Material			-2	\$2,000.00	(\$4,000.00
	0610	PULL BOX, F	PREFORMED CLASS 1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 147 on the current Payment Estimate.	2	\$2,000.00	\$4,000.00
	0620		ELE, 6 AWG 1	Material			-1,530	\$2.00	(\$3,060.00
	0620		ELE, 6 AWG 1 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payment Estimate Exception 148 on the current Payment Estimate.	1,530	\$2.00	\$3,060.00
	0640	WIRE, 6	AWG, BARE NEUTRAL	Material			-770	\$2.00	(\$1,540.00
	0640	WIRE, 6	AWG, BARE NEUTRAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 149 on the current Payment Estimate.	770	\$2.00	\$1,540.00
	0720	BRIDGE APPF	ROACH SLAB (MAJOR)	Material			-281	\$280.00	(\$78,680.00
	0720	BRIDGE APPF	ROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	281	\$280.00	\$78,680.00
	0760	PENETRATING	CONCRETE SEALER	MaterialCredit			117	\$5.00	\$585.0
	0760	PENETRATING	CONCRETE SEALER	Material			-117	\$5.00	(\$585.0
	0770	CLASS B-2	CONCRETE	Material			-3.4	\$4,500.00	(\$15,300.0
	0770	CLASS B-2	CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate.	3.4	\$4,500.00	\$15,300.00
	0930	BRIDGE APPF	ROACH SLAB (MAJOR)	Material			-153	\$300.00	(\$45,900.0
	0930	BRIDGE APPF	ROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	153	\$300.00	\$45,900.0
	0940		LEMENTARY IG SURFACE MATERIAL	Material			-23	\$700.00	(\$16,100.0
	0940		LEMENTARY IG SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	23	\$700.00	\$16,100.00



Progr			ontract ID rime Conti	220218-F r <b>actor</b> KCI Cons		Pay Period Start December 2, 2022 Or pany Pay Period End December 15, 2022 Ne Cu		der Amount	\$106,533.84
roject umber	Line No.	Item Descripti	ion	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
813149		Μ	IATERIAL			Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.			
	0950	CONCRETE V	IODIFIED VEARING SURFACE	Material			-1,073	\$130.00	(\$139,490.0
	0950	CONCRETE V	IODIFIED VEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.	1,073	\$130.00	\$139,490.0
	0970	PENETRATING CC	NCRETE SEALER	MaterialCredit			117	\$5.00	\$585.0
	0970	PENETRATING CC	NCRETE SEALER	Material			-117	\$5.00	(\$585.0
	0980	CLASS B-2 CC	NCRETE	Material			-3.4	\$4,500.00	(\$15,300.0
	0980	CLASS B-2 CC	NCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.	3.4	\$4,500.00	\$15,300.0
	1000	HALF-SOLE	REPAIR	Material			-10	\$98.50	(\$985.0
	1000	HALF-SOLE	EREPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 105 on the current Payment Estimate.	10	\$98.50	\$985.0
	1030	DECK REPAIR W TUBE REPLA		Material			-50	\$108.00	(\$5,400.0
	1030	DECK REPAIR W TUBE REPLA		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 112 on the current Payment Estimate.	50	\$108.00	\$5,400.0
	1130	BRIDGE APPROA	CH SLAB (MAJOR)	Material			-173	\$300.00	(\$51,900.0
	1130	BRIDGE APPROA	CH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	173	\$300.00	\$51,900.0
	1150	CONCRETE V	IODIFIED VEARING SURFACE	Material			-1,133	\$130.00	(\$147,290.0
	1150	CONCRETE V	IODIFIED VEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	1,133	\$130.00	\$147,290.0
	1170	PENETRATING CC	NCRETE SEALER	MaterialCredit			123	\$5.00	\$615.0
	1170	PENETRATING CC	NCRETE SEALER	Material			-123	\$5.00	(\$615.0
	1180	CLASS B-2 CC	NCRETE	Material			-3.4	\$4,500.00	(\$15,300.0
	1180	CLASS B-2 CC	NCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 85 on the current Payment Estimate.	3.4	\$4,500.00	\$15,300.0
	1220	HALF-SOLE	EREPAIR	Material			-181	\$98.50	(\$17,828.5



\$106,533.84	der Amount		Pay Period Start December 2, 2022 Or any Pay Period End December 15, 2022 Ne Ct	0218-F06 Cl Construction Com		timate Number 18 Contract ID Prime Contr	
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments		Adjustment Type	Item Description	Line No.
\$17,828.5	\$98.50	m j1 16	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0040) due to user kloepj1 overridding Payment Estimate Exception 106 on the current Payment Estimate.	aterial	R Materia	HALF-SOLE REPAIR	1220
(\$84,300.0	\$300.00	-281		aterial		BRIDGE APPROACH SLAB (MAJOR)	1340
\$84,300.C	\$300.00	m j1 6	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	aterial		BRIDGE APPROACH SLAB (MAJOR)	1340
\$615.0	\$5.00	123		Credit		PENETRATING CONCRETE SEALER	1380
(\$615.0	\$5.00	-123		aterial		PENETRATING CONCRETE SEALER	1380
(\$15,300.0	\$4,500.00	-3.4		aterial	E Materia	CLASS B-2 CONCRETE	1390
\$15,300.0	\$4,500.00	m j1 86	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 86 on the current Payment Estimate.	aterial	E Materia	CLASS B-2 CONCRETE	1390
(\$28,565.0	\$98.50	-290		aterial	R Materia	HALF-SOLE REPAIR	1430
\$28,565.0	\$98.50	m j1 J7	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0045) due to user kloepj1 overridding Payment Estimate Exception 107 on the current Payment Estimate.	aterial	R Materia	HALF-SOLE REPAIR	1430
(\$645.0	\$215.00	-3		aterial	R Materia	FULL DEPTH REPAIR	1440
\$645.0	\$215.00	m j1 0	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0046) due to user kloepj1 overridding Payment Estimate Exception 110 on the current Payment Estimate.	aterial	R Materia	FULL DEPTH REPAIR	1440
(\$78,720.0	\$320.00	-246		aterial		BRIDGE APPROACH SLAB (MAJOR)	2380
\$78,720.0	\$320.00	m j1 21	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0047) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	aterial		BRIDGE APPROACH SLAB (MAJOR)	2380
(\$24,500.0	\$700.00	-35		aterial	Ξ	SUPPLEMENTARY WEARING SURFACE MATERIAL	2390
\$24,500.0	\$700.00	m j1 i1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0048) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	aterial	Ξ	SUPPLEMENTARY WEARING SURFACE MATERIAL	2390
(\$160,513.0	\$151.00	-1,063		aterial	3	LATEX MODIFIED CONCRETE WEARING SURFACE	2400
\$160,513.0	\$151.00	m j1 i0	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	aterial	3	LATEX MODIFIED CONCRETE WEARING SURFACE	2400
(\$655.0	\$5.00	-131		aterial		PENETRATING CONCRETE SEALER	2420
(\$13,500.0	\$4,500.00	-3		aterial	E Materia	CLASS B-2 CONCRETE	2430



Progr		imate Number 18	Contract ID Prime Contr	220218-F actor KCI Cons		Pay Period Start December 2, 2022 Or pany Pay Period End December 15, 2022 Ne Cu		der Amount	\$106,533.84
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
613149	2430	CLASS B-2	CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0051) due to user kloepj1 overridding Payment Estimate Exception 87 on the current Payment Estimate.	3	\$4,500.00	\$13,500.00
	2440	TYPE	B BARRIER	Material			-4.3	\$220.00	(\$946.00
	2440	TYPE	B BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0052) due to user kloepj1 overridding Payment Estimate Exception 89 on the current Payment Estimate.	4.3	\$220.00	\$946.00
	2500	DECK REPAIF TUBE REF	R WITH VOID PLACEMENT	Material			-390	\$108.00	(\$42,120.00
	2500	DECK REPAIF TUBE REF	R WITH VOID PLACEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0053) due to user kloepj1 overridding Payment Estimate Exception 114 on the current Payment Estimate.	390	\$108.00	\$42,120.00
	2520		MISC.	Material			-5	\$147.50	(\$737.50
	2520		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0054) due to user kloepj1 overridding Payment Estimate Exception 116 on the current Payment Estimate.	5	\$147.50	\$737.50
	2770	BRIDGE APPR	OACH SLAB (MAJOR)	Material			-285	\$335.00	(\$95,475.00
	2770	BRIDGE APPR	OACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0055) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	285	\$335.00	\$95,475.00
	2780	SLA	B ON STEEL	Material			-4,285	\$425.00	(\$1,821,125.00
	2780	SLA	B ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Payment Estimate Exception 80 on the current Payment Estimate.	4,285	\$425.00	\$1,821,125.00
	2790	TYPE	D BARRIER	Material			-1,260	\$115.00	(\$144,900.00
	2790	TYPE	D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Payment Estimate Exception 99 on the current Payment Estimate.	1,260	\$115.00	\$144,900.00
	2800		MISC.	Material			-23	\$10,000.00	(\$230,000.00
	2800		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment Estimate Exception 103 on the current Payment Estimate.	23	\$10,000.00	\$230,000.00
	2810	SUBSTRUCT	JRE REPAIR (FORMED)	Material			-337	\$189.00	(\$63,693.0
	2810	SUBSTRUCT	JRE REPAIR (FORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment Estimate Exception 104 on the current Payment Estimate.	337	\$189.00	\$63,693.00
	2830		SYSTEM ON STRUCTURE	Material			-1	\$22,560.00	(\$22,560.00
	2830		SYSTEM ON STRUCTURE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	1	\$22,560.00	\$22,560.00



Progr		timate Number 18	Contract ID Prime Contr	220218-F actor KCI Cons		Pay Period Start December 2, 2022 Or pany Pay Period End December 15, 2022 Ne Ct	et Change Or	der Amount	
Project Number	Line No.	Item Desc	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3149						Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 135 on the current Payment Estimate.			
	2860		SYSTEM (ON STRUCTURE)	Material			-0.8	\$40,000.00	(\$32,000.00
	2860		SYSTEM (ON STRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 137 on the current Payment Estimate.	0.8	\$40,000.00	\$32,000.00
	3160	BRIDGE APPF	ROACH SLAB (MAJOR)	Material			-246	\$320.00	(\$78,720.00
	3160	BRIDGE APPF	ROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0062) due to user kloepj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	246	\$320.00	\$78,720.00
	3170		LEMENTARY IG SURFACE MATERIAL	Material			-36	\$700.00	(\$25,200.00
	3170		LEMENTARY IG SURFACE MATERIAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.	36	\$700.00	\$25,200.00
	3180		X MODIFIED E WEARING SURFACE	Material			-1,117	\$140.00	(\$156,380.00
	3180		X MODIFIED TE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.	1,117	\$140.00	\$156,380.00
	3200	PENETRATING	CONCRETE SEALER	Material			-137	\$5.00	(\$685.00
	3210	CLASS B-2	CONCRETE	Material			-3	\$4,500.00	(\$13,500.00
	3210	CLASS B-2	CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.	3	\$4,500.00	\$13,500.00
	3220	TYPE	E B BARRIER	Material			-13.5	\$200.00	(\$2,700.00
	3220	TYPE	E B BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.	13.5	\$200.00	\$2,700.00
	6007	REINFOR	CING STEEL	Material			-430	\$2.00	(\$860.00
	6007	REINFOR	CING STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Payment Estimate Exception 117 on the current Payment Estimate.	430	\$2.00	\$860.00
	6008	REINFOR	CING STEEL	Material			-20	\$2.00	(\$40.00
	6008	REINFOR	CING STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 126 on the current Payment Estimate.	20	\$2.00	\$40.00
J6I3187	3610	ASPHALTIC	CONCRETE	Other Item	Asphalt	SP125C 70-22. 12/5/22. Current Index:			\$1,823.63



Progr		timate Number 18	Contract ID Prime Contr	220218-F actor KCI Cons		Pay Period Start December 2, 2022 Or pany Pay Period End December 15, 2022 Ne Ct		der Amount	
Project lumber	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
613187		MIXTURE PG 64	-22 (SP125C MIX)	Adjustment	Cement Price Adjustment	631.25, Base Index: 531.25, Index Difference: 100			
	3620	ASPHALTIC MIXTURE PG 76	CONCRETE -22 (SP125C MIX)	Other Item Adjustment	Asphalt Cement Price Adjustment	SP125C 64-22. 12/5/22. Current Index: 631.25, Base Index: 531.25, Index Difference: 100			\$1,594.91
	3650		TACK COAT	Material			-1,020	\$2.50	(\$2,550.00
	3650		TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,020	\$2.50	\$2,550.00
	3730	6 IN. CONCRE	ETE MEDIAN STRIP	Material			-9.15	\$160.00	(\$1,464.00
	3730	6 IN. CONCRE	ETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	9.15	\$160.00	\$1,464.00
	3930		TE TRAFFIC IER, TYPE C	Material			-795.343	\$70.00	(\$55,674.01
	3930		TE TRAFFIC IER, TYPE C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.	795.343	\$70.00	\$55,674.01
	3990		MISC.	Material			-866	\$196.47	(\$170,143.02
	3990		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.	866	\$196.47	\$170,143.02
	4120		MISC.	Material			-15	\$2,600.00	(\$39,000.00
	4120		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 138 on the current Payment Estimate.	15	\$2,600.00	\$39,000.00
	6101		MISC.	Material			-1	\$4,867.89	(\$4,867.89
	6101		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0070) due to user kloepj1 overridding Payment Estimate Exception 150 on the current Payment Estimate.	1	\$4,867.89	\$4,867.89
otal									(\$33,551.31



	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J6I3149	I 55-3(97)	14 Bridge Rehabilitations	I-55	ST LOUIS	from Holly Hills Ave to Arsenal St						
J6I3187	l 55-3(101)	11 Bridge Rehabilitations	I-55	ST LOUIS	from Lindbergh Blvd (61/67) to Holly Hills Ave						

### Totals by Job Numbers

3149	This Estimate	Previous	To Date	
Posted Item Pay	\$803,129.94	\$10,274,692.20	\$11,077,822.14	
Gross Item Adjustments	(\$36,969.85)	\$144,737.63	\$107.767.78	
Gross Item Pay	\$766,160.09	\$10,419,429.83	\$11,185,589.92	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damages	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
······································				
3187	This Estimate	Previous	To Date	
Posted Item Pay	This Estimate \$132,476.74	Previous \$1,023,380.90	<b>To Date</b> \$1,155,857.64	
Posted Item Pay	\$132,476.74	\$1,023,380.90	\$1,155,857.64	
Posted Item Pay Gross Item Adjustments Gross Item Pay	\$132,476.74 \$3,418.54 <b>\$135,895.28</b>	\$1,023,380.90 \$364,724.42 <b>\$1,388,105.32</b>	\$1,155,857.64 \$368,142.96 <b>\$1,524,000.60</b>	
Posted Item Pay Gross Item Adjustments	\$132,476.74 \$3,418.54	\$1,023,380.90 \$364,724.42	\$1,155,857.64 \$368,142.96	
Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive	\$132,476.74 \$3,418.54 <b>\$135,895.28</b> \$0.00	\$1,023,380.90 \$364,724.42 <b>\$1,388,105.32</b> \$0.00	\$1,155,857.64 \$368,142.96 <b>\$1,524,000.60</b> \$0.00	



Exceptions / DiscrepenciesEntered ByStatusEstimate Exception Type: Insufficient Materials: Project J6l3187, Item 4071005, Project Item Line Number 3650, Material S4 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.Ongoing item, testing cannot be completed until installation is completekloepj1OverriddenEstimate Exception Type: Insufficient Materials: Project J6l3149, Item 5031010A, Project Item Line Number 0720, Material Set 5031010A96, Material 1035CSSL - Concrete Sealer (CS) - Silane Acceptance Action Generic 1053CSSL is insufficient.Ongoing item, testing cannot be completed until installation is completekloepj1OverriddenEstimate Exception Type: Insufficient Materials: Project J6l3149, Item 5031010A, Project Item Line Number 0720, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.Currently addressing testing cannot be completed until installation is testerkloepj1OverriddenEstimate Exception Type: Insuff
Number 3650, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H,       complete       complete       complete         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line       Ongoing item, testing cannot be completed until installation is       kloepj1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line       Ongoing item, testing cannot be completed until installation is       kloepj1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line       Ongoing item, testing cannot be completed until installation is       kloepj1       Overridden         Number 0720, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE       Currently addressing testing discrepancies with 3rd party       kloepj1       Overridden         4" (100mm), Acceptance Action Generic 0304SBT15KP - Compacted Type 1 & 5 Base,       Currently addressing testing discrepancies with 3rd party       kloepj1       Overridden         Number 0720, Material Set 5031010A96, Material 0304SBT15KP - Compacted Type 1 & 5 Base,       Currently addressing testing cannot be completed until installation is       kloepj1       Overridden         Number 0720, Material Set 5031010A96, Material Street J6I3149, Item 5031010A, Project Item Line       Currently addressing testing discrepancies with 3rd party       kloepj1       Overridden         Number 0720, Material Set 5031010A96, Material S
Number 0720, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane       @,       complete       complete       Complete         Acceptance Action Generic 1053CSSIL is insufficient.       Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 0720, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE       Ongoing item, testing cannot be completed until installation is complete       kloepj1       Overridden         4" (100mm), Acceptance Action Generic 1013DMCRPE04 - Underdrain Corrugated PE       Currently addressing testing discrepancies with 3rd party tester       kloepj1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 0720, Material Set 5031010A96, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.       Currently addressing testing discrepancies with 3rd party tester       kloepj1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 0720, Material Set 5031010A96, Material 0304SBT15KP is insufficient.       Ongoing item, testing cannot be completed until installation is complete       kloepj1       Overridden
Number 0720, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE       complete       complete       complete         4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.       complete       complete       complete         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 0720, Material Set 5031010A96, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.       Currently addressing testing discrepancies with 3rd party tester       kloepj1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 0720, Material Set 5031010A96, Material 1058PSB - Polyethylene Sheeting for Bond Breaker, Number 0720, Material Set 5031010A96, Material 1058PSB - Polyethylene Sheeting for Bond Breaker,       Ongoing item, testing cannot be completed until installation is complete       kloepj1       Overridden
Number 0720, Material Set 5031010A96, Material 0304SBT15KP - Compacted Type 1 & 5 Base,       tester         Acceptance Action Generic 0304SBT15KP is insufficient.       tester         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line       Ongoing item, testing cannot be completed until installation is         Number 0720, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker,       Ongoing item, testing cannot be completed until installation is
Number 0720, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, complete
Acceptance Action Generic 1058PSBB is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 0930, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 0930, Material Set 5031010A96, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 0930, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 0930, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 0930, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 1130, Material Set 5031010A96, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 1130, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 1130, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 1130, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 1130, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 1340, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 1340, Material Set 5031010A96, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 1340, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 1340, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 1340, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4* (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 2380, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 2380, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 2380, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 2380, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker,



Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered By	Status		
Acceptance Action Generic 1058PSBB is insufficient.					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 2380, Material Set 5031010A96, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 2770, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 2770, Material Set 5031010A96, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	ber 2770, Material Set 5031010A96, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 tester				
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 2770, Material Set 5031010A96, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 2770, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 2770, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 2770, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 3160, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 3160, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 3160, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 3160, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5031010A, Project Item Line Number 3160, Material Set 5031010A96, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	60, Material Set 5031010A96, Material 0304SBT15KP - Compacted Type 1 & 5 Base, tester		Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5041000, Project Item Line Number 0110, Material Set 504100096, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	0, Material Set 504100096, Material 0304SBT15KP - Compacted Type 1 & 5 Base, tester		Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5041000, Project Item Line Number 0110, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5041000, Project Item Line Number 0110, Material Set 504100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5050004, Project Item Line Number 0940, Material Set 5050004, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5050004, Project Item Line Number 2390, Material Set 5050004, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5050004, Project Item Line Number 2390, Material Set 5050004, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5050004, Project Item Line Number 2390, Material Set 5050004, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5050004, Project Item Line Number 3170, Material Set 5050004, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5050004, Project Item Line Number 3170, Material Set 5050004, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5050004, Project Item Line Number 3170, Material Set 5050004, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5052000, Project Item Line Number 0950, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5052000, Project Item Line	Currently addressing testing discrepancies with 3rd party	kloepj1	Overridden		



Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Entered By	Status	
Number 0950, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	tester		
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5052000, Project Item Line Number 1150, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5052000, Project Item Line Number 2400, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5052000, Project Item Line Number 2400, Material Set 505200096, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5052000, Project Item Line Number 2400, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5052000, Project Item Line Number 3180, Material Set 505200096, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5052000, Project Item Line Number 3180, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 5052000, Project Item Line Number 3180, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3187, Item 6083006, Project Item Line Number 3730, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3187, Item 6083006, Project Item Line Number 3730, Material Set 608300696, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 6083006, Project Item Line Number 0120, Material Set 608300696, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 6099903, Project Item Line Number 0150, Material Set 6099903, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 6099903, Project Item Line Number 0150, Material Set 6099903, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 6131010, Project Item Line Number 0210, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 6131010, Project Item Line Number 0210, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 6131010, Project Item Line Number 0210, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 6172000, Project Item Line Number 0270, Material Set 617200096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 6172000, Project Item Line Number 0270, Material Set 617200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 6172000, Project Item Line Number 0270, Material Set 617200096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3187, Item 6173000, Project Item Line Number 3930, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3187, Item 6179903, Project Item Line Number 3990, Material Set 6179903, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3187, Item 6179903, Project Item Line Number 3990, Material Set 6179903, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3187, Item 6179903, Project Item Line Number 3990, Material Set 6179903, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3187, Item 6179903, Project Item Line Number 3990, Material Set 6179903, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden



Extende Decision Type: Insulficient Materials: Project J05137. New 0173003, Project Item Line Number 3006. Material Set 017003. Material Conference Decision State C No. 5M10 Gr         Orgening Item, testing cannot be completed until installation is         Monep1         Overridden           Estimate Decogline Type: Insulficient Materials: Project J05137. New 0173003, Project Item Line Number 3006. Materials: Project J051470 - Provide State C No. 5M10 Gr         Orgening Item, testing cannot be completed until installation is         Monep1         Overridden           Estimate Decogline Type: Insulficient Materials: Project J051470 - Provide State C No. 5M10 Gr         Orgening Item, testing cannot be completed until installation is         Monep1         Acknowledged           Acceptance Acline Generic 103/25381L is insufficient.         Insufficient Materials: Project J051480, Item 7033013, Project Item Line Number 0707, Material Ser 7033015, Material: Project J051480, Item 7033013, Project Item Line Number 0707, Material Ser 7033015, Material 109265581L - Concrede State (C S) - State @.         Need PAL to be submitted         Monep1         Acknowledged           Acceptance Acline Generic 103/25381L is insufficient.         Need Number 170, Material Ser 7033015, Material 109265581L - Concrede State (C S) - State @.         Need PAL to be submitted         Monep1         Acknowledged           Acceptance Acline Generic 103/25381L is insufficient.         Need PAL to be submitted         Monep1         Acknowledged           Acceptance Acline Generic 103/25381L is insufficient.         Monep1         Acknowledged         Monep1<	Exceptions (Discrepancies) This Estimate Period			Ctatus	
Number 1990, Material 10365/SET CL2AM 6 - Res Istell C Ao. SM16 Gr         complefic         complefic           Estimate Exception Action General Colos SM10 Gr         Organization Action General Colos SM10 Gr         Organization Action General Colos SM10 Gr           Estimate Exception Action General Colos SM10 Gr         Organization Action General Colos SM10 Gr         Organization Action General Colos SM10 Gr           Estimate Exception Action General Colos SM10 Gr         Organization Action General Colos SM10 Gr         Need PAL to be submitted         Meed PAL to be submitted	Exceptions / Discrepencies	Explanation	Entered By	Status	
Number 3980, Material 5986 (75903), Material 5986/850/FE-CA2M19 - Rein Steel EC No. 6M19 Gr         complete           BitMacho (B), Consplexe Action Genetic Resteellants in multident.         Need PAL to be submitted         Kleepil         Acknowledged           Acceptance Action Genetic Resteellants in multident.         Need PAL to be submitted         Kleepil         Acknowledged           Acceptance Action Genetic Resteellants in multident.         Need PAL to be submitted         Kleepil         Acknowledged           Acceptance Action Genetic Resteellants in submitted         Need PAL to be submitted         Kleepil         Acknowledged           Acceptance Action Genetic Resteellants in submitted         Need PAL to be submitted         Kleepil         Acknowledged           Acceptance Action Genetic Resteellants is multifoant.         Need PAL to be submitted         Kleepil         Acknowledged           Acceptance Action Genetic Resteellants is multifoant.         Need PAL to be submitted         Kleepil         Acknowledged           Acceptance Action Genetic Resteellants is multifoant.         Need PAL to be submitted         Kleepil         Acknowledged           Acceptance Action Genetic Resteellants in Strepide I Resteellants in Resteellants in Resteellants in Resteellants in Resteellant Resteellants in Resteellants in Resteellants in R	Number 3990, Material Set 6179903, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr		kloepj1	Overridden	
Number 1950. Material Set 2003113, Material M3052SBL - Concrete Sealer (CS) - Slame (B).         Need PAL to be submitted         Need PAL to be submitted         Kloepit           Extinuet Exception Type: Institution         Extinuet Exception Type: Institution         Need PAL to be submitted         Kloepit         Acknowledged           Accoptance Action Generin 05052SBL in Institution         Extinuet Exception Type: Institution         Kloepit         Acknowledged           Accoptance Action Generin 05052SBL in Institution         Extinuet Exception Type: Institution         Kloepit         Acknowledged           Number 1970. Material Set 703015. Material 1903CBL - Concrete Sealer (CS) - Slame (B).         Need PAL to be submitted         Kloepit         Acknowledged           Accoptance Action Generin 05052SBL in Institution         Extinuet Exception Type: Institution Materials Project J08149, Item 703013, Project Item Line (B).         Need PAL to be submitted         Kloepit         Acknowledged           Accoptance Action Generin 05052SBL in Institution         Extinuet Exception Type: Institution         Kloepit         Acknowledged           Accoptance Action Generin 05052SBL in Institution         Extinuet Exception Type: Institution         Kloepit         Acknowledged           Acknowledged Institution         Kloepit         Acknowledged Institution         Kloepit         Acknowledged Institution           Extinute Exception Type: Institution         Lonovledged Insti	Number 3990, Material Set 6179903, Material 1036RSDFEC42M19 - Rein Steel EC No. 6/M19 Gr		kloepj1	Overridden	
Number 0970, Material Set 7330173, Material 1053CSSL - Concrete Sealer (CS) - Stane (),       Reed PAL to be submitted       Koepil         Estimate Exception Type: Insufficient Materials: Project J03140, Item 7033013, Project Item Line       Need PAL to be submitted       Koepil         Acknowledged       Acknowledged         Number 170, Material Set 7033017, Material 1053CSSL - Concrete Sealer (CS) - Stane (),       Need PAL to be submitted       Koepil         Acknowledged       Reed PAL to be submitted       Koepil       Acknowledged         Number 720, Material Set 7033017, Material 1053CSSL - Concrete Sealer (CS) - Stane (),       Need PAL to be submitted       Koepil       Acknowledged         Acceptance Action Genetic 053CSSEL is insufficiant.       Concrete Sealer (CS) - Stane (),       Need PAL to be submitted       Koepil       Acknowledged         Acceptance Action Genetic 053CSSEL is insufficiant.       Concrete Sealer (CS) - Stane (),       Need PAL to be submitted       Koepil       Acknowledged         Acceptance Action Genetic 053CSSEL is insufficiant.       Concrete Sealer (CS) - Stane (),       Need PAL to be submitted       Koepil       Acknowledged         Acceptance Action Genetic 053CSSEL is insufficiant.       Concrete Sealer (CS) - Stane (),       Need PAL to be submitted       Koepil       Acknowledged         Acceptance Action Genetic 053CSSEL is insufficiant.       Concrete Sealer (CS) - Stane (),       Need PAL to be submit	Number 0760, Material Set 7033013, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,	Need PAL to be submitted	kloepj1	Acknowledged	
Number 1790, Material Ser 7033013, Material 1053CCSSIL - Concrete Sealer (CS) - Silane (),         Need PAL to be submitted         Need PAL to be submitted         Neep11           Edimate Exception Type: Insufficient Materials: Project J803149, Item 7033013, Project Item Line Number 2300, Material 1053CCSSIL - Sonzete Sealer (CS) - Silane (),         Need PAL to be submitted         Neep11         Acknowledged           Edimate Exception Type: Insufficient Materials: Project J803149, Item 7033013, Project Item Line Number 2300, Material 1053CCSSIL - Sonzete Sealer (CS) - Silane (),         Need PAL to be submitted         Neep11         Acknowledged           Edimate Exception Type: Insufficient Materials: Project J803149, Item 7033013, Project Item Line Number 2300, Material 1053CCSSIL - Concrete Sealer (CS) - Silane (),         Need PAL to be submitted         Neep11         Acknowledged           Number 2300, Material Ser 7032013, Material 1053CCSSIL - Concrete Sealer (CS) - Silane (),         Orgoing Item, testing cannot be completed until installation is Complete         Orgoing Item, testing cannot be completed until installation is Complete         Overridden           Stringer 2300, Material Ser 703212, Sign Material 1053CCSSIL - Concrete Modified B-2 w/Ar, Acceptance Action Generic 053CCSILAD As insufficient.         Sign Orgoing Item, testing cannot be completed until installation is Complete         Overridden           Number 2300, Material Ser 703212306, Material 053CCSBL - Concrete Sealer (CS) - Silane (C	Number 0970, Material Set 7033013, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,	Need PAL to be submitted	kloepj1	Acknowledged	
Number 1380, Material Set 7033013, Material 1053CSSIL - Concrete Sealer (CS) - Silane (),         Need PAL to be submitted         Need PAL to be submitted         Kiloepit         Acknowledged           Estimate Exception Type: Insufficient Materials: Project J8(1349, Item 7033013, Project Item Line Acceptance Action Generic 1053CSSIL - Sonzeles Sealer (CS) - Silane (),         Need PAL to be submitted         Kiloepit         Acknowledged           Acceptance Action Generic 1053CSSIL - Sonzeles Sealer (CS) - Silane (),         Need PAL to be submitted         Kiloepit         Acknowledged           Acceptance Action Generic 1033CSSIL - Sonzeles Sealer (CS) - Silane (),         Need PAL to be submitted         Kiloepit         Acknowledged           Acceptance Action Generic 1033CSSIL - Sonzele Sealer (CS) - Silane (),         Ongoing Item, testing cannot be completed until installation is complete         Kiloepit         Overridden           Number 2780, Material Set 703421286, Material 30703LP - Sitay in Place Forms, Acceptance Action Generic 37033PF is insufficient.         Molepit I         Molepit I         Nonepit I	Number 1170, Material Set 7033013, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,	Need PAL to be submitted	kloepj1	Acknowledged	
Number 2420, Material Sch 7033013, Material 1053CSSIL - Concrete Sealer (CS) - Silane (C), concrete (C), concrete Sealer (CS) - Silane (C), concrete Sealer (CS) - Silane (C), concrete (C), concrete Sealer (CS) - Silane (C), concrete (C), concrete Sealer (CS) - Silane (C), concrete (C), concrete (CS) - Silane (C), concrete (C), concrete (C), concrete (C), concrete (CS) - Silane (C), concrete (C), concrete (C), concrete (C), concrete (CS) - Silane (C), concrete (C), concrete (C), concrete (C), concrete (CS) - Silane (C), concrete (C), concrete (C),	Number 1380, Material Set 7033013, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,	Need PAL to be submitted	kloepj1	Acknowledged	
Number 3200, Material 5er 7033013, Material 1033CSBL, Concrete Sealer (CS) - Silane (),         Concentione Action Generic 0503CSBL is insufficient.         Kiese ()           Estimate Exception Type: Insufficient Materials: Project J8i3149, Item 7034212, Project Item Line Number 2780, Material 5er 703421296, Material 37033IPF - Stay in Place Forms, Acceptance Action Ceneric 0501CCB2/MAD is insufficient.         Overridden         Verridden           Estimate Exception Type: Insufficient Materials: Project J8i3149, Item 7034212, Project Item Line Number 2780, Material 5er 703421296, Material 0501CCB2/MAD is insufficient.         Waiting on 28 day breaks         Koepi ()         Overridden           Estimate Exception Type: Insufficient Materials: Project J8i3149, Item 7034212, Project Item Line Number 2780, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane ()         Ongoing item, testing cannot be completed until installation is         Kloepi ()         Overridden           Estimate Exception Type: Insufficient Material: Project J8i3149, Item 7034214, Project Item Line Number 2780, Material Set 703421496, Material 10057ACCNS. CA - Natural Sand for Conc Class A, Acceptance Action Generic 1055CKCNS. CA - Natural Sand for Conc Class A, Acceptance Action Generic 0507CCB2 A: Insufficient Materials: Project J8i3149, Item 7034214, Project Item Line Number 2780, Material Set 703421496, Material 0501CCB2 A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2 A: Insufficient Materials: Project J8i3149, Item 7034214, Project Item Line Number 1800, Material Set 703421496, Material 0501CCB2 A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2 A: Insufficient Materials: Project J8i3149, Item 7034214, Project Item Line Number 1800, Material Set 703421496, Materia	Number 2420, Material Set 7033013, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,	Need PAL to be submitted	kloepj1	Acknowledged	
Number 2780, Material Set 703421296, Material 37/03SIPF - Stay in Place Forms, Acceptance Action         complete         complete <td>Number 3200, Material Set 7033013, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,</td> <td>Need PAL to be submitted</td> <td>kloepj1</td> <td>Acknowledged</td>	Number 3200, Material Set 7033013, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,	Need PAL to be submitted	kloepj1	Acknowledged	
Number 2780, Material Set 703421296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.Concrete Sealer (CS) - Silane (CS) - Silane 	Number 2780, Material Set 703421296, Material 3703SIPF - Stay in Place Forms, Acceptance Action		kloepj1	Overridden	
Number 2780, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @.       complete	Number 2780, Material Set 703421296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air,	Waiting on 28 day breaks	kloepj1	Overridden	
Number 0770, Material Set 703421496, Material 1005FACCNS.:CA - Natural Sand for Conc Class A,       complete       complete       complete         Status E Scoption Type: Insufficient Materials: Project J6i3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloep1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6i3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloep1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6i3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloep1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6i3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloep1       Overridden         Number 0300, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Acceptance Action Generic 0501CCB2.A is insufficient.       Vaiting on 28 day breaks       kloep1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6i3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloep1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6i3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloep1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6i3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloep1       Overridden	Number 2780, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,		kloepj1	Overridden	
Number 0980, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Waiting on 28 day breaks       kloepi1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6l3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6l3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6l3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6l3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6l3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Stimate Exception Type: Insuffic	Number 0770, Material Set 703421496, Material 1005FACCNSCA - Natural Sand for Conc Class A,		kloepj1	Overridden	
Number 1180, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Waiting on 28 day breaks       kloepi1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Estimate Exception Type: Insufficient Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Waiting on 28 day breaks       kloepi1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Number 3430, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Waiting on 28 day breaks       kloepi1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Number 3210, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Waiting on 28 day breaks       kloepi1       Overridden         Stimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepi1       Overridden         Stimate Exception Type: Insufficient Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Maiting on 28 day breaks       kloepi1       Overridden         Number 3210, Material Set 703421	Number 0980, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance	Waiting on 28 day breaks	kloepj1	Overridden	
Number 1390, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Stimate Exception Type: Insufficient.         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepj1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepj1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepj1       Overridden         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepj1       Overridden         Number 3210, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Acceptance       Stimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034214, Project Item Line       Waiting on 28 day breaks       kloepj1       Overridden         Number 2440, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Concrete Class B-2 w/Air, Acceptance       Stimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034215, Project Item Line       Nogoing item, testing cannot be completed until installation is       kloepj1       Overridden         Number 2440, Material Set 703421596, Material 1065DE - Delineators, Acceptance Action Generic       Ongoing item, testing cannot be completed until installat	Number 1180, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance	Waiting on 28 day breaks	kloepj1	Overridden	
Number 2430, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Waiting on 28 day breaks       Voi 1000000000000000000000000000000000000	Number 1390, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance	Waiting on 28 day breaks	kloepj1	Overridden	
Number 3210, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance       Concrete, Class B-2 w/Air, Acceptance         Action Generic 0501CCB2.A is insufficient.       Ongoing item, testing cannot be completed until installation is         Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034215, Project Item Line       Ongoing item, testing cannot be completed until installation is         Number 2440, Material Set 703421596, Material 1065DE - Delineators, Acceptance Action Generic       Ongoing item, testing cannot be completed until installation is	Number 2430, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance	Waiting on 28 day breaks	kloepj1	Overridden	
Number 2440, Material Set 703421596, Material 1065DE - Delineators, Acceptance Action Generic         complete           1065DE is insufficient.         complete	Number 3210, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance	Waiting on 28 day breaks	kloepj1	Overridden	
	Number 2440, Material Set 703421596, Material 1065DE - Delineators, Acceptance Action Generic		kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034215, Project Item Line Number 2440, Material Set 703421596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.		Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034215, Project Item Line Number 2440, Material Set 703421596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Number 2440, Material Set 703421596, Material 1005FACCNSCA - Natural Sand for Conc Class A,		kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034215, Project Item Line Number 2440, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Number 2440, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance	Waiting on 28 day breaks	kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034215, Project Item Line Number 2440, Material Set 703421596, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Number 2440, Material Set 703421596, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,		kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034215, Project Item Line Number 3220, Material Set 703421596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Number 3220, Material Set 703421596, Material 1005FACCNSCA - Natural Sand for Conc Class A,		kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034215, Project Item Line Number 3220, Material Set 703421596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,			kloepj1	Overridden	



Exceptions (Discrepancies) This Estimate Period		Entered						
Exceptions / Discrepencies	Exceptions / Discrepencies Explanation							
Acceptance Action Generic 100510CPCMLD is insufficient.								
Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7034215, Project Item Line Number 3220, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034215, Project Item Line Number 3220, Material Set 703421596, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034215, Project Item Line Number 3220, Material Set 703421596, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034219A, Project Item Line Number 2790, Material Set 7034219A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034219A, Project Item Line Number 2790, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034219A, Project Item Line Number 2790, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7034219A, Project Item Line Number 2790, Material Set 7034219A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7039907, Project Item Line Number 2800, Material Set 703990796, Material 4501CCUHPC - Concrete, Ultra High Performance Concrete JSP, Acceptance Action Generic 4501CCUHPC is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040101, Project Item Line Number 2810, Material Set 704010196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040104, Project Item Line Number 1000, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040104, Project Item Line Number 1220, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040104, Project Item Line Number 1430, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	430, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, tester		Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040104, Project Item Line Number 1840, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040106, Project Item Line Number 1230, Material Set 704010696, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040106, Project Item Line Number 1440, Material Set 704010696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Currently addressing testing discrepancies with 3rd party tester	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040106, Project Item Line Number 1440, Material Set 704010696, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040112, Project Item Line Number 1030, Material Set 704011296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040112, Project Item Line Number 1030, Material Set 704011296, Material 0501CCPAEA - Concrete, Pavement HES w/Air, Acceptance Action Generic 0501CCPAEA is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040112, Project Item Line Number 2500, Material Set 704011296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7040112, Project Item Line Number 3260, Material Set 704011296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day breaks	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7049903, Project Item Line Number 2520, Material Set 7049903, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7061000, Project Item Line Number 6007, Material Set 706100096, Material 1036RSSRPLAB - Plain Spiral Stl Rein for Anchor Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7061000, Project Item Line Number 6007, Material Set 706100096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden					
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7061000, Project Item Line	Working with Materials to adjust materials testing	kloepj1	Overridden					



Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered By	Status
Number 6007, Material Set 706100096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7061000, Project Item Line Number 6007, Material Set 706100096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7061000, Project Item Line Number 6007, Material Set 706100096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7061000, Project Item Line Number 6007, Material Set 706100096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7061000, Project Item Line Number 6007, Material Set 706100096, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7061000, Project Item Line Number 6007, Material Set 706100096, Material 1036RSDFPL42M22 - Reinforcing Steel No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7061000, Project Item Line Number 6007, Material Set 706100096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7061000, Project Item Line Number 6008, Material Set 706100096, Material 1036RSSRPLAB - Plain Spiral Stl Rein for Anchor Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7061000, Project Item Line Number 6008, Material Set 706100096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7061000, Project Item Line Number 6008, Material Set 706100096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7061000, Project Item Line Number 6008, Material Set 706100096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7061000, Project Item Line Number 6008, Material Set 706100096, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7061000, Project Item Line Number 6008, Material Set 706100096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7061000, Project Item Line Number 6008, Material Set 706100096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7061000, Project Item Line Number 6008, Material Set 706100096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7061000, Project Item Line Number 6008, Material Set 706100096, Material 1036RSDFPL42M22 - Reinforcing Steel No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with Materials to adjust materials testing	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7071000, Project Item Line Number 2830, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7071000, Project Item Line Number 2830, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 7123620, Project Item Line Number 2860, Material Set 712362096, Material 0712STDS - Drainage System on Structure, Acceptance Action Generic 0712STDS is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3187, Item 7319902, Project Item Line Number 4120, Material Set 7319902, Material 0614DFGTBP - Grates and Bearing Plates, Acceptance Action Generic 0614DFGTBP is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3187, Item 7319902, Project Item Line Number 4120, Material Set 7319902, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3149, Item 7319902, Project Item Line Number 0450, Material Set 7319902, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 9011070, Project Item Line Number 0560, Material Set 901107096, Material 0901LHZCAB - Bolts Galv Anchor for Highway Lighting, Acceptance Action Generic 0901LHZCAB is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 9011070, Project Item Line Number 0560, Material Set 901107096, Material 1091LHLP - Highway Lighting Pole, Acceptance Action Generic 1091LHLP is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden



Exceptions (Discrepancies) This Estimate Penou				
Exceptions / Discrepencies	Explanation	Entered By	Status	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 9011070, Project Item Line Number 0560, Material Set 901107096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 9011104, Project Item Line Number 0570, Material Set 901110496, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 9011104, Project Item Line Number 0570, Material Set 901110496, Material 1091LHLP - Highway Lighting Pole, Acceptance Action Generic 1091LHLP is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 9013003, Project Item Line Number 0590, Material Set 901300396, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 9016110, Project Item Line Number 0610, Material Set 901611096, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 9017006, Project Item Line Number 0620, Material Set 901700696, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3149, Item 9017206, Project Item Line Number 0640, Material Set 901720696, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden	
Estimate Exception Type: Insufficient Materials: Project J6I3187, Item 9039901, Project Item Line Number 6101, Material Set 9039901, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient.	Ongoing item, testing cannot be completed until installation is complete	kloepj1	Overridden	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 0940, Contract Line Item Number 0940, Item 5050004, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 1000, Contract Line Item Number 1000, Item 7040104, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 1220, Contract Line Item Number 1220, Item 7040104, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 1430, Contract Line Item Number 1430, Item 7040104, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 2810, Contract Line Item Number 2810, Item 7040101, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3187, Project Item Line Number 3860, Contract Line Item Number 3860, Item 6131015, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3187, Project Item Line Number 3870, Contract Line Item Number 3870, Item 6131017, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3187, Project Item Line Number 3880, Contract Line Item Number 3880, Item 6131018, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 0050, Contract Line Item Number 0050, Item 4030101, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 0180, Contract Line Item Number 0180, Item 6122020, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 0190, Contract Line Item Number 0190, Item 6122030, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 0300, Contract Line Item Number 0300, Item 6173600D, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 0730, Contract Line Item Number 0730, Item 5050004, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 0800, Contract Line Item Number 0800, Item 7040104, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	
Estimate Exception Type: Item Overrun: Contract 220218-F06, Contract Project J6I3149, Project Item Line Number 1350, Contract Line Item Number 1350, Item 5050004, Minor Item.	To be adjusted on an upcoming change order	kloepj1	Acknowledged	

### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
20218-F06	J6I3149	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$1,263,263.16	\$505,305.2
		0001	0020	2153000	SHAPING SLOPES, CLASS III	9.00	0.00	9.00	100F	0.00	\$900.00	\$0.0
		0001	0030	3102002	CRUSHED STONE (B)	750.00	0.00	750.00	TONS	76.00	\$47.00	\$3,572.0
		0001	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	203.10	0.00	203.10	TONS	0.00	\$122.00	\$0.0
		0001	0050	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	316.80	0.00	316.80	TONS	322.60	\$122.00	\$39,357.2
		0001	0060	4030105	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125C MIX)	497.90	0.00	497.90	TONS	281.30	\$122.00	\$34,318.6
		0001	0070	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	1,459.00	0.00	1,459.00	TONS	653.31	\$157.00	\$102,569.6
		0001	0080	4030206	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP190C MIX)	152.50	0.00	152.50	TONS	0.00	\$127.00	\$0.0
		0001	0090	4071005	TACK COAT	2,689.00	350.00	3,039.00	GAL	1,217.00	\$2.50	\$3,042.5
		0001	0100	4136000	PCCP JOINT/CRACK SEALING	15,000.00	0.00	15,000.00	LF	0.00	\$5.75	\$0.0
		0001	0110	5041000	CONCRETE APPROACH PAVEMENT	5,556.40	0.00	5,556.40	SQYD	2,810.20	\$117.00	\$328,793.4
		0001	0120	6083006	6 IN. CONCRETE MEDIAN STRIP	35.40	0.00	35.40	SQYD	11.00	\$155.00	\$1,705.0
		0001	0130	6086004	CONCRETE SIDEWALK, 4 IN.	325.70	0.00	325.70	SQYD	0.00	\$49.50	\$0.0
		0001	0140	6091052	CURB AND GUTTER TYPE B	20.00	0.00	20.00	LF	0.00	\$49.80	\$0.0
		0001	0150	6099903		1,956.00	0.00	1,956.00	LF	102.00	\$42.25	\$4,309.5
		0001	0160	6116010A	SLOPE PROTECTION	2,022.00	0.00	2,022.00	SQYD	287.00	\$95.00	\$27,265.0
		0001	0170	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	15.00	0.00	15.00	EA	7.00	\$3,025.00	\$21,175.0
		0001	0180	6122020	REPLACEMENT SAND BARREL	15.00	0.00	15.00	EA	18.00	\$448.00	\$8,064.0
		0001	0190	6122030	IMPACT ATTENUATOR (RELOCATION)	8.00	0.00	8.00	EA	10.00	\$678.00	\$6,780.0
		0001	0200	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	5.00	0.00	5.00	EA	0.00	\$3,000.00	\$0.00
		0001	0210	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	58.70	0.00	58.70	SQYD	39.00	\$230.00	\$8,970.00
		0001	0220	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	556.00	0.00	556.00	SQYD	2.00	\$18.00	\$36.00
		0001	0230	6139905	MISC.Type 1 or 5 Aggregate for Base (Var. Thick) (Pavement Repair)	59.00	0.00	59.00	SQYD	39.00	\$19.00	\$741.00
		0001	0240	6169901	MISC.Temporary Traffic Control	1.00	0.00	1.00	LS	0.50	\$780,000.00	\$390,000.00
		0001	0250	6169901	MISC.Traffic Signal Maintenance and Programming	1.00	0.00	1.00	LS	0.00	\$50,000.00	\$0.0
		0001	0260	6169902	MISC.NTCIP Compliant Changeable Message Sign (Contractor Furnished and Retained	8.00	0.00	8.00	EA	6.00	\$2,500.00	\$15,000.0
		0001	0270	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	34.00	0.00	34.00	LF	34.00	\$185.00	\$6,290.0
		0001	0280	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	9,338.00	0.00	9,338.00	LF	5,080.00	\$72.00	\$365,760.0
		0001	0290	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	577.00	0.00	577.00	LF	0.00	\$182.00	\$0.00
		0001	0300	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	16,457.00	0.00	16,457.00	LF	17,587.50	\$21.75	\$382,528.12
		0001	0310	6173700B	RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR	14,698.00	0.00	14,698.00	LF	7,300.00	\$26.40	\$192,720.00
			0220		FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION		0.00	852.00	LF		606.40	¢0.00
		0001	0320	6173706	SECTION, CONTRACTOR FURNISHED / RETAINED	852.00	0.00			0.00	\$26.40	\$0.00
		0001	0330	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	3,165.00	0.00	3,165.00	LF	3,054.00	\$14.50	\$44,283.00
		0001	0340	6181000	MOBILIZATION	1.00	-1.00	0.00	LS		\$2,700,000.00	\$0.00
		0001	0341	6181000	MOBILIZATION	0.00	1.00	1.00	LS		\$2,329,568.00	\$1,747,176.00
		0001	0350	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	23,269.00	0.00	23,269.00	LF	0.00	\$0.30	\$0.00
		0001	0360	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	18,706.00	0.00	18,706.00	LF	0.00	\$0.30	\$0.00
		0001	0370	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	451.00	0.00	451.00	LF	0.00	\$1.00	\$0.0
		0001	0380	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$6,000.00	\$0.0
		0001	0390	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	11,210.00	0.00	11,210.00	SQYD	5,967.00	\$2.52	\$15,036.84
		0001	0400	6221003	SURFACING (3 IN. THICK OR LESS) COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	3,601.00	0.00	3,601.00	SQYD	1,944.00	\$4.15	\$8,067.6
					SURFACING (GREATER THAN 3 IN. THICK)							
		0001	0410	6221011	COLDMILLING CONCRETE PAVEMENT FOR REMOVAL OF SURFACE	73.00	0.00	73.00	SQYD	0.00	\$44.38	\$0.0
		0001	0420	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	4,105.00	0.00	4,105.00	SQYD	0.00	\$5.85	\$0.00
		0001	0430	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	91.50	0.00	91.50	STA	0.00	\$27.00	\$0.00



### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
20218-F06	J6I3149	0001	0440	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.16	\$175,000.00	\$28,000.0
		0001	0450	7319902	MISC.Inlet Top Replacement (In Kind)	19.00	0.00	19.00	EA	6.00	\$2,600.00	\$15,600.0
		0001	0460	8059919	MISC.Seeding - Sigma Chemical Co.	2.50	0.00	2.50	ACRE	0.00	\$3,350.00	\$0.0
		0001	0470	8061016	SEDIMENT REMOVAL	3.00	0.00	3.00	CUYD	0.00	\$300.00	\$0.0
		0001	0480	8061019	SILT FENCE	228.00	0.00	228.00	LF	0.00	\$2.20	\$0.0
			0490	6061060	MGS GUARDRAIL	5,873.00	0.00	5,873.00	LF	2,334.00	\$33.00	\$77,022.0
		0010	0500	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	500.00	0.00	500.00	LF	0.00	\$38.00	\$0.0
		0010	0510	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	18.00	0.00	18.00	EA	8.00	\$3,800.00	\$30,400.
		0010	0520	6061080	MGS END ANCHOR	8.00	0.00	8.00	EA	3.00	\$1,500.00	\$4,500.
		0010	0530	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	9.00	0.00	9.00	EA	3.00	\$3,100.00	\$9,300.
		0010	0540	6063019	TYPE E CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	1.00	\$29,500.00	\$29,500.
		0010	0550	6069903	MISC.MGS Concrete Barrier Transition (Thrie Beam Rail)	138.00	0.00	138.00	LF	124.00	\$84.00	\$10,416.
		0020	0560	9011070	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE B DESIGN 3	4.00	0.00	4.00	EA	2.00	\$3,301.00	\$6,602.
		0020	0570	9011104	BRACKET ARM, 4 FT. OR 1.2 M	4.00	0.00	4.00	EA	2.00	\$415.00	\$830.
		0020	0580	9011313	LUMINAIRE, LED-C	4.00	0.00	4.00	EA	2.00	\$452.00	\$904.
		0020	0590	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	68.00	0.00	68.00	LF	37.00	\$21.00	\$777.
		0020	0600	9015010	TRENCHING TYPE I	68.00	0.00	68.00	LF	37.00	\$12.00	\$444.
		0020	0610	9016110	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	2.00	\$2,000.00	\$4,000.
		0020	0620	9017006	CABLE, 6 AWG 1 CONDUCTOR	3,030.00	0.00	3,030.00	LF	1,530.00	\$2.00	\$3,060.
		0020	0630	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	650.00	0.00	650.00	LF	0.00	\$1.00	\$0.
		0020	0640	9017206	WIRE, 6 AWG, BARE NEUTRAL	1,530.00	0.00	1,530.00	LF	770.00	\$2.00	\$1,540.
		0020	0650	9019901	MISC.Maintain &/or Reinstall Existing MoDOT Lighting	1.00	0.00	1.00	LS	0.00	\$140,500.00	\$0.
		0050	0660	9109902	MISC.MoDOT ITS Facility Temporary Relocation on I-55 at 2nd Street	1.00	0.00	1.00	EA	0.00	\$76,075.00	\$0.
		0070	0670	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,073.00	0.00	1,073.00	SQYD	1,073.00	\$48.00	\$51,504.
		0070	0680	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,660.00	0.00	9,660.00	SQFT	9,660.00	\$2.00	\$19,320.
		0070	0690	2161503	REMOVAL OF EXISTING DECK REPAIR	624.00	0.00	624.00	SQFT	4.00	\$22.00	\$88.
		0070	0700	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$2,705.00	\$2,705.
		0070	0710	2169903	MISC.Removal of Existing Approach Notch	124.00	0.00	124.00	LF	124.00	\$160.00	\$19,840.
		0070	0720	5031010A	BRIDGE APPROACH SLAB (MAJOR)	281.00	0.00	281.00	SQYD	281.00	\$280.00	\$78,680.
		0070	0730	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	8.00	0.00	8.00	CY	15.00	\$700.00	\$10,500.
		0070	0740	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,073.00	0.00	1,073.00	SQYD	1,073.00	\$138.00	\$148,074.
		0070	0750	7031004	DIAMOND GRINDING	1,073.00	0.00	1,073.00	SQYD	0.00	\$10.30	\$0.
		0070	0760	7033013	PENETRATING CONCRETE SEALER	117.00	0.00	117.00	SY	117.00	\$5.00	\$585.
		0070	0770	7034214	CLASS B-2 CONCRETE	3.40	0.00	3.40	CUYD	3.40	\$4,500.00	\$15,300.
		0070	0780	7039903	MISC.Median Barrier Transition (Type B)	40.00	0.00	40.00	LF	0.00	\$200.00	\$0.
		0070	0790	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	20.00	0.00	20.00	SQFT	0.00	\$134.75	\$0.
		0070	0800	7040104	HALF-SOLE REPAIR	250.00	0.00	250.00	SQFT	285.00	\$98.50	\$28,072
		0070	0810	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	0.00	\$215.00	\$0.
		0070	0820	7040107	SLAB EDGE REPAIR (BRIDGES)	15.00	0.00	15.00	LF	0.00	\$222.00	\$0.
		0070	0830	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	500.00	0.00	500.00	SQFT	52.00	\$108.00	\$5,616.
		0070	0840	7040113	CLEANING AND EPOXY COATING	50.00	0.00	50.00	SQFT	0.00	\$20.00	\$0.
		0070	0850	7049903	MISC.Curb Repair (Formed)	20.00	0.00	20.00	LF	0.00	\$147.25	\$0.
		0070	0860	7101000	REINFORCING STEEL (EPOXY COATED)	880.00	0.00	880.00	LB	880.00	\$3.00	\$2,640
		0070	0870	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0.0
		0071	0880	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,073.00	0.00	1,073.00	SQYD	1,073.00	\$49.00	\$52,577.0



### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
20218-F06	J6I3149	0071	0890	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,660.00	0.00	9,660.00	SQFT	9,660.00	\$2.00	\$19,320.0
		0071	0900	2161503	REMOVAL OF EXISTING DECK REPAIR	624.00	0.00	624.00	SQFT	33.00	\$22.00	\$726.0
		0071	0910	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$2,705.00	\$2,705.0
		0071	0920	2169903	MISC.Removal of Existing Approach Notch	124.00	0.00	124.00	LF	62.00	\$160.00	\$9,920.0
		0071	0930	5031010A	BRIDGE APPROACH SLAB (MAJOR)	281.00	0.00	281.00	SQYD	153.00	\$300.00	\$45,900.0
		0071	0940	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	8.00	0.00	8.00	CY	23.00	\$700.00	\$16,100.0
		0071	0950	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,073.00	0.00	1,073.00	SQYD	1,073.00	\$130.00	\$139,490.0
		0071	0960	7031004	DIAMOND GRINDING	1,073.00	0.00	1,073.00	SQYD	0.00	\$10.30	\$0.0
		0071	0970	7033013	PENETRATING CONCRETE SEALER	117.00	0.00	117.00	SY	117.00	\$5.00	\$585.0
		0071	0980	7034214	CLASS B-2 CONCRETE	3.40	0.00	3.40	CUYD	3.40	\$4,500.00	\$15,300.0
		0071	0990	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	35.00	0.00	35.00	SQFT	0.00	\$134.75	\$0.0
		0071	1000	7040104	HALF-SOLE REPAIR	250.00	0.00	250.00	SQFT	289.00	\$98.50	\$28,466.5
		0071	1010	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	0.00	\$215.00	\$0.0
		0071	1020	7040107	SLAB EDGE REPAIR (BRIDGES)	25.00	0.00	25.00	LF	0.00	\$230.00	\$0.0
		0071	1030	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	500.00	0.00	500.00	SQFT	301.00	\$108.00	\$32,508.0
		0071	1040	7040113	CLEANING AND EPOXY COATING	50.00	0.00	50.00	SQFT	0.00	\$20.00	\$0.0
		0071	1050	7049903	MISC.Curb Repair (Formed)	20.00	0.00	20.00	LF	0.00	\$147.25	\$0.0
		0071	1060	7101000	REINFORCING STEEL (EPOXY COATED)	880.00	0.00	880.00	LB	880.00	\$2.00	\$1,760.0
		0071	1070	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0.0
		0072	1080	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,133.00	0.00	1,133.00	SQYD	1,133.00	\$48.00	\$54,384.0
		0072	1090	2161502	REMOVAL OF CONCRETE WEARING SURFACE	10,193.00	0.00	10,193.00	SQFT	10,193.00	\$2.00	\$20,386.0
		0072	1100	2161503	REMOVAL OF EXISTING DECK REPAIR	424.00	0.00	424.00	SQFT	3.00	\$22.00	\$66.0
		0072	1110	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$2,705.00	\$2,705.0
		0072	1120	2169903	MISC.Removal os Existing Approach Notch	124.00	0.00	124.00	LF	124.00	\$160.00	\$19,840.0
		0072	1130	5031010A	BRIDGE APPROACH SLAB (MAJOR)	281.00	0.00	281.00	SQYD	173.00	\$300.00	\$51,900.0
		0072	1140	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	9.00	0.00	9.00	CY	9.00	\$700.00	\$6,300.0
		0072	1150	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,133.00	0.00	1,133.00	SQYD	1,133.00	\$130.00	\$147,290.0
		0072	1160	7031004	DIAMOND GRINDING	1,133.00	0.00	1,133.00	SQYD	0.00	\$10.30	\$0.0
		0072	1170	7033013	PENETRATING CONCRETE SEALER	123.00	0.00	123.00	SY	123.00	\$5.00	\$615.0
		0072	1180	7034214	CLASS B-2 CONCRETE	3.40	0.00	3.40	CUYD	3.40	\$4,500.00	\$15,300.0
		0072	1190	7039903	MISC.Median Barrier Transition (Type B)	40.00	0.00	40.00	LF	0.00	\$200.00	\$0.0
		0072	1200	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	20.00	0.00	20.00	SQFT	0.00	\$134.75	\$0.0
		0072	1210	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	10.00	0.00	10.00	SQFT	0.00	\$233.00	\$0.0
		0072	1220	7040104	HALF-SOLE REPAIR	250.00	0.00	250.00	SQFT	298.00	\$98.50	\$29,353.0
		0072	1230	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	4.00	\$215.00	\$860.0
		0072	1240	7040107	SLAB EDGE REPAIR (BRIDGES)	10.00	0.00	10.00	LF	0.00	\$235.00	\$0.0
		0072	1250	7040113	CLEANING AND EPOXY COATING	50.00	0.00	50.00	SQFT	0.00	\$20.00	\$0.0
		0072	1260	7049903	MISC.Curb Repair (Formed)	25.00	0.00	25.00	LF	0.00	\$147.25	\$0.0
		0072	1270	7101000	REINFORCING STEEL (EPOXY COATED)	970.00	0.00	970.00	LB	970.00	\$2.00	\$1,940.0
		0072	1280	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0.0
		0073	1290	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,133.00	0.00	1,133.00	SQYD	1,133.00	\$48.00	\$54,384.0
		0073	1300	2161502	REMOVAL OF CONCRETE WEARING SURFACE	10,193.00	0.00	10,193.00	SQFT	10,193.00	\$2.00	\$20,386.0
		0073	1310	2161503	REMOVAL OF EXISTING DECK REPAIR	427.00	0.00	427.00	SQFT	28.00	\$22.00	\$616.0
		0073	1320	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$2,705.00	\$2,705.0
		0073	1330	2169903	MISC.Removal of Existing Approach Notch	124.00	0.00	124.00	LF	124.00	\$160.00	\$19,840.0
		0073	1340	5031010A	BRIDGE APPROACH SLAB (MAJOR)	281.00	0.00	281.00	SQYD	281.00	\$300.00	\$84,300.0

# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

### Total Paid / All Items / All Estimates (Including this Estimate)

ed date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
20218-F06	J6I3149	0073	1350	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	9.00	0.00	9.00	CY	10.00	\$700.00	\$7,000.0
		0073	1360	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,133.00	0.00	1,133.00	SQYD	1,133.00	\$130.00	\$147,290.0
		0073	1370	7031004	DIAMOND GRINDING	1,133.00	0.00	1,133.00	SQYD	0.00	\$10.30	\$0.0
		0073	1380	7033013	PENETRATING CONCRETE SEALER	123.00	0.00	123.00	SY	123.00	\$5.00	\$615.0
		0073	1390	7034214	CLASS B-2 CONCRETE	3.40	0.00	3.40	CUYD	3.40	\$4,500.00	\$15,300.0
		0073	1400	7040101	SUBSTRUCTURE REPAIR (FORMED)	150.00	0.00	150.00	SQFT	0.00	\$146.75	\$0.0
		0073	1410	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	40.00	0.00	40.00	SQFT	0.00	\$188.00	\$0.0
		0073	1420	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	20.00	0.00	20.00	SQFT	0.00	\$179.75	\$0.0
		0073	1430	7040104	HALF-SOLE REPAIR	250.00	0.00	250.00	SQFT	290.00	\$98.50	\$28,565.0
		0073	1440	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	3.00	\$215.00	\$645.0
		0073	1450	7040107	SLAB EDGE REPAIR (BRIDGES)	10.00	0.00	10.00	LF	0.00	\$235.00	\$0.0
		0073	1460	7049903	MISC.Curb Repair (Formed)	29.00	0.00	29.00	LF	0.00	\$147.25	\$0.
		0073	1470	7101000	REINFORCING STEEL (EPOXY COATED)	970.00	0.00	970.00	LB	970.00	\$2.00	\$1,940.0
		0073	1480	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0.
		0074	1490	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,299.00	0.00	1,299.00	SQYD	0.00	\$48.00	\$0.0
		0074	1500	2161502	REMOVAL OF CONCRETE WEARING SURFACE	11,694.00	0.00	11,694.00	SQFT	0.00	\$2.00	\$0.0
		0074	1510	2161503	REMOVAL OF EXISTING DECK REPAIR	910.00	0.00	910.00	SQFT	0.00	\$22.00	\$0.
		0074	1520	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$2,705.00	\$0.
		0074	1530	2169903	MISC.Removal of Existing Approach Notch	124.00	0.00	124.00	LF	0.00	\$160.00	\$0.
		0074	1540	5031010A	BRIDGE APPROACH SLAB (MAJOR)	281.00	0.00	281.00	SQYD	0.00	\$300.00	\$0.
		0074	1550	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	9.00	0.00	9.00	CY	0.00	\$700.00	\$0.
		0074	1560	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,299.00	0.00	1,299.00	SQYD	0.00	\$130.00	\$0.
		0074	1570	7031004	DIAMOND GRINDING	1,299.00	0.00	1,299.00	SQYD	0.00	\$11.25	\$0.
		0074	1580	7033013	PENETRATING CONCRETE SEALER	139.00	0.00	139.00	SY	0.00	\$5.00	\$0.
		0074	1590	7034214	CLASS B-2 CONCRETE	3.40	0.00	3.40	CUYD	0.00	\$4,500.00	\$0.
		0074	1600	7039903	MISC.Median Barrier Transition (Type B)	40.00	0.00	40.00	LF	0.00	\$200.00	\$0.
		0074	1610	7040101	SUBSTRUCTURE REPAIR (FORMED)	100.00	0.00	100.00	SQFT	0.00	\$161.00	\$0.
		0074	1620	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	50.00	0.00	50.00	SQFT	0.00	\$177.25	\$0.0
		0074	1630	7040104	HALF-SOLE REPAIR	350.00	0.00	350.00	SQFT	0.00	\$98.50	\$0.0
		0074	1640	7040106	FULL DEPTH REPAIR	150.00	0.00	150.00	SQFT	0.00	\$215.00	\$0.0
		0074	1650	7040107	SLAB EDGE REPAIR (BRIDGES)	10.00	0.00	10.00	LF	0.00	\$235.00	\$0.
		0074	1660	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	1,150.00	0.00	1,150.00	SQFT	0.00	\$108.00	\$0.
		0074	1670	7049903	MISC.Curb Repair (Formed)	10.00	0.00	10.00	LF	0.00	\$147.25	\$0.
		0074	1680	7101000	REINFORCING STEEL (EPOXY COATED)	930.00	0.00	930.00	LB	0.00	\$2.00	\$0.
		0074	1690	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$0.
		0075	1700	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,231.00	0.00	1,231.00	SQYD	0.00	\$48.00	\$0.
		0075	1710	2161502	REMOVAL OF CONCRETE WEARING SURFACE	11,077.00	0.00	11,077.00	SQFT	0.00	\$2.00	\$0.
		0075	1720	2161503	REMOVAL OF EXISTING DECK REPAIR	911.00	0.00	911.00	SQFT	0.00	\$22.00	\$0.
		0075	1730	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$4,000.00	\$0.
		0075	1740	2169903	MISC.Removal of Barrier	59.00	0.00	59.00	LF	0.00	\$70.00	\$0.
		0075	1750	2169903	MISC.Removal of Existing Approach Notch	124.00	0.00	124.00	LF	0.00	\$160.00	\$0.
		0075	1760	5031010A	BRIDGE APPROACH SLAB (MAJOR)	281.00	0.00	281.00	SQYD	0.00	\$300.00	\$0.
		0075	1770	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	9.00	0.00	9.00	CY	0.00	\$700.00	\$0.
		0075	1780	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,231.00	0.00	1,231.00	SQYD	0.00	\$138.00	\$0.
		0075	1790	7031004	DIAMOND GRINDING	1,231.00	0.00	1,231.00	SQYD	0.00	\$11.50	\$0.
		00.0				.,201.00	5.00	.,_01.00		0.00	÷	φ0.

### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220218-F06	J6I3149	0075	1810	7034214	CLASS B-2 CONCRETE	3.40	0.00	3.40	CUYD	0.00	\$3,500.00	\$0.0
		0075	1820	7034215	TYPE B BARRIER	59.00	0.00	59.00	LF	0.00	\$200.00	\$0.0
		0075	1830	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	20.00	0.00	20.00	SQFT	0.00	\$188.00	\$0.0
		0075	1840	7040104	HALF-SOLE REPAIR	300.00	0.00	300.00	SQFT	160.00	\$98.50	\$15,760.0
		0075	1850	7040106	FULL DEPTH REPAIR	150.00	0.00	150.00	SQFT	0.00	\$215.00	\$0.0
		0075	1860	7040107	SLAB EDGE REPAIR (BRIDGES)	10.00	0.00	10.00	LF	0.00	\$235.00	\$0.0
		0075	1870	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	1,100.00	0.00	1,100.00	SQFT	0.00	\$108.00	\$0.0
		0075	1880	7101000	REINFORCING STEEL (EPOXY COATED)	910.00	0.00	910.00	LB	0.00	\$2.00	\$0.0
		0075	1890	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$0.0
		0076	1900	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,163.00	0.00	1,163.00	SQYD	0.00	\$48.00	\$0.0
		0076	1910	2161501	REMOVAL OF ASPHALT WEARING SURFACE	10,468.00	0.00	10,468.00	SQFT	0.00	\$2.00	\$0.0
		0076	1920	2161503	REMOVAL OF EXISTING DECK REPAIR	774.00	0.00	774.00	SQFT	0.00	\$22.00	\$0.0
		0076	1930	2169903	MISC.Removal of Barrier	17.00	0.00	17.00	LF	0.00	\$120.00	\$0.0
		0076	1940	2169903	MISC.Removal of Existing Approach Notch	108.00	0.00	108.00	LF	0.00	\$160.00	\$0.0
		0076	1950	5031010A	BRIDGE APPROACH SLAB (MAJOR)	246.00	0.00	246.00	SQYD	0.00	\$335.00	\$0.0
		0076	1960	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	14.00	0.00	14.00	CY	0.00	\$700.00	\$0.0
		0076	1970	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,163.00	0.00	1,163.00	SQYD	0.00	\$138.00	\$0.0
		0076	1980	7031004	DIAMOND GRINDING	1,163.00	0.00	1,163.00	SQYD	0.00	\$11.50	\$0.0
		0076	1990	7033013	PENETRATING CONCRETE SEALER	142.00	0.00	142.00	SY	0.00	\$5.00	\$0.0
		0076	2000	7034214	CLASS B-2 CONCRETE	3.00	0.00	3.00	CUYD	0.00	\$5,900.00	\$0.0
		0076	2010	7034215	TYPE B BARRIER	27.00	0.00	27.00	LF	0.00	\$206.00	\$0.0
		0076	2020	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	20.00	0.00	20.00	SQFT	0.00	\$188.00	\$0.0
		0076	2030	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	523.00	0.00	523.00	SQFT	0.00	\$159.00	\$0.0
		0076	2040	7040104	HALF-SOLE REPAIR	250.00	0.00	250.00	SQFT	0.00	\$98.50	\$0.0
		0076	2050	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$280.00	\$0.0
		0076	2060	7040107	SLAB EDGE REPAIR (BRIDGES)	15.00	0.00	15.00	LF	0.00	\$222.00	\$0.0
		0076	2070	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	1,550.00	0.00	1,550.00	SQFT	0.00	\$108.00	\$0.0
		0076	2080	7040113	CLEANING AND EPOXY COATING	600.00	0.00	600.00	SQFT	0.00	\$12.00	\$0.0
		0076	2090	7049903	MISC.Curb Repair (Formed)	20.00	0.00	20.00	LF	0.00	\$147.25	\$0.0
		0076	2100	7101000	REINFORCING STEEL (EPOXY COATED)	960.00	0.00	960.00	LB	0.00	\$3.00	\$0.0
		0076	2110	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$0.0
		0077	2120	2161001	TOTAL SURFACE HYDRO DEMOLITION	970.00	0.00	970.00	SQYD	0.00	\$48.00	\$0.0
		0077	2130	2161501	REMOVAL OF ASPHALT WEARING SURFACE	8,730.00	0.00	8,730.00	SQFT	0.00	\$2.00	\$0.0
		0077	2140	2161503	REMOVAL OF EXISTING DECK REPAIR	773.00	0.00	773.00	SQFT	0.00	\$22.00	\$0.0
		0077	2150	2169903	MISC.Removal of Barrier	28.00	0.00	28.00	LF	0.00	\$80.00	\$0.0
		0077	2160	2169903	MISC.Removal of Existing Approach Notch	108.00	0.00	108.00	LF	0.00	\$160.00	\$0.0
		0077	2170	5031010A	BRIDGE APPROACH SLAB (MAJOR)	246.00	0.00	246.00	SQYD	0.00	\$330.00	\$0.0
		0077	2180	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	11.00	0.00	11.00	CY	0.00	\$700.00	\$0.0
		0077	2190	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	970.00	0.00	970.00	SQYD	0.00	\$138.00	\$0.0
		0077	2200	7031004	DIAMOND GRINDING	970.00	0.00	970.00	SQYD	0.00	\$12.00	\$0.
		0077	2210	7033013	PENETRATING CONCRETE SEALER	121.00	0.00	121.00	SY	0.00	\$5.00	\$0.
		0077	2220	7034214	CLASS B-2 CONCRETE	3.00	0.00	3.00	CUYD	0.00	\$5,900.00	\$0.
		0077	2230	7034215	TYPE B BARRIER	38.00	0.00	38.00	LF	0.00	\$219.00	\$0.
		0077	2240	7040101	SUBSTRUCTURE REPAIR (FORMED)	15.00	0.00	15.00	SQFT	0.00	\$210.75	\$0.
		0077	2250	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	10.00	0.00	10.00	SQFT	0.00	\$241.00	\$0.0
		0077	2260	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	911.00	0.00	911.00	SQFT	0.00	\$145.25	\$0.0

### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220218-F06	J6I3149	0077	2270	7040104	HALF-SOLE REPAIR	250.00	0.00	250.00	SQFT	0.00	\$98.50	\$0.0
		0077	2280	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$280.00	\$0.0
		0077	2290	7040107	SLAB EDGE REPAIR (BRIDGES)	15.00	0.00	15.00	LF	0.00	\$222.00	\$0.0
		0077	2300	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	1,300.00	0.00	1,300.00	SQFT	0.00	\$108.00	\$0.0
		0077	2310	7049903	MISC.Curb Repair (Formed)	9.00	0.00	9.00	LF	0.00	\$147.25	\$0.0
		0077	2320	7101000	REINFORCING STEEL (EPOXY COATED)	960.00	0.00	960.00	LB	0.00	\$3.00	\$0.0
		0077	2330	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$0.0
		0078	2340	2161001	(EPOXY) TOTAL SURFACE HYDRO DEMOLITION	1,063.00	0.00	1,063.00	SQYD	1,063.00	\$47.00	\$49,961.0
		0078	2350	2161501	REMOVAL OF ASPHALT WEARING SURFACE	9,565.00	0.00	9,565.00	SQFT	9,565.00	\$2.00	\$19,130.0
		0078	2360	2161503	REMOVAL OF EXISTING DECK REPAIR	484.00	0.00	484.00	SQFT	58.00	\$22.00	\$1,276.0
		0078	2370	2169903	MISC.Removal of Existing Approach Notch	108.00	0.00	108.00	LF	108.00	\$160.00	\$17,280.0
		0078	2380	5031010A	BRIDGE APPROACH SLAB (MAJOR)	246.00	0.00	246.00	SQYD	246.00	\$320.00	\$78,720.0
		0078	2390	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	35.00	0.00	35.00	CY	35.00	\$700.00	\$24,500.0
		0078	2400	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,063.00	0.00	1,063.00	SQYD	1,063.00	\$151.00	\$160,513.0
		0078	2410	7031004	DIAMOND GRINDING	1,063.00	0.00	1,063.00	SQYD	237.00	\$10.50	\$2,488.5
		0078	2420	7033013	PENETRATING CONCRETE SEALER	131.00	0.00	131.00	SY	131.00	\$5.00	\$655.0
		0078	2420	7034214	CLASS B-2 CONCRETE	3.00	0.00	3.00	CUYD	3.00	\$4,500.00	\$13,500.0
		0078	2440	7034215	TYPE B BARRIER	37.00	0.00	37.00	LF	4.30	\$220.00	\$946.0
		0078	2450	7040101	SUBSTRUCTURE REPAIR (FORMED)	10.00	0.00	10.00	SQFT	0.00	\$246.00	\$0.0
		0078	2450	7040101	SUBSTRUCTURE REPAIR (UNFORMED)	10.00	0.00	10.00	SQFT	0.00	\$240.00	\$0.0
			2400	7040102	SUPERSTRUCTURE REPAIR (UNFORMED)	100.00	0.00	100.00	SQFT	0.00	\$158.50	\$0.0
		0078	2470	7040105	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$130.30	\$0.0
		0078	2400	7040100	SLAB EDGE REPAIR (BRIDGES)	20.00	0.00	20.00	LF	0.00	\$205.00	\$0.0
		0078	2500	7040107	DECK REPAIR WITH VOID TUBE REPLACEMENT	650.00	-435.00	215.00	SQFT	215.00	\$203.00	\$23,220.0
			2510	7040112	CLEANING AND EPOXY COATING	531.00	0.00	531.00	SQFT	0.00	\$100.00	\$23,220.0
		0078	2520	7049903	MISC.Curb Repair (Formed)	10.00	0.00	10.00	LF	5.00	\$147.50	\$737.5
		0078	2520	7049903	REINFORCING STEEL (EPOXY COATED)		0.00					
		0078		7110200		850.00		850.00	LB	850.00	\$3.00	\$2,550.0
		0078	2540	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$0.0
		0079	2550	2161001	TOTAL SURFACE HYDRO DEMOLITION	937.00	0.00	937.00	SQYD	0.00	\$47.00	\$0.0
		0079	2560	2161501	REMOVAL OF ASPHALT WEARING SURFACE	8,437.00	0.00	8,437.00	SQFT	0.00	\$2.00	\$0.0
		0079	2570	2161503	REMOVAL OF EXISTING DECK REPAIR	483.00	0.00	483.00	SQFT	0.00	\$22.00	\$0.0
		0079	2580	2169903	MISC.Removal of Existing Approach Notch	108.00	0.00	108.00	LF	0.00	\$160.00	\$0.0
		0079	2590	5031010A	BRIDGE APPROACH SLAB (MAJOR)	246.00	0.00	246.00	SQYD	0.00	\$320.00	\$0.0
		0079	2600	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	31.00	0.00	31.00	CY	0.00	\$700.00	\$0.0
		0079	2610	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	937.00	0.00	937.00	SQYD	0.00	\$140.00	\$0.0
		0079	2620	7031004	DIAMOND GRINDING	937.00	0.00	937.00	SQYD	0.00	\$10.50	\$0.0
		0079	2630	7033013	PENETRATING CONCRETE SEALER	117.00	0.00	117.00	SY	0.00	\$5.00	\$0.0
		0079	2640	7034214	CLASS B-2 CONCRETE	3.00	0.00	3.00	CUYD	0.00	\$4,500.00	\$0.0
		0079	2650	7034215	TYPE B BARRIER	49.00	0.00	49.00	LF	0.00	\$208.00	\$0.0
		0079	2660	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	30.00	0.00	30.00	SQFT	0.00	\$170.25	\$0.0
		0079	2670	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	100.00	0.00	100.00	SQFT	0.00	\$158.50	\$0.0
		0079	2680	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$280.00	\$0.0
		0079	2690	7040107	SLAB EDGE REPAIR (BRIDGES)	35.00	0.00	35.00	LF	0.00	\$210.00	\$0.0
		0079	2700	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	650.00	0.00	650.00	SQFT	0.00	\$108.00	\$0.0
		0079	2710	7040113	CLEANING AND EPOXY COATING	468.00	0.00	468.00	SQFT	0.00	\$12.00	\$0.0
		0079	2720	7049903	MISC.Curb Repair (Formed)	5.00	0.00	5.00	LF	0.00	\$147.25	\$0.0



### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220218-F06	J6I3149	0079	2730	7101000	REINFORCING STEEL (EPOXY COATED)	850.00	0.00	850.00	LB	0.00	\$2.00	\$0.0
		0079	2740	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$0.0
		0080	2750	2162500	REMOVAL OF EXISTING BRIDGE DECK	39,170.00	0.00	39,170.00	SQFT	39,170.00	\$18.00	\$705,060.0
		0080	2760	2169902	MISC.Removal of Existing Bearings	24.00	0.00	24.00	EA	24.00	\$5,000.00	\$120,000.0
		0080	2770	5031010A	BRIDGE APPROACH SLAB (MAJOR)	285.00	0.00	285.00	SQYD	285.00	\$335.00	\$95,475.0
		0080	2780	7034212	SLAB ON STEEL	4,285.00	0.00	4,285.00	SQYD	4,285.00	\$425.00	\$1,821,125.0
		0080	2790	7034219A	TYPE D BARRIER	1,260.00	0.00	1,260.00	LF	1,260.00	\$115.00	\$144,900.0
		0080	2800	7039907	MISC.Ultra-High Performance Concrete	23.00	0.00	23.00	CUYD	23.00	\$10,000.00	\$230,000.0
		0080	2810	7040101	SUBSTRUCTURE REPAIR (FORMED)	65.00	257.00	322.00	SQFT	337.00	\$189.00	\$63,693.0
		0080	2820	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	54.00	0.00	54.00	SQFT	0.00	\$189.00	\$0.0
		0080	2830	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	1.00	\$22,560.00	\$22,560.0
		0080	2840	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0.
		0080	2850	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	1,990.00	0.00	1,990.00	LB	1,990.00	\$75.00	\$149,250.
		0080	2860	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.80	\$40,000.00	\$32,000.
		0080	2870	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	500.00	0.00	500.00	SQFT	300.00	\$25.00	\$7,500.
		0080	2880	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	500.00	0.00	500.00	SQFT	0.00	\$2.00	\$0.
		0080	2890	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	700.00	0.00	700.00	SQFT	0.00	\$2.00	\$0.
		0080	2900	7126000	NON-DESTRUCTIVE TESTING	1,032.00	0.00	1,032.00	LF	288.00	\$11.00	\$3,168.
		0080	2910	7129902	MISC.Reset Bearings	10.00	0.00	10.00	EA	10.00	\$9,000.00	\$90,000.
		0080	2920	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	24.00	0.00	24.00	EA	24.00	\$4,850.00	\$116,400.
		0080	2930	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	210.00	0.00	210.00	LF	210.00	\$495.00	\$103,950.
		0081	2940	2162500	REMOVAL OF EXISTING BRIDGE DECK	33,618.00	0.00	33,618.00	SQFT	0.00	\$18.00	\$0.
		0081	2950	2169902	MISC.Removal of Existing Bearings	21.00	0.00	21.00	EA	0.00	\$5,000.00	\$0.
		0081	2960	5031010A	BRIDGE APPROACH SLAB (MAJOR)	240.00	0.00	240.00	SQYD	0.00	\$335.00	\$0.
		0081	2970	7034212	SLAB ON STEEL	3,607.00	0.00	3,607.00	SQYD	0.00	\$425.00	\$0.
		0081	2980	7034219A	TYPE D BARRIER	1,220.00	0.00	1,220.00	LF	0.00	\$115.00	\$0.
		0081	2990	7039907	MISC.Ultra-High Performance Concrete	20.90	0.00	20.90	CUYD	0.00	\$10,000.00	\$0.
		0081	3000	7040101	SUBSTRUCTURE REPAIR (FORMED)	150.00	0.00	150.00	SQFT	0.00	\$190.00	\$0.
		0081	3010	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$22,560.00	\$0.
		0081	3020	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0.
		0081	3030	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	1,460.00	0.00	1,460.00	LB	0.00	\$75.00	\$0.
		0081	3040	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$40,000.00	\$0.
		0081	3050	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	400.00	0.00	400.00	SQFT	0.00	\$25.00	\$0.
		0081	3060	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	400.00	0.00	400.00	SQFT	0.00	\$2.00	\$0.
		0081	3070	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	600.00	0.00	600.00	SQFT	0.00	\$2.00	\$0.
		0081	3080	7126000	NON-DESTRUCTIVE TESTING	767.00	0.00	767.00	LF	0.00	\$11.00	\$0.
		0081	3090	7129902	MISC.Reset Bearings	10.00	0.00	10.00	EA	0.00	\$9,000.00	\$0.
		0081	3100	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	21.00	0.00	21.00	EA	0.00	\$4,850.00	\$0.
		0081	3110	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	188.00	0.00	188.00	LF	0.00	\$495.00	\$0.
		0082	3120	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,117.00	0.00	1,117.00	SQYD	1,117.00	\$48.00	\$53,616.
		0082	3130	2161501	REMOVAL OF ASPHALT WEARING SURFACE	10,055.00	0.00	10,055.00	SQFT	10,055.00	\$2.00	\$20,110.
		0082	3140	2161503	REMOVAL OF EXISTING DECK REPAIR	857.00	0.00	857.00	SQFT	78.00	\$22.00	\$1,716.
		0082	3150	2169903	MISC.Removal of Existing Approach Notch	108.00	0.00	108.00	LF	108.00	\$160.00	\$17,280.
		0082	3160	5031010A	BRIDGE APPROACH SLAB (MAJOR)	246.00	0.00	246.00	SQYD	246.00	\$320.00	\$78,720.
		0082	3170	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	19.00	17.00	36.00	CY	36.00	\$700.00	\$25,200.

### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q	uantities	and Valu		based on F	Report Generated date and can differ from the posted am	ount at the	e time the	Estimate w	as Gene	erated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220218-F06	J6I3149	0082	3180	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,117.00	0.00	1,117.00	SQYD	1,117.00	\$140.00	\$156,380.00
		0082	3190	7031004	DIAMOND GRINDING	1,117.00	0.00	1,117.00	SQYD	158.00	\$10.25	\$1,619.50
		0082	3200	7033013	PENETRATING CONCRETE SEALER	137.00	0.00	137.00	SY	137.00	\$5.00	\$685.00
		0082	3210	7034214	CLASS B-2 CONCRETE	3.00	0.00	3.00	CUYD	3.00	\$4,500.00	\$13,500.00
		0082	3220	7034215	TYPE B BARRIER	39.00	0.00	39.00	LF	13.50	\$200.00	\$2,700.00
		0082	3230	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	45.00	0.00	45.00	SQFT	0.00	\$182.00	\$0.00
		0082	3240	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	300.00	0.00	300.00	SQFT	0.00	\$158.50	\$0.00
		0082	3250	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$280.00	\$0.00
		0082	3260	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	1,500.00	-655.00	845.00	SQFT	845.00	\$108.00	\$91,260.00
		0082	3270	7040113	CLEANING AND EPOXY COATING	486.00	0.00	486.00	SQFT	0.00	\$14.00	\$0.00
		0082	3280	7101000	REINFORCING STEEL (EPOXY COATED)	840.00	0.00	840.00	LB	840.00	\$2.00	\$1,680.00
		0082	3290	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.00
		0082	3300	7129902	MISC.Slab Drain Extension	12.00	0.00	12.00	EA	0.00	\$700.00	\$0.00
		0083	3310	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,293.00	0.00	1,293.00	SQYD	0.00	\$48.00	\$0.00
		0083	3320	2161501	REMOVAL OF ASPHALT WEARING SURFACE	11,641.00	0.00	11,641.00	SQFT	0.00	\$2.00	\$0.00
		0083	3330	2161503	REMOVAL OF EXISTING DECK REPAIR	856.00	0.00	856.00	SQFT	0.00	\$22.00	\$0.00
		0083	3340	2169903	MISC.Removal of Existing Approach Notch	128.00	0.00	128.00	LF	0.00	\$160.00	\$0.00
		0083	3350	5031010A	BRIDGE APPROACH SLAB (MAJOR)	291.00	0.00	291.00	SQYD	0.00	\$300.00	\$0.00
		0083	3360	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	22.00	0.00	22.00	CY	0.00	\$700.00	\$0.00
		0083	3370	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,293.00	0.00	1,293.00	SQYD	0.00	\$151.00	\$0.00
		0083	3380	7031004	DIAMOND GRINDING	1,293.00	0.00	1,293.00	SQYD	0.00	\$10.25	\$0.00
		0083	3390	7033013	PENETRATING CONCRETE SEALER	134.00	0.00	134.00	SY	0.00	\$5.00	\$0.00
		0083	3400	7034214	CLASS B-2 CONCRETE	3.60	0.00	3.60	CUYD	0.00	\$4,500.00	\$0.00
		0083	3410	7034215	TYPE B BARRIER	39.00	0.00	39.00	LF	0.00	\$220.00	\$0.00
		0083	3420	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	30.00	0.00	30.00	SQFT	0.00	\$170.25	\$0.00
		0083	3430	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	130.00	0.00	130.00	SQFT	0.00	\$159.50	\$0.00
		0083	3440	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$280.00	\$0.00
		0083	3450	7040107	SLAB EDGE REPAIR (BRIDGES)	15.00	0.00	15.00	LF	0.00	\$222.00	\$0.00
		0083	3460	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	1,750.00	0.00	1,750.00	SQFT	0.00	\$108.00	\$0.00
		0083	3470	7040113	CLEANING AND EPOXY COATING	486.00	0.00	486.00	SQFT	0.00	\$14.00	\$0.00
		0083	3480	7049903	MISC.Curb Repair (Formed)	5.00	0.00	5.00	LF	0.00	\$147.25	\$0.00
		0083	3490	7101000	REINFORCING STEEL (EPOXY COATED)	970.00	0.00	970.00	LB	0.00	\$3.00	\$0.00
		0083	3500	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.00
		0083	3510	7129902	MISC.Slab Drain Extension	12.00	0.00	12.00	EA	0.00	\$700.00	\$0.00
		0001	6001	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	0.00	2,685.00	2,685.00	SQYD	2,685.00	\$6.30	\$16,915.50
		0001	6002	4030107	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125CLP MIX)	0.00	374.60	374.60	TONS	374.60	\$147.00	\$55,066.20
		0001	6003	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$370,432.00	\$370,432.00
		0001	6004	6042020	ADJUSTING BASIN OR INLET	0.00	3.00	3.00	EA	3.00	\$1,248.00	\$3,744.00
		0078	6005	7040104	HALF-SOLE REPAIR	0.00	175.00	175.00	SQFT	175.00	\$98.50	\$17,237.50
					HALF-SOLE REPAIR	0.00	631.00	631.00	SQFT	631.00	\$98.50	\$62,153.50
				7061000	REINFORCING STEEL	0.00	430.00	430.00	LB	430.00	\$2.00	\$860.00
				REINFORCING STEEL	0.00	20.00	20.00	LB	20.00	\$2.00	\$40.00	
		0001	6009	7049904	MISC.Sign truss base repair - median	0.00	15.00	15.00	SQFT	15.00	\$134.75	\$2,021.25
	Project J J6l3187	613149 - To 0001	otal Value 3520	Posted to E 2022010	ate as of Report Generated Date REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.07	\$2,500,000.00	\$11,077,822.15 \$175,000.00
	0001 3530 2031000 CLASS A EXCAVATION							400.00	CUYD	0.00	\$30.00	\$0.00
Povision 4/1/201		0001				400.00	0.00		5010	0.00	<i>\$</i> 30.00	Bage 25 of 74

### Total Paid / All Items / All Estimates (Including this Estimate)

	uantities	and vaiu	les are i	pased on F	Report Generated date and can differ from the posted am	ount at the	e time the	Estimate w	as Gene	erated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220218-F06	J6I3187	0001	3540	2079909	MISC.Modified Linear Grading	7.70	0.00	7.70	STA	0.00	\$3,500.00	\$0.00
		0001	3550	2153000	SHAPING SLOPES, CLASS III	9.00	0.00	9.00	100F	0.00	\$900.00	\$0.00
		0001	3560	3030600	FURNISHING ROCK BASE MATERIAL	725.00	0.00	725.00	SQYD	0.00	\$9.50	\$0.00
		0001	3570	3030610A	PLACING ROCK BASE	725.00	0.00	725.00	SQYD	0.00	\$6.00	\$0.00
		0001	3580	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	2,376.00	0.00	2,376.00	SQYD	0.00	\$8.00	\$0.00
		0001	3590	3102002	CRUSHED STONE (B)	232.00	0.00	232.00	TONS	0.00	\$55.00	\$0.00
		0001	3600	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	166.50	0.00	166.50	TONS	0.00	\$152.00	\$0.00
		0001	3610	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	2,175.60	0.00	2,175.60	TONS	424.10	\$102.00	\$43,258.20
		0001	3620	4030105	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125C MIX)	2,491.20	0.00	2,491.20	TONS	370.91	\$107.00	\$39,687.37
		0001	3630	4030107	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125CLP MIX)	336.30	0.00	336.30	TONS	0.00	\$147.00	\$0.00
		0001	3640	4030306	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP250C MIX)	749.40	0.00	749.40	TONS	0.00	\$112.00	\$0.00
		0001	3650	4071005	TACK COAT	5,327.00	0.00	5,327.00	GAL	1,020.00	\$2.50	\$2,550.00
		0001	3660	4081010	PRIME-LIQUID ASPHALT RC 70 OR MC 30	409.00	0.00	409.00	GAL	0.00	\$8.00	\$0.00
		0001	3670	4131000	MICROSURFACING, TYPE II	3,506.00	0.00	3,506.00	SQYD	0.00	\$12.85	\$0.00
		0001	3680	4136000	PCCP JOINT/CRACK SEALING	14,800.00	0.00	14,800.00	LF	0.00	\$5.75	\$0.00
		0001	3690	5021310	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	1,150.70	0.00	1,150.70	SQYD	0.00	\$60.00	\$0.00
		0001	3700	5041000	CONCRETE APPROACH PAVEMENT	6,682.80	0.00	6,682.80	SQYD	0.00	\$118.00	\$0.00
		0001	3710	6049901	MISC.Inspection of 54" RCP Sanitary Sewer	1.00	0.00	1.00	LS	0.00	\$3,000.00	\$0.00
		0001	3720	6071012A	CHAIN-LINK FENCE (60 IN.)	800.00	0.00	800.00	LF	0.00	\$32.00	\$0.00
		0001	3730	6083006	6 IN. CONCRETE MEDIAN STRIP	81.60	0.00	81.60	SQYD	9.15	\$160.00	\$1,464.00
		0001	3740	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	360.00	0.00	360.00	LF	0.00	\$35.00	\$0.00
		0001	3750	6091041	CONCRETE GUTTER TYPE A	40.00	0.00	40.00	LF	0.00	\$49.00	\$0.00
		0001	3760	6099903	MISC.Concrete Curb Under Guardrail	466.00	0.00	466.00	LF	0.00	\$45.00	\$0.00
		0001	3770	6113020	FURNISHING TYPE 2 ROCK BLANKET	2,100.00	0.00	2,100.00	CUYD	0.00	\$43.20	\$0.00
		0001	3780	6113040	PLACING TYPE 2 ROCK BLANKET	2,100.00	0.00	2,100.00	CUYD	0.00	\$22.95	\$0.00
		0001	3790	6116010A	SLOPE PROTECTION	305.00	0.00	305.00	SQYD	0.00	\$95.00	\$0.00
		0001	3800	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	15.00	0.00	15.00	EA	0.00	\$3,025.00	\$0.00
		0001	3810	6122020	REPLACEMENT SAND BARREL	20.00	0.00	20.00	EA	0.00	\$448.00	\$0.00
		0001	3820	6122030	IMPACT ATTENUATOR (RELOCATION)	13.00	0.00	13.00	EA	3.00	\$678.00	\$2,034.00
		0001	3830	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	5.00	0.00	5.00	EA	0.00	\$3,000.00	\$0.00
		0001	3840	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	1,940.00	0.00	1,940.00	SQYD	1,214.80	\$160.00	\$194,368.00
		0001	3850	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	672.00	0.00	672.00	SQYD	0.00	\$18.00	\$0.00
		0001	3860	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	132.00	0.00	132.00	EA	161.00	\$15.00	\$2,415.00
		0001	3870	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	638.00	0.00	638.00	EA	648.00	\$15.00	\$9,720.00
		0001	3880	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	366.00	0.00	366.00	EA	421.00	\$14.00	\$5,894.00
		0001 3890 6139905 MIS		6139905	MISC.Type 1 or 5 Aggregeate for Base (Var. Thick) (Pavement Repair)	1,998.00	0.00	1,998.00	SQYD	1,214.90	\$10.00	\$12,149.00
		0001	3900	6169901	MISC.Temporary Traffic Control	1.00	0.00	1.00	LS	0.00	\$950,000.00	\$0.00
		0001	3910	6169901	MISC.Traffic Signal Maintenance and Programming	1.00	0.00	1.00	LS	0.00	\$50,000.00	\$0.00
		0001	3920	6169902	MISC.NTCIP Compliant Changeable Message Sign (Contractor Furnished and Retained	24.00	0.00	24.00	EA	0.00	\$3,200.00	\$0.00
		0001	3930	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	19,937.00	0.00	19,937.00	LF	1,952.75	\$70.00	\$136,692.50
		0001	3940	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	63,451.00	0.00	63,451.00	LF	8,825.00	\$21.75	\$191,943.75
		0001	3950	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	19,420.00	0.00	19,420.00	LF	0.00	\$26.40	\$0.00
		0001	3960	6173706	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION, CONTRACTOR FURNISHED / RETAINED	1,704.00	0.00	1,704.00	LF	0.00	\$26.40	\$0.00
		0001	3970	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	4,860.00	0.00	4,860.00	LF	137.50	\$9.35	\$1,285.62



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

### Total Paid / All Items / All Estimates (Including this Estimate)

ed date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
20218-F06	J6I3187	0001	3980	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	1,063.00	0.00	1,063.00	LF	0.00	\$14.50	\$0.0
		0001	3990	6179903	MISC.Concrete Traffic Barrier, Type C (Modified)	3,850.00	0.00	3,850.00	LF	866.00	\$196.47	\$170,143.0
		0001	4000	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$3,750,000.00	\$0.0
		0001	4010	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	47,861.00	0.00	47,861.00	LF	0.00	\$0.30	\$0.0
		0001	4020	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	25,432.00	0.00	25,432.00	LF	0.00	\$0.30	\$0.
		0001	4030	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,485.00	0.00	2,485.00	LF	0.00	\$1.00	\$0.
		0001	4040	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$6,000.00	\$0.
		0001	4050	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	3,529.00	0.00	3,529.00	SQYD	2,007.00	\$6.30	\$12,644.
		0001	4060	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	22,245.00	0.00	22,245.00	SQYD	5,642.00	\$2.79	\$15,741.
		0001	4070	6221011	COLDMILLING CONCRETE PAVEMENT FOR REMOVAL OF	4,808.00	0.00	4,808.00	SQYD	0.00	\$4.65	\$0.
		0001	4080	6224010	SURFACE MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,868.00	0.00	1,868.00	SQYD	0.00	\$9.98	\$0.
		0001	4090	6252004	SLAB JACKING MATERIAL CEMENTITIOUS GROUT	31.60	0.00	31.60	TONS	0.00	\$400.00	\$0.
		0001	4100	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	191.20	0.00	191.20	STA	0.00	\$27.00	\$0.
		0001	4110	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$135,000.00	\$0.
		0001	4120	7319902	MISC.Inlet Top Replacement (In Kind)	61.00	0.00	61.00	EA	15.00	\$2,600.00	\$39,000.
		0001	4130	8051000A	SEEDING - COOL SEASON GRASSES	1.00	0.00	1.00	ACRE	0.00	\$5,500.00	\$0.
		0001	4140	8061016	SEDIMENT REMOVAL	26.00	0.00	26.00	CUYD	0.00	\$34.00	\$0.
		0001	4150	8061019	SILT FENCE	2,429.00	0.00	2,429.00	LF	0.00	\$2.20	\$0.
		0010	4160	6061060	MGS GUARDRAIL	2,652.00	0.00	2,652.00	LF	0.00	\$33.00	\$0
		0010	4170	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	4,277.00	0.00	4,277.00	LF	0.00	\$38.00	\$0
		0010	4180	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED	12.00	0.00	12.00	EA	0.00	\$3,800.00	\$0
		0010			CURB)							
		0010	4190	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	12.00	0.00	12.00	EA	0.00	\$3,700.00	\$0
		0010	4200	6061080	MGS END ANCHOR	9.00	0.00	9.00	EA	0.00	\$1,500.00	\$0
		0010	4210	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	9.00	0.00	9.00	EA	0.00	\$3,100.00	\$0
		0020	4220	9019901	MISC.Maintain &/or Reinstall Existing MoDOT Lighting	1.00	0.00	1.00	LS	0.00	\$125,000.00	\$0
		0020	4230	9019902	MISC.Pull Box Replacement	1.00	0.00	1.00	EA	0.00	\$2,060.00	\$0
		0050	4240	9109902	MISC.MoDOT ITS Facility Temporary Relocation on I-55 at Gravois Creek	1.00	0.00	1.00	EA	0.00	\$70,275.00	\$0
		0050	4250	9109902	MISC.MoDOT ITS Facility Temporary Relocation on I-55 at Green Park	1.00	0.00	1.00	EA	0.00	\$49,885.00	\$0
		0050	4260	9109902	MISC.MoDOT ITS Facility Temporary Relocation on I-55 at MO Pacific Railroad bridge	1.00	0.00	1.00	EA	0.00	\$108,042.00	\$0.
		0050	4270	9109902	MISC.MoDOT ITS Facility Temporary Relocation on I-55 at River Des Peres	1.00	0.00	1.00	EA	0.00	\$105,389.00	\$0.
		0070	4280	2162500	REMOVAL OF EXISTING BRIDGE DECK	17,247.00	0.00	17,247.00	SQFT	0.00	\$18.00	\$0
		0070	4290	2169901	MISC.REMOVAL OF WING	1.00	0.00	1.00	LS	0.00	\$6,500.00	\$0
		0070	4300	5031010A	BRIDGE APPROACH SLAB (MAJOR)	275.00	0.00	275.00	SQYD	0.00	\$335.00	\$0
		0070	4310	7034212	SLAB ON STEEL	1,915.00	0.00	1,915.00	SQYD	0.00	\$425.00	\$0
		0070	4320	7034214	CLASS B-2 CONCRETE	4.20	0.00	4.20	CUYD	0.00	\$5,050.00	\$0
		0070	4330	7034219A	TYPE D BARRIER	596.00	0.00	596.00	LF	0.00	\$136.00	\$0
		0070	4340	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	275.00	0.00	275.00	SQFT	0.00	\$160.00	\$0
		0070	4350	7101000	REINFORCING STEEL (EPOXY COATED)	410.00	0.00	410.00	LB	0.00	\$3.00	\$0
		0070	4360	7123610	SLAB DRAIN	2.00	0.00	2.00	EA	0.00	\$1,250.00	\$0
		0070	4370	7126000	NON-DESTRUCTIVE TESTING	482.00	0.00	482.00	LF	0.00	\$11.00	\$0
		0070	4380	7129902	MISC.Reset Bearings	12.00	0.00	12.00	EA	0.00	\$7,575.00	\$0
		0071	4390	2162500	REMOVAL OF EXISTING BRIDGE DECK	17,132.00	0.00	17,132.00	SQFT	0.00	\$20.00	\$0
		0071	4400	2169901	MISC.REMOVAL OF WING	1.00	0.00	1.00	LS	0.00	\$6,500.00	\$0
		0071	4410	5031010A	BRIDGE APPROACH SLAB (MAJOR)	275.00	0.00	275.00	SQYD	0.00	\$335.00	\$0

### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220218-F06	J6I3187	0071	4420	7034212	SLAB ON STEEL	1,902.00	0.00	1,902.00	SQYD	0.00	\$425.00	\$0.0
		0071	4430	7034214	CLASS B-2 CONCRETE	4.20	0.00	4.20	CUYD	0.00	\$5,050.00	\$0.0
		0071	4440	7034219A	TYPE D BARRIER	567.00	0.00	567.00	LF	0.00	\$145.00	\$0.0
		0071	4450	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	350.00	0.00	350.00	SQFT	0.00	\$165.00	\$0.0
		0071	4460	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$11,060.00	\$0.0
		0071	4470	7101000	REINFORCING STEEL (EPOXY COATED)	360.00	0.00	360.00	LB	0.00	\$4.00	\$0.0
		0071	4480	7126000	NON-DESTRUCTIVE TESTING	482.00	0.00	482.00	LF	0.00	\$11.00	\$0.00
		0071	4490	7129902	MISC.Reset Bearings	12.00	0.00	12.00	EA	0.00	\$7,575.00	\$0.00
		0072	4500	2162500	REMOVAL OF EXISTING BRIDGE DECK	15,675.00	0.00	15,675.00	SQFT	0.00	\$18.00	\$0.00
		0072	4510	5031010A	BRIDGE APPROACH SLAB (MAJOR)	287.00	0.00	287.00	SQYD	0.00	\$335.00	\$0.00
		0072	4520	7034212	SLAB ON STEEL	1,741.00	0.00	1,741.00	SQYD	0.00	\$425.00	\$0.00
		0072	4530	7034214	CLASS B-2 CONCRETE	2.70	0.00	2.70	CUYD	0.00	\$6,000.00	\$0.00
		0072	4540	7034219A	TYPE D BARRIER	540.00	0.00	540.00	LF	0.00	\$115.00	\$0.00
		0072	4550	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	400.00	0.00	400.00	SQFT	0.00	\$165.00	\$0.00
		0072	4560	7101000	REINFORCING STEEL (EPOXY COATED)	140.00	0.00	140.00	LB	0.00	\$7.00	\$0.00
		0072	4570	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.00
		0072	4580	7123610	(EPOXY) SLAB DRAIN	20.00	0.00	20.00	EA	0.00	\$650.00	\$0.00
		0072	4590	7126000	NON-DESTRUCTIVE TESTING	363.00	0.00	363.00	LF	0.00	\$11.00	\$0.00
		0072	4600	2162500	REMOVAL OF EXISTING BRIDGE DECK	15,675.00	0.00	15,675.00	SQFT	0.00	\$18.00	\$0.00
		0073	4610	5031010A	BRIDGE APPROACH SLAB (MAJOR)	287.00	0.00	287.00	SQYD	0.00	\$335.00	\$0.00
		0073	4620	7034212	SLAB ON STEEL	1,741.00	0.00	1,741.00	SQYD	0.00	\$425.00	\$0.00
		0073	4630	7034212	CLASS B-2 CONCRETE	2.70	0.00	2.70	CUYD	0.00	\$6,000.00	\$0.00
			4640	7034214 7034219A	TYPE D BARRIER	540.00	0.00	540.00	LF	0.00	\$115.00	\$0.00
		0073	4650	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	265.00	0.00	265.00	SQFT		\$165.00	\$0.00
		0073	4660	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00		LS	0.00	\$105.00	\$0.00
		0073						1.00				
		0073	4670	7101000	REINFORCING STEEL (EPOXY COATED)	140.00	0.00	140.00	LB	0.00	\$7.00	\$0.00
		0073	4680	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.00
		0073	4690	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	0.00	\$650.00	\$0.00
		0073	4700	7126000	NON-DESTRUCTIVE TESTING	363.00	0.00	363.00	LF	0.00	\$11.00	\$0.00
		0074	4710	2161001	TOTAL SURFACE HYDRO DEMOLITION	3,405.00	0.00	3,405.00	SQYD	0.00	\$48.00	\$0.00
		0074	4720	2161502	REMOVAL OF CONCRETE WEARING SURFACE	24,405.00	0.00	24,405.00	SQFT	0.00	\$2.00	\$0.00
		0074	4730	2161503	REMOVAL OF EXISTING DECK REPAIR	1,500.00	0.00	1,500.00	SQFT	0.00	\$22.00	\$0.00
		0074	4740	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0074	4750	2169903	MISC.Remove Barrier Curb (use for expansion joint work)	30.00	0.00	30.00	LF	0.00	\$205.00	\$0.00
		0074	4760	5031010A	BRIDGE APPROACH SLAB (MAJOR)	554.00	0.00	554.00	SQYD	0.00	\$300.00	\$0.00
		0074	4770	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	71.00	0.00	71.00	CY	0.00	\$700.00	\$0.00
		0074	4780	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	3,534.00	0.00	3,534.00	SQYD	0.00	\$138.00	\$0.00
		0074	4790	7031004	DIAMOND GRINDING	3,534.00	0.00	3,534.00	SQYD	0.00	\$11.00	\$0.00
		0074	4800	7033013	PENETRATING CONCRETE SEALER	540.00	0.00	540.00	SY	0.00	\$5.00	\$0.00
		0074	4810	7034410	TYPE A BARRIER	70.00	0.00	70.00	LF	0.00	\$195.00	\$0.00
		0074	4820	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	50.00	0.00	50.00	SQFT	0.00	\$177.25	\$0.00
		0074	4830	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	100.00	0.00	100.00	SQFT	0.00	\$158.50	\$0.00
		0074	4840	7040104	HALF-SOLE REPAIR	2,000.00	0.00	2,000.00	SQFT	0.00	\$100.00	\$0.00
		0074	4850	7040106	FULL DEPTH REPAIR	300.00	0.00	300.00	SQFT	0.00	\$206.00	\$0.00
		0074	4860	7040107	SLAB EDGE REPAIR (BRIDGES)	10.00	0.00	10.00	LF	0.00	\$235.00	\$0.00
		0074	4870	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	1,500.00	0.00	1,500.00	SQFT	0.00	\$108.00	\$0.00

# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

### Total Paid / All Items / All Estimates (Including this Estimate)

ed date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See repor generated date)
20218-F06	J6I3187	0074	4880	7049901	MISC.Clean Weepholes for Slab Voids	1.00	0.00	1.00	LS	0.00	\$14,600.00	\$0.0
		0074	4890	7049903	MISC.Curb Repair (Formed)	15.00	0.00	15.00	LF	0.00	\$147.25	\$0.0
		0074	4900	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.0
		0075	4910	2162500	REMOVAL OF EXISTING BRIDGE DECK	36,035.00	0.00	36,035.00	SQFT	0.00	\$18.00	\$0.0
		0075	4920	2169901	MISC.Partial Removal of Existing Structural Steel	1.00	0.00	1.00	LS	0.00	\$125,000.00	\$0.
		0075	4930	5031010A	BRIDGE APPROACH SLAB (MAJOR)	288.00	0.00	288.00	SQYD	0.00	\$335.00	\$0.
		0075	4940	7034212	SLAB ON STEEL	3,998.00	0.00	3,998.00	SQYD	0.00	\$425.00	\$0.
		0075	4950	7034219A	TYPE D BARRIER	1,168.00	0.00	1,168.00	LF	0.00	\$115.00	\$0.
		0075	4960	7039907	MISC.Ultra-High Performance Concrete	19.90	0.00	19.90	CUYD	0.00	\$10,000.00	\$0.
		0075	4970	7040101	SUBSTRUCTURE REPAIR (FORMED)	140.00	0.00	140.00	SQFT	0.00	\$160.00	\$0.
		0075	4980	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	260.00	0.00	260.00	SQFT	0.00	\$160.00	\$0.
		0075	4990	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$20,130.00	\$0.
		0075	5000	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$0.
		0075	5010	7121100	FABRICATED STRUCTURAL LOW ALLOY STEEL (MISC)	31,010.00	0.00	31,010.00	LB	0.00	\$8.00	\$0.
		0075	5020	7121111	FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM)	82,630.00	0.00	82,630.00	LB	0.00	\$3.00	\$0.
		0075	5030	7123610	A709, GRADE 50 SLAB DRAIN	52.00	0.00	52.00	EA	0.00	\$600.00	\$0.
		0075	5040	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL	500.00	0.00	500.00	SQFT	0.00	\$30.00	\$0.
		0075	5050	7125210	STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER	500.00	0.00	500.00	SQFT	0.00	\$3.00	\$0.
		0075	5060	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	6,900.00	0.00	6,900.00	SQFT	0.00	\$3.00	\$0
		0075	5070	7161000	PLAIN NEOPRENE BEARING PAD	18.00	0.00	18.00	EA	0.00	\$530.00	\$0
		0075	5080	7163000	TYPE N PTFE BEARING	18.00	0.00	18.00	EA	0.00	\$3,000.00	\$0
		0075	5090	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	125.00	0.00	125.00	LF	0.00	\$495.00	\$0
		0076	5100	2162500	REMOVAL OF EXISTING BRIDGE DECK	35,246.00	0.00	35,246.00	SQFT	0.00	\$18.00	\$0
		0076	5110	2169901	MISC.Partial Removal of Existing Structural Steel	1.00	0.00	1.00	LS	0.00	\$125,000.00	\$0
		0076	5120	5031010A	BRIDGE APPROACH SLAB (MAJOR)	279.00	0.00	279.00	SQYD	0.00	\$335.00	\$0
		0076	5130	7034212	SLAB ON STEEL	3,911.00	0.00	3,911.00	SQYD	0.00	\$425.00	\$0
		0076	5140	7034219A	TYPE D BARRIER	1,141.00	0.00	1,141.00	LF	0.00	\$115.00	\$0
		0076	5150	7039907	MISC.Ultra-High Performance Concrete	19.90	0.00	19.90	CUYD	0.00	\$10,000.00	\$0
		0076	5160	7040101	SUBSTRUCTURE REPAIR (FORMED)	135.00	0.00	135.00	SQFT	0.00	\$160.00	\$0
		0076	5170	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	260.00	0.00	260.00	SQFT	0.00	\$165.00	\$0
		0076	5180	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$20,130.00	\$0
		0076	5190	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$0
		0076	5200	7121100	(EPOXY) FABRICATED STRUCTURAL LOW ALLOY STEEL (MISC)	30,720.00	0.00	30,720.00	LB	0.00	\$8.00	\$0
		0076	5210	7121111	FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM)	82,420.00	0.00	82,420.00	LB	0.00	\$3.00	\$0
					A709, GRADE 50							
		0076	5220	7123610	SLAB DRAIN	52.00	0.00	52.00	EA	0.00	\$600.00	\$0
		0076	5230	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	500.00	0.00	500.00	SQFT	0.00	\$30.00	\$0
		0076	5240	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	500.00	0.00	500.00	SQFT	0.00	\$3.00	\$0
		0076	5250	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	6,900.00	0.00	6,900.00	SQFT	0.00	\$3.00	\$0
		0076	5260	7161000	PLAIN NEOPRENE BEARING PAD	18.00	0.00	18.00	EA	0.00	\$530.00	\$0
		0076	5270	7163000	TYPE N PTFE BEARING	18.00	0.00	18.00	EA	0.00	\$3,000.00	\$0
		0076	5280	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	125.00	0.00	125.00	LF	0.00	\$495.00	\$0
		0077	5290	2161001	TOTAL SURFACE HYDRO DEMOLITION	2,676.00	0.00	2,676.00	SQYD	0.00	\$48.00	\$0
		0077	5300	2161502	REMOVAL OF CONCRETE WEARING SURFACE	24,083.00	0.00	24,083.00	SQFT	0.00	\$2.00	\$0
		0077	5310	2161503	REMOVAL OF EXISTING DECK REPAIR	1,200.00	0.00	1,200.00	SQFT	0.00	\$22.00	\$0
		0077	5320	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$2,705.00	\$0

### Total Paid / All Items / All Estimates (Including this Estimate)

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
218-F06	J6I3187	0077	5330	2169901	MISC.REMOVAL OF WING	1.00	0.00	1.00	LS	0.00	\$19,400.00	\$0.
		0077	5340	5031010A	BRIDGE APPROACH SLAB (MAJOR)	647.00	0.00	647.00	SQYD	0.00	\$300.00	\$0.
		0077	5350	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	40.00	0.00	40.00	CY	0.00	\$700.00	\$0
		0077	5360	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	2,676.00	0.00	2,676.00	SQYD	0.00	\$151.00	\$0
		0077	5370	7031004	DIAMOND GRINDING	2,676.00	0.00	2,676.00	SQYD	0.00	\$11.50	\$0
		0077	5380	7033013	PENETRATING CONCRETE SEALER	285.00	0.00	285.00	SY	0.00	\$5.00	\$0
		0077	5390	7034214	CLASS B-2 CONCRETE	10.30	0.00	10.30	CUYD	0.00	\$4,500.00	\$0
		0077	5400	7034215	TYPE B BARRIER	17.00	0.00	17.00	LF	0.00	\$287.00	\$0
		0077	5410	7034410	TYPE A BARRIER	40.00	0.00	40.00	LF	0.00	\$170.00	\$0
		0077	5420	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	250.00	0.00	250.00	SQFT	0.00	\$160.25	\$0
		0077	5430	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	2,000.00	0.00	2,000.00	SQFT	0.00	\$147.00	\$0
		0077	5440	7040104	HALF-SOLE REPAIR	1,850.00	0.00	1,850.00	SQFT	0.00	\$98.50	\$0
		0077	5450	7040106	FULL DEPTH REPAIR	950.00	0.00	950.00	SQFT	0.00	\$177.00	\$0
		0077	5460	7040107	SLAB EDGE REPAIR (BRIDGES)	10.00	0.00	10.00	LF	0.00	\$235.00	\$0
		0077	5470	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	2,000.00	0.00	2,000.00	SQFT	0.00	\$108.00	\$0
		0077	5480	7049901	MISC.Clean Slab Drains	1.00	0.00	1.00	LS	0.00	\$2,100.00	\$0
		0077	5490	7049901	MISC.Clean Weepholes for Slab Voids	1.00	0.00	1.00	LS	0.00	\$9,700.00	\$0
		0077	5500	7049903	MISC.Curb Repair (Formed)	40.00	0.00	40.00	LF	0.00	\$147.25	\$0
		0077	5510	7101000	REINFORCING STEEL (EPOXY COATED)	1,350.00	0.00	1,350.00	LB	0.00	\$3.00	\$0
		0077	5520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$
		0078	5530	2162500	REMOVAL OF EXISTING BRIDGE DECK	48,391.00	0.00	48,391.00	SQFT	0.00	\$18.00	\$
		0078	5540	2169902	MISC.Removal of Existing Bearings	20.00	0.00	20.00	EA	0.00	\$3,500.00	\$
		0078	5550	5031010A	BRIDGE APPROACH SLAB (MAJOR)	389.00	0.00	389.00	SQYD	0.00	\$335.00	\$
		0078	5560	6071060	PEDESTRIAN FENCE (STRUCTURES)	90.00	0.00	90.00	LF	0.00	\$240.00	\$
		0078	5570	6181015	RAILROAD PLAN SUBMITTAL	1.00	0.00	1.00	LS	0.00	\$15,000.00	\$
		0078	5580	7034212	SLAB ON STEEL	5,351.00	0.00	5,351.00	SQYD	0.00	\$425.00	\$
		0078	5590	7034219A	TYPE D BARRIER	1,370.00	0.00	1,370.00	LF	0.00	\$115.00	\$
		0078	5600	7039907	MISC.Ultra-High Performance Concrete	19.90	0.00	19.90	CUYD	0.00	\$10,000.00	\$
		0078	5610	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	365.00	0.00	365.00	SQFT	0.00	\$164.00	\$
		0078	5620	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$24,650.00	\$
		0078	5630	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$
		0078	5640	7121000	(EPOXY) FABRICATED STRUCTURAL CARBON STEEL (MISC)	60.00	0.00	60.00	LB	0.00	\$24.00	\$
		0078	5650	7123610	SLAB DRAIN	18.00	0.00	18.00	EA	0.00	\$680.00	\$
		0078	5660	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.00	\$19,499.60	\$
		0078	5670	7163000	TYPE N PTFE BEARING	20.00	0.00	20.00	EA	0.00	\$3,800.00	\$
		0078	5680	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	204.00	0.00	204.00	LF	0.00	\$490.00	ş
		0079	5690	2162500	REMOVAL OF EXISTING BRIDGE DECK	47,733.00	0.00	47,733.00	SQFT	0.00	\$18.00	ş
		0079	5700	2169902	MISC.Removal of Existing Bearings	20.00	0.00	20.00	EA	0.00	\$3,500.00	4
		0079	5710	5031010A		389.00	0.00	389.00	SQYD	0.00	\$335.00	ş
		0079	5720	6071060	PEDESTRIAN FENCE (STRUCTURES)	90.00	0.00	90.00	LF	0.00	\$240.00	9
		0079	5730	6181015	RAILROAD PLAN SUBMITTAL	1.00	0.00	1.00	LS	0.00	\$15,000.00	e e e e e e e e e e e e e e e e e e e
		0079	5740	7034212	SLAB ON STEEL	5,200.00	0.00	5,200.00	SQYD	0.00	\$425.00	4
		0079	5750	7034212 7034219A		1,420.00	0.00	1,420.00	LF	0.00	\$115.00	9
		0079	5760	7039907	MISC.Ultra-High Performance Concrete	33.20	0.00	33.20	CUYD	0.00	\$10,000.00	\$
			5770	7039907	SUBSTRUCTURE REPAIR (FORMED)	250.00	0.00	250.00	SQFT	0.00	\$170.00	4
		0079	5110	1040101	CODUCTIONE NET AIR (FURMED)	200.00	0.00	200.00	5Qf" I	0.00	φ17U.UU	\$

### Total Paid / All Items / All Estimates (Including this Estimate)

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
218-F06	J6I3187	0079	5790	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$24,650.00	\$0.0
		0079	5800	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$8,000.00	\$0.0
		0079	5810	7121100	FABRICATED STRUCTURAL LOW ALLOY STEEL (MISC)	39,200.00	0.00	39,200.00	LB	0.00	\$11.00	\$0.0
		0079	5820	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	0.00	\$660.00	\$0.0
		0079	5830	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	700.00	0.00	700.00	SQFT	0.00	\$30.00	\$0.0
		0079	5840	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	700.00	0.00	700.00	SQFT	0.00	\$3.00	\$0.0
		0079	5850	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	700.00	0.00	700.00	SQFT	0.00	\$3.00	\$0.0
		0079	5860	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	10.00	0.00	10.00	EA	0.00	\$1,500.00	\$0.0
		0079	5870	7163000	TYPE N PTFE BEARING	20.00	0.00	20.00	EA	0.00	\$4,800.00	\$0.0
		0079	5880	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	332.00	0.00	332.00	LF	0.00	\$485.00	\$0.0
		0080	5890	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$95,000.00	\$95,000.0
		0001	6101	9039901	MISC.Overhead Sign Repair	0.00	1.00	1.00	LS	1.00	\$4,867.89	\$4,867.8
	Project J	1613187 - To	otal Value	Posted to D	ate as of Report Generated Date							\$1,155,857.6
218-F06 Ove	rall - Tota	I Value Pos	ted to Da	te as of Rep	ort Generated Date							\$12,233,679.7



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6I3149

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0070	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP1	12/6/22	12/16/22	653.31	TONS		677+81		696+37		NB 2nd/3200 Broadway/Potomac
0090	4071005	TACK COAT	12/6/22	12/16/22	340.00	GAL		677+81		696+37		NB 2nd/3200 Broadway/Potomac
0110	5041000	CONCRETE APPROACH PAVEMENT	12/7/22	12/16/22	199.10	SQYD	NB 55 Virginia Stage 1B South & North approaches (546+41.21 - 546+71.21 & 548+65.21 - 548+95.21) North 100.0 SQYD & South 99.1 SQYD	546+41.21		548+95.21		Moved concrete approach pavement limits back to existing E joint locations. 22SLB2RS0009 poured back or 11/22/22
				12/16/22	259.20	SQYD	SB 55 Bates Stage 1B South & North approaches (551+49.82 - 552+06.32 & 554+10.70 - 554+34.53) North 101.9 SQYD & South 157.3 SQYD	551+49.82		554+34.53		Moved concrete approach pavement limits back to existing E joint locations. 22SLB2RS0009 w/ accelerator
0150	6099903	MISC. PAVED DRAINAGE	12/12/22	12/16/22	13.00	LF	I-55 NB 3200 Broadway Northside Right Shoulder	0		0		
0160	6116010A	SLOPE PROTECTION	12/12/22	12/16/22	12.00	SQYD	I-55 NB Potomac SW & NW and 2nd St NW Corners	0		0		11 SY was performed by Concrete Strategies at Potomac SW & NW Corners 1 SY was performed by KCI at 2nd St NW Corner
0210	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	12/8/22	12/16/22	39.00	SQYD	Pavement Repair at NB 55 3200 Broadway exit gore			692+35.70		Will need to be added to a change order at a later date
0230	6139905	MISC. PAVEMENT REPAIR	12/8/22	12/16/22	39.00	SQYD	Pavement Repair at NB 55 3200 Broadway exit gore			692+35.70		Will need to be added to a change order at a later date
0270	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	12/12/22	12/16/22	34.00	LF	I-55 NB 3200 Broadway SE Gore Section	0		0		
0280	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	12/13/22	12/16/22	32.00	LF	I-55 NB at 2nd Street right barrier at South Approach pavement and slab.					
			12/14/22	12/16/22	22.00	LF	CL 55 hand finish barrier tying into Sign Truss	570+02.5		570+24.5		
			12/15/22	12/16/22	282.00	LF	CL 55 North of Stage 3 Crossover	537+00		539+82		Machine finish concrete
0390	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	12/6/22	12/16/22	3,721.00	SQYD		677+81		696+37		NB 2nd/3200 Broadway/Potomac
0490	6061060	MGS GUARDRAIL	12/15/22	12/16/22	525.00	LF	I55 NB at off ramp to 3200 Broadway. Left and right side of ramp					
0510	6061068	MGS BRIDGE APP. TRANS SEC (EXT CURB)	12/15/22	12/16/22	1.00	EA	I55 NB at Northeast end of 2nd Street at barrier to guardrail transition					
0520	6061080	MGS END ANCHOR	12/15/22	12/16/22	2.00		I55 NB at off ramp to 3200 Broadway. Left and right side of ramp					
0540	6063019 6069903	TYPE E CRASHWORTHY END TERMINAL	12/15/22	12/16/22	1.00	EA LF	I55 NB at off ramp between 2nd Street and 3200 Broadway					
0550	0009903	MISC. GOARDRAIL ITEM	12/15/22	12/16/22	124.00	LF	I55 NB at off ramp to 3200 Broadway. Left and right side of ramp					
0560	9011070	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE B	12/14/22	12/16/22	2.00	EA	155 NB at 2nd Street on bridge deck on right barrier					
0570	9011104	BRACKET ARM, 4 FT. OR 1.2 M	12/14/22	12/16/22	2.00	EA	155 NB at 2nd Street on bridge deck on right barrier					
0580	9011313	LUMINAIRE, LED-C	12/14/22	12/16/22	2.00	EA	155 NB at 2nd Street on bridge deck on right barrier					
0590	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	12/14/22	12/16/22	37.00	LF	155 NB at 2nd Street South and North of bridge					
0600	9015010	TRENCHING TYPE I	12/14/22	12/16/22	37.00	LF	155 NB at 2nd Street South and North of bridge					
0610	9016110	PULL BOX, PREFORMED CLASS 1	12/14/22	12/16/22	2.00	EA	I55 NB at 2nd Street South and North of bridge					
0620	9017006	CABLE, 6 AWG 1 CONDUCTOR	12/14/22	12/16/22	1,530.00	LF	155 NB at 2nd Street in right traffic barrier on deck					
0640	9017206	WIRE, 6 AWG, BARE NEUTRAL	12/14/22	12/16/22	770.00	LF	155 NB at 2nd Street in right traffic barrier on deck					
0720	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	12/7/22	12/16/22	123.60	SQYD	NB 55 Virginia Stage 1B North & South Bridge Approach Slabs	546+71.21		548+65.21		22SLB2RS0009 poured back on 11/22/22.
0770	7034214	CLASS B-2 CONCRETE	12/7/22	12/16/22	1.70	CUYD	NB 55 Virginia Stage 1B approach notch	0		0		Poured at an earlier date
0980	7034214	CLASS B-2 CONCRETE	12/7/22	12/16/22	1.70	CUYD	SB 55 Virginia Stage 1B approach notch	0		0		Poured at an earlier date
1060	7101000	REINFORCING STEEL (EPOXY COATED)	12/7/22	12/16/22	440.00	LB	SB 55 Virginia Stage 1B approach notch steel	0		0		
1180	7034214	CLASS B-2 CONCRETE	12/7/22	12/16/22	1.70	CUYD	NB 55 Bates Stage 1B approach notch	0		0		Poured at an earlier date
1340	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	12/7/22	12/16/22	108.00	SQYD	NB 55 Bates Stage 1B North & South Bridge Approach Slabs	552+06.32		554+10.70		22SLB2RS0009
1390	7034214	CLASS B-2 CONCRETE	12/7/22	12/16/22	1.70	CUYD	SB 55 Bates Stage 1B approach notch	0		0		Poured at an earlier date
2410	7031004	DIAMOND GRINDING	12/9/22	12/16/22	237.00	SQYD	NB 55 Potomac Diamond Grinding	679+11.44		682+11.79		
2420	7033013	PENETRATING CONCRETE SEALER	12/5/22	12/16/22	131.00	SY	NB 55 Potomac left & right bridge barrier	679+93.44		681+60.29		Work performed at an earlier date when I was on vacation
2440	7034215	TYPE B BARRIER	12/12/22	12/16/22	4.30	LF	I-55 NB Potomac NW Corner	0		0		
2520	7049903	MISC.	12/12/22	12/16/22	5.00	LF	I-55 NB Potomac SW Corner	0		0		
2780	7034212	SLAB ON STEEL	12/13/22	12/16/22	428.50	SQYD	I-55 NB at 2nd Street Deck					
2790	7034219A	TYPE D BARRIER	12/7/22	12/16/22	1,260.00	LF	Left and Right deck barrier. Also left and right barrier on North and South approaches					
2800	7039907	MISC. CONCRETE CONSTRUCTION	12/2/22	12/14/22		CUYD	155 NB at 2nd Street at abutment 9 expansion joint					
3190	7031004	DIAMOND GRINDING	12/9/22	12/16/22	158.00	SQYD	NB 55 3200 Broadway Diamond Grinding	692+25.05		695+40.03		
3200	7033013	PENETRATING CONCRETE SEALER	12/5/22	12/16/22	137.00	SY	NB 55 3200 Broadway left & right bridge barrier	692+63.55		694+46.97		Work performed at an earlier date when I was on vacation

Due	ject:	101	24	07	
FIU	jeci.	10	21	01	

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
3610	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP1	12/5/22	12/16/22	424.10	TONS		456+16		539+50		SB I-55 Stage 3 Shoulder Virginia to Carondelet on ramp. Installed in 1 lift with mix from line 3620
3620	4030105	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125C MIX)	12/5/22	12/16/22	370.91	TONS		456+16		539+50		SB I-55 Stage 3 Shoulder Virginia to Carondelet on ramp
3650 4071005	TACK COAT	12/2/22	12/16/22	243.00	GAL		462+62		534+44		SB I-55 Stage 3 lane 1/2 joint Virginia to Carondelet on ramp	
			12/3/22	12/16/22	340.00	GAL		462+62		534+44		SB I-55 3/4 Joint Virginia to Carondelet on ramp + shoulder by Virginia
			12/5/22	12/16/22	437.00	GAL		456+16		539+50		SB I-55 Stage 3 Shoulder Virginia to Carondelet on ramp
3820	6122030	IMPACT ATTENUATOR (RELOCATION)	12/14/22	12/16/22	1.00	EA	NB 55 Relocated Impact Attenuator for Stage 3 crossover near River Des Peres	0		0		
3940	6173600D	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	12/14/22	12/16/22	600.00	LF	NB 55 Temporary Traffic Barrier for Stage 3 crossover near River Des Peres	0		0		Concrete and 1275 LF of barrier is being stockpiled behind this run of barrier for the time being
4050	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	12/2/22	12/16/22	1,287.00	SQYD		462+62		534+44		SB I-55 Stage 3 lane 1/2 joint Virginia to Carondelet on ramp
			12/3/22	12/16/22	720.00	SQYD		462+62		534+44		SB I-55 3/4 Joint Virginia to Carondelet on ramp + shoulder by Virginia
4060	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REM	12/5/22	12/16/22	5,642.00	SQYD		456+16		539+50		SB I-55 Stage 3 Shoulder Virginia to Carondelet on ramp
6101	9039901	MISC. HIGHWAY SIGNING	12/15/22	12/16/22	1.00	LS		213+25		726		

The information below this line are details for Construction Signs (if applicable). No Data Available



Dec 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6I3149	0050	ASPHALTIC CONCRETE	Other Item Adjustment	ACAD	13	Oct 4, 2022	kloepj1	\$3,103.82	SP125 22-90. 9/23/22. Current Index: 755, Base Index: 531.25, Index Difference: 223.75													
		MIXTURE PG 64-22 (SP1		ACAD - Tota	al			\$3,103.82														
		- X	Other Item Adjustment - Total					\$3,103.82														
			Overrun	Overrun	13	Oct 3, 2022	SYSTEM	(\$707.60)														
				Overrun - T	otal			(\$707.60)														
			Overrun - Tota	al				(\$707.60)														
	0050 -	50 - Total						\$2,396.22														
	0060	ASPHALTIC CONCRETE MIXTURE PG	Other Item Adjustment	ACAD	13	Oct 4, 2022	kloepj1	\$317.52	SP125 20-94. 4/19/22. Current Index: 557.5, Base Index: 531.25, Index Difference: 26.25													
		76-22 (SP125C		ACAD - Tota	al			\$317.52														
		MIX)	Other Item Ad	justment - To	tal			\$317.52														
	0060 -	Total						\$317.52														
	0070	ASPHALTIC CONCRETE MIXTURE PG	E Adjustment	ACAD	18	Dec 16, 2022	kloepj1	\$4,246.52	SP125BSM. 12/6/22. Current Index: 631.25, Base Index: 531.25, Index Difference: 100													
		76-22 (SP1		ACAD - Tota				\$4,246.52														
			Other Item Ad	justment - To	tal			\$4,246.52														
	0070 -	Total						\$4,246.52														
	0090	TACK COAT	Material		3	May 2, 2022	SYSTEM	\$1,522.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					3	May 2, 2022	SYSTEM	(\$1,522.50)														
				- Total				\$0.00														
			Material - Total					\$0.00														
	0090 -	Total						\$0.00														
	0110	CONCRETE APPROACH PAVEMENT			10	Aug 16, 2022	SYSTEM	\$27,869.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user mitcha3 overridding Payment Estimate Exception 7 on the current Payment Estimate.													
					10	Aug 16, 2022	SYSTEM	(\$27,869.40)														
												11	Sep 1, 2022	SYSTEM	\$41,698.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user mitcha3 overridding Payment Estimate Exception 14 on the current Payment Estimate.						
										11	Sep 1, 2022	SYSTEM	(\$41,698.80)									
												12	Sep 16, 2022	SYSTEM	\$116,321.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.						
																		12	Sep 16, 2022	SYSTEM	(\$116,321.40)	
																						13
												13	Oct 3, 2022	SYSTEM	(\$130,221.00)							
									14	Oct 15, 2022	SYSTEM	\$130,221.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user mitcha3 overridding Payment Estimate Exception 28 on the current Payment Estimate.									
					14	Oct 15, 2022	SYSTEM	(\$130,221.00)														
					15	Nov 2, 2022	SYSTEM	\$198,888.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user mitcha3 overridding Payment Estimate Exception 36 on the current Payment Estimate.													
				1	15	Nov 2, 2022	SYSTEM	(\$198,888.30)														
						16	Nov 16, 2022	SYSTEM	\$246,507.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mitcha3 overridding Payment Estimate Exception 48 on the current Payment Estimate.												
					16	Nov 16, 2022	SYSTEM	(\$246,507.30)														
					17	Dec 1, 2022	SYSTEM	\$275,172.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6I3149	0110	CONCRETE APPROACH PAVEMENT	Material						Estimate Exception 36 on the current Payment Estimate.	
					17	Dec 1, 2022	SYSTEM	(\$275,172.30)		
					18	Dec 16, 2022	SYSTEM	\$328,793.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	
					18	Dec 16, 2022	SYSTEM	(\$328,793.40)		
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
	0110 -	Total						\$0.00		
	0120	6 IN. CONCRETE MEDIAN STRIP	Material		8	Jul 18, 2022	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user mitcha3 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
					8	Jul 18, 2022	SYSTEM	(\$1,705.00)		
					9	Aug 2, 2022	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					9	Aug 2, 2022	SYSTEM	(\$1,705.00)		
					10	Aug 16, 2022	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user mitcha3 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
					10	Aug 16, 2022	SYSTEM	(\$1,705.00)		
					11	Sep 1, 2022	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user mitcha3 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
					11	Sep 1, 2022	SYSTEM	(\$1,705.00)		
					12	Sep 16, 2022	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	
					12	Sep 16, 2022	SYSTEM	(\$1,705.00)		
					13	Oct 3, 2022	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	
					13	Oct 3, 2022	SYSTEM	(\$1,705.00)		
					14	Oct 15, 2022	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user mitcha3 overridding Payment Estimate Exception 47 on the current Payment Estimate.	
					14	Oct 15, 2022	SYSTEM	(\$1,705.00)		
					15	Nov 2, 2022	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user mitcha3 overridding Payment Estimate Exception 58 on the current Payment Estimate.	
					15	Nov 2, 2022	SYSTEM	(\$1,705.00)		
						16	Nov 16, 2022	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mitcha3 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$1,705.00)		
					17	Dec 1, 2022	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 57 on the current Payment Estimate.	
					17	Dec 1, 2022	SYSTEM	(\$1,705.00)		
					18	Dec 16, 2022	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.	
					18	Dec 16, 2022	SYSTEM	(\$1,705.00)		
				- Total				\$0.00		



Dec 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J6I3149	0120	6 IN. CONCRETE MEDIAN STRIP	Material - Tota					\$0.00					
	0120 -	Total						\$0.00					
	0150	MISC. PAVED DRAINAGE	Material		14	Oct 15, 2022	SYSTEM	\$3,760.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user mitcha3 overridding Payment Estimate Exception 49 on the current Payment Estimate.				
					14	Oct 15, 2022	SYSTEM	(\$3,760.25)					
					15	Nov 2, 2022	SYSTEM	\$3,760.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user mitcha3 overridding Payment Estimate Exception 60 on the current Payment Estimate.				
					15	Nov 2, 2022	SYSTEM	(\$3,760.25)					
					16	Nov 16, 2022	SYSTEM	\$3,760.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mitcha3 overridding Payment Estimate Exception 69 on the current Payment Estimate.				
					16	Nov 16, 2022	SYSTEM	(\$3,760.25)					
					17	Dec 1, 2022	SYSTEM	\$3,760.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user mitcha3 overridding Payment Estimate Exception 58 on the current Payment Estimate.				
					17	Dec 1, 2022	SYSTEM	(\$3,760.25)					
										18	Dec 16, 2022	SYSTEM	\$4,309.50
					18	Dec 16, 2022	SYSTEM	(\$4,309.50)					
				- Total				\$0.00					
			Material - Tota	ıl				\$0.00					
	0150 -	Total						\$0.00					
	0160	SLOPE PROTECTION	Material		9	Aug 2, 2022	SYSTEM	\$12,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					9	Aug 2, 2022	SYSTEM	(\$12,920.00)					
					10	Aug 16, 2022	SYSTEM	\$15,010.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user mitcha3 overridding Payment Estimate Exception 21 on the current Payment Estimate.				
					10	Aug 16, 2022	SYSTEM	(\$15,010.00)					
					11	Sep 1, 2022	SYSTEM	\$15,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user mitcha3 overridding Payment Estimate Exception 31 on the current Payment Estimate.				
					11	Sep 1, 2022	SYSTEM	(\$15,200.00)					
					12	Sep 16, 2022	SYSTEM	\$21,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.				
					12	Sep 16, 2022	SYSTEM	(\$21,090.00)					
						13	Oct 3, 2022	SYSTEM	\$26,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.			
					13	Oct 3, 2022	SYSTEM	(\$26,125.00)					
					14	Oct 15, 2022	SYSTEM	\$26,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user mitcha3 overridding Payment Estimate Exception 53 on the current Payment Estimate.				
					14	Oct 15, 2022	SYSTEM	(\$26,125.00)					
					15	Nov 2, 2022	SYSTEM	\$26,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user mitcha3 overridding Payment Estimate Exception 64 on the current Payment Estimate.				
					15	Nov 2, 2022	SYSTEM	(\$26,125.00)					
				- Total									



t Li	ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
9 01	160	SLOPE PROTECTION	Material - Tota	ıl				\$0.00	
01	160 - 1	Total						\$0.00	
01	180	REPLACEMENT SAND BARREL	Overrun	Overrun	16	Nov 16, 2022	SYSTEM	(\$1,344.00)	
				Overrun - To	otal			(\$1,344.00)	
			Overrun - Total					(\$1,344.00)	
01	180 - '	Total						(\$1,344.00)	
01	190	IMPACT ATTENUATOR	Overrun	Overrun	16	Nov 16, 2022	SYSTEM	(\$1,356.00)	
		(RELOCATION)		Overrun - T	otal			(\$1,356.00)	
			Overrun - Tota	al				(\$1,356.00)	
01	190 - '	Total						(\$1,356.00)	
	210	FURN & PLACE CONC MATL FOR	Material		18	Dec 16, 2022	SYSTEM	\$8,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepi1 overridding Payment
		FULL DEPTH			18	Dec 16, 2022	SYSTEM	(\$8,970.00)	Estimate Exception 61 on the current Payment Estimate.
				- Total				\$0.00	
			Motorial Tat						
			Material - Tota					\$0.00	
	210 - ` 220	Total SUBGRADE COMPACTION (6	Material		10	Aug 16, 2022	SYSTEM	\$0.00 \$36.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user mitcha3 overridding Payment
		IN. DEPTH IN. (PAVEM			10	Aug 16,	SYSTEM	(\$36.00)	Estimate Exception 23 on the current Payment Estimate.
					11	2022 Sep 1, 2022	SYSTEM	\$36.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user mitcha3 overridding Payment
					11	Sep 1,	SYSTEM	(\$36.00)	Estimate Exception 36 on the current Payment Estimate.
					12	2022 Sep 16, 2022	SYSTEM	\$36.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment
					12	Sep 16, 2022	SYSTEM	(\$36.00)	Estimate Exception 48 on the current Payment Estimate.
					13	Oct 3, 2022	SYSTEM	\$36.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					13	Oct 3, 2022	SYSTEM	(\$36.00)	Esumate Exception 47 on the current Payment Estimate.
						14	Oct 15, 2022	SYSTEM	\$36.00
					14	Oct 15, 2022	SYSTEM	(\$36.00)	
				- Total				\$0.00	
			Material - Tota	d				\$0.00	
02	220 -	Total						\$0.00	
	270	CONCRETE TRAFFIC BARRIER, TYPE B	Material		18	Dec 16, 2022	SYSTEM	\$6,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 64 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$6,290.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
.02	270 - `	Total						\$0.00	
	280	CONCRETE TRAFFIC BARRIER, TYPE C	Material		5	Jun 2, 2022	SYSTEM	\$33,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mitcha3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		_, uer, i i i e U			5	Jun 2, 2022	SYSTEM	(\$33,192.00)	
					6	Jun 16,	SYSTEM	\$152,136.00	This adjustment offsets the original system-generated Material Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
9 (	0280	CONCRETE TRAFFIC	Material			2022			Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.					
		BARRIER, TYPE C			6	Jun 16, 2022	SYSTEM	(\$152,136.00)						
					7	Jul 1, 2022	SYSTEM	\$248,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 13 on the current Payment Estimate.					
					7	Jul 1, 2022	SYSTEM	(\$248,544.00)						
					8	Jul 18, 2022	SYSTEM	\$263,376.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user mitcha3 overridding Payment Estimate Exception 29 on the current Payment Estimate.					
					8	Jul 18, 2022	SYSTEM	(\$263,376.00)						
					9	Aug 2, 2022	SYSTEM	\$252,216.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.					
					9	Aug 2, 2022	SYSTEM	(\$252,216.00)						
					10	Aug 16, 2022	SYSTEM	\$265,896.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user mitcha3 overridding Paymen Estimate Exception 24 on the current Payment Estimate.					
					10	Aug 16, 2022	SYSTEM	(\$265,896.00)						
					11	Sep 1, 2022	SYSTEM	\$340,056.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user mitcha3 overridding Paymen Estimate Exception 41 on the current Payment Estimate.					
					11	Sep 1, 2022	SYSTEM	(\$340,056.00)						
										12	Sep 16, 2022	SYSTEM	\$340,056.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
												12	Sep 16, 2022	SYSTEM
					15	Nov 2, 2022	SYSTEM	\$340,056.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user mitcha3 overridding Paymen Estimate Exception 70 on the current Payment Estimate.					
					15	Nov 2, 2022	SYSTEM	(\$340,056.00)						
				- Total				\$0.00						
			Made and all Trade											
	0280 -	Total	Material - Tota	1				\$0.00						
	0280 - 0300	TEMPORARY TRAFFIC	Material - Tota Other Item Adjustment	nl MATL	4	May 16, 2022	mitcha3	\$0.00 \$0.00 \$3,297.00	KCI had left over non-glavanized barrier plates. MoDOT has opted to purchase these plates for use by maintenance.					
		TEMPORARY	Other Item				mitcha3	\$0.00						
		TEMPORARY TRAFFIC BARRIER, CONT.	Other Item	MATL MATL - Tota	al		mitcha3	<b>\$0.00</b> \$3,297.00						
		TEMPORARY TRAFFIC BARRIER, CONT.	Other Item Adjustment	MATL MATL - Tota	al Ital		mitcha3 SYSTEM	\$0.00 \$3,297.00 \$3,297.00						
		TEMPORARY TRAFFIC BARRIER, CONT.	Other Item Adjustment Other Item Ad Overrun	MATL MATL - Tota justment - To Overrun Overrun - T	al Ital 16	2022 Nov 16,		\$0.00 \$3,297.00 \$3,297.00 \$3,297.00 (\$24,588.38) (\$24,588.38)						
0	0300	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Other Item Adjustment Other Item Ad	MATL MATL - Tota justment - To Overrun Overrun - T	al Ital 16	2022 Nov 16,		\$0.00 \$3,297.00 \$3,297.00 (\$24,588.38) (\$24,588.38) (\$24,588.38)						
		TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Other Item Adjustment Other Item Ad Overrun	MATL MATL - Tota justment - To Overrun Overrun - T	al Ital 16	2022 Nov 16,		\$0.00 \$3,297.00 \$3,297.00 \$3,297.00 (\$24,588.38) (\$24,588.38)	purchase these plates for use by maintenance.					
	0300	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Other Item Adjustment Other Item Ad Overrun	MATL MATL - Tota justment - To Overrun Overrun - T	al Ital 16 otal	2022 Nov 16, 2022 Apr 18, 2022 Apr 18,	SYSTEM	\$0.00 \$3,297.00 \$3,297.00 (\$24,588.38) (\$24,588.38) (\$24,588.38) (\$21,291.38)	purchase these plates for use by maintenance.					
	0300	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Other Item Adjustment Other Item Ad Overrun	MATL MATL - Tota justment - To Overrun Overrun - T	al tal 16 ootal	2022 Nov 16, 2022 Apr 18, 2022	SYSTEM	\$0.00 \$3,297.00 \$3,297.00 (\$24,588.38) (\$24,588.38) (\$24,588.38) (\$21,291.38) \$5,200.00	purchase these plates for use by maintenance. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kloep)1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mitcha3 overridding Payment					
	0300	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Other Item Adjustment Other Item Ad Overrun	MATL MATL - Tota justment - To Overrun Overrun - T	al tal 16 otal 2 2	2022 Nov 16, 2022 Apr 18, 2022 Apr 18, 2022 May 2, 2022 May 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$3,297.00 \$3,297.00 (\$24,588.38) (\$24,588.38) (\$24,588.38) (\$24,588.38) (\$21,291.38) \$5,200.00	purchase these plates for use by maintenance.					
(	0300	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Other Item Adjustment Other Item Ad Overrun	MATL MATL - Tota justment - To Overrun Overrun - T	al tal 16 otal 2 2 3	2022 Nov 16, 2022 Apr 18, 2022 Apr 18, 2022 May 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$3,297.00 \$3,297.00 (\$24,588.38) (\$24,588.38) (\$24,588.38) (\$21,291.38) \$5,200.00 (\$5,200.00) \$5,200.00	purchase these plates for use by maintenance. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kloep)1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mitcha3 overridding Payment Estimate Item Adjustment (0001) due to user mitcha3 overridding Payment					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3149	0450	MISC. MANHOLES AND DROP INLETS	Material		5	Jun 2, 2022	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mitcha3 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$5,200.00)	
					6	Jun 16, 2022	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$5,200.00)	
					7	Jul 1, 2022	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mitcha3 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$5,200.00)	
					8	Jul 18, 2022	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mitcha3 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$5,200.00)	
					9	Aug 2, 2022	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					9	Aug 2, 2022	SYSTEM	(\$5,200.00)	
					10	Aug 16, 2022	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mitcha3 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					10	Aug 16, 2022	SYSTEM	(\$5,200.00)	
					11	Sep 1, 2022	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mitcha3 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					11	Sep 1, 2022	SYSTEM	(\$5,200.00)	
					12	Sep 16, 2022	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$7,800.00)	
					13	Oct 3, 2022	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 92 on the current Payment Estimate.
					13	Oct 3, 2022	SYSTEM	(\$13,000.00)	
					14	Oct 15, 2022	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 103 on the current Payment Estimate.
					14	Oct 15, 2022	SYSTEM	(\$13,000.00)	
					15	Nov 2, 2022	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user mitcha3 overridding Payment Estimate Exception 127 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$13,000.00)	
					16	Nov 16, 2022	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 140 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$13,000.00)	
					17	Dec 1, 2022	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user mitcha3 overridding Payment Estimate Exception 121 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$15,600.00)	
					18	Dec 16, 2022	SYSTEM	\$15,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 140 on the current Payment Estimate.
					18	Dec 16,	SYSTEM	(\$15,600.00)	



Dec 20, 2022

ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
149	0450	MISC. MANHOLES	Material	Туре		2022			
	0400	AND DROP INLETS	Wateria	- Total		2022		\$0.00	
		INCLIS	Material - Tota					\$0.00	
	0450 -	Total						\$0.00	
	0490	MGS GUARDRAIL	Construction Stockpile		13	Oct 3, 2022	SYSTEM	(\$20,391.89)	Payment Estimate Item Adjustment generated Stockpile Transaction
					16	Nov 16, 2022	SYSTEM	(\$16,168.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					18	Dec 16, 2022	SYSTEM	(\$10,610.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$47,170.14)	
			Construction	Stockpile - To	otal			(\$47,170.14)	
			Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$118,693.33	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$118,693.33	
			Construction	Stockpile STI	MI - Total			\$118,693.33	
	0490 -	Total						\$71,523.19	
	0500	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$11,550.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$11,550.00	
			Construction	Stockpile STI	MI - Total			\$11,550.00	
	0500 -							\$11,550.00	
	0510	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Construction Stockpile		13	Oct 3, 2022	SYSTEM	(\$15,400.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				Tabal	18	Dec 16, 2022	SYSTEM	(\$2,200.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total n Stockpile - Total				(\$17,600.00)	
				Stockpile - To	1	Amr 4	SYSTEM	(\$17,600.00)	Devenent Estimate Hom Adjustment reported Cleakails Transaction
			Construction Stockpile STMI	- Total	1	Apr 4, 2022	STSTEM	\$39,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		MI - Total			\$39,600.00	
	0510 -	Total						\$22,000.00	
- 5	0520	MGS END ANCHOR	Construction Stockpile		13	Oct 3, 2022	SYSTEM	(\$850.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					18	Dec 16, 2022	SYSTEM	(\$1,700.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$2,550.00)	
			Construction	Stockpile - To	otal			(\$2,550.00)	
			Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$6,800.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$6,800.00	
			Construction	Stockpile STI	MI - Total			\$6,800.00	
	0520 - 0530	TYPE A			13	Oct 3,	SYSTEM	\$4,250.00 (\$3,900.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		CRASHWORTHY END TERMINAL (MASH)	Stockpile		16	2022 Nov 16, 2022	SYSTEM	(\$1,950.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total		2022		(\$5,850.00)	
			Construction		otal			(\$5,850.00)	
			Construction Construction Stockpile	eteckpile - To	1	Apr 4, 2022	SYSTEM	(\$5,850.00) \$17,550.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$17,550.00	
			Construction		MI - Total			\$17,550.00	
	0530 -	Total						\$11,700.00	
	0540	TYPE E			18	Dec 16,	SYSTEM	(\$21,780.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		CRASHWORTHY END TERMINAL	Stockpile			2022			



Dec 20, 2022

t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
9	0540	TYPE E	Construction	Stockpile - To	otal			(\$21,780.00)		
		CRASHWORTHY END TERMINAL	Construction Stockpile		4	May 16, 2022	SYSTEM	\$21,780.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STMI	- Total				\$21,780.00		
			Construction	Stockpile STI	MI - Total			\$21,780.00		
	0540 -	Total						\$0.00		
ſ	0550	MISC. GUARDRAIL ITEM	Construction Stockpile		18	Dec 16, 2022	SYSTEM	(\$3,586.12)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$3,586.12)		
			Construction	Stockpile - To	otal			(\$3,586.12)		
			Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$3,991.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			5111	- Total				\$3,991.00		
			Construction	Stockpile ST	MI - Total			\$3,991.00		
	0550 -	Total						\$404.88		
	0560	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE B	Material		18	Dec 16, 2022	SYSTEM	\$6,602.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payme Estimate Exception 141 on the current Payment Estimate.	
					18	Dec 16, 2022	SYSTEM	(\$6,602.00)		
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
	0560 -	Total						\$0.00		
ſ	0570	BRACKET ARM, 4 FT. OR 1.2 M	Material		18	Dec 16, 2022	SYSTEM	\$830.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payme Estimate Exception 144 on the current Payment Estimate.	
					18	Dec 16, 2022	SYSTEM	(\$830.00)		
			- Total						\$0.00	
			Material - Tota	al				\$0.00		
	0570 -	Total						\$0.00		
	0590	CONDUIT, 3 IN. RIGID, IN TRENCH	Material		18	Dec 16, 2022	SYSTEM	\$777.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payme Estimate Exception 146 on the current Payment Estimate.	
					18	Dec 16, 2022	SYSTEM	(\$777.00)		
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
	0590 -	Total						\$0.00		
	0610	PULL BOX, PREFORMED CLASS 1	Material		18	Dec 16, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payme Estimate Exception 147 on the current Payment Estimate.	
					18	Dec 16, 2022	SYSTEM	(\$4,000.00)		
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
	0610 -	Total						\$0.00		
	0620	CABLE, 6 AWG 1 CONDUCTOR	Material		18	Dec 16, 2022	SYSTEM	\$3,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payme Estimate Exception 148 on the current Payment Estimate.	
					18	Dec 16, 2022	SYSTEM	(\$3,060.00)	. ,	
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
	0620 -	Total						\$0.00		
	0640	WIRE, 6 AWG, BARE NEUTRAL	Material		18	Dec 16, 2022	SYSTEM	\$1,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payme Estimate Exception 149 on the current Payment Estimate.	
					18	Dec 16,	SYSTEM	(\$1,540.00)	· · · ·	



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
3149	0640	WIRE, 6 AWG,	Material	- Total				\$0.00			
		BARE NEUTRAL	Material - Tota	I				\$0.00			
	0640 -	Total						\$0.00			
	0720	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		10	Aug 16, 2022	SYSTEM	\$44,072.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					10	Aug 16, 2022	SYSTEM	(\$44,072.00)			
					11	Sep 1, 2022	SYSTEM	\$44,072.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mitcha3 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					11	Sep 1, 2022	SYSTEM	(\$44,072.00)			
					12	Sep 16, 2022	SYSTEM	\$44,072.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					12	Sep 16, 2022	SYSTEM	(\$44,072.00)			
					13	Oct 3, 2022	SYSTEM	\$44,072.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					13	Oct 3, 2022	SYSTEM	(\$44,072.00)			
					14	Oct 15, 2022	SYSTEM	\$44,072.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					14	Oct 15, 2022	SYSTEM	(\$44,072.00)			
					15	Nov 2, 2022	SYSTEM	\$44,072.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user mitcha3 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
							15	Nov 2, 2022	SYSTEM	(\$44,072.00)	
					16	Nov 16, 2022	SYSTEM	\$44,072.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user mitcha3 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					16	Nov 16, 2022	SYSTEM	(\$44,072.00)			
					17	Dec 1, 2022	SYSTEM	\$44,072.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mitcha3 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					17	Dec 1, 2022	SYSTEM	(\$44,072.00)			
					18	Dec 16, 2022	SYSTEM	\$78,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					18	Dec 16, 2022	SYSTEM	(\$78,680.00)			
				- Total				\$0.00			
			Material - Tota	1				\$0.00			
	0720 -							\$0.00			
	0730	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		6	Jun 16, 2022	SYSTEM	\$4,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					6	Jun 16, 2022	SYSTEM	(\$4,900.00)			
					7	Jul 1, 2022	SYSTEM	\$4,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mitcha3 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					7	Jul 1, 2022	SYSTEM	(\$4,900.00)			
					8	Jul 18, 2022	SYSTEM	\$4,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					8	Jul 18, 2022	SYSTEM	(\$4,900.00)			
					9	Aug 2,	SYSTEM	\$4,900.00	This adjustment offsets the original system-generated Material Payment		



Dec 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J6I3149	0730	SUPPLEMENTARY WEARING	Material			2022			Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
		SURFACE MATERIAL			9	Aug 2, 2022	SYSTEM	(\$4,900.00)					
					10	Aug 16, 2022	SYSTEM	\$4,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mitcha3 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
					10	Aug 16, 2022	SYSTEM	(\$4,900.00)					
				- Total				\$0.00					
			Material - Tota	I				\$0.00					
			Overrun	Overrun	16	Nov 16, 2022	SYSTEM	(\$4,900.00)					
				Overrun - T	otal			(\$4,900.00)					
			Overrun - Tota	ıl				(\$4,900.00)					
		- Total						(\$4,900.00)					
	0740	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		6	Jun 16, 2022	SYSTEM	\$81,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
		00111102			6	Jun 16, 2022	SYSTEM	(\$81,420.00)					
					7	Jul 1, 2022	SYSTEM	\$81,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mitcha3 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
					7	Jul 1, 2022	SYSTEM	(\$81,420.00)					
						8	Jul 18, 2022	SYSTEM	\$81,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mitcha3 overridding Payment Estimate Exception 13 on the current Payment Estimate.			
										8	Jul 18, 2022	SYSTEM	(\$81,420.00)
					9	Aug 2, 2022	SYSTEM	\$81,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
							9	Aug 2, 2022	SYSTEM	(\$81,420.00)			
					10	Aug 16, 2022	SYSTEM	\$81,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mitcha3 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					10	Aug 16, 2022	SYSTEM	(\$81,420.00)					
				- Total				\$0.00					
			Material - Tota	I				\$0.00					
	0740 -							\$0.00					
	0760	PENETRATING CONCRETE SEALER	Material		14	Oct 15, 2022	SYSTEM	(\$585.00)					
					15	Nov 2, 2022	SYSTEM	(\$585.00)					
					16	Nov 16, 2022	SYSTEM	(\$585.00)					
					17	Dec 1, 2022	SYSTEM	(\$585.00)					
					18	Dec 16, 2022	SYSTEM	(\$585.00)					
				- Total				(\$2,925.00)					
			Material - Tota	1				(\$2,925.00)					
			MaterialCredit		15	Nov 2, 2022	SYSTEM	\$585.00					
					16	Nov 16, 2022	SYSTEM	\$585.00					
					17	Dec 1, 2022	SYSTEM	\$585.00					
					18	Dec 16, 2022	SYSTEM	\$585.00					



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
9 (	0760	PENETRATING CONCRETE	MaterialCredit	- Total				\$2,340.00	
		SEALER	MaterialCredit	- Total				\$2,340.00	
	0760 -	Total						(\$585.00)	
(	0770	CLASS B-2 CONCRETE	Material		8	Jul 18, 2022	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mitcha3 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$4,500.00)	
					9	Aug 2, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					9	Aug 2, 2022	SYSTEM	(\$7,650.00)	
					10	Aug 16, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mitcha3 overridding Paymer Estimate Exception 33 on the current Payment Estimate.
					10	Aug 16, 2022	SYSTEM	(\$7,650.00)	
					11	Sep 1, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mitcha3 overridding Paymen Estimate Exception 50 on the current Payment Estimate.
					11	Sep 1, 2022	SYSTEM	(\$7,650.00)	
					12	Sep 16, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Paymen Estimate Exception 70 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$7,650.00)	
					13	Oct 3, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Paymen Estimate Exception 65 on the current Payment Estimate.
					13	Oct 3, 2022	SYSTEM	(\$7,650.00)	
					14	Oct 15, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user mitcha3 overridding Paymen Estimate Exception 76 on the current Payment Estimate.
					14	Oct 15, 2022	SYSTEM	(\$7,650.00)	
					15	Nov 2, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user mitcha3 overridding Paymen Estimate Exception 80 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$7,650.00)	
					17	Dec 1, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user mitcha3 overridding Payme Estimate Exception 74 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$7,650.00)	
					18	Dec 16, 2022	SYSTEM	\$15,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Paymen Estimate Exception 83 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$15,300.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	0770 -							\$0.00	
0	0800	HALF-SOLE REPAIR	Material		4	May 16, 2022	SYSTEM	\$7,486.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mitcha3 overridding Paymen Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$7,486.00)	
					5	Jun 2, 2022	SYSTEM	\$21,867.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Paymen Estimate Exception 7 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$21,867.00)	
					6	Jun 16,	SYSTEM	\$21,867.00	This adjustment offsets the original system-generated Material Payment



Dec 20, 2022

_			1	1					
: 1	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
) (	0080	HALF-SOLE REPAIR	Material			2022			Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$21,867.00)	
					7	Jul 1, 2022	SYSTEM	\$22,458.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mitcha3 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$22,458.00)	
					8	Jul 18, 2022	SYSTEM	\$22,458.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mitcha3 overridding Paymen Estimate Exception 35 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$22,458.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
			Overrun	Overrun	15	Nov 2, 2022	SYSTEM	(\$3,447.50)	
				Overrun - T	otal	2022		(\$3,447.50)	
			Overrun - Tota	al				(\$3,447.50)	
0	0800 -	Total						(\$3,447.50)	
C	0830	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		4	May 16, 2022	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mitcha3 overridding Paymen Estimate Exception 9 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$1,512.00)	
					5	Jun 2, 2022	SYSTEM	\$3,996.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mitcha3 overridding Paymer Estimate Exception 17 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$3,996.00)	
					6	Jun 16, 2022	SYSTEM	\$3,996.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Paymen Estimate Exception 31 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$3,996.00)	
					7	Jul 1, 2022	SYSTEM	\$3,996.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mitcha3 overridding Paymen Estimate Exception 33 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$3,996.00)	
					8	Jul 18, 2022	SYSTEM	\$3,996.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mitcha3 overridding Paymer Estimate Exception 48 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$3,996.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
0	0830 - '	Total						\$0.00	
	0860	REINFORCING STEEL (EPOXY COATED)	Material		8	Jul 18, 2022	SYSTEM	\$660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mitcha3 overridding Paymen Estimate Exception 51 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$660.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
0	0860 - 1	Total						\$0.00	
C	0930	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		12	Sep 16, 2022	SYSTEM	\$22,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Paymen Estimate Exception 7 on the current Payment Estimate.
		,			12	Sep 16, 2022	SYSTEM	(\$22,800.00)	
					13	Oct 3, 2022	SYSTEM	\$45,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Paymen Estimate Exception 7 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J6I3149	0930	BRIDGE APPROACH SLAB	Material	Туре	13	Oct 3, 2022	SYSTEM	(\$45,900.00)	
		(MAJOR ROAD)			14	Oct 15, 2022	SYSTEM	\$45,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mitcha3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					14	Oct 15, 2022	SYSTEM	(\$45,900.00)	
					15	Nov 2, 2022	SYSTEM	\$45,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user mitcha3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$45,900.00)	Estimate Exception / on the current rayment Estimate.
					16	Nov 16, 2022	SYSTEM	\$45,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user mitcha3 overridding Payment
					16	Nov 16,	SYSTEM	(\$45,900.00)	Estimate Exception 6 on the current Payment Estimate.
					17	2022 Dec 1, 2022	SYSTEM	\$45,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user mitcha3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$45,900.00)	Estimate Exception 3 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	\$45,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$45,900.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0930 -	Total						\$0.00	
	0940	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		8	Jul 18, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mitcha3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		MATERIAL			8	Jul 18, 2022	SYSTEM	(\$5,600.00)	
					9	Aug 2, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 2, 2022	SYSTEM	(\$5,600.00)	
					10	Aug 16, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mitcha3 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					10	Aug 16, 2022	SYSTEM	(\$5,600.00)	
					11	Sep 1, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mitcha3 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					11	Sep 1, 2022	SYSTEM	(\$5,600.00)	
					12	Sep 16, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$5,600.00)	
					13	Oct 3, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					13	Oct 3, 2022	SYSTEM	(\$5,600.00)	
					14	Oct 15, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user mitcha3 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					14	Oct 15, 2022	SYSTEM	(\$5,600.00)	
					15	Nov 2, 2022	SYSTEM	\$16,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mitcha3 overridding Payment Estimate Exception 42 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J6I3149	0940	SUPPLEMENTARY	Material	Туре	15	Nov 2,	SYSTEM	(\$16,100.00)	
		WEARING SURFACE MATERIAL			16	2022 Nov 16,	SYSTEM	\$16,100.00	This adjustment offsets the original system-generated Material Payment
						2022			Estimate Item Adjustment (0020) due to user mitcha3 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$16,100.00)	
					17	Dec 1, 2022	SYSTEM	\$16,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user mitcha3 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$16,100.00)	
					18	Dec 16, 2022	SYSTEM	\$16,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$16,100.00)	
				- Total		2022		\$0.00	
			Material - Tota	ıl				\$0.00	
			Overrun	Overrun	15	Nov 2, 2022	SYSTEM	(\$10,500.00)	
				Overrun - T	otal			(\$10,500.00)	
			Overrun - Tota	al				(\$10,500.00)	
	0940 -	Total						(\$10,500.00)	
	0950	LATEX MODIFIED CONCRETE WEARING	Material		8	Jul 18, 2022	SYSTEM	\$75,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mitcha3 overridding Payment Estimate Exception 16 on the current Payment Estimate.
		SURFACE			8	Jul 18, 2022	SYSTEM	(\$75,660.00)	
					9	Aug 2, 2022	SYSTEM	\$75,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Aug 2, 2022	SYSTEM	(\$75,660.00)	
					10	Aug 16, 2022	SYSTEM	\$75,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mitcha3 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					10	Aug 16, 2022	SYSTEM	(\$75,660.00)	
					11	Sep 1, 2022	SYSTEM	\$75,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mitcha3 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					11	Sep 1, 2022	SYSTEM	(\$75,660.00)	
					12	Sep 16, 2022	SYSTEM	\$75,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$75,660.00)	
					13	Oct 3, 2022	SYSTEM	\$75,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					13	Oct 3, 2022	SYSTEM	(\$75,660.00)	
					14	Oct 15, 2022	SYSTEM	\$75,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user mitcha3 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					14	Oct 15, 2022	SYSTEM	(\$75,660.00)	
					15	Nov 2, 2022	SYSTEM	\$139,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user mitcha3 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$139,490.00)	
					16	Nov 16, 2022	SYSTEM	\$139,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user mitcha3 overridding Payment Estimate Exception 58 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
613149	0950	LATEX MODIFIED CONCRETE	Material		16	Nov 16, 2022	SYSTEM	(\$139,490.00)																		
		WEARING SURFACE			17	Dec 1, 2022	SYSTEM	\$139,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate.																	
					17	Dec 1, 2022	SYSTEM	(\$139,490.00)																		
					18	Dec 16, 2022	SYSTEM	\$139,490.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.																	
					18	Dec 16, 2022	SYSTEM	(\$139,490.00)																		
				- Total				\$0.00																		
			Material - Tota	ıl				\$0.00																		
	0950 -	Total						\$0.00																		
	0970	PENETRATING CONCRETE SEALER	Material		14	Oct 15, 2022	SYSTEM	(\$585.00)																		
		SEALER			15	Nov 2, 2022	SYSTEM	(\$585.00)																		
					16	Nov 16, 2022	SYSTEM	(\$585.00)																		
					17	Dec 1, 2022	SYSTEM	(\$585.00)																		
					18	Dec 16, 2022	SYSTEM	(\$585.00)																		
				- Total				(\$2,925.00)																		
			Material - Tota	1 1				(\$2,925.00)																		
			MaterialCredit		15	Nov 2, 2022	SYSTEM	\$585.00																		
											16	Nov 16, 2022	SYSTEM	\$585.00												
					17	Dec 1, 2022	SYSTEM	\$585.00																		
					18	Dec 16, 2022	SYSTEM	\$585.00																		
				- Total				\$2,340.00																		
			MaterialCredit	- Total				\$2,340.00																		
	0970 -	Total						(\$585.00)																		
	0980	CLASS B-2 CONCRETE	Material		12	Sep 16, 2022	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kloepj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.																	
					12	Sep 16, 2022	SYSTEM	(\$4,500.00)																		
																					13	13	Oct 3,	SYSTEM	\$7,650.00	
						2022			This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.																	
					13	2022 Oct 3, 2022	SYSTEM	(\$7,650.00)	Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment																	
					13	Oct 3,	SYSTEM SYSTEM		Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment																	
						Oct 3, 2022 Oct 15,		(\$7,650.00)	Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user mitcha3 overridding Payment																	
					14	Oct 3, 2022 Oct 15, 2022 Oct 15,	SYSTEM	(\$7,650.00) \$7,650.00	Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user mitcha3 overridding Payment																	
					14	Oct 3, 2022 Oct 15, 2022 Oct 15, 2022 Nov 2,	SYSTEM SYSTEM	(\$7,650.00) \$7,650.00 (\$7,650.00)	Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user mitcha3 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user mitcha3 overridding Payment																	
					14 14 15	Oct 3, 2022 Oct 15, 2022 Oct 15, 2022 Nov 2, 2022 Nov 2,	SYSTEM SYSTEM SYSTEM	(\$7,650.00) \$7,650.00 (\$7,650.00) \$7,650.00	Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user mitcha3 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user mitcha3 overridding Payment																	
					14 14 15 15	Oct 3, 2022           Oct 15, 2022           Oct 15, 2022           Nov 2, 2022           Nov 2, 2022           Nov 2, 2022           Nov 16, Nov 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$7,650.00) \$7,650.00 (\$7,650.00) \$7,650.00 (\$7,650.00)	Estimate Item Adjustment (0025) due to user kloepj1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user mitcha3 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user mitcha3 overridding Payment Estimate Exception 81 on the current Payment Estimate.																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J6I3149	0980	CLASS B-2	Material						Estimate Exception 75 on the current Payment Estimate.					
		CONCRETE			17	Dec 1, 2022	SYSTEM	(\$7,650.00)						
					18	Dec 16, 2022	SYSTEM	\$15,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.					
					18	Dec 16, 2022	SYSTEM	(\$15,300.00)						
				- Total		1		\$0.00						
			Material - Tota	1				\$0.00						
	0980 -	Total						\$0.00						
	1000	HALF-SOLE REPAIR	Material		13	Oct 3, 2022	SYSTEM	\$985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloep11 overridding Payment Estimate Exception 79 on the current Payment Estimate.					
					13	Oct 3, 2022	SYSTEM	(\$985.00)						
					14	Oct 15, 2022	SYSTEM	\$985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user mitcha3 overridding Payment Estimate Exception 90 on the current Payment Estimate.					
					14	Oct 15, 2022	SYSTEM	(\$985.00)						
					15	Nov 2, 2022	SYSTEM	\$985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mitcha3 overridding Payment Estimate Exception 93 on the current Payment Estimate.					
					15	Nov 2, 2022	SYSTEM	(\$985.00)						
					16	Nov 16, 2022	SYSTEM	\$985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user mitcha3 overridding Payment Estimate Exception 106 on the current Payment Estimate.					
										16	Nov 16, 2022	SYSTEM	(\$985.00)	
						17	Dec 1, 2022	SYSTEM	\$985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user mitcha3 overridding Payment Estimate Exception 87 on the current Payment Estimate.				
					17	Dec 1, 2022	SYSTEM	(\$985.00)						
					18	Dec 16, 2022	SYSTEM	\$985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 105 on the current Payment Estimate.					
					18	Dec 16, 2022	SYSTEM	(\$985.00)						
				- Total		1		\$0.00						
			Material - Tota	ıl				\$0.00						
			Overrun	Overrun	15	Nov 2, 2022	SYSTEM	(\$5,319.00)						
					16	Nov 16, 2022	SYSTEM	\$1,477.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',98.50000 - 98.50000, 'is applied (if non-zero).					
				Overrun - T	otal			(\$3,841.50)						
			Overrun - Tota	al				(\$3,841.50)						
	1000 -	Total						(\$3,841.50)						
	1030	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		13	Oct 3, 2022	SYSTEM	\$15,768.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloep11 overridding Payment Estimate Exception 86 on the current Payment Estimate.					
					13	Oct 3, 2022	SYSTEM	(\$15,768.00)						
					14	Oct 15, 2022	SYSTEM	\$15,768.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user mitcha3 overridding Payment Estimate Exception 97 on the current Payment Estimate.					
					14	Oct 15, 2022	SYSTEM	(\$15,768.00)						
					15	Nov 2, 2022	SYSTEM	\$20,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user mitcha3 overridding Payment Estimate Exception 100 on the current Payment Estimate.					
					15	Nov 2, 2022	SYSTEM	(\$20,088.00)						



ct	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks					
51	LINC	Description	Туре	Adjustment Type	Number	Date	By	Amount	Nelliaiks					
19	1030	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		16	Nov 16, 2022	SYSTEM	\$21,708.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user mitcha3 overridding Payment Estimate Exception 113 on the current Payment Estimate.					
					16	Nov 16, 2022	SYSTEM	(\$21,708.00)						
					17	Dec 1, 2022	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user mitcha3 overridding Payment Estimate Exception 94 on the current Payment Estimate.					
					17	Dec 1, 2022	SYSTEM	(\$5,400.00)						
					18	Dec 16, 2022	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 112 on the current Payment Estimate.					
					18	Dec 16, 2022	SYSTEM	(\$5,400.00)						
				- Total				\$0.00						
			Material - Tota	ป				\$0.00						
	1030 -	Total						\$0.00						
	1130	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		12	Sep 16, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kloepj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
					12	Sep 16, 2022	SYSTEM	(\$51,900.00)						
					13	Oct 3, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloepj1 overridding Paymen Estimate Exception 14 on the current Payment Estimate.					
					13	Oct 3, 2022	SYSTEM	(\$51,900.00)						
					14	Oct 15, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user mitcha3 overridding Paymer Estimate Exception 14 on the current Payment Estimate.					
										14	Oct 15, 2022	SYSTEM	(\$51,900.00)	
						15	Nov 2, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user mitcha3 overridding Paymer Estimate Exception 14 on the current Payment Estimate.				
					15	Nov 2, 2022	SYSTEM	(\$51,900.00)						
					16	Nov 16, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user mitcha3 overridding Paymer Estimate Exception 13 on the current Payment Estimate.					
					16	Nov 16, 2022	SYSTEM	(\$51,900.00)						
					17	Dec 1, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user mitcha3 overridding Paymer Estimate Exception 10 on the current Payment Estimate.					
					17	Dec 1, 2022	SYSTEM	(\$51,900.00)						
								18	Dec 16, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user kloepj1 overridding Paymen Estimate Exception 11 on the current Payment Estimate.		
					18	Dec 16, 2022	SYSTEM	(\$51,900.00)						
				- Total				\$0.00						
			Material - Tota	1				\$0.00						
	1130 -							\$0.00						
	1140	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		6	Jun 16, 2022	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Paymen Estimate Exception 4 on the current Payment Estimate.					
					6	Jun 16, 2022	SYSTEM	(\$2,800.00)						
					7	Jul 1, 2022	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mitcha3 overridding Paymer Estimate Exception 5 on the current Payment Estimate.					
					7	Jul 1,	SYSTEM	(\$2,800.00)						
					'	2022		(, , , , , , , , , , , , , , , , , , ,						



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
49	1140	SUPPLEMENTARY WEARING	Material			2022			Estimate Item Adjustment (0010) due to user mitcha3 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
		SURFACE MATERIAL			8	Jul 18, 2022	SYSTEM	(\$2,800.00)					
					9	Aug 2, 2022	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
					9	Aug 2, 2022	SYSTEM	(\$2,800.00)					
					10	Aug 16, 2022	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mitcha3 overridding Payment Estimate Exception 13 on the current Payment Estimate.				
					10	Aug 16, 2022	SYSTEM	(\$2,800.00)					
				- Total				\$0.00					
			Material - Tota	al				\$0.00					
	1140 -	Total						\$0.00					
	1150	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		6	Jun 16, 2022	SYSTEM	\$90,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
		SOIN ACE			6	Jun 16, 2022	SYSTEM	(\$90,090.00)					
					7	Jul 1, 2022	SYSTEM	\$90,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mitcha3 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					7	Jul 1, 2022	SYSTEM	(\$90,090.00)					
					8	Jul 18, 2022	SYSTEM	\$90,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mitcha3 overridding Paymen Estimate Exception 19 on the current Payment Estimate.				
										8	Jul 18, 2022	SYSTEM	(\$90,090.00)
						9	Aug 2, 2022	SYSTEM	\$90,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					9	Aug 2, 2022	SYSTEM	(\$90,090.00)					
					10	Aug 16, 2022	SYSTEM	\$90,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mitcha3 overridding Paymen Estimate Exception 17 on the current Payment Estimate.				
					10	Aug 16, 2022	SYSTEM	(\$90,090.00)					
					17	Dec 1, 2022	SYSTEM	\$147,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user mitcha3 overridding Paymen Estimate Exception 48 on the current Payment Estimate.				
					17	Dec 1, 2022	SYSTEM	(\$147,290.00)					
					18	Dec 16, 2022	SYSTEM	\$147,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.				
					18	Dec 16, 2022	SYSTEM	(\$147,290.00)					
				- Total				\$0.00					
			Material - Tota	al				\$0.00					
	1150 -	Total						\$0.00					
	1170	PENETRATING CONCRETE	Material		14	Oct 15, 2022	SYSTEM	(\$615.00)					
		SEALER			15	Nov 2, 2022	SYSTEM	(\$615.00)					
					16	Nov 16, 2022	SYSTEM	(\$615.00)					
					17	Dec 1, 2022	SYSTEM	(\$615.00)					
					18	Dec 16, 2022	SYSTEM	(\$615.00)					
				- Total				(\$3,075.00)					



Dec 20, 2022

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
3149	1170	PENETRATING	Material - Tota	I				(\$3,075.00)												
		CONCRETE SEALER	MaterialCredit		15	Nov 2, 2022	SYSTEM	\$615.00												
					16	Nov 16, 2022	SYSTEM	\$615.00												
					17	Dec 1, 2022	SYSTEM	\$615.00												
					18	Dec 16, 2022	SYSTEM	\$615.00												
				- Total				\$2,460.00												
			MaterialCredit	- Total				\$2,460.00												
	1170 -							(\$615.00)												
	1180	CLASS B-2 CONCRETE	Material		12	Sep 16, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kloepj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.											
					12	Sep 16, 2022	SYSTEM	(\$7,650.00)												
					13	Oct 3, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.											
							13	Oct 3, 2022	SYSTEM	(\$7,650.00)										
									14	Oct 15, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user mitcha3 overridding Payment Estimate Exception 80 on the current Payment Estimate.							
					1	14	Oct 15, 2022	SYSTEM	(\$7,650.00)											
														15	Nov 2, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user mitcha3 overridding Payment Estimate Exception 83 on the current Payment Estimate.		
						16	Nov 16, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user mitcha3 overridding Payment Estimate Exception 96 on the current Payment Estimate.										
					16	Nov 16, 2022	SYSTEM	(\$7,650.00)												
					17	Dec 1, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user mitcha3 overridding Payment Estimate Exception 76 on the current Payment Estimate.											
					17	Dec 1, 2022	SYSTEM	(\$7,650.00)												
					18	Dec 16, 2022	SYSTEM	\$15,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 85 on the current Payment Estimate.											
					18	Dec 16, 2022	SYSTEM	(\$15,300.00)												
				- Total				\$0.00												
			Material - Tota	I				\$0.00												
	1180 -	Total						\$0.00												
	1220	HALF-SOLE REPAIR	Material		4	May 16, 2022	SYSTEM	\$7,948.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mitcha3 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
					4	May 16, 2022	SYSTEM	(\$7,948.95)												
					5	Jun 2, 2022	SYSTEM	\$7,978.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mitcha3 overridding Payment Estimate Exception 11 on the current Payment Estimate.											
					5	Jun 2, 2022	SYSTEM	(\$7,978.50)												
					6	Jun 16, 2022	SYSTEM	\$17,828.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.											
			6 Jun 16, SYSTEM 2022	(\$17,828.50)																
					7	Jul 1,	SYSTEM	\$17,828.50	This adjustment offsets the original system-generated Material Payment											



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3149	1220	HALF-SOLE REPAIR	Material			2022			Estimate Item Adjustment (0010) due to user mitcha3 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$17,828.50)	
					8	Jul 18, 2022	SYSTEM	\$17,828.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user mitcha3 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$17,828.50)	
					9	Aug 2, 2022	SYSTEM	\$17,828.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					9	Aug 2, 2022	SYSTEM	(\$17,828.50)	
					15	Nov 2, 2022	SYSTEM	\$17,828.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mitcha3 overridding Payment Estimate Exception 94 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$17,828.50)	
					16	Nov 16, 2022	SYSTEM	\$17,828.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user mitcha3 overridding Payment Estimate Exception 107 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$17,828.50)	
					17	Dec 1, 2022	SYSTEM	\$17,828.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user mitcha3 overridding Payment Estimate Exception 88 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$17,828.50)	
					18	Dec 16, 2022	SYSTEM	\$17,828.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user kloepj1 overridding Payment Estimate Exception 106 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$17,828.50)	
			Material Tate	- Total				\$0.00	
			Material - Tota Overrun	Overrun	15	Nov 2,	SYSTEM	\$0.00 (\$4,728.00)	
				Overrun - T	otal	2022		(\$4,728.00)	
								(\$4,120.00)	
			Overrun - Tota					(\$4,728.00)	
	1220 -							(\$4,728.00) (\$4,728.00)	
	<b>1220 -</b> 1230	Total FULL DEPTH REPAIR			6	Jun 16, 2022	SYSTEM	(\$4,728.00) (\$4,728.00) \$860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
		FULL DEPTH			6	2022 Jun 16, 2022	SYSTEM	(\$4,728.00) (\$4,728.00) \$860.00 (\$860.00)	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
		FULL DEPTH			6	2022 Jun 16,		(\$4,728.00) (\$4,728.00) \$860.00	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment
		FULL DEPTH			6	2022 Jun 16, 2022 Jul 1,	SYSTEM	(\$4,728.00) (\$4,728.00) \$860.00 (\$860.00)	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mitcha3 overridding Payment
		FULL DEPTH			6 6 7	2022 Jun 16, 2022 Jul 1, 2022 Jul 1,	SYSTEM SYSTEM	(\$4,728.00) (\$4,728.00) \$860.00 (\$860.00) \$860.00	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mitcha3 overridding Payment
		FULL DEPTH			6 6 7 7	2022 Jun 16, 2022 Jul 1, 2022 Jul 1, 2022 Jul 1, 2022 Jul 18,	SYSTEM SYSTEM SYSTEM	(\$4,728.00) (\$4,728.00) \$860.00 (\$860.00) \$860.00 (\$860.00)	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mitcha3 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment
		FULL DEPTH			6 6 7 7 8	2022 Jun 16, 2022 Jul 1, 2022 Jul 1, 2022 Jul 18, 2022 Jul 18,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,728.00) (\$4,728.00) \$860.00 (\$860.00) \$860.00 (\$860.00) \$860.00	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mitcha3 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment
		FULL DEPTH			6 6 7 7 8 8	2022 Jun 16, 2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,728.00) (\$4,728.00) \$860.00 (\$860.00) \$860.00 (\$860.00) \$860.00 (\$860.00)	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mitcha3 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 44 on the current Payment Estimate.
		FULL DEPTH			6 6 7 7 8 8 8 9	2022 Jun 16, 2022 Jul 1, 2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,728.00) (\$4,728.00) \$860.00 (\$860.00) \$860.00 (\$860.00) \$860.00 (\$860.00) \$860.00	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mitcha3 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 44 on the current Payment Estimate.
		FULL DEPTH			6 7 7 8 8 9 9	2022 Jun 16, 2022 Jul 1, 2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,728.00) (\$4,728.00) \$860.00 (\$860.00) \$860.00 (\$860.00) \$860.00 (\$860.00) \$860.00	Estimate Item Adjustment (0011) due to user kloepj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mitcha3 overridding Payment Estimate Exception 28 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.



t L	_ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
9 1:	230	FULL DEPTH REPAIR	Material			2022			Estimate Item Adjustment (0012) due to user mitcha3 overridding Payme Estimate Exception 60 on the current Payment Estimate.								
					11	Sep 1, 2022	SYSTEM	(\$860.00)									
					12	Sep 16, 2022	SYSTEM	\$860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kloepj1 overridding Paymen Estimate Exception 85 on the current Payment Estimate.								
					12	Sep 16, 2022	SYSTEM	(\$860.00)									
					13	Oct 3, 2022	SYSTEM	\$860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payme Estimate Exception 83 on the current Payment Estimate.								
					13	Oct 3, 2022	SYSTEM	(\$860.00)									
				- Total				\$0.00									
			Material - Tota	al				\$0.00									
1	230 -	Total						\$0.00									
1:	340	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		11	Sep 1, 2022	SYSTEM	\$27,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mitcha3 overridding Payme Estimate Exception 7 on the current Payment Estimate.								
					11	Sep 1, 2022	SYSTEM	(\$27,300.00)									
					12	Sep 16, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kloepj1 overridding Payme Estimate Exception 21 on the current Payment Estimate.								
								12	Sep 16, 2022	SYSTEM	(\$51,900.00)						
					13	Oct 3, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user kloep/1 overridding Payme Estimate Exception 21 on the current Payment Estimate.								
														13	Oct 3, 2022	SYSTEM	(\$51,900.00)
							14	Oct 15, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user mitcha3 overridding Payme Estimate Exception 21 on the current Payment Estimate.						
					14	Oct 15, 2022	SYSTEM	(\$51,900.00)									
					15	Nov 2, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user mitcha3 overridding Payme Estimate Exception 21 on the current Payment Estimate.								
					15	Nov 2, 2022	SYSTEM	(\$51,900.00)									
					16	Nov 16, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user mitcha3 overridding Payme Estimate Exception 20 on the current Payment Estimate.								
					16	Nov 16, 2022	SYSTEM	(\$51,900.00)									
									17	Dec 1, 2022	SYSTEM	\$51,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user mitcha3 overridding Payme Estimate Exception 15 on the current Payment Estimate.				
				1	17	Dec 1, 2022	SYSTEM	(\$51,900.00)									
					18 18	18	Dec 16, 2022	SYSTEM	\$84,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user kloep11 overridding Payme Estimate Exception 16 on the current Payment Estimate.							
						18	Dec 16, 2022	SYSTEM	(\$84,300.00)								
				- Total				\$0.00									
			Material - Tota	al				\$0.00									
1	340 -	Total						\$0.00									
1	350	SUPPLEMENTARY WEARING SURFACE	Material		8	Jul 18, 2022	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mitcha3 overridding Paym Estimate Exception 10 on the current Payment Estimate.								
		MATERIAL			8	Jul 18, 2022	SYSTEM	(\$6,300.00)									
					9	Aug 2, 2022	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kloepj1 overridding Payme								



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks			
1010440	1050			Туре								
J6I3149	1350	SUPPLEMENTARY WEARING	Material		9	Aug 2,	SYSTEM	(\$6,300.00)	Estimate Exception 4 on the current Payment Estimate.			
		SURFACE MATERIAL				2022	OTOTEM	(\$0,000.00)				
					10	Aug 16, 2022	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mitcha3 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
					10	Aug 16, 2022	SYSTEM	(\$6,300.00)				
					11	Sep 1, 2022	SYSTEM	\$6,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 20 on the current Payment Estimate.			
					11	Sep 1, 2022	SYSTEM	(\$6,300.00)				
				- Total				\$0.00				
			Material - Tota	d				\$0.00				
			Overrun	Overrun	16	Nov 16, 2022	SYSTEM	(\$700.00)				
				Overrun - Total				(\$700.00)				
			Overrun - Tota	run - Total								
	1350 -	Total						(\$700.00)				
	1360	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		8	Jul 18, 2022	SYSTEM	\$86,710.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user mitcha3 overridding Payment Estimate Exception 22 on the current Payment Estimate.			
								8	Jul 18, 2022	SYSTEM	(\$86,710.00)	
					9	Aug 2, 2022	SYSTEM	\$86,710.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
								9	Aug 2, 2022	SYSTEM	(\$86,710.00)	
					10	Aug 16, 2022	SYSTEM	\$86,710.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user mitcha3 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
					10	Aug 16, 2022	SYSTEM	(\$86,710.00)				
					11	Sep 1, 2022	SYSTEM	\$86,710.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user mitcha3 overridding Payment Estimate Exception 25 on the current Payment Estimate.			
					11	Sep 1, 2022	SYSTEM	(\$86,710.00)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	1360 -	Total						\$0.00				
	1380	PENETRATING CONCRETE SEALER	Material			2022	SYSTEM	(\$615.00)				
					15	Nov 2, 2022	SYSTEM	(\$615.00)				
					16	Nov 16, 2022	SYSTEM	(\$615.00)				
					17	Dec 1, 2022	SYSTEM	(\$615.00)				
					18	Dec 16, 2022	SYSTEM	(\$615.00)				
				- Total				(\$3,075.00)				
			Material - Tota	l I				(\$3,075.00)				
			MaterialCredit		15	Nov 2, 2022	SYSTEM	\$615.00				
					16	Nov 16, 2022	SYSTEM	\$615.00				
					17	Dec 1, 2022	SYSTEM	\$615.00				
					18	Dec 16, 2022	SYSTEM	\$615.00				
				- Total				\$2,460.00				



Dec 20, 2022

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
3149	1380	PENETRATING CONCRETE SEALER	MaterialCredit	- Total				\$2,460.00														
	1380 -	Total						(\$615.00)														
	1390	CLASS B-2 CONCRETE	Material		10	Aug 16, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 35 on the current Payment Estimate.													
					10	Aug 16, 2022	SYSTEM	(\$7,650.00)														
					11	Sep 1, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user mitcha3 overridding Payment Estimate Exception 52 on the current Payment Estimate.													
					11	Sep 1, 2022	SYSTEM	(\$7,650.00)														
					12	Sep 16, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kloepj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.													
						12	Sep 16, 2022	SYSTEM	(\$7,650.00)													
					13	Oct 3, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user kloepj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.													
						13	Oct 3, 2022	SYSTEM	(\$7,650.00)													
								14	Oct 15, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user mitcha3 overridding Payment Estimate Exception 83 on the current Payment Estimate.										
														14	Oct 15, 2022	SYSTEM	(\$7,650.00)					
														2022 Estimate Item Adjustment (0039) due to user m	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user mitcha3 overridding Payment Estimate Exception 85 on the current Payment Estimate.							
						15	Nov 2, 2022	SYSTEM	(\$7,650.00)													
					16	Nov 16, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user mitcha3 overridding Payment Estimate Exception 98 on the current Payment Estimate.													
																		16	Nov 16, 2022	SYSTEM	(\$7,650.00)	
					17	Dec 1, 2022	SYSTEM	\$7,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user mitcha3 overridding Payment Estimate Exception 77 on the current Payment Estimate.													
					17	Dec 1, 2022	SYSTEM	(\$7,650.00)														
					18	Dec 16, 2022	SYSTEM	\$15,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user kloepj1 overridding Payment Estimate Exception 86 on the current Payment Estimate.													
					18	Dec 16, 2022	SYSTEM	(\$15,300.00)														
				- Total				\$0.00														
			Material - Tota	ıl				\$0.00														
	1390 -	Total						\$0.00														
	1430	HALF-SOLE REPAIR	Material		4	May 16, 2022	SYSTEM	\$7,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mitcha3 overridding Payment Estimate Exception 7 on the current Payment Estimate.													
					4	4	May 16, 2022	SYSTEM	(\$7,880.00)													
				5	Jun 2, 2022	SYSTEM	\$16,843.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mitcha3 overridding Payment Estimate Exception 14 on the current Payment Estimate.														
					5	Jun 2, 2022	SYSTEM	(\$16,843.50)														
					6	Jun 16, 2022	SYSTEM	\$40,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.													
					6	Jun 16, 2022	SYSTEM	(\$40,385.00)														
					7	Jul 1,	SYSTEM	\$24,625.00	This adjustment offsets the original system-generated Material Payment													



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks												
			Туре	Adjustment Type	Number	Date	Ву														
J6I3149	1430	HALF-SOLE REPAIR	Material			2022			Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 25 on the current Payment Estimate.												
					7	Jul 1, 2022	SYSTEM	(\$24,625.00)													
					8	Jul 18, 2022	SYSTEM	\$24,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user mitcha3 overridding Payment Estimate Exception 41 on the current Payment Estimate.												
					8	Jul 18, 2022	SYSTEM	(\$24,625.00)													
					9	Aug 2, 2022	SYSTEM	\$24,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.												
					9	Aug 2, 2022	SYSTEM	(\$24,625.00)													
					10	Aug 16, 2022	SYSTEM	\$24,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 40 on the current Payment Estimate.												
					10	Aug 16, 2022	SYSTEM	(\$24,625.00)													
					11	Sep 1, 2022	SYSTEM	\$24,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mitcha3 overridding Payment Estimate Exception 58 on the current Payment Estimate.												
					11	Sep 1, 2022	SYSTEM	(\$24,625.00)	Estimate Exception 30 on the current Payment Estimate.												
					12	Sep 16, 2022	SYSTEM	\$24,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kloepj1 overridding Payment Estimate Exception 83 on the current Payment Estimate.												
					12	Sep 16, 2022	SYSTEM	(\$24,625.00)													
					13	Oct 3, 2022	SYSTEM	\$24,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user kloepj1 overridding Payment Estimate Exception 81 on the current Payment Estimate.												
							13	Oct 3, 2022	SYSTEM	(\$24,625.00)											
					14	Oct 15, 2022	SYSTEM	\$24,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user mitcha3 overridding Payment Estimate Exception 92 on the current Payment Estimate.												
									14	Oct 15, 2022	SYSTEM	(\$24,625.00)									
					15	Nov 2, 2022	SYSTEM	\$29,254.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mitcha3 overridding Payment Estimate Exception 95 on the current Payment Estimate.												
													15	Nov 2, 2022	SYSTEM	(\$29,254.50)					
						16	Nov 16, 2022	SYSTEM	\$28,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user mitcha3 overridding Payment Estimate Exception 108 on the current Payment Estimate.											
																16	Nov 16, 2022	SYSTEM	(\$28,565.00)		
							17	Dec 1, 2022	SYSTEM	\$28,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user mitcha3 overridding Payment Estimate Exception 89 on the current Payment Estimate.										
					17	Dec 1, 2022	SYSTEM	(\$28,565.00)													
																	18	Dec 16, 2022	SYSTEM	\$28,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user kloepj1 overridding Payment Estimate Exception 107 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$28,565.00)													
				- Total				\$0.00													
			Material - Tota	ıl				\$0.00													
			Other Item Adjustment	OVRN	6	Jun 16, 2022	kloepj1	(\$15,760.00)	Overrun Quantity will be paid for on an upcoming Change Order												
					7	Jul 1, 2022	SYSTEM	\$15,760.00	Overrun Quantity will be paid for on an upcoming Change Order												
				OVRN - Tota	al			\$0.00													
			Other Item Ad	justment - To	tal			\$0.00													



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks													
J6I3149	1430	HALF-SOLE REPAIR	Overrun	Type Overrun	6	Jun 16, 2022	SYSTEM	\$15,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 39 on the current Payment Estimate. Material Insufficiency Quantity 410.000; Overrun Quantity Balance 160.00.													
					6	Jun 16, 2022	SYSTEM	(\$15,760.00)														
					15	Nov 2, 2022	SYSTEM	(\$4,629.50)														
					16	Nov 16, 2022	SYSTEM	\$689.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',98.50000 - 98.50000, 'is applied (if non-zero).													
				Overrun - T	otal			(\$3,940.00)														
			Overrun - Tota	al				(\$3,940.00)														
	1430 -	Total						(\$3,940.00)														
	1440	FULL DEPTH REPAIR	Material		6	Jun 16, 2022	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kloepj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.													
					6	Jun 16, 2022	SYSTEM	(\$645.00)														
					7	Jul 1, 2022	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user mitcha3 overridding Payment Estimate Exception 30 on the current Payment Estimate.													
					7	Jul 1, 2022	SYSTEM	(\$645.00)														
					8	Jul 18, 2022	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mitcha3 overridding Payment Estimate Exception 45 on the current Payment Estimate.													
					8	Jul 18, 2022	SYSTEM	(\$645.00)														
					9	Aug 2, 2022	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kloepj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.													
					9	Aug 2, 2022	SYSTEM	(\$645.00)														
					10	Aug 16, 2022	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user mitcha3 overridding Payment Estimate Exception 44 on the current Payment Estimate.													
					10	Aug 16, 2022	SYSTEM	(\$645.00)														
					11	Sep 1, 2022	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user mitcha3 overridding Payment Estimate Exception 61 on the current Payment Estimate.													
					11	Sep 1, 2022	SYSTEM	(\$645.00)														
						12	Sep 16, 2022	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kloepj1 overridding Payment Estimate Exception 86 on the current Payment Estimate.												
					12	Sep 16, 2022	SYSTEM	(\$645.00)														
																		13	Oct 3, 2022	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user kloepj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.
					13	Oct 3, 2022	SYSTEM	(\$645.00)														
					14	Oct 15, 2022	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user mitcha3 overridding Payment Estimate Exception 95 on the current Payment Estimate.													
					14	Oct 15, 2022	SYSTEM	(\$645.00)														
					15	2022 Es	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user mitcha3 overridding Payment Estimate Exception 98 on the current Payment Estimate.															
					15	Nov 2, 2022	SYSTEM	(\$645.00)														
					16	Nov 16, 2022	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user mitcha3 overridding Payment Estimate Exception 111 on the current Payment Estimate.													
					16	Nov 16,	SYSTEM	(\$645.00)														



Interval	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
Image: Provide and the second secon				Туре	Adjustment Type	Number	Date	Ву			
Image: Provide a construct of the second s	J6I3149	1440		Material			2022				
<ul> <li> <ul> <li></li></ul></li></ul>			NEI AIX			17		SYSTEM	\$645.00	Estimate Item Adjustment (0040) due to user mitcha3 overridding Payment	
Image: Note of the second se						17		SYSTEM	(\$645.00)		
Image: Note of the second se						18		SYSTEM	\$645.00	Estimate Item Adjustment (0046) due to user kloepj1 overridding Payment	
Number         9000           1440 - Total         9000           1440 - Total         9000           1440 - Total         Number           1450 - Total         Number           1450 - Total         Number           1450 - Total         Number           1450 - Total         Numer						18		SYSTEM	(\$645.00)		
1440-Total         90.00         100         100           1840         H42-Total         National         1422         SYSTEM         \$151700.00         The adjustment offsets the oxigonal operandom denoming operandom denomi					- Total	1	1		\$0.00		
180         HARPENDE REPAR         Material         7         211 2022         SYSTEM         S15:700.00         The adjustment offsets the original system-generated Material Payment Estimate Exception 27 on the current Payment Estimate.           7         Jul 1, 2022         SYSTEM         63:5:700.00         The adjustment offsets the original system-generated Material Payment Estimate Exception 27 on the current Payment Estimate.           8         Jul 1, 8         SYSTEM         63:5:700.00         The adjustment offsets the original system-generated Material Payment Estimate Exception 42 on the current Payment Estimate Estimate Exception 42 on the current Payment Estimate Estimate Exception 42 on the current Payment Estimate Estimate Exception 43 on the current Payment Estimate Estimate Exception 44 on the current Payment Estimate Estimate Excep				Material - Tota	al -				\$0.00		
REPAR         REPAR         REPAR         Repare the second of t		1440 -	Total		_				\$0.00		
Image: Normal System         Image: No		1840		Material		7		SYSTEM	\$15,760.00	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment	
<ul> <li>Image: Part of the standage is a constrained of the standage is a constrained is a constrained in the standage is a constrained is a constrained in the standage is a constrained in the</li></ul>						7		SYSTEM	(\$15,760.00)		
1         2022         0         0.0.0.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 28 on the current Payment Estimate.           9         2022         SYSTEM         \$15,760.00         This adjustment offsets the original system-generated Material Payment Estimate.           9         2022         SYSTEM         \$15,760.00         This adjustment offsets the original system-generated Material Payment.           10         Aug 16.         SYSTEM         \$15,760.00         This adjustment offsets the original system-generated Material Payment.           10         Aug 16.         SYSTEM         \$15,760.00         This adjustment offsets the original system-generated Material Payment.           11         Sep 1.         SYSTEM         \$15,760.00         This adjustment offsets the original system-generated Material Payment.           11         Sep 1.         SYSTEM         \$15,760.00         This adjustment offsets the original system-generated Material Payment.           12         Sep 1.         SYSTEM         \$15,760.00         This adjustment offsets the original system-generated Material Payment.           12         Sep 1.6         SYSTEM         \$15,760.00         This adjustment offsets the original system-generated Material Payment.           12         Sep 1.6         SYSTEM         \$15,760.00         This adjustment offsets the original sys						8		SYSTEM	\$15,760.00	Estimate Item Adjustment (0018) due to user mitcha3 overridding Payment	
Image: Normal System         Image: System         System <td></td> <td></td> <td></td> <td></td> <td>8</td> <td></td> <td>SYSTEM</td> <td>(\$15,760.00)</td> <td></td>						8		SYSTEM	(\$15,760.00)		
Image: Normal Part of the second se						9		SYSTEM	\$15,760.00	Estimate Item Adjustment (0015) due to user kloepj1 overridding Payment	
Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment Estimate           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment Estimate           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment           Image: Selence item Adjustment (00%) due to user mitcha3 overridding Payment						9		SYSTEM	(\$15,760.00)		
<ul> <li>In adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user micha3 overridding Payment Estimate Item Adjustment (0019) due to user micha3 overridding Payment Estimate Item Adjustment (0019) due to user micha3 overridding Payment Estimate Item Adjustment (0019) due to user micha3 overridding Payment Estimate Exception 89 on the current Payment Estimate Exception 89 on the current Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Esception 84 on the current Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Esception 84 on the current Payment Estimate Item Adjustment (0035) due to user Kleepi 1 overridding Payment Estimate Esception 84 on the current Payment Estimate Item Adjustment (0035) due to user Kleepi 1 overridding Payment Estimate Item Adjustment (0035) due to user Kleepi 1 overridding Payment Estimate Item Adjustment (0035) due to user Kleepi 1 overridding Payment Estimate Item Adjustment (0035) due to user Kleepi 1 overridding Payment Estimate Exception 82 on the current Payment Estimate Item Adjustment (0035) due to user Kleepi 1 overridding Payment Estimate Item Adjustment (0035) due to user Kleepi 1 overridding Payment Estimate Item Adjustment (0035) due to user Kleepi 1 overridding Payment Estimate Item Adjustment (0041) due to user micha3 overridding Payment Estimate Item Adjustment (0041) due to user micha3 overridding Payment Estimate Item Adjustment (0041) due to user micha3 overridding Payment Estimate Item Adjustment (0041) due to user micha3 overridding Payment Estimate Item Adjustment (0041) due to user micha3 overridding Payment Estimate Item Adjustment (0041) due to user micha3 overridding Payment Estimate Item Adjustment (0041) due to user micha3 overridding Payment Estimate Item Adjustment (0041) due to user micha3 overridding Payment Estimate Item Adjustment (0041) due to user micha3 overridding Payment Estimate Item Adjustment (0</li></ul>						10		SYSTEM	\$15,760.00	Estimate Item Adjustment (0016) due to user mitcha3 overridding Payment	
Image: Serial set of the series set of the set of the series set of the set of the series set of the set of the ser							10		SYSTEM	(\$15,760.00)	
Image: state in the state i						11		SYSTEM	\$15,760.00	Estimate Item Adjustment (0019) due to user mitcha3 overridding Payment	
Image: second						11		SYSTEM	(\$15,760.00)		
Image: series of the series								12		SYSTEM	\$15,760.00
Image: Problem in the state						12		SYSTEM	(\$15,760.00)		
Image: Constraint of the section o						13		SYSTEM	\$15,760.00	Estimate Item Adjustment (0035) due to user kloepj1 overridding Payment	
Image:						13		SYSTEM	(\$15,760.00)		
1840 - Total       \$0.00         2380       BRIDGE APPROACH SLAB (MAJOR ROAD)       Material       15       Nov 2, 2022       SYSTEM       \$78,720.00       This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user mitcha3 overridding Payment         15       Nov 2, 2022       SYSTEM       \$78,720.00       This adjustment offsets the original system-generated Material Payment         16       Nov 16, 2022       SYSTEM       \$78,720.00       This adjustment offsets the original system-generated Material Payment         16       Nov 16, 2022       SYSTEM       \$78,720.00       This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user mitcha3 overridding Payment         16       Nov 16, 2022       SYSTEM       \$78,720.00       This adjustment offsets the original system-generated Material Payment         17       Dec 1, 2022       SYSTEM       \$78,720.00       This adjustment (0041) due to user mitcha3 overridding Payment         17       Dec 1, 2022       SYSTEM       \$78,720.00       This adjustment (0041) due to user mitcha3 overridding Payment         17       Dec 1, 2022       SYSTEM       \$78,720.00       This adjustment (0041) due to user mitcha3 overridding Payment         17       Dec 1, 2022       SYSTEM       \$78,720.00       This adjustment offsets the original system-generated					- Total				\$0.00		
2380         BRIDGE APPROACH SLAB (MAJOR ROAD)         Material         15         Nov 2, 2022         SYSTEM         \$78,720.00         This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user mitcha3 overridding Payment           15         Nov 2, 2022         SYSTEM         \$78,720.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 28 on the current Payment Estimate.           16         Nov 16, 2022         SYSTEM         \$78,720.00         This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user mitcha3 overridding Payment Estimate Exception 27 on the current Payment Estimate.           16         Nov 16, 2022         SYSTEM         \$78,720.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 27 on the current Payment Estimate.           17         Dec 1, 2022         SYSTEM         \$78,720.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate.				Material - Tota	ıl				\$0.00		
APPROACH SLAB (MAJOR ROAD)       2022       2022       SYSTEM       Estimate Item Adjustment (0041) due to user mitcha3 overridding Payment Estimate Exception 28 on the current Payment Estimate.         15       Nov 2, 2022       SYSTEM       (\$78,720.00)         16       Nov 16, 2022       SYSTEM       \$78,720.00         17       Dec 1, 2022       SYSTEM       \$78,720.00		1840 -	Total						\$0.00		
16     Nov 16, 2022     SYSTEM     \$78,720.00     This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user mitcha3 overridding Payment       16     Nov 16, 2022     SYSTEM     \$78,720.00     This adjustment offsets the original system-generated Material Payment Estimate Exception 27 on the current Payment Estimate.       16     Nov 16, 2022     SYSTEM     \$78,720.00       17     Dec 1, 2022     SYSTEM     \$78,720.00       17     Dec 1, 2022     SYSTEM     \$78,720.00		2380	APPROACH SLAB	Material		15		SYSTEM	\$78,720.00	Estimate Item Adjustment (0041) due to user mitcha3 overridding Payment	
2022       2022       Estimate Item Adjustment (0037) due to user mitcha3 overridding Payment Estimate Exception 27 on the current Payment Estimate.         16       Nov 16, 2022       SYSTEM       (\$78,720.00)         17       Dec 1, 2022       SYSTEM       \$78,720.00         17       Dec 1, 2022       SYSTEM       (\$78,720.00)         17       Dec 1, SYSTEM       \$78,720.00       This adjustment (0041) due to user mitcha3 overridding Payment Estimate.         17       Dec 1, SYSTEM       \$78,720.00       This adjustment (0041) due to user mitcha3 overridding Payment Estimate.						15		SYSTEM	(\$78,720.00)		
2022     2022     2022       17     Dec 1, 2022     SYSTEM     \$78,720.00     This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user mitcha3 overridding Payment       17     Dec 1,     SYSTEM     \$78,720.00     This adjustment offsets the original system-generated Material Payment       17     Dec 1,     SYSTEM     \$78,720.00     This adjustment (0041) due to user mitcha3 overridding Payment						16		SYSTEM	\$78,720.00	Estimate Item Adjustment (0037) due to user mitcha3 overridding Payment	
17       Dec 1, 2022       SYSTEM       \$78,720.00       This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user mitcha3 overridding Payment         17       Dec 1,       SYSTEM       (\$78,720.00)						16		SYSTEM	(\$78,720.00)		
17 Dec 1, SYSTEM (\$78,720.00)						17	Dec 1,	SYSTEM	\$78,720.00	Estimate Item Adjustment (0041) due to user mitcha3 overridding Payment	
						17	Dec 1, 2022	SYSTEM	(\$78,720.00)		



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
9 2	2380	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		18	Dec 16, 2022	SYSTEM	\$78,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user kloepj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
		· · · · ·			18	Dec 16, 2022	SYSTEM	(\$78,720.00)											
				- Total				\$0.00											
			Material - Tota	ıl				\$0.00											
2	2380 -	Total						\$0.00											
2	2390	SUPPLEMENTARY WEARING SURFACE	Material		11	Sep 1, 2022	SYSTEM	\$24,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user mitcha3 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
		MATERIAL			11	Sep 1, 2022	SYSTEM	(\$24,500.00)											
					12	Sep 16, 2022	SYSTEM	\$24,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.										
					12	Sep 16, 2022	SYSTEM	(\$24,500.00)											
						13	Oct 3, 2022	SYSTEM	\$24,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user kloepj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.									
						13	Oct 3, 2022	SYSTEM	(\$24,500.00)										
					14	Oct 15, 2022	SYSTEM	\$24,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user mitcha3 overridding Payment Estimate Exception 34 on the current Payment Estimate.										
							14	Oct 15, 2022	SYSTEM	(\$24,500.00)									
													15	Nov 2, 2022	SYSTEM	\$24,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user mitcha3 overridding Payment Estimate Exception 43 on the current Payment Estimate.		
											15	Nov 2, 2022	SYSTEM	(\$24,500.00)					
								16	Nov 16, 2022	SYSTEM	\$24,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user mitcha3 overridding Payment Estimate Exception 52 on the current Payment Estimate.							
									16	Nov 16, 2022	SYSTEM	(\$24,500.00)							
					17	Dec 1, 2022	SYSTEM	\$24,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user mitcha3 overridding Payment Estimate Exception 40 on the current Payment Estimate.										
					17	Dec 1, 2022	SYSTEM	(\$24,500.00)											
				1	18	Dec 16, 2022	SYSTEM	\$24,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user kloepj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.										
					18	Dec 16, 2022	SYSTEM	(\$24,500.00)											
				- Total				\$0.00											
			Material - Tota	ıl				\$0.00											
2	2390 -	Total						\$0.00											
2	2400	LATEX MODIFIED CONCRETE WEARING	Material		11	Sep 1, 2022	SYSTEM	\$160,513.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user mitcha3 overridding Payment Estimate Exception 26 on the current Payment Estimate.										
		SURFACE													11	Sep 1, 2022	SYSTEM	(\$160,513.00)	
			1									12	Sep 16, 2022	SYSTEM	\$160,513.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.			
					12	Sep 16, 2022	SYSTEM	(\$160,513.00)											
					13	Oct 3, 2022	SYSTEM	\$160,513.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user kloepj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.										
					13	Oct 3, 2022	SYSTEM	(\$160,513.00)											
						14	Oct 15,	SYSTEM	\$160,513.00	This adjustment offsets the original system-generated Material Payment									



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
3149	2400	LATEX MODIFIED CONCRETE	Material			2022			Estimate Item Adjustment (0033) due to user mitcha3 overridding Payment Estimate Exception 41 on the current Payment Estimate.		
		WEARING SURFACE			14	Oct 15, 2022	SYSTEM	(\$160,513.00)			
					15	Nov 2, 2022	SYSTEM	\$160,513.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user mitcha3 overridding Payment Estimate Exception 50 on the current Payment Estimate.		
					15	Nov 2, 2022	SYSTEM	(\$160,513.00)			
					16	Nov 16, 2022	SYSTEM	\$160,513.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user mitcha3 overridding Payment Estimate Exception 59 on the current Payment Estimate.		
					16	Nov 16, 2022	SYSTEM	(\$160,513.00)			
					17	Dec 1, 2022	SYSTEM	\$160,513.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user mitcha3 overridding Payment Estimate Exception 49 on the current Payment Estimate.		
					17	Dec 1, 2022	SYSTEM	(\$160,513.00)			
					18	Dec 16, 2022	SYSTEM	\$160,513.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user kloepj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.		
					18	Dec 16, 2022	SYSTEM	(\$160,513.00)			
				- Total				\$0.00			
			Material - Tota	ıl				\$0.00			
	2400 -	Total						\$0.00			
	2420	PENETRATING CONCRETE SEALER	Material		18	Dec 16, 2022	SYSTEM	(\$655.00)			
				- Total				(\$655.00)			
	2420	Total	Material - Tota	11				(\$655.00)			
	2420 -		Matarial		13	Oct 2	SYSTEM	(\$655.00)	This adjustment effects the original system generated Material Devment		
	2430	CLASS B-2 CONCRETE	Material			Oct 3, 2022		\$6,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user kloepj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.		
							13	Oct 3, 2022	SYSTEM	(\$6,750.00)	
					14	Oct 15, 2022	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user mitcha3 overridding Payment Estimate Exception 86 on the current Payment Estimate.		
					14	Oct 15, 2022	SYSTEM	(\$13,500.00)			
					15	Nov 2, 2022	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user mitcha3 overridding Payment Estimate Exception 87 on the current Payment Estimate.		
					15	Nov 2, 2022	SYSTEM	(\$13,500.00)			
				1	16	Nov 16, 2022	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user mitcha3 overridding Payment Estimate Exception 100 on the current Payment Estimate.		
					16	Nov 16, 2022	SYSTEM	(\$13,500.00)			
					17	Dec 1, 2022	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user mitcha3 overridding Payment Estimate Exception 78 on the current Payment Estimate.		
					17	Dec 1, 2022	SYSTEM	(\$13,500.00)			
					18	Dec 16, 2022	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user kloep11 overridding Payment Estimate Exception 87 on the current Payment Estimate.		
					18	Dec 16, 2022	SYSTEM	(\$13,500.00)			
				- Total				\$0.00			
			Material - Tota	ıl				\$0.00			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1613149	2440	TYPE B BARRIER	Material	1360	18	Dec 16, 2022	SYSTEM	\$946.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user kloepj1 overridding Payment Estimate Exception 89 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$946.00)	Estimate Exception of on the current Payment Estimate.
				- Total		2022		\$0.00	
			Material - Tota					\$0.00	
	2440 -	Total						\$0.00	
	2500	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		10	Aug 16, 2022	SYSTEM	\$42,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					10	Aug 16, 2022	SYSTEM	(\$42,120.00)	
					11	Sep 1, 2022	SYSTEM	\$42,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user mitcha3 overridding Payment Estimate Exception 64 on the current Payment Estimate.
					11	Sep 1, 2022	SYSTEM	(\$42,120.00)	
					12	Sep 16, 2022	SYSTEM	\$42,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user kloep/1 overridding Payment Estimate Exception 89 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$42,120.00)	
					13	Oct 3, 2022	SYSTEM	\$42,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user kloepj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.
					13	Oct 3, 2022	SYSTEM	(\$42,120.00)	
					14	Oct 15, 2022	SYSTEM	\$42,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user mitcha3 overridding Payment Estimate Exception 99 on the current Payment Estimate.
					14	Oct 15, 2022	SYSTEM	(\$42,120.00)	
					15	Nov 2, 2022	SYSTEM	\$42,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user mitcha3 overridding Payment Estimate Exception 102 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$42,120.00)	
					16	Nov 16, 2022	SYSTEM	\$42,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user mitcha3 overridding Payment Estimate Exception 115 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$42,120.00)	
					17	Dec 1, 2022	SYSTEM	\$42,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user mitcha3 overridding Payment Estimate Exception 96 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$42,120.00)	
					18	Dec 16, 2022	SYSTEM	\$42,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user kloepj1 overridding Payment Estimate Exception 114 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$42,120.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	2500 -		Madagiat		10	D., 10	OVOTEN	\$0.00	This adhedres at affects the addition of the second second
	2520	MISC.	Material		18	Dec 16, 2022	SYSTEM	\$737.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user kloepj1 overridding Payment Estimate Exception 116 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$737.50)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	2520 -		Meteric		16	Nev: 40	OVOTEN	\$0.00	This adjustment offers the evision evidence of the trade D
	2770	BRIDGE APPROACH SLAB	Material		16	Nov 16, 2022	SYSTEM	\$47,737.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user mitcha3 overridding Payment



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
49	2770	(MAJOR ROAD)	Material						Estimate Exception 34 on the current Payment Estimate.												
					16	Nov 16, 2022	SYSTEM	(\$47,737.50)													
					17	Dec 1, 2022	SYSTEM	\$95,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user mitcha3 overridding Paymen Estimate Exception 25 on the current Payment Estimate.												
					17	Dec 1, 2022	SYSTEM	(\$95,475.00)													
					18	Dec 16, 2022	SYSTEM	\$95,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user kloepj1 overridding Paymen Estimate Exception 26 on the current Payment Estimate.												
					18	Dec 16, 2022	SYSTEM	(\$95,475.00)													
				- Total				\$0.00													
			Material - Tota	al				\$0.00													
	2770 -	Total						\$0.00													
	2780	SLAB ON STEEL	Material		10	Aug 16, 2022	SYSTEM	\$91,056.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user mitcha3 overridding Paymen Estimate Exception 28 on the current Payment Estimate.												
					10	Aug 16, 2022	SYSTEM	(\$91,056.25)													
					11	Sep 1, 2022	SYSTEM	\$91,069.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user mitcha3 overridding Payment Estimate Exception 45 on the current Payment Estimate.												
					11	Sep 1, 2022	SYSTEM	(\$91,069.00)													
															12	Sep 16, 2022	SYSTEM	\$236,652.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user kloepj1 overridding Paymen Estimate Exception 65 on the current Payment Estimate.		
										13	Oct 3, 2022	SYSTEM	\$364,237.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user kloepj1 overridding Paymen Estimate Exception 60 on the current Payment Estimate.							
					13	Oct 3, 2022	SYSTEM	(\$364,237.75)													
					14	Oct 15, 2022	SYSTEM	\$819,506.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user mitcha3 overridding Payme Estimate Exception 71 on the current Payment Estimate.												
					14	Oct 15, 2022	SYSTEM	(\$819,506.25)													
					15	Nov 2, 2022	SYSTEM	\$1,365,843.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user mitcha3 overridding Payme Estimate Exception 76 on the current Payment Estimate.												
					15	Nov 2, 2022	SYSTEM	(\$1,365,843.75)													
					16	Nov 16, 2022	SYSTEM	\$1,639,012.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user mitcha3 overridding Paymen Estimate Exception 90 on the current Payment Estimate.												
							16	Nov 16, 2022	SYSTEM	(\$1,639,012.50)											
					1	17	Dec 1, 2022	SYSTEM	\$1,639,012.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user mitcha3 overridding Payme Estimate Exception 72 on the current Payment Estimate.											
					17	Dec 1, 2022	SYSTEM	(\$1,639,012.50)													
					18	Dec 16, 2022	SYSTEM	\$1,821,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user kloepj1 overridding Paymen Estimate Exception 80 on the current Payment Estimate.												
					18	Dec 16, 2022	SYSTEM	(\$1,821,125.00)													
				- Total				\$0.00													
			Material - Tota	al				\$0.00													
	2780 -							\$0.00													
	2790	TYPE D BARRIER	Material		18	Dec 16, 2022	SYSTEM	\$144,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user kloepj1 overridding Paymen Estimate Exception 99 on the current Payment Estimate.												



Dec 20, 2022

Partial of the control of the contr						_																									
33134     7     7     0	Project	Line	Description	Adjustment Type		Est. Number	Created Date	Created By	Amount	Remarks																					
Valuent - 1 Color         Valuent - 1 Color         Valuent - 1 Color           723         COLORINGETE COLORINGUENER Network         Marriel Coloring - 1 Coloring Coloring - 1 Coloring - 1 Coloring - 1 Coloring Coloring - 1 Coloring - 1 Coloring - 1 Coloring - 1 Coloring Coloring - 1 Coloring - 1 Coloring - 1 Coloring - 1 Coloring - 1 Coloring Coloring - 1 Coloring - 1 Colo	J6I3149	2790	TYPE D BARRIER	Material		18		SYSTEM	(\$144,900.00)																						
Value         Value         Value         Value         Value           200         Editation 1 Characterization 1 Characterizat					- Total				\$0.00																						
2010         Construction         Internal processing datasets Psymeth           2010         Experimental internal processing datasets Psymeth         17         Dec.1         572144         1510,000.00         Employment Experimental Material Psymeth           2010         Experimental internal psymeth         17         Dec.1         572144         1510,000.00         The adjustment officies the argunal system generated Material Psymeth           2010         Dec.1         572144         1510,000.00         The adjustment officies the argunal system generated Material Psymeth           2010         Dec.1         572144         1510,000.00         The adjustment officies the argunal system generated Material Psymeth           2010         Total         Total         Total         Total         10         State           2011         SubSTRUCTURE         Material Total         11         State         11         State           2011         SubSTRUCTURE         Material Total         11         State         11         State         11         State           2011         State         11				Material - Tota	l																										
200         MSC CONCRETE         Makeid         17         De 1,         SYSTEM         \$150,000         The digitament offects in enginal system-generated Material Payment           200         MSC CONCRETE         No         1         SySTEM         \$150,000         The adjutament offects in enginal system-generated Material Payment           200         Total         Doc 1,         SYSTEM         \$200,000         The adjutament offects in enginal system-generated Material Payment           200         Total         Doc 1,         SYSTEM         \$200,000         The adjutament offects in enginal system-generated Material Payment           200         Total         Doc 1,         SYSTEM         \$200,000         The adjutament offects in enginal system-generated Material Payment           200         Total         Doc 1,         SYSTEM         \$200,000         The adjutament offects in enginal system-generated Material Payment           200         Total         SySTEM         \$11         SysT.1         \$77450         The adjutament offects in enginal system-generated Material Payment           201         SySTEM         \$90,1         \$7350         \$73500         The adjutament offects in enginal system-generated Material Payment           202         SySTEM         \$90,1         \$73500         \$735000         The adjutament offects in enginal system-g		2790 -	Total																												
Product         1 </td <td></td> <td>2800</td> <td></td> <td>Material</td> <td></td> <td>17</td> <td></td> <td>SYSTEM</td> <td>\$150,000.00</td> <td>Estimate Item Adjustment (0048) due to user mitcha3 overridding Payment</td>		2800		Material		17		SYSTEM	\$150,000.00	Estimate Item Adjustment (0048) due to user mitcha3 overridding Payment																					
Part Part Part Part Part Part Part Part						17		SYSTEM	(\$150,000.00)																						
Image: state interval in the state interval interva						18		SYSTEM	\$230,000.00	Estimate Item Adjustment (0058) due to user kloepj1 overridding Payment																					
Vietnesis         Vietnesis         Vietnesis           2010         Total         0.00         0.00         0.00           2810         SUBSTRUCTURE         Malerial         Seg.1, REPARE (GORMED)         SVSTEM         (227.405.00)         0           1         Seg.1, REPARE (GORMED)         SvSTEM         (227.405.00)         0         0           1         Seg.1, REPARE         SvSTEM         (227.405.00)         0         0         0           1         Seg.1, REPARE         SvSTEM         (SS.591.00)         0         0         0         0         0           1         Seg.1, REPARE         SvSTEM         (SS.591.00)         0						18		SYSTEM	(\$230,000.00)																						
2000 - Total         Unitarial         Unitarial         Numerical         Second					- Total				\$0.00																						
2810         SUBSTRUMER         Material         11         Sep 1.         SYSTEM         527,405.00         This ruligitanet disets the original system-appendent distributions (in no distribution) (in dois user inclusion).           11         Sep 1.         SYSTEM         (527,405.00)         Internalised internal distribution (inclusion).         Internalised i				Material - Tota	ıl				\$0.00																						
REPAR         REPAR         Reparation		2800 -	Total						\$0.00																						
$ \left  \begin{array}{c c c c c } & 2022 & 2$		2810	REPAIR	Material		11		SYSTEM	\$27,405.00	Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment																					
Image: Provide the image: Pr									11		SYSTEM	(\$27,405.00)																			
$ \left  \begin{array}{c c c c c c c } \hline \\ \hline $																											12		SYSTEM	\$35,910.00	Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment
																						12		SYSTEM	(\$35,910.00)						
For even table is a constrained of the table is a constrained of table is a constrained i																												13		SYSTEM	\$60,858.00
Image: Figure																									13		SYSTEM	(\$60,858.00)			
Image: Second											14		SYSTEM	\$60,858.00	Estimate Item Adjustment (0037) due to user mitcha3 overridding Payment																
Image: Second						14		SYSTEM	(\$60,858.00)																						
<ul> <li></li></ul>						15		SYSTEM	\$60,858.00	Estimate Item Adjustment (0011) due to user mitcha3 overridding Payment																					
Image: Figure						15		SYSTEM	(\$60,858.00)																						
$ \left  \begin{array}{c c c c c c c c c c c c c c c c c c c $						16		SYSTEM	\$63,126.00	Estimate Item Adjustment (0045) due to user mitcha3 overridding Payment																					
Image: Construct of the construction of the						16		SYSTEM	(\$63,126.00)																						
$ \begin{array}{ c c c c } \hline \begin{tabular}{ c c c } \hline \end{tabular} & \hline \en$																			17		SYSTEM	\$63,693.00	Estimate Item Adjustment (0050) due to user mitcha3 overridding Payment								
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $						17		SYSTEM	(\$63,693.00)																						
Image: Control of the contro													1	18		SYSTEM	\$63,693.00	Estimate Item Adjustment (0059) due to user kloepj1 overridding Payment													
Material - Total         \$0.00           Overrun         Overrun         11         Sep 1, 2022         SYSTEM         (\$15,120.00)           12         Sep 16, 2022         SYSTEM         (\$8,505.00)         (\$10,10,10,10,10,10,10,10,10,10,10,10,10,1						18		SYSTEM	(\$63,693.00)																						
Overrun         Overrun         11         Sep 1, 2022         SYSTEM         (\$15,120.00)           12         Sep 16, 2022         SYSTEM         (\$8,505.00)           13         Oct 3, SYSTEM         (\$24,948.00)					- Total				\$0.00																						
2022     2022     2022       12     Sep 16, 2022     SYSTEM     (\$8,505.00)       13     Oct 3,     SYSTEM     (\$24,948.00)				Material - Tota	ıl				\$0.00																						
2022         13         Oct 3,         SYSTEM         (\$24,948.00)				Overrun	Overrun	11		SYSTEM	(\$15,120.00)																						
						12		SYSTEM	(\$8,505.00)																						
						13		SYSTEM	(\$24,948.00)																						



	Line	Description	Adjustment	Other Adjustment	Est. Number	Created Date	Created	Amount	Remarks
			Туре	Туре			Ву		
J6I3149	2810	SUBSTRUCTURE REPAIR (FORMED)	Overrun	Overrun	15	Nov 2, 2022	SYSTEM	\$48,573.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',189.00000 - 189.00000, 'is applied (if non-zero).
					16	Nov 16, 2022	SYSTEM	(\$2,268.00)	
					17	Dec 1, 2022	SYSTEM	(\$567.00)	
				Overrun - T	otal			(\$2,835.00)	
			Overrun - Tot	al				(\$2,835.00)	
	2810 -	Total						(\$2,835.00)	
	2830	CONDUIT SYSTEM ON STRUCTURE	Material		15	Nov 2, 2022	SYSTEM	\$2,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment Estimate Exception 122 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$2,256.00)	
					16	Nov 16, 2022	SYSTEM	\$2,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user mitcha3 overridding Payment Estimate Exception 135 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$2,256.00)	
					17	Dec 1, 2022	SYSTEM	\$22,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user mitcha3 overridding Payment Estimate Exception 116 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$22,560.00)	
					18	Dec 16, 2022	SYSTEM	\$22,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user kloepj1 overridding Payment Estimate Exception 135 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$22,560.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	2830 -	Total						\$0.00	
	2860	DRAINAGE SYSTEM (ON STRUCTURE)	Material		15	Nov 2, 2022	SYSTEM	\$13,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user mitcha3 overridding Payment Estimate Exception 124 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$13,200.00)	
						2022			
					16	Nov 16, 2022	SYSTEM	\$32,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment Estimate Exception 137 on the current Payment Estimate.
					16 16	Nov 16,	SYSTEM SYSTEM	\$32,000.00	Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment
						Nov 16, 2022 Nov 16,			Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment
					16	Nov 16, 2022 Nov 16, 2022 Dec 1,	SYSTEM	(\$32,000.00)	Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment Estimate Exception 137 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user mitcha3 overridding Payment
					16 17	Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1,	SYSTEM SYSTEM	(\$32,000.00) \$32,000.00	Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment Estimate Exception 137 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user mitcha3 overridding Payment
					16 17 17	Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16,	SYSTEM SYSTEM SYSTEM	(\$32,000.00) \$32,000.00 (\$32,000.00)	Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment Estimate Exception 137 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user mitcha3 overridding Payment Estimate Exception 118 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment
				- Total	16 17 17 18	Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$32,000.00) \$32,000.00 (\$32,000.00) \$32,000.00	Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment Estimate Exception 137 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user mitcha3 overridding Payment Estimate Exception 118 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment
			Material - Tota		16 17 17 18	Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$32,000.00) \$32,000.00 (\$32,000.00) \$32,000.00 (\$32,000.00)	Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment Estimate Exception 137 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user mitcha3 overridding Payment Estimate Exception 118 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment
	2860 -	Total	Material - Tota		16 17 17 18	Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$32,000.00) \$32,000.00 (\$32,000.00) \$32,000.00 (\$32,000.00) \$0.00	Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment Estimate Exception 137 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user mitcha3 overridding Payment Estimate Exception 118 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment
	<b>2860</b> - 2920	LAMINATED NEOPRENE BEARING PAD	Material - Tota Material		16 17 17 18	Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$32,000.00) \$32,000.00 (\$32,000.00) \$32,000.00 (\$32,000.00) (\$32,000.00) \$0.00	Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment Estimate Exception 137 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user mitcha3 overridding Payment Estimate Exception 118 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment
		LAMINATED NEOPRENE			16 17 17 18 18	Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16, 2022 Dec 16, 2022 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$32,000.00) \$32,000.00 (\$32,000.00) \$32,000.00 (\$32,000.00) (\$32,000.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment Estimate Exception 137 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user mitcha3 overridding Payment Estimate Exception 118 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 137 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 137 on the current Payment Estimate.
		LAMINATED NEOPRENE BEARING PAD			16 17 17 18 18 18	Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16, 2022 Dec 16, 2022 Dec 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$32,000.00) \$32,000.00 (\$32,000.00) \$32,000.00 (\$32,000.00) \$0.00 \$33,950.00	Estimate Item Adjustment (0047) due to user mitcha3 overridding Payment Estimate Exception 137 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user mitcha3 overridding Payment Estimate Exception 118 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user kloepj1 overridding Payment Estimate Exception 137 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 137 on the current Payment Estimate.



Dec 20, 2022

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks		
	LING	Description	Туре	Adjustment Type	Number	Date	Ву	Amount	romano		
J6I3149	2920	LAMINATED NEOPRENE BEARING PAD	Material		12	Sep 16, 2022	SYSTEM	\$77,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user kloepj1 overridding Payment Estimate Exception 91 on the current Payment Estimate.		
		ASSEMBLY			12	Sep 16, 2022	SYSTEM	(\$77,600.00)			
				- Total				\$0.00			
			Material - Tota	1				\$0.00			
	2920 -	- Total						\$0.00			
	3100	LAMINATED NEOPRENE	Construction Stockpile		17	Dec 1, 2022	SYSTEM	\$41,580.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
		BEARING PAD ASSEMBLY	STMI	- Total	1			\$41,580.00			
			Construction	Stockpile STI	MI - Total			\$41,580.00			
	3100 -	- Total						\$41,580.00			
	3160	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		16	Nov 16, 2022	SYSTEM	\$78,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user mitcha3 overridding Payment Estimate Exception 41 on the current Payment Estimate.		
					16	Nov 16, 2022	SYSTEM	(\$78,720.00)			
					17	Dec 1, 2022	SYSTEM	\$78,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user mitcha3 overridding Payment Estimate Exception 31 on the current Payment Estimate.		
						17	Dec 1, 2022	SYSTEM	(\$78,720.00)		
										18	Dec 16, 2022
					18	Dec 16, 2022	SYSTEM	(\$78,720.00)			
				- Total				\$0.00			
			Material - Tota	1				\$0.00			
	3160 ·	- Total						\$0.00			
	3170	SUPPLEMENTARY WEARING SURFACE	Material		14	Oct 15, 2022	SYSTEM	\$25,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mitcha3 overridding Payment Estimate Exception 37 on the current Payment Estimate.		
		MATERIAL			14	Oct 15, 2022	SYSTEM	(\$25,200.00)			
							LOLL				
					15	Nov 2, 2022	SYSTEM	\$25,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate.		
					15 15	Nov 2,	SYSTEM SYSTEM	\$25,200.00 (\$25,200.00)	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment		
						Nov 2, 2022 Nov 2,			Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment		
					15	Nov 2, 2022 Nov 2, 2022 Nov 16,	SYSTEM	(\$25,200.00)	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user mitcha3 overridding Payment		
					15 16	Nov 2, 2022 Nov 2, 2022 Nov 16, 2022 Nov 16,	SYSTEM SYSTEM	(\$25,200.00) \$25,200.00	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user mitcha3 overridding Payment		
					15 16 16	Nov 2, 2022 Nov 2, 2022 Nov 16, 2022 Nov 16, 2022 Dec 1,	SYSTEM SYSTEM SYSTEM	(\$25,200.00) \$25,200.00 (\$25,200.00)	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user mitcha3 overridding Payment		
					15 16 16 17	Nov 2, 2022 Nov 2, 2022 Nov 16, 2022 Nov 16, 2022 Dec 1, Dec 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$25,200.00) \$25,200.00 (\$25,200.00) \$25,200.00	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user mitcha3 overridding Payment		
					15 16 16 17 17	Nov 2,           2022           Nov 2,           2022           Nov 16,           2022           Dec 1,           2022           Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$25,200.00) \$25,200.00 (\$25,200.00) \$25,200.00 (\$25,200.00)	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user mitcha3 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 43 on the current Payment Estimate.		
				- Total	15 16 16 17 17 18	Nov 2, 2022 Nov 2, 2022 Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$25,200.00) \$25,200.00) (\$25,200.00) \$25,200.00 (\$25,200.00) \$25,200.00	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user mitcha3 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 43 on the current Payment Estimate.		
			Material - Tota		15 16 16 17 17 18	Nov 2, 2022 Nov 2, 2022 Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$25,200.00) \$25,200.00) (\$25,200.00) \$25,200.00) (\$25,200.00) \$25,200.00 (\$25,200.00)	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user mitcha3 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 43 on the current Payment Estimate.		
			Material - Tota Overrun		15 16 16 17 17 18	Nov 2, 2022 Nov 2, 2022 Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$25,200.00) \$25,200.00) (\$25,200.00) \$25,200.00) (\$25,200.00) \$25,200.00 (\$25,200.00) \$0.00	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user mitcha3 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 43 on the current Payment Estimate.		
				l	15 16 17 17 18 18	Nov 2, 2022 Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16, 2022 Dec 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$25,200.00) \$25,200.00 (\$25,200.00) \$25,200.00 (\$25,200.00) \$25,200.00 (\$25,200.00) \$25,200.00	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user mitcha3 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 43 on the current Payment Estimate.		
				l	15 16 17 17 18 18 18 18	Nov 2, 2022 Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16, 2022 Dec 16, 2022 Dec 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$25,200.00) \$25,200.00) (\$25,200.00) \$25,200.00) (\$25,200.00) \$25,200.00 (\$25,200.00) \$0.00 \$0.00 (\$11,900.00)	Estimate Item Adjustment (0013) due to user mitcha3 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user mitcha3 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.		



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3149	3170 -	Total						\$0.00	
	3180	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		14	Oct 15, 2022	SYSTEM	\$156,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user mitcha3 overridding Payment Estimate Exception 44 on the current Payment Estimate.
		SOLUTION			14	Oct 15, 2022	SYSTEM	(\$156,380.00)	
					15	Nov 2, 2022	SYSTEM	\$156,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user mitcha3 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$156,380.00)	
					16	Nov 16, 2022	SYSTEM	\$156,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user mitcha3 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$156,380.00)	
					17	Dec 1, 2022	SYSTEM	\$156,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user mitcha3 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$156,380.00)	
					18	Dec 16, 2022	SYSTEM	\$156,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$156,380.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	3180 -	Total						\$0.00	
ſ	3200		ONCRETE		18	Dec 16, 2022	SYSTEM	(\$685.00)	
		JEALER		- Total				(\$685.00)	
			Material - Tota					(\$685.00)	
ļ	3200 -	Total						(\$685.00)	
	3210	CLASS B-2 CONCRETE	Material		15	Nov 2, 2022	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user mitcha3 overridding Payment Estimate Exception 89 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$13,500.00)	
					16	Nov 16, 2022	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user mitcha3 overridding Payment Estimate Exception 102 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$13,500.00)	
					17	Dec 1, 2022	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user mitcha3 overridding Payment Estimate Exception 79 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$13,500.00)	
					18	Dec 16, 2022	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user kloepj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$13,500.00)	
				- Total				\$0.00	
			Material - Tota	d				\$0.00	
	3210 -	Total						\$0.00	
	3220	TYPE B BARRIER	Material		17	Dec 1, 2022	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user mitcha3 overridding Payment Estimate Exception 80 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$2,700.00)	
					18	Dec 16, 2022	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user kloepj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
49	3220	TYPE B BARRIER	Material		18	Dec 16, 2022	SYSTEM	(\$2,700.00)											
				- Total				\$0.00											
			Material - Tota	al				\$0.00											
	3220 -	Total						\$0.00											
ĺ	3260	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		12	Sep 16, 2022	SYSTEM	\$47,628.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user kloepj1 overridding Paymen Estimate Exception 90 on the current Payment Estimate.										
					12	Sep 16, 2022	SYSTEM	(\$47,628.00)											
					13	Oct 3, 2022	SYSTEM	\$159,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user kloepj1 overridding Paymen Estimate Exception 89 on the current Payment Estimate.										
					13	Oct 3, 2022	SYSTEM	(\$159,408.00)											
					14	Oct 15, 2022	SYSTEM	\$159,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user mitcha3 overridding Paymen Estimate Exception 100 on the current Payment Estimate.										
				14	Oct 15, 2022	SYSTEM	(\$159,408.00)												
					15	Nov 2, 2022	SYSTEM	\$91,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user mitcha3 overridding Payme Estimate Exception 103 on the current Payment Estimate.										
									15	Nov 2, 2022	SYSTEM	(\$91,260.00)							
									16	Nov 16, 2022	SYSTEM	\$91,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user mitcha3 overridding Payme Estimate Exception 116 on the current Payment Estimate.						
					16	Nov 16, 2022	SYSTEM	(\$91,260.00)											
				- Total				\$0.00											
			Material - Tota	tal		\$0.00													
	3260 -	Total						\$0.00											
	6002	ASPHALTIC CONCRETE MIXTURE PG	Other Item Adjustment	ACAD		Oct 4, 2022	kloepj1	\$422.83	SP125 20-94. 4/18/22. Current Index: 557.5, Base Index: 531.25, Index Difference: 26.25										
		64-22 (SP1		ACAD - Tot	al			\$422.83											
			Other Item Ad	justment - To	otal			\$422.83											
	6002 -	Total			_			\$422.83											
	6007	REINFORCING STEEL	Material		15	Nov 2, 2022	SYSTEM	\$860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user mitcha3 overridding Payme Estimate Exception 104 on the current Payment Estimate.										
					15	Nov 2, 2022	SYSTEM	(\$860.00)											
															16	Nov 16, 2022	SYSTEM	\$860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user mitcha3 overridding Payme Estimate Exception 117 on the current Payment Estimate.
												16	Nov 16, 2022	SYSTEM	(\$860.00)				
					17	Dec 1, 2022	SYSTEM	\$860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user mitcha3 overridding Payme Estimate Exception 98 on the current Payment Estimate.										
					17	Dec 1, 2022	SYSTEM	(\$860.00)											
										18	18	Dec 16, 2022	SYSTEM	\$860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user kloepj1 overridding Paymen Estimate Exception 117 on the current Payment Estimate.				
					18	Dec 16, 2022	SYSTEM	(\$860.00)											
				- Total				\$0.00											
			Material - Tota	al				\$0.00											
	6007 -	Total						\$0.00											



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	LIIIO	Description	Туре	Adjustment Type	Number	Date	Ву	Amount	- Condito
J6I3149	6008	REINFORCING STEEL	Material			2022			
		STEEL			16	Nov 16, 2022	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user mitcha3 overridding Payment Estimate Exception 126 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$40.00)	
					17	Dec 1, 2022	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user mitcha3 overridding Payment Estimate Exception 107 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$40.00)	
					18	Dec 16, 2022	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user kloepj1 overridding Payment Estimate Exception 126 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$40.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	6008 -	- Total						\$0.00	
J6I3149 -	Total							\$107,767.78	
J6I3187	3610	ASPHALTIC CONCRETE	Other Item Adjustment	ACAD	18	Dec 16, 2022	kloepj1	\$1,823.63	SP125C 70-22. 12/5/22. Current Index: 631.25, Base Index: 531.25, Index Difference: 100
		MIXTURE PG 64-22 (SP1		ACAD - Tota	al			\$1,823.63	
			Other Item Ad	justment - To	tal			\$1,823.63	
	3610 -	- Total						\$1,823.63	
	3620	ASPHALTIC CONCRETE	Other Item Adjustment	ACAD	18	Dec 16, 2022	kloepj1	\$1,594.91	SP125C 64-22. 12/5/22. Current Index: 631.25, Base Index: 531.25, Index Difference: 100
		MIXTURE PG 76-22 (SP125C		ACAD - Tota	al			\$1,594.91	
		MIX)	Other Item Ad	justment - To	tal			\$1,594.91	
	3620 -	- Total						\$1,594.91	
	3650	TACK COAT	Material		18	Dec 16, 2022	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$2,550.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00 \$0.00	
	3650 -	- Total	Material - Tota						
	3650 - 3730	Total 6 IN. CONCRETE MEDIAN STRIP	Material - Tota Material		15	Nov 2, 2022	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 56 on the current Payment Estimate.
		6 IN. CONCRETE			15		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment
		6 IN. CONCRETE				2022 Nov 2,		\$0.00 \$0.00 \$976.00	Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment
		6 IN. CONCRETE			15	2022 Nov 2, 2022 Nov 16,	SYSTEM	\$0.00 \$0.00 \$976.00 (\$976.00)	Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 56 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment
		6 IN. CONCRETE			15 16	2022 Nov 2, 2022 Nov 16, 2022 Nov 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$976.00 (\$976.00) \$1,464.00	Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 56 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment
		6 IN. CONCRETE			15 16 16	2022 Nov 2, 2022 Nov 16, 2022 Nov 16, 2022 Dec 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$976.00 (\$976.00) \$1,464.00 (\$1,464.00)	Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 56 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 65 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment
		6 IN. CONCRETE			15 16 16 17	2022 Nov 2, 2022 Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$976.00 (\$976.00) \$1,464.00 (\$1,464.00) \$1,464.00	Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 56 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 65 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment
		6 IN. CONCRETE			15 16 16 17 17	2022 Nov 2, 2022 Nov 16, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$976.00 (\$976.00) \$1,464.00 (\$1,464.00) \$1,464.00 (\$1,464.00)	Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 56 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 65 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 55 on the current Payment Estimate.
		6 IN. CONCRETE			15 16 16 17 17 18	2022 Nov 2, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$976.00 (\$976.00) \$1,464.00 (\$1,464.00) \$1,464.00 (\$1,464.00) \$1,464.00	Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 56 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 65 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 55 on the current Payment Estimate.
		6 IN. CONCRETE		al - Total	15 16 16 17 17 18	2022 Nov 2, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$976.00 (\$976.00) \$1,464.00 (\$1,464.00) \$1,464.00 (\$1,464.00) \$1,464.00 (\$1,464.00)	Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 56 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 65 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 55 on the current Payment Estimate.
	3730	6 IN. CONCRETE	Material	al - Total	15 16 16 17 17 18	2022 Nov 2, 2022 Nov 16, 2022 Dec 1, 2022 Dec 1, 2022 Dec 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$976.00 (\$976.00) \$1,464.00 (\$1,464.00) \$1,464.00 (\$1,464.00) \$1,464.00 (\$1,464.00) \$1,464.00	Estimate Item Adjustment (0014) due to user mitcha3 overridding Payment Estimate Exception 56 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 65 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payment Estimate Exception 55 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 55 on the current Payment Estimate.



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
37 :	3840	FULL DEPTH	Material						Estimate Exception 33 on the current Payment Estimate.
					11	Sep 1, 2022	SYSTEM	(\$53,280.00)	
					12	Sep 16, 2022	SYSTEM	\$98,304.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$98,304.00)	
					13	Oct 3, 2022	SYSTEM	\$189,568.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kloepj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					13	Oct 3, 2022	SYSTEM	(\$189,568.00)	
					14	Oct 15, 2022	SYSTEM	\$194,368.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mitcha3 overridding Paymen Estimate Exception 54 on the current Payment Estimate.
					14	Oct 15, 2022	SYSTEM	(\$194,368.00)	
					15	Nov 2, 2022	SYSTEM	\$194,368.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user mitcha3 overridding Paymer Estimate Exception 65 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$194,368.00)	
					16	Nov 16, 2022	SYSTEM	\$194,368.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mitcha3 overridding Paymer Estimate Exception 73 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$194,368.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	3840 -	Total						\$0.00	
:	<b>3840 -</b> 3850	SUBGRADE COMPACTION (6 IN. DEPTH)	Material		12	Sep 16, 2022	SYSTEM	\$5,065.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Paymen Estimate Exception 47 on the current Payment Estimate.
		(PAVEM			12	Sep 16, 2022	SYSTEM	(\$5,065.20)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	3850 -	Total				_		\$0.00	
;	3860	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		12	Sep 16, 2022	SYSTEM	\$1,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Paymen Estimate Exception 49 on the current Payment Estimate.
		11031			12	Sep 16, 2022	SYSTEM	(\$1,020.00)	
					13	Oct 3, 2022	SYSTEM	\$2,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Paymen Estimate Exception 48 on the current Payment Estimate.
					13	Oct 3, 2022	SYSTEM	(\$2,325.00)	
					14	Oct 15, 2022	SYSTEM	\$2,415.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mitcha3 overridding Payme Estimate Exception 57 on the current Payment Estimate.
					14	Oct 15, 2022	SYSTEM	(\$2,415.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
			Overrun	Overrun	13	Oct 3, 2022	SYSTEM	(\$345.00)	
					14	Oct 15, 2022	SYSTEM	(\$90.00)	
				Overrun - T	otal			(\$435.00)	
								(\$435.00)	
			Overrun - Tota	al				· · ·	
	3860 - 3870	Total DOWEL BAR	Overrun - Tota Material	al	12	Sep 16,	SYSTEM	(\$435.00) \$2,040.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
613187	3870	INSTALL WITH	Material	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					Estimate Exception 51 on the current Payment Estimate.				
		BASK			12	Sep 16,	SYSTEM	(\$2,040.00)					
					13	2022 Oct 3, 2022	SYSTEM	\$9,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment				
					13	Oct 3, 2022	SYSTEM	(\$9,480.00)	Estimate Exception 50 on the current Payment Estimate.				
					14	Oct 15, 2022	SYSTEM	\$9,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mitcha3 overridding Payment Estimate Exception 59 on the current Payment Estimate.				
					14	Oct 15, 2022	SYSTEM	(\$9,720.00)					
				- Total				\$0.00					
			Material - Tota	al				\$0.00					
			Overrun	Overrun	14	Oct 15, 2022	SYSTEM	(\$150.00)					
				Overrun - T	otal			(\$150.00)					
			Overrun - Tota	al				(\$150.00)					
	3870 -							(\$150.00)					
	3880	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		12	Sep 16, 2022	SYSTEM	\$1,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.				
					12	Sep 16, 2022	SYSTEM	(\$1,960.00)					
					13	Oct 3, 2022	SYSTEM	\$5,558.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kloepj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.				
						13	Oct 3, 2022	SYSTEM	(\$5,558.00)				
					14	Oct 15, 2022	SYSTEM	\$5,894.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mitcha3 overridding Payment Estimate Exception 60 on the current Payment Estimate.				
					14	Oct 15, 2022	SYSTEM	(\$5,894.00)					
				- Total				\$0.00					
			Material - Tota	al	_	_		\$0.00					
			Overrun	Overrun		Oct 3, 2022	SYSTEM	(\$434.00)					
					14	Oct 15, 2022	SYSTEM	(\$336.00)					
				Overrun - T	otal			(\$770.00)					
			Overrun - Tota	al				(\$770.00)					
	3880 -	Total						(\$770.00)					
	3890	MISC. PAVEMENT REPAIR	Material		11	Sep 1, 2022	SYSTEM	\$3,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mitcha3 overridding Payment Estimate Exception 37 on the current Payment Estimate.				
					11	Sep 1, 2022	SYSTEM	(\$3,330.00)					
							12	Sep 16, 2022	SYSTEM	\$6,144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.		
												12	Sep 16, 2022
					13	Oct 3, 2022	SYSTEM	\$11,849.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kloepj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.				
					13	Oct 3, 2022	SYSTEM	(\$11,849.00)					
					14	Oct 15, 2022	SYSTEM	\$12,149.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mitcha3 overridding Payment Estimate Exception 63 on the current Payment Estimate.				
					14 Oct 15, SYSTEM (\$12,149.00)								
					14	Oct 15, 2022	STSTEIVI	(\$12,149.00)					



Dec 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3187	3890	MISC. PAVEMENT REPAIR	Material	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		2022			Estimate Item Adjustment (0016) due to user mitcha3 overridding Payment Estimate Exception 67 on the current Payment Estimate.
		NEFAIN			15	Nov 2, 2022	SYSTEM	(\$12,149.00)	Lisunate Exception of on the current rayment Estimate.
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	3890 -	Total						\$0.00	
	3930	CONCRETE TRAFFIC BARRIER, TYPE C	Material		11	Sep 1, 2022	SYSTEM	\$2,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mitcha3 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					11	Sep 1, 2022	SYSTEM	(\$2,940.00)	
					12	Sep 16, 2022	SYSTEM	\$18,690.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					12	Sep 16, 2022	SYSTEM	(\$18,690.00)	
					13	Oct 3, 2022	SYSTEM	\$18,690.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kloepj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					13	Oct 3,	SYSTEM	(\$18,690.00)	Estimate Exception 57 on the current Payment Estimate.
					14	2022 Oct 15, 2022	SYSTEM	\$74,095.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user mitcha3 overridding Payment Estimate Exception 64 on the current Payment Estimate.
					14	Oct 15, 2022	SYSTEM	(\$74,095.00)	Estimate Exception of on the current raymont Estimate.
					15	Nov 2, 2022	SYSTEM	\$112,595.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user mitcha3 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					15	Nov 2, 2022	SYSTEM	(\$112,595.00)	
					16	Nov 16, 2022	SYSTEM	\$120,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mitcha3 overridding Payment Estimate Exception 75 on the current Payment Estimate.
					16	Nov 16,	SYSTEM	(\$120,470.00)	Esumate Exception 75 on the current Payment Estimate.
					17	2022 Dec 1, 2022	SYSTEM	\$55,674.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mitcha3 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$55,674.01)	
					18	Dec 16, 2022	SYSTEM	\$55,674.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kloepj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$55,674.01)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	3930 -	Total						\$0.00	
	3990	MISC. CONCRETE TRAFFIC BARRIER	Material		16	Nov 16, 2022	SYSTEM	\$170,143.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mitcha3 overridding Payment Estimate Exception 77 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$170,143.02)	
					17	Dec 1, 2022	SYSTEM	\$170,143.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mitcha3 overridding Payment Estimate Exception 61 on the current Payment Estimate.
					17	Dec 1, 2022	SYSTEM	(\$170,143.02)	
					18	Dec 16, 2022	SYSTEM	\$170,143.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kloepj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$170,143.02)	
				- Total				\$0.00	



Dec 20, 2022

ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
37	3990	MISC. CONCRETE TRAFFIC BARRIER	Material - Tota	ıl				\$0.00							
	3990 -	Total						\$0.00							
ſ	4120	MISC. MANHOLES AND DROP INLETS	Material		11	Sep 1, 2022	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mitcha3 overridding Paymen Estimate Exception 66 on the current Payment Estimate.						
					11	Sep 1, 2022	SYSTEM	(\$7,800.00)							
					12	Sep 16, 2022	SYSTEM	\$20,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Paymen Estimate Exception 92 on the current Payment Estimate.						
					12	Sep 16, 2022	SYSTEM	(\$20,800.00)							
					13	Oct 3, 2022	SYSTEM	\$31,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kloepj1 overridding Paymen Estimate Exception 90 on the current Payment Estimate.						
					13	Oct 3, 2022	SYSTEM	(\$31,200.00)							
					14	Oct 15, 2022	SYSTEM	\$33,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user mitcha3 overridding Payme Estimate Exception 101 on the current Payment Estimate.						
					14	Oct 15, 2022	SYSTEM	(\$33,800.00)							
					15	Nov 2, 2022	SYSTEM	\$33,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user mitcha3 overridding Payme Estimate Exception 125 on the current Payment Estimate.						
											15	Nov 2, 2022	SYSTEM	(\$33,800.00)	
											16	Nov 16, 2022	SYSTEM	\$33,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mitcha3 overridding Payme Estimate Exception 138 on the current Payment Estimate.
					16	Nov 16, 2022	SYSTEM	(\$33,800.00)							
					17	Dec 1, 2022	SYSTEM	\$39,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mitcha3 overridding Payme Estimate Exception 119 on the current Payment Estimate.						
					17	Dec 1, 2022	SYSTEM	(\$39,000.00)							
					18	Dec 16, 2022	SYSTEM	\$39,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kloepj1 overridding Paymen Estimate Exception 138 on the current Payment Estimate.						
					18	Dec 16, 2022	SYSTEM	(\$39,000.00)							
				- Total				\$0.00							
			Material - Tota	ıl				\$0.00							
	4120 -	Total						\$0.00							
	4160	MGS GUARDRAIL	Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$53,596.92	Payment Estimate Item Adjustment generated Stockpile Transaction						
				- Total				\$53,596.92							
			Construction	Stockpile ST	MI - Total			\$53,596.92							
	4160 -	Total						\$53,596.92							
	4170	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$98,752.50	Payment Estimate Item Adjustment generated Stockpile Transaction						
		F1 3 IN	GTIVI	- Total				\$98,752.50							
			Construction	Stockpile ST	MI - Total			\$98,752.50							
	4170 -	Total						\$98,752.50							
	4180	MGS BRIDGE APP. TRANS SEC	Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$26,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction						
		(EXT CURB)	U I IVII	- Total				\$26,400.00							
			Construction	Stockpile ST	MI - Total			\$26,400.00							
	4180 -	Total						\$26,400.00							
	4190	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$25,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction						



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
187	4190	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI	- Total				\$25,200.00	
			Construction	Stockpile ST	MI - Total			\$25,200.00	
	4190 -	Total						\$25,200.00	
	4200	MGS END ANCHOR	Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$7,650.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$7,650.00	
			Construction Stockpile STMI - Total					\$7,650.00	
	4200 -							\$7,650.00	
	4210	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile STMI	- Total	1	Apr 4, 2022	SYSTEM	\$17,550.00 \$17,550.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		MI - Total			\$17,550.00	
	4210 -	Total	Construction Stockpile STMI - Total					\$17,550.00	
		PLAIN NEOPRENE BEARING PAD	Construction Stockpile STMI		17	Dec 1, 2022	SYSTEM	\$1,170.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,170.00	
			Construction	MI - Total			\$1,170.00		
	5070 -	Total						\$1,170.00	
	5080	TYPE N PTFE BEARING	Construction Stockpile STMI		17	Dec 1, 2022	SYSTEM	\$15,480.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$15,480.00	
5			Construction	Stockpile ST	MI - Total			\$15,480.00	
	5080 -	Total						\$15,480.00	
	5260	PLAIN NEOPRENE BEARING PAD	Construction Stockpile STMI		17	Dec 1, 2022	SYSTEM	\$1,170.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,170.00	
			Construction	Stockpile ST	MI - Total			\$1,170.00	
	5260 -	Total							
	5270	TYPE N PTFE BEARING	Construction Stockpile STMI		17	Dec 1, 2022	SYSTEM	\$15,480.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$15,480.00	
		Construction Stockpile STMI - Total						\$15,480.00	
	<b>5270</b> - 5670	Total TYPE N PTFE BEARING	Construction Stockpile		17	Dec 1, 2022	SYSTEM	<b>\$15,480.00</b> <b>\$44,760.00</b>	Payment Estimate Item Adjustment generated Stockpile Transaction
		DEARING	STMI	- Total		2022		\$44,760.00	
			Construction Stockpile STMI - Total					\$44,760.00	
	5670 -	Total						\$44,760.00	
	5860	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	Construction Stockpile		17	Dec 1, 2022	SYSTEM	\$14,150.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$14,150.00	
			Construction	Construction Stockpile STMI - Total				\$14,150.00	
	5860 -	Total						\$14,150.00	
	5870	TYPE N PTFE BEARING	Construction Stockpile		17	Dec 1, 2022	SYSTEM	\$44,720.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$44,720.00	
		Construction Stockpile STMI - Total						\$44,720.00	
	5870 -	Total						\$44,720.00	
	6101	MISC. HIGHWAY SIGNING	Material		18	Dec 16, 2022	SYSTEM	\$4,867.89	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user kloepj1 overridding Payment Estimate Exception 150 on the current Payment Estimate.
					18	Dec 16, 2022	SYSTEM	(\$4,867.89)	Encopier record and entern raymon Edunate.
				- Total				\$0.00	
			Material - Tota	al				\$0.00	



Dec 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3187	6101 -	Total						\$0.00	
J6I3187 ·	Total							\$368,142.96	
Overall -	Total						\$475,910.74		