

Pay Estimate Created Date: December 2, 2022

Progress Estimate Number	Contract ID	220218-F07	Pay Period Start	November 16, 2022	Original Contract Amount	\$2,828,777.00
10	Prime Contractor	Pace Construction Company, LLC	Pay Period End	d December 1, 2022	Net Change Order Amount Current Contract Amount	(\$452,683.37) \$2,376,093.63

Approval Date		By User
December 2, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	bedarl2
December 2, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	washas
December 5, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2022	November 1, 2022	November 4, 2022	93.70%

	Milestones		
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	March 1, 2022	March 1, 2022	
Letting Date	February 18, 2022	February 18, 2022	
Notice to Proceed Date	April 4, 2022	April 4, 2022	
Open to Traffic Date			
Work Began Date	July 5, 2022	July 5, 2022	

Contract Total Pay For Estimate No. 10							
		This Estimate	Previous	To Date			
220218-F07							
	Total Posted Items Pay	\$16,263.20	\$2,210,071.30	\$2,226,334.50			
	Gross Item Adjustments	\$0.00	\$154,062.43	\$154,062.43			
	Incentive	\$0.00	\$0.00	\$0.00			
	Disincentive	\$0.00	\$0.00	\$0.00			
	Liquidated Damage	\$0.00	(\$7,650.00)	(\$7,650.00)			
	Other Contract Adjustments	\$0.00	\$53,813.06	\$53,813.06			
	•		\$2,410,296.79	\$2,426,559.99			
Contract Total Pa	avable This Estimate:	\$16,263,20					

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3424	0300	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$20.000	36	\$720.00
	0310	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$300.000	1	\$300.00
	0330	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	EA	\$550.000	1	\$550.00
	0350	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	EA	\$180.000	9	\$1,620.00
	0380	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.300	444	\$133.20
	0390	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.300	200	\$60.00
	0420	6209901	MISC.Temporary Pavement Marking Paint	LS	\$9,600.000	1	\$9,600.00
	0430	6209902	MISC.INLAID PAVEMENT MARKERS	EA	\$40.000	7	\$280.00
	0440	6209902	MISC.PREFORMED THERMOPLASTIC SOLID WHITE LANE DROP MERGE LEFT ARROW	EA	\$1,500.000	2	\$3,000.00
Project J6I	3424 - Tota	ıl					\$16,263.20
Overall - To	otal						\$16,263.20

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Page 1 of 24 Revision 4/1/2020



Pay Estimate Created Date: December 2, 2022

Pay Period November 16, **Progress Estimate Contract ID** 220218-F07 Original Contract Amount \$2,828,777.00 Number Start 2022 Pay Period End December 1, 2022 Net Change Order Prime Pace Construction Company, 10 (\$452,683.37) Amount (\$452,683.37)

Current Contract Amount \$2,376,093.63 Contractor LLC

ct er	No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
24	0800	TYPE A2 SHOULDER	Material			-133.3	\$160.00	(\$21,328.00
	0800	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user bedarl2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	133.3	\$160.00	\$21,328.00
	0120	PAVED APPROACH, 7 IN.	Material			-35.7	\$200.00	(\$7,140.00
	0120	PAVED APPROACH, 7 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	35.7	\$200.00	\$7,140.00
	0140	CONCRETE SIDEWALK, 4 IN.	Material			-861	\$70.00	(\$60,270.00
	0140	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	861	\$70.00	\$60,270.00
	0150	MISC.	Material			-21	\$2,400.00	(\$50,400.00
	0150	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	21	\$2,400.00	\$50,400.00
(0160	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-86	\$44.50	(\$3,827.00
	0160	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user bedarl2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	86	\$44.50	\$3,827.00
	0170	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material			-142	\$46.00	(\$6,532.00
	0170	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user bedarl2 overridding Payment Estimate Exception 15 on the current Payment Estimate.	142	\$46.00	\$6,532.00
	0180	MISC.	Material			-402	\$44.50	(\$17,889.00
	0180	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 18 on the current Payment Estimate.	402	\$44.50	\$17,889.00
	0270	CONCRETE TRAFFIC BARRIER, TYPE C (RETAINING WALL)	Material			-147	\$225.00	(\$33,075.00
	0270	CONCRETE TRAFFIC BARRIER, TYPE C (RETAINING WALL)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user bedarl2 overridding Payment Estimate Exception 21 on the current Payment Estimate.	147	\$225.00	\$33,075.00
	0380	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material			-23,607	\$0.30	(\$7,082.10

Revision 4/1/2020 Page 2 of 24



Pay Estimate Created Date: December 2, 2022

Pay Period November 16, **Progress Estimate Contract ID** 220218-F07 Original Contract Amount \$2,828,777.00 Number Start 2022 Pay Period End December 1, 2022 Net Change Order Prime Pace Construction Company, 10 (\$452,683.37) Amount (\$452,083.31)

Current Contract Amount \$2,376,093.63 Contractor LLC

t Line er No.		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
4	BEADS						
0380	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate.	23,607	\$0.30	\$7,082.10
0390	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-6,592	\$0.30	(\$1,977.60
0390	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment Estimate Exception 27 on the current Payment Estimate.	6,592	\$0.30	\$1,977.60
0400	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-3,575	\$1.00	(\$3,575.00
0400	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Exception 29 on the current Payment Estimate.	3,575	\$1.00	\$3,575.00
0420	MISC.	Material			-1	\$9,600.00	(\$9,600.00
0420	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Exception 31 on the current Payment Estimate.	1	\$9,600.00	\$9,600.00
0550	POST, SIGNAL 8 FT. OR 2.4 M	Material			-22	\$950.00	(\$20,900.00
0550	POST, SIGNAL 8 FT. OR 2.4 M	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 34 on the current Payment Estimate.	22	\$950.00	\$20,900.00
0560	VIDEO DETECTION SYSTEM	Material			-2	\$25,000.00	(\$50,000.00
0560	VIDEO DETECTION SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user bedarl2 overridding Payment Estimate Exception 37 on the current Payment Estimate.	2	\$25,000.00	\$50,000.00
0570	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material			-64	\$14.00	(\$896.00
0570	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 38 on the current Payment Estimate.	64	\$14.00	\$896.00
0580	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material			-156	\$35.00	(\$5,460.00
0580	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user bedarl2 overridding Payment Estimate Exception 39	156	\$35.00	\$5,460.00

Revision 4/1/2020 Page 3 of 24



Pay Estimate Created Date: December 2, 2022

Pay Period November 16, **Progress Estimate Contract ID** 220218-F07 Original Contract Amount \$2,828,777.00 Number Start 2022 Pay Period End December 1, 2022 Net Change Order Prime Pace Construction Company, 10 (\$452,683.37) Amount (\$452,683.37)

Current Contract Amount \$2,376,093.63 Contractor LLC

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
124					on the current Payment Estimate.			
	0590	CABLE, 16 AWG 2 CONDUCTOR	Material			-2,338	\$1.05	(\$2,454.90
	0590	CABLE, 16 AWG 2 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate.	2,338	\$1.05	\$2,454.90
	0600	CABLE, 16 AWG 5 CONDUCTOR	Material			-2,342	\$1.25	(\$2,927.50
	0600	CABLE, 16 AWG 5 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user bedarl2 overridding Payment Estimate Exception 41 on the current Payment Estimate.	2,342	\$1.25	\$2,927.50
	0610	BASE, CONCRETE	Material			-4.8	\$3,100.00	(\$14,880.00
	0610	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate.	4.8	\$3,100.00	\$14,880.00
	0630	MISC.	Material			-14	\$958.00	(\$13,412.00
	0630	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment Estimate Exception 47 on the current Payment Estimate.	14	\$958.00	\$13,412.00
	0640	MISC.	Material			-14	\$470.00	(\$6,580.00
	0640	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate.	14	\$470.00	\$6,580.00
	0650	MISC.	Material			-1	\$204.00	(\$204.00
	0650	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate.	1	\$204.00	\$204.00
	0660	CONCRETE FOOTINGS, EMBEDDED	Material			-0.2	\$3,000.00	(\$600.00
	0660	CONCRETE FOOTINGS, EMBEDDED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user bedarl2 overridding Payment Estimate Exception 50 on the current Payment Estimate.	0.2	\$3,000.00	\$600.00
	0670	PIPE POSTS	Material			-70	\$10.00	(\$700.00
	0670	PIPE POSTS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user bedarl2 overridding Payment Estimate Exception 53 on the current Payment Estimate.	70	\$10.00	\$700.00
	0680	2 IN. PSST POST - 12 GA.	Material			-10	\$40.00	(\$400.00
	0680	2 IN. PSST POST - 12 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	10	\$40.00	\$400.00

Revision 4/1/2020 Page 4 of 24



Pay Estimate Created Date: December 2, 2022

Progress Estimate Number	Contract ID	220218-F07	Pay Period Start	November 16, 2022	Original Contract Amount	\$2,828,777.00
10	Prime Contractor	Pace Construction Company, LLC	Pay Period End	December 1, 2022	Net Change Order Amount Current Contract Amount	(\$452,683.37) \$2,376,093.63

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3424					Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate.			
	0690	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material			-3	\$60.00	(\$180.00)
	0690	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate.	3	\$60.00	\$180.00
Total								\$0.00

Revision 4/1/2020 Page 5 of 24



	Contract Project Information							
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work			
J6I3424	I 70-5(347)	Coldmill and resurface	I-70	ST LOUIS CITY	from Branch St to Biddle St under I-44			

Totals by Job	by Job Numbers										
J6I3424		This Estimate	Previous	To Date							
	Posted Item Pay Gross Item Adjustments	\$16,263.20 \$0.00	\$2,210,071.30 \$154,062.43	\$2,226,334.50 \$154,062.43							
	Gross Item Pay	\$16,263.20	\$2,364,133.73	\$2,380,396.93							
	Incentive	\$0.00	\$0.00	\$0.00							
	Disincentive	\$0.00	\$0.00	\$0.00							
	Liquidated Damages	\$0.00	(\$7,650.00)	(\$7,650.00)							
	Other Contract Adjustments	\$0.00	\$53,813.06	\$53,813.06							

Revision 4/1/2020 Page 6 of 24



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 5021340, Project Item Line Number 0080, Material Set 502134096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 5021340, Project Item Line Number 0080, Material Set 502134096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6085007, Project Item Line Number 0120, Material Set 608500796, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6085007, Project Item Line Number 0120, Material Set 608500796, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6085007, Project Item Line Number 0120, Material Set 608500796, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6085007, Project Item Line Number 0120, Material Set 608500796, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6086004, Project Item Line Number 0140, Material Set 608600496, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6086004, Project Item Line Number 0140, Material Set 608600496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6086004, Project Item Line Number 0140, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6089902, Project Item Line Number 0150, Material Set 608990296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6089902, Project Item Line Number 0150, Material Set 608990296, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6089902, Project Item Line Number 0150, Material Set 608990296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6091010, Project Item Line Number 0160, Material Set 609101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6091010, Project Item Line Number 0160, Material Set 609101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6092021, Project Item Line Number 0170, Material Set 609202196, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6092021, Project Item Line Number 0170, Material Set 609202196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6092021, Project Item Line Number 0170, Material Set 609202196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6099903, Project Item Line Number 0180, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6099903, Project Item Line Number 0180, Material Set 6099903, Material 1057JMTBE42013 - Tie Bar Ep Ctd 12" No. 4/M13 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6099903, Project Item Line Number 0180, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6173001, Project Item Line Number 0270, Material Set 6173001, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6173001, Project Item Line Number 0270, Material Set 6173001, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6173001, Project Item Line Number 0270, Material Set 6173001, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6173001, Project Item Line Number 0270, Material Set 6173001, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden

Revision 4/1/2020 Page 7 of 24



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Generic 0501CCB1.A is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6205902A, Project Item Line Number 0380, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J613424, Item 6205902A, Project Item Line Number 0380, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6205903A, Project Item Line Number 0390, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6205903A, Project Item Line Number 0390, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6205906A, Project Item Line Number 0400, Material Set 6205906A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6205906A, Project Item Line Number 0400, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6209901, Project Item Line Number 0420, Material Set 620990196, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6209901, Project Item Line Number 0420, Material Set 620990196, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 6209901, Project Item Line Number 0420, Material Set 620990196, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9022708, Project Item Line Number 0550, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9022708, Project Item Line Number 0550, Material Set 902270896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9022708, Project Item Line Number 0550, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9024975, Project Item Line Number 0560, Material Set 902497596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9025300, Project Item Line Number 0570, Material Set 902530096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9027300, Project Item Line Number 0580, Material Set 902730096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9028308, Project Item Line Number 0590, Material Set 902830896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9028310, Project Item Line Number 0600, Material Set 902831096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9029902, Project Item Line Number 0630, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9029902, Project Item Line Number	Working with the materials department and the contractor to	bedarl2	Overridden

Revision 4/1/2020 Page 8 of 24



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
0640, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	get this updated.		
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 9029902, Project Item Line Number 0650, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9031010, Project Item Line Number 0660, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6i3424, Item 9031010, Project Item Line Number 0660, Material Set 903101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3424, Item 9031010, Project Item Line Number 0660, Material Set 903101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6i3424, Item 9031220, Project Item Line Number 0670, Material Set 903122096, Material 0903HSPSPI - Pipe Post for Highway Signing, Acceptance Action Generic 0903HSPSPI is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3424, Item 9031270A, Project Item Line Number 0680, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6i3424, Item 9031271, Project Item Line Number 0690, Material Set 903127196, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Working with the materials department and the contractor to get this updated.	bedarl2	Overridden
Estimate Exception Type: Item Overrun: Contract 220218-F07, Contract Project J6l3424, Project Item Line Number 0120, Contract Line Item Number 0120, Item 6085007, Minor Item.	Pending change order	bedarl2	Overridden
Estimate Exception Type: Item Overrun: Contract 220218-F07, Contract Project J6l3424, Project Item Line Number 0550, Contract Line Item Number 0550, Item 9022708, Minor Item.	Pending change order	bedarl2	Overridden
Estimate Exception Type: Item Overrun: Contract 220218-F07, Contract Project J6l3424, Project Item Line Number 0600, Contract Line Item Number 0600, Item 9028310, Minor Item.	Pending change order	bedarl2	Overridden
Estimate Exception Type: Item Overrun: Contract 220218-F07, Contract Project J6l3424, Project Item Line Number 0050, Contract Line Item Number 0050, Item 4011209, Minor Item.	Pending change order	bedarl2	Overridden
Estimate Exception Type: Item Overrun: Contract 220218-F07, Contract Project J6l3424, Project Item Line Number 0070, Contract Line Item Number 0070, Item 4071005, Minor Item.	Pending change order	bedarl2	Overridden
Estimate Exception Type: Item Overrun: Contract 220218-F07, Contract Project J6l3424, Project Item Line Number 0090, Contract Line Item Number 0090, Item 6049902, Minor Item.	Pending change order	bedarl2	Overridden

Revision 4/1/2020 Page 9 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted an Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220218-F07	J6I3424	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$53,771.65	\$53,771.65
		0001	0020	2072000	LINEAR GRADING CLASS 2	5.70	0.00	5.70	STA	5.70	\$2,000.00	\$11,400.00
		0001	0030	2153000	SHAPING SLOPES, CLASS III	8.00	0.00	8.00	100F	1.00	\$1,400.00	\$1,400.00
		0001	0040	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	145.00	0.00	145.00	SQYD	133.00	\$3.00	\$399.00
		0001	0050	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	1,827.20	-631.20	1,196.00	TONS	1,221.00	\$82.25	\$100,427.25
		0001	0060	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	9,175.80	-2,119.80	7,056.00	TONS	7,055.55	\$131.50	\$927,804.82
		0001	0070	4071005	TACK COAT	17,772.00	-11,592.00	6,180.00	GAL	6,230.00	\$2.30	\$14,329.00
		0001	0080	5021340	TYPE A2 SHOULDER	145.30	0.00	145.30	SQYD	133.30	\$160.00	\$21,328.00
		0001	0090	6049902	MISC.PULLBOX ADJUSTMENT	8.00	0.00	8.00	EA	9.00	\$700.00	\$6,300.00
		0001	0100	6049902	MISC.INLET TOP REPLACEMENT	2.00	0.00	2.00	EA	0.00	\$1,300.00	\$0.00
		0001	0110	6083006	6 IN. CONCRETE MEDIAN STRIP	27.90	0.00	27.90	SQYD	0.00	\$240.00	\$0.00
		0001	0120	6085007	PAVED APPROACH, 7 IN.	15.00	0.00	15.00	SQYD	35.70	\$200.00	\$7,140.00
		0001	0130	6085008	PAVED APPROACH, 8 IN.	20.70	0.00	20.70	SQYD	0.00	\$245.00	\$0.00
		0001	0140	6086004	CONCRETE SIDEWALK, 4 IN.	861.00	0.00	861.00	SQYD	861.00	\$70.00	\$60,270.00
		0001	0150	6089902	MISC.ADA CURB RAMP	22.00	0.00	22.00	EA	21.00	\$2,400.00	\$50,400.00
		0001	0160	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	86.00	0.00	86.00	LF	86.00	\$44.50	\$3,827.00
		0001	0170	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	142.00	0.00	142.00	LF	142.00	\$46.00	\$6,532.00
		0001	0180	6099903	MISC.CONCRETE CURB UNDER GUARDRAIL	1,106.00	0.00	1,106.00	LF	402.00	\$44.50	\$17,889.00
		0001	0190	6099903	MISC.MODIFIED TYPE A INTEGRAL CURB (OVER 6 IN HEIGHT) DOWELED ON CONCRETE	122.00	0.00	122.00	LF	0.00	\$95.00	\$0.00
		0001	0200	6119907	MISC.FURNISHING MODIFIED ROCK BLANKET	238.00	0.00	238.00	CUYD	134.00	\$31.00	\$4,154.00
		0001	0210	6119907	MISC.PLACING MODIFIED ROCK BLANKET	238.00	0.00	238.00	CUYD	134.00	\$30.00	\$4,020.00
		0001	0220	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0230	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	145.00	0.00	145.00	SQYD	133.00	\$20.00	\$2,660.00
		0001	0240	6169901	MISC.TEMP TRAFFIC CONTROL	1.00	0.00	1.00	LS	1.00	\$13,927.00	\$13,927.00
		0001	0250	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN CONTRACTOR FURNISHED/RETAINED	2.00	2.00	4.00	EA	4.00	\$2,850.00	\$11,400.00
		0001	0260	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	18.00	0.00	18.00	LF	0.00	\$455.00	\$0.00
		0001	0270	6173001	CONCRETE TRAFFIC BARRIER, TYPE C (RETAINING WALL)	147.00	0.00	147.00	LF	147.00	\$225.00	\$33,075.00
		0001	0280	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$290,000.00	\$290,000.00
		0001	0290	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	37.00	0.00	37.00	LF	37.00	\$10.00	\$370.00
		0001	0300	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	709.00	0.00	709.00	LF	649.00	\$20.00	\$12,980.00
		0001	0310	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	7.00	0.00	7.00	EA	6.00	\$300.00	\$1,800.00
		0001	0320	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	6.00	0.00	6.00	EA	4.00	\$300.00	\$1,200.00
		0001	0330	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	3.00	0.00	3.00	EA	3.00	\$550.00	\$1,650.00
		0001	0340	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	3.00	0.00	3.00	EA	2.00	\$550.00	\$1,100.00
		0001	0350	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	91.00	0.00	91.00	EA	39.00	\$180.00	\$7,020.00
		0001	0360	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	14.00	0.00	14.00	EA	14.00	\$55.00	\$770.00
		0001	0370	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	240.00	0.00	240.00	LF	0.00	\$1.00	\$0.00
		0001	0380	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	27,957.00	0.00	27,957.00	LF	23,607.00	\$0.30	\$7,082.10
		0001	0390	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	19,604.00	0.00	19,604.00	LF	6,592.00	\$0.30	\$1,977.60
		0001	0400	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,025.00	0.00	7,025.00	LF	3,575.00	\$1.00	\$3,575.00
		0001	0410	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	2.00	0.00	2.00	EA	2.00	\$250.00	\$500.00
		0001	0420	6209901	MISC.Temporary Pavement Marking Paint	1.00	0.00	1.00	LS	1.00	\$9,600.00	\$9,600.00
		0001	0430	6209902	MISC.INLAID PAVEMENT MARKERS	330.00	0.00	330.00	EA	208.00	\$40.00	\$8,320.00

Revision 4/1/2020 Page 10 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0218-F07	J6I3424	0001	0440	6209902	MISC.PREFORMED THERMOPLASTIC SOLID WHITE LANE DROP MERGE LEFT ARROW	4.00	0.00	4.00	EA	2.00	\$1,500.00	\$3,000.00
		0001	0450	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	94,037.00	-31,189.00	62,848.00	SQYD	62,848.00	\$2.90	\$182,259.20
		0001	0460	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	4,750.00	-782.90	3,967.10	SQYD	3,967.10	\$4.75	\$18,843.7
		0001	0470	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	475.00	0.00	475.00	SQYD	475.00	\$1.95	\$926.2
		0001	0480	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	280.00	-127.50	152.50	STA	152.50	\$54.00	\$8,235.0
		0001	0490	0490 6274000 CONTRACTOR FURNISHED SURVEYING AND STAKIN		1.00	0.00	1.00	LS	1.00	\$1,500.00	\$1,500.0
		0010 0500 6061060 0010 0510 6061068		6061060	MGS GUARDRAIL	2,700.00	0.00	2,700.00	LF	1,962.50	\$39.00	\$76,537.5
		0010	0510	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	15.00	0.00	15.00	EA	11.00	\$3,900.00	\$42,900.0
		0010	0520	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	2.00	0.00	2.00	EA	2.00	\$3,800.00	\$7,600.0
		0010	0530	6061080	MGS END ANCHOR	5.00	0.00	5.00	EA	4.00	\$1,600.00	\$6,400.0
		0010	0540	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	10.00	0.00	10.00	EA	9.00	\$3,300.00	\$29,700.0
		0030	0550	9022708	POST, SIGNAL 8 FT. OR 2.4 M	11.00	0.00	11.00	EA	22.00	\$950.00	\$20,900.0
		0030	0560	9024975	VIDEO DETECTION SYSTEM	2.00	0.00	2.00	EA	2.00	\$25,000.00	\$50,000.0
		0030	0570	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	64.00	0.00	64.00	LF	64.00	\$14.00	\$896.0
		0030	0580	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	156.00	0.00	156.00	LF	156.00	\$35.00	\$5,460.0
		0030	0590	9028308	CABLE, 16 AWG 2 CONDUCTOR	2,340.00	0.00	2,340.00	LF	2,338.00	\$1.05	\$2,454.9
		0030	0600	9028310	CABLE, 16 AWG 5 CONDUCTOR	2,340.00	0.00	2,340.00	LF	2,342.00	\$1.25	\$2,927.5
		0030	0610	9029100	BASE, CONCRETE	4.80	0.00	4.80	CUYD	4.80	\$3,100.00	\$14,880.0
		0030	0620	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	1.00	\$27,000.00	\$27,000.0
		0030	0630	9029902	MISC.APS-AUDIBLE PEDESTRIAN PUSH BUTTON & SIGNING	14.00	0.00	14.00	EA	14.00	\$958.00	\$13,412.0
		0030	0640	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1 S	14.00	0.00	14.00	EA	14.00	\$470.00	\$6,580.0
		0030	0650	9029902	MISC.PUSH BUTTON EXTENSION	2.00	0.00	2.00	EA	1.00	\$204.00	\$204.0
		0040	0660	9031010	CONCRETE FOOTINGS, EMBEDDED	0.20	0.00	0.20	CUYD	0.20	\$3,000.00	\$600.0
		0040	0670	9031220	PIPE POSTS	70.00	0.00	70.00	LB	70.00	\$10.00	\$700.0
		0040	0680	9031270A	2 IN. PSST POST - 12 GA.	10.00	0.00	10.00	LF	10.00	\$40.00	\$400.0
		0040	0690	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	3.00	LF	3.00	\$60.00	\$180.0		
		0040	0700	9035004A	SH-FLAT SHEET	11.00	0.00	11.00	SQFT	11.00	\$40.00	\$440.0
		0050	0710	9109903	MISC.MODOT ITS ASSETS RELOCATION	138.00	0.00	138.00	LF	0.00	\$19.50	\$0.0
	Project .	1613424 - To	otal Value	Posted to D	Date as of Report Generated Date							\$2,226,334.5
218-F07 Ove	rall - Tota	Value Pos	ted to Da	ate as of Rep	ort Generated Date							\$2,226,334

Revision 4/1/2020 Page 11 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0300	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	11/30/22	12/2/22	36.00	LF	Broadway/ Biddle/ Salisbury/ McKinley	0+00		0+00		
0310	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	11/30/22	12/2/22	1.00	EA	Installed 11/6/22	0+00		0+00		
0330	6200027	PREF THERMO PVMT MARKING, COMBO	11/30/22	12/2/22	1.00	EA	Installed 11/6/2022	0+00		0+00		
0350	6200036	PREF THERMO PVMT MARK, 30" WHT MIDBL	11/30/22	12/2/22	9.00	EA	Installed 11/6/2022	0+00		0+00		
0380	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	11/30/22	12/2/22	444.00	LF	Installed 11/6/2022	0+00		0+00		White HB Waterborne Type L Beads greater/equal 450 mod = 31.24% (at 105% pay), White HB Waterborne Type L Beads 400 - 449 mod = 32.70% (at 100% pay), White HB Waterborne Type L Beads 300 - 399 mod = 36.06% (at 80% pay),
0390	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	11/30/22	12/2/22	200.00	LF	Installed 11/6/2022	0+00	0+00			Yellow HB Waterborne Type L Beads greater/equal 450 mcd = 9,52% (at 105% pay), Yellow HB Waterborne Type L Beads 400 - 499 mcd = 66.67% (at 100% pay), Yellow HB Waterborne Type L Beads 300 -399 mcd = 23.81% (at 80% pay).
0420	6209901	MISC. PAVEMENT MARKINGS	11/30/22	12/2/22	1.00	LS	Mid blocks at 9th and Salisbury, Mid blocks at 11th, Salisbury and McKinley. And Broadway off ramp.	0+00		0+00		Contractor's paperwork says Installed 11/6/2022 48' of white paint for mid blocks, And 373' of 4" yellow installed 11/8/2022. And 1,345' of 4" white installed 11/8/2022.
0430	6209902	MISC. PAVEMENT MARKINGS	11/30/22	12/2/22	7.00	EA	Installed 11/6/2022	0+00		0+00		
0440	6209902	MISC. PAVEMENT MARKINGS	11/30/22	12/2/22	2.00	EA	From the Stan Musial Bridge to WB I-70	0+00		0+00		From the Stan Musial Bridge to WB I-70

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 12 of 24



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J6I3424	0040	TYPE 5 AGGREGATE	Price FUEL		8	Nov 2, 2022	SYSTEM	\$13.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
		FOR BASE			9	Nov 17, 2022	SYSTEM	(\$0.07)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
				- Total				\$12.93								
			Price FUEL -	Total				\$12.93								
	0040 -	Total						\$12.93								
	0050	BIT. PAVEMENT MIXTURE	Other Item Adjustment	ACAD	6	Oct 3, 2022	bedarl2	\$9,098.57	BP-1 21-16 Second Period September 2022							
		PG64-22 (BP-1)			9	Nov 17, 2022	bedarl2	\$148.69	BP-1 First Period of November							
				ACAD - Tota	al			\$9,247.26								
			Other Item A	djustment - T	otal			\$9,247.26								
			Overrun	Overrun	9	Nov 17, 2022	SYSTEM	(\$2,177.43)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
				Overrun - T	otal			(\$2,177.43)								
			Overrun - To	tal				(\$2,177.43)								
			Price FUEL		6	Oct 3, 2022	SYSTEM	\$5,719.95	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
					7	Oct 17, 2022	SYSTEM	(\$0.95)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
					9	Nov 17, 2022	SYSTEM	\$121.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
				- Total				\$5,840.18								
			Price FUEL -	Total				\$5,840.18								
	0050 -	Total						\$12,910.01								
	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP1	Material		5	Sep 16, 2022	SYSTEM	\$806,292.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					5	Sep 16, 2022	SYSTEM	(\$806,292.25)								
												6	Oct 3, 2022	SYSTEM	\$927,804.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Oct 3, 2022	SYSTEM	(\$927,804.82)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
			Other Item Adjustment	ACAD	6	Oct 3, 2022	bedarl2	\$83,694.14	SP125 21-17 First Period September 2022							
					6	Oct 3, 2022	bedarl2	\$12,611.45	SP125 21-17 Second Period September 2022							
				ACAD - Tota	al			\$96,305.59								
			Other Item A	djustment - T	otal			\$96,305.59								
			Price FUEL		5	Sep 16, 2022	SYSTEM	\$29,313.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
					6	Oct 3, 2022	SYSTEM	\$4,417.70	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
				- Total				\$33,731.17								
			Price FUEL -	Total				\$33,731.17								
	0060 -	Total						\$130,036.76								
	0070	TACK COAT	Material		5	Sep 16, 2022	SYSTEM	\$10,193.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bedarl2 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
		_			5	Sep 16, 2022	SYSTEM	(\$10,193.60)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
			Overrun	Overrun	9	Nov 17,	SYSTEM	(\$115.00)								



ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
104	0070	TAOK OOAT		Туре			_,		
124	0070	TACK COAT	Overrun			2022			
				Overrun - T	otal			(\$115.00)	
			Overrun - To	tal				(\$115.00)	
	0070 -	Total						(\$115.00)	
	0800	TYPE A2 SHOULDER	Material		8	Nov 2, 2022	SYSTEM	\$21,328.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$21,328.00)	
					9	Nov 17, 2022	SYSTEM	\$21,328.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$21,328.00)	
					10	Dec 2, 2022	SYSTEM	\$21,328.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user bedarl2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$21,328.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0080 -	Total						\$0.00	
	0090	MISC.	Material		8	Nov 2,	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment
	0090	DRAINAGE ITEM	Material			2022			Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$700.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	9	Nov 17, 2022	SYSTEM	(\$700.00)	
				Overrun - T	otal			(\$700.00)	
			Overrun - To	tal				(\$700.00)	
	0090 -	Total						(\$700.00)	
	0120	PAVED APPROACH, 7 IN.	Material		8	Nov 2, 2022	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bedarl2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$7,140.00)	
					9	Nov 17, 2022	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$7,140.00)	
					10	Dec 2, 2022	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$7,140.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	8	Nov 2, 2022	SYSTEM	(\$4,147.40)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				Overrun - T	otal			(\$4,147.40)	
			Overrun - To	otal				(\$4,147.40)	
			Price FUEL		8	Nov 2, 2022	SYSTEM	\$12.76	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$12.76	
			Price FUEL -	Total				\$12.76	
	0120 -	Total						(\$4,134.64)	
	-0120	· otal						(\$4,154.64)	



1445 OLIAD CONCRETE Material Total	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks									
SIDEWALK, 4 IN.				Type			Date	Ву											
	J6I3424	0140		Material		8		SYSTEM	\$57,120.00	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment									
2022 SYSTEM (800,270,000)						8		SYSTEM	(\$57,120.00)										
10						9		SYSTEM	\$60,270.00	Estimate Item Adjustment (0008) due to user bedarl2 overridding Payment									
2022 10 De 0.2 SYSTEM (800.270.00)						9		SYSTEM	(\$60,270.00)										
Total						10		SYSTEM	\$60,270.00	Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment									
Material - Total						10		SYSTEM	(\$60,270.00)										
Second Concept Seco					- Total				\$0.00										
No. 1.00 1				Material - To	tal				\$0.00										
CONCRETE		0140 -	Total						\$0.00										
2022 9		0150	MISC.	Material		8		SYSTEM	\$31,200.00	Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment									
2022 SYSTEM SS0,400.00 This adjustment (0009) due to user bedarf2 overridding Payment Estimate Exception 10 on the current Payment Estimate Payment Estimate Exception 10 on the current Payment Estimate Payment Estimate Exception 10 on the current Payment Estimate Payment Estimate Exception 10 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate Exception 10 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate Exception 10 on the current Payment Estimate Estimate Estimate Exception 10 on the current Payment Estimate Payment Estimate Estimate Exception 10 on the current Payment Estimate Estimate Estimate Exception 10 on the current Payment Estimate Payment Estimate Esti						8		SYSTEM	(\$31,200.00)										
10						9		SYSTEM	\$50,400.00	Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment									
2022 Estimate Item Adjustment (0004) due to user bedart2 overridding Payment Estimate Exception 10 on the current Payment Estimate.						9		SYSTEM	(\$50,400.00)										
10						10		SYSTEM	\$50,400.00	Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment									
Nov 2						10		SYSTEM	(\$50,400.00)										
					- Total				\$0.00										
Nov 2, 2022 SYSTEM S2,714.50 Stimate Exception 19 on the current Payment Estimate Exception 13 on the current Payment Estimate Estimate Item Adjustment (0012) due to user bedari2 overridding Payment Estimate Exception 23 on the current Payment Estimate Estimate Item Adjustment (0012) due to user bedari2 overridding Payment Estimate Item Adjustment (0011) due to user bedari2 overridding Payment Estimate Item Adjustment (0011) due to user bedari2 overridding Payment Estimate Item Adjustment (0011) due to user bedari2 overridding Payment Estimate Item Adjustment (0011) due to user bedari2 overridding Payment Estimate Item Adjustment (0011) due to user bedari2 overridding Payment Estimate Item Adjustment (0011) due to user bedari2 overridding Payment Estimate Item Adjustment (0011) due to user bedari2 overridding Payment Estimate Item Adjustment (0011) due to user bedari2 overridding Payment Estimate Item Adjustment (0011) due to user bedari2 overr				Material - To	tal				\$0.00										
CURB (6 IN. HEIGHT AND UNDER)		0150 -	Total						\$0.00										
8		0160	CURB (6 IN. HEIGHT AND	Material		8		SYSTEM	\$2,714.50	Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment									
System System System Stimate Estimate Estimate Exception 13 on the current Payment Paym			ONDEN			8		SYSTEM	(\$2,714.50)										
2022 10 Dec 2, SYSTEM \$3,827.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. 10 Dec 2, SYSTEM (\$3,827.00) - Total S0.00 Material - Total S0.00 1NTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A 8 Nov 2, 2022 9 Nov 17, SYSTEM \$6,532.00 This adjustment offsets the original system-generated Material Payment Estimate. 10 Dec 2, SYSTEM S6,210.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. 10 Dec 2, SYSTEM S6,210.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. 10 Dec 2, SYSTEM S6,210.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. 10 Dec 2, SYSTEM S6,210.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. 10 Dec 2, SYSTEM S6,210.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate.						9		SYSTEM	\$3,827.00	Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment									
Estimate Item Adjustment (0005) due to user bedarl2 overridding Payment Estimate Exception 13 on the current Payment Estimate. 10 Dec 2, 2022 \$ SYSTEM \$ (\$3,827.00) \$ Naterial - Total \$ 0.00 \$ NATEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A						9		SYSTEM	(\$3,827.00)										
Total So.00 Material - Total So.00 O160 - Total So.00 INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A Nov 2, 2022 SYSTEM \$6,210.00 B Nov 2, 2022 SYSTEM \$6,210.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. Nov 2, 2022 SYSTEM \$6,532.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. Nov 1, 2022 Nov 17, SYSTEM \$6,532.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bedar/2 overridding Payment Estimate Exception 15 on the current Payment Estimate. Nov 1, SYSTEM (\$6,532.00)															10		SYSTEM	\$3,827.00	Estimate Item Adjustment (0005) due to user bedarl2 overridding Payment
Material - Total \$0.00						10		SYSTEM	(\$3,827.00)										
Solution Solution					- Total				\$0.00										
Nov 2, 2022 SYSTEM \$6,210.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Exception 23 on the current Payment Estimate. 8 Nov 2, 2022 SYSTEM (\$6,210.00) 9 Nov 17, 2022 SYSTEM \$6,532.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Exception 15 on the current Payment Estimate.				Material - To	tal				\$0.00										
CURB (OVER 6 IN. HEIGHT) TYPE A 8 Nov 2, 2022 9 Nov 17, 2022 9 Nov 17, SYSTEM (\$6,532.00) 10 Nov 17, SYSTEM (\$6,532.00) 11 Setimate Exception 23 on the current Payment Estimate. 12 Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Exception 23 on the current Payment Estimate. 13 Nov 2, 2022 14 Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Exception 15 on the current Payment Estimate. 15 Nov 17, SYSTEM (\$6,532.00)		0160 -	Total						\$0.00										
8 Nov 2, 2022 SYSTEM (\$6,210.00) 9 Nov 17, 2022 SYSTEM \$6,532.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Exception 15 on the current Payment Estimate. 9 Nov 17, SYSTEM (\$6,532.00)		0170	CURB (OVER 6 IN. HEIGHT)	Material		8		SYSTEM	\$6,210.00	Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment									
Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Exception 15 on the current Payment Estimate. 9 Nov 17, SYSTEM (\$6,532.00)			ITPEA			8		SYSTEM	(\$6,210.00)										
								9		SYSTEM	\$6,532.00	Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment							
						9		SYSTEM	(\$6,532.00)										



at	Line	Description	Adiustosant	Other	Est.	Created	Created	Amazint	Damarka					
ct	Line	Description	Adjustment Type	Adjustment	Number	Created Date	By	Amount	Remarks					
				Туре										
24	0170	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material		10	Dec 2, 2022	SYSTEM	\$6,532.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bedarl2 overridding Payment Estimate Exception 15 on the current Payment Estimate.					
		TIFEA			10	Dec 2, 2022	SYSTEM	(\$6,532.00)						
				- Total				\$0.00						
			Material - Tot	tal				\$0.00						
	0170 -	Total						\$0.00						
	0180	MISC. PAVED DRAINAGE	Material		8	Nov 2, 2022	SYSTEM	\$17,889.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 28 on the current Payment Estimate.					
					8	Nov 2, 2022	SYSTEM	(\$17,889.00)						
					9	Nov 17, 2022	SYSTEM	\$17,889.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Exception 18 on the current Payment Estimate.					
						9	Nov 17, 2022	SYSTEM	(\$17,889.00)					
					10	Dec 2, 2022	SYSTEM	\$17,889.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 18 on the current Payment Estimate.					
					10	Dec 2, 2022	SYSTEM	(\$17,889.00)						
				- Total	tal			\$0.00						
			Material - Tot	tal				\$0.00						
	0180 -	Total						\$0.00						
	0200	MISC. EMBANKMENT PROTECTION	Material		8	Nov 2, 2022	SYSTEM	\$7,357.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bedarl2 overridding Payment Estimate Exception 32 on the current Payment Estimate.					
										8	Nov 2, 2022	SYSTEM	(\$7,357.85)	
							9	Nov 17, 2022	SYSTEM	\$4,154.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user bedarl2 overridding Payment Estimate Exception 21 on the current Payment Estimate.			
					9	Nov 17, 2022	SYSTEM	(\$4,154.00)						
				- Total				\$0.00						
			Material - Tot	tal				\$0.00						
	0200 -	Total						\$0.00						
	0230	SUBGRADE COMPACTION (6 IN. DEPTH)	Material		8	Nov 2, 2022	SYSTEM	\$2,666.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 33 on the current Payment Estimate.					
		(PAVEM			8	Nov 2, 2022	SYSTEM	(\$2,666.00)						
				- Total				\$0.00						
			Material - Tot	tal				\$0.00						
	0230 -	Total						\$0.00						
	0240	MISC.	Material		5	Sep 16, 2022	SYSTEM	\$6,963.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					5	Sep 16, 2022	SYSTEM	(\$6,963.50)						
				- Total				\$0.00						
			Material - Tot	tal				\$0.00						
	0240 -	Total						\$0.00						
	0240 -		Overrun	Overrun	6	Oct 3, 2022	SYSTEM	(\$5,700.00)						
					7	Oct 17, 2022	SYSTEM	\$5,700.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2850.00000 - 2850.00000, 'is applied (if non-zero).					
				Overrun - T	otal			\$0.00						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J6I3424	0250	MISC. TRAFFIC CONTROL DEVICES	Overrun - To	tal				\$0.00									
	0250 -	Total						\$0.00									
	0270	CONCRETE TRAFFIC BARRIER, TYPE	Material		8	Nov 2, 2022	SYSTEM	\$33,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user bedarl2 overridding Payment Estimate Exception 34 on the current Payment Estimate.								
		C (RETAINING WALL)			8	Nov 2, 2022	SYSTEM	(\$33,075.00)									
					9	Nov 17, 2022	SYSTEM	\$33,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 22 on the current Payment Estimate.								
					9	Nov 17, 2022	SYSTEM	(\$33,075.00)									
					10	Dec 2, 2022	SYSTEM	\$33,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user bedarl2 overridding Payment Estimate Exception 21 on the current Payment Estimate.								
					10	Dec 2, 2022	SYSTEM	(\$33,075.00)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	0270 -	Total						\$0.00									
	0290	PREF THERMO PAVMT MARKING, 6 IN	Material		9	Nov 17, 2022	SYSTEM	\$370.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bedarl2 overridding Payment Estimate Exception 26 on the current Payment Estimate.								
		WHITE			9	Nov 17, 2022	SYSTEM	(\$370.00)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	0290 -	Total						\$0.00									
	0300	PREF THERMO PVMT MARK, 24 IN WHIT	Material		7	Oct 17, 2022	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user bedarl2 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
													7	Oct 17, 2022	SYSTEM	(\$2,800.00)	
							8	Nov 2, 2022	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate.						
					8	Nov 2, 2022	SYSTEM	(\$2,800.00)									
					9	Nov 17, 2022	SYSTEM	\$12,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user bedarl2 overridding Payment Estimate Exception 27 on the current Payment Estimate.								
					9	Nov 17, 2022	SYSTEM	(\$12,260.00)									
				- Total				\$0.00									
			Material - Tot	ial				\$0.00									
	0300 -							\$0.00									
	0310	PREF THERMO PVMT MARK, LT/RT ARROW	Material		7	Oct 17, 2022	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user bedarl2 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					7	Oct 17, 2022	SYSTEM	(\$1,500.00)									
					8	Nov 2, 2022	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user bedarl2 overridding Payment Estimate Exception 41 on the current Payment Estimate.								
					8	Nov 2, 2022	SYSTEM	(\$1,500.00)									
					9	Nov 17, 2022	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user bedarl2 overridding Payment Estimate Exception 28 on the current Payment Estimate.								
					9	Nov 17, 2022	SYSTEM	(\$1,500.00)									
				- Total				\$0.00									



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
13424	0310	PREF THERMO PVMT MARK, LT/RT ARROW	Material - To	tal				\$0.00		
	0310 -	Total						\$0.00		
	0320	PREF THERMO PVMT MRKG, STRIAGHT ARROW	Material		7	Oct 17, 2022	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user bedarl2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					7	Oct 17, 2022	SYSTEM	(\$1,200.00)		
					8	Nov 2, 2022	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate.	
					8	Nov 2, 2022	SYSTEM	(\$1,200.00)		
					9	Nov 17, 2022	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
					9	Nov 17, 2022	SYSTEM	(\$1,200.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0320 -	Total						\$0.00		
	0330	PREF THERMO PVMT MARKING,	Material		7	Oct 17, 2022	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user bedarl2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
		COMBO			7	Oct 17, 2022	SYSTEM	(\$1,100.00)		
					8	Nov 2, 2022	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate.	
					8	Nov 2, 2022	SYSTEM	(\$1,100.00)		
							9	Nov 17, 2022	SYSTEM	\$1,100.00
						9	Nov 17, 2022	SYSTEM	(\$1,100.00)	
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0330 -	Total	Material - To	tal						
	0330 - 0340	Total PREF THERMO PVMT MARK, WORD (ONLY)	Material - To	tal	7	Oct 17, 2022	SYSTEM	\$0.00 \$0.00 \$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
,		PREF THERMO PVMT MARK,		tal	7	2022 Oct 17, 2022	SYSTEM	\$0.00 \$0.00 \$550.00 (\$550.00)	Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
		PREF THERMO PVMT MARK,		tal	7 7 8	2022 Oct 17,		\$0.00 \$0.00 \$550.00	Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment	
		PREF THERMO PVMT MARK,		tal	7	2022 Oct 17, 2022 Nov 2,	SYSTEM	\$0.00 \$0.00 \$550.00 (\$550.00)	Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment	
		PREF THERMO PVMT MARK,		tal	7	2022 Oct 17, 2022 Nov 2, 2022 Nov 2,	SYSTEM SYSTEM	\$0.00 \$0.00 \$550.00 (\$550.00)	Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment	
		PREF THERMO PVMT MARK,		tal	7 8	2022 Oct 17, 2022 Nov 2, 2022 Nov 2, 2022 Nov 17,	SYSTEM SYSTEM	\$0.00 \$0.00 \$550.00 (\$550.00) \$550.00	Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment	
		PREF THERMO PVMT MARK,		tal - Total	7 8 8 9	2022 Oct 17, 2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$550.00 (\$550.00) \$550.00 (\$550.00)	Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment	
		PREF THERMO PVMT MARK,		- Total	7 8 8 9	2022 Oct 17, 2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$550.00 (\$550.00) \$550.00 (\$550.00) \$1,100.00	Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment	
		PREF THERMO PVMT MARK, WORD (ONLY)	Material	- Total	7 8 8 9	2022 Oct 17, 2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$550.00 (\$550.00) \$550.00 (\$550.00) \$1,100.00 (\$1,100.00)	Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment	
	0340	PREF THERMO PVMT MARK, WORD (ONLY)	Material	- Total	7 8 8 9	2022 Oct 17, 2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$550.00 (\$550.00) \$550.00 (\$550.00) \$1,100.00 (\$1,100.00)	Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment	
	0340 -	PREF THERMO PVMT MARK, WORD (ONLY) Total PREF THERMO PVMT MARK,	Material - To	- Total	7 8 8 9	2022 Oct 17, 2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$550.00 (\$550.00) \$550.00 (\$550.00) \$1,100.00 \$0.00 \$0.00	Estimate Item Adjustment (0007) due to user bedarl2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 31 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment	



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
13424	0350	PREF THERMO PVMT MARK, 30" WHT MIDBL	Material - Tot	tal				\$0.00	
	0350 -	Total						\$0.00	
	0360	PREF THERMO PVMT MARK, YIELD TRIAN	Material		9	Nov 17, 2022	SYSTEM	\$770.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$770.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0360 -	Total						\$0.00	
	0380	6 IN. WHITE HIGH BUILD WATERBORNE	Material		10	Dec 2, 2022	SYSTEM	\$7,082.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user bedarl2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
		PAINT			10	Dec 2, 2022	SYSTEM	(\$7,082.10)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0380 -	Total						\$0.00	
	0390	6 IN. YELLOW HIGH BUILD WATERBORNE	Material		10	Dec 2, 2022	SYSTEM	\$1,977.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user bedarl2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
		PAINT			10	Dec 2, 2022	SYSTEM	(\$1,977.60)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0390 -	Total						\$0.00	
	0400 W	12 IN. WHITE HIGH BUILD WATERBORNE PAINT			10	Dec 2, 2022	SYSTEM	\$3,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user bedarl2 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$3,575.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0400 -	Total						\$0.00	
	0420	MISC. PAVEMENT MARKINGS	Material		10	Dec 2, 2022	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user bedarl2 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$9,600.00)	
				- Total				\$0.00	
			Material - Tot	Material - Total					
	0420 -	Total						\$0.00	
	0430	MISC. PAVEMENT MARKINGS	Material		9	Nov 17, 2022	SYSTEM	\$8,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user bedarl2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$8,040.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0430 -	Total						\$0.00	
	0470	PERMANENT EROSION CONTROL	Material		8	Nov 2, 2022	SYSTEM	\$925.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user bedarl2 overridding Payment Estimate Exception 45 on the current Payment Estimate.
		GEOTEXTILE			8	Nov 2, 2022	SYSTEM	(\$925.65)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0470 -	Total						\$0.00	
_									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3424	0500	MGS GUARDRAIL	Construction Stockpile		3	Jul 18, 2022	SYSTEM	(\$30,315.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					4	Aug 2, 2022	SYSTEM	(\$7,578.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Nov 2, 2022	SYSTEM	(\$1,768.38)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$39,662.13)	
			Construction	Stockpile - 1	Total			(\$39,662.13)	
			Construction Stockpile STMI		1	Apr 4, 2022	SYSTEM	\$54,567.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$54,567.00	
			Construction	Stockpile S	ΓMI - Tota			\$54,567.00	
	0500 -	Total						\$14,904.87	
	0510	MGS BRIDGE APP. TRANS SEC (EXT	Construction Stockpile		3	Jul 18, 2022	SYSTEM	(\$13,200.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		CURB)			4	Aug 2, 2022	SYSTEM	(\$4,400.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Nov 2, 2022	SYSTEM	(\$6,600.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$24,200.00)	
			Construction	Stockpile - 1				(\$24,200.00)	
			Construction Stockpile STMI		2	Jul 5, 2022	SYSTEM	\$33,000.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$33,000.00	
			Construction	Stockpile S	MI - Tota			\$33,000.00	
	0510 -							\$8,800.00	
	0520	MGS VERTICAL CONCRETE BARRIER TRANSITION	Construction Stockpile		3	Jul 18, 2022	SYSTEM	(\$1,940.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				Total	4	Aug 2, 2022	SYSTEM	(\$1,940.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			0 4 41	- Total				(\$3,880.00)	
			Construction Stockpile STMI	Stockpile - 1			0)/0==1/	(\$3,880.00)	
				Total	2	Jul 5, 2022	SYSTEM	\$3,880.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total Stockpile STMI - Total				\$3,880.00	
	0520-	Total	Construction	Stockpile S	IWII - Tota			\$3,880.00	
	0520 -	MGS END ANCHOR	Construction Stockpile		3	Jul 18, 2022	SYSTEM	\$0.00 (\$2,550.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		22.	, -		8	Nov 2, 2022	SYSTEM	(\$850.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$3,400.00)	
			Construction	Stockpile - 1	Total			(\$3,400.00)	
			Construction Stockpile		1	Apr 4, 2022	SYSTEM	\$4,250.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$4,250.00	
			Construction	Stockpile S	ΓΜΙ - Tota			\$4,250.00	
	0530 -	Total						\$850.00	
	0540	TYPE A CRASHWORTHY	Construction Stockpile		3	Jul 18, 2022	SYSTEM	(\$11,700.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL (MASH)			4	Aug 2, 2022	SYSTEM	(\$3,900.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					9	Nov 17, 2022	SYSTEM	(\$1,950.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$17,550.00)	
			Construction	Stockpile - 1	Total			(\$17,550.00)	
			Construction Stockpile		1	Apr 4, 2022	SYSTEM	\$19,500.00	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J6I3424	0540	TYPE A CRASHWORTHY	STMI	- Total				\$19,500.00					
		END TERMINAL (MASH)	Construction	Stockpile S	TMI - Total			\$19,500.00					
	0540 -	Total						\$1,950.00					
	0550	POST, SIGNAL 8 FT. OR 2.4 M	Material		8	Nov 2, 2022	SYSTEM	\$10,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user bedarl2 overridding Payment Estimate Exception 46 on the current Payment Estimate.				
					8	Nov 2, 2022	SYSTEM	(\$10,450.00)					
					9	Nov 17, 2022	SYSTEM	\$20,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 35 on the current Payment Estimate.				
					9	Nov 17, 2022	SYSTEM	(\$20,900.00)					
					10	Dec 2, 2022	SYSTEM	\$20,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user bedarl2 overridding Payment Estimate Exception 34 on the current Payment Estimate.				
					10	Dec 2, 2022	SYSTEM	(\$20,900.00)					
				- Total				\$0.00					
			Material - Tot					\$0.00					
			Overrun	Overrun	9	Nov 17, 2022	SYSTEM	(\$10,450.00)					
				Overrun - T	otal			(\$10,450.00)					
			Overrun - To	tal				(\$10,450.00)					
	0550 -	Total						(\$10,450.00)					
	0560	VIDEO DETECTION SYSTEM	Material		9	Nov 17, 2022	SYSTEM	\$50,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user bedarl2 overridding Payment Estimate Exception 38 on the current Payment Estimate.				
					9	Nov 17, 2022	SYSTEM	(\$50,000.00)					
					10	Dec 2, 2022	SYSTEM	\$50,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user bedarl2 overridding Payment Estimate Exception 37 on the current Payment Estimate.				
					10	Dec 2, 2022	SYSTEM	(\$50,000.00)					
				- Total				\$0.00					
			Material - Tot	tal				\$0.00					
	0560 -	Total						\$0.00					
	0570	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material	Material	Material		9	Nov 17, 2022	SYSTEM	\$896.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 39 on the current Payment Estimate.		
					9	Nov 17, 2022	SYSTEM	(\$896.00)					
										10	Dec 2, 2022	SYSTEM	\$896.00
					10	Dec 2, 2022	SYSTEM	(\$896.00)					
				- Total				\$0.00					
			Material - Tot	tal				\$0.00					
	0570 -	Total						\$0.00					
	0580	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		9	Nov 17, 2022	SYSTEM	\$5,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate.				
					9	Nov 17, 2022	SYSTEM	(\$5,460.00)					
					10	Dec 2, 2022	SYSTEM	\$5,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user bedarl2 overridding Payment Estimate Exception 39 on the current Payment Estimate.				
					10	Dec 2, 2022	SYSTEM	(\$5,460.00)					



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3424	0580	CONDUIT, 3 IN., PUSHED WITH	Material	- Total				\$0.00	
	TRACER WIRE Material - Total							\$0.00	
	0580 -	Total						\$0.00	
	0590	CABLE, 16 AWG 2 CONDUCTOR	Material		9	Nov 17, 2022	SYSTEM	\$2,454.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$2,454.90)	
					10	Dec 2, 2022	SYSTEM	\$2,454.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user bedarl2 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$2,454.90)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0590 -	Total						\$0.00	
	0600	CABLE, 16 AWG 5 CONDUCTOR	Material		9	Nov 17, 2022	SYSTEM	\$2,927.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$2,927.50)	
					10	Dec 2, 2022	SYSTEM	\$2,927.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user bedarl2 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$2,927.50)	
				- Total				\$0.00	
			Material - To					\$0.00	
			Overrun	Overrun	9	Nov 17, 2022	SYSTEM	(\$2.50)	
				Overrun - T	otal	2022		(\$2.50)	
			Overrun - To	tal				(\$2.50)	
	0600 -	Total						(\$2.50)	
	0610	BASE, CONCRETE					SYSTEM		
	0610		Material		8	Nov 2, 2022	SYSTEM	\$14,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate.
	0610		Material		8		SYSTEM	\$14,880.00 (\$14,880.00)	Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment
	0610		Material			2022 Nov 2,			Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment
	0610		Material		8	2022 Nov 2, 2022 Nov 17,	SYSTEM	(\$14,880.00)	Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bedarl2 overridding Payment
	0610		Material		8	Nov 2, 2022 Nov 17, 2022 Nov 17,	SYSTEM	(\$14,880.00) \$14,880.00	Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bedarl2 overridding Payment
	0610		Material		8 9 9	Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2,	SYSTEM SYSTEM	(\$14,880.00) \$14,880.00 (\$14,880.00)	Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment
	0610		Material	- Total	8 9 9	2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$14,880.00) \$14,880.00 (\$14,880.00) \$14,880.00	Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment
	0610		Material - To		8 9 9	2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$14,880.00) \$14,880.00 (\$14,880.00) \$14,880.00	Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment
	0610	CONCRETE			8 9 9	2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$14,880.00) \$14,880.00 (\$14,880.00) \$14,880.00 (\$14,880.00)	Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment
		CONCRETE			8 9 9	2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$14,880.00) \$14,880.00 (\$14,880.00) \$14,880.00 (\$14,880.00) \$0.00	Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment
	0610 -	CONCRETE	Material - To		9 9 10	2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022 Dec 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$14,880.00) \$14,880.00 (\$14,880.00) \$14,880.00 (\$14,880.00) \$0.00 \$0.00	Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user bedarl2 overridding Payment Estimate Item Adjustment (0033) due to user bedarl2 overridding Payment
	0610 -	CONCRETE	Material - To		9 10 10	2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022 Dec 2, 2022 Nov 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$14,880.00) \$14,880.00 (\$14,880.00) \$14,880.00 (\$14,880.00) \$0.00 \$0.00 \$13,412.00	Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user bedarl2 overridding Payment Estimate Item Adjustment (0033) due to user bedarl2 overridding Payment
	0610 -	CONCRETE	Material - To		9 10 10 9 9	2022 Nov 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022 Nov 17, 2022 Nov 17, 2022 Dec 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$14,880.00) \$14,880.00 (\$14,880.00) \$14,880.00 (\$14,880.00) \$0.00 \$0.00 \$13,412.00	Estimate Item Adjustment (0027) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bedarl2 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user bedarl2 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment Estimate Item Adjustment (0020) due to user bedarl2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J6I3424	0630	MISC.	Material - Tot	tal				\$0.00					
	0630 -	Total						\$0.00					
	0640	MISC.	Material		9	Nov 17, 2022	SYSTEM	\$6,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate.				
					9	Nov 17, 2022	SYSTEM	(\$6,580.00)					
					10	Dec 2, 2022	SYSTEM	\$6,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user bedarl2 overridding Payment Estimate Exception 48 on the current Payment Estimate.				
					10	Dec 2, 2022	SYSTEM	(\$6,580.00)					
				- Total				\$0.00					
			Material - Tot	tal				\$0.00					
	0640 -	Total						\$0.00					
	0650	MISC.	Material		9	Nov 17, 2022	SYSTEM	\$204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user bedarl2 overridding Payment Estimate Exception 50 on the current Payment Estimate.				
					9	Nov 17, 2022	SYSTEM	(\$204.00)					
					10	Dec 2, 2022	SYSTEM	\$204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user bedarl2 overridding Payment Estimate Exception 49 on the current Payment Estimate.				
					10	Dec 2, 2022	SYSTEM	(\$204.00)					
				- Total				\$0.00					
			Material - Tot	tal				\$0.00					
	0650 -	Total						\$0.00					
	0660	CONCRETE FOOTINGS, EMBEDDED	Material		9	Nov 17, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user bedarl2 overridding Payment Estimate Exception 51 on the current Payment Estimate.				
					9	Nov 17, 2022	SYSTEM	(\$600.00)					
					10	Dec 2, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user bedarl2 overridding Payment Estimate Exception 50 on the current Payment Estimate.				
					10	Dec 2, 2022	SYSTEM	(\$600.00)					
				- Total				\$0.00					
			Material - Tot	tal				\$0.00					
	0660 -	Total						\$0.00					
	0670	PIPE POSTS	Material		8	Nov 2, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate.				
									8	Nov 2, 2022	SYSTEM	(\$700.00)	
							9	Nov 17, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate.		
					9	Nov 17, 2022	SYSTEM	(\$700.00)					
					10	Dec 2, 2022	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user bedarl2 overridding Payment Estimate Exception 53 on the current Payment Estimate.				
					10	Dec 2, 2022	SYSTEM	(\$700.00)					
				- Total				\$0.00					
			Material - Tot	tal				\$0.00					
	0670 -	Total						\$0.00					
	0680	2 IN. PSST POST - 12 GA.	Material		8	Nov 2, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate.				

Dec 6, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J6I3424	0680	2 IN. PSST POST - 12 GA.	Material		8	Nov 2, 2022	SYSTEM	(\$400.00)								
					9	Nov 17, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate.							
					9	Nov 17, 2022	SYSTEM	(\$400.00)								
					10	Dec 2, 2022	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user bedarl2 overridding Payment Estimate Exception 54 on the current Payment Estimate.							
					10	Dec 2, 2022	SYSTEM	(\$400.00)								
				- Total				\$0.00								
			Material - Tot	tal				\$0.00								
	0680 -							\$0.00								
	0690	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		8	Nov 2, 2022	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user bedarl2 overridding Payment Estimate Exception 56 on the current Payment Estimate.							
					8	Nov 2, 2022	SYSTEM	(\$180.00)								
					9	Nov 17, 2022	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user bedarl2 overridding Payment Estimate Exception 56 on the current Payment Estimate.							
					9	Nov 17, 2022	SYSTEM	(\$180.00)								
												10	Dec 2, 2022	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user bedarl2 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					10	Dec 2, 2022	SYSTEM	(\$180.00)								
				- Total				\$0.00								
			Material - Tot	tal				\$0.00								
	0690 -	Total						\$0.00								
613424 -	Total							\$154,062.43								
)verall -	Total						\$154,062.43									