

Pay Estimate Created Date: October 3, 2022

Progress Estimate Number 7		Contract ID Prime Contractor	220318-B01 Emery Sapp & Sons, Inc.				Original Contract Amount Net Change Order Amount Current Contract Amount	t \$0.00
Approval Date								By User
October 3, 2022			Generated and App	roved (and should b	e considered D	raft) at	the Project Office Level by	gardb1
October 4, 2022			Reviewed and Approved	d (and should be cor	nsidered Draft)	at the F	Resident Engineer Level by	lincom
October 4, 2022			Rev	viewed and Approve	d at the Central	Office	Controllers Office Level by	ramses1
Original Comp	letion Date	etion Date Current Completion Date Actual Completion Date % of Current Contract Am						
December	1, 2022	per 1, 2022				82.59%		
,						,,		

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	April 6, 2022	April 6, 2022	
Letting Date	March 18, 2022	March 18, 2022	
Notice to Proceed Date	June 6, 2022	June 6, 2022	
Open to Traffic Date			
Work Began Date			

Contract Total Pa	y For Estimate No. 7			
		This Estimate	Previous	To Date
220318-B01				
	Total Posted Items Pay	\$193,006.20	\$3,208,176.61	\$3,401,182.81
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	,		\$3,208,176.61	\$3,401,182.81
<b>Contract Total Pa</b>	yable This Estimate:	\$193,006.20		

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J2P3156	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$44,000.000	0.2	\$8,800.00
	0070	2063300	CLASS 4 EXCAVATION	CUYD	\$17.000	108	\$1,836.00
	0090	3030600	FURNISHING ROCK BASE MATERIAL	SQYD	\$17.100	1,564	\$26,744.40
	0100	3030610A	PLACING ROCK BASE	SQYD	\$7.250	1,564	\$11,339.00
	0110	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$9.150	291	\$2,662.65
	0120	3049905	MISC.Rigid Geogrid to Enhance Aggregate or Rock Base	SQYD	\$2.850	1,564	\$4,457.40
	0130	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$49.000	24	\$1,176.00
	0150	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	SQYD	\$92.000	732	\$67,344.00
	0170	6059903	MISC.FRENCH DRAIN	LF	\$22.000	377	\$8,294.00
	0280	6122030	IMPACT ATTENUATOR (RELOCATION)	EA	\$750.000	2	\$1,500.00
	0320	6161030	TYPE III MOVEABLE BARRICADE	EA	\$125.000	6	\$750.00
	0350	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	LF	\$20.000	550	\$11,000.00
	0370	6173706	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION, CONTRACTOR FURNISHED / RETAINED	LF	\$36.000	425.5	\$15,318.00
	0380	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	LF	\$12.000	925	\$11,100.00
	0470	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.750	1,664	\$1,248.00
	0480	6205903A	$6\mbox{IN.}$ YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.750	2,182	\$1,636.50
	0490	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$2.500	30	\$75.00

Revision 4/1/2020 Page 1 of 25



Pay Estimate Created Date: October 3, 2022

					Original Contract Amount	
7	Prime Contractor	Emery Sapp & Sons, Inc.	Pay Period End	September 30, 2022	Net Change Order Amount	\$0.00
,					<b>Current Contract Amount</b>	\$4,117,988.35

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J2P3156	0500	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.500	2,762	\$1,381.00
	0520	6240104A	SEPARATION GEOTEXTILE	SQYD	\$2.750	1,563	\$4,298.25
	0530	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$29,000.000	0.25	\$7,250.00
	0640	8051000A	SEEDING - COOL SEASON GRASSES	ACRE	\$2,450.000	1.6	\$3,920.00
	0650	8061004	SEDIMENT TRAP ROCK	CUYD	\$70.000	0.8	\$56.00
	0680	8061017	TEMPORARY SEEDING	ACRE	\$2,050.000	0.4	\$820.00
Project J2	2P3156 - T	otal					\$193,006.20
Overall - 1	Total						\$193,006,20

#### Contract Adjustments This Estimate

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
156	0040	EMBANKMENT IN PLACE	MaterialCredit	31		4,332	\$15.10	\$65,413.20
	0040	EMBANKMENT IN PLACE	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$65,413.20
	0050	COMPACTING EMBANKMENT	MaterialCredit			8,983	\$3.70	\$33,237.10
	0050	COMPACTING EMBANKMENT	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$33,237.10
	0800	SUBGRADE COMPACTION (6-INCH DEPTH)	MaterialCredit			33.7	\$720.00	\$24,264.00
	0800	SUBGRADE COMPACTION (6-INCH DEPTH)	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$24,264.00
	0110	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	MaterialCredit			2,459	\$9.15	\$22,499.85
	0110	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$22,499.85
	0120	MISC.	MaterialCredit			13,424	\$2.85	\$38,258.40
	0120	MISC.	Material			-12,988	\$2.85	(\$37,015.80
	0120	MISC.	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$1,242.60
	0150	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	MaterialCredit			12,553	\$92.00	\$1,154,876.00
	0150	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Material			-13,285	\$92.00	(\$1,222,220.00
	0150	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Other Item Adjustment	Material Discrepancy Payment Adjustment				\$67,344.00
	0180	6 IN. CONCRETE MEDIAN STRIP	MaterialCredit			854.9	\$82.00	\$70,101.80
	0180	6 IN. CONCRETE MEDIAN	Material			-854.9	\$82.00	(\$70,101.80

Page 2 of 25 Revision 4/1/2020



Pay Estimate Created Date: October 3, 2022

Progress Estimate Number	Contract ID				Original Contract Amount	
7	Prime Contractor	Emery Sapp & Sons, Inc.	Pay Period End	September 30, 2022	Net Change Order Amount	\$0.00
•					Current Contract Amount	\$4,117,988.35

t	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
er	No.	item Description	Туре	Adjustment Type	Confinents	Quantity	Adjustment Unit Price	amount
6		STRIP						
	0190	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	MaterialCredit			377	\$52.00	\$19,604.00
	0190	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-377	\$52.00	(\$19,604.00)
	0200	CONCRETE CURB LOW PROFILE TYPE F	MaterialCredit			452	\$28.00	\$12,656.00
	0200	CONCRETE CURB LOW PROFILE TYPE F	Material			-452	\$28.00	(\$12,656.00
	0220	FURNISHING TYPE 2 ROCK DITCH LINER	MaterialCredit			695	\$53.00	\$36,835.00
	0220	FURNISHING TYPE 2 ROCK DITCH LINER	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$36,835.00)
	0250	ROCK LINING	MaterialCredit			84	\$97.00	\$8,148.00
	0250	ROCK LINING	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$8,148.00)
	0260	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	MaterialCredit			8	\$2,100.00	\$16,800.00
	0260	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$16,800.00)
	0340	TEMPORARY LONG-TERM RUMBLE STRIPS	MaterialCredit			6	\$1,000.00	\$6,000.00
	0340	TEMPORARY LONG-TERM RUMBLE STRIPS	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$6,000.00)
	0350	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	MaterialCredit			625	\$20.00	\$12,500.00
	0350	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$12,500.00)
	0360	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	MaterialCredit			737.5	\$36.00	\$26,550.00
	0360	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	Other Item Adjustment					(\$26,550.00)
	0440	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	MaterialCredit			3,146	\$1.35	\$4,247.10
	0440	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Other Item Adjustment					(\$4,247.10)
	0450	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	MaterialCredit			2,541	\$1.35	\$3,430.35

Revision 4/1/2020 Page 3 of 25



Pay Estimate Created Date: October 3, 2022

Pı	rogre	ss Est	imate Number 7	Contract ID Prime Contrac	220318- tor Emery S			September 16, 2022 September 30, 2022		der Amount		
Proj	ect	Line	Item Descr	ription A	Adjustment	Other Item	Cor	mments	Adjustment	Line Item	Adjustment	

					- Juli	rrent Contra	ot Amount	\$4,117,900.33
ject nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3156	0450	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$3,430.35
	0460	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	MaterialCredit			5,293	\$0.75	\$3,969.75
	0460	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-5,293	\$0.75	(\$3,969.7
	0470	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-1,664	\$0.75	(\$1,248.0
	0470	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Other Item Adjustment	Material Discrepancy Payment Adjustment				\$1,248.0
	0480	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-2,182	\$0.75	(\$1,636.5
	0480	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Other Item Adjustment	Material Discrepancy Payment Adjustment				\$1,636.5
	0490	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-30	\$2.50	(\$75.0
	0490	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Other Item Adjustment	Material Discrepancy Payment Adjustment				\$75.0
	0510	PERMANENT EROSION CONTROL GEOTEXTILE	MaterialCredit			2,246	\$3.55	\$7,973.3
	0510	PERMANENT EROSION CONTROL GEOTEXTILE	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$7,973.30
	0520	SEPARATION GEOTEXTILE	MaterialCredit			13,424	\$2.75	\$36,916.00
	0520	SEPARATION GEOTEXTILE	Other Item Adjustment	Material Discrepancy Payment Adjustment				(\$36,916.00
	0560	18 IN. PIPE GROUP C	MaterialCredit			36	\$65.00	\$2,340.00
	0560	18 IN. PIPE GROUP C	Material			-36	\$65.00	(\$2,340.00
	0640	SEEDING - COOL SEASON GRASSES	Material			-1.6	\$2,450.00	(\$3,920.00
	0640	SEEDING - COOL SEASON GRASSES	Other Item Adjustment	Material Discrepancy Payment Adjustment				\$3,920.00
	0820	CONCRETE FOOTINGS, EMBEDDED	MaterialCredit			2.04	\$775.00	\$1,581.00
	0820	CONCRETE FOOTINGS, EMBEDDED	Material			-2.04	\$775.00	(\$1,581.00
	0900	SH-FLAT SHEET	MaterialCredit			252.75	\$24.25	\$6,129.19

Revision 4/1/2020 Page 4 of 25



Pay Estimate Created Date: October 3, 2022

Progr	ess Est	imate Number 7	Contract ID Prime Contr		B01 app & Sons, Inc.		September 16, 2022 September 30, 2022		rder Amount	\$4,117,988.35 \$0.00 \$4,117,988.35
Project Number	Line No.	Item Descr	ription	Adjustment Type	Other Item Adjustment Type	Cor	mments	Adjustmer Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2P3156	0900	SH-F	LAT SHEET	Other Item Adjustment	Material Discrepancy Payment Adjustment					(\$6,129.19)
	0920		LAT SHEET ORESCENT	MaterialCredit				5	\$28.15	\$1,604.55
	0920		LAT SHEET ORESCENT	Other Item Adjustment	Material Discrepancy Payment Adjustment					(\$1,604.55)
Total										\$0.00

Revision 4/1/2020 Page 5 of 25



					(	Contract Project Information		
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work	
J2P3156	FAF 54-4(65)	Grading, paving, and drainage to construct roundabout	54	AUDRAIN	at Rte. 19 junction north o	f Laddonia		
otals by	Job Numbe	ers						
J2P3156					This Estimate	Previous	To Date	1
		ed Item Pay s Item Adjustn		s Item Pay	\$193,006.20 \$0.00 <b>\$193,006.20</b>	\$3,208,176.61 \$0.00 <b>\$3,208,176.61</b>	\$3,401,182.81 \$0.00 <b>\$3,401,182.81</b>	
	Incen	tive			\$0.00	\$0.00	\$0.00	
		centive			\$0.00	\$0.00	\$0.00	
	Liqui	dated Damage	s		\$0.00	\$0.00	\$0.00	
		Contract Adia	4 4 -	_	\$0.00	\$0.00	\$0.00	

Revision 4/1/2020 Page 6 of 25



#### **Exceptions (Discrepancies) This Estimate Period**

Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 3049905, Project Item Line Number 0120, Material Set 304990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 100510CPCMLD - PCCP or Masonry 1" Max Ls/DO, Acceptance Action Generic 100510CPCMLD - PCCP or Masonry 1" Max Ls/DO, Acceptance Action Generic 1055CMMLDST2 : White Pavement-Bridge Dissipating Cure @. Acceptance Action Generic 1055CMMLDST2 is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 1055JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@. Acceptance Action Generic ReinforcingMisc is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 1055CMMLDST10 - Clear Pavement-Bridge Dissipating Cure @. Acceptance Action Generic 100510CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 1055CMMLDST10 is insufficient.  Estimate Excepti
Number 0120, Material Set 30490596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 100510. CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510. CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 100510. CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510. CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 100510. CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.
Number 0150, Material Set 502130996, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 1055TJMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.
Number 0150, Material Set 502130996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic Reinforcing/Misc is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.
Number 0150, Material Set 502130996, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 5021309, Project Item Line Number 0150, Material Set 502130996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.  PAL reporting Needed  QC/QA test have been submitted for review.  PAL reporting needed.  gardb1 Acknow Packet Action Generic 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.
Number 0150, Material Set 502130996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 10055CMMLDST1D is insufficient.
Number 0180, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.
Number 0180, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.
Estimate Expension Type: Inquifficient Materials: Broiset 12D2156, Item 6092006, Broiset Item Line OC/OA test boys been submitted for review
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6083006, Project Item Line Number 0180, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.  GC/QA test have been submitted for review.  GC/QA test have been submitted for review.  GRACH STATE OF THE STATE OF TH
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6091010, Project Item Line Number 0190, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.  QC/QA test have been submitted for review.  gardb1  Acknowledge Ackno
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6091010, Project Item Line Number 0190, Material Set 609101096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.  PAL reporting needed.  gardb1  Acknowledge Acceptance Action Generic 1055CMMLDST2 is insufficient.
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6091010, Project Item Line Number 0190, Material Set 609101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.  QC/QA test have been submitted for review.  gardb1  Acknowledge Ack
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6091010, Project Item Line Number 0190, Material Set 609101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.  QC/QA test have been submitted for review.  gardb1  Acknowledge Ackn
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6092032, Project Item Line Number 0200, Material Set 609203296, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.  PAL reporting needed.  gardb1  Acknowledge Action Generic 1055CMMLDST2 is insufficient.
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6092032, Project Item Line Number 0200, Material Set 609203296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.  QC/QA test have been submitted for review.  gardb1  Acknowledge Ackn
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6092032, Project Item Line Number 0200, Material Set 609203296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.  QC/QA test have been submitted for review.  gardb1  Acknowledge  A
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6205901A, Project Item Line Number 0460, Material Set 6205901A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.  Certs submitted  gardb1  Acknowledge  Ack
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6205901A, Project Item Line Number 0460, Material Set 6205901A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.  Certs needed for Type L Beads  gardb1  Acknowledge Action Generic 1048PMRBEMTL is insufficient.
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6205902A, Project Item Line Number 0470, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.  Certs have been submitted.  gardb1  Acknowledge  Acknowledge  Acknowledge  Acknowledge  Acknowledge  Bardb1  Acknowledge  Acknowledge  Acknowledge  Bardb1  Acknowledge  Acknowledge  Bardb1  Acknowledge  Acknowledge  Bardb1  Acknowledge  Acknowledge  Bardb1  Acknowledge  B
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6205902A, Project Item Line Number 0470, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.  Certs needed for Type L Beads  gardb1  Acknowledge Action Generic 1048PMRBEMTL is insufficient.
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6205903A, Project Item Line Number 0480, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.  Certs have been submitted.  gardb1  Acknow
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6205903A, Project Item Line Number 0480, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.  Certs needed for Type L Beads  gardb1  Acknowledge Action Generic 1048PMRBEMTL is insufficient.
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6205906A, Project Item Line Number 0490, Material Set 6205906A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.  Certs needed for Type L Beads  gardb1  Acknowledge Action Generic 1048PMRBEMTL is insufficient.
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 6205906A, Project Item Line Number 0490, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.  Certs have been submitted  gardb1  Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 7250418, Project Item Line Number 0560, Material Set 725041896, Material 1020CPCSZC.018 - CulvPipe Zn Ctd Corrug Stl 18"  PAL reporting needed.  gardb1  Acknowledge  Acknowledge  Acknowledge  Acknowledge  Acknowledge  PAL reporting needed.

Revision 4/1/2020 Page 7 of 25



#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
450mm, Acceptance Action Generic 1020CPCSZC.018 is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 8051000A, Project Item Line Number 0640, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.	Certs have been submitted.	gardb1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 9031010, Project Item Line Number 0820, Material Set 903101096, Material 0501CCCOM - Concrete, Commercial, Acceptance Action Generic 0501CCCOM is insufficient.	QA concrete report needed.	gardb1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2P3156, Item 9031010, Project Item Line Number 0820, Material Set 903101096, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient.	QA concrete report needed.	gardb1	Acknowledged

Revision 4/1/2020 Page 8 of 25



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220318-B01	J2P3156	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.90	\$44,000.00	\$39,600.00
		0001	0020	2027000	DISPOSAL AND PLUGGING OF WELLS	1.00	0.00	1.00	EA	1.00	\$4,000.00	\$4,000.00
		0001	0030	2031000	CLASS A EXCAVATION	16,003.00	0.00	16,003.00	CUYD	15,933.00	\$13.00	\$207,129.00
		0001	0040	2035500	EMBANKMENT IN PLACE	4,332.00	0.00	4,332.00	CUYD	4,332.00	\$15.10	\$65,413.20
		0001	0050	2036000	COMPACTING EMBANKMENT	9,043.00	0.00	9,043.00	CUYD	8,983.00	\$3.70	\$33,237.10
		0001	0060	2063000	CLASS 3 EXCAVATION	294.00	0.00	294.00	CUYD	294.00	\$11.50	\$3,381.00
		0001	0070	2063300	CLASS 4 EXCAVATION	408.00	0.00	408.00	CUYD	408.00	\$17.00	\$6,936.00
		0001	0800	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	37.00	0.00	37.00	100F	33.70	\$720.00	\$24,264.00
		0001	0090	3030600	FURNISHING ROCK BASE MATERIAL	16,551.00	0.00	16,551.00	SQYD	14,988.00	\$17.10	\$256,294.8
		0001	0100	3030610A	PLACING ROCK BASE	16,551.00	0.00	16,551.00	SQYD	14,988.00	\$7.25	\$108,663.0
		0001	0110	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	2,750.00	0.00	2,750.00	SQYD	2,750.00	\$9.15	\$25,162.5
		0001	0120	3049905	MISC.Rigid Geogrid to Enhance Aggregate or Rock Base	16,551.00	0.00	16,551.00	SQYD	14,988.00	\$2.85	\$42,715.8
		0001	0130	3105002	GRAVEL (A) OR CRUSHED STONE (B)	52.00	0.00	52.00	TONS	24.00	\$49.00	\$1,176.0
		0001	0140	4019905	MISC.OPTIONAL PAVEMENT, TEMPORARY WIDENING	2,750.00	0.00	2,750.00	SQYD	2,459.00	\$76.15	\$187,252.8
		0001	0150	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	16,551.00	0.00	16,551.00	SQYD	13,285.00	\$92.00	\$1,222,220.0
		0001	0160	6039931	GAS	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.0
		0001	0170	6059903	MISC.FRENCH DRAIN	377.00	0.00	377.00	LF	377.00	\$22.00	\$8,294.0
		0001	0180	6083006	6 IN. CONCRETE MEDIAN STRIP	1,079.10	0.00	1,079.10	SQYD	854.90	\$82.00	\$70,101.8
		0001	0190	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	377.00	0.00	377.00	LF	377.00	\$52.00	\$19,604.0
		0001	0200	6092032	CONCRETE CURB LOW PROFILE TYPE F	452.00	0.00	452.00	LF	452.00	\$28.00	\$12,656.0
		0001	0210	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	335.00	0.00	335.00	CUYD	0.00	\$43.00	\$0.0
		0001	0220	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	695.00	0.00	695.00	CUYD	695.00	\$53.00	\$36,835.0
		0001	0230	6096041	PLACING TYPE 1 ROCK DITCH LINER	335.00	0.00	335.00	CUYD	0.00	\$22.00	\$0.0
		0001	0240	6096042	PLACING TYPE 2 ROCK DITCH LINER	665.00	0.00	665.00	CUYD	665.00	\$22.00	\$14,630.0
		0001	0250	6097000	ROCK LINING	128.00	0.00	128.00	CUYD	84.00	\$97.00	\$8,148.0
		0001	0260	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	8.00	0.00	8.00	EA	8.00	\$2,100.00	\$16,800.0
		0001	0270	6122020	REPLACEMENT SAND BARREL	4.00	0.00	4.00	EA	0.00	\$150.00	\$0.0
		0001	0280	6122030	IMPACT ATTENUATOR (RELOCATION)	8.00	0.00	8.00	EA	5.00	\$750.00	\$3,750.0
		0001	0290	6161005	CONSTRUCTION SIGNS	1,513.00	0.00	1,513.00	SQFT	1,267.00	\$7.00	\$8,869.0
		0001	0300	6161008	ADVANCED WARNING RAIL SYSTEM	7.00	0.00	7.00	EA	7.00	\$40.00	\$280.0
		0001	0310	6161025	CHANNELIZER (TRIM LINE)	351.00	0.00	351.00	EA	351.00	\$10.00	\$3,510.0
		0001	0320	6161030	TYPE III MOVEABLE BARRICADE	23.00	0.00	23.00	EA	20.00	\$125.00	\$2,500.0
		0001	0330	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,700.00	\$18,800.0
		0001	0340	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	6.00	0.00	6.00	EA	6.00	\$1,000.00	\$6,000.0
		0001	0350	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,175.00	0.00	1,175.00	LF	1,175.00	\$20.00	\$23,500.0
		0001	0360	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	1,050.00	0.00	1,050.00	LF	737.50	\$36.00	\$26,550.0
		0001	0370	6173706	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION, CONTRACTOR FURNISHED / RETAINED	1,488.00	0.00	1,488.00	LF	1,488.00	\$36.00	\$53,568.0
		0001	0380	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,025.00	0.00	1,025.00	LF	1,025.00	\$12.00	\$12,300.0
		0001	0390	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	463.00	0.00	463.00	LF	0.00	\$28.00	\$0.0
		0001	0400	6175013	RELOCATING TEMPORARY TRAFFIC BARRIER STIFFNESS	213.00	0.00	213.00	LF	0.00	\$28.00	\$0.0
		0001	0410	6181000	TRANSITION SECTION  MOBILIZATION	1.00	0.00	1.00	LS	1 00	\$268,000.00	\$268,000.0
		0001	0420	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$200,000.0
		0001	0420	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	133.00	0.00	133.00	LF	0.00	\$24.00	\$0.0
		0001		0200010	YELLOW	133.00		133.00		0.00	φ24.00	φυ.υ
		0001	0440	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	12,251.00	0.00	12,251.00	LF	3,146.00	\$1.35	\$4,247.1

Revision 4/1/2020 Page 9 of 25



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
20318-B01	J2P3156	0001	0450	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	13,062.00	0.00	13,062.00	LF	2,541.00	\$1.35	\$3,430.3
		0001	0460	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,313.00	0.00	7,313.00	LF	5,293.00	\$0.75	\$3,969.7
		0001	0470	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	6,510.00	0.00	6,510.00	LF	1,664.00	\$0.75	\$1,248.0
		0001	0480	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,894.00	0.00	2,894.00	LF	2,182.00	\$0.75	\$1,636.5
		0001	0490	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	47.00	0.00	47.00	LF	30.00	\$2.50	\$75.0
		0001	0500	6207001	PAVEMENT MARKING REMOVAL	25,313.00	0.00	25,313.00	LF	9,003.00	\$0.50	\$4,501.5
		0001	0510	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	3,894.00	0.00	3,894.00	SQYD	2,246.00	\$3.55	\$7,973.3
		0001	0520	6240104A	SEPARATION GEOTEXTILE	16,551.00	0.00	16,551.00	SQYD	14,987.00	\$2.75	\$41,214.2
		0001	0530	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.85	\$29,000.00	\$24,650.0
		0001	0540	7034041	CLASS B-1 CONCRETE (CULVERTS)	208.10	0.00	208.10	CUYD	167.00	\$575.00	\$96,025.0
		0001	0550	7061030	REINFORCING STEEL (CULVERTS)	31,800.00	0.00	31,800.00	LB	25,440.00	\$1.00	\$25,440.0
		0001	0560	7250418	18 IN. PIPE GROUP C	36.00	0.00	36.00	LF	36.00	\$65.00	\$2,340.0
		0001	0570	7261048	48 IN. PIPE GROUP A	78.00	0.00	78.00	LF	78.00	\$155.00	\$12,090.0
		0001	0580	7265024	JACKED 24 IN. CLASS III REINFORCED CONCRETE PIPE CULVERTS (GASKET TYPE)	101.00	0.00	101.00	LF	101.00	\$1,100.00	\$111,100.0
		0001	0590	7265030	JACKED 30 IN. CLASS III REINFORCED CONCRETE PIPE CULVERTS (GASKET TYPE)	148.00	0.00	148.00	LF	148.00	\$1,145.00	\$169,460.0
		0001	0600	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$985.00	\$1,970.0
		0001	0610	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	4.00	0.00	4.00	EA	2.00	\$1,500.00	\$3,000.0
		0001	0620	7320818A	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$365.00	\$730.0
		0001	0630	7321020A	48 IN. OR ALLOWED SUBSTITUTE SAFETY SLOPE END SECTION	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.0
		0001	0640	8051000A	SEEDING - COOL SEASON GRASSES	8.00	0.00	8.00	ACRE	1.60	\$2,450.00	\$3,920.0
		0001	0650	8061004	SEDIMENT TRAP ROCK	10.80	0.00	10.80	CUYD	0.80	\$70.00	\$56.0
		0001	0660	8061005	ROCK DITCH CHECK	589.00	0.00	589.00	LF	171.00	\$11.50	\$1,966.5
		0001	0670	8061016	SEDIMENT REMOVAL	55.00	0.00	55.00	CUYD	0.00	\$35.00	\$0.0
		0001	0680	8061017	TEMPORARY SEEDING	4.00	0.00	4.00	ACRE	0.40	\$2,050.00	\$820.0
		0001	0690	8061019	SILT FENCE	400.00	0.00	400.00	LF	0.00	\$2.60	\$0.0
		0020	0700	7032002	CLASS B CONCRETE (MISC)	2.10	0.00	2.10	CUYD	0.00	\$2,300.00	\$0.0
		0020	0710	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	0.00	\$7,360.00	\$0.0
		0020	0720	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	232.00	0.00	232.00	LF	212.00	\$13.00	\$2,756.0
		0020	0730	9015010	TRENCHING TYPE I	1,620.00	0.00	1,620.00	LF	402.00	\$4.50	\$1,809.0
		0020	0740	9016110	PULL BOX, PREFORMED CLASS 1	6.00	0.00	6.00	EA	1.00	\$1,160.00	\$1,160.0
		0020	0750	9017002	CABLE, 2 AWG 1 CONDUCTOR	60.00	0.00	60.00	LF	0.00	\$4.50	\$0.0
		0020	0760	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	800.00	0.00	800.00	LF	0.00	\$1.00	\$0.0
		0020	0770	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	2,250.00	0.00	2,250.00	LF	0.00	\$4.70	\$0.0
		0020	0780	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	8.00	0.00	8.00	EA	2.00	\$1,894.00	\$3,788.0
		0020	0790	9018610	POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE, LIGHTING ONLY	1.00	0.00	1.00	EA	0.00	\$2,000.00	\$0.0
		0020	0800	9019902	MISC.Top Mount Light Pole, 45 FT	8.00	0.00	8.00	EA	0.00	\$3,548.00	\$0.0
		0020	0810	9019902	MISC.Top Mounted LED-C Luminaire	8.00	0.00	8.00	EA	0.00	\$600.00	\$0.0
		0040	0820	9031010	CONCRETE FOOTINGS, EMBEDDED	8.00	0.00	8.00	CUYD	2.04	\$775.00	\$1,581.0
		0040	0830	9031210	STRUCTURAL STEEL POSTS	1,950.00	0.00	1,950.00	LB	348.75	\$9.05	\$3,156.1
		0040	0840	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL	2.00	0.00	2.00	EA	0.00	\$1,085.00	\$0.0
			0850	9031242	TUBE) 36 IN. SURFACE-MOUNT DELINEATOR POST	32.00	0.00	32.00	EA	24.00	\$101.00	\$2,424.0
		0040	0860	9031242 9031270A	2 IN. PSST POST - 12 GA.	483.00	0.00	483.00	LF	228.50	\$101.00	\$4,455.7
		0040	0870	9031270A	POST ANCHOR FOR 2 IN. PSST - 12 GA.	114.00	0.00	114.00	LF	57.00	\$55.10	\$3,140.7

Revision 4/1/2020 Page 10 of 25



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220318-B01	J2P3156	0040	0880	9031280	2.5 IN. PSST POST - 12 GA.	198.00	0.00	198.00	LF	92.50	\$22.25	\$2,058.12
		0040	0890	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	39.00	0.00	39.00	LF	18.00	\$62.00	\$1,116.00
		0040	0900	9035004A	SH-FLAT SHEET	430.00	0.00	430.00	SQFT	252.75	\$24.25	\$6,129.19
		0040	0910	9035011A	ST-STRUCTURAL	168.00	0.00	168.00	SQFT	0.00	\$45.00	\$0.00
		0040	0920	9035069A	SHF-FLAT SHEET FLUORESCENT	100.00	0.00	100.00	SQFT	57.00	\$28.15	\$1,604.55
Project J2P3156 - Total Value Posted to Date as of Report Generated Date										\$3,401,182.80		
220318-B01 Overall - Total Value Posted to Date as of Report Generated Date										\$3,401,182.80		

Revision 4/1/2020 Page 11 of 25



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J2P3156

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	9/30/22	10/3/22	0.20	LS		876+00				
0070	2063300	CLASS 4 EXCAVATION	9/30/22	10/3/22	108.00	CUYD		8+52				
0090	3030600	FURNISHING ROCK BASE MATERIAL	9/30/22	10/3/22	1,564.00	SQYD		876+00				
0100	3030610A	PLACING ROCK BASE	9/30/22	10/3/22	1,564.00	SQYD		876+00				
0110	3040504	TYPE 5 AGGREGATE FOR BASE	9/30/22	10/3/22	291.00	SQYD	Stage 5	876+00				
0120	3049905	MISC. AGGREGATE FOR BASE	9/30/22	10/3/22	1,564.00	SQYD		876+00				
0130	3105002	GRAVEL (A) OR CRUSHED STONE (B)	9/30/22	10/3/22	24.00	TONS	Rte 54/19 PE	10+29				
0150	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED,	9/30/22	10/3/22	732.00	SQYD		876+00				
0170	6059903	MISC. UNDERDRAINAGE	9/30/22	10/3/22	377.00	LF		876+00				
0280	6122030	IMPACT ATTENUATOR (RELOCATION)	9/30/22	10/3/22	2.00	EA		876+00				
0320	6161030	TYPE III MOVEABLE BARRICADE	9/30/22	10/3/22	6.00	EA		876+00				
0350	6173600D	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	9/30/22	10/3/22	550.00	LF	Stage 5	876+00				
0370	6173706	TEMP. TRAF. BARR. STIFF. TRNS. SEC, CONT	9/30/22	10/3/22	425.50	LF	Stage 5 Route 54/19	876+00				
0380	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	9/30/22	10/3/22	925.00	LF	Stage 5	876+00				
0470	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	9/20/22	9/29/22	264.00	LF	Face and Top of Curb Concrete Median Strip Route 19, 54, and 54/19	876+00				
			9/30/22	10/3/22	1,400.00	LF	Stage 5	876+00				
0480	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	9/20/22	9/29/22	2,182.00	LF	Face and Top of Curb Concrete Median Strip Route 19, 54, and 54/19	876+00				
0490	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAINT	9/30/22	10/3/22	30.00	LF	Stage 5	876+00				
0500	6207001	PAVEMENT MARKING REMOVAL	9/30/22	10/3/22	2,762.00	LF	Stage 5	876+00				
0520	6240104A	SEPARATION GEOTEXTILE	9/30/22	10/3/22	1,563.00	SQYD	Stage 5	876+00				
0530	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	9/30/22	10/3/22	0.25	LS		876+00				
0640	8051000A	SEEDING - COOL SEASON GRASSES	9/30/22	10/3/22	1.60	ACRE	Partial Payment of 80%	876+00				
0650	8061004	SEDIMENT TRAP ROCK	9/30/22	10/3/22	0.80	CUYD	Culvert Outlet	13+50				
0680	8061017	TEMPORARY SEEDING	9/30/22	10/3/22	0.40	ACRE	Partial Payment of 40%	876+00				

			letails for Construction Signs (i									
	Line Number		Total Quantity Posted For DWR Date	Sign Information	Station		Location			Special Sign	SF Each Special Sign	
23156	0290	June 30, 2022	547	R11-2 48x30 10.00 ROAD CLOSED		.380	Route J	2.00	10			
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		9.12	Route J	1	12.5			1:
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		.486	Route J	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		233.739	Route 54/19	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		234.442	CRD 456	1.00	16			
				CONST-7 48x24 8.00 RATE OUR WORK ZONE		234.442	Route 54/19	1.00	8			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		234.558	Route 54/19	1.00	12			
				WO3-5 48x48 16.00 SPEED LIMIT XX AHEAD (SYMBOL)		234.897	Route 19	1.00	16			
				CONST-3A 60x48 20.00 FINE SIGN		235.018	Route 19	1.00	20			
				R2-1 36x48 12.00 SPEED LIMIT XX		235.138	Route 19	1.00	12			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		235.138	Route 19	1.00	6			
				WO21-5 48x48 16.00 SHOULDER WORK AHEAD		235.402	Route 19	1.00	16			
				WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		235.46	Route 19	1.00	16			
			R2-1 36x48 12.00 SPEED LIMIT XX		235.961	Route 54	1.00	12				
				R2-1 36x48 12.00 SPEED LIMIT XX		236.917	Route 19	1.00	12			
				CONST-7 48x24 8.00 RATE OUR WORK ZONE		25.673	Route 19	1.00	8			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		25.700	CRD 472/556	2.00	16			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		25.797	Route 19	1.00	12			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		25.908	Route 19	1.00	16			
				WO3-5 48x48 16.00 SPEED LIMIT XX AHEAD (SYMBOL)		26.119	Route 19	1.00	16			
				CONST-3A 60x48 20.00 FINE SIGN		26.237	Route 19	1.00	20			
				R2-1 36x48 12.00 SPEED LIMIT XX		26.340	Route 19	1.00	12			
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		26.340	Route 19	1.00	6			
				WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		26.733	Route 19	1.00	16			
				R2-1 36x48 12.00 SPEED LIMIT XX		28.145	Route 54/19	1.00	12			
				CONST-7 48x24 8.00 RATE OUR WORK ZONE		35.528	Route 54	1.00	8			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		35.600	CRD 509	2.00	16			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		35.742	Route 54	1.00	12			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		35.922	Route 54	1.00	16			
				WO3-5 48x48 16.00 SPEED LIMIT XX AHEAD (SYMBOL)		35.950	Route 54	1.00	16			
				CONST-5 96x48 32.00 POINT OF		35.997	Route 54	1.00	32			

Revision 4/1/2020 Page 12 of 25



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

# The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The info	rmation belo	w this line are d	etails for Construction Signs (									
Project J2P3156	Line Number 0290	DWR Date June 30, 2022	Total Quantity Posted For DWR Date 547	Sign Information PRESENCE	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
				CONST-3A 60x48 20.00 FINE SIGN		36.065	Route 54	1.00	20			20
				R2-1 36x48 12.00 SPEED LIMIT XX		36.171	Route 54	1.00	12			12
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		36.171	Route 54	1.00	6			6
				WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		36.392	Route 54	1.00	16			16
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		.382	Route J	1	16			16
		August 31, 2022	86	WO1-4L 48x48 16.00 REVERSE CURVE (SYMBOL LEFT ARROW)			Rte 54/19, Rte 19	2.00	16.00			32.00
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)			Rte 54/19, Rte 19, Rte 54	3	6.00			18.00
				R2-1 36x48 12.00 SPEED LIMIT XX			Rte 54/19, Rte 19, Rte 54	3.00	12.00			36.00
				WO1-4R 48x48 16.00 REVERSE CURVE (SYMBOL RIGHT ARROW)			Rte 54		16.00			
		September 6, 2022	634	Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		1.767	Route 154	19.50	1.00	Sign 50F		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		9.55	Route 154	19.50	1.00	Sign 50F		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		12.293	Route 154	19.50	1.00	Sign 50J		19.50
				WO20-2 48x48 16.00 DETOUR AHEAD		21.614, 27.64, 235.34	Route 19, 54, 54/19	3	16.00			48.00
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		21.832	Route 19	19.50	1.00	Sign 50D		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		22.004	Route 19	19.50	1.00	Sign 50E		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		22.28	Route 19	19.50	1.00	Sign 50F		19.50
				Variable ??x?? 1.00 SPECIAL SIGN		22.797	Route 154	19.50	1.00	Sign 50G		19.50
				BY QUANTITY OF SQUARE FEET  Variable ??x?? 1.00 SPECIAL SIGN		23.01	Route 154	19.50	1.00	Sign 50H		19.50
				BY QUANTITY OF SQUARE FEET  Variable ??x?? 1.00 SPECIAL SIGN		23.151	Route 54	19.50	1.00	Sign 50I		19.50
				BY QUANTITY OF SQUARE FEET  Variable ??x?? 1.00 SPECIAL SIGN		23.151	Route 54	19.50	1.00	Sign 50J		19.50
				BY QUANTITY OF SQUARE FEET R11-3a 60x30 12.50 ROAD		23.181	Route 54	1.00	12.50	Sign 55E		12.50
				CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY								
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		23.284	Route 19	19.50	1.00	Sign 50F		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		235.6111	Route 19	19.5	1.00	Sign 50A		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		237.093	Route 19	19.50	1.00	Sign 50A		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		239.541	Route 19	19.50	1.00	Sign 50A		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		240.526	Route 19	19.50	1.00	Sign 50B		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		240.774	Route 19	19.50	1.00	Sign 50C		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		25.727	Route 19	19.50	1.00	Sign 50F		19.50
				MO4-8a 24x18 3.00 END DETOUR		27.631, 249.163	Route 19, Route 54	2.00	3.00	Sign 52		6.00
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		27.836	Route 54	1.00	12.50	Sign 55D		12.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		3.647	Route 154	19.50	1.00	Sign 50F		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		30.727	Route 154	19.50	1.00	Sign 50A		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		32.751	Route 154	19.50	1.00	Sign 50A		19.50
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		32.99	Route 54	1.00	12.50	Sign 55C		12.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		34.773	Route 154	19.50	1.00	Sign 50A		19.50
				R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC		35.560	Route 54	1.00	12.50	Sign 55A		12.50
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		35.741	Route 54	1.00	16.00	Sign 20A		16.00
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		35.917	Route 54	1.00	16.00	Sign 20B		16.00
				R11-2 48x30 10.00 ROAD CLOSED		35.918	Route 54	1.00	10.00	Sign 29		10.00
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		36.611	Route 154	19.50	1.00	Sign 50A		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		5.464	Route 154	19.50	1.00	Sign 50F		19.50
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		7.5	Route 154	19.50	1.00	Sign 50F		19.50
				Variable 22x22 1.00 SPECIAL SIGN		12.118	Route 154	19.50	1.00	Sign 50I		19.50
				BY QUANTITY OF SQUARE FEET								

Revision 4/1/2020 Page 13 of 25



J2P3156 0040 EMBANKMENT IN PLACE 2 Jul 17, 2022 SYSTEM (\$52,321.50)  3 Aug 2, 2022 SYSTEM (\$52,321.50)  4 Aug 16, 2022 (\$65,413.20)	
2022 4 Aug 16, SYSTEM (\$65,413.20) 2022	
2022	
5 Sep 2, SYSTEM (\$65,413.20)	
6 Sep 18, SYSTEM (\$65,413.20)	
- Total (\$300,882.60)	
Material - Total (\$300,882.60)	
MaterialCredit 3 Aug 2, SYSTEM \$52,321.50	
2022 4 Aug 16, SYSTEM \$52,321.50	
2022 5 Sep 2, SYSTEM \$65,413.20	
2022	
6 Sep 18, SYSTEM \$65,413.20	
7 Oct 3, 2022 \$YSTEM \$65,413.20	
- Total \$300,882.60	
MaterialCredit - Total \$300,882.60	
Other Item         MDPA         2         Jul 17, 2022         gardb1         \$52,321.50	
4 Aug 16, gardb1 \$13,091.70 2022	
7 Oct 3, gardb1 (\$65,413.20) 2022	
MDPA - Total \$0.00	
Other Item Adjustment - Total \$0.00	
0040 - Total \$0.00	
0050 COMPACTING Material 2 Jul 17, 2022 (\$26,443.90)	
3 Aug 2, SYSTEM (\$33,055.80)	
2022	
4 Aug 16, SYSTEM (\$33,055.80)	
4 Aug 16, SYSTEM (\$33,055.80)	
4 Aug 16, SYSTEM (\$33,055.80) 5 Sep 2, SYSTEM (\$33,237.10)	
4 Aug 16, SYSTEM (\$33,055.80)  5 Sep 2, SYSTEM (\$33,237.10)  6 Sep 18, SYSTEM (\$33,237.10)  - Total (\$159,029.70)	
4 Aug 16, SYSTEM (\$33,055.80)  5 Sep 2, 2022 SYSTEM (\$33,237.10)  6 Sep 18, SYSTEM (\$33,237.10)  - Total (\$159,029.70)  Material - Total (\$159,029.70)	
4 Aug 16, SYSTEM (\$33,055.80)  5 Sep 2, 2022 6 Sep 18, SYSTEM (\$33,237.10)  - Total (\$159,029.70)	
4 Aug 16, SYSTEM (\$33,055.80)  5 Sep 2, 2022 SYSTEM (\$33,237.10)  6 Sep 18, SYSTEM (\$33,237.10)  - Total (\$159,029.70)  Material - Total (\$159,029.70)	
4 Aug 16, SYSTEM (\$33,055.80)  5 Sep 2, SYSTEM (\$33,237.10)  6 Sep 18, SYSTEM (\$33,237.10)  - Total (\$159,029.70)  Material - Total (\$159,029.70)  MaterialCredit 3 Aug 2, 2022 SYSTEM \$26,443.90  4 Aug 16, SYSTEM \$33,055.80	
Aug 16, 2022   SYSTEM (\$33,055.80)	
4 Aug 16, 2022 SYSTEM (\$33,055.80)  5 Sep 2, 2022 SYSTEM (\$33,237.10)  6 Sep 18, 2022 (\$159,029.70)  Material - Total (\$159,029.70)  MaterialCredit 3 Aug 2, 2022 SYSTEM \$26,443.90  4 Aug 16, SYSTEM \$33,055.80  2022 SYSTEM \$33,055.80  5 Sep 2, 2022 SYSTEM \$33,055.80  6 Sep 18, 2022 SYSTEM \$33,055.80  6 Sep 18, 2022 SYSTEM \$33,237.10  7 Oct 3, 2022 SYSTEM \$33,237.10  - Total \$159,029.70	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J2P3156	0050	COMPACTING EMBANKMENT	Other Item Adjustment	MDPA	5	Sep 2, 2022	gardb1	\$181.30				
					7	Oct 3, 2022	gardb1	(\$33,237.10)				
				MDPA - Tota	al			\$0.00				
			Other Item Ad	justment - To	tal			\$0.00				
	0050 -	Total						\$0.00				
	0800	SUBGRADE COMPACTION (6-INCH	Material		2	Jul 17, 2022	SYSTEM	(\$14,472.00)				
		DEPTH)			3	Aug 2, 2022	SYSTEM	(\$14,472.00)				
					4	Aug 16, 2022	SYSTEM	(\$14,472.00)				
					5	Sep 2, 2022	SYSTEM	(\$24,264.00)				
					6	Sep 18, 2022	SYSTEM	(\$24,264.00)				
				- Total				(\$91,944.00)				
			Material - Tota	1				(\$91,944.00)				
			MaterialCredit		3	Aug 2, 2022	SYSTEM	\$14,472.00				
					4	Aug 16, 2022	SYSTEM	\$14,472.00				
					5	Sep 2, 2022	SYSTEM	\$14,472.00				
					6	Sep 18, 2022	SYSTEM	\$24,264.00				
		N			7	Oct 3, 2022	SYSTEM	\$24,264.00				
				- Total				\$91,944.00				
			MaterialCredit	- Total				\$91,944.00				
			Other Item Adjustment	MDPA	2	Jul 17, 2022	gardb1	\$14,472.00				
			•		5	Sep 2, 2022	gardb1	\$9,792.00				
					7	Oct 3, 2022	gardb1	(\$24,264.00)				
				MDPA - Tot	al			\$0.00				
			Other Item Ad	justment - To	tal			\$0.00				
	0080 -	Total						\$0.00				
	0110	TYPE 5 AGGREGATE FOR BASE	Material		2	Jul 17, 2022	SYSTEM	(\$13,889.70)				
		TONBAGE			3	Aug 2, 2022	SYSTEM	(\$13,889.70)				
					4	Aug 16, 2022	SYSTEM	(\$14,704.05)				
					5	Sep 2, 2022	SYSTEM	(\$22,499.85)				
					6	Sep 18, 2022	SYSTEM	(\$22,499.85)				
				- Total				(\$87,483.15)				
			Material - Tota	ı				(\$87,483.15)				
			MaterialCredit		3	Aug 2, 2022	SYSTEM	\$13,889.70				
					4	Aug 16, 2022	SYSTEM	\$13,889.70				
					5	Sep 2, 2022	SYSTEM	\$14,704.05				
								6	Sep 18, 2022	SYSTEM	\$22,499.85	
					7	Oct 3,	SYSTEM	\$22,499.85				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2P3156	0110	TYPE 5 AGGREGATE	MaterialCredit			2022			
		FOR BASE	Mataria I Orandi	- Total				\$87,483.15	
			MaterialCredit Other Item	- Total MDPA	2	Jul 17,	gordh1	\$87,483.15	
			Adjustment	WIDEA		2022	gardb1	\$13,889.70	
					4	Aug 16, 2022	gardb1	\$814.35	
					5	Sep 2, 2022	gardb1	\$7,795.80	
					7	Oct 3, 2022	gardb1	(\$22,499.85)	
				MDPA - Tot				\$0.00	
	0440	Takal	Other Item Ad	justment - To	tal			\$0.00	
	0110 -	MISC.	Material		0	l.:1.47	OVOTEM	\$0.00	
	0120	AGGREGATE FOR BASE	Material		2	Jul 17, 2022	SYSTEM	(\$1,841.10)	
					3	Aug 2, 2022	SYSTEM	(\$2,850.00)	
					4	Aug 16, 2022	SYSTEM	(\$33,516.00)	
					5	Sep 2, 2022	SYSTEM	(\$33,516.00)	
					6	Sep 18, 2022	SYSTEM	(\$38,258.40)	
					7	Oct 3, 2022	SYSTEM	(\$37,015.80)	
				- Total				(\$146,997.30)	
			Material - Tota	ıl				(\$146,997.30)	
			MaterialCredit		3	Aug 2, 2022	SYSTEM	\$1,841.10	
					4	Aug 16, 2022	SYSTEM	\$2,850.00	
					5	Sep 2, 2022	SYSTEM	\$33,516.00	
					6	Sep 18, 2022	SYSTEM	\$33,516.00	
					7	Oct 3, 2022	SYSTEM	\$38,258.40	
				- Total				\$109,981.50	
			MaterialCredit	- Total				\$109,981.50	
			Other Item Adjustment	MDPA	2	Jul 17, 2022	gardb1	\$1,841.10	
					3	Aug 2, 2022	gardb1	\$1,008.90	
					4	Aug 16, 2022	gardb1	\$30,666.00	
					6	Sep 18, 2022	gardb1	\$4,742.40	
					7	Oct 3, 2022	gardb1	(\$1,242.60)	
				MDPA - Tota				\$37,015.80	
			Other Item Ad	justment - To	tal			\$37,015.80	
	0120 -							\$0.00	
	0150	CONCRETE PAVEMENT (9 IN. NON-	Material		4	Aug 16, 2022	SYSTEM	(\$335,432.00)	
		REINFORCED,			5	Sep 2, 2022	SYSTEM	(\$1,069,408.00)	
					6	Sep 18, 2022	SYSTEM	(\$1,154,876.00)	
					7	Oct 3, 2022	SYSTEM	(\$1,222,220.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3156	0150	CONCRETE PAVEMENT (9 IN. NON- REINFORCED,	Material	- Total				(\$3,781,936.00)	
			Material - Tota					(\$3,781,936.00)	
			MaterialCredit		5	Sep 2, 2022	SYSTEM	\$335,432.00	
					6	Sep 18, 2022	SYSTEM	\$1,069,408.00	
					7	Oct 3, 2022	SYSTEM	\$1,154,876.00	
				- Total				\$2,559,716.00	
			MaterialCredit					\$2,559,716.00	
			Other Item Adjustment	MDPA		Aug 16, 2022	gardb1	\$335,432.00	
					5	Sep 2, 2022	gardb1	\$733,976.00	
					6	Sep 18, 2022	gardb1	\$85,468.00	
					7	Oct 3, 2022	gardb1	\$67,344.00	
			Othor How A	MDPA - Tota				\$1,222,220.00	
	0150 -	Total	Other Item Adj	ustment - 10	tal			\$1,222,220.00 \$0.00	
	0180	6 IN. CONCRETE MEDIAN STRIP	Material		5	Sep 2, 2022	SYSTEM	(\$53,300.00)	
					6	Sep 18, 2022	SYSTEM	(\$70,101.80)	
					7	Oct 3, 2022	SYSTEM	(\$70,101.80)	
				- Total				(\$193,503.60)	
			Material - Tota					(\$193,503.60)	
			MaterialCredit		6	Sep 18, 2022	SYSTEM	\$53,300.00	
					7	Oct 3, 2022	SYSTEM	\$70,101.80	
				- Total				\$123,401.80	
			MaterialCredit					\$123,401.80	
			Other Item Adjustment			Sep 2, 2022	gardb1	\$53,300.00	
					6	Sep 18, 2022	gardb1	\$16,801.80	
			Othor Itom Ad	MDPA - Tota				\$70,101.80	
	0180 -	Total	Other Item Adj	usunent - 10	tal			\$70,101.80 \$0.00	
	0190		Material		4	Aug 16, 2022	SYSTEM	(\$19,604.00)	
		HEIGHT AND UNDER)			5	Sep 2, 2022	SYSTEM	(\$19,604.00)	
					6	Sep 18, 2022	SYSTEM	(\$19,604.00)	
					7	Oct 3, 2022	SYSTEM	(\$19,604.00)	
				- Total				(\$78,416.00)	
			Material - Tota					(\$78,416.00)	
			MaterialCredit		5	Sep 2, 2022	SYSTEM	\$19,604.00	
					6	Sep 18, 2022	SYSTEM	\$19,604.00	
					7	Oct 3, 2022	SYSTEM	\$19,604.00	
				- Total				\$58,812.00	
			MaterialCredit	- Total				\$58,812.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J2P3156	0190	CONCRETE CURB (6 IN. HEIGHT AND	Other Item Adjustment	MDPA	4	Aug 16, 2022	gardb1	\$19,604.00		
		UNDER)		MDPA - Tot	al			\$19,604.00		
			Other Item Ad	justment - To	tal			\$19,604.00		
	0190 -	Total						\$0.00		
	0200	CONCRETE CURB LOW PROFILE TYPE F	Material		4	Aug 16, 2022	SYSTEM	(\$12,656.00)		
					5	Sep 2, 2022	SYSTEM	(\$12,656.00)		
						6	Sep 18, 2022	SYSTEM	(\$12,656.00)	
					7	Oct 3, 2022	SYSTEM	(\$12,656.00)		
				- Total				(\$50,624.00)		
			Material - Tota	l				(\$50,624.00)		
			MaterialCredit		5	Sep 2, 2022	SYSTEM	\$12,656.00		
					6	Sep 18, 2022	SYSTEM	\$12,656.00		
					7	Oct 3, 2022	SYSTEM	\$12,656.00		
				- Total				\$37,968.00		
			MaterialCredit	- Total				\$37,968.00		
			Other Item Adjustment	MDPA	4	Aug 16, 2022	gardb1	\$12,656.00		
				MDPA - Tota	al			\$12,656.00		
			Other Item Ad	justment - To	tal			\$12,656.00		
	0200 -	0200 - Total						\$0.00		
	0220	FURN. TYPE 2 ROCK DITCH LINER	Material		6	Sep 18, 2022	SYSTEM	(\$36,835.00)		
				- Total				(\$36,835.00)		
			Material - Tota	ı				(\$36,835.00)		
			MaterialCredit		7	Oct 3, 2022	SYSTEM	\$36,835.00		
				- Total				\$36,835.00		
			MaterialCredit					\$36,835.00		
			Other Item Adjustment	MDPA		Sep 18, 2022	gardb1	\$36,835.00		
					7	Oct 3, 2022	gardb1	(\$36,835.00)		
			Other K	MDPA - Tota				\$0.00		
	0220 -	Total	Other Item Ad	justment - To	tai			\$0.00		
	0220 -	ROCK LINING	Material		6	Sep 18, 2022	SYSTEM	\$0.00 (\$8,148.00)		
				- Total				(\$8,148.00)		
			Material - Tota					(\$8,148.00)		
			MaterialCredit		7	Oct 3, 2022	SYSTEM	\$8,148.00		
				- Total				\$8,148.00		
			MaterialCredit					\$8,148.00		
			Other Item Adjustment	MDPA	6	Sep 18, 2022	gardb1	\$8,148.00		
					7	Oct 3, 2022	gardb1	(\$8,148.00)		
				MDPA - Tota	al			\$0.00		
			Other Item Ad	justment - To	tal			\$0.00		
	0250 -	- Total						\$0.00		

# MoDOT

# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3156	0260	IMPACT ATTENUATOR			1	Jul 1, 2022	SYSTEM	(\$8,400.00)	
		60 MPH (SAND BARREL ARRAY)			2	Jul 17, 2022	SYSTEM	(\$8,400.00)	
					3	Aug 2, 2022	SYSTEM	(\$10,500.00)	
					4	Aug 16, 2022	SYSTEM	(\$10,500.00)	
					5	Sep 2, 2022	SYSTEM	(\$16,800.00)	
					6	Sep 18, 2022	SYSTEM	(\$16,800.00)	
				- Total				(\$71,400.00)	
			Material - Tota	ıl			0) (0 === )	(\$71,400.00)	
			MaterialCredit		2	Jul 17, 2022	SYSTEM	\$8,400.00	
					3	Aug 2, 2022	SYSTEM	\$8,400.00	
					4	Aug 16, 2022	SYSTEM	\$10,500.00	
					5	Sep 2, 2022	SYSTEM	\$10,500.00	
					6	Sep 18, 2022	SYSTEM	\$16,800.00	
					7	Oct 3, 2022	SYSTEM	\$16,800.00	
				- Total				\$71,400.00	
			MaterialCredit	- Total				\$71,400.00	
			Other Item Adjustment	MDPA	1	Jul 1, 2022	gardb1	\$8,400.00	Material Payment Adjustment
					3	Aug 2, 2022	gardb1	\$2,100.00	
					5	Sep 2, 2022	gardb1	\$6,300.00	
					7	Oct 3, 2022	gardb1	(\$16,800.00)	
				MDPA - Tot	al			\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
	0260 -						0) (0 === )	\$0.00	
	0340	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		1	Jul 1, 2022	SYSTEM	(\$6,000.00)	
					2	Jul 17, 2022	SYSTEM	(\$6,000.00)	
					3	Aug 2, 2022	SYSTEM	(\$6,000.00)	
					4	Aug 16, 2022	SYSTEM	(\$6,000.00)	
					5	Sep 2, 2022	SYSTEM	(\$6,000.00)	
					6	Sep 18, 2022	SYSTEM	(\$6,000.00)	
				- Total				(\$36,000.00)	
			Material - Tota	ıl				(\$36,000.00)	
			Material - Tota MaterialCredit	al	2	Jul 17, 2022	SYSTEM	(\$36,000.00) \$6,000.00	
				al	3	Jul 17, 2022 Aug 2, 2022	SYSTEM SYSTEM		
				al		2022 Aug 2,		\$6,000.00	
				al .	3	2022 Aug 2, 2022 Aug 16,	SYSTEM	\$6,000.00 \$6,000.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3156	0340	TEMPORARY LONG-TERM RUMBLE	MaterialCredit		7	2022 Oct 3, 2022	SYSTEM	\$6,000.00	
		STRIPS		- Total		2022		\$36,000.00	
			MaterialCredit					\$36,000.00	
			Other Item Adjustment	MDPA	1	Jul 1, 2022	gardb1	\$6,000.00	Material Payment Adjustment
					7	Oct 3, 2022	gardb1	(\$6,000.00)	
				MDPA - Tota	al			\$0.00	
		Total	Other Item Ad	ustment - To	tal			\$0.00	
	0340 -							\$0.00	
	0350	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		1	Jul 1, 2022	SYSTEM	(\$2,500.00)	
					2	Jul 17, 2022	SYSTEM	(\$2,500.00)	
					3	Aug 2, 2022	SYSTEM	(\$10,000.00)	
					4	Aug 16, 2022	SYSTEM	(\$10,000.00)	
					5	Sep 2, 2022	SYSTEM	(\$10,000.00)	
					6	Sep 18, 2022	SYSTEM	(\$12,500.00)	
				- Total				(\$47,500.00)	
			Material - Tota					(\$47,500.00)	
			MaterialCredit		2	Jul 17, 2022	SYSTEM	\$2,500.00	
					3	Aug 2, 2022	SYSTEM	\$2,500.00	
					4	Aug 16, 2022	SYSTEM	\$10,000.00	
					5	Sep 2, 2022	SYSTEM	\$10,000.00	
					6	Sep 18, 2022	SYSTEM	\$10,000.00	
					7	Oct 3, 2022	SYSTEM	\$12,500.00	
				- Total				\$47,500.00	
			MaterialCredit	- Total				\$47,500.00	
			Other Item Adjustment		1	Jul 1, 2022	gardb1	\$2,500.00	Material Payment Adjustment
					3	Aug 2, 2022	gardb1	\$7,500.00	
					6	Sep 18, 2022	gardb1	\$2,500.00	
					7	Oct 3, 2022	gardb1	(\$12,500.00)	
				MDPA - Tota	al			\$0.00	
			Other Item Ad	ustment - To	tal			\$0.00	
	0350 -							\$0.00	
	0360	TEMP. TRAFFIC BARRIER	Material		1	Jul 1, 2022	SYSTEM	(\$4,500.00)	
		ANCHORED., CONT			2	Jul 17, 2022	SYSTEM	(\$4,500.00)	
					3	Aug 2, 2022	SYSTEM	(\$26,550.00)	
					4	Aug 16, 2022	SYSTEM	(\$26,550.00)	
					5	Sep 2, 2022	SYSTEM	(\$26,550.00)	



J2P3156   O360   TEMP. TRAFFIC BARRIER ANCHORED., CONT   CONT	
ANCHORED., CONT    Material - Total   (\$115,200.00)	
Material Credit  2 Jul 17, 2022 3 Aug 2, 2022 4 Aug 16, 2022 5 Sep 2, 2022 5 Sep 18, SYSTEM \$26,550.00 6 Sep 18, SYSTEM \$26,550.00 7 Oct 3, SYSTEM \$26,550.00	
2022 3 Aug 2, 2022 4 Aug 16, 2022 5 Sep 2, 2022 6 Sep 18, 2022 7 Oct 3, SYSTEM \$26,550.00	
2022 4 Aug 16, SYSTEM \$26,550.00 5 Sep 2, 2022 6 Sep 18, SYSTEM \$26,550.00 7 Oct 3, SYSTEM \$26,550.00	
2022 5 Sep 2, 2022 6 Sep 18, 2022 7 Oct 3, SYSTEM \$26,550.00	
2022 6 Sep 18, SYSTEM \$26,550.00 7 Oct 3, SYSTEM \$26,550.00	
7 Oct 3, SYSTEM \$26,550.00	
- Total \$115,200.00	
MaterialCredit - Total \$115,200.00	
Other Item MDPA 1 Jul 1, gardb1 \$4,500.00 Material Payment Adjustment 2022	
3 Aug 2, gardb1 \$22,050.00 2022	
7 Oct 3, gardb1 (\$26,550.00)	
MDPA - Total \$0.00	
Other Item Adjustment - Total \$0.00	
0360 - Total \$0.00	
0440 TEMPORARY Material 1 Jul 1, SYSTEM (\$816.75) REMOVABLE 2022 MARKING	
TAPE 4 IN., 2 Jul 17, 2022 (\$816.75)	
3 Aug 2, SYSTEM (\$4,247.10)	
4 Aug 16, 2022 (\$4,247.10)	
5 Sep 2, SYSTEM (\$4,247.10)	
6 Sep 18, 2022 SYSTEM (\$4,247.10)	
MaterialCredit   2	
2022	
4 Aug 16, 2022 \$YSTEM \$4,247.10 \$5 \$ep 2, \$YSTEM \$4,247.10	
6 Sep 18, SYSTEM \$4,247.10	
7 Oct 3, SYSTEM \$4,247.10	
- Total \$18,621.90	
WaterialCredit - 10tal \$18.621.90	
MaterialCredit - Total \$18,621.90  Other Item MDPA 1 Jul 1, gardb1 \$816.75 Material Payment Adjustment Adjustment 2022	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3156	0440	TEMPORARY REMOVABLE	Other Item Adjustment	MDPA - Tota	al			\$0.00	
		MARKING TAPE 4 IN.,	Other Item Ad	justment - To	tal			\$0.00	
	0440 -	Total						\$0.00	
	0450	TEMPORARY REMOVABLE MARKING TAPE	Material		3	Aug 2, 2022	SYSTEM	(\$3,430.35)	
					4	Aug 16, 2022	SYSTEM	(\$3,430.35)	
					5	Sep 2, 2022	SYSTEM	(\$3,430.35)	
					6	Sep 18, 2022	SYSTEM	(\$3,430.35)	
				- Total				(\$13,721.40)	
			Material - Tota	ıl				(\$13,721.40)	
			MaterialCredit		4	Aug 16, 2022	SYSTEM	\$3,430.35	
					5	Sep 2, 2022	SYSTEM	\$3,430.35	
					6	Sep 18, 2022	SYSTEM	\$3,430.35	
				T-4-1	7	Oct 3, 2022	SYSTEM	\$3,430.35	
				- Total				\$13,721.40	
			MaterialCredit			4 0		\$13,721.40	
			Other Item Adjustment	MDPA		Aug 2, 2022	gardb1	\$3,430.35	
				MDDA Total	7	Oct 3, 2022	gardb1	(\$3,430.35)	
			Other Item Ad	MDPA - Tota				\$0.00 \$0.00	
	0450 -	Total	Other item Au	justilient - 10	Lai			\$0.00	
	0460	4 IN. YELLOW HIGH BUILD	Material		4	Aug 16, 2022	SYSTEM	(\$3,969.75)	
		WATERBORNE PAINT			5	Sep 2, 2022	SYSTEM	(\$3,969.75)	
					6	Sep 18, 2022	SYSTEM	(\$3,969.75)	
					7	Oct 3, 2022	SYSTEM	(\$3,969.75)	
				- Total				(\$15,879.00)	
			Material - Tota	ıl				(\$15,879.00)	
			MaterialCredit		5	Sep 2, 2022	SYSTEM	\$3,969.75	
					6	Sep 18, 2022	SYSTEM	\$3,969.75	
					7	Oct 3, 2022	SYSTEM	\$3,969.75	
				- Total				\$11,909.25	
			MaterialCredit					\$11,909.25	
			Other Item Adjustment	MDPA		Aug 16, 2022	gardb1	\$3,969.75	
			Oil II -	MDPA - Tota				\$3,969.75	
	0.400	Total	Other Item Ad	justment - To	lal			\$3,969.75	
	0460 -		M-4- : !		7	0.10	OVOTEL	\$0.00	
	0470	6 IN. WHITE HIGH BUILD WATERBORNE	Material	T-4-1	7	Oct 3, 2022	SYSTEM	(\$1,248.00)	
		PAINT	N-A	- Total				(\$1,248.00)	
			Material - Tota		7	0.10		(\$1,248.00)	
			Other Item Adjustment	MDPA	/	Oct 3, 2022	gardb1	\$1,248.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3156	0470	6 IN. WHITE HIGH BUILD	Other Item Adjustment	MDPA - Tot	al			\$1,248.00	
		WATERBORNE PAINT	Other Item Ad	justment - To	tal			\$1,248.00	
	0470 -	- Total						\$0.00	
	0480	6 IN. YELLOW HIGH BUILD	Material		7	Oct 3, 2022	SYSTEM	(\$1,636.50)	
		WATERBORNE PAINT		- Total				(\$1,636.50)	
			Material - Tota	ıl				(\$1,636.50)	
			Other Item Adjustment	MDPA	7	Oct 3, 2022	gardb1	\$1,636.50	
				MDPA - Tot	al			\$1,636.50	
			Other Item Ad	justment - To	tal			\$1,636.50	
	0480 -	- Total						\$0.00	
	0490	12 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		7	Oct 3, 2022	SYSTEM	(\$75.00)	
				- Total				(\$75.00)	
			Material - Tota	ıl				(\$75.00)	
			Other Item Adjustment	MDPA	7	Oct 3, 2022	gardb1	\$75.00	
				MDPA - Tot	al			\$75.00	
			Other Item Ad	justment - To	tal			\$75.00	
	0490 -	- Total						\$0.00	
	0510	PERMANENT EROSION CONTROL GEOTEXTILE	Material		6	Sep 18, 2022	SYSTEM	(\$7,973.30)	
				- Total				(\$7,973.30)	
			Material - Tota	ıl				(\$7,973.30)	
			MaterialCredit		7	Oct 3, 2022	SYSTEM	\$7,973.30	
				- Total				\$7,973.30	
			MaterialCredit	- Total				\$7,973.30	
			Other Item Adjustment	MDPA	6	Sep 18, 2022	gardb1	\$7,973.30	
					7	Oct 3, 2022	gardb1	(\$7,973.30)	
				MDPA - Total				\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
	0510 -	- Total						\$0.00	
	0520	SEPARATION GEOTEXTILE	Material		2	Jul 17, 2022	SYSTEM	(\$1,776.50)	
					3	Aug 2, 2022	SYSTEM	(\$2,750.00)	
					4	Aug 16, 2022	SYSTEM	(\$32,340.00)	
					5	Sep 2, 2022	SYSTEM	(\$32,340.00)	
					6	Sep 18, 2022	SYSTEM	(\$36,916.00)	
				- Total				(\$106,122.50)	
			Material - Tota	ıl				(\$106,122.50)	
			MaterialCredit		3	Aug 2, 2022	SYSTEM	\$1,776.50	
					4	Aug 16, 2022	SYSTEM	\$2,750.00	
					5	Sep 2, 2022	SYSTEM	\$32,340.00	
					6	Sep 18, 2022	SYSTEM	\$32,340.00	
					7	Oct 3, 2022	SYSTEM	\$36,916.00	

# MoDOT

# Line Item Adjustments by Estimate

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
23156	0520	SEPARATION	MaterialCredit	- Total				\$106,122.50	
		GEOTEXTILE	MaterialCredit	- Total				\$106,122.50	
			Other Item Adjustment	MDPA	2	Jul 17, 2022	gardb1	\$1,776.50	
					3	Aug 2, 2022	gardb1	\$973.50	
					4	Aug 16, 2022	gardb1	\$29,590.00	
					6	Sep 18, 2022	gardb1	\$4,576.00	
					7	Oct 3, 2022	gardb1	(\$36,916.00)	
				MDPA - Tota				\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
	0520 -							\$0.00	
	0560	18 IN. PIPE CULVERT GROUP C	Material		2	Jul 17, 2022	SYSTEM	(\$2,340.00)	
					3	Aug 2, 2022	SYSTEM	(\$2,340.00)	
					4	Aug 16, 2022	SYSTEM	(\$2,340.00)	
					5	Sep 2, 2022	SYSTEM	(\$2,340.00)	
					6	Sep 18, 2022	SYSTEM	(\$2,340.00)	
					7	Oct 3, 2022	SYSTEM	(\$2,340.00)	
				- Total				(\$14,040.00)	
			Material - Tota	l				(\$14,040.00)	
			MaterialCredit		3	Aug 2, 2022	SYSTEM	\$2,340.00	
					4	Aug 16, 2022	SYSTEM	\$2,340.00	
					5	Sep 2, 2022	SYSTEM	\$2,340.00	
					6	Sep 18, 2022	SYSTEM	\$2,340.00	
					7	Oct 3, 2022	SYSTEM	\$2,340.00	
				- Total				\$11,700.00	
			MaterialCredit Other Item	- Total MDPA	2	Jul 17,	gardb1	\$11,700.00 \$2,340.00	
			Adjustment	MDPA - Tota	al	2022		\$2,340.00	
			Other Item Ad					\$2,340.00	
	0560 -	Total		<u></u>				\$0.00	
	0640	SEEDING - COOL SEASON	Material		7	Oct 3, 2022	SYSTEM	(\$3,920.00)	
		GRASSES		- Total				(\$3,920.00)	
			Material - Tota					(\$3,920.00)	
			Other Item Adjustment	MDPA		Oct 3, 2022	gardb1	\$3,920.00	
				MDPA - Tota				\$3,920.00	
			Other Item Ad	justment - To	tal			\$3,920.00	
J	0640 -							\$0.00	
	0820	CONCRETE FOOTINGS, EMBEDDED	Material		6	Sep 18, 2022	SYSTEM	(\$1,581.00)	
		J			7	Oct 3, 2022	SYSTEM	(\$1,581.00)	
				- Total				(\$3,162.00)	

Oct 5, 2022



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3156	0820	CONCRETE FOOTINGS, EMBEDDED	Material - Tota	ı				(\$3,162.00)	
			MaterialCredit		7	Oct 3, 2022	SYSTEM	\$1,581.00	
				- Total				\$1,581.00	
			MaterialCredit	- Total				\$1,581.00	
			Other Item Adjustment	MDPA	6	Sep 18, 2022	gardb1	\$1,581.00	
				MDPA - Tota	al			\$1,581.00	
			Other Item Ad	justment - To	tal			\$1,581.00	
	0820 -	- Total						\$0.00	
	0900	SH-FLAT SHEET	Material		6	Sep 18, 2022	SYSTEM	(\$6,129.19)	
				- Total				(\$6,129.19)	
			Material - Tota	I				(\$6,129.19)	
			MaterialCredit		7	Oct 3, 2022	SYSTEM	\$6,129.19	
				- Total				\$6,129.19	
			MaterialCredit	- Total				\$6,129.19	
			Other Item Adjustment	MDPA	6	Sep 18, 2022	gardb1	\$6,129.19	
					7	Oct 3, 2022	gardb1	(\$6,129.19)	
				MDPA - Tot	al			\$0.00	
			Other Item Ad	ustment - To	tal			\$0.00	
	0900 -	- Total						\$0.00	
	0920	SHF-FLAT SHEET FLUORESCENT	Material		6	Sep 18, 2022	SYSTEM	(\$1,604.55)	
				- Total				(\$1,604.55)	
			Material - Tota	l				(\$1,604.55)	
			MaterialCredit		7	Oct 3, 2022	SYSTEM	\$1,604.55	
				- Total				\$1,604.55	
			MaterialCredit	- Total				\$1,604.55	
			Other Item Adjustment	MDPA	6	Sep 18, 2022	gardb1	\$1,604.55	
					7	Oct 3, 2022	gardb1	(\$1,604.55)	
				MDPA - Tota				\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
		- Total					\$0.00		
J2P3156 -								\$0.00	
Overall -	Total						\$0.00		