

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 4, 2023

Progress Estin		Contract ID Prime Contractor	220318-D01 Widel, Inc.	Pay Period Start Pay Period End	December 16, 2022 January 1, 2023	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,650,249.30 (\$51,485.85) \$1,598,763.45				
Approval Date							By User				
January 4, 2023	Generated and Approved (and should be considered Draft) at the Project Office Level by										
January 4, 2023		Revie	wed and Appr	oved (and should be	e considered Draft) at	the Resident Engineer Level by	webers1				
January 5, 2023				Reviewed and App	roved at the Central (Office Controllers Office Level by	ramses1				
Original Comp	mpletion Date Current Completion Date Actual Completion Date % of Current Contract Amou										
December	1, 2022	December 1	, 2022	December	1, 2022	95.85%					

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	April 6, 2022	April 6, 2022	
Letting Date	March 18, 2022	March 18, 2022	
Notice to Proceed Date	May 10, 2022	May 10, 2022	
Open to Traffic Date			
Work Began Date	August 23, 2022	August 23, 2022	

Contract Total Pa	ny For Estimate No. 12				
		This Estimate	Previous	To Date	
220318-D01					
	Total Posted Items Pay	\$344.00	\$1,532,013.46	\$1,532,357.46	
	Gross Item Adjustments	\$0.00	(\$289.05)	(\$289.05)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$1,531,724.41	\$1,532,068.41	
Contract Total Pa	yable This Estimate:	\$344.00			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3448	0320	8061005	ROCK DITCH CHECK	LF	\$17.200	20	\$344.00
Project J5S3448 - 1	Γotal						\$344.00
Overall - Total							\$344.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

_ine Item .	Adjusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3448	0260	PERMANENT EROSION CONTROL GEOTEXTILE	Material			-193	\$3.55	(\$685.15)
	0260	PERMANENT EROSION CONTROL GEOTEXTILE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user woods6 overridding Payment Estimate Exception 6 on the current Payment Estimate.	193	\$3.55	\$685.15
	0320	ROCK DITCH CHECK	Material			-20	\$17.20	(\$344.00)
	0320	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woods6 overridding Payment Estimate Exception 8 on the current Payment Estimate.	20	\$17.20	\$344.00
	0350	MGS GUARDRAIL	Material			-1,500	\$35.50	(\$53,250.00)
	0350	MGS GUARDRAIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	1,500	\$35.50	\$53,250.00

Revision 4/1/2020 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 4, 2023

Progress Estimate Number	Contract ID Prime Contractor			-, -	Original Contract Amount Net Change Order Amount	\$1,650,249.30 (\$51,485,85)	
12	Trinic Contractor	Widel, IIIe.	r uy r criou Enu	Junuary 1, 2020	Current Contract Amount	\$1,598,763.45	

					Current	Contract Am	ount wi	,590,703.45
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3448					Adjustment (0003) due to user woods6 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
	0390	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Material			-1	\$500.00	(\$500.00)
	0390	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Payment Estimate Exception 9 on the current Payment Estimate.	1	\$500.00	\$500.00
	0400	2.25 IN. PSST POST - 12 GA.	Material			-7	\$34.50	(\$241.50)
	0400	2.25 IN. PSST POST - 12 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 10 on the current Payment Estimate.	7	\$34.50	\$241.50
	0430	SH-FLAT SHEET	Material			-4	\$48.50	(\$194.00)
	0430	SH-FLAT SHEET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 11 on the current Payment Estimate.	4	\$48.50	\$194.00
	0470	BRIDGE APPROACH SLAB (MINOR ROAD)	Material			-90	\$313.00	(\$28,170.00)
	0470	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.	90	\$313.00	\$28,170.00
	0560	BRIDGE APPROACH SLAB (MINOR ROAD)	Material			-99	\$300.00	(\$29,700.00)
	0560	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate.	99	\$300.00	\$29,700.00
Total								\$0.00

Revision 4/1/2020 Page 2 of 14



Incentive Disincentive Liquidated Damages Other Contract Adjustments

Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information												
Project Number													
J5S3448	FAS S402(78)	Bridge rehabilitation	M and Z	COOPER	0.19 miles North of Route	19 miles North of Route OO and 0.27 miles South of Route AE							
Totals by .	Job Numbe	rs											
J5S3448		d Item Pay Item Adjustm		Item Pay	This Estimate \$344.00 \$0.00 \$344.00	Previous \$1,532,013.46 (\$289.05) \$1,531,724.41	To Date \$1,532,357.46 (\$289.05) \$1,532,068.41						

\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00

\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3448, Item 5031011A, Project Item Line Number 0470, Material Set 5031011A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Working with contractor and materials to resolve.	woods6	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3448, Item 5031011A, Project Item Line Number 0470, Material Set 5031011A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Working with contractor and materials to resolve.	woods6	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3448, Item 5031011A, Project Item Line Number 0560, Material Set 5031011A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Working with contractor and materials to resolve.	woods6	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3448, Item 5031011A, Project Item Line Number 0560, Material Set 5031011A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Working with contractor and materials to resolve.	woods6	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3448, Item 6061060, Project Item Line Number 0350, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	Working with contractor and materials to resolve.	woods6	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3448, Item 6240103A, Project Item Line Number 0260, Material Set 6240103A96, Material 1011GXT3 - Geotextile Fabric for ErosionControl(T3), Acceptance Action Generic 1011GXT3 is insufficient.	Working with contractor and materials to resolve.	woods6	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3448, Item 7040112, Project Item Line Number 0530, Material Set 704011296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Working with contractor and materials to resolve.	woods6	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3448, Item 8061005, Project Item Line Number 0320, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Working with contractor and materials to resolve.	woods6	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3448, Item 9031241, Project Item Line Number 0390, Material Set 903124196, Material 0903HSBA - Breakaway Assembly for Highway Signing, Acceptance Action Generic 0903HSBA is insufficient.	Working with contractor and materials to resolve.	woods6	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3448, Item 9031272, Project Item Line Number 0400, Material Set 903127296, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Working with contractor and materials to resolve.	woods6	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3448, Item 9035004A, Project Item Line Number 0430, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Working with contractor and materials to resolve.	woods6	Overridden

Revision 4/1/2020 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
20318-D01	J5S3448	0001	0010	2019901	MISC.CLEARING AND GRUBBING	1.00	0.00	1.00	LS	1.00	\$1,365.00	\$1,365.0
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.0
		0001	0030	2031000	CLASS A EXCAVATION	433.00	0.00	433.00	CUYD	433.00	\$3.70	\$1,602.
		0001	0040	2035500	EMBANKMENT IN PLACE	3,133.00	0.00	3,133.00	CUYD	3,133.00	\$24.00	\$75,192.0
		0001	0050	2036000	COMPACTING EMBANKMENT	362.00	0.00	362.00	CUYD	362.00	\$8.20	\$2,968.4
		0001	0060	2063000	CLASS 3 EXCAVATION	2.00	0.00	2.00	CUYD	2.00	\$75.00	\$150.0
		0001	0070	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	154.00	0.00	154.00	SQYD	154.00	\$9.60	\$1,478.
		0001	0800	4019905	MISC.OPTIONAL PAVEMENT (8 IN. JPCP OR 10 IN. HMA)	153.90	0.00	153.90	SQYD	153.90	\$140.00	\$21,546.
		0001	0090	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	27.00	0.00	27.00	CUYD	27.00	\$31.00	\$837.
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	27.00	0.00	27.00	CUYD	27.00	\$5.80	\$156.
		0001	0110	6097000	ROCK LINING	2.00	0.00	2.00	CUYD	2.00	\$215.50	\$431
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$16,300.00	\$0
		0001	0130	6161005	CONSTRUCTION SIGNS	1,270.00	0.00	1,270.00	SQFT	938.00	\$7.50	\$7,035
		0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	11.00	0.00	11.00	EA	7.00	\$48.50	\$339
		0001	0150	6161025	CHANNELIZER (TRIM LINE)	119.00	0.00	119.00	EA	64.00	\$225.00	\$14,400
		0001	0160	6161030	TYPE III MOVEABLE BARRICADE	19.00	1.00	20.00	EA	20.00	\$125.00	\$2,500
		0001	0170	6161033	DIRECTIONAL INDICATOR BARRICADE	30.00	0.00	30.00	EA	30.00	\$105.00	\$3,150
		0001	0180	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000
		0001	0190	6161052	WARNING LIGHT, TYPE B	38.00	0.00	38.00	EA	0.00	\$70.00	\$0
		0001	0200	6161055	SEQUENTIAL FLASHING WARNING LIGHT	30.00	0.00	30.00	EA	30.00	\$70.00	\$2,10
		0001	0210	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$3,500.00	\$14,000
		0001	0220	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	0.00	\$1,025.00	\$0
		0001	0230	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$159,000.00	\$0
		0001	0231	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$117,744.00	\$117,744
		0001	0240	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0
		0001	0250	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,116.00	0.00	1,116.00	LF	1,116.00	\$2.15	\$2,399
		0001	0260	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	193.00	0.00	193.00	SQYD	193.00	\$3.55	\$685
		0001	0270	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$14,500.00	\$14,500
		0001	0280	7250318A	18 IN. PIPE GROUP B	22.00	0.00	22.00	LF	22.00	\$53.00	\$1,166
		0001	0290	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$460.00	\$92
		0001	0300	8051000A	SEEDING - COOL SEASON GRASSES	2.20	0.00	2.20	ACRE	2.20	\$3,450.00	\$7,590
		0001	0310	8061004	SEDIMENT TRAP ROCK	5.20	0.00	5.20	CUYD	0.00	\$105.00	\$0
		0001	0320	8061005	ROCK DITCH CHECK	120.00	0.00	120.00	LF	20.00	\$17.20	\$344
		0001	0330	8061016	SEDIMENT REMOVAL	44.00	0.00	44.00	CUYD	0.00	\$50.00	\$0
		0001	0340	8061019	SILT FENCE	2,800.00	0.00	2,800.00	LF	2,640.00	\$5.20	\$13,728
		0010	0350	6061060	MGS GUARDRAIL	1,500.00	0.00	1,500.00	LF	1,500.00	\$35.50	\$53,250
		0010	0360	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	8.00	0.00	8.00	EA	8.00	\$3,550.00	\$28,40
		0010	0370	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	8.00	\$3,400.00	\$27,20
		0040	0380	9031010	CONCRETE FOOTINGS, EMBEDDED	0.50	0.00	0.50	CUYD	0.50	\$1,850.00	\$925
		0040	0390	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL	1.00	0.00	1.00	EA	1.00	\$500.00	\$500
		0040	0400	9031272	TUBE) 2.25 IN. PSST POST - 12 GA.	7.00	0.00	7.00	LF	7.00	\$34.50	\$24
		0040	0410	9031280	2.5 IN. PSST POST - 12 GA.	72.00	0.00	72.00	LF	72.00	\$24.20	\$1,742
		0040	0410	9031280	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	18.00	0.00	18.00	LF	18.00	\$67.25	\$1,742
		0040	0 /20	0001201		10.00	0.00	10.00	-1	10.00	ψ01.23	Ψ1,210

Revision 4/1/2020 Page 5 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220318-D01	J5S3448	0070	0440	2161000	SCARIFICATION OF BRIDGE DECK	459.00	0.00	459.00	SQYD	459.00	\$20.65	\$9,478.35
		0070	0450	2161001	TOTAL SURFACE HYDRO DEMOLITION	459.00	0.00	459.00	SQYD	459.00	\$130.00	\$59,670.00
		0070	0460	2161503	REMOVAL OF EXISTING DECK REPAIR	400.00	0.00	400.00	SQFT	289.50	\$18.00	\$5,211.00
		0070	0470	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	90.00	0.00	90.00	SQYD	90.00	\$313.00	\$28,170.00
		0070	0480	5059905	MISC.High Performance Concrete Wearing Surface	459.00	0.00	459.00	SQYD	459.00	\$595.50	\$273,334.50
		0070	0490	5059907	MISC.MODIFIED SUPPLEMENTARY WEARING SURFACE MATERIAL	10.00	0.00	10.00	CUYD	10.00	\$5,725.00	\$57,250.00
		0070	0500	7034600	CURB BLOCKOUT	413.00	0.00	413.00	LF	413.00	\$135.00	\$55,755.00
		0070	0510	7040104	HALF-SOLE REPAIR	1,250.00	-41.00	1,209.00	SQFT	1,209.00	\$7.15	\$8,644.35
		0070	0520	7040106	FULL DEPTH REPAIR	50.00	-50.00	0.00	SQFT	0.00	\$350.00	\$0.00
		0070	0530	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	150.00	39.00	189.00	SQFT	189.00	\$360.00	\$68,040.00
	0070 0540 7049902 MISC.Core				MISC.Cored Void Tube Weep Holes	172.00	-8.00	164.00	EA	164.00	\$100.00	\$16,400.00
		0071	0550	2169905	MISC.Scarification by Diamond Grinding of Bridge Deck	500.00	0.00	500.00	SQYD	500.00	\$39.00	\$19,500.00
		0071	0560	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	99.00	0.00	99.00	SQYD	99.00	\$300.00	\$29,700.00
		0071	0570	5059905	MISC.High Performance Concrete Wearing Surface	500.00	0.00	500.00	SQYD	500.00	\$543.00	\$271,500.00
		0071	0580	7034600	CURB BLOCKOUT	410.00	0.00	410.00	LF	410.00	\$143.00	\$58,630.00
		0071	0590	7040104	HALF-SOLE REPAIR	1,800.00	36.00	1,836.00	SQFT	1,836.00	\$7.75	\$14,229.00
		0071	0600	7040106	FULL DEPTH REPAIR	50.00	-21.00	29.00	SQFT	29.00	\$346.70	\$10,054.30
		0071	0610	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	200.00	-104.00	96.00	SQFT	96.00	\$364.00	\$34,944.00
		0071	0620	7049902	MISC.Cored Void Tube Weep Holes	238.00	-52.00	186.00	EA	186.00	\$100.00	\$18,600.00
		0071	0630	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$8,000.00	\$8,000.00
		0001	5001	6189901	MISC.Mobilization Adjusted for Contract Bond	\$41,256.00	\$41,256.00					
		0070	5002	5059901	MISC.Additional wearing surface test pour demonstration.	0.00	1.00	1.00	LS	1.00	\$3,000.00	\$3,000.00
	Project J	5S3448 - To	tal Value	Posted to D	ate as of Report Generated Date							\$1,532,357.45
220318-D01 Ove	erall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$1,532,357.45

Revision 4/1/2020 Page 6 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date		Units		From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0320	8061005	ROCK DITCH CHECK	12/28/22	1/4/23	20.00	LF	2-10' ditch checks on each side of 18" pipe					

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 7 of 14



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3448	0030	CLASS A EXCAVATION	Price FUEL		9	Nov 17, 2022	SYSTEM	\$83.50	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Dec 1, 2022	SYSTEM	\$39.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$122.98	
			Price FUEL -	Total				\$122.98	
	0030 -	Total						\$122.98	
	0040	EMBANKMENT IN PLACE	Material		9	Nov 17, 2022	SYSTEM	\$13,152.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$13,152.00)	
					10	Dec 1, 2022	SYSTEM	\$75,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Dec 1, 2022	SYSTEM	(\$75,192.00)	
					11	Dec 16, 2022	SYSTEM	\$75,192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Dec 16, 2022	SYSTEM	(\$75,192.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		9	Nov 17, 2022	SYSTEM	\$272.36	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Dec 1, 2022	SYSTEM	\$1,284.74	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$1,557.10	
			Price FUEL -	Total				\$1,557.10	
	0040 -	Total						\$1,557.10	
	0050	COMPACTING EMBANKMENT	Material		9	Nov 17, 2022	SYSTEM	\$2,017.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$2,017.20)	
					10	Dec 1, 2022	SYSTEM	\$2,968.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Dec 1, 2022	SYSTEM	(\$2,968.40)	
						11	Dec 16, 2022	SYSTEM	\$2,968.40
					11	Dec 16, 2022	SYSTEM	(\$2,968.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0050 -	Total						\$0.00	
	0070	TYPE 1 AGGREGATE FOR BASE (4 IN.	Price FUEL		8	Nov 2, 2022	SYSTEM	\$3.06	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		THICK)			10	Dec 1, 2022	SYSTEM	\$25.69	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$28.75	
			Price FUEL -	Total				\$28.75	
	0070 -	Total						\$28.75	
	0160	TYPE III MOVEABLE	Overrun	Overrun	6	Sep 30, 2022	SYSTEM	(\$125.00)	
		BARRICADE			9	Nov 17, 2022	SYSTEM	\$125.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',125.00000 - 125.00000, 'is applied (if non-zero).



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J5S3448	0160	TYPE III	Overrun	Overrun - T	otal			\$0.00							
		MOVEABLE BARRICADE	Overrun - To	tal				\$0.00							
	0160 -	Total						\$0.00							
	0250	4 IN. YELLOW WATERBORNE PAVEMENT	Material		11	Dec 16, 2022	SYSTEM	\$2,399.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woods6 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
		MARKING			11	Dec 16, 2022	SYSTEM	(\$2,399.40)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
			Other Item Adjustment	REFL	11	Dec 16, 2022	woods6	(\$479.88)	20% withheld for retro results.						
			,	REFL - Tota	1			(\$479.88)							
			Other Item A	djustment - T				(\$479.88)							
	0250 -	Total	Other item A	ujustilielit - 1	Otal			(\$479.88)							
			Material		9	Nov 17.	CVCTEM		This adjustment offsets the eviginal system generated Material Dayment						
	0260	PERMANENT EROSION CONTROL GEOTEXTILE	Material		9	2022	SYSTEM	\$238.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
		GEOTEXTILE			9	Nov 17, 2022	SYSTEM	(\$238.56)							
					10	Dec 1, 2022	SYSTEM	\$685.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 11 on the current Payment Estimate.						
					10	Dec 1, 2022	SYSTEM	(\$685.15)							
											11	Dec 16, 2022	SYSTEM	\$685.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					11	Dec 16, 2022	SYSTEM	(\$685.15)							
					12	Jan 4, 2023	SYSTEM	\$685.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woods6 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
					12	Jan 4, 2023	SYSTEM	(\$685.15)							
				- Total	Total										
			Material - To	tal				\$0.00							
	0260 -	Total						\$0.00							
	0300	SEEDING - COOL SEASON GRASSES	Other Item Adjustment	OTHR	11	Dec 16, 2022	woods6	(\$1,518.00)	20% withheld for seed growth						
				OTHR - Total				(\$1,518.00)							
			Other Item Adjustment - Total					(\$1,518.00)							
	0300 -	Total						(\$1,518.00)							
	0320	ROCK DITCH CHECK	Material	Material	Material		12	Jan 4, 2023	SYSTEM	\$344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woods6 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					12	Jan 4, 2023	SYSTEM	(\$344.00)							
				- Total				\$0.00							
			Material - To	Material - Total											
	0320 -	320 - Total													
	0340	SILT FENCE	T FENCE Material		7	Oct 15, 2022	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woods6 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
					7	Oct 15, 2022	SYSTEM	(\$13,000.00)							
					8	Nov 2, 2022	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user davisg7 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
					8	Nov 2, 2022	SYSTEM	(\$13,000.00)	•						



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
48	0340	SILT FENCE	Material		9	Nov 17, 2022	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woods6 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					9	Nov 17, 2022	SYSTEM	(\$13,000.00)		
				- Total				\$0.00		
			Material - Tot	tal				\$0.00		
	0340 -	Total						\$0.00		
	0350	MGS GUARDRAIL	Construction Stockpile		9	Nov 17, 2022	SYSTEM	(\$8,426.83)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					10	Dec 1, 2022	SYSTEM	(\$21,590.42)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$30,017.25)		
			Construction	Stockpile - 1	Total			(\$30,017.25)		
			Construction Stockpile STMI		1	Jun 6, 2022	SYSTEM	\$30,017.25	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$30,017.25		
			Construction	n Stockpile STMI - Total				\$30,017.25		
			Material		9	Nov 17, 2022	SYSTEM	\$8,431.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woods6 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					9	Nov 17, 2022	SYSTEM	(\$8,431.25)		
						10	Dec 1, 2022	SYSTEM	\$53,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Dec 1, 2022	SYSTEM	(\$53,250.00)		
						11	Dec 16, 2022	SYSTEM	\$53,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 7 on the current Payment Estimate.
						11	Dec 16, 2022	SYSTEM	(\$53,250.00)	
						12	Jan 4, 2023	SYSTEM	\$53,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woods6 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					12	Jan 4, 2023	SYSTEM	(\$53,250.00)		
				- Total				\$0.00		
			Material - Tot	tal				\$0.00		
	0350 -	Total						\$0.00		
	0360	MGS BRIDGE APP. TRANS SEC (REG/NO			9	Nov 17, 2022	SYSTEM	(\$14,202.64)	, , ,	
		CURB)			10	Dec 1, 2022	SYSTEM	(\$852.16)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$15,054.80)		
				Stockpile - 1				(\$15,054.80)		
			Construction Stockpile STMI		5	Sep 16, 2022	SYSTEM	\$15,054.80	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$15,054.80		
			Construction	Stockpile S	MI - Total			\$15,054.80		
	0360 -	Total						\$0.00		
	0370	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		9	Nov 17, 2022	SYSTEM	(\$13,588.85)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		(MASH)		- Total	10	Dec 1, 2022	SYSTEM	(\$2,011.15)	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Construction		Cotal					
				Stockpile - 1		lum O	OVOTEL	(\$15,600.00)	December 5-directs them Adjustment as a 1-1-21-1-7-7	
			Construction Stockpile		1	Jun 6, 2022	SYSTEM	\$15,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J5S3448	0370	TYPE A CRASHWORTHY END TERMINAL (MASH)	STMI	STMI - Total												
			Construction	Stockpile S1	MI - Total			\$15,600.00								
	0370 -	· Total						\$0.00								
	0380	CONCRETE FOOTINGS, EMBEDDED	Material		9	Nov 17, 2022	SYSTEM	\$148.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woods6 overridding Payment Estimate Exception 11 on the current Payment Estimate.							
					9	Nov 17, 2022	SYSTEM	(\$148.00)								
					10	Dec 1, 2022	SYSTEM	\$148.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment Estimate Exception 13 on the current Payment Estimate.							
					10	Dec 1, 2022	SYSTEM	(\$148.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0380 -	· Total						\$0.00								
	0390	BREAKAWAY ASSEMBLY (PERFORATED	Material		11	Dec 16, 2022	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 12 on the current Payment Estimate.							
		SQUARE STEEL TUBE)			11	Dec 16, 2022	SYSTEM	(\$500.00)								
												12	Jan 4, 2023	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Jan 4, 2023	SYSTEM	(\$500.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0390 -	· Total						\$0.00								
	0400	2.25 IN. PSST POST - 12 GA.	Material		11	Dec 16, 2022	SYSTEM	\$241.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woods6 overridding Payment Estimate Exception 13 on the current Payment Estimate.							
					11	Dec 16, 2022	SYSTEM	(\$241.50)								
					12	Jan 4, 2023	SYSTEM	\$241.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
					12	Jan 4, 2023	SYSTEM	(\$241.50)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0400 -	· Total						\$0.00								
	0430	SH-FLAT SHEET	Material		11	Dec 16, 2022	SYSTEM	\$194.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
					11	Dec 16, 2022	SYSTEM	(\$194.00)								
				12	12	Jan 4, 2023	SYSTEM	\$194.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 11 on the current Payment Estimate.							
					12	Jan 4, 2023	SYSTEM	(\$194.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0430 -	· Total						\$0.00								
	0470	BRIDGE APPROACH SLAB (MINOR	Material		10	Dec 1, 2022	SYSTEM	\$28,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
		ROAD)			10	Dec 1,	SYSTEM	(\$28,170.00)								
						2022										



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3448	0470	BRIDGE APPROACH SLAB (MINOR	Material			2022			Estimate Item Adjustment (0009) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		ROAD)			11	Dec 16, 2022	SYSTEM	(\$28,170.00)	
					12	Jan 4, 2023	SYSTEM	\$28,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Jan 4, 2023	SYSTEM	(\$28,170.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0470 -							\$0.00	
	0500	CURB BLOCKOUT	Material		6	Sep 30, 2022	SYSTEM	\$55,755.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Sep 30, 2022	SYSTEM	(\$55,755.00)	
					7	Oct 15, 2022	SYSTEM	\$55,755.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Oct 15, 2022	SYSTEM	(\$55,755.00)	
					8	Nov 2, 2022	SYSTEM	\$55,755.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user davisg7 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Nov 2, 2022	SYSTEM	(\$55,755.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0500 -	500 - Total						\$0.00	
	0510	HALF-SOLE REPAIR	Material		7	Oct 15, 2022	SYSTEM	\$3,207.49	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Oct 15, 2022	SYSTEM	(\$3,207.49)	
		Material - Total						\$0.00	
			Material - To	- Total tal				\$0.00 \$0.00	
	0510 -		Material - To						
	0510 - 0530	DECK REPAIR WITH VOID TUBE	Material - To		7	Oct 15, 2022	SYSTEM	\$0.00 \$0.00 \$40,104.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		DECK REPAIR WITH VOID			7		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0005) due to user woods6 overridding Payment
		DECK REPAIR WITH VOID TUBE				2022 Oct 15,		\$0.00 \$0.00 \$40,104.00	Estimate Item Adjustment (0005) due to user woods6 overridding Payment
		DECK REPAIR WITH VOID TUBE			7	2022 Oct 15, 2022 Nov 2,	SYSTEM	\$0.00 \$0.00 \$40,104.00 (\$40,104.00)	Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davisg7 overridding Payment
		DECK REPAIR WITH VOID TUBE			7	2022 Oct 15, 2022 Nov 2, 2022 Nov 2,	SYSTEM	\$0.00 \$0.00 \$40,104.00 (\$40,104.00) \$18,144.00	Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davisg7 overridding Payment
		DECK REPAIR WITH VOID TUBE		tal - Total	7	2022 Oct 15, 2022 Nov 2, 2022 Nov 2,	SYSTEM	\$0.00 \$0.00 \$40,104.00 (\$40,104.00) \$18,144.00	Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davisg7 overridding Payment
		DECK REPAIR WITH VOID TUBE	Material	tal - Total	7 8 8	2022 Oct 15, 2022 Nov 2, 2022 Nov 2,	SYSTEM	\$0.00 \$0.00 \$40,104.00 (\$40,104.00) \$18,144.00 (\$18,144.00)	Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davisg7 overridding Payment
		DECK REPAIR WITH VOID TUBE	Material Material - To	- Total tal	7 8 8	2022 Oct 15, 2022 Nov 2, 2022 Nov 2, 2022 Nov 2, 2022	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$40,104.00 (\$40,104.00) \$18,144.00 (\$18,144.00) \$0.00	Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davisg7 overridding Payment Estimate Exception 6 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all
		DECK REPAIR WITH VOID TUBE	Material Material - To	- Total tal	7 8 8 8	2022 Oct 15, 2022 Nov 2, 2022 Nov 2, 2022 Nov 2, 2022 Nov 17, 17, 17, 17, 17, 17, 17, 17, 17, 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$40,104.00 (\$40,104.00) \$18,144.00 (\$18,144.00) \$0.00 \$0.00 (\$144.00)	Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davisg7 overridding Payment Estimate Exception 6 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',360.00000 - 360.00000, 'i
		DECK REPAIR WITH VOID TUBE	Material Material - To	- Total tal Overrun Overrun - T	7 8 8 8	2022 Oct 15, 2022 Nov 2, 2022 Nov 2, 2022 Nov 2, 2022 Nov 17, 17, 17, 17, 17, 17, 17, 17, 17, 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$40,104.00 (\$40,104.00) \$18,144.00 (\$18,144.00) \$0.00 (\$144.00)	Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davisg7 overridding Payment Estimate Exception 6 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',360.00000 - 360.00000, 'i
		DECK REPAIR WITH VOID TUBE REPLACEMENT	Material - To Overrun	- Total tal Overrun Overrun - T	7 8 8 8	2022 Oct 15, 2022 Nov 2, 2022 Nov 2, 2022 Nov 2, 2022 Nov 17, 17, 17, 17, 17, 17, 17, 17, 17, 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$40,104.00 (\$40,104.00) \$18,144.00 (\$18,144.00) \$0.00 (\$144.00) \$144.00	Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davisg7 overridding Payment Estimate Exception 6 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',360.00000 - 360.00000, 'is
	0530	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material - To Overrun	- Total tal Overrun Overrun - T	7 8 8 8	2022 Oct 15, 2022 Nov 2, 2022 Nov 2, 2022 Nov 2, 2022 Nov 17, 17, 17, 17, 17, 17, 17, 17, 17, 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$40,104.00 (\$40,104.00) \$18,144.00 (\$18,144.00) \$0.00 (\$144.00) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user davisg7 overridding Payment Estimate Exception 6 on the current Payment Estimate. Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',360.00000 - 360.00000, 'is



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3448	0560	BRIDGE	Material			2022			
		APPROACH SLAB (MINOR ROAD)			9	Nov 17, 2022	SYSTEM	\$29,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Nov 17, 2022	SYSTEM	(\$29,700.00)	
					10	Dec 1, 2022	SYSTEM	\$29,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woods6 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Dec 1, 2022	SYSTEM	(\$29,700.00)	
					11	Dec 16, 2022	SYSTEM	\$29,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woods6 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Dec 16, 2022	SYSTEM	(\$29,700.00)	
					12	Jan 4, 2023	SYSTEM	\$29,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Jan 4, 2023	SYSTEM	(\$29,700.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0560 -	Total						\$0.00	
	0580	CURB BLOCKOUT	Material		4	Sep 2, 2022	SYSTEM	\$58,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Sep 2, 2022	SYSTEM	(\$58,630.00)	
					5	Sep 16, 2022	SYSTEM	\$58,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Sep 16, 2022	SYSTEM	(\$58,630.00)	
					6	Sep 30, 2022	SYSTEM	\$58,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woods6 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Sep 30, 2022	SYSTEM	(\$58,630.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0580 -	Total						\$0.00	
	0590	HALF-SOLE REPAIR	Material		5	Sep 16, 2022	SYSTEM	\$1,409.57	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Sep 16, 2022	SYSTEM	(\$1,409.57)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
			Overrun	Overrun	7	Oct 15, 2022	SYSTEM	(\$279.00)	
					9	Nov 17, 2022	SYSTEM	\$279.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',7.75000 - 7.75000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0590 -	Total						\$0.00	
	0600	FULL DEPTH REPAIR	Material		5	Sep 16, 2022	SYSTEM	\$10,140.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Sep 16, 2022	SYSTEM	(\$10,140.98)	
				- Total				\$0.00	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3448	0600	FULL DEPTH REPAIR	Material - Tot	al				\$0.00	
	0600 -	600 - Total							
	0610	DECK REPAIR WITH VOID TUBE	Material	Material	5	Sep 16, 2022	SYSTEM	\$13,832.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		REPLACEMENT			5		SYSTEM	(\$13,832.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0610 -	Total						\$0.00	
J5S3448 -	- Total							(\$289.05)	
Overall -	Total						(\$289.05)		