

Pay Estimate Created Date: March 16, 2023

Progress Estimate N 5	umber	Contract ID Prime Contracto	220819-H03 r Emery Sapp & Se	ons, Inc.	Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,451,654.55 \$0.00 \$2,451,654.55
Approval Date								By User
March 16, 2023			Generated and	Approved	(and should be cor	nsidered Draft)	at the Project Office Level by	thomar1
March 16, 2023		R	eviewed and Appro	oved (and	should be conside	red Draft) at the	Resident Engineer Level by	stottt1
March 17, 2023				Reviewed	and Approved at t	he Central Offic	e Controllers Office Level by	ramses1
Original Completion	n Date	Current Cor	npletion Date	Actu	al Completion Da	ite	% of Current Contract Amoun	t Complete
October 1, 2023	3	Octobe	r 1, 2023				50.97%	
	Contrac	t Informational Dat	tes		Milest	ones		
Date Description	Original	Completion Date	Current Complet	ion Date	No Milestones E	xist for Contrac	t	
Acceptance Date								
Awarded Date	Septemb	per 7, 2022	September 7, 202	2				
Letting Date	August 1	19, 2022	August 19, 2022					
Notice to Proceed Date	October	11, 2022	October 11, 2022					
Open to Traffic Date								
Work Began Date								

Contract Total Pay	For Estimate No. 5			
		This Estimate	Previous	To Date
220819-H03				
	Total Posted Items Pay	\$161,318.50	\$1,088,182.14	\$1,249,500.64
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$1,088,182.14	\$1,249,500.64
Contract Total Pay	able This Estimate:	\$161,318.50		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9P3586	0020	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$195.000	36.8	\$7,176.00
	0030	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	SQYD	\$8.000	36.8	\$294.40
	0040	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	SQYD	\$23.000	36.7	\$844.10
	0050	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$2.500	167	\$417.50
	0060	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$8.750	78	\$682.50
	0080	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	EA	\$5.000	48	\$240.00
	0110	6134001	DOWEL BAR RETROFIT	EA	\$64.000	2,369.75	\$151,664.00
^v roject J9	P3586 - T	otal					\$161,318.50
Overall - 1	Total						\$161,318.50

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

	Aujust	inenta Thia Latinate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3586	0020	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT				-3,104.77	\$195.00	(\$605,430.15



Pay Estimate Created Date: March 16, 2023

Progre	ess Est	timate Number 5	Contract ID Prime Contr		9-H03 / Sapp & Son	s, Inc. Pay Period End March 15, 2023 Net	inal Contract Change Orde rent Contract	r Amount	\$2,451,654.55 \$0.00 \$2,451,654.55
Project Number	Line No.	Item Descr	iption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
9P3586			REPAIR						
	0020	FURNISHING AN CONCRETE MAT FULL DEPTH	ERIAL FOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	3,104.77	\$195.00	\$605,430.15
	0060	DOWEL BAR FURNI INSTALLATION DEPTH PAVEME	SHING AND FOR FULL	Material			-354	\$8.75	(\$3,097.50
	0060	DOWEL BAR FURNI INSTALLATION; DEPTH PAVEME	SHING AND FOR FULL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	354	\$8.75	\$3,097.50
	0070	DOWEL BAR (F AND INSTALLA BASKETS DEPTH PAVEME	TION WITH) FOR FULL	Material			-1,036	\$12.00	(\$12,432.00
	0070	DOWEL BAR (F AND INSTALLA BASKETS DEPTH PAVEME	TION WITH) FOR FULL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user thomar1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1,036	\$12.00	\$12,432.00
	0080	FURNI INSTALLATION DEPTH PAVEME		Material			-539	\$5.00	(\$2,695.00
	0080	FURNI INSTALLATION DEPTH PAVEME		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user thomar1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	539	\$5.00	\$2,695.00
	0090	FURNISHING AN CONCRETE MAT CLASS A PAR PAVEME	ERIAL FOR	Material			-0.8	\$1,331.00	(\$1,064.80
	0090	FURNISHING AN CONCRETE MAT CLASS A PAR PAVEME	ERIAL FOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user thomar1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	0.8	\$1,331.00	\$1,064.80
otal									\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Information	1
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9P3586	FAF 412-1(18)	Pavement rehabilitation	412	DUNKLIN	from Route 25 to I-155		
Totals by 、	Job Numbe	rs					
J9P3586					This Estimate	Previous	To Date
	Postec	d Item Pay			\$161,318.50	\$1,088,182.14	\$1,249,500.64
	Gross	Item Adjustme	ents		\$0.00	\$0.00	\$0.00
			Gross	Item Pay	\$161,318.50	\$1,088,182.14	\$1,249,500.64
	Incent	ive			\$0.00	\$0.00	\$0.00
	Disinc	entive			\$0.00	\$0.00	\$0.00
	Liquid	ated Damages			\$0.00	\$0.00	\$0.00
					\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3586, Item 6131010, Project Item Line Number 0020, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Contractor put there tests under the wrong material code.	thomar1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3586, Item 6131015, Project Item Line Number 0060, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Need Certification for Epoxy bonding agent.	thomar1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3586, Item 6131017, Project Item Line Number 0070, Material Set 613101796, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Need Certification for Epoxy bonding agent.	thomar1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3586, Item 6131017, Project Item Line Number 0070, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials need to remove the dowel bars that are not used.	thomar1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3586, Item 6131018, Project Item Line Number 0080, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Waiting on certification for epoxy bonding agent.	thomar1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3586, Item 6131018, Project Item Line Number 0080, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials need to remove the dowel bars that are not used.	thomar1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3586, Item 6132018, Project Item Line Number 0090, Material Set 613201896, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Material test was not reported to Line #.	thomar1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3586, Item 6132018, Project Item Line Number 0090, Material Set 613201896, Material 1036RSWFPLW6W4 - W6.3-W4 Plain Weld Wire Fabric for PCCP@, Acceptance Action Generic ReSteelFabric is insufficient.	Material test was not reported to Line #.	thomar1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
0819-H03	J9P3586	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.25	\$35,000.00	\$8,750.0
		0001	0020	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	4,486.70	0.00	4,486.70	SQYD	3,104.77	\$195.00	\$605,430.1
		0001	0030	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	3,261.00	0.00	3,261.00	SQYD	2,661.45	\$8.00	\$21,291.6
		0001	0040	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	3,261.00	0.00	3,261.00	SQYD	2,661.35	\$23.00	\$61,211.0
		0001	0050	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	11,198.00	0.00	11,198.00	LF	7,635.00	\$2.50	\$19,087.5
		0001	0060	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	740.00	0.00	740.00	EA	354.00	\$8.75	\$3,097.5
		0001	0070	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	1,496.00	0.00	1,496.00	EA	1,036.00	\$12.00	\$12,432.0
		0001	0080	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	720.00	0.00	720.00	EA	539.00	\$5.00	\$2,695.0
		0001	0090	6132018	FURNISHING AND PLACING CONCRETE MATERIAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	11.20	0.00	11.20	CUYD	0.80	\$1,331.00	\$1,064.8
		0001	0100	6132019	REMOVAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	80.00	0.00	80.00	SQYD	4.11	\$364.00	\$1,496.0
		0001	0110	6134001	DOWEL BAR RETROFIT	9,303.00	0.00	9,303.00	EA	4,739.50	\$64.00	\$303,328.0
		0001	0120	6134002	CROSS STITCH TIE BAR	1,242.00	0.00	1,242.00	EA	285.00	\$60.00	\$17,100.0
		0001	0130	6161005	CONSTRUCTION SIGNS	660.00	0.00	660.00	SQFT	208.00	\$10.00	\$2,080.0
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	200.00	\$21.00	\$4,200.0
		0001	0150	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	1.00	\$995.00	\$995.0
		0001	0160	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,746.00	\$7,492.0
		0001	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$237,000.00	\$177,750.0
		0001	0180	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	14,636.00	0.00	14,636.00	LF	0.00	\$0.47	\$0.0
		0001	0190	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	11,569.00	0.00	11,569.00	LF	0.00	\$0.47	\$0.
		0001	0200	6223010	DIAMOND GRINDING (CONCRETE PAVEMENT)	30,850.00	0.00	30,850.00	SQYD	0.00	\$5.95	\$0.
		0001	0210	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	47,900.00	0.00	47,900.00	LB	0.00	\$4.50	\$0.0



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line lumber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	3/14/23	3/16/23	1.10	SQYD	Driving lane of the EBL. size 5'x2'	25.876		0		
				3/16/23	9.30	SQYD	Driving lane of the EBL. size 14'x6'	26.354		0		
				3/16/23	9.30	SQYD	Driving lane of the EBL. size 14'x6'	26.380		0		
				3/16/23	17.10	SQYD	Driving lane of the WBL. size 14'x11'	25.654		0		
0030	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	3/14/23	3/16/23	1.10	SQYD	Driving lane of the EBL. size 5'x2'	25.876		0		
				3/16/23	9.30	SQYD	Driving lane of the EBL. size 14'x6'	26.354		0		
				3/16/23	9.30	SQYD	Driving lane of the EBL. size 14'x6'	26.380		0		
				3/16/23	17.10	SQYD	Driving lane of the WBL. size 14'x11'	25.654		0		
0040	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	3/14/23	3/16/23	1.10	SQYD	Driving lane of the EBL. size 5'x2'	25.876		0		
				3/16/23	9.30	SQYD	Driving lane of the EBL. size 14'x6'	26.354		0		
				3/16/23	9.30	SQYD	Driving lane of the EBL. size 14'x6'	26.380		0		
				3/16/23	17.00	SQYD	Driving lane of the WBL. size 14'x11'	25.654		0		
0050	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	3/14/23	3/16/23	14.00	LF	Driving lane of the EBL. size 5'x2'	25.876		0		
				3/16/23	46.00	LF	Driving lane of the EBL. size 14'x6'	26.354		0		
				3/16/23	46.00	LF	Driving lane of the EBL. size 14'x6'	26.380		0		
				3/16/23	61.00	LF	Driving lane of the WBL. size 14'x11'	25.654		0		
0060	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	3/14/23	3/16/23	6.00	EA	Driving lane of the EBL. size 5'x2'	25.876		0		
				3/16/23	24.00	EA	Driving lane of the EBL. size 14'x6'	26.354		0		
				3/16/23	24.00	EA	Driving lane of the EBL. size 14'x6'	26.380		0		
				3/16/23	24.00	EA	Driving lane of the WBL. size 14'x11'	25.654		0		
0080	6131018	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	3/14/23	3/16/23	6.00	EA	Driving lane of the EBL. size 5'x2'	25.876		0		
				3/16/23	14.00	EA	Driving lane of the EBL. size 14'x6'	26.354		0		
				3/16/23	14.00	EA	Driving lane of the EBL. size 14'x6'	26.380		0		
				3/16/23	14.00	EA	Driving lane of the WBL. size 14'x11'	25.654		0		
0110	6134001	DOWEL BAR RETROFIT	3/14/23	3/16/23	377.50	EA	Driving lane of the WBL.	24.218		24.394		
				3/16/23	940.75	EA	Driving lane of the WBL.	24.518		25.167		
				3/16/23	1,051.50	EA	Driving lane of the WBL.	23.192		23.687		

The information below this line are details for Construction Signs (if applicable). No Data Available



Line Item Adjustments by Estimate

Contract ID: 220819-H03

Project Line Description Adjustment Type Other Number Est. Date Created By Amount Amount Remarks J9P336 020 FURN & FLACE FULL DEPTH Material FULL DEPTH Material Full DEPTH Material Full DEPTH Image: Full DEPTH Full DEPTH Material Full DEPTH Sectors SYSTEM S345,797.40 This adjustment offsets the original system-general Estimate Exception 1 on the current Payment Estimate Estimate Exception 2 on the current Payment Estimate Estimate Exception 2 on the current Payment Estimate Estimate Exception 4 on the current Payment Estimate Estimate Exception 5 on the current Payment Estimate Es	mar1 overridding Payment timate. rated Material Payment mar1 overridding Payment timate. rated Material Payment mar1 overridding Payment
JPP3586 0020 FURN & PLACE CONCIMATL FOR FULL DEFINE Material Full DEFINE Material Full DEFINE Material Full DEFINE Material Full DEFINE Material Full DEFINE Material Full DEFINE State Full DEFINE State Full DEFINE State Full DEFINE Full State Full DEFINE Full State Full DEFINE Full State Full DEFINE Full DEFINE Material Full DEFINE Full DE	mar1 overridding Payment timate. rated Material Payment mar1 overridding Payment timate. rated Material Payment mar1 overridding Payment
CONC MATL FOR FULL DEPTH	mar1 overridding Payment timate. rated Material Payment mar1 overridding Payment timate. rated Material Payment mar1 overridding Payment
040 For any and a set of	mar1 overridding Payment timate. rated Material Payment mar1 overridding Payment
0040 For adjustment (0001) due to user thom Estimate Exception 1 on the current Payment Estimate Exception 2 on the current	mar1 overridding Payment timate. rated Material Payment mar1 overridding Payment
Image: Constraint of the	mar1 overridding Payment
0020 - Total 5 Mar 16, 2023 SYSTEM (\$605,430.15) 0020 - Total 5 Mar 16, 2023 SYSTEM (\$605,430.15) 0020 - Total 5 SYSTEM (\$605,430.15) 5 0020 - Total 5 SYSTEM (\$605,430.15) 5 0020 - Total 5 SYSTEM \$0.00 5 0020 - Total 5 SYSTEM \$30,590.00 This adjustment offsets the original system-general Estimate tem Adjustment (0002) due to user thom Estimate Exception 4 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 4 on the current Paymen	mar1 overridding Payment
Odd Order of the transmitter of tra	
Solution Solution OUD - Total Solution OUD TYPE 1 OR 5 AGGREGATE FOR BASE (4) IN TH Addressed of the original system-general Estimate tem Adjustment (0002) due to user thom Estimate Exception 4 on the current Payment Estimate Estimate Exception 5 on the current Payment Estimate Estimate Exception 4 on the current Payment Estimate Estimate Exception 5 on the current Payment Estimate Estimate Exception 5 on the current Payment Estimate Estimate Exception 4 on the current Payment Estimate Estimate Exception 2 on the current Paym	
0020 - Total \$0.00 0040 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH Material AGGREGATE FOR BASE (4 IN. TH Subsect (50,00,00) SYSTEM \$\$30,590.00 This adjustment offsets the original system-general Estimate Exception 4 on the current Payment Estim Estimate Exception 4 on the current Payment Estim (5,000) 0040 - Total Subsect (1,00,00) Subsect (1,00,00) This adjustment offsets the original system-general Estimate Item Adjustment (0003) due to user thom Estimate Exception 5 on the current Payment Estim (001,00,00) 0060 DOWEL BAR (DRILLING, FURNISHING AND INST Material (1,00,00) SYSTEM \$\$1,050.00 This adjustment offsets the original system-general Estimate Item Adjustment (0003) due to user thom Estimate Exception 5 on the current Payment Estim (1,002,00) Mar 1, 2023 SYSTEM \$\$1,050.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom Estimate Exception 4 on the current Payment Estim Estimate Item Adjustment (0002) due to user thom Estimate Exception 4 on the current Payment Estim Estimate Item Adjustment (0002) due to user thom Estimate Item Adjustment (0002) due to user thom	
0040 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN, TH Material Herial 3 Feb 2, 2023 SYSTEM \$30,590.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom. Estimate Exception 4 on the current Payment Estin Subscription 4 on the current Paymen	
AGGREGATE FOR BASE (4 IN. TH Estimate Item Adjustment (0002) due to user thom. Estimate Exception 4 on the current Payment Estin S0.00 0040 - Total S0.00 OU40 - Total OU40 - Total S0.00 OU40 - Total OU40 - Total OU40 - Total Sumation and the current Payment Estin OU40 - Total OU40 - Tota	
040 - Total - Total \$0.00 040 - Total \$0.00 0060 DOWEL BAR (DRILLING, FURNISHING AND INST Material \$3 Feb 2, 2023 \$YSTEM \$1,050.00 0060 DOWEL BAR (DRILLING, FURNISHING AND INST Material \$3 Feb 2, 2023 \$YSTEM \$1,050.00 This adjustment offsets the original system-general Estimate Item Adjustment (0003) due to user thom. Estimate Exception 5 on the current Payment Estin Estimate Item Adjustment (0002) due to user thom. Estimate Item Adjustment (0002) due to user thom.	mar1 overridding Payment
Oddo - Total S0.00 0040 - Total \$0.00 0060 DOWEL BAR (DRILLING, FURNISHING AND) INST Material 1 3 Feb 2, 2023 SYSTEM \$1,050.00 This adjustment offsets the original system-general Estimate Item Adjustment (0003) due to user thom. 1 3 Feb 2, 2023 SYSTEM \$1,050.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom. 1 3 Feb 2, 2023 SYSTEM \$1,050.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom. 1 2023 SYSTEM \$2,415.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom. 2023 SYSTEM \$2023 SYSTEM \$2,415.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom. 5 Mar 16, 2023 SYSTEM \$3,097.50 This adjustment offsets the original system-general Estimate Exception 2 on the current Payment Estimate	
0040 - Total \$0.00 0060 DOWEL BAR (DRILLING, FURNISHING AND INST Material 3 Feb 2, 2023 SYSTEM \$1,050.00 This adjustment offsets the original system-general Estimate Item Adjustment (0003) due to user thom Estimate Exception 5 on the current Payment Estin 3 Feb 2, 2023 SYSTEM (\$1,050.00) This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom Estimate Item Adjustment (0002) due to user thom Estimate Exception 4 on the current Payment Estin 4 Mar 1, 2023 SYSTEM \$2,415.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom Estimate Exception 4 on the current Payment Estin 5 Mar 16, 2023 SYSTEM \$3,097.50 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom Estimate Exception 2 on the current Payment Estin	
0060 DOWEL BAR (DRILLING, FURNISHING AND INST Material 3 Feb 2, 2023 SYSTEM \$1,050.00 This adjustment offsets the original system-general Estimate Item Adjustment (0003) due to user thom. 3 Feb 2, 2023 SYSTEM \$1,050.00 This adjustment offsets the original system-general Estimate Exception 5 on the current Payment Estim 4 Mar 1, 2023 SYSTEM \$2,415.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom. 4 Mar 1, 2023 SYSTEM \$2,415.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom. 5 Mar 16, 2023 SYSTEM \$3,097.50 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom. 5 Mar 16, 2023 SYSTEM \$3,097.50 This adjustment offsets the original system-general Estimate Exception 2 on the current Payment Estim	
(DRILLING, FURNISHING AND INST (DRILLING, FURNISHING AND INST 2023 2023 Estimate Item Adjustment (0003) due to user thom. Estimate Exception 5 on the current Payment Estim 3 Feb 2, 2023 SYSTEM (\$1,050.00) 4 Mar 1, 2023 SYSTEM \$2,415.00 4 Mar 1, 2023 SYSTEM (\$2,415.00) 5 Mar 16, 2023 SYSTEM \$3,097.50 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom. Estimate Exception 2 on the current Payment Estim	
3 Feb 2, 2023 SYSTEM (\$1,050.00) 4 Mar 1, 2023 SYSTEM \$2,415.00 This adjustment offsets the original system-general Estimate Item Adjustment (0002) due to user thom. Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate Item Adjustment (0002) due to user thom. Estimate Exception 4 on the current Payment Estimate Exception 2 on the current Payment Estimate Estimate Estimate Exception 2 on the current Payment Estimate Estim	mar1 overridding Payment
2023 2023 Estimate Item Adjustment (0002) due to user thom. Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate Item Adjustment offsets the original system-generate Estimate Item Adjustment (0002) due to user thom. Estimate Exception 2 on the current Payment Estimate Item Adjustment (0002) due to user thom. Estimate Exception 2 on the current Payment Estimate Estimate Estimate Exception 2 on the current Payment Estimate Est	
2023 2023 Ctrick of all all all all all all all all all al	mar1 overridding Payment
2023 Estimate Item Adjustment (0002) due to user thom. Estimate Exception 2 on the current Payment Estimate 5 Mar 16, SYSTEM (\$3,097.50)	
	mar1 overridding Payment
2023	
- Total \$0.00	
Material - Total \$0.00	
0060 - Total \$0.00	
0070 DOWEL BAR (FURNISH AND INSTALL WITH Material 3 Feb 2, 2023 SYSTEM \$7,392.00 This adjustment offsets the original system-general Estimate Item Adjustment (0004) due to user thom Estimate Exception 6 on the current Payment Estimate	mar1 overridding Payment
BASK 3 Feb 2, 2023 SYSTEM (\$7,392.00)	
4 Mar 1, 2023 SYSTEM \$12,432.00 This adjustment offsets the original system-general Estimate Item Adjustment (0003) due to user thom Estimate Exception 5 on the current Payment Estim	mar1 overridding Payment
4 Mar 1, 2023 SYSTEM (\$12,432.00)	
5 Mar 16, 2023 SYSTEM \$12,432.00 This adjustment offsets the original system-general Estimate Item Adjustment (0003) due to user thom Estimate Exception 3 on the current Payment Estim	mar1 overridding Payment
5 Mar 16, 2023 SYSTEM (\$12,432.00)	
- Total \$0.00	
- Total \$0.00	
Material - Total \$0.00	



Line Item Adjustments by Estimate

Contract ID: 220819-H03

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3586	0080	FURN & INSTAL) (TYPE L	Material			2023			Estimate Item Adjustment (0005) due to user thomar1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Feb 2, 2023	SYSTEM	(\$1,400.00)	
					4	Mar 1, 2023	SYSTEM	\$2,455.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thomar1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Mar 1, 2023	SYSTEM	(\$2,455.00)	
					5	Mar 16, 2023	SYSTEM	\$2,695.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thomar1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Mar 16, 2023	SYSTEM	(\$2,695.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0080 -	Total						\$0.00	
	0090		Material		4	Mar 1, 2023	SYSTEM	\$1,064.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thomar1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Mar 1, 2023	SYSTEM	(\$1,064.80)	
					5	Mar 16, 2023	SYSTEM	\$1,064.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thomar1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Mar 16, 2023	SYSTEM	(\$1,064.80)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0090 -	Total						\$0.00	
	0110		Material		2	Jan 3, 2023	SYSTEM	\$151,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jan 3, 2023	SYSTEM	(\$151,664.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -	Total						\$0.00	
	0120	CROSS STITCH TIE BAR	Material		3	Feb 2, 2023	SYSTEM	\$7,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user thomar1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Feb 2, 2023	SYSTEM	(\$7,920.00)	
					4	Mar 1, 2023	SYSTEM	\$17,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user thomar1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Mar 1, 2023	SYSTEM	(\$17,100.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0120 -	Total						\$0.00	
	0130	CONSTRUCTION SIGNS	Material		1	Dec 15, 2022	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Dec 15, 2022	SYSTEM	(\$1,800.00)	
					2	Jan 3, 2023	SYSTEM	\$2,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Jan 3, 2023	SYSTEM	(\$2,080.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	



Line Item Adjustments by Estimate

Mar 18, 2023

Contract ID: 220819-H03

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3586	0130 -	Total						\$0.00	
	0140	CHANNELIZER (TRIM LINE)	Material		1	Dec 15, 2022	SYSTEM	\$3,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thomar1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Dec 15, 2022	SYSTEM	(\$3,150.00)	
					2	Jan 3, 2023	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thomar1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Jan 3, 2023	SYSTEM	(\$4,200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0140 -	Total						\$0.00	
	0150	FLASHING ARROW PANEL	Material		1	Dec 15, 2022	SYSTEM	\$995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thomar1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Dec 15, 2022	SYSTEM	(\$995.00)	
					2	Jan 3, 2023	SYSTEM	\$995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thomar1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Jan 3, 2023	SYSTEM	(\$995.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0150 -	Total						\$0.00	
	0160	CMS W/O COMMUNICATION INTERFACE,	Material		2	Jan 3, 2023	SYSTEM	\$7,492.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thomar1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		CONT F/			2	Jan 3, 2023	SYSTEM	(\$7,492.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0160 -	Total						\$0.00	
J9P3586 -	Total							\$0.00	
Overall - T	Total							\$0.00	