

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 3, 2023

Progress Estimate Number	Contract ID	221021-C02	Pay Period Start	April 16, 2023	Original Contract Amount	\$4,918,576.89
4	Prime Contractor	Radmacher Brothers Excavating Co.,Inc.	Pay Period End	May 1, 2023	Amount	\$0.00
					Current Contract Amount	\$4,918,576.89

Original Comp	letion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amou	int Complete				
May 3, 2023	Reviewed and Approved at the Central Office Controllers Office Level by								
May 3, 2023		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by							
May 3, 2023		Generated and	Approved (and should be considere	d Draft) at the Project Office Level by	frizzm				
Approval Date					By User				

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete				
December 1, 2023	December 1, 2023		37.94%				

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	November 2, 2022	November 2, 2022	
Letting Date	October 21, 2022	October 21, 2022	
Notice to Proceed Date	December 21, 2022	December 21, 2022	
Open to Traffic Date			
Work Began Date			

Contract Total Pay For Estima	te No. 4				
		This Estimate	Previous	To Date	
221021-C02					
Total Po	sted Items Pay	\$752,207.70	\$1,113,948.96	\$1,866,156.66	
Gross It	em Adjustments	(\$336,860.76)	\$481,323.33	\$144,462.57	
Incentiv	е	\$0.00	\$0.00	\$0.00	
Disincer	ntive	\$0.00	\$0.00	\$0.00	
Liquidat	ed Damage	\$0.00	\$0.00	\$0.00	
Other C	ontract Adjustments	\$0.00	\$0.00	\$0.00	
			\$1,595,272.29	\$2,010,619.23	
Contract Total Payable This Es	stimate:	\$415,346.94			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3451	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$44,107.500	0.2	\$8,821.50
	0370	6181000	MOBILIZATION	LS	\$191,409.500	0.5	\$95,704.75
	0480	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$18,016.500	0.4	\$7,206.60
	0680	2061000	CLASS 1 EXCAVATION	CUYD	\$68.750	110	\$7,562.50
	0750	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	LF	\$135.500	280	\$37,940.00
	0760	7025002	PILE WAVE ANALYSIS	EA	\$530.000	2	\$1,060.00
	0780	7027000	PILE POINT REINFORCEMENT	EA	\$133.000	14	\$1,862.00
	0790	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	CUYD	\$999.500	58.5	\$58,470.75
	0800	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	CUYD	\$1,086.000	41.6	\$45,177.60
	0830	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	LF	\$414.000	1,113	\$460,782.00
	0850	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$2.000	11,770	\$23,540.00
	0870	7161000	PLAIN NEOPRENE BEARING PAD	EA	\$152.000	12	\$1,824.00
	0880	7161002	LAMINATED NEOPRENE BEARING PAD	EA	\$188.000	12	\$2,256.00
Project J4I345	1 - Total						\$752,207.70
Overall - Total							\$752,207.70

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item Adjustments This Estimate

Revision 3/23/2023 Page 1 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 3, 2023

Progress Estimate Number
4 Contract ID 221021-C02 Pay Period Start 2023 Original Contract Amount \$4,918,576.89

Prime Contractor Co.,Inc. Pay Period End May 1, 2023 Net Change Order Amount \$4,918,576.89

ct er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
51	0090	MISC.	Material			-2,783	\$22.75	(\$63,313.25
	0090	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,783	\$22.75	\$63,313.25
	0130	TACK COAT - LOW OR NON-TRACKING	Material			-116	\$5.25	(\$609.00
	0130	TACK COAT - LOW OR NON-TRACKING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.	116	\$5.25	\$609.00
	0350	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material			-3,352.5	\$16.50	(\$55,316.25
	0350	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.	3,352.5	\$16.50	\$55,316.25
	0410	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-12,745	\$0.50	(\$6,372.50
	0410	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.	12,745	\$0.50	\$6,372.50
	0420	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-14,726	\$0.50	(\$7,363.00
	0420	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.	14,726	\$0.50	\$7,363.00
	0710	ROCK SOCKETS (4 FT 0 IN. DIA.)	Material			-75	\$564.00	(\$42,300.00
	0710	ROCK SOCKETS (4 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.	75	\$564.00	\$42,300.00
	0750	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material			-280	\$135.50	(\$37,940.00
	0750	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.	280	\$135.50	\$37,940.00
	0780	PILE POINT REINFORCEMENT	Material			-14	\$133.00	(\$1,862.00
	0780	PILE POINT REINFORCEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11	14	\$133.00	\$1,862.00

Revision 3/23/2023 Page 2 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 3, 2023

Progress Estimate Number
4
Contract ID
Prime Radmacher Brothers Excavating Contractor
Co.,Inc.
Pay Period April 16, Start 2023
Pay Period End May 1, 2023
Pay Period End May 1, 2023
Pay Period End May 1, 2023
Net Change Order 4mount \$4,918,576.89
Current Contract Amount \$4,918,576.89

oject mber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
3451					on the current Payment Estimate.						
	0790	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-58.5	\$999.50	(\$58,470.7			
	0790	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.	58.5	\$999.50	\$58,470.7			
	0800	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material			-51.8	\$1,086.00	(\$56,254.8			
	0800	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.	51.8	\$1,086.00	\$56,254.8			
	0830	NU 43, PRESTRESSED CONCRETE NU-GIRDER	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$336,860.7			
	0850	REINFORCING STEEL (EPOXY COATED)	Material			-11,770	\$2.00	(\$23,540.0			
	0850	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.	11,770	\$2.00	\$23,540.0			
	0870	PLAIN NEOPRENE BEARING PAD	Material			-12	\$152.00	(\$1,824.0			
	0870	PLAIN NEOPRENE BEARING PAD	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 19 on the current Payment Estimate.	12	\$152.00	\$1,824.0			
	0880	LAMINATED NEOPRENE BEARING PAD	Material			-12	\$188.00	(\$2,256.0			
	0880	LAMINATED NEOPRENE BEARING PAD	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 20 on the current Payment Estimate.	12	\$188.00	\$2,256.0			
al								(\$336,860.7			

Revision 3/23/2023 Page 3 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J4I3451	I 435-1(333)	2 Bridge replacements	I-435	JACKSON	over 87th Street, 1.1 miles north of Route W and 2.2 miles south of Gregory Boulevard near Raytown							

Revision 3/23/2023 Page 4 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 3049905, Project Item Line Number 0090, Material Set 304990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 3049905, Project Item Line Number 0090, Material Set 304990596, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 4071007, Project Item Line Number 0130, Material Set 407100796, Material 1015EASS1VH - Emulsified Asphalt - Trackless Tack, Acceptance Action Generic AspEmulsion is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 6173600D, Project Item Line Number 0350, Material Set 6173600D96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 6205902A, Project Item Line Number 0410, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 6205902A, Project Item Line Number 0410, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 6205903A, Project Item Line Number 0420, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 6205903A, Project Item Line Number 0420, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7011206, Project Item Line Number 0710, Material Set 701120696, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7021212, Project Item Line Number 0750, Material Set 702121296, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7027000, Project Item Line Number 0780, Material Set 702700096, Material 0702PLPT - Pile Point Reinforcement, Acceptance Action Generic 0702PLPT is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7032003, Project Item Line Number 0790, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7032003, Project Item Line Number 0790, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7032003, Project Item Line Number 0790, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7034003, Project Item Line Number 0800, Material Set 703400396, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7034003, Project Item Line Number 0800, Material Set 703400396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7034003, Project Item Line Number 0800, Material Set 703400396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3451, Item 7101000, Project Item Line Number 0850, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7161000, Project Item Line Number 0870, Material Set 716100096, Material 1038BBPD - Bridge Bearing Pad, Acceptance Action Generic 1038BBPD is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3451, Item 7161002, Project Item Line Number 0880, Material Set 716100296, Material 1038BBPD - Bridge Bearing Pad, Acceptance Action Generic 1038BBPD is insufficient.	Material was inspected at the time of incorporation into the project. Project Office staff is working on resolution to the exception. frizzm 5/3/23	frizzm	Overridden
Estimate Exception Type: Item Overrun: Contract 221021-C02, Contract Project J4l3451, Project Item Line Number 0420, Contract Line Item Number 0420, Item 6205903A, Minor Item.	A change order will be generated to address this overrun item. frizzm 5/3/23	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221021-C02, Contract Project J4l3451, Project Item Line Number 0120, Contract Line Item Number 0120, Item 4030206, Minor Item.	A change order will be generated to address this overrun item. frizzm 5/3/23	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221021-C02, Contract Project J4l3451, Project Item Line Number 0280, Contract Line Item Number 0280, Item 6161033, Minor Item.	A change order will be generated to address this overrun item. frizzm 5/3/23	frizzm	Acknowledged

Revision 3/23/2023 Page 5 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor- generated date)
1021-C02	J4I3451	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$44,107.50	\$22,053.
		0001	0020	2031000	CLASS A EXCAVATION	672.00	0.00	672.00	CUYD	0.00	\$10.75	\$0.
		0001	0030	2036000	COMPACTING EMBANKMENT	580.00	0.00	580.00	CUYD	0.00	\$1.25	\$0.
		0001	0040	2063000	CLASS 3 EXCAVATION	8.00	0.00	8.00	CUYD	0.00	\$12.00	\$0.
		0001	0050	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	18.00	0.00	18.00	100F	0.00	\$441.50	\$0
		0001	0060	2153000	SHAPING SLOPES, CLASS III	23.00	0.00	23.00	100F	0.00	\$770.50	\$0
		0001	0070	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	624.00	0.00	624.00	SQYD	0.00	\$11.00	\$0
		0001	0800	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	702.00	0.00	702.00	SQYD	0.00	\$13.75	\$0
		0001	0090	3049905	MISC.TYPE 5 AGGREGATE 8 IN. THICK	2,783.00	0.00	2,783.00	SQYD	2,783.00	\$22.75	\$63,313
		0001	0100	4019905	MISC.OPTIONAL PAVEMENT	2,783.30	0.00	2,783.30	SQYD	2,783.30	\$82.75	\$230,318
		0001	0110	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	619.00	0.00	619.00	TONS	492.30	\$175.00	\$86,152
		0001	0120	4030206	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP190C MIX)	979.30	0.00	979.30	TONS	1,006.58	\$166.50	\$167,595
		0001	0130	4071007	TACK COAT - LOW OR NON-TRACKING	979.00	0.00	979.00	GAL	116.00	\$5.25	\$609
		0001	0140	5029905	MISC.4 IN. CONCRETE PAVEMENT (DECORATIVE)	324.70	0.00	324.70	SQYD	0.00	\$70.00	\$(
		0001	0150	5041000	CONCRETE APPROACH PAVEMENT	702.40	0.00	702.40	SQYD	0.00	\$157.00	\$1
		0001	0160	6083008	8 IN. CONCRETE MEDIAN STRIP	139.40	0.00	139.40	SQYD	0.00	\$74.00	\$
		0001	0170	6086004	CONCRETE SIDEWALK, 4 IN.	159.70	0.00	159.70	SQYD	0.00	\$48.25	\$1
		0001	0180	6099907	MISC.FURNISHING ROCK SLOPE PROTECTION	242.00	0.00	242.00	CUYD	0.00	\$58.00	\$
		0001	0190	6099907	MISC.PLACING ROCK SLOPE PROTECTION	242.00	0.00	242.00	CUYD	0.00	\$56.00	\$
		0001	0200	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	3.00	0.00	3.00	EA	2.00	\$4,239.00	\$8,47
		0001	0210	6122030	IMPACT ATTENUATOR (RELOCATION)	4.00	0.00	4.00	EA	1.00	\$1,854.50	\$1,85
		0001	0220	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$2,490.50	\$
		0001	0230	6141028	GRATE AND BEARING PLATE (5 FT. 1 IN. X 3 FT. 1 IN. OR 1549	1.00	0.00	1.00	EA	0.00	\$2,692.00	\$
		0001	0240	6161005	MM X 940 MM) CONSTRUCTION SIGNS	1,479.00	0.00	1,479.00	SQFT	1,479.00	\$10.50	\$15,52
		0001	0250	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$132.50	\$53
		0001	0260	6161025	CHANNELIZER (TRIM LINE)	434.00	0.00	434.00	EA	206.00	\$39.25	\$8,08
		0001	0270	6161030	TYPE III MOVEABLE BARRICADE	28.00	0.00	28.00	EA	26.00	\$286.00	\$7,43
		0001	0280	6161033	DIRECTIONAL INDICATOR BARRICADE	30.00	0.00	30.00	EA	39.00	\$106.00	\$4,13
		0001	0290	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$2,596.50	\$10,38
		0001	0300	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	4.00	0.00	4.00	EA	4.00	\$10,333.00	\$41,33
		0001	0300	0101090A	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	LA	4.00	ψ10,333.00	ψ41,33
		0001	0310	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	7.00	0.00	7.00	EA	7.00	\$1,430.50	\$10,01
		0001	0320	6169902	MISC.ADA COMPLIANT MOVEABLE BARRICADE	4.00	0.00	4.00	EA	4.00	\$106.00	\$42
		0001	0330	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	350.00	0.00	350.00	LF	0.00	\$212.50	\$
		0001	0340	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	794.00	0.00	794.00	LF	0.00	\$99.25	\$
		0001	0350	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	5,135.00	0.00	5,135.00	LF	3,352.50	\$16.50	\$55,31
		0001	0360	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	10,438.00	0.00	10,438.00	LF	0.00	\$9.25	\$
		0001	0370	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$191,409.50	\$143,55
		0001	0380	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$
		0001	0390	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	41,586.00	0.00	41,586.00	LF	0.00	\$1.50	\$
		0001	0400	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	35,833.00	0.00	35,833.00	LF	0.00	\$1.50	\$
		0001	0410	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	21,622.00	0.00	21,622.00	LF	12,745.00	\$0.50	\$6,37
		0001	0420	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	13,614.00	0.00	13,614.00	LF	14,726.00	\$0.50	\$7,36
		0001	0430	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,578.00	0.00	2,578.00	LF	0.00	\$2.75	\$
		0001	0440	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,102.00	0.00	1,102.00	LF	0.00	\$0.40	\$

Revision 3/23/2023 Page 6 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

0001	0450				Order	Quantity		Posted Approved Qty		To Date (See repor generated date)
0001		6207001	PAVEMENT MARKING REMOVAL	38,029.00	0.00	38,029.00	LF	1,780.00	\$0.40	\$712.0
	0460	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	6,525.00	0.00	6,525.00	SQYD	4,396.10	\$13.25	\$58,248.3
0001	0470	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	58.10	0.00	58.10	STA	0.00	\$96.75	\$0.0
0001	0480	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$18,016.50	\$9,008.2
0001	0490	7261018	18 IN. PIPE GROUP A	650.00	0.00	650.00	LF	650.00	\$53.00	\$34,450.0
0001	0500	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	2.00	0.00	2.00	FT	0.00	\$2,371.00	\$0.0
0001	0510	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$387.00	\$0.
0001	0520	8025006	MULCHING	0.60	0.00	0.60	ACRE	0.00	\$2,584.50	\$0.
0001	0530	8051000A	SEEDING - COOL SEASON GRASSES	0.50	0.00	0.50	ACRE	0.00	\$3,075.00	\$0
0001	0540	8061005	ROCK DITCH CHECK	8.00	0.00	8.00	LF	0.00	\$15.25	\$0.
0001	0550	8061007A	CURB INLET CHECK	4.00	0.00	4.00	EA	0.00	\$95.50	\$0
0001	0560	8061016	SEDIMENT REMOVAL	28.00	0.00	28.00	CUYD	0.00	\$94.50	\$0.
0001	0570	8061017	TEMPORARY SEEDING	0.10	0.00	0.10	ACRE	0.00	\$2,295.50	\$0.
0001	0580	8061019	SILT FENCE	2,553.00	0.00	2,553.00	LF	0.00	\$1.75	\$0.
0010	0590	6061060	MGS GUARDRAIL	2,100.00	0.00	2,100.00	LF	0.00	\$28.50	\$0.
0010	0600	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	6.00	0.00	6.00	EA	0.00	\$3,932.00	\$0.
0010	0610	6061080	MGS END ANCHOR	3.00	0.00	3.00	EA	0.00	\$1,430.50	\$0
0010	0620	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	0.00	\$3,410.50	\$0
0010	0630	6069902	MISC.CABLE TO GUARDRAIL TRANSITION	3.00	0.00	3.00	EA	0.00	\$4,815.50	\$0
0010	0640	6069902	MISC.HTGC ANCHOR ASSEMBLY	3.00	0.00	3.00	EA	0.00	\$4,345.00	\$0
0010	0650	6069903	MISC.HIGH TENSION GUARD CABLE	840.00	0.00	840.00	LF	0.00	\$39.25	\$0
0040 066										\$0
										\$2,763
										\$7,562
										\$105,929
										\$0
										\$42,300
										\$159
										\$21,420
										\$0
										\$37,940
										\$1,060
										\$17,797
										\$1,862
										\$58,470
										\$56,254
										\$0
										\$100.700
										\$460,782
0070										\$11,480
	U850	/101000	REINFURGING STEEL (EPOXY COATED)							\$23,540
0070					0.00	2 00	EA	0.00		
0070	0860	7151001	VERTICAL DRAIN AT END BENTS						\$3,959.00	
	0860 0870 0880	7151001 7161000 7161002	VERTICAL DRAIN AT END BENTS PLAIN NEOPRENE BEARING PAD LAMINATED NEOPRENE BEARING PAD	12.00	0.00	12.00	EA EA	12.00	\$152.00 \$188.00	\$1,824 \$2,256
	0070 0070 0070 0070 0070 0070 0070 007	0070 0675 0070 0680 0070 0690 0070 0700 0070 0710 0070 0720 0070 0730 0070 0740 0070 0750 0070 0760 0070 0770 0070 0780 0070 0800 0070 0810 0070 0820 0070 0830 0070 0840	0070 0675 2024043 0070 0680 2061000 0070 0690 2160500 0070 0700 5031010A 0070 0710 7011206 0070 0720 7011300 0070 0730 7011400 0070 0740 7011600 0070 0750 7021212 0070 0760 7025002 0070 0780 7027000 0070 0790 7032003 0070 0800 703403 0070 0810 7034219A 0070 0820 7034221 0070 0830 7056022 0070 0840 7061060	0070 0675 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 0070 0680 2061000 CLASS 1 EXCAVATION 0070 0690 2160500 REMOVAL OF BRIDGES 0070 0700 5031010A BRIDGE APPROACH SLAB (MAJOR) 0070 0710 7011206 ROCK SOCKETS (4 FT 0 IN. DIA.) 0070 0720 7011300 VIDEO CAMERA INSPECTION 0070 0730 7011400 FOUNDATION INSPECTION HOLES 0070 0740 7011600 SONIC LOGGING TESTING 0070 0750 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 0070 0760 7025002 PILE WAVE ANALYSIS 0070 0770 7026000 PRE-BORE FOR PILING 0070 0780 7027000 PILE POINT REINFORCEMENT 0070 0790 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 0070 0800 7034003 CLASS B-1 CONCRETE (SUBSTRUCTURE) 0070 0810 7034219A TYPE D BARRIER 0070 0820	0070 0675 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 18.00 0070 0680 2061000 CLASS 1 EXCAVATION 110.00 0070 0690 2160500 REMOVAL OF BRIDGES 1.00 0070 0700 5031010A BRIDGE APPROACH SLAB (MAJOR) 252.00 0070 0710 7011206 ROCK SOCKETS (4 FT 0 IN. DIA.) 75.00 0070 0720 7011300 VIDEO CAMERA INSPECTION 3.00 0070 0730 7011400 FOUNDATION INSPECTION HOLES 105.00 0070 0740 7011600 SONIC LOGGING TESTING 3.00 0070 0750 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 280.00 0070 0760 7025002 PILE WAVE ANALYSIS 2.00 0070 0770 7026000 PRE-BORE FOR PILING 210.00 0070 0780 7027000 PILE POINT REINFORCEMENT 14.00 0070 0800 7034003 CLASS B CONCRETE (SUBSTRUCTURE) 58.50 0070	0070 0675 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 18.00 0.00 0070 0680 2061000 CLASS 1 EXCAVATION 110.00 0.00 0070 0690 2160500 REMOVAL OF BRIDGES 1.00 0.00 0070 0700 5031010A BRIDGE APPROACH SLAB (MAJOR) 252.00 0.00 0070 0710 7011206 ROCK SOCKETS (4 FT 0 IN. DIA.) 75.00 0.00 0070 0720 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 0070 0730 7011400 FOUNDATION INSPECTION HOLES 105.00 0.00 0070 0740 7011600 SONIC LOGGING TESTING 3.00 0.00 0070 0750 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 280.00 0.00 0070 0760 7025002 PILE WAVE ANALYSIS 2.00 0.00 0070 0770 7026000 PRE-BORE FOR PILING 210.00 0.00 0070 0780 7027000 PILE P	0070 0675 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 18.00 0.00 18.00 0070 0680 2061000 CLASS 1 EXCAVATION 110.00 0.00 110.00 0070 0690 2160500 REMOVAL OF BRIDGES 1.00 0.00 1.00 0070 0700 5031010A BRIDGE APPROACH SLAB (MAJOR) 252.00 0.00 252.00 0070 0710 7011206 ROCK SOCKETS (4 FT 0 IN. DIA.) 75.00 0.00 75.00 0070 0720 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 0070 0730 7011400 FOUNDATION INSPECTION HOLES 105.00 0.00 105.00 0070 0740 7011600 SONIC LOGGING TESTING 3.00 0.00 3.00 0070 0750 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 280.00 0.00 280.00 0070 0760 7025002 PILE WAVE ANALYSIS 2.00 0.00 2.00 0070	0070 0675 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 18.00 0.00 18.00 SQFT 0070 0680 2061000 CLASS 1 EXCAVATION 110.00 0.00 110.00 CUYD 0070 0690 2160500 REMOVAL OF BRIDGES 1.00 0.00 1.00 LS 0070 0700 5031010A BRIDGE APPROACH SLAB (MAJOR) 252.00 0.00 252.00 SQYD 0070 0710 7011206 ROCK SOCKETS (4 FT 0 IN. DIA.) 75.00 0.00 75.00 LF 0070 0720 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 EA 0070 0730 7011400 FOUNDATION INSPECTION HOLES 105.00 0.00 105.00 LF 0070 0740 7011600 SONIC LOGGING TESTING 3.00 0.00 3.00 EA 0070 0750 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN) 280.00 0.00 280.00 LF 0070 <t< td=""><td>0070 0675 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 18.00 0.00 18.00 SQFT 18.00 0070 0680 2061000 CLASS 1 EXCAVATION 110.00 0.00 110.00 CUYD 110.00 0070 0690 2160500 REMOVAL OF BRIDGES 1.00 0.00 1.00 LS 1.00 0070 0700 5031010A BRIDGE APPROACH SLAB (MAJOR) 252.00 0.00 252.00 SQYD 0.00 0070 0710 7011206 ROCK SOCKETS (4 FT 0 IN. DIA.) 75.00 0.00 75.00 LF 75.00 0070 0720 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 EA 3.00 0070 0730 7011400 FOUNDATION INSPECTION HOLES 105.00 0.00 105.00 LF 105.00 0070 0740 701600 SONIC LOGGING TESTING 3.00 0.00 3.00 EA 0.00 0070 0760 7021212 GALVANI</td><td>0070 0675 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 18.00 0.00 18.00 SOFT 18.00 \$153.50 0070 0680 2061000 CLASS 1 EXCAVATION 110.00 0.00 110.00 CUVD 110.00 \$88.75 0070 0690 2160500 REMOVAL OF BRIDGES 1.00 0.00 1.00 LS 1.00 \$105,929.00 0070 0701 5031010A BRIDGE APPROACH SLAB (MAJOR) 252.00 0.00 252.00 SQYD 0.00 \$299.50 0070 0710 7011206 ROCK SOCKETS (4 FT 0 IN. DIA.) 75.00 0.00 75.00 LF 75.00 \$564.00 0070 0720 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 EA 3.00 \$580.00 0070 0730 7011400 FOUNDATION INSPECTION HOLES 105.00 0.00 105.00 LF 105.00 LF 105.00 LF 105.00 LF 105.00 LF 105.00</td></t<>	0070 0675 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 18.00 0.00 18.00 SQFT 18.00 0070 0680 2061000 CLASS 1 EXCAVATION 110.00 0.00 110.00 CUYD 110.00 0070 0690 2160500 REMOVAL OF BRIDGES 1.00 0.00 1.00 LS 1.00 0070 0700 5031010A BRIDGE APPROACH SLAB (MAJOR) 252.00 0.00 252.00 SQYD 0.00 0070 0710 7011206 ROCK SOCKETS (4 FT 0 IN. DIA.) 75.00 0.00 75.00 LF 75.00 0070 0720 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 EA 3.00 0070 0730 7011400 FOUNDATION INSPECTION HOLES 105.00 0.00 105.00 LF 105.00 0070 0740 701600 SONIC LOGGING TESTING 3.00 0.00 3.00 EA 0.00 0070 0760 7021212 GALVANI	0070 0675 2024043 REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) 18.00 0.00 18.00 SOFT 18.00 \$153.50 0070 0680 2061000 CLASS 1 EXCAVATION 110.00 0.00 110.00 CUVD 110.00 \$88.75 0070 0690 2160500 REMOVAL OF BRIDGES 1.00 0.00 1.00 LS 1.00 \$105,929.00 0070 0701 5031010A BRIDGE APPROACH SLAB (MAJOR) 252.00 0.00 252.00 SQYD 0.00 \$299.50 0070 0710 7011206 ROCK SOCKETS (4 FT 0 IN. DIA.) 75.00 0.00 75.00 LF 75.00 \$564.00 0070 0720 7011300 VIDEO CAMERA INSPECTION 3.00 0.00 3.00 EA 3.00 \$580.00 0070 0730 7011400 FOUNDATION INSPECTION HOLES 105.00 0.00 105.00 LF 105.00 LF 105.00 LF 105.00 LF 105.00 LF 105.00

Revision 3/23/2023 Page 7 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
21021-C02	J4I3451	0071	0900	2061000	CLASS 1 EXCAVATION	110.00	0.00	110.00	CUYD	0.00	\$68.75	\$0.00
		0071	0910	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.00	\$105,929.00	\$0.00
		0071 0920 5031010A 0071 0930 7011206		5031010A	BRIDGE APPROACH SLAB (MAJOR)	252.00	0.00	252.00	SQYD	0.00	\$299.50	\$0.00
				7011206	ROCK SOCKETS (4 FT 0 IN. DIA.)	63.00	0.00	63.00	LF	0.00	\$615.50	\$0.00
		0071	0071 0940 7011300		VIDEO CAMERA INSPECTION	3.00	0.00	3.00	EA	0.00	\$53.00	\$0.00
		0071	0950	7011400	FOUNDATION INSPECTION HOLES	93.00	0.00	93.00	LF	93.00	\$209.50	\$19,483.50
		0071	0960	7011600	SONIC LOGGING TESTING	3.00	0.00	3.00	EA	0.00	\$1,589.50	\$0.00
		0071	0970	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	280.00	0.00	280.00	LF	0.00	\$135.50	\$0.00
		0071	0980	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	0.00	\$530.00	\$0.00
		0071	0990	7026000	PRE-BORE FOR PILING	210.00	0.00	210.00	LF	0.00	\$84.75	\$0.00
		0071	1000	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	0.00	\$133.00	\$0.00
		0071	1010	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	54.50	0.00	54.50	CUYD	0.00	\$1,058.50	\$0.00
		0071	1020	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	49.30	0.00	49.30	CUYD	0.00	\$1,131.00	\$0.00
		0071	1030	7034219A	TYPE D BARRIER	416.00	0.00	416.00	LF	0.00	\$102.50	\$0.00
		0071	1040	7034221	SLAB ON CONCRETE NU-GIRDER	1,230.00	0.00	1,230.00	SQYD	0.00	\$396.00	\$0.00
		0071	1050	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	1,116.00	0.00	1,116.00	LF	0.00	\$414.00	\$0.00
		0071	1060	7061060	REINFORCING STEEL (BRIDGES)	4,940.00	0.00	4,940.00	LB	0.00	\$2.00	\$0.00
		0071	1070	7101000	REINFORCING STEEL (EPOXY COATED)	11,720.00	0.00	11,720.00	LB	0.00	\$2.00	\$0.00
		0071	1080	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$3,959.00	\$0.00
		0071	1090	7161000	PLAIN NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	0.00	\$152.00	\$0.00
		0071	1100	7161002	LAMINATED NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	0.00	\$188.00	\$0.00
	Project .	J4I3451 - To	tal Value	Posted to D	ate as of Report Generated Date							\$1,866,156.64
1021-C02 Ove	erall - Tota	I Value Pos	sted to Da	ite as of Rep	ort Generated Date							\$1,866,156.64

Revision 3/23/2023 Page 8 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	5/1/23	5/3/23	0.20	LS	Concrete slope protection	736+47		738+28		
0370	6181000	MOBILIZATION	5/1/23	5/3/23	0.50	LS	Project jobsite	726+00		747+00		
0480	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	5/1/23	5/3/23	0.40	LS	Br. A9236	736+23		738+13		
0680	0680 2061000 CLASS 1 EXCAVATION		4/21/23	5/3/23	55.00	CUYD	Bent 1	736+23				
			4/24/23	5/3/23	55.00	CUYD	Bent 3	738+13				
0750	0750 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN	GALVANIZED STRUCTURAL STEEL PILES (12 IN	4/19/23	5/3/23	140.00	LF	Bent 1	736+23				
			4/24/23	5/3/23	140.00	LF	Bent 3	738+13				
0760	7025002	PILE WAVE ANALYSIS	4/19/23	5/3/23	2.00	EA	Bents 1 and 3 of Br. A9236	736+23		738+13		
0780	780 7027000 PILE POINT REINFORCEMENT	4/19/23	5/3/23	7.00	EA	Bent 1	736+23					
			4/24/23	5/3/23	7.00	EA	Bent 3	738+13				
0790	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	4/21/23	5/3/23	29.30	CUYD	Bent 1	736+23				
			4/24/23	5/3/23	29.20	CUYD	Bent 3	738+13				
0800	7034003	CLASS B-1 CONCRETE (SUBSTR)	4/17/23	5/3/23	41.60	CUYD	Bent 2 cap	737+18				
0830	7056022	NU 43, PRESTRESSED CONC NU-GIRDER	4/28/23	5/3/23	930.00	LF	Span 1-2 and span 2-3. 10 Girders set.	736+23		738+13		
			5/1/23	5/3/23	183.00	LF	Span 1-2 and span 2-3. 2 girders set.	736+23		738+13		
0850	7101000	REINFORCING STEEL (EPOXY COATED)	4/17/23	5/3/23	11,770.00	LB	Bent 2 columns and cap	737+18				
0870	7161000	PLAIN NEOPRENE BEARING PAD	4/26/23	5/3/23	12.00	EA	Bents 1, 2, and 3	736+23		738+13		
0880	7161002	LAMINATED NEOPRENE BEARING PAD	4/26/23	5/3/23	12.00	EA	Bents 1, 2, and 3	736+23		738+13		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 9 of 16



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3451	0090	MISC. AGGREGATE FOR BASE	Material		2	Apr 4, 2023	SYSTEM	\$63,313.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 4, 2023	SYSTEM	(\$63,313.25)	
					3	Apr 17, 2023	SYSTEM	\$63,313.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Apr 17, 2023	SYSTEM	(\$63,313.25)	
					4	May 3, 2023	SYSTEM	\$63,313.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$63,313.25)	Examina Exception (of the earliest cyricin Editinate)
				- Total				\$0.00	
			Material - Total					\$0.00	
	0090 -	Total	material - 10					\$0.00	
			Oth. "	10:-	0	Ann 4			AO adhashaart fan March 40 i A 114
	0100	MISC.	Other Item Adjustment	ACAD		Apr 4, 2023	frizzm	(\$6,033.61)	AC adjustment for March 16 to April 1.
				ACAD - Total				(\$6,033.61)	
			Other Item A	djustment - T	otal			(\$6,033.61)	
	0100 -	Total						(\$6,033.61)	
	0110	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	1	Mar 17, 2023	frizzm	(\$547.10)	AC adjustment for March 1 to 15.
					2	Apr 4, 2023	frizzm	(\$1,420.87)	AC adjustment for March 16 to April 1.
				ACAD - Tota	al			(\$1,967.97)	
			Other Item A	djustment - T	otal			(\$1,967.97)	
	0110 -	Total						(\$1,967.97)	
	0120	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP1	ETE Adjustment PG	ACAD	1	Mar 17, 2023	frizzm	(\$824.84)	AC adjustment for March 1 to 15.
					2	Apr 4, 2023	frizzm	(\$2,964.89)	AC adjustment for March 16 to April 1.
				ACAD - Tota	al			(\$3,789.73)	
			Other Item A	Adjustment - Total				(\$3,789.73)	
			Overrun - To	Overrun	2	Apr 4, 2023	SYSTEM	(\$4,542.12)	
				Overrun - T	otal			(\$4,542.12)	
				tal				(\$4,542.12)	
	0120 -	Total						(\$8,331.85)	
	0130	TACK COAT - LOW OR NON- TRACKING	Material		1	Mar 17, 2023	SYSTEM	\$609.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Mar 17, 2023	SYSTEM	(\$609.00)	
					2	Apr 4, 2023	SYSTEM	\$609.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Apr 4, 2023	SYSTEM	(\$609.00)	
					3	Apr 17, 2023	SYSTEM	\$609.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Apr 17, 2023	SYSTEM	(\$609.00)	
					4	May 3, 2023	SYSTEM	\$609.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
									Estimate Exception 3 on the current Fayment Estimate.
					4	May 3, 2023	SYSTEM	(\$609.00)	Estimate Exception 3 of the current rayment Estimate.
				- Total	4		SYSTEM	(\$609.00) \$0.00	Estimate Exception 3 of the current rayment Estimate.



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
3451	0130	TACK COAT - LOW OR NON- TRACKING	Material - To	tal				\$0.00		
	0130 -	Total						\$0.00		
	0200	MPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	Material		2	Apr 4, 2023	SYSTEM	\$8,478.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					2	Apr 4, 2023	SYSTEM	(\$8,478.00)		
					3	Apr 17, 2023	SYSTEM	\$8,478.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					3	Apr 17, 2023	SYSTEM	(\$8,478.00)		
				- Total				\$0.00		
			Material - Total					\$0.00		
	0200 -	Total						\$0.00		
	0240	CONSTRUCTION SIGNS	Material		2	Apr 4, 2023	SYSTEM	\$8,377.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					2	Apr 4, 2023	SYSTEM	(\$8,377.95)		
						3	Apr 17, 2023	SYSTEM	\$15,529.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Apr 17, 2023	SYSTEM	(\$15,529.50)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0240 -	Total						\$0.00		
	0250	ADVANCED WARNING RAIL SYSTEM	Material		2	Apr 4, 2023	SYSTEM	\$530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					2	Apr 4, 2023	SYSTEM	(\$530.00)		
					3	Apr 17, 2023	SYSTEM	\$530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					3	Apr 17, 2023	SYSTEM	(\$530.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0250 -	Total						\$0.00		
	0260	CHANNELIZER (TRIM LINE)	Material		2	Apr 4, 2023	SYSTEM	\$8,085.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					2	Apr 4, 2023	SYSTEM	(\$8,085.50)		
					3	Apr 17, 2023	SYSTEM	\$8,085.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					3	Apr 17, 2023	SYSTEM	(\$8,085.50)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0260 -	Total						\$0.00		
	0270	TYPE III MOVEABLE BARRICADE	Material		3	Apr 17, 2023	SYSTEM	\$7,436.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					3	Apr 17, 2023	SYSTEM	(\$7,436.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		



Line	e Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
027	0 - Total						\$0.00					
028	DIRECTIONAL INDICATOR BARRICADE	Material		2	Apr 4, 2023	SYSTEM	\$4,134.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.				
				2	Apr 4, 2023	SYSTEM	(\$4,134.00)					
				3	Apr 17, 2023	SYSTEM	\$4,134.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.				
				3	Apr 17, 2023	SYSTEM	(\$4,134.00)					
			- Total				\$0.00					
		Material - Tot	tal				\$0.00					
		Overrun	Overrun	2	Apr 4, 2023	SYSTEM	(\$954.00)					
			Overrun - T	otal			(\$954.00)					
		Overrun - To	tal				(\$954.00)					
028	0 - Total						(\$954.00)					
029	_	Material		2	Apr 4, 2023	SYSTEM	\$10,386.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.				
					2	Apr 4, 2023	SYSTEM	(\$10,386.00)				
				3	Apr 17, 2023	SYSTEM	\$10,386.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.				
				3	Apr 17, 2023	SYSTEM	(\$10,386.00)					
			- Total				\$0.00					
		Material - Total					\$0.00					
029	0 - Total						\$0.00					
030	COMMUNICATION INTERFACE,	Material		1	Mar 17, 2023	SYSTEM	\$41,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.				
	CONT F/							1	Mar 17, 2023	SYSTEM	(\$41,332.00)	
								2	Apr 4,	SYSTEM	044 000 00	TI: 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
					2023		\$41,332.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.				
				2	Apr 4, 2023	SYSTEM	(\$41,332.00)	Estimate Item Adjustment (0011) due to user frizzm overridding Payment				
				2	Apr 4,	SYSTEM		Estimate Item Adjustment (0011) due to user frizzm overridding Payment				
					Apr 4, 2023 Apr 17,		(\$41,332.00)	Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment				
			- Total	3	Apr 4, 2023 Apr 17, 2023 Apr 17,	SYSTEM	(\$41,332.00) \$41,332.00	Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment				
		Material - Tol		3	Apr 4, 2023 Apr 17, 2023 Apr 17,	SYSTEM	(\$41,332.00) \$41,332.00 (\$41,332.00)	Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment				
030	0 - Total	Material - Tol		3	Apr 4, 2023 Apr 17, 2023 Apr 17,	SYSTEM	(\$41,332.00) \$41,332.00 (\$41,332.00) \$0.00	Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment				
030				3	Apr 4, 2023 Apr 17, 2023 Apr 17,	SYSTEM	(\$41,332.00) \$41,332.00 (\$41,332.00) \$0.00	Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment				
	0 TEMPORARY LONG-TERM			3	Apr 4, 2023 Apr 17, 2023 Apr 17, 2023 Apr 4,	SYSTEM	(\$41,332.00) \$41,332.00 (\$41,332.00) \$0.00 \$0.00	Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment				
	0 TEMPORARY LONG-TERM			3	Apr 4, 2023 Apr 17, 2023 Apr 17, 2023 Apr 17, 2023 Apr 4, 2023	SYSTEM SYSTEM SYSTEM	(\$41,332.00) \$41,332.00 (\$41,332.00) \$0.00 \$0.00 \$2,861.00	Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment				
	0 TEMPORARY LONG-TERM			2	Apr 4, 2023 Apr 17, 2023 Apr 17, 2023 Apr 4, 2023 Apr 4, 2023 Apr 17, 2023	SYSTEM SYSTEM SYSTEM	(\$41,332.00) \$41,332.00 (\$41,332.00) \$0.00 \$0.00 \$2,861.00	Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment				
	0 TEMPORARY LONG-TERM			3 3 2 2 3	Apr 4, 2023 Apr 17, 2023 Apr 17, 2023 Apr 4, 2023 Apr 4, 2023 Apr 17, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	(\$41,332.00) \$41,332.00 (\$41,332.00) \$0.00 \$0.00 \$2,861.00 (\$2,861.00) \$10,013.50	Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment				
	0 TEMPORARY LONG-TERM		tal - Total	3 3 2 2 3	Apr 4, 2023 Apr 17, 2023 Apr 17, 2023 Apr 4, 2023 Apr 4, 2023 Apr 17, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	(\$41,332.00) \$41,332.00 (\$41,332.00) \$0.00 \$0.00 \$2,861.00 (\$2,861.00) \$10,013.50	Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment				
031	0 TEMPORARY LONG-TERM	Material	tal - Total	3 3 2 2 3	Apr 4, 2023 Apr 17, 2023 Apr 17, 2023 Apr 4, 2023 Apr 4, 2023 Apr 17, 2023	SYSTEM SYSTEM SYSTEM SYSTEM	(\$41,332.00) \$41,332.00 (\$41,332.00) \$0.00 \$0.00 \$2,861.00 (\$2,861.00) \$10,013.50 (\$10,013.50)	Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment				



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
51	0350	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		2	Apr 4, 2023	SYSTEM	\$55,316.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.				
		TONWIL			2	Apr 4, 2023	SYSTEM	(\$55,316.25)					
									3	Apr 17, 2023	SYSTEM	\$55,316.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.
					3	Apr 17, 2023	SYSTEM	(\$55,316.25)					
					4	May 3, 2023	SYSTEM	\$55,316.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					4	May 3, 2023	SYSTEM	(\$55,316.25)					
				- Total				\$0.00					
ı			Material - To	tal				\$0.00					
	0350 -						0) (0 === 1	\$0.00					
	0400	TEMPORARY REMOVABLE MARKING TAPE	Material		2	Apr 4, 2023	SYSTEM	\$16,221.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.				
					2	Apr 4, 2023	SYSTEM	(\$16,221.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0400 -							\$0.00					
	0410	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		3	Apr 17, 2023	SYSTEM	\$6,372.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 14 on the current Payment Estimate.				
			7,444		3	Apr 17, 2023	SYSTEM	(\$6,372.50)					
					4	May 3, 2023	SYSTEM	\$6,372.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.				
					4	May 3, 2023	SYSTEM	(\$6,372.50)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0410 -	Total						\$0.00					
	0420	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		3	Apr 17, 2023	SYSTEM	\$7,363.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					3	Apr 17, 2023	SYSTEM	(\$7,363.00)					
					4	May 3, 2023	SYSTEM	\$7,363.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.				
					4	May 3, 2023	SYSTEM	(\$7,363.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
			Overrun	Overrun		Apr 17, 2023	SYSTEM	(\$556.00)					
				Overrun - T	otal			(\$556.00)					
	0.400	Total	Overrun - To	tal				(\$556.00)					
	0420 - 0590	Total MGS GUARDRAIL	Construction		3	Apr 17,	SYSTEM	(\$556.00) \$30,261.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
			Stockpile STMI	- Total		2023		\$30,261.00					
			Construction	Stockpile S	TMI - Tota			\$30,261.00					
	05 <u>90 -</u>	0 - Total						\$30,261.00					
	0600	MGS BRIDGE	Construction		3	Apr 17,	SYSTEM	\$6,120.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
						10. 111		, -, 0.00	, , , , , , , , , , , , , , , , , , , ,				



							2 1		
Lir	e Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
060					2023				
	(EXT CURB)	STMI		3	Apr 17, 2023	SYSTEM	\$6,120.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			- Total			\$12,240.00			
		Construction	1 Stockpile S	TMI - Tota			\$12,240.00		
060	0 - Total						\$12,240.00		
06	0 MGS END ANCHOR	Construction Stockpile		3	Apr 17, 2023	SYSTEM	\$2,490.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
		STMI	- Total				\$2,490.00		
		Construction	1 Stockpile S	TMI - Tota			\$2,490.00		
061	0 - Total						\$2,490.00		
062	CRASHWORTHY END TERMINAL	Construction Stockpile STMI		3	Apr 17, 2023	SYSTEM	\$5,625.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
	(MASH)	STIVII	- Total				\$5,625.00		
		Construction	n Stockpile S	TMI - Tota			\$5,625.00		
062	0 - Total						\$5,625.00		
07′	0 ROCK SOCKETS (4 FT 0 IN. DIA.)	Material		3	Apr 17, 2023	SYSTEM	\$42,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.	
				3	Apr 17, 2023	SYSTEM	(\$42,300.00)		
				4	May 3, 2023	SYSTEM	\$42,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.	
				4	May 3, 2023	SYSTEM	(\$42,300.00)		
			- Total				\$0.00		
		Material - To	tal				\$0.00		
071	0 - Total						\$0.00		
075	GALVANIZED STRUCTURAL STEEL PILES (12 IN		aterial	4	May 3, 2023	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.	
				4	May 3, 2023	SYSTEM	(\$37,940.00)		
			- Total				\$0.00		
		Material - To	tal				\$0.00		
075	60 - Total						\$0.00		
078	PILE POINT REINFORCEMENT	Material		4	May 3, 2023	SYSTEM	\$1,862.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				4	May 3, 2023	SYSTEM	(\$1,862.00)		
			- Total				\$0.00		
		Material - To	tal				\$0.00		
078	0 - Total						\$0.00		
079	00 CLASS B CONCRETE (SUBSTRUCTURE)	Material		4	May 3, 2023	SYSTEM	\$58,470.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.	
				4	May 3, 2023	SYSTEM	(\$58,470.75)		
			- Total				\$0.00		
		Material - To	tal				\$0.00		
079	0 - Total						\$0.00		
080	CLASS B-1 CONCRETE (SUBSTR)	Material		4	May 3, 2023	SYSTEM	\$56,254.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.	
				4	May 3, 2023	SYSTEM	(\$56,254.80)		
			- Total				\$0.00		
		Material - To	tal				\$0.00		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3451	0800 -	· Total						\$0.00	
	0820	SLAB ON CONCRETE NU- GIRDER	Construction Stockpile STMI		1	Mar 17, 2023	SYSTEM	\$111,690.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		GINDLIN	STIVII	- Total				\$111,690.00	
			Construction	Stockpile S	TMI - Total			\$111,690.00	
	0820 -	·Total						\$111,690.00	
	0830	NU 43, PRESTRESSED CONC NU-GIRDER	Construction Stockpile		4	May 3, 2023	SYSTEM	(\$336,860.76)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$336,860.76)	
			Construction	Stockpile - 1	Total			(\$336,860.76)	
			Construction Stockpile STMI		1	Mar 17, 2023	SYSTEM	\$336,860.76	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$336,860.76	
			Construction	Stockpile S	TMI - Total			\$336,860.76	
	0830 -	· Total						\$0.00	
	0850	REINFORCING STEEL (EPOXY COATED)	Material		4	May 3, 2023	SYSTEM	\$23,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$23,540.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0850 -	· Total						\$0.00	
	0870	PLAIN NEOPRENE BEARING PAD	Material		4	May 3, 2023	SYSTEM	\$1,824.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 19 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$1,824.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0870 -	· Total						\$0.00	
	0880	LAMINATED NEOPRENE BEARING PAD	Material		4	May 3, 2023	SYSTEM	\$2,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 20 on the current Payment Estimate.
					4	May 3, 2023	SYSTEM	(\$2,256.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0880 -	Total						\$0.00	
J4I3451 -	Total						\$144,462.57		
Overall -	Total							\$144,462.57	
								,	

MoDOT

Contract Adjustments for Contract - 221021-C02

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 16 of 16