

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 1, 2023

Progress Estimate Number 4		Contract ID Prime Contractor	221118-C01 Ideker, Inc.	Pay Period Start Pay Period End	July 16, 2023 August 1, 2023	Original Contract Amount Net Change Order Amount Current Contract Amount	\$7,757,617.87 \$0.00 \$7,757,617.87		
Approval Date									
August 2, 2023		Ger	nerated and Ap	proved (and should	be considered Dra	aft) at the Project Office Level by	johnsse		
August 3, 2023		Reviewe	ed and Approve	ed (and should be co	nsidered Draft) a	t the Resident Engineer Level by	wilsor2		
August 3, 2023			Re	eviewed and Approve	ed at the Central (	Office Controllers Office Level by	ramses1		
Original Comp	letion Date	Current Completi	ion Date	Actual Completion Date % of Current Contract Amo			ount Complete		
November	1, 2023	November 1, 2023 5.06%				5.06%			

	Contract Informational Dates										
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract								
Acceptance Date											
Awarded Date	December 6, 2022	December 6, 2022									
Letting Date	November 18, 2022	November 18, 2022									
Notice to Proceed Date	February 6, 2023	February 6, 2023									
Open to Traffic Date											
Work Began Date	May 31, 2023	May 31, 2023									

Contract Total Pay For Estimate No. 4			
	This Estimate	Previous	To Date
221118-C01			
Total Posted Items Pay	\$0.00	\$392,390.57	\$392,390.57
Gross Item Adjustments	\$0.00	\$420,705.05	\$420,705.05
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$ <mark>813,095.62</mark>	\$813,095.62
Contract Total Payable This Estimate:	\$0.00		

## Items Paid This Estimate Period

No Data Available

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		stments Exist on Contract						
Line Item	Adjust	tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3334	0060	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-467	\$18.75	(\$8,756.25)
	0060	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user johnsse overridding Payment Estimate Exception 2 on the current Payment Estimate.	467	\$18.75	\$8,756.25
	0110	8 IN. CONCRETE MEDIAN STRIP	Material			-3.8	\$2,160.30	(\$8,209.14)
	0110	8 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user johnsse overridding Payment Estimate Exception 3 on the current Payment Estimate.	3.8	\$2,160.30	\$8,209.14
	0120	MISC.	Material			-97	\$60.85	(\$5,902.45)
	0120	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user johnsse overridding Payment Estimate Exception 4 on the current Payment Estimate.	97	\$60.85	\$5,902.45
	0140	FURNISHING AND PLACING	Material			-186.3	\$379.45	(\$70,691.54)

Revision 3/23/2023 Page 1 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 1, 2023

Progress Estimate Number	Contract ID			. , .,	• •	\$7,757,617.87
4	Prime Contractor	Ideker, Inc.	Pay Period End	August 1, 2023	Net Change Order Amount Current Contract Amount	\$0.00 \$7,757,617.87

						Jonitract Ann	ψ.,	757,017.07
ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
334		CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR						
	0140	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user johnsse overridding Payment Estimate Exception 5 on the current Payment Estimate.	186.3	\$379.45	\$70,691.54
	0180	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-288	\$7.60	(\$2,188.80
	0180	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user johnsse overridding Payment Estimate Exception 6 on the current Payment Estimate.	288	\$7.60	\$2,188.80
	0210	CONSTRUCTION SIGNS	Material			-507	\$6.00	(\$3,042.00
	0210	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user johnsse overridding Payment Estimate Exception 8 on the current Payment Estimate.	507	\$6.00	\$3,042.00
	0230	CHANNELIZER (TRIM LINE)	Material			-402	\$17.00	(\$6,834.00
	0230	CHANNELIZER (TRIM LINE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user johnsse overridding Payment Estimate Exception 9 on the current Payment Estimate.	402	\$17.00	\$6,834.00
	0240	TYPE III MOVEABLE BARRICADE	Material			-9	\$165.00	(\$1,485.00
	0240	TYPE III MOVEABLE BARRICADE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user johnsse overridding Payment Estimate Exception 10 on the current Payment Estimate.	9	\$165.00	\$1,485.00
	0260	FLASHING ARROW PANEL	Material			-3	\$2,000.00	(\$6,000.00
	0260	FLASHING ARROW PANEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 11 on the current Payment Estimate.	3	\$2,000.00	\$6,000.00
	0280	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material			-3	\$4,000.00	(\$12,000.00
	0280	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user johnsse overridding Payment Estimate Exception 12 on the current Payment Estimate.	3	\$4,000.00	\$12,000.00
	0300	PAVEMENT EDGE TREATMENT	Material			-415	\$12.50	(\$5,187.50
	0300	PAVEMENT EDGE TREATMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user johnsse	415	\$12.50	\$5,187.50

Revision 3/23/2023 Page 2 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 1, 2023

Progress Estimate Number 4				221118-C01 Ideker, Inc.	Pay Period Start Pay Period End	July 16, 2023 August 1, 2023	Net Chan	Contract Amount nge Order Amount Contract Amount		\$7,757,617.87 \$0.00 \$7,757,617.87	
Project Number	Line No.	Item Description	on	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3334							overridding Payment Estimate Exception 13 on the current Payment Estimate.				
	0430	ALTERNATE DITCH	H CHECK	Material					-41	\$12.50	(\$512.50)
	0430	ALTERNATE DITCH	I CHECK	Material		generated Mat Adjustmen overridding Pay	nt offsets the origin terial Payment Est nt (0012) due to us ment Estimate Ex e current Payment	imate Item er johnsse ception 14	41	\$12.50	\$512.50
	0450	SIL	Γ FENCE	Material					-215	\$5.40	(\$1,161.00
	0450	SIL	Γ FENCE	Material		This adjustmen generated Mat Adjustmen overridding Pay on th	215	\$5.40	\$1,161.00		
Total											\$0.00

Revision 3/23/2023 Page 3 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J4I3334	I 435-1(329)	Resurface	I-435	CLAY	from 108th St. to Route 69							
rotals by	Job Numbers	3										
J4I3334					This Estimate Previous To Date							

Totals by Job Numb	bers			
J4I3334		This Estimate	Previous	To Date
Post	ted Item Pay	\$0.00	\$392,390.57	\$392,390.57
Gros	ss Item Adjustments	\$0.00	\$420,705.05	\$420,705.05
	Gross Item Pay	\$0.00	\$813,095.62	\$813,095.62
Ince	entive	\$0.00	\$0.00	\$0.00
Disir	ncentive	\$0.00	\$0.00	\$0.00
Liqu	idated Damages	\$0.00	\$0.00	\$0.00
Othe	er Contract Adjustments	\$0.00	\$0.00	\$0.00
	•			

Revision 3/23/2023 Page 4 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 3040506, Project Item Line Number 0060, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3334, Item 3040506, Project Item Line Number 0060, Material Set 304050696, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3334, Item 6083008, Project Item Line Number 0110, Material Set 608300896, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 6099903, Project Item Line Number 0120, Material Set 6099903, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 6131010, Project Item Line Number 0140, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 6131015, Project Item Line Number 0180, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 6131015, Project Item Line Number 0180, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 6161005, Project Item Line Number 0210, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 6161025, Project Item Line Number 0230, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 6161030, Project Item Line Number 0240, Material Set 616103096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 6161040, Project Item Line Number 0260, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 6161098A, Project Item Line Number 0280, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 6191000, Project Item Line Number 0300, Material Set 619100096, Material 0619PET - Material for Pavement Edge Treatment, Acceptance Action Generic 0619PET is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 8061006, Project Item Line Number 0430, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3334, Item 8061019, Project Item Line Number 0450, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient.	No Remark was entered by Engineer	johnsse	Overridden
Estimate Exception Type: Item Overrun: Contract 221118-C01, Contract Project J4l3334, Project Item Line Number 0110, Contract Line Item Number 0110, Item 6083008, Minor Item.	No Remark was entered by Engineer	johnsse	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221118-C01, Contract Project J4l3334, Project Item Line Number 0140, Contract Line Item Number 0140, Item 6131010, Minor Item.	No Remark was entered by Engineer	johnsse	Acknowledged
Estimate Exception Type: Item Overrun: Contract 221118-C01, Contract Project J4l3334, Project Item Line Number 0170, Contract Line Item Number 0170, Item 6131014, Minor Item.	No Remark was entered by Engineer	johnsse	Acknowledged

Revision 3/23/2023 Page 5 of 13



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)		
221118-C01	J4I3334	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.95	\$54,315.56	\$51,599.7		
		0001	0020	2031000	CLASS A EXCAVATION	226.00	0.00	226.00	CUYD	226.00	\$58.45	\$13,209.7		
		0001	0030	2036000	COMPACTING EMBANKMENT	13.00	0.00	13.00	CUYD	13.00	\$60.25	\$783.2		
		0001	0040	2072000	LINEAR GRADING CLASS 2	1.80	0.00	1.80	STA	1.80	\$3,022.85	\$5,441.1		
		0001	0050	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	4.00	0.00	4.00	100F	4.00	\$869.15	\$3,476.6		
		0001	0060	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	467.00	0.00	467.00	SQYD	467.00	\$18.75	\$8,756.2		
		0001	0070	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	12,726.40	0.00	12,726.40	TONS	0.00	\$85.83	\$0.0		
		0001	0080	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	36,343.60	0.00	36,343.60	TONS	0.00	\$117.60	\$0.0		
		0001	0090	4039905	MISC.OPTIONAL PAVEMENT	475.60	0.00	475.60	SQYD	475.60	\$82.20	\$39,094.3		
		0001	0100	4071005	TACK COAT	51,322.00	0.00	51,322.00	GAL	0.00	\$3.68	\$0.0		
		0001	0110	6083008	8 IN. CONCRETE MEDIAN STRIP	0.40	0.00	0.40	SQYD	3.80	\$2,160.30	\$8,209.1		
		0001	0120	6099903	MISC.CONCRETE CURB REPAIR	229.00	0.00	229.00	LF	97.00	\$60.85	\$5,902.4		
		0001	0130	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$2,500.00	\$0.0		
		0001 0140	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	151.00		151.00	SQYD	186.30	\$379.45	\$70,691.5			
		0001	0150	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	16.00	0.00	16.00	SQYD	0.00	\$1.00	\$0.0		
		0001	0160	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	16.00	0.00	16.00	SQYD	0.00	\$1.00	\$0.0		
		0001			0170	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	650.00	650.00 0.00	650.00	LF	738.00	\$1.50	\$1,107.0
					0180	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	325.00	0.00	325.00	EA	288.00	\$7.60	\$2,188.8
		0001	0190	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	9.80	0.00	9.80	TONS	0.00	\$4,086.45	\$0.0		
		0001	0200	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	90.00	0.00	90.00	SQYD	0.00	\$378.99	\$0.0		
		0001	0210	6161005	CONSTRUCTION SIGNS	1,390.00	0.00	1,390.00	SQFT	507.00	\$6.00	\$3,042.0		
		0001	0220	6161008	ADVANCED WARNING RAIL SYSTEM	17.00	0.00	17.00	EA	0.00	\$55.00	\$0.0		
		0001	0230	6161025	CHANNELIZER (TRIM LINE)	700.00	0.00	700.00	EA	402.00	\$17.00	\$6,834.0		
		0001	0240	6161030	TYPE III MOVEABLE BARRICADE	9.00	0.00	9.00	EA	9.00	\$165.00	\$1,485.0		
		0001	0250	6161033	DIRECTIONAL INDICATOR BARRICADE	55.00	0.00	55.00	EA	0.00	\$45.00	\$0.0		
		0001	0260	6161040	FLASHING ARROW PANEL	8.00	0.00	8.00	EA	3.00	\$2,000.00	\$6,000.0		
		0001	0270	6161055	SEQUENTIAL FLASHING WARNING LIGHT	55.00	0.00	55.00	EA	0.00	\$45.00	\$0.0		
		0001	0280	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	3.00	\$4,000.00	\$12,000.0		
		0001	0290	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$462,422.44	\$0.0		
		0001	0291	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.25	\$427,618.44	\$106,904.6		
		0001	0300	6191000	PAVEMENT EDGE TREATMENT	415.00	0.00	415.00	LF	415.00	\$12.50	\$5,187.5		
		0001	0310	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	1,312.00	0.00	1,312.00	LF	0.00	\$16.00	\$0.0		
		0001	0320	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	13.00	0.00	13.00	EA	0.00	\$280.00	\$0.0		
		0001	0330	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	152,616.00	0.00	152,616.00	LF	0.00	\$0.33	\$0.0		
		0001	0340	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	119,858.00	0.00	119,858.00	LF	0.00	\$0.33	\$0.0		
		0001	0350	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	13,343.00	0.00	13,343.00	LF	0.00	\$0.65	\$0.0		
		0001	0360	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	65.00	0.00	65.00	LF	0.00	\$0.50	\$0.0		
		0001	0370	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE-REDUCTION ARROW	2.00	0.00	2.00	EA	0.00	\$450.00	\$0.0		
		0001	0380	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	513,196.00	0.00	513,196.00	SQYD	0.00	\$2.40	\$0.0		
		0001	0390	6261000A		1,229.70	0.00	1,229.70	STA	0.00	\$19.38	\$0.0		
		0001	0400	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$4,000.00	\$4,000.0		
		0001	0410	8025006	MULCHING	0.50	0.00	0.50	ACRE	0.00	\$4,300.00	\$0.0		

Page 6 of 13 Revision 3/23/2023



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221118-C01	J4I3334	0001	0420	8051000A	SEEDING - COOL SEASON GRASSES	0.50	0.00	0.50	ACRE	0.00	\$4,300.00	\$0.00
		0001	0430	8061006	ALTERNATE DITCH CHECK	82.00	0.00	82.00	LF	41.00	\$12.50	\$512.50
		0001	0440	8061016	SEDIMENT REMOVAL	8.00	0.00	8.00	CUYD	0.00	\$200.00	\$0.00
		0001	0450	8061019	SILT FENCE	215.00	0.00	215.00	LF	215.00	\$5.40	\$1,161.00
		0040	0470	9031270A	2 IN. PSST POST - 12 GA.	42.00	0.00	42.00	LF	0.00	\$28.00	\$0.00
		0040	0485	9031274	CONCRETE POST ANCHOR FOR 2 IN. PSST 7 GA.	3.00	0.00	3.00	EA	0.00	\$270.00	\$0.00
		0040	0490	9031280	2.5 IN. PSST POST - 12 GA.	16.00	0.00	16.00	LF	0.00	\$30.00	\$0.00
		0040	0505	9031285	CONCRETE POST ANCHOR FOR 2.5 IN. PSST 7 GA.	1.00	0.00	1.00	EA	0.00	\$280.00	\$0.00
		0040	0510	9035004A	SH-FLAT SHEET	25.00	0.00	25.00	SQFT	0.00	\$25.00	\$0.00
		0040	0520	9039902	MISC.RELOCATE EXISTING SIGNS TO NEW POSTS	3.00	0.00	3.00	EA	0.00	\$100.00	\$0.00
		0001	5001	6189901	MISC.CONTRACT BOND PAYMENT	0.00	1.00	1.00	LS	1.00	\$34,804.00	\$34,804.00
	Project .	J4I3334 - To	otal Value	Posted to D	Date as of Report Generated Date							\$392,390.57
221118-C01 Overall - Total Value Posted to Date as of Report Generated Date									\$392,390.57			

Revision 3/23/2023 Page 7 of 13

16.00

16.00

16.00

16.00



June 9, 48

2023

#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

WO20-3 48x48 16.00 ROAD CLOSED AHEAD

WO20-1 48x48 16.00

WO20-1 48x48 16.00

WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD

ROAD/BRIDGE/RAMP WORK AHEAD

ROAD/BRIDGE/RAMP WORK AHEAD

DWR Total Quantity Posted Sign Information Station SF SF Each Total SE Project Line Log Mile Location Number Special Number Date For DWR Date Each Special Sign of Items Sign to Post Sign J4I3334 0210 May 80 WO20-1 48x48 16.00 RP IS435S to Shoal 16.00 0.170 1.00 16.00 ROAD/BRIDGE/RAMP WORK AHEAD Creek Pkwy S 2023 WO20-1 48x48 16.00 CST NE Shoal Creek 0.064 16.00 32 00 2 00 ROAD/BRIDGE/RAMP WORK AHEAD Pkwy N WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD 24.245 IS 435 N 1.00 16.00 16.00 48x48 16.00 24.534 IS 435 N 1.00 16.00 16.00 ROAD/BRIDGE/RAMP NARROWS 77 WO4-1aL 48x48 16.00 MERGE CST NE Shoal Creek 1.00 16.00 June 1, 0.109 16.00 2023 (ARROW SYMBOL) WO20-5 48x48 16.00 CST NE Shoal Creek 0.104 2.00 16.00 32.00 RIGHT/CENTER/LEFT LANE CLOSED Pkwy N AHFAD CST NE Shoal Creek WO20-6a 48x48 16.00 16.00 0.109 1.00 16.00 RIGHT/CENTER/LEFT LANE CLOSED Pkwy N R1-1 48x48 13.25 STOP RP IS435N to Shoal 0.264 1.00 13.25 13.25 Creek Rd N RP IS435N to Shoal June 2. 26 R11-2 48x30 10.00 ROAD 0.004 1.00 10.00 10.00 CLOSED Creek Rd N 2023

24.457

0.405

1.436

1.854

IS 435 N

(EB LM)

CST NE Shoal Creek

Pkwy S (NB LM)

CST NE 108th St E

CST NE 108th St W

1.00

1.00

1.00

1.00

16.00

16.00

16.00

16.00

Revision 3/23/2023 Page 8 of 13



# Line Item Adjustments by Estimate

!4	Line	Description	A -1:	Other	F-4	0	0	A t	Damardia	
roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
13334	0060	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		3	Jul 17, 2023	SYSTEM	\$8,756.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsse overridding Payment Estimate Exception 2 on the current Payment Estimate.	
		THICK)			3	Jul 17, 2023	SYSTEM	(\$8,756.25)		
					4	Aug 2, 2023	SYSTEM	\$8,756.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsse overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					4	Aug 2, 2023	SYSTEM	(\$8,756.25)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0060 -	Total						\$0.00		
	0800	ASPHALTIC CONCRETE	Construction Stockpile		2	Apr 3, 2023	SYSTEM	\$441,576.66	Payment Estimate Item Adjustment generated Stockpile Transaction	
		MIXTURE PG 76-22 (SP1	STMI	- Total				\$441,576.66		
		•	Construction	Stockpile S	ΓΜΙ - Total			\$441,576.66		
	0080 -	Total						\$441,576.66		
	0110	8 IN. CONCRETE MEDIAN STRIP	Material		3	Jul 17, 2023	SYSTEM	\$8,209.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsse overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					3	Jul 17, 2023	SYSTEM	(\$8,209.14)		
					4	Aug 2, 2023	SYSTEM	\$8,209.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsse overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					4	Aug 2, 2023	SYSTEM	(\$8,209.14)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
			Overrun	Overrun	3	Jul 17, 2023	SYSTEM	(\$7,345.02)		
				Overrun - T	otal			(\$7,345.02)		
			Overrun - To	tal				(\$7,345.02)		
	0110 -	Total						(\$7,345.02)		
	0120	MISC. PAVED DRAINAGE	Material		3	Jul 17, 2023	SYSTEM	\$5,902.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsse overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					3	Jul 17, 2023	SYSTEM	(\$5,902.45)		
						4	Aug 2, 2023	SYSTEM	\$5,902.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsse overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Aug 2, 2023	SYSTEM	(\$5,902.45)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0120 -	Total						\$0.00		
	0140	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		3	Jul 17, 2023	SYSTEM	\$70,691.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsse overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					3	Jul 17, 2023	SYSTEM	(\$70,691.54)		
					4	Aug 2, 2023	SYSTEM	\$70,691.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsse overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					4	Aug 2, 2023	SYSTEM	(\$70,691.54)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
			Overrun	Overrun	3	Jul 17,	SYSTEM	(\$13,394.59)		



# Line Item Adjustments by Estimate

t Li	ine	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks	
4 01	140	FURN & PLACE	Overrun	Туре		2023				
		CONC MATL FOR FULL DEPTH	0.000.000	Overrun - To	otal	2020		(\$13.394.59)		
		FULL DEPTH	Overrun - To		o tui			(\$13,394.59)		
01	140 -	Total	Overruin 10					(\$13,394.59)		
	170	FULL DEPTH PAVEMENT	Overrun	Overrun	3	Jul 17,	SYSTEM	(\$132.00)		
		REPAIR SAW CUT		Overrun - To	otal	2023		(\$132.00)		
		,	Overrun - To	tal				(\$132.00)		
01	170 -	Total						(\$132.00)		
01	180	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		3	Jul 17, 2023	SYSTEM	\$2,188.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsse overridding Payment Estimate Exception 6 on the current Payment Estimate.	
		IONI			3	Jul 17, 2023	SYSTEM	(\$2,188.80)		
					4	Aug 2, 2023	SYSTEM	\$2,188.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsse overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					4	Aug 2, 2023	SYSTEM	(\$2,188.80)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
01	180 -	Total						\$0.00		
02	210	CONSTRUCTION SIGNS	Material		3	Jul 17, 2023	SYSTEM	\$3,042.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					3	Jul 17, 2023	SYSTEM	(\$3,042.00)		
					4	Aug 2, 2023	SYSTEM	\$3,042.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsse overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					4	Aug 2, 2023	SYSTEM	(\$3,042.00)		
				- Total				\$0.00		
			Material - Tot	tal				\$0.00		
02	210 -	Total						\$0.00		
02	0230	CHANNELIZER (TRIM LINE)			3	Jul 17, 2023	SYSTEM	\$6,834.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user johnsse overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					3	Jul 17, 2023	SYSTEM	(\$6,834.00)		
						4	Aug 2, 2023	SYSTEM	\$6,834.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsse overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Aug 2, 2023	SYSTEM	(\$6,834.00)		
				- Total				\$0.00		
			Material - Total					\$0.00		
02	230 -	Total						\$0.00		
02	0240	TYPE III MOVEABLE BARRICADE	Material		3	Jul 17, 2023	SYSTEM	\$1,485.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user johnsse overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					3	Jul 17, 2023	SYSTEM	(\$1,485.00)		
					4	Aug 2, 2023	SYSTEM	\$1,485.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user johnsse overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					4	Aug 2, 2023	SYSTEM	(\$1,485.00)		
				- Total				\$0.00		
			Material - Tot	tal				\$0.00		
02	240 -	Total						\$0.00		



# Line Item Adjustments by Estimate

ARROW PANEL	ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
A   Aug 2   SYSTEM   \$6.000.00   This adjustment offsets the original system-generated Material Payme Estimate Exception 11 on the current Payment Estimate.	334	0260		Material		3		SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user johnsse overridding Payment Estimate Exception 11 on the current Payment Estimate.			
Aug 2,   2023   SYSTEM   (66,000.00)						3		SYSTEM	(\$6,000.00)				
CASE   CASE WID   Material   Total   So 00						4		SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user johnsse overridding Payment Estimate Exception 11 on the current Payment Estimate.			
Material - Total						4		SYSTEM	(\$6,000.00)				
CMS W/O   Material					- Total				\$0.00				
National				Material - To	tal				\$0.00				
COMMUNICATION		0260 -	Total						\$0.00				
3		0280	COMMUNICATION INTERFACE,	Material		3		SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user johnsse overridding Payment Estimate Exception 12 on the current Payment Estimate.			
2023   SYSTEM   Estimate Item Adjustment (0010) due to user johnsse overridding Pay Estimate Exception 12 on the current Payment Estimate.			CONT F/			3		SYSTEM	(\$12,000.00)				
Total   S0.00						4		SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user johnsse overridding Payment Estimate Exception 12 on the current Payment Estimate.			
Naterial - Total   So.00						4	Aug 2, 2023	SYSTEM	(\$12,000.00)				
Solid   Soli					- Total				\$0.00				
PAVEMENT EDGE TREATMENT   Material TREATMENT   Substitute   Substitu				Material - To	tal				\$0.00				
TREATMENT    2023   SySTEM   Estimate Item Adjustment (0014) due to user johnsse overridding Pay Estimate Exception 13 on the current Payment Estimate.		0280 -	Total						\$0.00				
Aug 2, SYSTEM   S5,187.50   This adjustment offsets the original system-generated Material Payme Estimate Exception 13 on the current Payment Estimate.		0300		Material		3		SYSTEM	\$5,187.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user johnsse overridding Payment Estimate Exception 13 on the current Payment Estimate.			
Estimate Item Adjustment (0011) due to user johnsse overridding Pay Estimate Exception 13 on the current Payment Estimate.    Aug 2, 2023   SYSTEM   \$5.00						3		SYSTEM	(\$5,187.50)				
Total  Total  Total  S0.00  Material - Total  S0.00  S0.00  ALTERNATE DITCH CHECK  Material  Aug 2, 2023  SYSTEM  STILT FENCE  Material  SULT FENCE  Material  SO.00  SYSTEM  SYSTEM  STILT FENCE  SO.00  SYSTEM  STILT FENCE  SO.00  SYSTEM  SO.00  SYSTEM  STILT FENCE  SO.00  SYSTEM  STILT FENCE  SO.00  SYSTEM  STILT FENCE  SO.00  SO.00  SYSTEM  STILT FENCE  SO.00  SO.00  STILT FENCE  Material  SO.00  SO.00  SILT FENCE  Material  SO.00  SILT FENCE  SO.00  SO.00  SILT FENCE  SO.00						4		SYSTEM	\$5,187.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user johnsse overridding Payment Estimate Exception 13 on the current Payment Estimate.			
Substitute   Sub						4		SYSTEM	(\$5,187.50)				
Solid   State   Solid   Soli					- Total				\$0.00				
ALTERNATE DITCH CHECK  Material  ALTERNATE DITCH CHECK  Material  ALTERNATE DITCH CHECK  Material  ALTERNATE DITCH CHECK  Material  ALTERNATE DITCH CHECK  BUSINESS OF ALTERNATE DITC				Material - To	tal				\$0.00				
DITCH CHECK  2023 Estimate Item Adjustment (0015) due to user johnsse overridding Pay Estimate Exception 14 on the current Payment Estimate.  3 Jul 17, 2023 SYSTEM (\$512.50)  4 Aug 2, 2023 SYSTEM \$512.50 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0012) due to user johnsse overridding Pay Estimate Exception 14 on the current Payment Estimate.  4 Aug 2, 2023 SYSTEM (\$512.50)  - Total \$0.00  Material - Total \$0.00  0430 - Total \$0.00  0450 SILT FENCE Material 3 Jul 17, 2023 SYSTEM \$1,161.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0016) due to user johnsse overridding Pay Estimate Item Adjustment (0016) due to user johnsse overridding Pay Estimate Exception 15 on the current Payment Estimate.		0300 -	Total						\$0.00				
2023  4 Aug 2, 2023  4 Aug 2, 2023  4 Aug 2, 2023  5 SYSTEM \$512.50  This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0012) due to user johnsse overridding Payrestimate Exception 14 on the current Payment Estimate.  5 O.00  Material - Total  5 O.00  0430 - Total  5 O.00  0430 - Total  5 O.00  0430 - SILT FENCE Material  3 Jul 17, 2023  SYSTEM \$1,161.00  This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0016) due to user johnsse overridding Payrestimate Exception 15 on the current Payment Estimate.		0430				3		SYSTEM	\$512.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user johnsse overridding Payment Estimate Exception 14 on the current Payment Estimate.			
2023 Estimate Item Adjustment (0012) due to user johnsse overridding Payl Estimate Exception 14 on the current Payment Estimate.  4 Aug 2, 2023 \$9.00  - Total \$0.00  Material - Total \$0.00  0430 - Total \$0.00  0450 SILT FENCE Material \$3 Jul 17, 2023 \$9.5TEM \$1,161.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0016) due to user johnsse overridding Payl Estimate Exception 15 on the current Payment Estimate.									3		SYSTEM	(\$512.50)	
- Total \$0.00  Material - Total \$0.00  0430 - Total \$0.00  0450 SILT FENCE Material 3 Jul 17, 2023 \$1,161.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0016) due to user johnsse overridding Paylestimate Exception 15 on the current Payment Estimate.						4		SYSTEM	\$512.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user johnsse overridding Payment Estimate Exception 14 on the current Payment Estimate.			
Material - Total  \$0.00  0430 - Total  \$0.00  0450 SILT FENCE Material 3 Jul 17, 2023 SYSTEM \$1,161.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0016) due to user johnsse overridding Paylestimate Exception 15 on the current Payment Estimate.						4		SYSTEM	(\$512.50)				
\$0.430 - Total       0450     SILT FENCE     Material     3     Jul 17, 2023     \$1,161.00     This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0016) due to user johnsse overridding Payrestimate Exception 15 on the current Payment Estimate.					- Total				\$0.00				
O450 SILT FENCE Material 3 Jul 17, 2023 \$1,161.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0016) due to user johnsse overridding Payment Estimate Exception 15 on the current Payment Estimate.				Material - Total					\$0.00				
Estimate Item Adjustment (0016) due to user johnsse overridding Payl Estimate Exception 15 on the current Payment Estimate.		0430 -	Total						\$0.00				
0 0000000		0450	SILT FENCE	Material		3		SYSTEM	\$1,161.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user johnsse overridding Payment Estimate Exception 15 on the current Payment Estimate.			
3 Jul 17, 2023 (\$1,161.00)						3	Jul 17, 2023	SYSTEM	(\$1,161.00)				
						4		SYSTEM	\$1,161.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user johnsse overridding Payment Estimate Exception 15 on the current Payment Estimate.			
4 Aug 2, SYSTEM (\$1,161.00)						4		SYSTEM	(\$1,161.00)				

Aug 4, 2023



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3334	4 0450 SILT FENCE Material - Total								
	0450 - Total							\$0.00	
J4I3334 -	- Total						\$420,705.05		
Overall - Total									

# MoDOT

## Contract Adjustments for Contract - 221118-C01

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 13 of 13