

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 4, 2023

Progress Estima	ate Number	Contract ID Prime Contractor	221118-F01 Concrete Strategies,	Pay Period Start LLC Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$3,706,765.90 \$0.00 \$3,706,765.90
Approval Date							By User
December 4, 2023			Generated and Ap	proved (and should be	considered Draft) at	the Project Office Level by	BAUERD1
December 4, 2023			Reviewed and Approv	ed (and should be cons	idered Draft) at the F	Resident Engineer Level by	BAUERD1
December 5, 2023	Reviewed and Approved at the Central Office Controllers Office Level by						
Original Comp	letion Date	Current Co	mpletion Date	Actual Completion	Date %	of Current Contract Amount	Complete
September 3	30, 2024	Septemb	er 30, 2024				

Contract Informational Dat	.03	Milestones
Original Completion Date	Current Completion Date	No Milestones Exist for Contract
December 6, 2022	December 6, 2022	
November 18, 2022	November 18, 2022	
July 10, 2023	July 10, 2023	
	December 6, 2022 November 18, 2022	December 6, 2022 December 6, 2022 November 18, 2022 November 18, 2022

Contract Total Pa	y For Estimate No. 9			
		This Estimate	Previous	To Date
221118-F01				
	Total Posted Items Pay	\$328,812.50	\$1,186,053.02	\$1,514,865.52
	Gross Item Adjustments	(\$62,870.75)	(\$29,143.22)	(\$92,013.97)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$1,156,909.80	\$1,422,851.55
Contract Total Pag	yable This Estimate:	\$265,941.75		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3326	0280	6181000	MOBILIZATION	LS	\$867,800.000	0.25	\$216,950.00
	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$540.000	2	\$1,080.00
	0360	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$4.250	1,290	\$5,482.50
	0370	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$4.250	1,624	\$6,902.00
	0690	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$154.500	369	\$57,010.50
	0700	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	SQFT	\$150.500	275	\$41,387.50
Project J6I3	3 <mark>326 - Tot</mark> a	ı					\$328,812.50
Overall - To	otal						\$328,812.50

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3326	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)				337.5	\$15.00	\$5,062.50
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)				-337.5	\$15.00	(\$5,062.50)
	0110	CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-184.5	\$235.00	(\$43,357.50)

Revision 3/23/2023 Page 1 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 4, 2023

Progress Estimate Number 9 Contract ID 221118-F01 Pay Period Start November 16, 2023 Original Contract Amount \$3,706,765.90 Pay Period End December 1, 2023 Original Contract Amount \$0.00

ct er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
26	0110	CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user roberg5 overridding Payment Estimate Exception 3 on the current Payment Estimate.	184.5	\$235.00	\$43,357.50
	0160	FURNISHING TYPE 1 ROCK DITCH LINER	Material			-33.22	\$65.50	(\$2,175.91
	0160	FURNISHING TYPE 1 ROCK DITCH LINER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user roberg5 overridding Payment Estimate Exception 8 on the current Payment Estimate.	33.22	\$65.50	\$2,175.91
	0300	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-2	\$540.00	(\$1,080.00
	0360	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun			-535	\$4.25	(\$2,273.75
	0360	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-1,290	\$4.25	(\$5,482.50
03	0370	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun			-584	\$4.25	(\$2,482.00
	0370	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-1,624	\$4.25	(\$6,902.00
	0410	FLOWABLE BACKFILL	Material			-11.5	\$1,700.00	(\$19,550.00
	0410	FLOWABLE BACKFILL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user roberg5 overridding Payment Estimate Exception 14 on the current Payment Estimate.	11.5	\$1,700.00	\$19,550.00
	0650	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material			-5	\$700.00	(\$3,500.00
	0650	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user roberg5 overridding Payment Estimate Exception 4 on the current Payment Estimate.	5	\$700.00	\$3,500.00
	0660	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-1,259	\$132.00	(\$166,188.00
	0660	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user roberg5 overridding Payment Estimate Exception 5 on the current Payment Estimate.	1,259	\$132.00	\$166,188.00
06	0690	SUBSTRUCTURE REPAIR (FORMED)	Overrun			-289	\$154.50	(\$44,650.50
	0700	SUBSTRUCTURE REPAIR (UNFORMED)	Material			-275	\$150.50	(\$41,387.50
	0700	SUBSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user roberg5	275	\$150.50	\$41,387.50

Revision 3/23/2023 Page 2 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 4, 2023

Progr	ess Es	timate Number 9	Contract ID Prime Contr			Pay Period Start November 16, 2023 Orig LC Pay Period End December 1, 2023 Net Cur	Change Ord	er Amount	
Project Number	Line No.	·		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6l3326						overridding Payment Estimate Exception 15 on the current Payment Estimate.			
Total									(\$62,870.75)

Revision 3/23/2023 Page 3 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number											
J6I3326	FAS S501(83)	2 Bridge rehabilitations	I-70	ST LOUIS	on McDonnell Boulevard and Lambert International Boulevard						

Revision 3/23/2023 Page 4 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Element Deception Type: Insulficient Materials Project (2002). Items 304004, Project Iden Line Linescent Delaments. Acceptance Action General 1007 (TABL D. 1 % insulficient Linescent Delaments. Acceptance Action General 1007 (TABL D. 1 % insulficient Linescent Delaments. Acceptance Action General 1007 (TABL D. 1 % insulficient Linescent Delaments. Acceptance Action General 1007 (TABL D. 1 % insulficient Linescent Delaments. Acceptance Action General 1007 (TABL D. 1 % insulficient Linescent Delaments. Acceptance Action General 1007 (TABL D. 1 % insulficient Linescent Delaments (See 2005)). Acceptance Action General 1007 (TABL D. 1 % insulficient Linescent Delaments (See 2005)). Acceptance Action General Report Insulficient Linescent Delaments (Project Idea). Acceptance Action General Report Insulficient Linescent Deposit Insulficient Line Report Insulficient Linescent Report Insulficient Report Insulficient Linescent Report Insulficient Report Insulficient Report Insulficient Linescent Report Insulficient Report Insulficient Report Insulficient Report Insulficient Report Insulficient Report Insulficient Linescent Report Insulficient Report Insulficient Report Insulficient Linescent Report Insulficient Report Insulficient Report Insulficient Report Insulficient Report Insulficient Report Insulficient Linescent Report Insulficient Report Insulficient Linescent Report Insulficient Report Insulficient Linescent Report Insulficient Report Insulficient Report Insulficient Linescent Report Insulficient Report Insulficient Linescent Report Insulfici	Exceptions (Discrepancies) This Estimate Period			
Number (100), Material Set 30:000059056, Material 100711AB.D. 175 - Ago Base Type 1 & S (interaction) Committee Companies Anno Section (10071ABL D. 175 - Interaction) Committee Companies Anno Section (10071ABL D. 175 - Interaction) Committee Companies Anno Section (10071ABL D. 175 - Interaction) Companies Anno Section (10071ABL D. 175 - In	Exceptions / Discrepencies	Explanation		Status
Namber Gold, Material Set 30050006, Material 005050187 (special property of a 5 Base, Acceptance Action Genetic C00408111 (pp. 1 emillicient Materials Project, 103208, then 5020131), Project them Lee Namber Gold, Materials 520733101, Materials (103208, then 5020131), Project them Lee Namber Gold, Acceptance Set 502733101, Materials (103208, then 5020007, Project than Like Namber Gold, Materials (103208, then 5020007, Project than Like Namber Gold, Materials (103208, then 5020007, Project than Like Namber Gold, Materials (103208, then 5020007, Project than Like Namber Gold, Materials (10320006, Materials (103208, then 5020007, Project than Like Namber Gold), Materials (10320006, Materials (103208, then 5020007, Project than Like Namber Gold), Materials (1032006, Materials (103208, then 5020007, Project than Like Namber Gold), Materials (10320006, Materials (103208, then 5030007, Project than Like Namber Gold), Materials (10320006, Materials (103208, then 5030007, Project than Like Namber Gold), Materials (10320006, Materials (103208, then 5030007, Project than Like Namber Gold), Materials (10320006, Materials (103208, then 5030007, Project than Like Namber Gold), Materials (10320006, Materials (103208, then 5030007, Project than Like Namber Gold), Materials (1032006, then 103208, then 5030007, Project than Like Namber Gold), Materials (1032006, then 103208, then 5030007, Project than Like Namber Gold), Materials (1032006, then 103208, then 5030007, Project than Like Namber Gold), Materials (1032006, then 10300007, Project than Like Namber Gold), Materials (1032006, then 1030007, then 10300007, Project than Like Organia (103200007, Project than Like Namber Gold), Materials (10320007, then 1030007, then 1030007, Project than Like Organia (10320007, then 1030007, then	Number 0060, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5	CRE20 Report not submitted. Contractor notified.	roberg5	Acknowledged
Number 010, Material Set 600133196, Material Ströndschlaß 1 in Entire Control of Strong Control of Str	Number 0060, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base,	CRE2O Report not submitted. Contractor notified.	roberg5	Acknowledged
Number (650, Material Set 500006.4 Material OSCCLATX. Bridge Deck Concrete, Latex, Acceptance Action Genetic OSCCLATX is instifficated. Elements Exception Type: Instifficant Materials: Project JIS3328, Item 5052000. Project Item Line Number 0600, Material OSCCCLATX. Bridge Deck Concrete, Latex, Acceptance Action Genetic Genetic Concrete, Latex, Acceptance Action Genetic Genetics Concrete (Latex). Walting on concrete test results.	Number 0110, Material Set 502133196, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60	of situation and waiting for Materials to clear issue on	roberg5	Overridden
Namber 0680, Material Set 95000058, Material 0505CCLATX - Bridge Deck Concriees, Latex, Acceptance Action Generic 0505CCLATS in instificient. Eliminate Exception Type: Instificient Materials: Popical, 3813328, Item 5050000, Project Item Line Number 0680, Material set 950000058, Material 0505CEMS. SSD in its will instificient. Eliminate Exception Type: Instificient Materials: Popical, 3813338, Item 5050000, Project Item Line Number 0680, Material Set 950000058, Material 0505FGCMS. CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. Ca - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. Ca - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. Ca - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. Ca - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. Ca - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. Ca - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. Activated 1005FACCNS. Ca - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS and train of Sand FACCH Plant Plant Plant Sand FACCH Plant Plant Sand FACCH Plant Plant Sand FACCH Plant Plant Sand FACCH Plant Plant Plant Sand FACCH Plant Plant Plant Plant FACCH Plant P	Number 0650, Material Set 5050004, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance	Waiting on concrete test results.	roberg5	Overridden
Number (1966), Material Set (1952) (2005) (Asterial 1005) (CEML SBD 1- Bridge Wearing Surface Grade ELE) (EMDO) (Acceptance Action Generic 1005) (2005) (Asterial 1005) (Asterial Set (1952) (2005)) (Asterial 1005)	Number 0660, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex,	Waiting on concrete test results.	roberg5	Overridden
Number 680, Material Set 69500096, Material ORSPACCNS. CA. Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. CA. Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. CA is insufficient. Eliminate Exception Type: Insufficient Materials: Project Ji33328, Item 698010A, Project Item Line Number 0180, Material Set 69801046, Material 30807DD. Paved Drainage Material for Ditch Liner. Acceptance Action Generic 0609FDCL is insufficient. Eliminate Exception Type: Insufficient Materials: Project Ji33328, Item 6200021, Project Item Line Number 0300, Material Set 2000002190, Material Set 20000020190, Material Set 20000020190, Material Set 20000020190, Material Set 200000020190, Material Set 200000020190, Material Set 200000020190, Material Set 2000000000000000000000000000000000000	Number 0660, Material Set 505200096, Material 1005GECMLSBD - Bridge Wearing Surface Grade E	Waiting on concrete test results.	roberg5	Overridden
Number 0160. Material Set 6006010A96. Material 0060PPDL - Paved Drainage Material for Ditch Liner. Acceptance Action Generic 0060PPDL in issufficient. Paved Drainage Material for Ditch Liner. Acceptance Action Generic 0160PMPFWHXV - Pref Mrk Tape Direct Indicat or Shape WH. Acceptance Action Generic 1048PMPFWHXV. Pref Mrk Tape Direct Indicat or Shape WH. Acceptance Action Generic 1048PMPFWHXV. Pref Mrk Tape Direct Indicat or Shape WH. Acceptance Action Generic 1048PMPFWHXV. Pref Mrk Tape Direct Indicat or Shape WH. Acceptance Action Generic 1048PMPFWHXV. Pref Mrk Tape Direct Indicat or Shape WH. Acceptance Action Generic 1048PMPFWHXV. Pref Mrk Tape Direct Indicat or Shape WH. Acceptance Action Generic 1048PMPFWHXV. Insufficient. Estimate Exception Type Insufficient Materials: Project J813336. Item 800000C, Project Item Line Number 0300. Material Set 200000CGG, Material 1048PMRFWHY Insufficient. Estimate Exception Type Insufficient Materials: Project J813336. Item 800000C, Project Item Line Number 0300. Material Set 200000CGG, Material 1048PMRFWHY Insufficient Line Number 0300. Material Set 200000CGG, Material 1048PMRFWHY Insufficient Line Number 0300. Material Set 200000CGG, Material 1048PMRFWHY Insufficient Line Number 0300. Material Set 200000CGG, Material 1048PMRFWHY Insufficient Line Number 0300. Material Set 200000CGG, Material 1048PMRFWHY Insufficient Line Number 0300. Material Set 200000CGG, Material 1048PMRFWHY Insufficient Line Number 0300. Material Set 200000CGG, Material 1048PMRFWHY Insufficient Line Number 0300. Material Set 200000CGG, Material 1048PMRFWHY Insufficient Materials Project J813336, Item 8024600A, Project Item Line Number 0300. Material Set 200000CGG, Material 1048PMRFFP Pis Insufficient. Estimate Exception Type: Insufficient Materials: Project J813336, Item 8024600A, Project Item Line Number 0300. Material Set 200000CGG, Material 4068SPSM - Special Provision Special Mortar, Acceptance Action Generic 1048PMRFFP Pis Insufficient. Estimate Exception Type: Item Overnur. Contract 21118-	Number 0660, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A,	Waiting on concrete test results.	roberg5	Overridden
Number 0300, Material Set 620002196, Material 1048PMFPVHXX : Insufficient. Estimate Exception Type: Insufficient Materials: Project, 1813326, Item 8206000C, Project Item Line Number 0300, Material Set 200000C69, Material 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project 1813326, Item 8206000C, Project Item Line Number 0300, Material Set 620000C69, Material 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project 1813326, Item 8206000C, Project Item Line Number 0300, Material Set 620000C69, Material 1048PMRTWWWH- Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMRTWWWH- Marking Paint Acrylic Waterborne Villor, Acceptance Action Generic 1048PMRTWWWH- Marking Paint Acrylic Waterborne Villor, Acceptance Action Generic 1048PMRTWWWH- Marking Paint Acrylic Waterborne Villor, Acceptance Action Generic 1048PMRTWWWH- Marking Paint Acrylic Waterborne Villor, Acceptance Action Generic 1048PMRTWWH- Marking Paint Acrylic Waterborne Villor, Acceptance Action Generic 1048PMRTWWH- Marking Paint Acrylic Waterborne Villor, Acceptance Action Generic 1048PMRTWWH- Marking Paint Acrylic Waterborne Villor, Acceptance Action Generic 1048PMRTWWH- Marking Paint Acrylic Waterborne Villor, Acceptance Action Generic 1048PMRTWWH- Marking Paint Acrylic Waterborne Villor, Acceptance Action Generic 1048PMRTWWH- Marking Paint Acrylic Waterborne Villor, Acceptance Action Generic 1048PMRTWWH- Marking Paint Acrylic Waterborne Villor, Acceptance Action Generic 1048PMRTWWH- Marking Paint Acrylic Waterborne Villor, Marking Paint Acrylic Waterborne Villor, Marking Paint Acrylic Waterborne Villor, Waterborne Vill	Number 0160, Material Set 6096010A96, Material 0609PDDL - Paved Drainage Material for Ditch Liner,	of use in field and requested Sampling Checklist to be revised to reflect use in field. Sample Record submitted under	roberg5	Overridden
Number 0360, Material Set 6206000C96, Material 1048PMRBTP is insufficient. Materials Exception Type: Insufficient Materials: Project Jisl3326, Item 6206000C, Project Item Line Number 0360, Material Set 6206000C6, Material 1048PMRTWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project Jisl3326, Item 620600TC, Project Item Line Number 0370, Material Set 620600C10C6, Material 1048PMRTWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project Jisl3326, Item 620600TC, Project Item Line Number 0370, Material Set 620600TC6, Material 1048PMRTWBYL is insufficient. Estimate Exception Type: Insufficient Materials: Project Jisl3326, Item 620600TC, Project Item Line Number 0370, Material Set 620600TC6, Material 1048PMRBTP: Insufficient Materials: Project Jisl3326, Item 620600TC, Project Item Line Number 0370, Material Set 620600TC6, Material 1048PMRBTP: Insufficient Materials: Project Jisl3326, Item 6214600A, Project Item Line Number 0410, Material Set 6274600A96, Material 1062PTF: Flowable Backfil, Acceptance Action Generic 0416PMRTWBYL is insufficient. Estimate Exception Type: Insufficient Materials: Project Jisl3326, Item 6214600A, Project Item Line Number 0700, Material Set 6274600A96, Material 062PTF: Flowable Backfil, Acceptance Action Generic 062FTF is insufficient. Estimate Exception Type: Insufficient Materials: Project Jisl3326, Item 6214600A, Project Item Line Number 0706, Material Set 6274600A96, Material 062PTF: Flowable Backfil, Acceptance Action Generic 04668PSM is insufficient. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project Jisl3326, Project Item Quantity on Change Order under review. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project Jisl3326, Project Item Quantity on Change Order under review. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project Jisl3326, Project Item Quantity on Change Order under review. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract P	Number 0300, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or	Certs not submitted by contractor.	roberg5	Acknowledged
Number 0360, Material Set 6206000C96, Material 1048PMTRWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I3326, Item 6206001C, Project Item Line Number 0370, Material Set 6206001C96, Material 1048PMTRWBYL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6I3326, Item 6206001C, Project Item Line Number 0360, Ontract Line Item Number 0360, Contract Line Item Number 0360, Item 6206001C, Minor Item. Estimate Exception Type: Insufficient Materials: Project J6I3326, Item 6206001C, Project Item Line Number 0360, Contract Line Item Number 0410, Contract Project J6I3326, Project Item Line Number 0410, Contract Line Item Number 0410, Contract Line Item Number 04100, Item 60000, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0360, Contract Line Item Number 0370, Under 221118-F01, Contract Project J6I3326, Project Item Line Number 0360, Contract Line Item Number 0370, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0360, Contract Line Item Number 0370, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0360, Contract Line Item Number 0370, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0360, Contract Line Item Number 0370, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0370, Londard Line Item Number 0370, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0370, Contract Line Item Number 0370, Item 60000, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 04000, Contract Line	Number 0360, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf	Certs not submitted by contractor.	roberg5	Acknowledged
Number 0370, Material Set 6206001C96, Material 1048PMTRWBYL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i3326, Item 6206001C, Project Item Line Number 0370, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i3326, Item 6214600A, Project Item Line Number 0700, Material Set 6214600A, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0462FBF FBF in sinsufficient. Estimate Exception Type: Insufficient Materials: Project J6i3326, Item 6214600A, Project Item Line Number 0700, Material Set 6214600A, Material 4066SPSM is insufficient. Estimate Exception Type: Insufficient Materials: Project J6i3326, Item 7040102, Project Item Line Number 0700, Material Set 704010296, Material 4066SPSM is insufficient. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0370, Contract Line Item Number 0370, Item 6206000C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0370, Contract Line Item Number 0370, Item 6206000C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0370, Contract Line Item Number 0690, Item 3040504, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0690, Contract Line Item Number 0690, Item 3040504, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0690, Contract Line Item Number 0690, Item 3040504, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract	Number 0360, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne	Certs not submitted by contractor.	roberg5	Acknowledged
Number 0370, Material Set 6206001C96, Material 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l3326, Item 6214600A, Project Item Line Number 0410, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient. Estimate Exception Type: Insufficient Materials: Project J6l3326, Item 7040102, Project Item Line Requires QC. Working with Materials to resolve issue. Contractor given ok by RE to use product not on pre-approved list pending performance. Will evaluate performance. Will evaluate performance after material has been placed and cured. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6l3326, Project Item Line Number 0360, Contract Line Item Number 0360, Contract Line Item Number 0360, Contract Line Item Number 0370, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6l3326, Project Item Line Number 0370, Contract Line Item Number 0370, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6l3326, Project Item Line Number 0370, Contract Line Item Number 0590, Contract Line Item Number 0590, Contract Line Item Number 0690, Contract Line Item Number 0690, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6l3326, Project Item Line Number 0690, Contract Line Item Number 0690, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6l3326, Project Item Line Number 0060, Contract Line Item Number 0690, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6l3326, Project Item Line Number 0060, Contract Line Item Number 0060, Item 3040504, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6l3326, Project Item Line Number 0070, Contract Line Item Number 0070, Item 4011231, Minor Item. Estimate Except	Number 0370, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne	Certs not submitted by contractor.	roberg5	Acknowledged
Number 0410, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient. Estimate Exception Type: Insufficient Number 0360, Contract Line Item Number 0370, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Line Number 0060, Contract Line Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Line Number 0060, Contract Line Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cuerton Type: Item Overrun: Contract 221118-F01, Contract Project J613326, Project Item Cu	Number 0370, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf	Certs not submitted by contractor.	roberg5	Acknowledged
Number 0700, Material Set 704010296, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0360, Contract Line Item Number 0370, Item 6206000C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0370, Contract Line Item Number 0370, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0390, Contract Line Item Number 0390, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0690, Contract Line Item Number 0690, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0060, Contract Line Item Number 0060, Item 3040504, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0110, Contract Line Item Number 0110, Item 5021331, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0110, Contract Line Item Number 0110, Item 5021331, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0070, Contract Line Item Number 0070, Item 4011231, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Quantity on Change Order under review.	Number 0410, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action		roberg5	Overridden
Line Number 0360, Contract Line Item Number 0360, Item 6206000C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Unimber 0370, Contract Line Item Number 0370, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Unimber 0690, Contract Line Item Number 0690, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Unimber 0690, Contract Line Item Number 0690, Item 3040504, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Unimber 0060, Contract Line Item Number 0060, Item 3040504, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Unimber 0110, Contract Unime Item Number 0110, Item 5021331, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Unimber 0070, Contract Line Item Number 0070, Item 4011231, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Unimber 0070, Item 4011231, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Unimber 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Unimber 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Unimber 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Unimber 0260, Contract Unimer Project J6I3326, Project Item Unimper 0260, Contract Unimer Project J6I3326, Project Item Unimper 0260, Contract Unimer Project J6I3326, Project I	Number 0700, Material Set 704010296, Material 4066SPSM - Special Provision Special Mortar,	approved list pending performance. Will evaluate	roberg5	Overridden
Line Number 0370, Contract Line Item Number 0370, Item 6206001C, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0690, Contract Line Item Number 0690, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0690, Contract Line Item Number 0600, Item 3040504, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0110, Contract Line Item Number 0110, Item 5021331, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0110, Item 5021331, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0070, Contract Line Item Number 0070, Item 4011231, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Quantity on Change Order under review. Foberg5 Acknowledged Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Quantity on Change Order under review. Foberg5 Acknowledged Contract Line Item Number 0260, Item 6173600D, Minor Item.		Quantity on Change Order under review.	roberg5	Acknowledged
Line Number 0690, Contract Line Item Number 0690, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0060, Contract Line Item Number 0060, Item 3040504, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0110, Contract Line Item Number 0110, Item 5021331, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0110, Contract Line Item Number 01070, Contract Line Item Number 0070, Item 4011231, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0070, Contract Line Item Number 0070, Item 4011231, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6I3326, Project Item Quantity on Change Order under review. roberg5 Acknowledged		Quantity on Change Order under review.	roberg5	Acknowledged
Line Number 0060, Contract Line Item Number 0060, Item 3040504, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0110, Contract Line Item Number 0110, Item 5021331, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0070, Contract Line Item Number 0070, Item 4011231, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0070, Contract Line Item Number 0070, Item 4011231, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Quantity on Change Order under review. roberg5 Acknowledged Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Quantity on Change Order under review. roberg5 Acknowledged		Quantity on Change Order under review.	roberg5	Acknowledged
Line Number 0110, Contract Line Item Number 0110, Item 5021331, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0070, Contract Line Item Number 0070, Item 4011231, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Quantity on Change Order under review. roberg5 Acknowledged		Quantity on Change Order under review.	roberg5	Acknowledged
Line Number 0070, Contract Line Item Number 0070, Item 4011231, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Quantity on Change Order under review. roberg5 Acknowledged		Quantity on Change Order under review.	roberg5	Acknowledged
Line Number 0260, Contract Line Item Number 0260, Item 6173600D, Minor Item. Estimate Exception Type: Item Overrun: Contract 221118-F01, Contract Project J6i3326, Project Item Quantity on Change Order under review. roberg5 Acknowledged		Quantity on Change Order under review.	roberg5	Acknowledged
		Quantity on Change Order under review.	roberg5	Acknowledged
		Quantity on Change Order under review.	roberg5	Acknowledged

Revision 3/23/2023 Page 5 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221118-F01	J6I3326	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.25	\$58,200.00	\$14,550.00
		0001	0020	2035500	EMBANKMENT IN PLACE	36.00	0.00	36.00	CUYD	0.00	\$87.50	\$0.00
		0001	0030	2071000	LINEAR GRADING CLASS 1	3.40	0.00	3.40	STA	0.00	\$1,845.00	\$0.00
		0001	0040	2072000	LINEAR GRADING CLASS 2	3.70	0.00	3.70	STA	1.85	\$3,391.00	\$6,273.35
		0001	0050	2159910	MISC.SHAPING SLOPES, CLASS III	2.00	0.00	2.00	100F	1.00	\$1,944.00	\$1,944.00
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	216.00	0.00	216.00	SQYD	337.50	\$15.00	\$5,062.50
		0001	0070	4011231	BITUMINOUS PAVEMENT MIXTURE PG58-28H, (BP-1)	32.50	0.00	32.50	TONS	45.96	\$540.00	\$24,818.40
		0001	0800	4071005	TACK COAT	26.00	0.00	26.00	GAL	20.00	\$27.00	\$540.00
		0001	0090	4139903	MISC.CRACK SEALING USING HOT POUR	1,050.00	0.00	1,050.00	LF	0.00	\$5.00	\$0.00
		0001	0100	5021312	CONCRETE PAVEMENT (12 IN. NON-REINFORCED 15 FT. JOINTS)	69.40	0.00	69.40	SQYD	0.00	\$226.00	\$0.00
		0001	0110	5021331	CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	145.80	0.00	145.80	SQYD	184.50	\$235.00	\$43,357.50
		0001	0120	5041000	CONCRETE APPROACH PAVEMENT	758.10	0.00	758.10	SQYD	0.00	\$145.00	\$0.0
		0001	0130	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	18.00	0.00	18.00	LF	18.00	\$104.00	\$1,872.00
		0001	0140	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	75.00	0.00	75.00	LF	0.00	\$52.00	\$0.00
		0001	0150	6094010	DRAIN BASIN	1.00	0.00	1.00	EA	0.00	\$6,300.00	\$0.00
		0001	0160	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	45.00	0.00	45.00	CUYD	33.22	\$65.50	\$2,175.9
		0001	0170	6096041	PLACING TYPE 1 ROCK DITCH LINER	45.00	0.00	45.00	CUYD	33.22	\$101.00	\$3,355.22
	0001	0180	6113020	FURNISHING TYPE 2 ROCK BLANKET	72.00	0.00	72.00	CUYD	43.50	\$60.50	\$2,631.75	
		0001	0190	6113040	PLACING TYPE 2 ROCK BLANKET	72.00	0.00	72.00	CUYD	43.50	\$85.75	\$3,730.1
		0001	0200	6122008	IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	1.00	\$2,477.00	\$2,477.0
		0001	0210	6122020	REPLACEMENT SAND BARREL	9.00	0.00	9.00	EA	0.00	\$475.00	\$0.0
		0001	0220	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$112,055.00	\$56,027.5
		0001	0230	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	8.00	0.00	8.00	EA	3.00	\$2,700.00	\$8,100.0
		0001	0240	6172001	CONCRETE TRAFFIC BARRIER, TYPE B (MODIFIED)	55.00	0.00	55.00	LF	0.00	\$232.00	\$0.0
		0001	0250	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	182.00	0.00	182.00	LF	182.00	\$288.00	\$52,416.0
		0001	0260	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	450.00	0.00	450.00	LF	475.00	\$38.75	\$18,406.2
		0001	0270	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	450.00	0.00	450.00	LF	0.00	\$16.00	\$0.0
		0001	0280	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$867,800.00	\$650,850.00
		0001	0290	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.0
		0001	0300	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	2.00	\$540.00	\$1,080.0
		0001	0310	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STRILT/RT	3.00	0.00	3.00	EA	0.00	\$810.00	\$0.0
		0001	0320	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	250.00	0.00	250.00	LF	539.00	\$10.75	\$5,794.2
		0001	0330	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	900.00	0.00	900.00	LF	457.00	\$5.25	\$2,399.2
		0001	0340	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,480.00	0.00	1,480.00	LF	0.00	\$2.10	\$0.0
		0001	0350	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	740.00	0.00	740.00	LF	0.00	\$4.25	\$0.0
		0001	0360	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	755.00	0.00	755.00	LF	1,290.00	\$4.25	\$5,482.5
		0001	0370	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,040.00	0.00	1,040.00	LF	1,624.00	\$4.25	\$6,902.0
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	4,745.00	0.00	4,745.00	LF	0.00	\$2.10	\$0.0
		0001	0390	6209902	MISC.SPECIAL PAVEMENT MARKING, WORDS (TO, I-70, EAST)	3.00	0.00	3.00	EA	0.00	\$2,160.00	\$0.0
		0001	0400	6209903	MISC.TEMPORARY REMOVABLE MARKING TAPE, 4" BLACK	3,595.00	0.00	3,595.00	LF	638.00	\$3.25	\$2,073.5
		0001	0410	6214600A	FLOWABLE BACKFILL	21.00	0.00	21.00	CUYD	11.50	\$1,700.00	\$19,550.0
		0001	0420	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	136.00	0.00	136.00	SQYD	136.00	\$4.75	\$646.00
		0001	0430	8025006	SURFACING (GREATER THAN 3 IN. THICK) MULCHING	0.80	0.00	0.80	ACRE	0.00	\$4,320.00	\$0.00

Revision 3/23/2023 Page 6 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
21118-F01	J6I3326	0001	0440	8051000A	SEEDING - COOL SEASON GRASSES	0.40	0.00	0.40	ACRE	0.00	\$8,100.00	\$0.
		0001	0450	8061017	TEMPORARY SEEDING	0.40	0.00	0.40	ACRE	0.00	\$3,888.00	\$0.
		0001	0460	8064132	TYPE 1B EROSION CONTROL BLANKET	1,791.00	0.00	1,791.00	SQYD	0.00	\$3.10	\$0.
		0001	0470	9109903	MISC.MODOT ITS ASSETS RELOCATION	100.00	0.00	100.00	LF	0.00	\$43.00	\$0.
		0010	0480	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	200.00	0.00	200.00	LF	137.50	\$39.00	\$5,362.
		0010	0490	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	1.00	0.00	1.00	EA	0.00	\$4,536.00	\$0.
		0010	0500	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULARINO CURB)	4.00	0.00	4.00	EA	3.00	\$4,428.00	\$13,284
		0010	0510	6061080	MGS END ANCHOR	3.00	0.00	3.00	EA	1.00	\$1,729.00	\$1,729
		0010	0520	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$3,672.00	\$7,344
		0010	0530	6069902	MISC.BLACK POWDER COATED MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	1.00	0.00	1.00	EA	0.00	\$5,400.50	\$0.
		0010	0540	6069902	MISC.BLACK POWDER COATED MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	1.00	0.00	1.00	EA	0.00	\$5,292.50	\$0
		0010	0550	6069902	MISC.BLACK POWDER COATED TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$4,536.50	\$0
		0010	0560	6069903	MISC.BLACK POWDER COATED MGS GUARDRAIL, 8 FT. POSTS. 6 FT 3 IN. SPACING	588.00	0.00	588.00	LF	0.00	\$50.75	\$0
		0030	0570	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE & PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$24,000.00	\$0
		0040	0580	9031250A	U-CHANNEL POST, 3 LB	36.00	0.00	36.00	LF	0.00	\$26.00	\$0
		0040	0590	9039902	MISC.COVER EXISTING OVERHEAD SIGNS	11.00	0.00	11.00	EA	0.00	\$3,900.00	\$0
		0040	0600	9039902	MISC.REMOVE AND RELOCATE GROUND MOUNTED SIGNS	4.00	0.00	4.00	EA	0.00	\$650.00	\$0
		0070	0610	2161000	SCARIFICATION OF BRIDGE DECK	1,259.00	0.00	1,259.00	SQYD	1,259.00	\$14.50	\$18,25
		0070	0620	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,259.00	0.00	1,259.00	SQYD	1,259.00	\$68.00	\$85,61
		0070	0630	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	92.00	0.00	92.00	LF	92.00	\$431.00	\$39,65
		0070	0640	2169903	MISC.Remove and Replace Barrier Curb	12.00	0.00	12.00	LF	12.00	\$964.50	\$11,57
		0070	0650	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CY	5.00	\$700.00	\$3,50
		0070	0660	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,259.00	0.00	1,259.00	SQYD	1,259.00	\$132.00	\$166,18
		0070	0670	7031004	DIAMOND GRINDING	1,259.00	0.00	1,259.00	SQYD	0.00	\$14.00	\$
		0070	0680	7034214	CLASS B-2 CONCRETE	9.00	0.00	9.00	CUYD	9.00	\$5,200.00	\$46,80
		0070	0690	7040101	SUBSTRUCTURE REPAIR (FORMED)	200.00	0.00	200.00	SQFT	489.00	\$154.50	\$75,55
		0070	0700	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	520.00	0.00	520.00	SQFT	275.00	\$150.50	\$41,38
		0070	0710	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$104.00	\$
		0070	0720	7040110	EPOXY PRESSURE INJECTING	150.00	0.00	150.00	LF	0.00	\$55.50	\$
		0070	0730	7040113	CLEANING AND EPOXY COATING	50.00	0.00	50.00	SQFT	0.00	\$8.75	\$
		0070	0740	7049903	MISC.Barrier Curb Repair (Unformed)	21.00	0.00	21.00	LF	0.00	\$346.00	\$(
		0070	0750	7101000	REINFORCING STEEL (EPOXY COATED)	1,390.00	0.00	1,390.00	LB	1,390.00	\$4.05	\$5,62
		0070	0760	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$8,425.00	\$
		0070	0770	7125102	(EPOXY) SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$4,537.00	\$
		0070	0780	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$3,133.00	\$
		0070	0790	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	86.00	0.00	86.00	LF	86.00	\$587.00	\$50,48
		0071	0800	2161000	SCARIFICATION OF BRIDGE DECK	2,369.00	0.00	2,369.00	SQYD	0.00	\$14.50	\$
		0071	0810	2161001	TOTAL SURFACE HYDRO DEMOLITION	2,369.00	0.00	2,369.00	SQYD	0.00	\$68.00	\$
		0071	0820	2161503	REMOVAL OF EXISTING DECK REPAIR	105.00	0.00	105.00	SQFT	0.00	\$36.00	\$
		0071	0830	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	198.00	0.00	198.00	LF	0.00	\$431.00	\$
		0071	0840	2169903	MISC.Remove and Replace Barrier Curb	32.00	0.00	32.00	LF	0.00	\$964.50	\$
		0071	0850	5031010A	BRIDGE APPROACH SLAB (MAJOR)	476.00	0.00	476.00	SQYD	0.00	\$235.00	\$(
		0071	0860	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	16.00	0.00	16.00	CY	0.00	\$700.00	\$0

Revision 3/23/2023 Page 7 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221118-F01	J6I3326	0071	0870	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	2,369.00	0.00	2,369.00	SQYD	0.00	\$132.00	\$0.00
		0071	0880	7031004	DIAMOND GRINDING	2,369.00	0.00	2,369.00	SQYD	0.00	\$14.00	\$0.00
		0071	0890	7034214	CLASS B-2 CONCRETE	16.80	0.00	16.80	CUYD	0.00	\$5,350.00	\$0.00
		0071	0900	7040101	SUBSTRUCTURE REPAIR (FORMED)	600.00	0.00	600.00	SQFT	0.00	\$154.25	\$0.00
		0071	0910	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	230.00	0.00	230.00	SQFT	0.00	\$150.25	\$0.00
		0071	0920	7040106	FULL DEPTH REPAIR	1,100.00	0.00	1,100.00	SQFT	0.00	\$104.00	\$0.00
		0071	0930	7040113	CLEANING AND EPOXY COATING	1,500.00	0.00	1,500.00	SQFT	0.00	\$7.25	\$0.00
		0071	0940	7101000	REINFORCING STEEL (EPOXY COATED)	900.00	0.00	900.00	LB	0.00	\$4.05	\$0.00
		0071	0950	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$14,700.00	\$0.00
		0071	0960	7120915	EXPANSION DEVICE (FLAT PLATE)	198.00	0.00	198.00	LF	0.00	\$1,425.00	\$0.00
		0071	0970	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	80.00	0.00	80.00	LB	0.00	\$74.75	\$0.00
		0071	0980	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$5,700.00	\$0.00
		0071	0990	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$3,700.00	\$0.00
	Project J	J6I3326 - To	tal Value	Posted to E	late as of Report Generated Date							\$1,514,865.50
221118-F01 Ove	rall - Total	l Value Pos	ted to Da	te as of Rep	ort Generated Date							\$1,514,865.50

Revision 3/23/2023 Page 8 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6l3326

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0280	6181000	MOBILIZATION	11/17/23	12/4/23	0.25	LS	Jobsite					25% of contract earned. 3rd partial payment.
0300	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	11/18/23	11/22/23	2.00	EA	NB McDonnell					
0360	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	11/18/23	11/22/23	1,290.00	LF	McDonnell Blvd.					
0370	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	11/18/23	11/22/23	1,624.00	LF	McDonnell Blvd.					
0690	7040101	SUBSTRUCTURE REPAIR (FORMED)	11/17/23	12/4/23	369.00	SQFT	McDonnell Bridge North Abutment					
0700	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	12/1/23	12/4/23	275.00	SQFT	south substructure of McDonnell Blvd. bridge.					

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 9 of 17



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3326	0060	TYPE 5 AGGREGATE FOR	Material		7	Nov 2, 2023	SYSTEM	(\$1,642.50)	
		BASE			8	Nov 16, 2023	SYSTEM	(\$5,062.50)	
					9	Dec 4, 2023	SYSTEM	(\$5,062.50)	
				- Total				(\$11,767.50)	
			Material - Tota	ı				(\$11,767.50)	
			MaterialCredit		8	Nov 16, 2023	SYSTEM	\$1,642.50	
					9	Dec 4, 2023	SYSTEM	\$5,062.50	
				- Total				\$6,705.00	
			MaterialCredit	- Total				\$6,705.00	
			Overrun	Overrun	8	Nov 16, 2023	SYSTEM	(\$1,822.50)	
				Overrun - Total				(\$1,822.50)	
			Overrun - Tota	ıl				(\$1,822.50)	
	0060 -	Total						(\$6,885.00)	
	0070	BIT. PAVEMENT MIXTURE PG58-28H (BP-1)	Overrun	Overrun	7	Nov 2, 2023	SYSTEM	(\$7,268.40)	
				Overrun - T	otal			(\$7,268.40)	
			Overrun - Tota	n - Total					
	0070 -	Total						(\$7,268.40)	
	0800	TACK COAT	Material		4	Sep 18, 2023	SYSTEM	\$297.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user unlanj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Sep 18, 2023	SYSTEM	(\$297.00)	
					5	Oct 2, 2023	SYSTEM	(\$297.00)	
					6	Oct 16, 2023	SYSTEM	(\$297.00)	
				- Total				(\$594.00)	
			Material - Tota	ı				(\$594.00)	
			MaterialCredit	MaterialCredit	6	Oct 16, 2023	SYSTEM	\$297.00	
					7 Nov 2, 2023		SYSTEM	\$297.00	
				- Total				\$594.00	
			MaterialCredit	- Total				\$594.00	
	0080 -							\$0.00	
	0110	CONCRETE PAVEMENT (7 1/2 IN. NON-REINF,	Material		4	Sep 18, 2023	SYSTEM	\$8,577.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user unlanj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Sep 18, 2023	SYSTEM	(\$8,577.50)	
					5	Oct 2, 2023	SYSTEM	(\$8,577.50)	
					6	Oct 16, 2023	SYSTEM	\$8,577.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user roberg5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Oct 16, 2023	SYSTEM	(\$8,577.50)	
					7	Nov 2, 2023	SYSTEM	\$8,577.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user roberg5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Nov 2, 2023	SYSTEM	(\$8,577.50)	
					8	Nov 16, 2023	SYSTEM	\$43,357.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user roberg5 overridding Payment Estimate Exception 3 on the current Payment Estimate.



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
26	0110	CONCRETE PAVEMENT (7 1/2	Material	. , , , ,	8	Nov 16, 2023	SYSTEM	(\$43,357.50)														
		IN. NON-REINF,			9	Dec 4, 2023	SYSTEM	\$43,357.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user roberg5 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
					9	Dec 4, 2023	SYSTEM	(\$43,357.50)														
				- Total				(\$8,577.50)														
			Material - Tota	ı				(\$8,577.50)														
			MaterialCredit		6	Oct 16, 2023	SYSTEM	\$8,577.50														
				- Total				\$8,577.50														
			MaterialCredit - Total					\$8,577.50														
			Overrun	Overrun	8	Nov 16, 2023	SYSTEM	(\$9,094.50)														
				Overrun - To	otal			(\$9,094.50)														
			Overrun - Tota	ıl				(\$9,094.50)														
	0110 -	Total						(\$9,094.50)														
	0160	FURNISHING TYPE 1 ROCK DITCH LINER	Material		4	Sep 18, 2023	SYSTEM	\$400.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user unlanj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
					4	Sep 18, 2023	SYSTEM	(\$400.86)														
						5	Oct 2, 2023	SYSTEM	\$859.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user roberg5 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					5	Oct 2, 2023	SYSTEM	(\$859.36)														
																		6	Oct 16, 2023	SYSTEM	\$859.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user roberg5 overridding Payment Estimate Exception 8 on the current Payment Estimate.
											6	Oct 16, 2023	SYSTEM	(\$859.36)								
								7	Nov 2, 2023	SYSTEM	\$1,059.79	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user roberg5 overridding Payment Estimate Exception 7 on the current Payment Estimate.										
					7	Nov 2, 2023	SYSTEM	(\$1,059.79)														
					8	Nov 16, 2023	SYSTEM	\$2,175.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user roberg5 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
					8	Nov 16, 2023	SYSTEM	(\$2,175.91)														
					9	Dec 4, 2023	SYSTEM	\$2,175.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user roberg5 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
					9	Dec 4, 2023	SYSTEM	(\$2,175.91)														
				- Total				\$0.00														
			Material - Tota	I				\$0.00														
	0160 -	Total						\$0.00														
	0180	FURNISHING TYPE 2 ROCK BLANKET	Material		4	Sep 18, 2023	SYSTEM	\$1,936.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user unlanj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.													
					4	Sep 18, 2023	SYSTEM	(\$1,936.00)														
					5	Oct 2, 2023	SYSTEM	\$1,936.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user roberg5 overridding Payment Estimate Exception 6 on the current Payment Estimate.													
					5	Oct 2, 2023	SYSTEM	(\$1,936.00)														
				- Total				\$0.00														
			Material - Tota	l				\$0.00														
	0180 -	Total						\$0.00														



	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
613326	0200	IMPACT ATTENUATOR 40	Material		1	Aug 2, 2023	SYSTEM	(\$2,477.00)	
		MPH (SAND BARREL ARRAY)		- Total				(\$2,477.00)	
			Material - Tota	1				(\$2,477.00)	
			MaterialCredit		2	Aug 16, 2023	SYSTEM	\$2,477.00	
				- Total				\$2,477.00	
			MaterialCredit	- Total				\$2,477.00	
	0200 -	Total						\$0.00	
	0230	MISC. TRAFFIC CONTROL	Material		1	Aug 2, 2023	SYSTEM	(\$5,400.00)	
		DEVICES		- Total				(\$5,400.00)	
			Material - Tota					(\$5,400.00)	
			MaterialCredit		2	Aug 16,	SYSTEM	\$5,400.00	
				Total		2023		05 400 00	
			MatarialOussia	- Total				\$5,400.00	
	0200	Total	MaterialCredit	- Total				\$5,400.00	
	0230 -		Outer	0	4	A C	ever::	\$0.00	
	0260	TEMPORARY TRAFFIC BARRIER, CONT.	Overrun	Overrun		Aug 2, 2023	SYSTEM	(\$968.75)	
		FURN/RE		Overrun - To	otal			(\$968.75)	
			Overrun - Tota	ıl				(\$968.75)	
	0260 -	Total						(\$968.75)	
	0300	PREF THERMO PVMT MARK, LT/RT ARROW	Material		9	Dec 4, 2023	SYSTEM	(\$1,080.00)	
				- Total				(\$1,080.00)	
			Material - Tota	l				(\$1,080.00)	
	0300 -	Total						(\$1,080.00)	
	0320	TEMPORARY REMOVABLE	Material		5	Oct 2,	SYSTEM	(\$5,794.25)	
	0320					2023		(ψο, το 4.20)	
		MARKING TAPE 4 IN.,		- Total				(\$5,794.25)	
		MARKING TAPE 4	Material - Tota						
		MARKING TAPE 4	Material - Tota MaterialCredit		6		SYSTEM	(\$5,794.25)	
		MARKING TAPE 4			6	2023 Oct 16,		(\$5,794.25) (\$5,794.25)	
		MARKING TAPE 4		l - Total	6	2023 Oct 16,		(\$5,794.25) (\$5,794.25) \$5,794.25	
		MARKING TAPE 4	MaterialCredit MaterialCredit Overrun	- Total - Total Overrun	5	2023 Oct 16,		(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25	
		MARKING TAPE 4	MaterialCredit MaterialCredit Overrun	l - Total - Total	5	Oct 16, 2023	SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25	
		MARKING TAPE 4	MaterialCredit MaterialCredit Overrun	- Total - Total Overrun	5	Oct 16, 2023	SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75)	
	0320 -	MARKING TAPE 4 IN.,	MaterialCredit MaterialCredit Overrun	- Total - Total Overrun	5	Oct 16, 2023	SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75)	
	0320 - 0330	MARKING TAPE 4 IN., Total TEMPORARY REMOVABLE	MaterialCredit MaterialCredit Overrun	- Total - Total Overrun	5	Oct 16, 2023	SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75) (\$3,106.75)	
		MARKING TAPE 4 IN., Total TEMPORARY	MaterialCredit MaterialCredit Overrun Overrun - Tota	- Total - Total Overrun	5 otal	Oct 16, 2023 Oct 2, 2023 Oct 2,	SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75) (\$3,106.75) (\$3,106.75) (\$3,106.75)	
		MARKING TAPE 4 IN., Total TEMPORARY REMOVABLE	MaterialCredit MaterialCredit Overrun Overrun - Tota	- Total - Total Overrun Overrun - Total	5 otal	Oct 16, 2023 Oct 2, 2023 Oct 2,	SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75) (\$3,106.75) (\$3,106.75) (\$3,106.75) (\$2,399.25)	
		MARKING TAPE 4 IN., Total TEMPORARY REMOVABLE	MaterialCredit MaterialCredit Overrun Overrun - Tota	- Total - Total Overrun Overrun - Total	5 otal	Oct 16, 2023 Oct 2, 2023 Oct 2, 2023	SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75) (\$3,106.75) (\$3,106.75) (\$2,399.25)	
		MARKING TAPE 4 IN., Total TEMPORARY REMOVABLE	MaterialCredit MaterialCredit Overrun Overrun - Tota Material Material - Tota	- Total - Total Overrun Overrun - Total - Total	5 otal	Oct 16, 2023 Oct 2, 2023 Oct 2, 2023	SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75) (\$3,106.75) (\$3,106.75) (\$2,399.25) (\$2,399.25) \$2,399.25	
		MARKING TAPE 4 IN., Total TEMPORARY REMOVABLE	MaterialCredit MaterialCredit Overrun Overrun - Tota Material Material - Tota MaterialCredit	- Total - Total Overrun - Total - Total	5 otal	Oct 16, 2023 Oct 2, 2023 Oct 2, 2023	SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75) (\$3,106.75) (\$3,106.75) (\$2,399.25) (\$2,399.25) \$2,399.25	
	0330	Total TEMPORARY REMOVABLE MARKING TAPE	MaterialCredit MaterialCredit Overrun Overrun - Tota Material Material - Tota	- Total - Total Overrun - Total - Total	5 otal	Oct 16, 2023 Oct 2, 2023 Oct 2, 2023	SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75) (\$3,106.75) (\$3,106.75) (\$2,399.25) (\$2,399.25) \$2,399.25 \$2,399.25 \$2,399.25	
	0330	Total TEMPORARY REMOVABLE MARKING TAPE	MaterialCredit MaterialCredit Overrun Overrun - Tota Material Material - Tota MaterialCredit MaterialCredit	- Total - Total Overrun - Total - Total	5 5	Oct 16, 2023 Oct 2, 2023 Oct 2, 2023 Oct 16, 2023	SYSTEM SYSTEM SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75) (\$3,106.75) (\$3,106.75) (\$2,399.25) (\$2,399.25) \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25	
	0330	Total Total TEMPORARY REMOVABLE MARKING TAPE Total 4 IN. WHITE WATERBORNE	MaterialCredit MaterialCredit Overrun Overrun - Tota Material Material - Tota MaterialCredit MaterialCredit	- Total - Total Overrun - Total - Total - Total - Total - Total	5 otal	Oct 16, 2023 Oct 2, 2023 Oct 2, 2023	SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75) (\$3,106.75) (\$3,106.75) (\$2,399.25) (\$2,399.25) \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25	
	0330	Total Temporary REMOVABLE MARKING TAPE Total 4 IN. WHITE	MaterialCredit MaterialCredit Overrun Overrun - Tota Material Material - Tota MaterialCredit MaterialCredit	- Total - Total Overrun - Total - Total	5 5	Oct 16, 2023 Oct 2, 2023 Oct 16, 2023	SYSTEM SYSTEM SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75) (\$3,106.75) (\$3,106.75) (\$2,399.25) (\$2,399.25) \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25	
	0330	Total Total TEMPORARY REMOVABLE MARKING TAPE Total 4 IN, WHITE WATERBORNE PAVEMENT	MaterialCredit MaterialCredit Overrun Overrun - Tota Material Material - Tota MaterialCredit MaterialCredit	- Total - Total Overrun - Total - Total - Total - Total - Total	5 5	Oct 16, 2023 Oct 2, 2023 Oct 16, 2023	SYSTEM SYSTEM SYSTEM	(\$5,794.25) (\$5,794.25) \$5,794.25 \$5,794.25 \$5,794.25 \$5,794.25 (\$3,106.75) (\$3,106.75) (\$3,106.75) (\$2,399.25) (\$2,399.25) \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25 \$2,399.25	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
26	0360	4 IN. WHITE WATERBORNE	Overrun	Overrun - T	otal			(\$2,273.75)		
		PAVEMENT MARKING	Overrun - Tota	al				(\$2,273.75)		
	0360 -	Total						(\$7,756.25)		
	0370	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		9	Dec 4, 2023	SYSTEM	(\$6,902.00)		
				- Total				(\$6,902.00)		
			Material - Tota	ıl				(\$6,902.00)		
			Overrun	Overrun	9	Dec 4, 2023	SYSTEM	(\$2,482.00)		
				Overrun - T	otal			(\$2,482.00)		
			Overrun - Tota	al				(\$2,482.00)		
	0370 -	Total						(\$9,384.00)		
	0410	FLOWABLE BACKFILL	Material		4	Sep 18, 2023	SYSTEM	\$19,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user unlanj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					4	Sep 18, 2023	SYSTEM	(\$19,550.00)		
					5	Oct 2, 2023	SYSTEM	\$19,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user roberg5 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					5	Oct 2, 2023	SYSTEM	(\$19,550.00)		
					6	Oct 16, 2023	SYSTEM	\$19,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user roberg5 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					6	Oct 16, 2023	SYSTEM	(\$19,550.00)		
					7	Nov 2, 2023	SYSTEM	\$19,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user roberg5 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					7	Nov 2, 2023	SYSTEM	(\$19,550.00)		
					8	Nov 16, 2023	SYSTEM	\$19,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user roberg5 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
						8	Nov 16, 2023	SYSTEM	(\$19,550.00)	
					9	Dec 4, 2023	SYSTEM	\$19,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user roberg5 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					9	Dec 4, 2023	SYSTEM	(\$19,550.00)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
	0410 -	Total						\$0.00		
	0480	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile		8	Nov 16, 2023	SYSTEM	(\$694.12)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		1 1 O IIV		- Total				(\$694.12)		
			Construction	Stockpile - To	otal			(\$694.12)		
			Construction Stockpile STMI		6	Oct 16, 2023	SYSTEM	\$1,851.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$1,851.00		
			Construction	Stockpile STI	MI - Total			\$1,851.00		
	0480 - 0490	MGS BRIDGE	Construction		6	Oct 16,	SYSTEM	\$1,156.88 \$2,265.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
		APP. TRANS SEC (EXT CURB)	Stockpile STMI	- Total		2023		\$2,265.00		
			Construction	Stockpile STI	MI - Total			\$2,265.00		
	0490 -	Total						\$2,265.00		
	0500	MGS BRIDGE	Construction		8	Nov 16,	SYSTEM	(\$2,200.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
	2000	03 DI (IDOL	2000.0001			7107 10,	J. OI LIVI	(42,200.00)		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J6I3326	0500	APP. TRANS SEC (REG/NO CURB)	Stockpile			2023																				
		(ICEG/NO COICE)		- Total				(\$2,200.00)																		
			Construction	Stockpile - To	otal			(\$2,200.00)																		
			Construction Stockpile		6	Oct 16, 2023	SYSTEM	\$4,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction																	
			STMI	- Total				\$4,400.00																		
			Construction	Stockpile STI	MI - Total			\$4,400.00																		
	0500 -	Total						\$2,200.00																		
	0510	MGS END ANCHOR	Construction Stockpile		6	Oct 16, 2023	SYSTEM	\$1,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction																	
			STMI	- Total				\$1,750.00																		
			Construction	Stockpile STI	MI - Total			\$1,750.00																		
	0510 -	Total						\$1,750.00																		
	0520	TYPE A CRASHWORTHY	Construction Stockpile		8	Nov 16, 2023	SYSTEM	(\$1,875.00)	Payment Estimate Item Adjustment generated Stockpile Transaction																	
		END TERMINAL	·	- Total				(\$1,875.00)																		
		(MASH)	Construction		otal			(\$1,875.00)																		
			Construction Stockpile		6	Oct 16, 2023	SYSTEM	\$1,875.00	Payment Estimate Item Adjustment generated Stockpile Transaction																	
			STMI	- Total		2020		\$1,875.00																		
			Construction		tockpile STMI - Total			\$1,875.00																		
	0520 -	Total	Construction .	otookpiio o ri	iii rotai			\$0.00																		
	0530	MISC. GUARDRAIL ITEM	Construction Stockpile		6	Oct 16, 2023	SYSTEM	\$2,265.00	Payment Estimate Item Adjustment generated Stockpile Transaction																	
		CONTROL TIEM	STMI	- Total		2020		\$2,265.00																		
			Construction		MI - Total			\$2,265.00																		
	0530 -	Total	Construction	Otockpile OTI	vii - Totai			\$2,265.00																		
	0530 -	MISC. GUARDRAIL ITEM	MISC.	Construction Stockpile		6	Oct 16, 2023	SYSTEM	\$2,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction																
			STMI	- Total				\$2,200.00																		
			Construction	Stockpile STI	MI - Total			\$2,200.00																		
	0540 -	Total						\$2,200.00																		
	0550	MISC. GUARDRAIL ITEM	Construction Stockpile		6	Oct 16, 2023	SYSTEM	\$3,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction																	
			STMI	- Total				\$3,750.00																		
			Construction	Stockpile STI	MI - Total			\$3,750.00																		
	0550 -	Total						\$3,750.00																		
	0560	MISC. GUARDRAIL ITEM	Construction Stockpile		6	Oct 16, 2023	SYSTEM	\$10,874.63	Payment Estimate Item Adjustment generated Stockpile Transaction																	
			STMI					\$10,874.63																		
			Construction	- Total Stockpile STI	VII - Total			\$10,874.63																		
	0560 -	Total						\$10,874.63																		
	0650	SUPPLEMENTARY WEARING	Material		6	Oct 16, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user roberg5 overridding Payment																	
		SURFACE MATERIAL			6	Oct 16, 2023	SYSTEM	(\$3,500.00)	Estimate Exception 4 on the current Payment Estimate.																	
					7	Nov 2, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user roberg5 overridding Payment Estimate Exception 3 on the current Payment Estimate.																	
																						7	Nov 2, 2023	SYSTEM	(\$3,500.00)	
					8	Nov 16, 2023	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user roberg5 overridding Payment Estimate Evention 4 on the output Dayment Estimate.																	
									8	Nov 16, 2023	SYSTEM	(\$3,500.00)	Estimate Exception 4 on the current Payment Estimate.													
					9	Dec 4,	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment																	
						2023			Estimate Item Adjustment (0012) due to user roberg5 overridding Payment																	



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
26	0650	SUPPLEMENTARY WEARING	Material						Estimate Exception 4 on the current Payment Estimate.
		SURFACE MATERIAL			9	Dec 4, 2023	SYSTEM	(\$3,500.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Other Item Adjustment	MDPA		Nov 16, 2023	roberg5	(\$583.33)	Low breaks on Phase 1 of deck pour McDonnell Bridge. Withholding 1/3 value of quantity poured until agreement can be reached per RE direction.
				MDPA - Tot				(\$583.33)	
			Other Item Ad	justment - To	tal			(\$583.33)	
	0650 -							(\$583.33)	
	0660	LATEX MODIFIED CONCRETE WEARING			3	Sep 5, 2023	SYSTEM	\$80,797.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user roberg5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		SURFACE			3	Sep 4, 2023	SYSTEM	(\$80,797.20)	
					4	Sep 18, 2023	SYSTEM	\$80,797.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user unlanj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Sep 18, 2023	SYSTEM	(\$80,797.20)	
					5	Oct 2, 2023	SYSTEM	\$80,797.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user roberg5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Oct 2, 2023	SYSTEM	(\$80,797.20)	
						6	Oct 16, 2023	SYSTEM	\$166,188.00
					6	Oct 16, 2023	SYSTEM	(\$166,188.00)	
						7	Nov 2, 2023	SYSTEM	\$166,188.00
					7	Nov 2, 2023	SYSTEM	(\$166,188.00)	
					8	Nov 16, 2023	SYSTEM	\$166,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user roberg5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Nov 16, 2023	SYSTEM	(\$166,188.00)	
					9	Dec 4, 2023	SYSTEM	\$166,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user roberg5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Dec 4, 2023	SYSTEM	(\$166,188.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Other Item Adjustment	MDPA		Nov 16, 2023	roberg5	(\$27,698.00)	Low breaks on Phase 1 of deck pour McDonnell Bridge. Withholding 1/3 value of quantity poured until agreement can be reached per RE direction.
				MDPA - Tot				(\$27,698.00)	
			Other Item Ad	justment - To	tal			(\$27,698.00)	
	0660 -							(\$27,698.00)	
	0690	SUBSTRUCTURE REPAIR (FORMED)	Overrun	Overrun		Dec 4, 2023	SYSTEM	(\$44,650.50)	
		()		Overrun - T	otal			(\$44,650.50)	
			Overrun - Tota	al				(\$44,650.50)	
	0690 -							(\$44,650.50)	
	0700	SUBSTRUCTURE REPAIR (UNFORMED)	Material		6	Oct 16, 2023	SYSTEM	\$18,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user roberg5 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Oct 16, 2023	SYSTEM	(\$18,060.00)	
					9	Dec 4,	SYSTEM	\$41,387.50	This adjustment offsets the original system-generated Material Payment

Dec 6, 2023



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6l3326	0700	SUBSTRUCTURE REPAIR (UNFORMED)	Material	Material			2023			Estimate Item Adjustment (0014) due to user roberg5 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					9	Dec 4, 2023	SYSTEM	(\$41,387.50)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
	0700 -	0700 - Total								
	0750	REINFORCING STEEL (EPOXY COATED)	Material		3	Sep 5, 2023	SYSTEM	\$2,875.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user roberg5 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					3	Sep 4, 2023	SYSTEM	(\$2,875.50)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
	0750 -	Total						\$0.00		
J6i3326 - Total								(\$92,013.97)		

MoDOT

Contract Adjustments for Contract - 221118-F01

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 17 of 17