

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 1, 2024

Progress Estimate Number 10	Contract ID 221216-C03 Pay Period Start January 16, 2024 Or Prime Contractor Comanche Construction, Inc. Pay Period End March 1, 2024 No. Cu.	(\$29,657.99)

Approval Date		By User
March 1, 2024	Generated and Approved (and should be considered Draft) at the Project Office Level by	yostj1
March 1, 2024	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	sandis1
March 5, 2024	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2023	November 1, 2023	October 23, 2023	100.00%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	January 4, 2023	January 4, 2023	
Letting Date	December 16, 2022	December 16, 2022	
Notice to Proceed Date	February 6, 2023	February 6, 2023	
Open to Traffic Date			
Work Began Date	September 5, 2023	September 5, 2023	

Contract Total Pa	ay For Estimate No. 10			
		This Estimate	Previous	To Date
221216-C03				
	Total Posted Items Pay	\$6,005.06	\$1,795,950.77	\$1,801,955.83
	Gross Item Adjustments	\$0.78	(\$0.78)	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$1,795,949.99	\$1,801,955.83
<b>Contract Total Pa</b>	yable This Estimate:	\$6,005.84		

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3486	0120	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	LF	\$52.270	3.6	\$188.17
	0190	6161005	CONSTRUCTION SIGNS	SQFT	\$6.360	103	\$655.08
	0210	6161025	CHANNELIZER (TRIM LINE)	EA	\$18.360	135	\$2,478.60
	0240	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	EA	\$2,683.990	1	\$2,683.99
	5002	9039904	MISC.Relocate Signs	SQFT	\$19.530	-0.04	(\$0.78)
Project J	1413486 - 1	Total					\$6,005.06
Overall -	Total						\$6,005.06

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjus	tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3486	0050	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-22	\$169.51	(\$3,729.22)
	0050	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	22	\$169.51	\$3,729.22
	0130	FURNISHING AND PLACING	Material			-447	\$285.35	(\$127,551.45)

Revision 3/23/2023 Page 1 of 18

#### Missouri Department of Transportation Contractor's Pay Estimate Summary



Pay Estimate Created Date: March 1, 2024

Progress Estimate Number 10 Contract ID 221216-C03 Pay Period Start January 16, 2024 Original Contract Amount \$1,831,613.81 Pay Period End March 1, 2024 Net Change Order Amount (\$29,657.99) Current Contract Amount \$1,801,955.82

et er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
36		CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR						
	0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user yostj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	447	\$285.35	\$127,551.45
	0170	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-1,147	\$36.73	(\$42,129.31
	0170	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user yostj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	1,147	\$36.73	\$42,129.31
	0280	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-1,109	\$0.24	(\$266.16)
	0280	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	1,109	\$0.24	\$266.16
	0290	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-1,109	\$0.24	(\$266.16
	0290	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user yostj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1,109	\$0.24	\$266.16
	0310	MULCHING	Material			-0.1	\$16,951.50	(\$1,695.15
	0310	MULCHING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user yostj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	0.1	\$16,951.50	\$1,695.15
	0320	SEEDING - COOL SEASON GRASSES	Material			-0.1	\$21,189.30	(\$2,118.93
	0320	SEEDING - COOL SEASON GRASSES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user yostj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	0.1	\$21,189.30	\$2,118.93
	0370	CONCRETE FOOTINGS, EMBEDDED	Material			-2.52	\$1,234.63	(\$3,111.27
	0370	CONCRETE FOOTINGS, EMBEDDED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	2.52	\$1,234.63	\$3,111.27
	0430	BRIDGE APPROACH SLAB (MAJOR)	Material			-58	\$429.44	(\$24,907.52
	0430	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user yostj1	58	\$429.44	\$24,907.52

Revision 3/23/2023 Page 2 of 18



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 1, 2024

Progress Estimate Number 10 Contract ID 221216-C03 Pay Period Start January 16, 2024 Original Contract Amount \$1,831,613.81 Pay Period End March 1, 2024 Net Change Order Amount (\$29,657.99) Current Contract Amount \$1,801,955.82

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3486				туре	overridding Payment Estimate Exception 2 on the current Payment Estimate.		Offic Price	
	0450	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-3,155	\$174.64	(\$550,989.20
	0450	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	3,155	\$174.64	\$550,989.20
	0480	CLEANING AND EPOXY COATING	Material			-1,721	\$14.13	(\$24,317.73
	0480	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	1,721	\$14.13	\$24,317.73
	0490	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material			-1	\$14,126.23	(\$14,126.23
	0490	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user yostj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	1	\$14,126.23	\$14,126.23
	5002	MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.53000 - 19.53000, 'is applied (if non-zero).	0.04	\$19.53	\$0.78
otal								\$0.7

Revision 3/23/2023 Page 3 of 18



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4I3486	I-670-1(159)	Bridge rehabilitation	I-670	JACKSON	on ramp from Wyomir	ng Street to I-670 eastbound	
Totals by	Job Numbers						
	Job Numbers				This Estimate	Previous	To Date
J4I3486	Job Numbers Posted I				This Estimate \$6,005.06	Previous \$1,795,950.77	To Date \$1,801,955.83
	Posted I		ts				
	Posted I	tem Pay em Adjustmen	ts Gross Ite	em Pay	\$6,005.06	\$1,795,950.77	\$1,801,955.83
	Posted I	tem Pay em Adjustmen		em Pay	\$6,005.06 \$0.78 <b>\$6,005.84</b>	\$1,795,950.77 (\$0.78) <b>\$1,795,949.99</b>	\$1,801,955.83 \$0.00 <b>\$1,801,955.83</b>
	Posted I	tem Pay em Adjustmen		em Pay	\$6,005.06 \$0.78	\$1,795,950.77 (\$0.78)	\$1,801,955.83 \$0.00 <b>\$1,801,955.83</b> \$0.00
	Posted It Gross Ite Incentive Disincen	tem Pay em Adjustmen		em Pay	\$6,005.06 \$0.78 <b>\$6,005.84</b> \$0.00	\$1,795,950.77 (\$0.78) <b>\$1,795,949.99</b> \$0.00	\$1,801,955.83 \$0.00 <b>\$1,801,955.83</b>

Revision 3/23/2023 Page 4 of 18



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

O050, Material Set 30/4050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ResteleBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0430, Material Set 503200096, Material 1056FCMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Material 1056FCMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Material 1005GECMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005GECMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200	Status  Overridden  Overridden  Overridden  Overridden  Overridden  Overridden  Overridden  Overridden  Overridden
O050, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 5031010A, Project Item Line Number 0430, Material Set 50521010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1053CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1053CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 5052000, Project Item Line Number 0430, Material Set 505200096, Material 1058PSBB - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 50520000, Project Item Line Number 0450, Material Set 505200096, Material 1055PACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005GECMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 50520000, Project Item Line Number 0450, Material Set 505200096, Material 5055CCLATX - Natural Sand for Conc Class A, Acceptance Action Generic 1005GECMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Pro	Overridden Overridden Overridden Overridden Overridden Overridden Overridden
Number 0430, Material Set 5031010A96, Material 1057 JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057 JMFRPF is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005GECMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005GECMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Material Set	Overridden Overridden Overridden Overridden Overridden Overridden
Number 0430, Material Set 5031010A96, Material 1036RSDFEC42M13 - Rein Steel ÉC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5031010A, Project Item Line Number 0430, Material Set 5031010A96, Material Set 5031010A96, Material Set 5031010A96, Material Set 505200096, Material Set 50	Overridden Overridden Overridden Overridden Overridden
Number 0430, Material Set 5031010A96, Material in 053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5031010A, Project Item Line Number 0430, Material Set 50320096, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Ma	Overridden Overridden Overridden Overridden
Number 0430, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 50520096, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number insufficient materials testing.  Working with the contractor and materials to resolve insufficient materials testing.  Working with the contractor and materials to resolve insufficient materials testing.	Overridden Overridden Overridden
0450, Material Set 505200096, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 5052000, Project Item Line Number (1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 5052000, Project Item Line Number (1005FACCNSCA is insufficient).  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 5052000, Project Item Line Number (1005FACCNSCA is insufficient).  Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 5052000, Project Item Line Number (1005FACCNSCA is insufficient).  Working with the contractor and materials to resolve insufficient material	Overridden Overridden
0450, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 5052000, Project Item Line Number 0450, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action  Working with the contractor and materials to resolve insufficient materials testing.	Overridden
0450, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action insufficient materials testing.	
	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 6086004, Project Item Line Number 0100, Material Set 608600496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	
Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 6131010, Project Item Line Number 0130, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 6131010, Project Item Line Number 0130, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 6131015, Project Item Line Number 0170, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 6205902A, Project Item Line Number 0280, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.  Working with the contractor and materials to resolve insufficient materials testing.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 6205902A, Project Item Line Number 0280, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.  Working with the contractor and materials to resolve insufficient materials testing.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3486, Item 6205902A, Project Item Line Number 0280, Material Set 6205902A96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.  Working with the contractor and materials to resolve insufficient materials testing.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 6205903A, Project Item Line Number 0290, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.  Working with the contractor and materials to resolve insufficient materials testing.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 6205903A, Project Item Line Number 0290, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 6205903A, Project Item Line Number 0290, Material Set 6205903A96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.  Working with the contractor and materials to resolve insufficient materials testing.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 7040113, Project Item Line Number 0480, Material Set 704011396, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 7110200, Project Item Line Number 0490, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 8025006, Project Item Line Number 0310, Material Set 8025006, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 8051000A, Project Item Line Number 0320, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.  Working with the contractor and materials to resolve insufficient materials testing.	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3486, Item 9031010, Project Item Line Number 0370, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Overridden

Revision 3/23/2023 Page 5 of 18



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
221216-C03	J4I3486	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$85,000.00	\$85,000.0
		0001	0020	2063500	CULVERT CLEANOUT	18.00	0.00	18.00	EA	18.00	\$2,151.07	\$38,719.2
		0001	0030	2071000	LINEAR GRADING CLASS 1	5.30	0.00	5.30	STA	5.30	\$4,063.70	\$21,537.6
		0001	0040	2153000	SHAPING SLOPES, CLASS III	2.00	-2.00	0.00	100F	0.00	\$988.84	\$0.0
		0001	0050	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	22.00	0.00	22.00	SQYD	22.00	\$169.51	\$3,729.2
		0001	0060	6079903	MISC.TEMPORARY FENCE	347.00	-347.00	0.00	LF	0.00	\$14.37	\$0.0
		0001	0070	6081010	CONCRETE CURB RAMP	16.70	17.60	34.30	SQYD	34.30	\$652.63	\$22,385.2
		0001	0080	6081012	TRUNCATED DOMES	30.00	20.00	50.00	SQFT	50.00	\$45.20	\$2,260.
		0001	0090	6083006	6 IN. CONCRETE MEDIAN STRIP	66.00	0.00	66.00	SQYD	66.00	\$175.17	\$11,561.
		0001	0100	6086004	CONCRETE SIDEWALK, 4 IN.	259.70	41.10	300.80	SQYD	300.80	\$84.76	\$25,495.
		0001	0110	6086008	CONCRETE SIDEWALK, 8 IN.	22.20	0.00	22.20	SQYD	22.20	\$107.36	\$2,383.
		0001	0120	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	280.00	-23.40	256.60	LF	256.60	\$52.27	\$13,412.
		0001	0130	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	450.00	-3.00	447.00	SQYD	447.00	\$285.35	\$127,551.
		0001	0140	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	45.00	-45.00	0.00	SQYD	0.00	\$5.65	\$0.
		0001	0150	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	45.00	-45.00	0.00	SQYD	0.00	\$16.95	\$0.
		0001	0160	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,016.00	-316.00	1,700.00	LF	1,700.00	\$8.48	\$14,416
		0001	0170	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,120.00	27.00	1,147.00	EA	1,147.00	\$36.73	\$42,129
		0001	0180	6143013	MANHOLE FRAME AND COVER, TYPE 3	1.00	0.00	1.00	EA	1.00	\$19,008.25	\$19,008
		0001	0190	6161005	CONSTRUCTION SIGNS	284.00	103.00	387.00	SQFT	387.00	\$6.36	\$2,461
		0001	0200	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	-2.00	0.00	EA	0.00	\$56.51	\$0
		0001	0210	6161025	CHANNELIZER (TRIM LINE)	160.00	0.00	160.00	EA	160.00	\$18.36	\$2,937
		0001	0220	6161030	TYPE III MOVEABLE BARRICADE	4.00	0.00	4.00	EA	4.00	\$211.89	\$847
		0001	0230	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,695.15	\$3,390
		0001	0240	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	2.00	0.00	2.00	EA	2.00	\$2,683.99	\$5,367
		0001	0250	6169902	RETAINED  MISC.ADA COMPLIANT MOVEABLE BARRICADE	4.00	0.00	4.00	EA	4.00	\$105.95	\$423
		0001	0260	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$138,000.00	\$(
		0001	0261	6181000	MOBILIZATION	0.00	1.00	1.00	LS		\$129,218.00	\$129,218
		0001	0270	6181015	RAILROAD PLAN SUBMITTAL	1.00	0.00	1.00	LS	1.00	\$79,813.16	\$79,813
		0001	0280	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,109.00	0.00	1,109.00	LF	1,109.00	\$0.24	\$260
		0001	0290	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,109.00	0.00	1,109.00	LF	1,109.00	\$0.24	\$26
		0001	0300	7319902	MISC.DROP INLET LID REPLACEMENT	1.00	0.00	1.00	EA	1.00	\$3,390.29	\$3,39
		0001	0310	8025006	MULCHING	0.10	0.00	0.10	ACRE	0.10	\$16,951.50	\$1,695
		0001	0320	8051000A	SEEDING - COOL SEASON GRASSES	0.10	0.00	0.10	ACRE	0.10	\$21,189.30	\$2,118
		0001	0330	8061007A	CURB INLET CHECK	3.00	-3.00	0.00	EA	0.00	\$169.52	\$(
		0010	0340	6061060	MGS GUARDRAIL	125.00	-125.00	0.00	LF	0.00	\$38.14	\$1
		0010	0350	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED	2.00	-2.00	0.00	EA	0.00	\$5,605.29	\$
			0000	0000044	CURB)	0.00	0.00	0.00		0.00	04 400 00	
		0010	0360	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	-2.00	0.00	EA	0.00	\$4,138.99	\$3 11:
		0040	0370	9031010	CONCRETE FOOTINGS, EMBEDDED	1.80	0.72	2.52	CUYD	2.52	\$1,234.63	\$3,11
		0040	0380	9031220	PIPE POSTS	1,190.00	449.75	1,639.75	LB	1,639.75	\$8.69	\$14,24
		0070	0390	2161000	SCARIFICATION OF BRIDGE DECK	3,155.00	0.00	3,155.00	SQYD	3,155.00	\$21.56	\$68,02
		0070	0400	2161001	TOTAL SURFACE HYDRO DEMOLITION	3,155.00	0.00	3,155.00	SQYD	3,155.00	\$52.87	\$166,804
		0070	0410	2161503	REMOVAL OF EXISTING DECK REPAIR	250.00	-92.00	158.00	SQFT	158.00	\$45.78	\$7,233
		0070	0420	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	52.00	0.00	52.00	LF	52.00	\$102.22	\$5,315

Revision 3/23/2023 Page 6 of 18



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
221216-C03	J4I3486	0070	0430	5031010A	BRIDGE APPROACH SLAB (MAJOR)	58.00	0.00	58.00	SQYD	58.00	\$429.44	\$24,907.52
		0070	0440	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	25.00	-6.20	18.80	CY	18.80	\$700.00	\$13,160.00
		0070	0450	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	3,155.00	0.00	3,155.00	SQYD	3,155.00	\$174.64	\$550,989.20
		0070	0460	7031004	DIAMOND GRINDING	3,155.00	0.00	3,155.00	SQYD	3,155.00	\$13.69	\$43,191.95
		0070	0470	7040106	FULL DEPTH REPAIR	100.00	-100.00	0.00	SQFT	0.00	\$107.08	\$0.00
		0070	0480	7040113	CLEANING AND EPOXY COATING	1,721.00	0.00	1,721.00	SQFT	1,721.00	\$14.13	\$24,317.73
		0070	0490	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$14,126.23	\$14,126.23
		0070	0500	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	260.00	0.00	260.00	LB	260.00	\$105.85	\$27,521.00
		0070	0510	7123000	STEEL BAR DAM	4.00	0.00	4.00	EA	4.00	\$17,669.08	\$70,676.32
		0070	0520	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,900.00	0.00	1,900.00	SQFT	1,900.00	\$28.25	\$53,675.00
		0070	0530	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,900.00	0.00	1,900.00	SQFT	1,900.00	\$4.24	\$8,056.00
		0070	0540	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,900.00	0.00	1,900.00	SQFT	1,900.00	\$4.24	\$8,056.00
		0070	0550	7125370A	FINISH FIELD COAT (SYSTEM G)	1,900.00	0.00	1,900.00	SQFT	1,900.00	\$4.90	\$9,310.00
		0070	0560	7172002	STRIP SEAL	52.00	0.00	52.00	LF	52.00	\$264.69	\$13,763.88
		0040	5001	9035004A	SH-FLAT SHEET	0.00	54.30	54.30	SQFT	54.30	\$25.20	\$1,368.36
		0040	5002	9039904	MISC.Relocate Signs	0.00	180.90	180.90	SQFT	180.90	\$19.53	\$3,532.98
		0001	5003	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$8,782.00	\$8,782.00
	Project J	1413486 - To	tal Value	Posted to D	ate as of Report Generated Date							\$1,801,955.81
221216-C03 Ove	erall - Tota	l Value Pos	ted to Da	ate as of Rep	ort Generated Date							\$1,801,955.81

Revision 3/23/2023 Page 7 of 18



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J4I3486

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0120	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	2/20/24	2/26/24	3.60	LF		0		0		Rounding and Correcting Previous Payment to Amount Installed
0190	6161005	CONSTRUCTION SIGNS	2/20/24	2/26/24	103.00	SQFT	I-670 EB from State Line to just east of the Wyoming on Ramp.	0		0.55		Double lane closure for low slump overlay phases 2 and 3.
0210	6161025	CHANNELIZER (TRIM LINE)	2/20/24	2/26/24	135.00	EA	I-670 EB from State Line to just east of the Wyoming on Ramp.	0		0.55		Double lane closure for low slump overlay phases 2 and 3.
0240	6161098A	CMS W/O COMMUNICATION INTERFACE, CONT F/	2/20/24	2/26/24	1.00	EA	I-670 EB from State Line to just east of the Wyoming on Ramp.	0		0.55		Double lane closure for low slump overlay phases 2 and 3.
5002	9039904	MISC. HIGHWAY SIGNING	2/20/24	2/26/24	-0.04	SQFT		0		0		Rounding and Correcting Previous Payment to Amount Installed

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 8 of 18



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
413486	0050	TYPE 5 AGGREGATE FOR BASE	Material		6	Nov 16, 2023	SYSTEM	\$1,864.61	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user baiamf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Nov 16, 2023	SYSTEM	(\$1,864.61)	
					7	Dec 4, 2023	SYSTEM	\$3,729.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user baiamf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$3,729.22)	
					8	Dec 18, 2023	SYSTEM	\$3,729.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user baiamf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Dec 18, 2023	SYSTEM	(\$3,729.22)	
					9	Jan 16, 2024	SYSTEM	\$3,729.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Jan 16, 2024	SYSTEM	(\$3,729.22)	
					10	Mar 1, 2024	SYSTEM	\$3,729.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Mar 1, 2024	SYSTEM	(\$3,729.22)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
9	0050 -	Total						\$0.00	
(	0070	CONCRETE CURB RAMP	Material		6	Nov 16, 2023	SYSTEM	\$18,208.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baiamf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Nov 16, 2023	SYSTEM	(\$18,208.38)	
					7	Dec 4, 2023	SYSTEM	\$18,208.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user baiamf1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$18,208.38)	
					8	Dec 18, 2023	SYSTEM	\$22,385.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baiamf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Dec 18, 2023	SYSTEM	(\$22,385.21)	
				- Total				\$0.00	
			Material - To					\$0.00	
			Overrun	Overrun	6	Nov 16, 2023	SYSTEM	(\$7,309.46)	
					8	Dec 18, 2023	SYSTEM	\$7,309.46	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',652.63000 - 652.63000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0070 -		Material		7	Dec 4	CVCTEA:	\$0.00	This adjustment affects the original protess and the desired Development
	0800	TRUNCATED DOMES	Material		7	Dec 4, 2023	SYSTEM	\$1,356.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$1,356.00)	
					8	Dec 18, 2023	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Dec 18,	SYSTEM	(\$2,260.00)	
						2023			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4I3486	0800	TRUNCATED DOMES	Material - To	otal				\$0.00		
	0080 -	Total						\$0.00		
	0090	6 IN. CONCRETE MEDIAN STRIP	Material		7	Dec 4, 2023	SYSTEM	\$11,561.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					7	Dec 4, 2023	SYSTEM	(\$11,561.22)		
					8	Dec 18, 2023	SYSTEM	\$11,561.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user baiamf1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					8	Dec 18, 2023	SYSTEM	(\$11,561.22)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0090 -	Total						\$0.00		
	0100	CONCRETE SIDEWALK, 4 IN.	Material		6	Nov 16, 2023	SYSTEM	\$23,732.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baiamf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					6	Nov 16, 2023	SYSTEM	(\$23,732.80)		
					7	Dec 4, 2023	SYSTEM	\$23,732.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user baiamf1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					7	Dec 4, 2023	SYSTEM	(\$23,732.80)		
						8	Dec 18, 2023	SYSTEM	\$25,495.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baiamf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	Dec 18, 2023	SYSTEM	(\$25,495.81)		
							9	Jan 16, 2024	SYSTEM	\$25,495.81
					9	Jan 16, 2024	SYSTEM	(\$25,495.81)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
			Overrun	Overrun	6	Nov 16, 2023	SYSTEM	(\$1,720.63)		
					8	Dec 18, 2023	SYSTEM	\$1,720.63	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',84.76000 - 84.76000, 'is applied (if non-zero).	
				Overrun - T	otal			\$0.00		
			Overrun - T	otal				\$0.00		
	0100 -	Total						\$0.00		
	0110	CONCRETE SIDEWALK, 8 IN.	Material		6	Nov 16, 2023	SYSTEM	\$1,191.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baiamf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					6	Nov 16, 2023	SYSTEM	(\$1,191.70)		
					7	Dec 4, 2023	SYSTEM	\$2,383.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user baiamf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					7	Dec 4, 2023	SYSTEM	(\$2,383.39)		
					8	Dec 18, 2023	SYSTEM	\$2,383.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					8	Dec 18, 2023	SYSTEM	(\$2,383.39)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J4I3486	0110 -	· Total						\$0.00										
	0120	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		6	Nov 16, 2023	SYSTEM	\$9,617.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user baiamf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
					6	Nov 16, 2023	SYSTEM	(\$9,617.68)										
					7	Dec 4, 2023	SYSTEM	\$13,224.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user baiamf1 overridding Payment Estimate Exception 16 on the current Payment Estimate.									
					7	Dec 4, 2023	SYSTEM	(\$13,224.31)										
					8	Dec 18, 2023	SYSTEM	\$13,224.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user baiamf1 overridding Payment Estimate Exception 17 on the current Payment Estimate.									
					8	Dec 18, 2023	SYSTEM	(\$13,224.31)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0120 -	Total						\$0.00										
	0130	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		6	Nov 16, 2023	SYSTEM	\$51,933.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user baiamf1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
					6	Nov 16, 2023	SYSTEM	(\$51,933.70)										
					7	Dec 4, 2023	SYSTEM	\$127,551.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user baiamf1 overridding Payment Estimate Exception 17 on the current Payment Estimate.									
					7	Dec 4, 2023	SYSTEM	(\$127,551.45)										
					8	Dec 18, 2023	SYSTEM	\$127,551.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user baiamf1 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
					8	Dec 18, 2023	SYSTEM	(\$127,551.45)										
					9	Jan 16, 2024	SYSTEM	\$127,551.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandis1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
					9	Jan 16, 2024	SYSTEM	(\$127,551.45)										
														10	Mar 1, 2024	SYSTEM	\$127,551.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user yostj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Mar 1, 2024	SYSTEM	(\$127,551.45)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0130 -	Total						\$0.00										
	0170	DOWEL BAR (DRILLING, FURNISHING AND	Material		6	Nov 16, 2023	SYSTEM	\$12,488.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user baiamf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
		INST		6						6	Nov 16, 2023	SYSTEM	(\$12,488.20)					
															7	Dec 4, 2023	SYSTEM	\$42,129.31
					7	Dec 4, 2023	SYSTEM	(\$42,129.31)										
							1					8		8	Dec 18, 2023	SYSTEM	\$42,129.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baiamf1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					8	Dec 18, 2023	SYSTEM	(\$42,129.31)										
					9	Jan 16, 2024	SYSTEM	\$42,129.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user sandis1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									



March   Down	ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
No.   10	3486	0170	(DRILLING,	Material		9		SYSTEM	(\$42,129.31)	
Total   Supplied   S						10		SYSTEM	\$42,129.31	Estimate Item Adjustment (0004) due to user yostj1 overridding Payment
Material - Total						10		SYSTEM	(\$42,129.31)	
Overtus					- Total				\$0.00	
B				Material - To	otal				\$0.00	
				Overrun	Overrun	7		SYSTEM	(\$991.71)	
170   Total						8		SYSTEM	\$991.71	previous payment estimates. Price Adjustments of ',36.73000 - 36.73000, 'is
170   170					Overrun - T	otal			\$0.00	
180				Overrun - T	otal				\$0.00	
Part		0170 -	Total						\$0.00	
2023   8   Dec 16   SYSTEM   \$19,008.25   This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate.		0180	FRAME AND	Material		7		SYSTEM	\$19,008.25	Estimate Item Adjustment (0015) due to user baiamf1 overridding Payment
2023   SySTEM   Sys						7		SYSTEM	(\$19,008.25)	
Company   Comp						8		SYSTEM	\$19,008.25	Estimate Item Adjustment (0013) due to user baiamf1 overridding Payment
Naterial - Total						8		SYSTEM	(\$19,008.25)	
					- Total				\$0.00	
CHANNELIZER (TRIM LINE)				Material - To	otal				\$0.00	
CTRIM LINE		0180 -	Total						\$0.00	
2023   3		0210		Material		2		SYSTEM	\$459.00	Estimate Item Adjustment (0001) due to user sandis1 overridding Payment
2023   Estimate Item Adjustment (0001) due to user balamf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						2		SYSTEM	(\$459.00)	
Communication   Communicatio						3		SYSTEM	\$459.00	Estimate Item Adjustment (0001) due to user baiamf1 overridding Payment
Material - Total   S0.00						3		SYSTEM	(\$459.00)	
D220   TYPE III   Material   2   Sep 18, 2023   SYSTEM   \$847.56   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sandis1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					- Total				\$0.00	
D220				Material - To	otal				\$0.00	
MOVEABLE BARRICADE		0210 -	Total						\$0.00	
2023  3 Oct 3, 2023  3 Oct 3, 2023  SYSTEM \$847.56 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  - Total  **So.00**  Material - Total  \$0.00  CMS W/O COMMUNICATION INTERFACE, CONT F/  CONT F/  2 Sep 18, 2023  SYSTEM \$2,683.99  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandis1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  2 Sep 18, SYSTEM \$2,683.99  (\$2,683.99)		0220	MOVEABLE	Material		2		SYSTEM	\$847.56	Estimate Item Adjustment (0002) due to user sandis1 overridding Payment
2023 Estimate Item Adjustment (0002) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  3 Oct 3, 2023 SYSTEM (\$847.56)  - Total \$0.00  Material - Total \$0.00  0220 - Total \$0.00  0240 CMS W/O COMMUNICATION INTERFACE, CONT F/ CONT F/ CONT F/ CONT F/ (\$2.683.99) SYSTEM (\$2.683.99)  2 Sep 18, SYSTEM (\$2.683.99) SYSTEM (\$2.683.99) SYSTEM (\$2.683.99) SYSTEM (\$2.683.99)						2		SYSTEM	(\$847.56)	
2023  - Total  Material - Total  \$0.00   0220 - Total  CMS W/O COMMUNICATION INTERFACE, CONT F/ CONT F/  Sep 18, SYSTEM \$2,683.99  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandis1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  2 Sep 18, SYSTEM (\$2,683.99)						3		SYSTEM	\$847.56	Estimate Item Adjustment (0002) due to user baiamf1 overridding Payment
Material - Total   \$0.00						3		SYSTEM	(\$847.56)	
CMS W/O COMMUNICATION INTERFACE, CONT F/   CONT F/   CONT F/   Sep 18, 2023   SySTEM   SyST					- Total				\$0.00	
O240 CMS W/O COMMUNICATION INTERFACE, CONT F/				Material - To	otal				\$0.00	
COMMUNICATION INTERFACE, CONT F/  2 Sep 18, 2023  Estimate Item Adjustment (0003) due to user sandis1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  2 Sep 18, 2023  (\$2,683.99)		0220 -	Total						\$0.00	
2 Sep 18, 2023 (\$2,683.99)		0240	COMMUNICATION INTERFACE,	Material		2		SYSTEM	\$2,683.99	Estimate Item Adjustment (0003) due to user sandis1 overridding Payment
3 Oct 3, SYSTEM \$2,683.99 This adjustment offsets the original system-generated Material Payment			CONT F/			2		SYSTEM	(\$2,683.99)	
						3	Oct 3,	SYSTEM	\$2,683.99	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J4I3486	0240	CMS W/O COMMUNICATION	Material			2023			Estimate Item Adjustment (0003) due to user balamf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		INTERFACE, CONT F/			3	Oct 3, 2023	SYSTEM	(\$2,683.99)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0240 -	Total						\$0.00	
	0280	6 IN. WHITE HIGH BUILD WATERBORNE	Material		8	Dec 18, 2023	SYSTEM	\$266.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user baiamf1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
		PAINT			8	Dec 18, 2023	SYSTEM	(\$266.16)	
					9	Jan 16, 2024	SYSTEM	\$266.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandis1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Jan 16, 2024	SYSTEM	(\$266.16)	
					10	Mar 1, 2024	SYSTEM	\$266.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Mar 1, 2024	SYSTEM	(\$266.16)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0280 -	Total						\$0.00	
	0290	6 IN. YELLOW HIGH BUILD WATERBORNE	Material		8	Dec 18, 2023	SYSTEM	\$266.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user baiamf1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
		PAINT			8	Dec 18, 2023	SYSTEM	(\$266.16)	
					9	Jan 16, 2024	SYSTEM	\$266.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					9	Jan 16, 2024	SYSTEM	(\$266.16)	
					10	Mar 1, 2024	SYSTEM	\$266.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user yostj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					10	Mar 1, 2024	SYSTEM	(\$266.16)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0290 -	Total						\$0.00	
	0310	MULCHING	Material		8	Dec 18, 2023	SYSTEM	\$1,695.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					8	Dec 18, 2023	SYSTEM	(\$1,695.15)	
					9	Jan 16, 2024	SYSTEM	\$1,695.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandis1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					9	Jan 16, 2024	SYSTEM	(\$1,695.15)	
					10	Mar 1, 2024	SYSTEM	\$1,695.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user yostj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					10	Mar 1, 2024	SYSTEM	(\$1,695.15)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0310 -	Total						\$0.00	
	0320	SEEDING - COOL SEASON	Material		8	Dec 18, 2023	SYSTEM	\$2,118.93	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user baiamf1 overridding Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3486	0320	GRASSES	Material						Estimate Exception 33 on the current Payment Estimate.
					8	Dec 18, 2023	SYSTEM	(\$2,118.93)	
					9	Jan 16, 2024	SYSTEM	\$2,118.93	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandis1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					9	Jan 16, 2024	SYSTEM	(\$2,118.93)	
					10	Mar 1, 2024	SYSTEM	\$2,118.93	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user yostj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					10	Mar 1, 2024	SYSTEM	(\$2,118.93)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0320 -	· Total						\$0.00	
	0370	CONCRETE FOOTINGS, EMBEDDED	Material		10	Mar 1, 2024	SYSTEM	\$3,111.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					10	Mar 1, 2024	SYSTEM	(\$3,111.27)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	7	Dec 4, 2023	SYSTEM	(\$888.93)	
					9	Jan 16, 2024	SYSTEM	\$888.93	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1234.63000 - 1234.63000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T					\$0.00	
	0370 -	· Total						\$0.00	
	0380	PIPE POSTS	Overrun	Overrun	7	Dec 4, 2023	SYSTEM	(\$2,952.43)	
					9	Jan 16, 2024	SYSTEM	\$2,952.43	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',8.69000 - 8.69000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	applied (ii flori 2010).
			Overrun - T		otal			\$0.00 \$0.00	applied (i flot) 2010).
	0380 -	· Total	Overrun - T		otal				applied (intel 2019).
	<b>0380</b> - 0430	BRIDGE APPROACH SLAB (MAJOR ROAD)			otal 7	Dec 4, 2023	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		BRIDGE APPROACH SLAB					SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment
		BRIDGE APPROACH SLAB			7	2023 Dec 4,		\$0.00 \$0.00 \$24,907.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment
		BRIDGE APPROACH SLAB			7	2023  Dec 4, 2023  Dec 18,	SYSTEM	\$0.00 \$0.00 \$24,907.52 (\$24,907.52)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment
		BRIDGE APPROACH SLAB			7 7 8	Dec 4, 2023  Dec 18, 2023  Dec 18,	SYSTEM SYSTEM	\$0.00 \$0.00 \$24,907.52 (\$24,907.52) \$24,907.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment
		BRIDGE APPROACH SLAB			7 7 8 8 8	Dec 4, 2023  Dec 18, 2023  Dec 18, 2023  Jan 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$24,907.52 (\$24,907.52) \$24,907.52 (\$24,907.52)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user sandis1 overridding Payment
		BRIDGE APPROACH SLAB			7 7 8 8 9	2023  Dec 4, 2023  Dec 18, 2023  Dec 18, 2023  Jan 16, 2024  Jan 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$24,907.52 (\$24,907.52) \$24,907.52 (\$24,907.52) \$24,907.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user sandis1 overridding Payment
		BRIDGE APPROACH SLAB			7 7 8 8 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 16, 2024 Mar 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$24,907.52 (\$24,907.52) \$24,907.52 (\$24,907.52) \$24,907.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user sandis1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
		BRIDGE APPROACH SLAB			7 7 8 8 9 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 16, 2024 Mar 1, 2024 Mar 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$24,907.52 (\$24,907.52) \$24,907.52 (\$24,907.52) \$24,907.52 (\$24,907.52)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user sandis1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
		BRIDGE APPROACH SLAB		otal - Total	7 7 8 8 9 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 16, 2024 Mar 1, 2024 Mar 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$24,907.52 (\$24,907.52) \$24,907.52 (\$24,907.52) \$24,907.52 (\$24,907.52) \$24,907.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user sandis1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3486	0450	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		4	Oct 17, 2023	SYSTEM	\$153,683.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user baiamf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		SURFACE			4	Oct 17, 2023	SYSTEM	(\$153,683.20)	
					5	Nov 2, 2023	SYSTEM	\$550,989.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user baiamf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Nov 2, 2023	SYSTEM	(\$550,989.20)	
					6	Nov 16, 2023	SYSTEM	\$550,989.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user baiamf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Nov 16, 2023	SYSTEM	(\$550,989.20)	
					7	Dec 4, 2023	SYSTEM	\$550,989.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user baiamf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$550,989.20)	
					8	Dec 18, 2023	SYSTEM	\$550,989.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user baiamf1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Dec 18, 2023	SYSTEM	(\$550,989.20)	
					9	Jan 16, 2024	SYSTEM	\$550,989.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user sandis1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Jan 16, 2024	SYSTEM	(\$550,989.20)	
					10	Mar 1, 2024	SYSTEM	\$550,989.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Mar 1, 2024	SYSTEM	(\$550,989.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00 \$0.00	
	0450	Total						φ <b>υ.</b> υυ	
	<b>0450</b> - 0480	Total  CLEANING AND EPOXY COATING	Material		7	Dec 4, 2023	SYSTEM	\$24,317.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
		CLEANING AND	Material		7	2023 Dec 4,	SYSTEM	\$24,317.73 (\$24,317.73)	
		CLEANING AND	Material			2023			Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment
		CLEANING AND	Material		7	2023  Dec 4, 2023  Dec 18,	SYSTEM	(\$24,317.73)	Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user baiamf1 overridding Payment
		CLEANING AND	Material		7	Dec 4, 2023  Dec 18, 2023  Dec 18,	SYSTEM SYSTEM	(\$24,317.73) \$24,317.73	Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user baiamf1 overridding Payment
		CLEANING AND	Material		7 8	Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 16,	SYSTEM SYSTEM	(\$24,317.73) \$24,317.73 (\$24,317.73)	Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user baiamf1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user sandis1 overridding Payment
		CLEANING AND	Material		7 8 8 9	2023  Dec 4, 2023  Dec 18, 2023  Dec 18, 2023  Jan 16, 2024  Jan 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$24,317.73) \$24,317.73 (\$24,317.73) \$24,317.73	Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user baiamf1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user sandis1 overridding Payment
		CLEANING AND	Material		7 8 8 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 16, 2024 Mar 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$24,317.73) \$24,317.73 (\$24,317.73) \$24,317.73	Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user baiamf1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user sandis1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment
		CLEANING AND	Material	- Total	7 8 8 9 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 16, 2024 Mar 1, 2024 Mar 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$24,317.73) \$24,317.73 (\$24,317.73) \$24,317.73 (\$24,317.73) \$24,317.73	Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user baiamf1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user sandis1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment
	0480	CLEANING AND EPOXY COATING	Material - To		7 8 8 9 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 16, 2024 Mar 1, 2024 Mar 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$24,317.73) \$24,317.73 (\$24,317.73) \$24,317.73 (\$24,317.73) \$24,317.73	Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user baiamf1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user sandis1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment
		CLEANING AND EPOXY COATING			7 8 8 9 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 16, 2024 Mar 1, 2024 Mar 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$24,317.73) \$24,317.73 (\$24,317.73) \$24,317.73 (\$24,317.73) \$24,317.73 (\$24,317.73)	Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user baiamf1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user sandis1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment
	0480	CLEANING AND EPOXY COATING	Material - To		7 8 8 9 9	2023 Dec 4, 2023 Dec 18, 2023 Dec 18, 2023 Jan 16, 2024 Mar 1, 2024 Mar 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$24,317.73) \$24,317.73 (\$24,317.73) \$24,317.73 (\$24,317.73) \$24,317.73 (\$24,317.73) \$0.00 \$0.00	Estimate Item Adjustment (0018) due to user baiamf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user baiamf1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user sandis1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3486	0490	PROTECTIVE	Material			2023			
		COATING - CONCRETE BENTS AND			8	Dec 18, 2023	SYSTEM	\$14,126.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user baiamf1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					8	Dec 18, 2023	SYSTEM	(\$14,126.23)	
					9	Jan 16, 2024	SYSTEM	\$14,126.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user sandis1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					9	Jan 16, 2024	SYSTEM	(\$14,126.23)	
					10	Mar 1, 2024	SYSTEM	\$14,126.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user yostj 1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					10	Mar 1, 2024	SYSTEM	(\$14,126.23)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0490 -	Total						\$0.00	
	0510	STEEL BAR DAM	Material		3	Oct 3, 2023	SYSTEM	\$70,676.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baiamf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Oct 3, 2023	SYSTEM	(\$70,676.32)	
					4	Oct 17, 2023	SYSTEM	\$70,676.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baiamf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Oct 17, 2023	SYSTEM	(\$70,676.32)	
					5	Nov 2, 2023	SYSTEM	\$70,676.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baiamf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Nov 2, 2023	SYSTEM	(\$70,676.32)	
					6	Nov 16, 2023	SYSTEM	\$70,676.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user baiamf1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Nov 16, 2023	SYSTEM	(\$70,676.32)	
					7	Dec 4, 2023	SYSTEM	\$70,676.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user baiamf1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$70,676.32)	
					8	Dec 18, 2023	SYSTEM	\$70,676.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user baiamf1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					8	Dec 18, 2023	SYSTEM	(\$70,676.32)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0510 -	Total						\$0.00	
	5001	SH-FLAT SHEET	Material		7	Dec 4, 2023	SYSTEM	\$1,368.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user baiamf1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					7	Dec 4, 2023	SYSTEM	(\$1,368.36)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5001 -	Total						\$0.00	
	5002	MISC. HIGHWAY SIGNING	Material		7	Dec 4, 2023	SYSTEM	\$3,533.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baiamf1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Dec 4,	SYSTEM	(\$3,533.76)	





Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J4I3486	5002	MISC. HIGHWAY SIGNING	Material			2023			
		SIGINING			8	Dec 18, 2023	SYSTEM	\$3,533.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user baiamf1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					8	Dec 18, 2023	SYSTEM	(\$3,533.76)	
					9	Jan 16, 2024	SYSTEM	\$3,533.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sandis1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Jan 16, 2024	SYSTEM	(\$3,533.76)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	7	Dec 4, 2023	SYSTEM	(\$785.89)	
					9	Jan 16, 2024	SYSTEM	\$785.11	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.53000 - 19.53000, 'is applied (if non-zero).
					10	Mar 1, 2024	SYSTEM	\$0.78	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.53000 - 19.53000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	5002 -	Total						\$0.00	
								60.00	
J4I3486 -	- Total							\$0.00	

## MoDOT

### Contract Adjustments for Contract - 221216-C03

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 18 of 18