ramses1



August 17, 2023

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 15, 2023

Progress Estim	ate Number	Contract ID Prime Contractor	230120-C01 Emery Sapp & Sons, Inc.			Original Contract Amount Net Change Order Amount Current Contract Amount	
Approval Date							By User
August 16, 2023			Generated and Approved	d (and should be co	nsidered Draft) at	the Project Office Level by	degrow1
August 16, 2023		Re	eviewed and Approved (and	d should be conside	ered Draft) at the F	Resident Engineer Level by	rileyr1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2023	November 1, 2023		6.74%

Reviewed and Approved at the Central Office Controllers Office Level by

	Contract Informational Dat	es	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	February 8, 2023	February 8, 2023	
Letting Date	January 20, 2023	January 20, 2023	
Notice to Proceed Date	March 13, 2023	March 13, 2023	
Open to Traffic Date			
Work Began Date	July 24, 2023	July 24, 2023	

Contract Total Pa	ay For Estimate No. 4				
		This Estimate	Previous	To Date	
230120-C01					
	Total Posted Items Pay	\$373,607.90	\$117,343.90	\$490,951.80	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$117,343.90	\$490,951.80	
Contract Total Pa	ayable This Estimate:	\$373,607.90			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J3P3112	0110	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$426.700	592	\$252,606.40
	0140	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$9.500	2,664	\$25,308.00
	0150	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$6.400	1,070	\$6,848.00
	0261	6181000	MOBILIZATION	LS	\$355,382.000	0.25	\$88,845.50
Project J3	P3112 - To	otal					\$373,607.90
Overall - T	otal						\$373,607.90

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3P3112	0110	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-728	\$426.70	(\$310,637.60)
	0110	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user degrow1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	728	\$426.70	\$310,637.60

Revision 3/23/2023 Page 1 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 15, 2023

Progress Estimate Number
4

Contract ID 230120-C01 Pay Period Start August 2, 2023 Original Contract Amount S7,282,686.35
Pay Period End August 15, 2023 Original Contract Amount Current Contract Amount S7,282,686.35

199112 15									
DEPTH PAZMEMT REPAIR OTSO DOWEL BAR (PORLLING, INSTALLATION) FOR FULL DEPTH PAZMEMT REPAIR OTSO DOWEL BAR (PORLLING, INSTALLATION) FOR FULL DEPTH PAZMEMT REPAIR OTTO THE BAR (DRILLING, INSTALLATION) FOR FULL DEPTH PAZMEMT REPAIR OTTO THE BAR (DRILLING, INSTALLATION) FOR FULL DEPTH PAZMEMT REPAIR OTTO THE BAR (DRILLING, INSTALLATION) FOR FULL DEPTH PAZMEMT REPAIR OTTO THE BAR (DRILLING, INSTALLATION) FOR FULL DEPTH PAZMEMT REPAIR OTTO THE BAR (DRILLING, INSTALLATION) FOR FULL DEPTH PAZMEMT REPAIR OTTO THE BAR (DRILLING, INSTALLATION) FOR FULL DEPTH PAZMEMT REPAIR OTTO THE BAR (DRILLING, INSTALLATION) FOR FULL DEPTH PAZMEMT REPAIR OTTO THE BAR (DRILLING, INSTALLATION) FOR FULL DEPTH PAZMEMT REPAIR OTTO OTTO THE BAR (DRILLING, INSTALLATION) FOR FULL DEPTH PAZMEMT REPAIR OTTO	Project Number		Item Description		Adjustment	Comments		Adjustment	
FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	J3P3112	0150	FURNISHING AND INSTALLATION) FOR FULL	Material			-1,328	\$6.40	(\$8,499.20)
FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)		0150	FURNISHING AND INSTALLATION) FOR FULL	Material		generated Material Payment Estimate Item Adjustment (0002) due to user degrow1 overridding Payment Estimate Exception 4 on	1,328	\$6.40	\$8,499.20
FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) 200 CONSTRUCTION SIGNS Material This adjustment offsets the original system-generated Material Payment Estimate Estimate Exception 7 on the current Payment Estimate Score (\$5.54.00 on the current Payment Estimate) 210 ADVANCED WARNING RAIL SYSTEM Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user degrowd overridding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0005) due to user degrowd overridding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0005) due to user degrowd overridding Payment Estimate Exception 8 on the current Payment Estimate Item Adjustment (0005) due to user degrowd overridding Payment Estimate Item Adjustment (0005) due to user degrowd overridding Payment Estimate Exception 9 on the current Payment Estimate Item Adjustment (0005) due to user degrowd overridding Payment Estimate Item Adjustment (0005) due to user degrowd overridding Payment Estimate Item Adjustment (0006) due to user degrowd overridding Payment Estimate Item Adjustment (0006) due to user degrowd overridding Payment Estimate Item Adjustment (0006) due to user degrowd overridding Payment Estimate Item Adjustment (0006) due to user degrowd overridding Payment Estimate Item Adjustment (0006) due to user degrowd overridding Payment Estimate Item Adjustment (0006) due to user degrowd overridding Payment Estimate Item Adjustment (0007) due to user degrowd overridding Payment Estimate Item Adjustment (0006) due to user degrowd overridding Payment Estimate Item Adjustment (0007) due to user degrowd overridding Payment Estimate Item Adjustment (0007) due to user degrowd overridding Payment Estimate Item Adjustment (0006) due to user degrowd overridding Payment Estimate Item Adjustment (0006) due to user degrowd overridding Payment Estimate Item Adjustment (0006) due to user degrowd overridding Payment Estimate Item Adjustment		0170	FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-12	\$5.75	(\$69.00)
CONSTRUCTION SIGNS Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user degrow1 overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 17 on the current Payment Estimate Exception 18 on the current Payment Estimate Item Adjustment (0005) due to user degrow1 overridding Payment Estimate Exception 8 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 19 on the current Payment Estimate Exception 10 on the current Payment Estimate Exception 11 on the current Payment Estimate.		0170	FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		generated Material Payment Estimate Item Adjustment (0003) due to user degrow1 overridding Payment Estimate Exception 5 on	12	\$5.75	\$69.00
generated Material Payment Estimate Item Adjustment (0004) due to user degrow1 overridding Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0005) due to user degrow1 overridding Payment Estimate Item Adjustment (0005) due to user degrow1 overridding Payment Estimate Item Adjustment (0005) due to user degrow1 overridding Payment Estimate Item Adjustment (0005) due to user degrow1 overridding Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate Exception 9 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 10 on the current Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 10 on the current Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 10 on the current Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Item Adjustment (0008) due to user degrow1 overridding		0200	CONSTRUCTION SIGNS	Material			-904	\$7.25	(\$6,554.00)
SYSTEM 0210 ADVANCED WARNING RAIL SYSTEM 0210 ADVANCED WARNING RAIL SYSTEM 0210 ADVANCED WARNING RAIL SYSTEM 0220 CHANNELIZER (TRIM LINE) Material Degree and the current Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate Exception 9 on the current Payment Estimate. 0240 CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED 0240 CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED 0240 CHANGEABLE MESSAGE Material SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR RETAINED 0240 CHANGEABLE MESSAGE Material SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR RETAINED 0250 TEMPORARY LONG-TERM RUMBLE STRIPS 0250 TEMPORARY LON		0200	CONSTRUCTION SIGNS	Material		generated Material Payment Estimate Item Adjustment (0004) due to user degrow1 overridding Payment Estimate Exception 7 on	904	\$7.25	\$6,554.00
generated Material Payment Estimate Item Adjustment (0005) due to user degrow1 overridding Payment Estimate Exception 8 on the current Payment Estimate. CHANNELIZER (TRIM LINE) Material CHANNELIZER (TRIM LINE) Description of the current Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate Exception 9 on the current Payment Estimate Exception 9 on the current Payment Estimate. CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED COMMUNICATION INTERFACE, CONTRACTOR RETAINED COMMUNICATION INTERFACE, CONTRACTOR RETAINED This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system- generated Material Payment Estimate Exception 10 on the current Payment Estimate. This adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 10 on the current Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Estimate Item Adjustment (0008) due to user degrow1 overriddi		0210		Material			-2	\$72.00	(\$144.00)
CHANNELIZER (TRIM LINE) Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate. CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR FURNISHED, CONTRACTOR FURNISHED, CONTRACTOR FURNISHED, CONTRACTOR FURNISHED, CONTRACTOR FURNISHED, CONTRACTOR RETAINED COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR FURNISHED, CONTRACTOR RETAINED COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED Temporary Long-tem RUMBLE STRIPS Material This adjustment offsets the original system- generated Material Payment Estimate Adjustment offsets the original system- generated Material Payment Estimate This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0210		Material		generated Material Payment Estimate Item Adjustment (0005) due to user degrow1 overridding Payment Estimate Exception 8 on	2	\$72.00	\$144.00
generated Material Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate. CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED Description This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system- generated Material This adjustment offsets the original system- generated Material Payment Estimate. This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0220	CHANNELIZER (TRIM LINE)	Material			-150	\$19.75	(\$2,962.50)
SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED 0240 CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR FURNISHED, CONTRACTOR FURNISHED, CONTRACTOR RETAINED 0250 TEMPORARY LONG-TERM RUMBLE STRIPS 0250 TEMPORARY L		0220	CHANNELIZER (TRIM LINE)	Material		generated Material Payment Estimate Item Adjustment (0006) due to user degrow1 overridding Payment Estimate Exception 9 on	150	\$19.75	\$2,962.50
SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED 0250 TEMPORARY LONG-TERM RUMBLE STRIPS 0250		0240	SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	Material			-2	\$3,900.00	(\$7,800.00)
RUMBLE STRIPS 0250 TEMPORARY LONG-TERM RUMBLE STRIPS 0260 RUMBLE STRIPS 0270 TEMPORARY LONG-TERM RUMBLE STRIPS 0270 TEMPORARY LONG-TERM RUMBLE STRIPS 0270 TEMPORARY LONG-TERM RUMBLE STRIPS 0270 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0240	SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	Material		generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 10	2	\$3,900.00	\$7,800.00
RUMBLE STRIPS generated Material Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0250		Material			-4	\$1,425.00	(\$5,700.00)
Fotal \$0.00		0250		Material		generated Material Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Exception 11	4	\$1,425.00	\$5,700.00
	Total								\$0.00

Revision 3/23/2023 Page 2 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Informa	tion
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J3P3112	FAF 65-3(114)	Resurface	65	SALINE	from east of Rte. 24 to Rte	. 240 in Marshall	
Totals by J	Job Numbe	ers					
J3P3112		d Item Pay Item Adjustmo		Item Pay	This Estimate \$373,607.90 \$0.00 \$373,607.90	Previous \$117,343.90 \$0.00 \$117,343.90	To Date \$490,951.80 \$0.00 \$490,951.80
	Liquid	tive centive dated Damages Contract Adju:			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 3/23/2023 Page 3 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J3P3112, Item 6131010, Project Item Line Number 0110, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Passing tests achieved. Results need entered into AWP.	degrow1	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3112, Item 6131010, Project Item Line Number 0110, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Passing tests achieved. Results need entered into AWP.	degrow1	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3112, Item 6131010, Project Item Line Number 0110, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Passing tests achieved. Results need entered into AWP.	degrow1	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3112, Item 6131015, Project Item Line Number 0150, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Passing tests achieved. Results need entered into AWP.	degrow1	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3112, Item 6131018, Project Item Line Number 0170, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Passing tests achieved. Results need entered into AWP.	degrow1	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3112, Item 6131018, Project Item Line Number 0170, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Passing tests achieved. Results need entered into AWP.	degrow1	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3112, Item 6161005, Project Item Line Number 0200, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications saved to SharePoint. Tests need to be entered into AWP.	degrow1	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3112, Item 6161008, Project Item Line Number 0210, Material Set 616100896, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications saved to SharePoint. Tests need to be entered into AWP.	degrow1	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3112, Item 6161025, Project Item Line Number 0220, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications saved to SharePoint. Tests need to be entered into AWP.	degrow1	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3112, Item 6161098A, Project Item Line Number 0240, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications saved to SharePoint. Tests need to be entered into AWP.	degrow1	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3112, Item 6162002, Project Item Line Number 0250, Material Set 616200296, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications saved to SharePoint. Tests need to be entered into AWP.	degrow1	Overridden

Revision 3/23/2023 Page 4 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230120-C01	J3P3112	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$7,750.00	\$0.00
		0001	0020	2153000	SHAPING SLOPES, CLASS III	16.00	0.00	16.00	100F	0.00	\$1,116.00	\$0.00
		0001	0030	3049910	MISC.Permanent Aggregate Edge Treatment	1,279.00	0.00	1,279.00	TONS	0.00	\$51.50	\$0.00
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	280.00	0.00	280.00	TONS	0.00	\$142.50	\$0.00
		0001	0050	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	18,125.00	0.00	18,125.00	TONS	0.00	\$105.75	\$0.00
		0001	0060	4030015	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP048F MIX)	11,585.00	0.00	11,585.00	TONS	0.00	\$119.00	\$0.00
		0001	0070	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	21,803.00	0.00	21,803.00	TONS	0.00	\$105.10	\$0.00
		0001	0080	4031057	ASPHALT PERFORMANCE TESTING REPORTING	1.00	0.00	1.00	LS	0.00	\$7,800.00	\$0.00
		0001	0090	4071005	TACK COAT	27,060.00	0.00	27,060.00	GAL	0.00	\$2.50	\$0.00
		0001	0100	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,625.00	\$0.00
		0001	0110	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	1,392.00	0.00	1,392.00	SQYD	728.00	\$426.70	\$310,637.60
		0001	0120	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	139.00	0.00	139.00	SQYD	0.00	\$1.00	\$0.00
		0001	0130	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	139.00	0.00	139.00	SQYD	0.00	\$1.00	\$0.00
		0001	0140	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	6,264.00	0.00	6,264.00	LF	3,276.00	\$9.50	\$31,122.00
		0001	0150	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	4,176.00	0.00	4,176.00	EA	1,328.00	\$6.40	\$8,499.20
		0001	0160	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	36.00	0.00	36.00	EA	0.00	\$16.50	\$0.00
		0001	0170	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	30.00	0.00	30.00	EA	12.00	\$5.75	\$69.00
		0001	0180	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	83.00	0.00	83.00	TONS	0.00	\$291.00	\$0.00
		0001	0190	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	500.00	0.00	500.00	SQYD	0.00	\$192.25	\$0.00
		0001	0200	6161005	CONSTRUCTION SIGNS	1,497.00	0.00	1,497.00	SQFT	904.00	\$7.25	\$6,554.00
		0001	0210	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$72.00	\$144.00
		0001	0220	6161025	CHANNELIZER (TRIM LINE)	150.00	0.00	150.00	EA	150.00	\$19.75	\$2,962.50
		0001	0230	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$2,475.00	\$0.00
		0001	0240	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	2.00	\$3,900.00	\$7,800.00
		0001	0250	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	4.00	\$1,425.00	\$5,700.00
		0001	0260	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$384,000.00	\$0.00
		0001	0261	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.25	\$355,382.00	\$88,845.50
		0001	0270	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	300.00	0.00	300.00	LF	0.00	\$22.00	\$0.00
		0001	0280	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	0.00	\$358.00	\$0.00
		0001	0290	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	5.00	0.00	5.00	EA	0.00	\$247.85	\$0.00
		0001	0300	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	102,980.00	0.00	102,980.00	LF	0.00	\$0.20	\$0.00
		0001	0310	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	167,006.00	0.00	167,006.00	LF	0.00	\$0.23	\$0.00
		0001	0320	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	8,448.00	0.00	8,448.00	SQYD	0.00	\$2.25	\$0.00
		0001	0330	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,959.00	0.00	2,959.00	SQYD	0.00	\$15.35	\$0.00
		0001	0340	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,616.50	0.00	1,616.50	STA	0.00	\$9.90	\$0.00
		0001	0350	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	820.80	0.00	820.80	STA	0.00	\$9.90	\$0.00
		0010	0360	6061060	MGS GUARDRAIL	1,558.00	0.00	1,558.00	LF	0.00	\$27.40	\$0.00
		0010	0370	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	8.00	0.00	8.00	EA	0.00	\$3,965.00	\$0.00
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	0.00	\$3,690.00	\$0.00
		0001	5001	6189901	MISC.Adjust Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$28,618.00	\$28,618.00
	Project J	3P3112 - To	otal Value	Posted to D	Date as of Report Generated Date							\$490,951.80
230120-C01 Ove	erall - Total	Value Pos	ted to Da	te as of Rep	ort Generated Date							\$490,951.80

Page 5 of 10 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J3P3112

Project												
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0110	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	8/15/23	8/15/23	0.00		Locations continued: 109.065= 109.195= 109.224= 109.286= 109.347= 109.408= 109.540= 109.564= All locations listed have 8 square yards each.		0		0	
				8/15/23			All locations issed nave 8 square yards each. 105.513= 105.588= 105.680= 105.788= 105.788= 105.788= 105.781= 105.874= 105.892= 105.874= 105.892= 105.892= 110.593= 111.593= 111.394= 111.498= 111.541= 111.541= 111.541= 111.541= 111.541= 111.558= 111.541= 1		0		0	
0140	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	8/15/23	8/15/23	0.00	LF		0	0	0	0	Locations continued: 109.065= 109.105= 109.124= 109.224= 109.286= 109.347= 109.408= 109.540= 109.540= All locations listed have 36 LF each.
				8/15/23	2,664.00	LF		0	0	0	0	10.5 13= 10.5 13= 10.5 88= 10.5 834= 10.5 834= 10.5 788= 10.5 788= 10.5 783= 11.5 783=

Revision 3/23/2023 Page 6 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

		elow this line is supplemental to the Estimate										
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log	Offset/ Distance	Log	Offset/ Distance	Comments
0140	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	8/15/23					Mile		Mile		113.829= 113.959= 107.324= 107.356= 107.356= 107.450= 107.450= 107.570= 107.570= 107.570= 107.570= 107.571= 107.741= 107.741= 107.741= 107.741= 107.741= 107.741= 107.742= 108.390= 108.493= 108.290= 108.493= 108
0150	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	8/15/23	8/15/23	0.00	EA		0	0	0	0	105.519-17 105.588-17 105.588-17 105.588-17 105.788-17 105.788-17 105.788-17 105.788-17 105.783-13 105.874-15 105.822-16 105.822-16 105.822-16 105.822-16 105.822-16 105.822-16 105.822-16 105.822-16 105.822-16 105.822-16 105.822-16 105.822-16 105.822-16 105.822-16 105.822-16 110.559-14 110.741-16 110.855-15 110.825-15 110.825-15 110.825-15 110.825-15 110.825-15 111.92-12 111.909-15 110.909-15 110.909-15 111.909-16 111.909-16 1
0261	6181000	MOBILIZATION	8/15/23		1,070.00	EA	5% complete	0	0	0	0	Locations continued: 103.505(NB)=11 103.123=15 103.123=15 103.123=16 103.123=14 103.123=14 103.123=14 103.123=14 103.123=15 103.123=

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 7 of 10



Line Item Adjustments by Estimate

Contract ID: 230120-C01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3112	0110	FURN & PLACE CONC MATL FOR FULL DEPTH	Material	•	3	Aug 2, 2023	SYSTEM	\$58,031.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user degrow1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 2, 2023	SYSTEM	(\$58,031.20)	
					4	Aug 15, 2023	SYSTEM	\$310,637.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user degrow1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 15, 2023	SYSTEM	(\$310,637.60)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -	Total						\$0.00	
	0150	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		3	Aug 2, 2023	SYSTEM	\$1,651.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user degrow1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Aug 2, 2023	SYSTEM	(\$1,651.20)	
					4	Aug 15, 2023	SYSTEM	\$8,499.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user degrow1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Aug 15, 2023	SYSTEM	(\$8,499.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0150 -	Total						\$0.00	
	0170	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		3	Aug 2, 2023	SYSTEM	\$69.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user degrow1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		·			3	Aug 2, 2023	SYSTEM	(\$69.00)	
					4	Aug 15, 2023	SYSTEM	\$69.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Aug 15, 2023	SYSTEM	(\$69.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0170 -	0170 - Total						\$0.00	
	0200	CONSTRUCTION SIGNS	Material		3	Aug 2, 2023	SYSTEM	\$6,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user degrow1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Aug 2, 2023	SYSTEM	(\$6,554.00)	
					4	Aug 15, 2023	SYSTEM	\$6,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user degrow1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Aug 15, 2023	SYSTEM	(\$6,554.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0200 - Total							\$0.00	
	0210	ADVANCED WARNING RAIL SYSTEM	Material		3	Aug 2, 2023	SYSTEM	\$144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user degrow1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Aug 2, 2023	SYSTEM	(\$144.00)	
					4	Aug 15, 2023	SYSTEM	\$144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user degrow1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				4	4	Aug 15, 2023	SYSTEM	(\$144.00)	
				- Total				\$0.00	



Line Item Adjustments by Estimate

Contract ID: 230120-C01

Estimate Exception 7 on the current Payment Estimate.	J3P3112	0210 -	WARNING RAIL	Material - To				Ву		
CHANNELIZER (TRIM LINE)				Material - Total					\$0.00	
CTRIM LINE 2023 Estimate Item Adjustment (0000) due to user degrow1 overridding Payment Estimate Exception 7 on the current Payment Estimate. 2023 SYSTEM 22,962.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0000) due to user degrow1 overridding Payment Estimate Exception 9 on the current Payment Estimate. 2024 SySTEM S0.00			· Total						\$0.00	
2023 4		0220		Material		3		SYSTEM	\$2,962.50	Estimate Item Adjustment (0006) due to user degrow1 overridding Payment
2023 Estimate Item Adjustment (0009) due to user degrow1 overridding Paymer Estimate Exception 9 on the current Payment Estimate.						3		SYSTEM	(\$2,962.50)	
Total \$0.00						4		SYSTEM	\$2,962.50	Estimate Item Adjustment (0006) due to user degrow1 overridding Payment
						4		SYSTEM	(\$2,962.50)	
COMMUNICATION COMMUNICATION NITERFACE, CONT F/ 2023 SYSTEM \$7,800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate Estimate Exception 3 on the current Payment Estimate Estimate Exception 8 on the current Payment Estimate. 3					- Total				\$0.00	
0240 CMS W/O COMMUNICATION INTERFACE, CONT F/ 2023 SYSTEM \$7,800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 2 Jul 17, 2023 SYSTEM \$7,800.00 System-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 2 Jul 17, 2023 SYSTEM \$7,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 8 on the current Payment Estimate. 3 Aug 2, 2023 SYSTEM \$7,800.00 SySTEM \$7,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 10 on the current Payment Estimate. 3 Aug 15, 2023 SYSTEM \$0.00 So.00				Material - To	otal				\$0.00	
COMMUNICATION INTERFACE. CONT F/ 2 Jul 17, 2023 (\$7,800.00) 3 Aug 2, 2023 (\$7,800.00) 3 Aug 2, 2023 (\$7,800.00) 4 Aug 15, 2023 (\$7,800.00) - Total Material - Total 0250 TEMPORARY LONG-TERM RUMBLE STRIPS Aug 2, 2023 (\$7,800.00) - Temporary Long-Term Rumble Strings Aug 2, 2023 (\$7,800.00) - Temporary Long-Term Rumble Strings Aug 2, 2023 (\$7,800.00) - Temporary Long-Term Rumble Strings Aug 2, 2023 (\$7,800.00) - Total - Total - Total - Temporary Long-Term Rumble Strings - Aug 2, 2023 (\$7,800.00) - Temporary Long-Term Rumble Strings - Aug 2, 2023 (\$7,800.00) - Total - Temporary Long-Term Rumble Strings - Aug 2, 2023 (\$7,800.00) - Temporary Long-Term Rumble Strings - Aug 2, 2023 (\$7,800.00) - Temporary Long-Term Rumble Strings - Aug 2, 2023 (\$7,800.00) - Temporary Long-Term Rumble Strings - Aug 2, 2023 (\$7,800.00) - This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate. - This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate. - This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.		0220 -	Total						\$0.00	
2 Jul 17, 2023 SYSTEM (\$7,800.00)		0240	COMMUNICATION INTERFACE,	Material		2		SYSTEM	\$7,800.00	Estimate Item Adjustment (0001) due to user degrow1 overridding Payment
2023 Estimate Item Adjustment (0007) due to user degrow1 overridding Paymer Estimate Exception 8 on the current Payment Estimate. 3			CONT F/			2		SYSTEM	(\$7,800.00)	
Aug 15, 2023 SYSTEM \$7,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user degrow1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						3		SYSTEM	\$7,800.00	Estimate Item Adjustment (0007) due to user degrow1 overridding Payment
2023 Estimate Item Adjustment (0007) due to user degrow1 overridding Paymer Estimate Exception 10 on the current Payment Estimate. Aug 15, 2023 \$\frac{1}{2023}\$ \$\frac{1}{20						3		SYSTEM	(\$7,800.00)	
- Total \$0.00 Material - Total \$0.00 Description						4		SYSTEM	\$7,800.00	Estimate Item Adjustment (0007) due to user degrow1 overridding Payment
Material - Total \$0.00						4		SYSTEM	(\$7,800.00)	
Solution					- Total				\$0.00	
D250 TEMPORARY LONG-TERM RUMBLE STRIPS 3 Aug 2, 2023 SYSTEM \$5,700.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user degrow1 overridding Payment Estimate Exception 9 on the current Payment Estimate. 3 Aug 2, 2023 SYSTEM (\$5,700.00) 4 Aug 15, SYSTEM \$5,700.00 This adjustment offsets the original system-generated Material Payment				Material - Total					\$0.00	
LONG-TERM RUMBLE STRIPS 2023 Estimate Item Adjustment (0008) due to user degrow1 overridding Paymer Estimate Exception 9 on the current Payment Estimate. 3 Aug 2, 2023 4 Aug 15, SYSTEM \$5,700.00 This adjustment offsets the original system-generated Material Payment		0240 -	Total						\$0.00	
2023 4 Aug 15, SYSTEM \$5,700.00 This adjustment offsets the original system-generated Material Payment		0250	LONG-TERM	Material		3		SYSTEM	\$5,700.00	Estimate Item Adjustment (0008) due to user degrow1 overridding Payment
						3		SYSTEM	(\$5,700.00)	
Estimate Exception 11 on the current Payment Estimate.						4		SYSTEM	\$5,700.00	Estimate Item Adjustment (0008) due to user degrow1 overridding Payment
4 Aug 15, SYSTEM (\$5,700.00)						4		SYSTEM	(\$5,700.00)	
- Total \$0.00					- Total				\$0.00	
Material - Total \$0.00				Material - To	otal				\$0.00	
0250 - Total \$0.00		0250 -	0 - Total							
	J3P3112	Total							\$0.00	
J3P3112 - Total \$0.00	Overall -	Total							\$0.00	

MoDOT

Contract Adjustments for Contract - 230120-C01

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 10 of 10