

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 4, 2023

Progress Estimate Number	Contract ID	230421-F06	Pay Period Start November 16, 202	3 Original Contract Amount \$28,247,068.30
11	Prime Contracto	or N.B. West Contracting Compar	y Pay Period End December 1, 2023	
				Current Contract Amount \$28,247,068.30

Approval Date		By User
December 4, 2023	Generated and Approved (and should be considered Draft) at the Project Office Level by	jamesc4
December 4, 2023	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	REDHAC
December 5, 2023	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2024	November 1, 2024		24.36%

	Milestones		
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	May 3, 2023	May 3, 2023	
Letting Date	April 21, 2023	April 21, 2023	
Notice to Proceed Date	June 5, 2023	June 5, 2023	
Open to Traffic Date			
Work Began Date	June 27, 2023	June 27, 2023	

Contract Total Pay For Estimate No. 11									
	This Estimate	Previous	To Date						
230421-F06									
Total Posted Items Pay	\$1,006,414.95	\$5,873,563.31	\$6,879,978.26						
Gross Item Adjustments	(\$120,721.05)	\$663,255.53	\$542,534.48						
Incentive	\$0.00	\$0.00	\$0.00						
Disincentive	\$0.00	\$0.00	\$0.00						
Liquidated Damage	\$0.00	\$0.00	\$0.00						
Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
		\$6,536,818.84	\$7,422,512.74						
Contract Total Payable This Estimate:	\$885,693.90								

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6P3288	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$295,000.000	0.1	\$29,500.00
	0020	2159910	MISC.SHAPING SLOPES, CLASS III (MODIFIED)	100F	\$750.000	19	\$14,250.00
	0070	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	LF	\$62.000	13	\$806.00
	0155	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	EA	\$10,000.000	2	\$20,000.00
	0170	6169902	MISC.NTICP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	EA	\$2,500.000	3	\$7,500.00
	0200	6181000	MOBILIZATION	LS	\$1,550,000.000	0.25	\$387,500.00
	0280	6061060	MGS GUARDRAIL	LF	\$25.000	1,050	\$26,250.00
	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$3,600.000	3	\$10,800.00
	0310	6061080	MGS END ANCHOR	EA	\$1,400.000	1	\$1,400.00
	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$3,000.000	2	\$6,000.00
	1200	7049903	MISC.Barrier Curb Repair	LF	\$349.000	11.5	\$4,013.50
	1960	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	SQYD	\$118.000	515.7	\$60,852.60
	2430	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	SQFT	\$70.000	1,400	\$98,000.00
	2440	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	SQFT	\$4.000	1,400	\$5,600.00
	2630	5031010A	BRIDGE APPROACH SLAB (MAJOR)	SQYD	\$492.000	89	\$43,788.00
Project J6I	P3288 - To	otal					\$716,260.10
J6S3283B	3890	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	TONS	\$85.000	732.31	\$62,246.35
	3950	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$193.500	213.3	\$41,273.55

Revision 3/23/2023 Page 1 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 4, 2023

Progress Estimate Number	Contract ID	230421-F06	Pay Period Star	tNovember 16, 202	3 Original Contract Amount \$28,247,068.30
11	Prime Contracto	or N.B. West Contracting Compan	y Pay Period End	December 1, 2023	Net Change Order Amount \$0.00
					Current Contract Amount \$28,247,068.30

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J6S3283B	3980	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$9.000	601	\$5,409.00	
	3990	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$13.400	148	\$1,983.20	
	4030	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	EA	\$2,500.000	1	\$2,500.00	
	4040	6181000	MOBILIZATION	LS	\$650,000.000	0.25	\$162,500.00	
	4130	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	LF	\$0.250	5,563	\$1,390.75	
	4140	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$1.400	9,180	\$12,852.00	
Project J69	S3283B - ⁻	Total					\$290,154.85	
Overall - Total								

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

ine Item A	djustm	ents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6P3288	0070	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-62.5	\$62.00	(\$3,875.00)
	0155	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material			-2	\$10,000.00	(\$20,000.00)
	0155	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.	2	\$10,000.00	\$20,000.00
	0280	MGS GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$15,655.50)
	0290	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$6,150.00)
	0310	MGS END ANCHOR	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$820.00)
	0320	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$3,750.00)
	2440	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material			-1,400	\$4.00	(\$5,600.00)
	2440	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment Estimate Exception 15 on the current Payment Estimate.	1,400	\$4.00	\$5,600.00
	2630	BRIDGE APPROACH SLAB (MAJOR)	Material			-89	\$492.00	(\$43,788.00)
	2650	CLASS B-2 CONCRETE	Material			-36	\$1,650.00	(\$59,400.00)
	2650	CLASS B-2 CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.	36	\$1,650.00	\$59,400.00
J6S3283B	3950	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Overrun			-123.3	\$193.50	(\$23,858.55)

Revision 3/23/2023 Page 2 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 4, 2023

Progress Estimate Number
11 Contract ID 230421-F06 Pay Period Start November 16, 2023 Original Contract Amount \$28,247,068.30
Prime Contractor N.B. West Contracting Company Pay Period End December 1, 2023 Net Change Order Amount \$0.00
Current Contract Amount \$28,247,068.30

							·	-, ,
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3283B		REPAIR						
	3950	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Overrun			-90	\$193.50	(\$17,415.00
	3980	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	Overrun			-343	\$9.00	(\$3,087.00
	3980	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	Overrun			-258	\$9.00	(\$2,322.00
	4130	4 IN TEMPORARY PAVEMENT MARKING PAINT	Material			-5,563	\$0.25	(\$1,390.75
	4130	4 IN TEMPORARY PAVEMENT MARKING PAINT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user jamesc4 overridding Payment Estimate Exception 11 on the current Payment Estimate.	5,563	\$0.25	\$1,390.75
Total								(\$120,721.0

Revision 3/23/2023 Page 3 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Information		
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work	
J6P3288	FAF-21-2(87)	17 Bridge rehabilitations	21	JEFFERSON	at various location	ons in Jefferson County		
J6S3283B	FAF-21-2(91)	Coldmill and resurface	21, Old 21	JEFFERSON	on Route 21 from	n Meramec River to Schen	ık Road and on Old Route 21 from Roι	ite 21 to Konert Roa
otals by Jo	ob Numbers							
J6P3288				Th	nis Estimate	Previous	To Date	
	Posted Item Gross Item	Adjustments	ss Item F	(\$	716,260.10 74,038.50) 642,221.60	\$2,434,915.51 \$316,364.30 \$2,751,279.81	\$3,151,175.61 \$242,325.80 \$3,393,501.41	
	Incentive			\$0	0.00	\$0.00	\$0.00	
	Disincentiv	е			0.00	\$0.00	\$0.00	
	Liquidated				0.00	\$0.00	\$0.00	
	Other Cont	ract Adjustmen	ts	\$0	0.00	\$0.00	\$0.00	
J6S3283B				Th	nis Estimate	Previous	To Date	1
	Posted Item	n Pav			290,154.85	\$3,438,647.80	\$3,728,802.65	
		Adjustments			46,682.55)	\$346,891.23	\$300,208.68	
	Gross Item Pay		Pay \$2	243,472.30	\$3,785,539.03	\$4,029,011.33		
	Incentive			\$0	0.00	\$0.00	\$0.00	
	Disincentiv	е		\$0	0.00	\$0.00	\$0.00	
	Liquidated				0.00	\$0.00	\$0.00	
	Other Cont	ract Adjustment	ts	\$0	0.00	\$0.00	\$0.00	

Revision 3/23/2023 Page 4 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Estimate Ecosption Type: Institutioned Miderials Protect, JESS2858, Item 6030003, Project tiem Line Actionate Ecosption Type: Institutioned Miderials Protect, JESS2858, Item 6030003, Project tiem Line Actionate Conference (Institution of Institution) Editionate Ecosption Type: Institutioned Miderials Protect, JESS288, Item 60310004, Project tiem Line Actionate Conference (Institution) Editionate Ecosption Type: Institutioned Miderials Protect, JESS288, Item 60310004, Project tiem Line Actionate Conference (Institution) Editionate Conference (Institution) Editionat	Exceptions (Discrepancies) This Estimate Period			
Number 380b. Material Set 430000586, Material Discosphere Project Jupice Post From Cere C. Acceptance Action Genetic Application in Studies of Material Discosphere Project Jupice Project	Exceptions / Discrepencies	Explanation		Status
Namer 2500, Material Scription (1940). Material 1007-JAMEREP - Proformed Foot Experience Joint Mart (2014). Project Item Line (2014). Project Item L	Number 3890, Material Set 403000396, Material 0403SP095C - Superpave 9.5 mm, Des C, Acceptance	Working with SL materials to resolve	jamesc4	Overridden
Number 2500, Material Set 5031010A66, Material Singers Polyethylere Sheeting for Bond Brinster, Acceptance Action Generic 103PSGES in similarities. Estimate Exception Type: Insufficient Materials: Project JPSGESS, Bine 5031010A, Project then Line Materials Exception Type: Insufficient Materials: Project JPSGESS, Bine 5031010A, Project then Line Committee Committe	Number 2630, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl	Working with contractor to resolve	jamesc4	Acknowledged
Number 2300, Material Set 500 (100 ACR), Material 160 CPCAQCOA - Concrete, Pawment contractor inx or COAA, Acceptance Action Generic 100 CPCAQCOA in sustificant. Estimate Exception Type: Insufficient Materials: Project J8P288, Item 930 101 (A), Project Item Line Number 2300, Material 105 CPCAMDEST 10 - Item strandship of the State of Contractor to resolve Number 2300, Material 105 CPCAMDEST 10 - Item strandship of the State of Contractor Interest Number 2300, Material 105 CPCAMDEST 10 - Item strandship of CPCA	Number 2630, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker,	Working with contractor to resolve	jamesc4	Acknowledged
Number 250, Material Set 630310 (DASR, Material 1055CMMLDST1D - Clear Pawement-Ridings bespitating Cure (Q. Acceptance Action Generic 1055CMMLDST1D an insufficient Materials: Project JB92388, Item 5031010A, Project Item Line Number 250, Material Set 5031010A, Project Item Line Number 250, Material Set 5031010A, Material Set 5031010A, Project Item Line Number 250, Material Set 5031010A, Material Set 5031010A, Project Item Line Number 250, Material Set 5031010A, Material Set 5031010A, Project Item Line Number 250, Material Set 5031010A, Material Set 5031010A, Project Item Line Number 250, Material Set 5031010A, Material Set 5031010A, Project Item Line Number 250, Material Set 5031010A, Project Item Line Number 250, Material Set 5031010A, Project Item Line Number 2500, Material Set 5031010A, Project Item Line Number 250, Material Set 5031010A, Project Item Line Number 250, Material Set 50310A, Project Item Line Number 250, Material Set 50310A, Material Set 50310A, Project Item Line Number 250, Material Set 50310A, Material Set 50310A, Project Item Line Number 250, Material Set 50310A, Material Set 50310A, Project Item Line Number 250, Material Set 50310A, Material Set 50310A, Project Item Line Number 250, Material Set 50310A, Material Set 50310A, Project Item Line Number 210, Material Set 50310A, Material Set 50310A, Project Item Line Number 210, Material Set 50300A, Material Set 50310A, Project Item Line Number 210, Material Set 50300A, Material Set 50310A, Project Item Line Number 210, Material Set 50300A, Material Set 50310A, Project Item Line Number 210, Material Set 50300A, Material Set 50310A, Project Item Line Number 210, Material Set 50300A, Material Set 50310A, Project Item Line Number 210, Material Set 50300A, Material Set 50310A, Material Set 50310A, Material Set 50310A, Material Set 50310A, Material	Number 2630, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix	Working with contractor to resolve	jamesc4	Acknowledged
Number 230, Material Set 5031010A96, Material 1053CSSUL - Concrete Seater (CS) - Stane @. Estimate Exception Type: Insufficient Materials: Project J6P2288, liem 503101A, Project Item Line Number 230, Material Set 5031010A6, Material 10510MCRPE. 04 - Vindomin, Acceptance Action Generic 10130MCRPE. 04 - Insufficient. Estimate Exception Type: Insufficient Materials: Project J6P2288, liem 503200, Project Item Line Number 3770, Material Set 505200098, Material 1050SECMLS - Masonry Grade E LSDO, Acceptance Action Generic 10130MCRPE. 04 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6P2288, liem 5022001, Project Item Line Number 3770, Material Set 505200098, Material 1050SECMLS - Masonry Grade E LSDO, Acceptance Action Generic 1055CMMLDST10 - Clear Pavement-Bridge Dissipating Cure @. Acceptance Action Generic 1055CMMLDST10 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6P2288, liem 502000AP, Project Item Line Number 0175, Material Set 50200017 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6P2288, liem 502000AP, Project Item Line Number 0155, Material Set 5020007 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6P2288, liem 50200AP, Project Item Line Number 0155, Material Set 5020007 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6P2288, liem 5020076, Project Item Line Number 4130, Material Set 5020076, Material 045PMTRHSHWBYL - Materials Project J6P2288, liem 5020076, Project Item Line Number 4130, Material Set 5020076, Material 045PMTRHSHWBYL - Materials Project J6P2288, liem 5020076, Project Item Line Number 4130, Material Set 5020076, Material 045PMTRHSHWBYL - Materials Project J6P2288, liem 5020076, Project Item Line Number 4130, Material Set 5020076, Material 045PMTRHSWBYL - Materials Project J6P2288, liem 5020076, Project Item Line Number 4130, Material Set 7020076, Material 045PMTRHSWBYL - Materials Project J6P2288, liem 5020076, Project Item Line Number 4200, Materia	Number 2630, Material Set 5031010A96, Material 1055CMMLDST1D - Clear Pavement-Bridge	Working with contractor to resolve	jamesc4	Acknowledged
Number 2830, Material Set 5031010A96, Material 1013DMCRPE, 04 is insufficient. Estimate Exception Type: Insufficient Materials: Project J893288, Item 502000, Project Item Line Number 3770, Material Set 50320006, Material 1005CECMLS - Masonry Grade E LSTOD, Acceptance Action Generic 1005CECMLS is insufficient. Estimate Exception Type: Insufficient Materials: Project J893288, Item 6022011, Project Item Line Number 0070, Material Set 603201196, Material 1005CECMMLDST10 is insufficient. Estimate Exception Type: Insufficient Materials: Project J893288, Item 6022017, Project Item Line Number 0170, Material Set 603201106, Material 1055CMMLDST10 is insufficient. Estimate Exception Type: Insufficient Materials: Project J893288, Item 6132000A, Project Item Line Number 0175, Material Set 603201106, Material 1055CMMLDST10 is insufficient. Estimate Exception Type: Insufficient Materials: Project J893288, Item 6202076, Project Item Line Number 4150, Material Set 612020076, Material 1045PMTRHSWNYL - Material Pant Acrylic Walf Hisld Yallow, Acceptance Action Generic 1045PMTRHSWNYL - Material Pant Acrylic Walf Hisld Yallow, Acceptance Action Generic 1045PMTRHSWNYL - Material Pant Acrylic Walf Hisld Yallow, Acceptance Action Generic 1045PMTRHSWNYL - Material Pant Acrylic Walf Hisld Yallow, Acceptance Action Generic 1045PMTRHSWNYL - Material Pant Acrylic Walf Hisld Yallow, Acceptance Action Generic 1045PMTRHSWNYL - Material Pant Acrylic Walf Hisld Yallow, Acceptance Action Generic 1045PMTRHSWNYL - Material Pant Acrylic Walf Hisld Yallow, Acceptance Action Generic 1045PMTRHSWNYL - Material Pant Acrylic Walf Hisld Yallow, Acceptance Action Generic 1045PMTRHSWNYL - Material Vallow, Acceptance Action Generic 1045PMTRHSWNYL - Material	Number 2630, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,	Working with contractor to resolve	jamesc4	Acknowledged
Number 3770, Material Set 505200096, Material 1095GECMLS - Masonry Grade E LS/DC, Acceptance Action Generio 1005GECML is insufficient. Estimate Exception Type: Insufficient Materials: Project J693288, Item 6020011, Project Item Line Number 0707, Material Set 6020017 196, Material 1056CMMLDST10 is insufficient. Estimate Exception Type: Insufficient Materials: Project J693288, Item 6123000A89, Material Set 6123000A89, Material Set 6123000A89, Material Set 6123000A89, Material Set 612300A89, Material Set 61230A89, Material Set 6	Number 2630, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE	Working with contractor to resolve	jamesc4	Acknowledged
Number 0707, Material Set 609201196, Material 1055CMMLDST10 - Clear Pavement-Bridge Dissipating Cure (Q. Acceptance Action Generic 1056CMMLDST10 is insufficient. Estimate Exception Type: Insufficient Materials: Project_JE97288, Item 612300QA, Project Item Line Number 0156, Material Set 612000A69, Material of 1056TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project_JES72888, Item 620076, Project Item Line Number 4130, Material Set 6200076, Material 1048PMTRHBWBYL is insufficient. Estimate Exception Type: Insufficient Materials: Project_JES32888, Item 6208076, Project Item Line Number 4130, Material Set 6208076, Material 1048PMTRHBWBYL is insufficient. Estimate Exception Type: Insufficient Materials: Project_JES32838, Item 6208076, Project Item Line Number 4130, Material Set 6208076, Material 1048PMTRHBWBYL is insufficient. Estimate Exception Type: Insufficient Materials: Project_JES32838, Item 6208076, Project Item Line Number 4130, Material Set 6208076, Material 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project_JES32838, Item 6208076, Project Item Line Number 4130, Material Set 6208076, Material 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project_JES32838, Item 6208076, Project Item Line Number 4130, Material Set 703421466, Material 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project_JES9288, Item 7034214, Project Item Line Number 2505, Material Set 703421466, Material 04511CDB2.A - Concrete, Class Bez-Walir, Acceptance Action Generic 0501CCB2 A is insufficient. Estimate Exception Type: Item Materials: Project_JES9288, Item 7125210, Project Item Line Number 2505, Contract Line Item Number 3080, Item 6131010, Minor Item. Estimate Exception Type: Item Overrun: Contract_20421-F06, Contract Project_JES32838, Project Item Line Number 3080, Contract Line Item Number 3080, Item 6131014, Minor Item. Estimate Exception Type: Item Overrun: Contract_20421-F06, Contract Proje	Number 3770, Material Set 505200096, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance	Working with contractor to resolve	jamesc4	Overridden
Number 0155, Material 5et 6123000A96, Material 1045PMTR-HBWBYL - Marking Paint Acrylic Wart Hilbld Various Acceptance Action Genetic 0161FMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J653283B, Item 6208076, Project Item Line Number 4130, Material 5et 6208076, Material 1048PMTRHBWBYL - Marking Paint Acrylic Wart Hilbld Various Action Genetic 1048PMTRHBWBYL is insufficient. Estimate Exception Type: Insufficient Materials: Project J653283B, Item 6208076, Project Item Line Number 4130, Material 5et 6208076, Material 1044PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J653283B, Item 6208076, Project Item Line Number 4130, Material 5et 6208076, Material 1044PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J653283B, Item 6208076, Project Item Line Number 4130, Material 5et 6208076, Material 5et 7048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J653283B, Item 7034214, Project Item Line Number 4550, Material 5et 703421496, Material 5et 703	Number 0070, Material Set 609201196, Material 1055CMMLDST1D - Clear Pavement-Bridge	Working with contractor to resolve	jamesc4	Acknowledged
Number 4130, Material Set 6208076, Material 1048PMTRHBWPYL - Marking Paint Acrylic Water HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3283B, Item 6208076, Project Item Line Number 4130, Material Set 6208076, Material 1048PMTRHBWPT - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMTRHB is insufficient Paint Anxiety P Perf Insufficient Materials: Project J6S3283B, Item 6208076, Project Item Line Number 4130, Material Set 6208076, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld While, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 7034214, Project Item Line Number 2600, Material Set 703421498, Material 50510CB2 A - Concrete, Class B-2 w/Air, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 7125210, Project Item Line Number 2050, Orbit Aderial Set 7125210, Project J6P3288, Item 7125210, Project J6P3288, Project Item Line Number 2050, Contract Cline Item Number 3950, Contract Line Item Number 3950, Item 6131010, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3950, Contract Line Item Number 3950, Item 6131010, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3950, Contract Line Item Number 3950, Item 6131010, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3950, Contract Line Item Number 3950, Item 6131010, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2300, Contract Line Item Number 2500, Item 6131010, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2500, Co	Number 0155, Material Set 6123000A96, Material 0616TMTC - Temporary Traffic Control Devices,	Sample record forthcoming	jamesc4	Overridden
Number 4130, Material Set 6208076, Material 1048PMRRTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRRTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3283B, Item 6208076, Project Item Line Number 2450, Material Set 6208076, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH - Insufficient Insufficient Insufficient Materials: Project J6P328B, Item 7034214, Project Item Line Number 2650, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6P328B, Item 7125210, Project Item Line Number 2440, Material Set 712521096, Material 10501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic O45PTIZ is insufficient. Estimate Exception Type: Insufficient Materials: Project J6P328B, Item 7125210, Project Item Line Number 2440, Material Set 712521096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is Insufficient. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3950, Contract Line Item Number 3950, Item 6131010, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3950, Contract Line Item Number 3950, Item 6131014, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2500, Contract Line Item Number 1230, Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2500, Contract Line Item Number 2500, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2600, Contract Line Item Number 2600, Contract Eriget J6P3288, Project Item Line Number 2600, Contract Line Item Number 3050004, Minor Item. Estimate Exception Type: Item O	Number 4130, Material Set 6208076, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld	Sample record forthcoming	jamesc4	Overridden
Number 4130, Material Set 6208076, Material 1048PMTRHBWBWH is mustificient. Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 7034214, Project Item Line Number 2650, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient Materials: Project J6P3288, Item 7125210, Project Item Line Number 2650, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient Materials: Project J6P3288, Item 7125210, Project Item Line Number 2440, Material Set 712521096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3950, Contract Line Item Number 3950, Item 6131010, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3950, Contract Line Item Number 3950, Item 61310114, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3950, Contract Line Item Number 3950, Item 6131014, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 1230, Contract Line Item Number 1230, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2250, Contract Line Item Number 2500, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2660, Contract Line Item Number 2660, Contract Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2660, Contract Line Item Number 3760, Contract Li	Number 4130, Material Set 6208076, Material 1048PMRBTP - Reflective Glass Beads Type P Perf	Sample record forthcoming	jamesc4	Overridden
Number 2650, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6P3288, Item 7125210, Project Item Line Number 2440, Material Set 712521096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3950, Contract Line Item Number 3950, Item 6131010, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3980, Contract Line Item Number 3980, Item 6131014, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3980, Contract Line Item Number 3980, Item 6131014, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 1230, Contract Line Item Number 1230, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2250, Contract Line Item Number 2250, Contract Line Item Number 2660, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2660, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2660, Contract Line Item Number 2660, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 360, Contract Line Item Number 360, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Pr	Number 4130, Material Set 6208076, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld	No Remark was entered by Engineer	jamesc4	Overridden
Number 2440, Material Set 712521096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3950, Contract Line Item Number 3950, Item 6131010, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3980, Contract Line Item Number 3980, Item 6131014, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 1230, Contract Line Item Number 1230, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2250, Contract Line Item Number 2250, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2250, Contract Line Item Number 2550, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2660, Contract Line Item Number 2660, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Contract Line Item Number 3020, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Contract Line Item Number 3020, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Change order forthcoming Jamesc4	Number 2650, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance	Working with contractor to resolve	jamesc4	Overridden
Line Number 3950, Contract Line Item Number 3950, Item 6131010, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3980, Contract Line Item Number 3980, Item 6131014, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 1230, Contract Line Item Number 1230, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2250, Contract Line Item Number 2250, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2250, Contract Line Item Number 2250, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2660, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Contract Line Item Number 3020, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Contract Line Item Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Change order forthcoming Jamesc4 Acknowledged Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Change order forthcoming Jamesc4 Acknowledged	Number 2440, Material Set 712521096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint,	Sample record forthcoming	jamesc4	Overridden
Line Number 3980, Contract Line Item Number 3980, Item 6131014, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 1230, Contract Line Item Number 1230, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2250, Contract Line Item Number 2250, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2660, Contract Line Item Number 2660, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Contract Line Item Number 3020, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Change order forthcoming Jamesc4 Acknowledged Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Change order forthcoming Jamesc4 Acknowledged		Change order forthcoming	jamesc4	Acknowledged
Line Number 1230, Contract Line Item Number 1230, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2250, Contract Line Item Number 2250, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2660, Contract Line Item Number 2660, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Contract Line Item Number 3020, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Contract Line Item Number 3020, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item.		Change order forthcoming	jamesc4	Acknowledged
Line Number 2250, Contract Line Item Number 2250, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 2660, Contract Line Item Number 2660, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Contract Line Item Number 3020, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Contract Line Item Number 3020, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Change order forthcoming jamesc4 Acknowledged Change order forthcoming		Change order forthcoming	jamesc4	Acknowledged
Line Number 2660, Contract Line Item Number 2660, Item 7040101, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3020, Contract Line Item Number 3020, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Change order forthcoming jamesc4 Acknowledged Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Change order forthcoming jamesc4 Acknowledged		Change order forthcoming	jamesc4	Acknowledged
Line Number 3020, Contract Line Item Number 3020, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6P3288, Project Item Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Change order forthcoming jamesc4 Acknowledged		Change order forthcoming	jamesc4	Acknowledged
Line Number 3760, Contract Line Item Number 3760, Item 5050004, Minor Item. Estimate Exception Type: Item Overrun: Contract 230421-F06, Contract Project J6S3283B, Project Item Change order forthcoming jamesc4 Acknowledged		Change order forthcoming	jamesc4	Acknowledged
		Change order forthcoming	jamesc4	Acknowledged
		Change order forthcoming	jamesc4	Acknowledged

Revision 3/23/2023 Page 5 of 25



Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
30421-F06	J6P3288	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.30	\$295,000.00	\$88,500.0
		0001	0015	2079909	MISC.MODIFIED LINEAR GRADING	259.80	0.00	259.80	STA	0.00	\$1,189.50	\$0.0
		0001	0020	2159910	MISC.SHAPING SLOPES, CLASS III (MODIFIED)	194.00	0.00	194.00	100F	34.00	\$750.00	\$25,500.0
		0001	0025	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	29,076.00	0.00	29,076.00	SQYD	0.00	\$19.45	\$0.0
		0001	0030	4010150	TYPE A2 SHOULDER	29,075.90	0.00	29,075.90	SQYD	0.00	\$25.00	\$0.0
		0001	0040	4136000	PCCP JOINT/CRACK SEALING	13,050.00	0.00	13,050.00	LF	0.00	\$3.00	\$0.0
		0001	0050	5041000	CONCRETE APPROACH PAVEMENT	2,742.60	0.00	2,742.60	SQYD	0.00	\$181.00	\$0.0
		0001	0060	6091041	CONCRETE GUTTER TYPE A	280.00	0.00	280.00	LF	0.00	\$145.00	\$0.0
		0001	0070	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	250.00	0.00	250.00	LF	62.50	\$62.00	\$3,875.0
		0001	0080	6113020	FURNISHING TYPE 2 ROCK BLANKET	53.00	0.00	53.00	CUYD	0.00	\$45.00	\$0.0
		0001	0090	6113040	PLACING TYPE 2 ROCK BLANKET	53.00	0.00	53.00	CUYD	0.00	\$301.00	\$0.0
		0001	0100	6116010A	SLOPE PROTECTION	37.00	0.00	37.00	SQYD	0.00	\$829.00	\$0.0
		0001	0110	6122010	IMPACT ATTENUATOR 50 MPH (SAND BARREL ARRAY)	8.00	0.00	8.00	EA	0.00	\$1,500.00	\$0.0
		0001	0120	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	13.00	0.00	13.00	EA	6.00	\$1,500.00	\$9,000.0
		0001	0130	6122020	REPLACEMENT SAND BARREL	21.00	0.00	21.00	EA	0.00	\$250.00	\$0.0
		0001	0140	6122030	IMPACT ATTENUATOR (RELOCATION)	21.00	0.00	21.00	EA	4.00	\$1,000.00	\$4,000.0
		0001	0150	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	4.00	0.00	4.00	EA	0.00	\$5,000.00	\$0.0
		0001	0155	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$10,000.00	\$20,000.0
		0001	0160	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$120,000.00	\$60,000.0
		0001	0170	6169902	MISC.NTICP COMPLIANT CHANGEABLE MESSAGE SIGN	4.00	0.00	4.00	EA	3.00	\$2,500.00	\$7,500.0
	0001 0180 6173600D			(CONTRACTOR FURNISHED AND RETAINED) TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	12,175.00	0.00	12,175.00	LF	5,287.50	\$32.00	\$169,200.0	
					RETAINED							
		0001	0190	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	12,175.00	0.00	12,175.00	LF	4,062.50	\$10.00	\$40,625.0
		0001	0200	6181000	MOBILIZATION	1.00	0.00	1.00	LS		\$1,550,000.00	\$775,000.0
		0001	0210	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	57,350.00	0.00	57,350.00	LF	3,094.00	\$2.00	\$6,188.0
		0001	0220	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	57,350.00	0.00	57,350.00	LF	2,751.00	\$2.00	\$5,502.0
		0001	0230	6207001	PAVEMENT MARKING REMOVAL	129,037.00	0.00	129,037.00	LF	3,049.00	\$0.60	\$1,829.4
		0001	0240	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	129,037.00	0.00	129,037.00	LF	21,265.00	\$1.00	\$21,265.0
		0001	0250	6214600A	FLOWABLE BACKFILL	45.00	0.00	45.00	CUYD	15.00	\$824.00	\$12,360.0
		0001	0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	605.00	0.00	605.00	SQYD	0.00	\$35.00	\$0.0
		0001	0270	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.0
		0010	0280	6061060	MGS GUARDRAIL	14,550.00	0.00	14,550.00	LF	2,225.00	\$25.00	\$55,625.0
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	47.00	0.00	47.00	EA	5.00	\$3,600.00	\$18,000.0
		0010	0300	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	0.00	\$650.00	\$0.0
		0010	0310	6061080	MGS END ANCHOR	13.00	0.00	13.00	EA	1.00	\$1,400.00	\$1,400.0
		0010	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	34.00	0.00	34.00	EA	4.00	\$3,000.00	\$12,000.0
		0040	0330	9031270A	2 IN. PSST POST - 12 GA.	418.00	0.00	418.00	LF	0.00	\$20.00	\$0.0
		0040	0340	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	114.00	0.00	114.00	EA	0.00	\$150.00	\$0.0
		0040	0350	9035069A	SHF-FLAT SHEET FLUORESCENT	140.00	0.00	140.00	SQFT	0.00	\$28.00	\$0.0
		0050	0360	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$16,000.00	\$0.0
		0050	0370	2161501	REMOVAL OF ASPHALT WEARING SURFACE	12,569.00	0.00	12,569.00	SQFT	12,569.00	\$1.75	\$21,995.7
		0050	0380	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$52,000.00	\$0.0
		0050	0390	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	123.00	0.00	123.00	LF	0.00	\$631.00	\$0.0
		0050	0400	2169903	CONCRETE MISC.Remove and Replace Barrier Curb	16.00	0.00	16.00	LF	0.00	\$1,001.00	\$0.0
		0050	0410	5031010A	BRIDGE APPROACH SLAB (MAJOR)	178.00	0.00	178.00	SQYD	0.00	\$492.00	\$0.0
		0050	0420	7031004	DIAMOND GRINDING	1,382.00	0.00	1,382.00	SQYD	0.00	\$9.75	\$0.0
												\$0.0
		0050	0430	7034214	CLASS B-2 CONCRETE	33.00	0.00	33.00	CUYD	0.00	\$2,700.00	\$0.0

Revision 3/23/2023 Page 6 of 25



Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230421-F06	J6P3288	0050	0440	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	0.00	20.00	SQFT	0.00	\$169.00	\$0.0
		0050	0450	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	31.00	0.00	31.00	SQFT	0.00	\$173.25	\$0.0
		0050	0460	7040113	CLEANING AND EPOXY COATING	200.00	0.00	200.00	SQFT	0.00	\$30.00	\$0.0
		0050	0470	7061070	MECHANICAL BAR SPLICE	64.00	0.00	64.00	EA	0.00	\$12.80	\$0.0
		0050	0480	7101000	REINFORCING STEEL (EPOXY COATED)	3,670.00	0.00	3,670.00	LB	0.00	\$2.35	\$0.0
		0050	0490	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$17,500.00	\$0.0
		0050	0500	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,100.00	0.00	1,100.00	SQFT	0.00	\$70.00	\$0.0
		0050	0510	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,100.00	0.00	1,100.00	SQFT	0.00	\$4.00	\$0.0
		0050	0520	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$3.00	\$0.0
		0050	0530	7125370A	FINISH FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$2.00	\$0.0
		0050	0540	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	61.00	0.00	61.00	LF	0.00	\$488.00	\$0.0
		0050	0550	7172054	OPEN CELL FOAM JOINT SEAL	61.00	0.00	61.00	LF	0.00	\$52.00	\$0.0
		0051	0560	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,382.00	0.00	1,382.00	SQYD	667.30	\$60.00	\$40,038.0
		0051	0570	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	0.00	\$31.00	\$0.0
		0051	0580	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	8.00	0.00	8.00	CY	1.72	\$700.00	\$1,204.0
		0051	0590	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,382.00	0.00	1,382.00	SQYD	784.00	\$118.00	\$92,512.0
		0051	0600	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$139.00	\$0.
		0053	0650	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$16,000.00	\$0.0
		0053	0660	2161501	REMOVAL OF ASPHALT WEARING SURFACE	10,868.00	0.00	10,868.00	SQFT	0.00	\$2.00	\$0.
		0053	0670	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$47,000.00	\$0.
		0053	0680	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	112.00	0.00	112.00	LF	0.00	\$631.00	\$0.
		0053	0690	2169903	CONCRETE MISC.Remove and Replace Barrier Curb	15.00	0.00	15.00	LF	0.00	\$1,001.00	\$0.
		0053	0700	5031010A	BRIDGE APPROACH SLAB (MAJOR)	178.00	0.00	178.00	SQYD	0.00	\$492.00	\$0.
		0053	0710	7031004	DIAMOND GRINDING	1,194.00	0.00	1,194.00	SQYD	0.00	\$9.75	\$0.
		0053	0720	7034214	CLASS B-2 CONCRETE	28.30	0.00	28.30	CUYD	0.00	\$2,700.00	\$0.
		0053	0730	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	6.00	0.00	6.00	SQFT	0.00	\$173.25	\$0
		0053	0740	7040110	EPOXY PRESSURE INJECTING	64.00	0.00	64.00	LF	0.00	\$52.50	\$0.
		0053	0750	7040113	CLEANING AND EPOXY COATING	825.00	0.00	825.00	SQFT	0.00	\$30.00	\$0
		0053	0760	7061070	MECHANICAL BAR SPLICE	64.00	0.00	64.00	EA	0.00	\$12.80	\$0
		0053	0770	7101000	REINFORCING STEEL (EPOXY COATED)	3,370.00	0.00	3,370.00	LB	0.00	\$2.35	\$0
		0053	0780	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$17,500.00	\$0.
		0055			(EPOXY)							
		0053	0790	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,100.00	0.00	1,100.00	SQFT	0.00	\$70.00	\$0.
		0053	0800	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,100.00	0.00	1,100.00	SQFT	0.00	\$4.00	\$0.
		0053	0810	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$3.00	\$0.
		0053	0820	7125370A	FINISH FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$2.00	\$0
		0053	0830	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	56.00	0.00	56.00	LF	0.00	\$488.00	\$0
		0053	0840	7172054	OPEN CELL FOAM JOINT SEAL	56.00	0.00	56.00	LF	0.00	\$52.00	\$0
		0054	0850	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,194.00	0.00	1,194.00	SQYD	0.00	\$60.00	\$0
		0054	0860	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CY	0.00	\$700.00	\$0
		0054	0870	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,194.00	0.00	1,194.00	SQYD	0.00	\$118.00	\$0
		0054	0880	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$139.00	\$0
		0056	0930	2161000	SCARIFICATION OF BRIDGE DECK	1,160.00	0.00	1,160.00	SQYD	0.00	\$13.00	\$0.
		0056	0940	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	72.00	0.00	72.00	LF	0.00	\$631.00	\$0.
		0056	0950	2169903	MISC.Remove and Replace Barrier Curb	12.00	0.00	12.00	LF	0.00	\$1,001.00	\$0.
		0056	0960	7031004	DIAMOND GRINDING	1,160.00	0.00	1,160.00	SQYD	0.00	\$9.75	\$0.

Revision 3/23/2023 Page 7 of 25



Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
80421-F06	J6P3288	0056	0970	7034214	CLASS B-2 CONCRETE	6.80	0.00	6.80	CUYD	0.00	\$4,025.00	\$0.
		0056	0980	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	59.00	0.00	59.00	SQFT	0.00	\$173.25	\$0.
		0056	0990	7040110	EPOXY PRESSURE INJECTING	104.00	0.00	104.00	LF	0.00	\$52.50	\$0.
		0056	1000	7040113	CLEANING AND EPOXY COATING	100.00	0.00	100.00	SQFT	0.00	\$30.00	\$0.
		0056	1010	7101000	REINFORCING STEEL (EPOXY COATED)	710.00	0.00	710.00	LB	0.00	\$2.35	\$0.
		0056	1020	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0.
		0056	1030	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,100.00	0.00	1,100.00	SQFT	0.00	\$70.00	\$0
		0056	1040	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,100.00	0.00	1,100.00	SQFT	0.00	\$4.00	\$0
		0056	1050	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$3.00	\$0
		0056	1060	7125370A	FINISH FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$2.00	\$0
		0056	1070	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	67.00	0.00	67.00	LF	0.00	\$488.00	\$0
		0057	1080	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,160.00	0.00	1,160.00	SQYD	0.00	\$60.00	\$0
		0057	1090	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	0.00	4.00	CY	0.00	\$700.00	\$0
		0057	1100	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,160.00	0.00	1,160.00	SQYD	0.00	\$118.00	\$0
		0057	1110	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$139.00	\$0
		0059	1160	2161501	REMOVAL OF ASPHALT WEARING SURFACE	14,109.00	0.00	14,109.00	SQFT	14,109.00	\$1.75	\$24,690
		0059	1170	7031004	DIAMOND GRINDING	1,568.00	0.00	1,568.00	SQYD	0.00	\$9.75	\$1
		0059	1180	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	12.00	0.00	12.00	SQFT	0.00	\$173.25	\$
		0059	1190	7040110	EPOXY PRESSURE INJECTING	30.00	0.00	30.00	LF	0.00	\$52.50	\$
		0059	1200	7049903	MISC.Barrier Curb Repair	51.00	0.00	51.00	LF	38.90	\$349.00	\$13,57
		0059	1210	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$10,500.00	\$
		0060	1220	2161001	(EPOXY) TOTAL SURFACE HYDRO DEMOLITION	1,568.00	0.00	1,568.00	SQYD	1,568.00	\$60.00	\$94,08
		0060	1230	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	43.93	\$700.00	\$30,75
		0060	1240	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,568.00	0.00	1,568.00	SQYD	1,568.00	\$118.00	\$185,02
		0062	1280	2161501	REMOVAL OF ASPHALT WEARING SURFACE	13,604.00	0.00	13,604.00	SQFT	0.00	\$1.75	9
		0062	1290	7031004	DIAMOND GRINDING	1,512.00	0.00	1,512.00	SQYD	0.00	\$9.75	9
		0062	1300	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	12.00	0.00	12.00	SQFT	0.00	\$173.25	
		0062	1310	7040110	EPOXY PRESSURE INJECTING	35.00	0.00	35.00	LF	0.00	\$52.50	
		0062	1320	7049903	MISC.Barrier Curb Repair	10.00	0.00	10.00	LF	0.00	\$349.00	
		0062	1330	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$10,500.00	9
		0063	1340	2161001	(EPOXY) TOTAL SURFACE HYDRO DEMOLITION	1,512.00	0.00	1,512.00	SQYD	0.00	\$60.00	\$
		0063	1350	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$700.00	\$
		0063	1360	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,512.00	0.00	1,512.00	SQYD	0.00	\$118.00	\$
		0065	1400	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$16,000.00	
		0065	1410	2161501	REMOVAL OF ASPHALT WEARING SURFACE	9,986.00	0.00	9,986.00	SQFT	0.00	\$2.00	
		0065	1420	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$64,000.00	
		0065	1430	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	123.00	0.00	123.00	LF	0.00	\$631.00	
		0065	1440	2169903	CONCRETE MISC.Remove and Replace Barrier Curb	19.00	0.00	19.00	LF	0.00	\$1,001.00	
		0065	1450	5031010A	BRIDGE APPROACH SLAB (MAJOR)	177.00	0.00	177.00	SQYD	0.00	\$492.00	
		0065	1460	7031004	DIAMOND GRINDING	1,088.00	0.00	1,088.00	SQYD	0.00	\$9.75	
		0065	1470	7031004	CLASS B-2 CONCRETE	50.10	0.00	50.10	CUYD	0.00	\$1,752.00	
		0065	1470	7034214	SUBSTRUCTURE REPAIR (FORMED)	65.00	0.00	65.00	SQFT	0.00	\$1,732.00	
		0065	1490	7040101	SUBSTRUCTURE REPAIR (UNFORMED)	90.00	0.00	90.00	SQFT	0.00	\$173.25	
			1500	7040102	SLAB EDGE REPAIR (BRIDGES)	5.00	0.00	5.00	LF	0.00	\$173.25	3
		0065	1510	7040107	EPOXY PRESSURE INJECTING	24.00	0.00	24.00	LF	0.00	\$410.00	3
		0065	1010	1040110	2. SALT I NEGOGIAL INDECTING	24.00	0.00	24.00	ᄕ	0.00	φυΖ.υυ	3

Revision 3/23/2023 Page 8 of 25



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					port Generated date and can differ from the posted amo							
Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
421-F06	J6P3288	0065	1530	7061070	MECHANICAL BAR SPLICE	37.00	0.00	37.00	EA	0.00	\$12.80	\$0.
		0065	1540	7101000	REINFORCING STEEL (EPOXY COATED)	4,580.00	0.00	4,580.00	LB	0.00	\$2.35	\$0.
		0065	1550	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$14,000.00	\$0.
		0065	1560	7125200	(EPOXY) SURFACE PREPARATION FOR RECOATING STRUCTURAL	1,100.00	0.00	1,100.00	SQFT	0.00	\$70.00	\$0
		0065	1570	7125210	STEEL FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,100.00	0.00	1,100.00	SQFT	0.00	\$4.00	\$0
		0065	1580	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$3.00	\$0
		0065	1590	7125370A	FINISH FIELD COAT (SYSTEM G)	1,100.00	0.00	1,100.00	SQFT	0.00	\$2.00	\$0
		0065	1600	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	61.00	0.00	61.00	LF	0.00	\$488.00	\$0
		0065	1610	7172054	OPEN CELL FOAM JOINT SEAL	61.00	0.00	61.00	LF	0.00	\$52.00	\$1
		0066	1620	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,088.00	0.00	1,088.00	SQYD	0.00	\$60.00	\$
		0066	1630	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$31.00	\$
		0066	1640	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	7.00	0.00	7.00	CY	0.00	\$700.00	\$
		0066	1650	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,088.00	0.00	1,088.00	SQYD	0.00	\$118.00	\$
		0066	1660	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$139.00	\$
		0068	1710	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$16,000.00	\$
		0068	1720	2161501	REMOVAL OF ASPHALT WEARING SURFACE	10,771.00	0.00	10,771.00	SQFT	10,771.00	\$2.00	\$21,54
		0068	1730	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$75,000.00	\$
		0068	1740	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	145.00	0.00	145.00	LF	0.00	\$631.00	\$
			1750	2169903	CONCRETE MISC.Remove and Replace Barrier Curb	63.00	0.00	63.00	LF	0.00	\$1,001.00	9
		0068	1760	5031010A		177.00	0.00	177.00	SQYD	0.00	\$492.00	
		0068	1770	7031004	BRIDGE APPROACH SLAB (MAJOR) DIAMOND GRINDING	1,183.00	0.00		SQYD	0.00	\$492.00	\$
		0068						1,183.00	CUYD			
		0068	1780	7034214	CLASS B-2 CONCRETE	57.90	0.00	57.90		0.00	\$1,752.00	
		0068	1790	7040101	SUBSTRUCTURE REPAIR (FORMED)	19.00	0.00	19.00	SQFT	0.00	\$169.00 \$173.25	
		0068	1810	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	20.00	0.00	20.00	LF	0.00	\$173.25	:
		0068	1820		SLAB EDGE REPAIR (BRIDGES)	70.00		70.00	LF		\$410.00	
		0068	1830	7040110	EPOXY PRESSURE INJECTING		0.00			0.00		
		0068		7040113	CLEANING AND EPOXY COATING	100.00	0.00	100.00	SQFT	0.00	\$30.00	
		0068	1840	7061070	MECHANICAL BAR SPLICE	37.00	0.00	37.00	EA	0.00	\$12.80	
		0068	1850	7101000	REINFORCING STEEL (EPOXY COATED)	4,410.00	0.00	4,410.00	LB	0.00	\$2.35	
		0068	1860	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$14,000.00	
		0068	1870	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,200.00	0.00	1,200.00	SQFT	0.00	\$70.00	
		0068	1880	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,200.00	0.00	1,200.00	SQFT	0.00	\$4.00	
		0068	1890	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,200.00	0.00	1,200.00	SQFT	0.00	\$3.00	
		0068	1900	7125370A	FINISH FIELD COAT (SYSTEM G)	1,200.00	0.00	1,200.00	SQFT	0.00	\$2.00	
		0068	1910	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	71.00	0.00	71.00	LF	0.00	\$488.00	
		0068	1920	7172054	OPEN CELL FOAM JOINT SEAL	74.00	0.00	74.00	LF	0.00	\$52.00	
		0069	1930	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,183.00	0.00	1,183.00	SQYD	1,183.00	\$60.00	\$70,9
		0069	1940	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	0.00	\$31.00	
		0069	1950	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	6.00	0.00	6.00	CY	0.00	\$700.00	
		0069	1960	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,183.00	0.00	1,183.00	SQYD	1,183.00	\$118.00	\$139,5
		0069	1970	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$139.00	
		0071	2020	2161501	REMOVAL OF ASPHALT WEARING SURFACE	13,440.00	0.00	13,440.00	SQFT	0.00	\$1.75	
		0071	2030	2169903	MISC.Remove and Replace Barrier Curb	20.00	0.00	20.00	LF	0.00	\$1,001.00	
		0071	2040	7031004	DIAMOND GRINDING	1,493.00	0.00	1,493.00	SQYD	0.00	\$9.75	
		0071	2050	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	8.00	0.00	8.00	SQFT	0.00	\$173.25	
		0071	2060	7040107	SLAB EDGE REPAIR (BRIDGES)	20.00	0.00	20.00	LF	0.00	\$410.00	

Revision 3/23/2023 Page 9 of 25



Total Paid / All Items / All Estimates (Including this Estimate)

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POST To Date (See rep generated date
421-F06	J6P3288	0071	2070	7040110	EPOXY PRESSURE INJECTING	20.00	0.00	20.00	LF	0.00	\$52.50	\$
		0071	2080	7049903	MISC.Barrier Curb Repair	4.00	0.00	4.00	LF	0.00	\$349.00	\$
		0071	2090	7129902	MISC.Cored Slab Drains	1.00	0.00	1.00	EA	0.00	\$1,984.00	\$
		0071	2100	7172054	OPEN CELL FOAM JOINT SEAL	93.00	0.00	93.00	LF	0.00	\$52.00	\$
		0072	2110	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,493.00	0.00	1,493.00	SQYD	0.00	\$60.00	\$
		0072	2120	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$700.00	\$
		0072	2130	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,493.00	0.00	1,493.00	SQYD	0.00	\$118.00	5
		0074	2170	2161501	REMOVAL OF ASPHALT WEARING SURFACE	14,179.00	0.00	14,179.00	SQFT	8,784.00	\$1.75	\$15,3
		0074	2180	7031004	DIAMOND GRINDING	1,575.00	0.00	1,575.00	SQYD	0.00	\$9.75	
		0074	2190	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	9.00	0.00	9.00	SQFT	0.00	\$173.25	
		0074	2200	7040110	EPOXY PRESSURE INJECTING	28.00	0.00	28.00	LF	0.00	\$52.50	
		0074	2210	7049903	MISC.Barrier Curb Repair	4.00	0.00	4.00	LF	0.00	\$349.00	
		0074	2220	7172054	OPEN CELL FOAM JOINT SEAL	98.00	0.00	98.00	LF	0.00	\$52.00	
		0075	2230	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,575.00	0.00	1,575.00	SQYD	1,575.00	\$60.00	\$94,
		0075	2240	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$31.00	
		0075	2250	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	11.69	\$700.00	\$8,
		0075	2260	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,575.00	0.00	1,575.00	SQYD	894.70	\$118.00	\$105,
		0075	2270	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$139.00	
		0077	2320	2161501	REMOVAL OF ASPHALT WEARING SURFACE	13,271.00	0.00	13,271.00	SQFT	0.00	\$1.80	
		0077	2330	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	86.00	0.00	86.00	LF	0.00	\$631.00	
		0077	2340	2169903	CONCRETE MISC.Remove and Replace Barrier Curb	15.00	0.00	15.00	LF	0.00	\$1,001.00	
			2350	7031004	DIAMOND GRINDING	1,457.00	0.00	1,457.00	SQYD	0.00	\$9.75	
		0077	2360	7031004	CLASS B-2 CONCRETE	7.20	0.00	7.20	CUYD	0.00	\$4,025.00	
		0077	2370	7034214	SUBSTRUCTURE REPAIR (UNFORMED)	45.00	0.00	45.00	SQFT	0.00	\$173.25	
		0077							LF			
		0077	2380	7040110	EPOXY PRESSURE INJECTING	121.00	0.00	121.00		0.00	\$52.50	
		0077	2390	7040113	CLEANING AND EPOXY COATING	505.00	0.00	505.00	SQFT	0.00	\$30.00	
		0077	2400	7061070	MECHANICAL BAR SPLICE	10.00	0.00	10.00	EA	0.00	\$12.80	
		0077	2410	7101000	REINFORCING STEEL (EPOXY COATED)	680.00	0.00	680.00	LB	0.00	\$2.35	
		0077	2420	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,000.00	
		0077	2430	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,400.00	0.00	1,400.00	SQFT	1,400.00	\$70.00	\$98,
		0077	2440	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,400.00	0.00	1,400.00	SQFT	1,400.00	\$4.00	\$5,
		0077	2450	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,400.00	0.00	1,400.00	SQFT	0.00	\$3.00	
		0077	2460	7125370A	FINISH FIELD COAT (SYSTEM G)	1,400.00	0.00	1,400.00	SQFT	0.00	\$2.00	
		0077	2470	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	86.00	0.00	86.00	LF	0.00	\$488.00	
		0078	2480	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,457.00	0.00	1,457.00	SQYD	0.00	\$60.00	
		0078	2490	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	11.00	0.00	11.00	CY	0.00	\$700.00	
		0078	2500	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,457.00	0.00	1,457.00	SQYD	0.00	\$118.00	
		0078	2510	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	0.00	\$139.00	
		0800	2560	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	23.00	0.00	23.00	SQFT	0.00	\$350.00	
		0800	2570	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$16,000.00	
		0800	2580	2161501	REMOVAL OF ASPHALT WEARING SURFACE	8,506.00	0.00	8,506.00	SQFT	5,160.00	\$2.25	\$11,
		0080	2590	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.50	\$50,000.00	\$25,
		0080	2600	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	137.00	0.00	137.00	LF	68.50	\$631.00	\$43,
					CONCRETE				LF			
		0080	2610	2169903	MISC REMOVAL OF EXISTING BRIDGE RAIL	480.00	0.00	480.00		0.00	\$21.00	
		0800	2620	2169903	MISC.Remove and Replace Barrier Curb	17.00	0.00	17.00	LF	0.00	\$1,001.00	
		0800	2630	5031010A	BRIDGE APPROACH SLAB (MAJOR)	178.00	0.00	178.00	SQYD	89.00	\$492.00	\$43

Revision 3/23/2023 Page 10 of 25



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					port Generated date and can differ from the posted amou							
Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See repor generated date)
30421-F06	J6P3288	0800	2640	7031004	DIAMOND GRINDING	911.00	0.00	911.00	SQYD	0.00	\$9.75	\$0.0
		0800	2650	7034214	CLASS B-2 CONCRETE	61.80	0.00	61.80	CUYD	36.00	\$1,650.00	\$59,400.0
		0800	2660	7040101	SUBSTRUCTURE REPAIR (FORMED)	10.00	0.00	10.00	SQFT	16.05	\$169.00	\$2,712.4
		0800	2670	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	20.00	0.00	20.00	SQFT	0.00	\$173.25	\$0.0
		0800	2680	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	29.00	0.00	29.00	SQFT	0.00	\$180.00	\$0.
		0800	2690	7040110	EPOXY PRESSURE INJECTING	11.00	0.00	11.00	LF	0.00	\$52.50	\$0.
		0800	2700	7040164	FIBER REINFORCED POLYMER WRAP	83.00	0.00	83.00	SF	0.00	\$178.00	\$0.
		0800	2710	7049904	MISC.CLEANING AND PROTECTIVE COATING (EPOXY)	988.00	0.00	988.00	SQFT	0.00	\$15.00	\$0.
		0800	2720	7061070	MECHANICAL BAR SPLICE	30.00	0.00	30.00	EA	0.00	\$12.80	\$0
		0800	2730	7101000	REINFORCING STEEL (EPOXY COATED)	5,850.00	0.00	5,850.00	LB	771.00	\$2.35	\$1,811
		0800	2740	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$14,000.00	\$0.
		0080	2750	7151001	(EPOXY) VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$6,000.00	\$0.
		0081	2760	2161001	TOTAL SURFACE HYDRO DEMOLITION	911.00	0.00	911.00	SQYD	573.00	\$60.00	\$34,380.
		0081	2770	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	6.00	0.00	6.00	CY	2.36	\$700.00	\$1.648.
		0081	2780	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	911.00	0.00	911.00	SQYD	573.00	\$118.00	\$67,614
			2790	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$139.00	\$07,014.
		0081	2840	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,672.00	0.00	7,672.00	SQFT	0.00	\$2.30	\$0
		0083	2850	7031004	DIAMOND GRINDING	852.00	0.00	852.00	SQYD	0.00	\$9.75	\$0
		0083										
		0083	2860	7040110	EPOXY PRESSURE INJECTING	16.00	0.00	16.00	LF	0.00	\$52.50	\$0
		0083	2870	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0
		0083	2880	7172054	OPEN CELL FOAM JOINT SEAL	80.00	0.00	80.00	LF	0.00	\$52.00	\$0
		0084	2890	2161001	TOTAL SURFACE HYDRO DEMOLITION	852.00	0.00	852.00	SQYD	0.00	\$60.00	\$0
		0084	2900	2161503	REMOVAL OF EXISTING DECK REPAIR	125.00	0.00	125.00	SQFT	0.00	\$31.00	\$0
		0084	2910	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	2.00	0.00	2.00	CY	0.00	\$700.00	\$0
		0084	2920	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	852.00	0.00	852.00	SQYD	0.00	\$118.00	\$1
		0086	2960	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,650.00	0.00	7,650.00	SQFT	4,676.00	\$2.30	\$10,75
		0086	2970	7031004	DIAMOND GRINDING	850.00	0.00	850.00	SQYD	0.00	\$9.75	\$
		0086	2980	7040113	CLEANING AND EPOXY COATING	4.00	0.00	4.00	SQFT	0.00	\$30.00	\$0
		0086	2990	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$1
		0086	3000	7172054	OPEN CELL FOAM JOINT SEAL	79.00	0.00	79.00	LF	0.00	\$52.00	\$0
		0087	3010	2161001	TOTAL SURFACE HYDRO DEMOLITION	850.00	0.00	850.00	SQYD	519.70	\$60.00	\$31,182
		0087	3020	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	2.00	0.00	2.00	CY	11.74	\$700.00	\$8,218
		0087	3030	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	850.00	0.00	850.00	SQYD	413.00	\$118.00	\$48,734
		0089	3070	2161501	REMOVAL OF ASPHALT WEARING SURFACE	15,134.00	0.00	15,134.00	SQFT	0.00	\$1.75	\$0
		0089	3080	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$12,000.00	\$(
		0089	3090	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	112.00	0.00	112.00	LF	0.00	\$631.00	\$1
		0089	3100	2169902	CONCRETE MISC.REMOVAL OF EXISTING BEARINGS AND ANCHOR BOLTS	12.00	0.00	12.00	EA	0.00	\$3,300.00	\$(
			3110	2169903	MISC.Remove and Replace Barrier Curb	14.00	0.00	14.00	LF	0.00	\$1,001.00	\$1
		0089										
		0089	3120	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	198.00	0.00	198.00	SQYD	0.00	\$340.00	\$1
		0089	3130	7031004	DIAMOND GRINDING	1,652.00	0.00	1,652.00	SQYD	0.00	\$9.75	\$0
		0089	3140	7034214	CLASS B-2 CONCRETE	13.70	0.00	13.70	CUYD	0.00	\$4,250.00	\$1
		0089	3150	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	30.00	0.00	30.00	SQFT	0.00	\$173.25	\$1
		0089	3160	7040110	EPOXY PRESSURE INJECTING	54.00	0.00	54.00	LF	0.00	\$52.50	\$
		0089	3170	7061070	MECHANICAL BAR SPLICE	16.00	0.00	16.00	EA	0.00	\$12.80	\$0
		0089	3180	7101000	REINFORCING STEEL (EPOXY COATED)	1,620.00	0.00	1,620.00	LB	0.00	\$2.35	\$0
		0089	3190	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$17,500.00	\$0

Revision 3/23/2023 Page 11 of 25



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230421-F06	J6P3288	0089	3200	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,300.00	0.00	1,300.00	SQFT	0.00	\$70.00	\$0.00
		0089	3210	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,300.00	0.00	1,300.00	SQFT	0.00	\$4.00	\$0.00
		0089	3220	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,300.00	0.00	1,300.00	SQFT	0.00	\$3.00	\$0.00
		0089	3230	7125370A	FINISH FIELD COAT (SYSTEM G)	1,300.00	0.00	1,300.00	SQFT	0.00	\$2.00	\$0.00
		0089	3240	7163000	TYPE N PTFE BEARING	12.00	0.00	12.00	EA	0.00	\$3,150.00	\$0.00
		0089	3250	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	112.00	0.00	112.00	LF	0.00	\$488.00	\$0.00
		0090	3260	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,652.00	0.00	1,652.00	SQYD	0.00	\$60.00	\$0.00
		0090	3270	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$700.00	\$0.00
		0090	3280	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,652.00	0.00	1,652.00	SQYD	0.00	\$118.00	\$0.00
		0092	3320	2161000	SCARIFICATION OF BRIDGE DECK	1,277.00	0.00	1,277.00	SQYD	0.00	\$12.00	\$0.00
		0092	3330	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	75.00	0.00	75.00	LF	0.00	\$631.00	\$0.00
		0092	3340	2169903	MISC.Remove and Replace Barrier Curb	12.00	0.00	12.00	LF	0.00	\$1,001.00	\$0.00
		0092	3350	7031004	DIAMOND GRINDING	1,277.00	0.00	1,277.00	SQYD	0.00	\$9.75	\$0.00
		0092	3360	7034214	CLASS B-2 CONCRETE	6.30	0.00	6.30	CUYD	0.00	\$3,950.00	\$0.00
		0092	3370	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	0.00	20.00	SQFT	0.00	\$169.00	\$0.00
		0092	3380	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	76.00	0.00	76.00	SQFT	0.00	\$173.25	\$0.00
		0092	3390	7040110	EPOXY PRESSURE INJECTING	115.00	0.00	115.00	LF	0.00	\$52.50	\$0.00
		0092	3400	7040113	CLEANING AND EPOXY COATING	175.00	0.00	175.00	SQFT	0.00	\$30.00	\$0.00
		0092	3410	7061070	MECHANICAL BAR SPLICE	10.00	0.00	10.00	EA	0.00	\$12.80	\$0.00
		0092	3420	7101000	REINFORCING STEEL (EPOXY COATED)	600.00	0.00	600.00	LB	0.00	\$2.35	\$0.00
		0092	3430	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0.00
		0092	3440	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1,300.00	0.00	1,300.00	SQFT	0.00	\$70.00	\$0.00
		0092	3450	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1,300.00	0.00	1,300.00	SQFT	0.00	\$4.00	\$0.00
		0092	3460	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	1,300.00	0.00	1,300.00	SQFT	0.00	\$3.00	\$0.00
		0092	3470	7125370A	FINISH FIELD COAT (SYSTEM G)	1,300.00	0.00	1,300.00	SQFT	0.00	\$2.00	\$0.00
		0092	3480	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	75.00	0.00	75.00	LF	0.00	\$488.00	\$0.00
		0093	3490	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,277.00	0.00	1,277.00	SQYD	0.00	\$60.00	\$0.00
		0093	3500	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	6.00	0.00	6.00	CY	0.00	\$700.00	\$0.00
		0093	3510	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,277.00	0.00	1,277.00	SQYD	0.00	\$118.00	\$0.00
		0093	3520	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$139.00	\$0.00
		0095	3570	2161501	REMOVAL OF ASPHALT WEARING SURFACE	16,029.00	0.00	16,029.00	SQFT	0.00	\$8.50	\$0.00
		0095	3580	7031004	DIAMOND GRINDING	1,781.00	0.00	1,781.00	SQYD	0.00	\$9.75	\$0.00
		0095	3590	7040110	EPOXY PRESSURE INJECTING	50.00	0.00	50.00	LF	0.00	\$52.50	\$0.00
		0095	3600	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,500.00	\$0.00
		0096	3610	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,781.00	0.00	1,781.00	SQYD	0.00	\$60.00	\$0.00
		0096	3620	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CY	0.00	\$700.00	\$0.00
		0096	3630	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,781.00	0.00	1,781.00	SQYD	0.00	\$118.00	\$0.00
		0096	3640	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$139.00	\$0.00
		0098	3690	2161501	REMOVAL OF ASPHALT WEARING SURFACE	16,335.00	0.00	16,335.00	SQFT	16,335.00	\$8.50	\$138,847.50
		0098	3700	7031004	DIAMOND GRINDING	1,815.00	0.00	1,815.00	SQYD	0.00	\$9.75	\$0.00
		0098	3710	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	4.00	0.00	4.00	SQFT	0.00	\$173.25	\$0.00
		0098	3720	7040110	EPOXY PRESSURE INJECTING	6.00	0.00	6.00	LF	0.00	\$52.50	\$0.00
		0098	3730	7049903	MISC.Barrier Curb Repair	4.00	0.00	4.00	LF	0.00	\$349.00	\$0.00
		0098	3740	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$10,500.00	\$0.00
		0099	3750	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,815.00	0.00	1,815.00	SQYD	1,208.30	\$60.00	\$72,498.00

Revision 3/23/2023 Page 12 of 25



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230421-F06	J6P3288	0099	3760	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	0.00	4.00	CY	9.41	\$700.00	\$6,587.00
		0099	3770	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,815.00	0.00	1,815.00	SQYD	1,208.30	\$118.00	\$142,579.40
	Project J6	P3288 - Tota	al Value I	Posted to Da	te as of Report Generated Date							\$3,151,175.60
	J6S3283B	0001	3810	2019901	MISC.CLEAR VEGETATION AND DEBRIS	1.00	0.00	1.00	LS	1.00	\$4,725.00	\$4,725.00
		0001	3820	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$120,000.00	\$0.00
		0001	3830	2063000	CLASS 3 EXCAVATION	18.00	0.00	18.00	CUYD	18.00	\$106.50	\$1,917.00
		0001	3840	2071000	LINEAR GRADING CLASS 1	2.00	0.00	2.00	STA	2.00	\$597.00	\$1,194.00
		0001	3850	2129909	MISC.SHOULDERING	1,969.00	0.00	1,969.00	STA	0.00	\$233.00	\$0.00
		0001	3860	2159910	MISC.SHAPING SLOPES, CLASS III (MODIFIED)	282.00	0.00	282.00	100F	0.00	\$750.00	\$0.00
		0001	3870	3101003	GRAVEL (A)	1,404.00	0.00	1,404.00	SQYD	0.00	\$23.25	\$0.00
		0001	3880	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	28,138.40	0.00	28,138.40	TONS	0.00	\$70.00	\$0.00
		0001	3890	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	34,041.50	0.00	34,041.50	TONS	13,074.58	\$85.00	\$1,111,339.30
		0001	3900	4030011	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095CLP MIX)	34,041.50	0.00	34,041.50	TONS	0.00	\$86.00	\$0.00
		0001	3910	4071005	TACK COAT	45,432.00	0.00	45,432.00	GAL	0.00	\$2.85	\$0.00
		0001	3920	4139912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	64,990.00	0.00	64,990.00	GAL	29,288.00	\$2.85	\$83,470.80
		0001	3930	6083006	6 IN. CONCRETE MEDIAN STRIP	953.00	0.00	953.00	SQYD	0.00	\$82.75	\$0.00
		0001	3940	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	6.00	0.00	6.00	EA	0.00	\$2,500.00	\$0.00
		0001	3950	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	4,956.00	0.00	4,956.00	SQYD	5,734.20	\$193.50	\$1,109,567.70
		0001	3960	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	496.00	0.00	496.00	SQYD	0.00	\$5.00	\$0.00
		0001	3970	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	496.00	0.00	496.00	SQYD	0.00	\$5.00	\$0.00
		0001	3980	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	21,800.00	0.00	21,800.00	LF	22,885.00	\$9.00	\$205,965.00
		0001	3990	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	12,048.00	0.00	12,048.00	EA	11,332.00	\$13.40	\$151,848.80
		0001	4000	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	660.00	0.00	660.00	TONS	639.82	\$215.00	\$137,561.30
		0001	4010	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	4,000.00	0.00	4,000.00	SQYD	5,387.00	\$30.00	\$161,610.00
		0001	4020	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$50,000.00	\$25,000.00
		0001	4030	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	4.00	0.00	4.00	EA	3.00	\$2,500.00	\$7,500.00
		0001	4040	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$650,000.00	\$487,500.00
		0001	4050	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	183.00	0.00	183.00	LF	0.00	\$20.00	\$0.00
		0001	4060	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	24.00	0.00	24.00	EA	0.00	\$300.00	\$0.00
		0001	4070	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	39.00	0.00	39.00	EA	0.00	\$25.00	\$0.00
		0001	4080	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	167,465.00	0.00	167,465.00	LF	0.00	\$0.26	\$0.00
		0001	4090	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	132,587.00	0.00	132,587.00	LF	0.00	\$0.25	\$0.00
		0001	4100	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,381.00	0.00	8,381.00	LF	0.00	\$0.85	\$0.00
		0001	4110	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3,372.00	0.00	3,372.00	LF	0.00	\$0.20	\$0.00
		0001	4120	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3,372.00	0.00	3,372.00	LF	0.00	\$0.20	\$0.00
		0001	4130	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	254,025.00	0.00	254,025.00	LF	5,563.00	\$0.25	\$1,390.75
		0001	4140	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	339,811.00	0.00	339,811.00	SQYD	162,375.00	\$1.40	\$227,325.00
		0001	4150	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	53,703.00	0.00	53,703.00	SQYD	0.00	\$0.10	\$0.00
		0001	4160	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,484.00	0.00	2,484.00	STA	0.00	\$24.75	\$0.00
		0001	4170	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$2,500.00	\$0.00
		0001	4180	7261012	12 IN. PIPE GROUP A	80.00	0.00	80.00	LF	80.00	\$123.50	\$9,880.00
		0001	4190	7320612A	12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$504.00	\$1,008.00
		0010	4200	6061060	MGS GUARDRAIL	23,388.00	0.00	23,388.00	LF	0.00	\$25.00	\$0.00
		0010	4210	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	2.00	0.00	2.00	EA	0.00	\$3,600.00	\$0.00
Revision 3/23/20	023											Page 13 of 25



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230421-F06	J6S3283B				(REGULAR/NO CURB)							
		0010	4220	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	0.00	\$650.00	\$0.00
		0010	4230	6061080	MGS END ANCHOR	41.00	0.00	41.00	EA	0.00	\$1,400.00	\$0.00
		0010	4240	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	42.00	0.00	42.00	EA	0.00	\$3,000.00	\$0.00
		0010	4250	6063021	TYPE D CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$31,000.00	\$0.00
		0040	4260	9031010	CONCRETE FOOTINGS, EMBEDDED	19.00	0.00	19.00	CUYD	0.00	\$1,800.00	\$0.00
		0040	4270	9031210	STRUCTURAL STEEL POSTS	9,650.00	0.00	9,650.00	LB	0.00	\$5.50	\$0.00
		0040	4280	9031220	PIPE POSTS	1,810.00	0.00	1,810.00	LB	0.00	\$7.50	\$0.00
		0040	4290	9031270A	2 IN. PSST POST - 12 GA.	135.00	0.00	135.00	LF	0.00	\$20.00	\$0.00
		0040	4300	9031273A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 7 GA.	15.00	0.00	15.00	EA	0.00	\$250.00	\$0.00
		0040	4310	9035004A	SH-FLAT SHEET	1,310.00	0.00	1,310.00	SQFT	0.00	\$26.00	\$0.00
		0040	4320	9035011A	ST-STRUCTURAL	1,968.00	0.00	1,968.00	SQFT	0.00	\$29.00	\$0.00
		0050	4330	9109903	MISC.MODOT ITS ASSETS RELOCATION	1,000.00	0.00	1,000.00	LF	0.00	\$18.00	\$0.00
	Project J65	3283B - To	otal Value	Posted to D	late as of Report Generated Date							\$3,728,802.65
230421-F06 Ove	rall - Total V	alue Poste	d to Date	as of Repor	t Generated Date							\$6,879,978.25

Revision 3/23/2023 Page 14 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6P3288

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	11/29/23	12/1/23	0.10	LS	SB route 21					bridge removals
0020	2159910	MISC. SHAPING SLOPES	11/20/23	11/21/23	4.00	100F	439+54.5 to 442+42 bridge 6					SB route 21
				11/21/23	15.00	100F	bridge 7 from station 509+70 to 516+70 station on the north side and station 519+69 to 521+44 station on the south side of the bridge					SB route 21 bridge 7
							4 439+54.5 to 442+42 bridge 6					
0070	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	11/16/23	11/21/23	13.00	LF	Bridge 7 phase 2					SB route 21
0155	6123000A	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	11/28/23	12/1/23	2.00	EA	route 21					
0170	6169902	MISC. TRAFFIC CONTROL DEVICES	11/30/23	12/1/23	3.00	EA	SB route 21					
0200	6181000	MOBILIZATION	11/30/23	12/4/23	0.25	LS	2nd partial payment					
0280	6061060	MGS GUARDRAIL	11/20/23	11/21/23	250.00	LF	439+54.5 to 442+42 bridge 6					SB route 21
				11/21/23	800.00	LF	662.5 - NB of bridge station 509+70 to 516+70 137.5 SB of bridge station 519+69 to 521+44					SB route 21 bridge 7
0290	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	11/20/23	11/21/23	1.00	EA	439+54.5 to 442+42 bridge 6					SB route 21
				11/21/23	2.00	EA	bridge 7 from station 509+70 to 516+70 station on the north side and station 519+69 to 521+44 station on the south side of the bridge					SB route 21 bridge 7
0310	6061080	MGS END ANCHOR	11/20/23	11/21/23	1.00	EA	SB of bridge 7 station 521+44					SB route 21
0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	11/20/23	11/21/23	1.00	EA	439+54.5 to 442+42 bridge 6					SB route 21
				11/21/23	1.00	EA	NB of bridge 7 station 509+69					SB route 21
1200	7049903	MISC.	11/16/23	11/21/23	11.50	LF	East side of bridge 7					
1960	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	11/16/23	11/20/23	515.70	SQYD	Bridge 3 SB route 21 phase 2					
2430	7125200	SURFACE PREPARATION FOR RECOATING	11/29/23	12/1/23	1,400.00	SQFT	NB and SB lanes 21					
2440	7125210	FIELD APPLICATION OF INORGANIC ZINC	11/29/23	12/1/23	1,400.00	SQFT	NB and SB lanes 21					
2630	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	11/29/23	12/1/23	89.00	SQYD	SB route 21 bridge 1 approaches					phase 1

Project: J6S3283B

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
3890	4030003	ASPH. CONC. MIXTURE PG 70-22 (SP095C)	11/16/23	11/20/23	732.31	TONS	Schenk on ramp to NB 21 Shady Valley On/off Ramps	175.5		180.6		
3950	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	11/21/23	11/30/23	123.30	SQYD	NB on ramp from 141 to 21	186.5		186.5		
			11/28/23	11/30/23	90.00	SQYD	NB on ramp from 141 to 21					
3980	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	11/21/23	11/30/23	343.00	LF	NB on ramp from 141 to 21					
			11/28/23	11/30/23	258.00	LF	NB on ramp from 141 to 21					
3990	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	11/21/23	11/30/23	73.00	EA	NB on ramp from 141 to 21	185.6		185.6		
			11/28/23	11/30/23	75.00	EA	NB on ramp from 141 to 21					
4030	6169902	MISC. TRAFFIC CONTROL DEVICES	11/30/23	12/1/23	1.00	EA	Route 21					
4040	6181000	MOBILIZATION	11/30/23	12/4/23	0.25	LS	3rd partial payment					
4130	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	11/30/23	12/1/23	5,563.00	LF	3460 yellow/white bridge 6 3199 yellow/white bridge 7 59 skips					Only paying 80% until reflectivity can be determined
4140	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	11/16/23	11/20/23	9,180.00	SQYD	Schenk on ramp to NB 21 Shady Valley On/off Ramps					

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 15 of 25



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3288	0070	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		9	Nov 1, 2023	SYSTEM	\$1,984.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user jamesc4 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Nov 1, 2023	SYSTEM	(\$1,984.00)	
					10	Nov 16, 2023	SYSTEM	\$3,069.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user jamesc4 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$3,069.00)	Zamato Zaoption to on the same symbol Zamato.
					11	Dec 4,	SYSTEM	(\$3,875.00)	
				Total		2023		(\$0.075.00)	
			Material Tata	- Total				(\$3,875.00)	
	0070	Total	Material - Tota	11				(\$3,875.00)	
	0070 -					5 4	OVOTEN	(\$3,875.00)	
	0155	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material		11	Dec 4, 2023	SYSTEM	\$20,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		(,			11	Dec 4, 2023	SYSTEM	(\$20,000.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0155 -	Total						\$0.00	
	0240	4 IN TEMPORARY PAVEMENT MARKING PAINT	Material		3	Aug 2, 2023	SYSTEM	\$5,129.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Aug 2, 2023	SYSTEM	(\$5,129.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0240 -	Total						\$0.00	
	0280	MGS GUARDRAIL	Construction Stockpile		9	Nov 1, 2023	SYSTEM	(\$17,519.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
					11	Dec 4, 2023	SYSTEM	(\$15,655.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$33,174.75)	
			Construction S	Stockpile - To				(\$33,174.75)	
			Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$216,940.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$216,940.50	
			Construction S	Stockpile STM	VII - Total			\$216,940.50	
	0280 -	Total						\$183,765.75	
	0290	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		9	Nov 1, 2023	SYSTEM	(\$4,100.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(.125,110 00110)			11	Dec 4, 2023	SYSTEM	(\$6,150.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$10,250.00)	
			Construction S	Stockpile - To	otal			(\$10,250.00)	
			Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$96,350.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$96,350.00	
			Construction S	Stockpile STI	VII - Total			\$96,350.00	
	0290 -	Total						\$86,100.00	
	0300	MGS HEIGHT AND BLOCK TRANSITION	Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$394.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$394.50	
			Construction S	Stockpile STI	VII - Total			\$394.50	
	0300 -	Total						\$394.50	
	0310	MGS END	Construction		11	Dec 4,	SYSTEM	(\$820.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		ANCHOR	Stockpile	- Total		2023		(\$820.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3288	0310	MGS END	Construction	Stockpile - To	otal			(\$820.00)	
		ANCHOR	Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$10,660.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$10,660.00	
			Construction	Stockpile STI	VII - Total			\$10,660.00	
	0310 -	Total						\$9,840.00	
	0320	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		9	Nov 1, 2023	SYSTEM	(\$3,750.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					11	Dec 4, 2023	SYSTEM	(\$3,750.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$7,500.00)	
			Construction	Stockpile - To	otal			(\$7,500.00)	
			Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$63,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$63,750.00	
			Construction	Stockpile STI	VII - Total			\$63,750.00	
	0320 -	Total						\$56,250.00	
	0580	SUPPLEMENTARY WEARING SURFACE	Material		9	Nov 1, 2023	SYSTEM	\$1,204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		MATERIAL			9	Nov 1, 2023	SYSTEM	(\$1,204.00)	
					10	Nov 16, 2023	SYSTEM	\$1,204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$1,204.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0580 -	· Total						\$0.00	
	0590	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		9	Nov 1, 2023	SYSTEM	\$92,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Nov 1, 2023	SYSTEM	(\$92,512.00)	
					10	Nov 16, 2023	SYSTEM	\$92,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$92,512.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0590 -	Total						\$0.00	
	1200	MISC.	Material		5	Sep 5, 2023	SYSTEM	\$9,562.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$9,562.60)	
					6	Sep 19, 2023	SYSTEM	\$9,562.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Sep 19, 2023	SYSTEM	(\$9,562.60)	
						0.40	CVCTEM	(\$9,562.60)	
					7	Oct 2, 2023	SYSTEM	(ψ0,002.00)	
					8		SYSTEM	\$9,562.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user jamesc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.
						2023 Oct 16,		, ,	Estimate Item Adjustment (0005) due to user jamesc4 overridding Payment
					8	2023 Oct 16, 2023 Oct 16,	SYSTEM	\$9,562.60	Estimate Item Adjustment (0005) due to user jamesc4 overridding Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3288	1200	MISC.	Material	Турс		2023			
				- Total				(\$9,562.60)	
			Material - Tota	ı				(\$9,562.60)	
			MaterialCredit		8	Oct 16,	SYSTEM	\$9,562.60	
						2023		40.740.40	
			MatarialOvalit	- Total				\$9,562.60	
	4200	- Total	MaterialCredit	- Iotai				\$9,562.60 \$0.00	
		SUPPLEMENTARY	Overrun	Overrun	8	Oct 16,	SYSTEM	(\$11,851.00)	
	1230	WEARING SURFACE MATERIAL	Overruit	Overruit	10	2023 Nov 16,	SYSTEM	(\$16,800.00)	
				Overrun - T		2023		(\$28,651.00)	
			Overrun - Total					(\$28,651.00)	
	1230 -	- Total						(\$28,651.00)	
	1240	LATEX MODIFIED CONCRETE WEARING	Material		10	Nov 16, 2023	SYSTEM	\$185,024.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		WEARING SURFACE			10	Nov 16, 2023	SYSTEM	(\$185,024.00)	Estimate Exception 6 on the Cultert Faymont Estimate.
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1240 -	- Total						\$0.00	
	1960	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		8	Oct 16, 2023	SYSTEM	\$78,741.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Oct 16, 2023	SYSTEM	(\$78,741.40)	
					9	Nov 1, 2023	SYSTEM	\$78,741.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user jamesc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Nov 1, 2023	SYSTEM	(\$78,741.40)	
					10	Nov 16, 2023	SYSTEM	\$78,741.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user jamesc4 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Nov 16,	SYSTEM	(\$70.741.40)	
						2023		(\$78,741.40)	
				- Total		2023		\$0.00	
			Material - Tota			2023			
	1960 -	· Total	Material - Tota			2023		\$0.00	
		SUPPLEMENTARY WEARING SURFACE			9	Nov 1, 2023	SYSTEM	\$0.00 \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		SUPPLEMENTARY WEARING				Nov 1,	SYSTEM	\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment
		SUPPLEMENTARY WEARING SURFACE			9	Nov 1, 2023		\$0.00 \$0.00 \$0.00 \$8,183.00	Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment
		SUPPLEMENTARY WEARING SURFACE			9	Nov 1, 2023 Nov 1, 2023 Nov 16,	SYSTEM	\$0.00 \$0.00 \$0.00 \$8,183.00 (\$8,183.00)	Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
		SUPPLEMENTARY WEARING SURFACE			9 9 10	Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM	\$0.00 \$0.00 \$0.00 \$8,183.00 (\$8,183.00) \$8,183.00	Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
		SUPPLEMENTARY WEARING SURFACE		I - Total	9 9 10	Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM	\$0.00 \$0.00 \$0.00 \$8,183.00 (\$8,183.00) \$8,183.00	Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
		SUPPLEMENTARY WEARING SURFACE	Material	- Total I Overrun	9 9 10 10	Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM	\$0.00 \$0.00 \$8,183.00 (\$8,183.00) \$8,183.00 (\$8,183.00) \$0.00 \$0.00 (\$6,083.00)	Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
		SUPPLEMENTARY WEARING SURFACE	Material Material - Tota Overrun	- Total I Overrun	9 9 10 10	Nov 1, 2023 Nov 1, 2023 Nov 16, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$8,183.00 (\$8,183.00) \$8,183.00 (\$8,183.00) \$0.00 (\$6,083.00)	Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
	2250	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material Material - Tota	- Total I Overrun	9 9 10 10	Nov 1, 2023 Nov 1, 2023 Nov 16, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$8,183.00 (\$8,183.00) \$8,183.00 (\$8,183.00) \$0.00 \$0.00 (\$6,083.00) (\$6,083.00)	Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
	2250	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material Material - Tota Overrun	- Total I Overrun	9 9 10 10 10 9 otal	Nov 1, 2023 Nov 1, 2023 Nov 16, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$8,183.00 (\$8,183.00) \$8,183.00 (\$8,183.00) \$0.00 (\$6,083.00)	Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment
	2250	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material Material - Tota Overrun	- Total I Overrun	9 9 10 10	Nov 1, 2023 Nov 1, 2023 Nov 16, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$8,183.00 (\$8,183.00) \$8,183.00 (\$8,183.00) \$0.00 \$0.00 (\$6,083.00) (\$6,083.00)	Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J6P3288	2260	LATEX MODIFIED		Туре	10	Nov 16,	SYSTEM	\$105,574.60	This adjustment offsets the original system-generated Material Payment
JOF 3200	2200	CONCRETE WEARING	Waterial		10	2023	STOTEM	\$103,374.00	Estimate Item Adjustment (0016) due to user jamesc4 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		SURFACE			10	Nov 16, 2023	SYSTEM	(\$105,574.60)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	2260 -	Total						\$0.00	
	2440	FIELD APPLICATION OF INORGANIC ZINC	Material		11	Dec 4, 2023	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					11	Dec 4, 2023	SYSTEM	(\$5,600.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	2440 -	· Total						\$0.00	
	2630	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		11	Dec 4, 2023	SYSTEM	(\$43,788.00)	
				- Total				(\$43,788.00)	
			Material - Tota	ıl				(\$43,788.00)	
	2630 -	Total						(\$43,788.00)	
	2650	CLASS B-2 CONCRETE	Material		10	Nov 16, 2023	SYSTEM	\$59,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user jamesc4 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$59,400.00)	
					11	Dec 4, 2023	SYSTEM	\$59,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user jamesc4 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					11	Dec 4, 2023	SYSTEM	(\$59,400.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	2650 -	Total						\$0.00	
	2660	SUBSTRUCTURE REPAIR (FORMED)	Overrun	Overrun		Nov 1, 2023	SYSTEM	(\$1,022.45)	
				Overrun - Total				(\$1,022.45)	
		Overrun - Total							
	2660 -							(\$1,022.45)	
		SUPPLEMENTARY WEARING SURFACE						(\$1,022.45)	
	2770	WEARING SURFACE	Material		5	Sep 5, 2023	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	2770	WEARING	Material		5	2023 Sep 5, 2023	SYSTEM	(\$1,022.45) \$1,648.50 (\$1,648.50)	Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	2770	WEARING SURFACE	Material			2023 Sep 5,		(\$1,022.45) \$1,648.50	Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment
	2770	WEARING SURFACE	Material		5	2023 Sep 5, 2023 Sep 19,	SYSTEM	(\$1,022.45) \$1,648.50 (\$1,648.50)	Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment
	2770	WEARING SURFACE	Material		5	2023 Sep 5, 2023 Sep 19, 2023	SYSTEM SYSTEM	(\$1,022.45) \$1,648.50 (\$1,648.50) \$1,648.50	Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment
	2770	WEARING SURFACE	Material		5 6	2023 Sep 5, 2023 Sep 19, 2023 Sep 19, 2023 Oct 2,	SYSTEM SYSTEM SYSTEM	(\$1,022.45) \$1,648.50 (\$1,648.50) \$1,648.50 (\$1,648.50)	Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment
	2770	WEARING SURFACE	Material		5 6 6 7	2023 Sep 5, 2023 Sep 19, 2023 Sep 19, 2023 Oct 2, 2023 Nov 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,022.45) \$1,648.50 (\$1,648.50) \$1,648.50 (\$1,648.50)	Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user jamesc4 overridding Payment
	2770	WEARING SURFACE	Material	- Total	5 6 6 7 10	2023 Sep 5, 2023 Sep 19, 2023 Sep 19, 2023 Oct 2, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,022.45) \$1,648.50 (\$1,648.50) \$1,648.50 (\$1,648.50) (\$1,648.50)	Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user jamesc4 overridding Payment
	2770	WEARING SURFACE	Material - Tota		5 6 6 7 10	2023 Sep 5, 2023 Sep 19, 2023 Sep 19, 2023 Oct 2, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,022.45) \$1,648.50 (\$1,648.50) \$1,648.50 (\$1,648.50) \$1,648.50 (\$1,648.50)	Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user jamesc4 overridding Payment
	2770	WEARING SURFACE			5 6 6 7 10	2023 Sep 5, 2023 Sep 19, 2023 Sep 19, 2023 Oct 2, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,022.45) \$1,648.50 (\$1,648.50) \$1,648.50 (\$1,648.50) (\$1,648.50) (\$1,648.50)	Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user jamesc4 overridding Payment
	2770	WEARING SURFACE	Material - Tota MaterialCredit	l - Total	5 6 6 7 10	2023 Sep 5, 2023 Sep 19, 2023 Sep 19, 2023 Oct 2, 2023 Nov 16, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,022.45) \$1,648.50 (\$1,648.50) \$1,648.50 (\$1,648.50) (\$1,648.50) (\$1,648.50) (\$1,648.50)	Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user jamesc4 overridding Payment
	2770	WEARING SURFACE MATERIAL	Material - Tota	l - Total	5 6 6 7 10	2023 Sep 5, 2023 Sep 19, 2023 Sep 19, 2023 Oct 2, 2023 Nov 16, 2023 Nov 16, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,022.45) \$1,648.50 (\$1,648.50) \$1,648.50 (\$1,648.50) \$1,648.50 (\$1,648.50) (\$1,648.50) \$1,648.50	Estimate Item Adjustment (0007) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user jamesc4 overridding Payment



5 .		5		6					
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3288	2780	LATEX MODIFIED CONCRETE WEARING	Material		5	Sep 5, 2023	SYSTEM	\$67,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		SURFACE			5	Sep 5, 2023	SYSTEM	(\$67,614.00)	
					6	Sep 19, 2023	SYSTEM	\$67,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user jamesc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6 7 10	6	Sep 19, 2023	SYSTEM	(\$67,614.00)	
					7	Oct 2, 2023	SYSTEM	(\$67,614.00)	
					10	Nov 16, 2023	SYSTEM	\$67,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user jamesc4 overridding Payment
					10	Nov 16,	SYSTEM	(\$67,614.00)	Estimate Exception 11 on the current Payment Estimate.
						2023			
				- Total				(\$67,614.00)	
			Material - Tota			-		(\$67,614.00)	
			MaterialCredit		8	Oct 16, 2023	SYSTEM	\$67,614.00	
				- Total				\$67,614.00	
			MaterialCredit	- Total				\$67,614.00	
	2780 -	Total						\$0.00	
	3020	SUPPLEMENTARY WEARING SURFACE MATERIAL	ARING RFACE		5	Sep 5, 2023	SYSTEM	\$2,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Sep 5, 2023	SYSTEM	(\$2,205.00)	
					6	Sep 19, 2023	SYSTEM	\$2,205.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Sep 19, 2023	SYSTEM	(\$2,205.00)	
			Material - Tota MaterialCredit		7	Oct 2, 2023	SYSTEM	(\$2,205.00)	
					10	Nov 16, 2023	SYSTEM	\$8,218.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$8,218.00)	
				- Total				(\$2,205.00)	
				I				(\$2,205.00)	
					8	Oct 16, 2023	SYSTEM	\$2,205.00	
				- Total				\$2,205.00	
			MaterialCredit	- Total				\$2,205.00	
			Overrun	Overrun	5	Sep 5, 2023	SYSTEM	(\$805.00)	
					10	Nov 16, 2023	SYSTEM	(\$6,013.00)	
				Overrun - T	otal			(\$6,818.00)	
			Overrun - Tota	ı				(\$6,818.00)	
	3020 -							(\$6,818.00)	
	3030	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		5	Sep 5, 2023	SYSTEM	\$48,734.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user jamesc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		SURFACE			5	Sep 5, 2023	SYSTEM	(\$48,734.00)	
					6	Sep 19, 2023	SYSTEM	\$48,734.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user jamesc4 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Sep 19, 2023	SYSTEM	(\$48,734.00)	
					7	Oct 2,	SYSTEM	(\$48,734.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3288	3030	LATEX MODIFIED	Material			2023			
		CONCRETE WEARING SURFACE			10	Nov 16, 2023	SYSTEM	\$48,734.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user jamesc4 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$48,734.00)	
				- Total				(\$48,734.00)	
			Material - Tota	ı				(\$48,734.00)	
			MaterialCredit		8	Oct 16, 2023	SYSTEM	\$48,734.00	
				- Total				\$48,734.00	
			MaterialCredit	- Total				\$48,734.00	
	3030 -	- Total						\$0.00	
	3760	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		6	Sep 19, 2023	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Sep 19, 2023	SYSTEM	(\$4,200.00)	
					7	Oct 2, 2023	SYSTEM	(\$4,200.00)	
					10	Nov 16, 2023	SYSTEM	\$6,587.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user jamesc4 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Nov 16, 2023	SYSTEM	(\$6,587.00)	
				- Total				(\$4,200.00)	
			Material - Tota	ı				(\$4,200.00)	
			MaterialCredit		8	Oct 16, 2023	SYSTEM	\$4,200.00	
				- Total				\$4,200.00	
			MaterialCredit	- Total				\$4,200.00	
			Overrun	Overrun	6	Sep 19, 2023	SYSTEM	(\$1,400.00)	
					10	Nov 16, 2023	SYSTEM	(\$2,387.00)	
				Overrun - T	otal			(\$3,787.00)	
			Overrun - Tota	al .				(\$3,787.00)	
	3760 -	- Total						(\$3,787.00)	
	3770	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		6	Sep 19, 2023	SYSTEM	\$142,579.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user jamesc4 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		JONI ACL			6	Sep 19, 2023	SYSTEM	(\$142,579.40)	
					7	Oct 2, 2023	SYSTEM	(\$142,579.40)	
					8	Oct 16,	SYSTEM	\$142,579.40	This adjustment offsets the original system-generated Material Payment
						2023			Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	2023 Oct 16, 2023	SYSTEM	(\$142,579.40)	Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.
						Oct 16,	SYSTEM	(\$142,579.40) \$142,579.40	Estimate Item Adjustment (0008) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Oct 16, 2023 Nov 1,		,	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment
					8	Oct 16, 2023 Nov 1, 2023	SYSTEM	\$142,579.40	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment
					9	Oct 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16,	SYSTEM	\$142,579.40 (\$142,579.40)	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment
				- Total	8 9 9	Oct 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM SYSTEM	\$142,579.40 (\$142,579.40) \$142,579.40	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment
			Material - Tota		8 9 9	Oct 16, 2023 Nov 1, 2023 Nov 1, 2023 Nov 16, 2023	SYSTEM SYSTEM	\$142,579.40 (\$142,579.40) \$142,579.40 (\$142,579.40)	Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment



March System March System March System Syst	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
3772 Total	riojost	Line	Description		Adjustment				Amount	romano
1973 1974 1975	J6P3288	3770	CONCRETE	MaterialCredit	- Total				\$142,579.40	
				MaterialCredit	- Total				\$142,579.40	
Microscopy March Microscopy Microsco		3770 -	· Total						\$0.00	
MACTURE FO 7-722 (SPVISO) Page 2033 10 Nov 16. SYSTEM (\$1.04.002 db)	J6P3288 -	Total							\$242,325.80	
10	J6S3283B	3890	MIXTURE PG	Material		10		SYSTEM	\$1,049,092.95	Estimate Item Adjustment (0021) due to user jamesc4 overridding Payment
Total Substitute Substitu						10		SYSTEM	(\$1,049,092.95)	,
					Total		2020		0.00	
1				Maradal Tar						
1				material - Total						
CONDITION COND		3890 -	Total						\$0.00	
2023 2228,898.90		3950	CONC MATL FOR	Material		1		SYSTEM	\$28,057.50	Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment
2023 SYSTEM G329,839.30 Estimate Exception 1 on the current Payment Estimate Exception 2 on the curren						1		SYSTEM	(\$28,057.50)	
2023 SYSTEM \$310,780.35 This adjustment offsets the original system-generated Material Payment Estimate Isomatory on the Current Payment Isomatory on t						2		SYSTEM	\$229,839.30	Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment
2023 SySTEM S280,102.36 SySTEM S280,102.39 SySTEM S280,102.39 SySTEM						2		SYSTEM	(\$229,839.30)	
2023 SySTEM \$286,012.35 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 9 on the current Payment Estimate Extended Internal Exception 9 on the current Payment Estimate Exception 9 on the current Payment Estimate Extended Internal Except						3		SYSTEM	\$310,780.35	Estimate Item Adjustment (0003) due to user jamesc4 overridding Payment
2023 Estimate Example (1) Estimate Exception 5 on the current Payment Estimate Estimate Estimate Exception 5 on the current Payment Estimate Estimate Estimate Estimate Estimate Exception 9 on the current Payment Estimate Estimate Exception 9 on the current Payment Estimate. Total						3		SYSTEM	(\$310,780.35)	
Sep 5,						5		SYSTEM	\$286,012.35	Estimate Item Adjustment (0012) due to user jamesc4 overridding Payment
7						5		SYSTEM	(\$286,012.35)	
Total Summer Su						7	Oct 2,	SYSTEM	\$286,012.16	Estimate Item Adjustment (0002) due to user jamesc4 overridding Payment
Note						7		SYSTEM	(\$286,012.16)	Estimate Exception 9 on the current Payment Estimate.
Material - Total Summary Summa					- Total				\$0.00	
Overrun Overrun Overrun T Oct 2, 2023 SYSTEM (\$2,244.60)				Material - Tota						
8						7		SYSTEM		
10					Overruin	8		SYSTEM	(\$52,109.55)	
2023 11 Dec 4, 2023 SYSTEM (\$41,273.55)						10		SYSTEM	(\$54.954.00)	
Overrun - Total (\$150,581.70) Overrun - Total Overrun -							2023			
3950 - Total (\$150,581.70) 3950 - Total (\$150,581.70) 3980					Overrun - T			0.0.2		
System S				Overrup Tete		orar				
3980 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR 10 Nov 16, 2023 SYSTEM (\$4,356.00)		00	Table	Overrun - Tota	<u> </u>					
2023 11 Dec 4, 2023 (\$5,409.00)										
Coverrun - Total Cisp.765.00		3980	PAVEMENT	Overrun	Overrun	10		SYSTEM	(\$4,356.00)	
3990 DOWEL BAR (DRILLING, FURNISHING AND INST 1 Jun 30, 2023 SYSTEM \$3,886.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user jamesc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.						11		SYSTEM	(\$5,409.00)	
3990 DOWEL BAR (DRILLING, FURNISHING AND INST DIA Jun 30, 2023 SYSTEM 1 Jun 30, 2023 SYSTEM (\$3,886.00) 1 Jun 30, 2023 SYSTEM (\$3,886.00) 1 Jun 30, 2023 SYSTEM (\$3,886.00)					Overrun - T	otal			(\$9,765.00)	
3990 DOWEL BAR (DRILLING, FURNISHING AND INST INST INST INST INST INST INST INST				Overrun - Tota	l e				(\$9,765.00)	
3990 DOWEL BAR (DRILLING, FURNISHING AND INST System		3980 -	· Total							
1 Jun 30, 2023 SYSTEM (\$3,886.00)			DOWEL BAR (DRILLING, FURNISHING AND	Material		1		SYSTEM		Estimate Item Adjustment (0001) due to user jamesc4 overridding Payment
			INST			1		SYSTEM	(\$3,886.00)	
						2		SYSTEM	\$27,202.00	This adjustment offsets the original system-generated Material Payment

MoDOT

Line Item Adjustments by Estimate

ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
83B	3990	DOWEL BAR (DRILLING,	Material			2023			Estimate Item Adjustment (0001) due to user jamesc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
		FURNISHING AND INST			2	Jul 17, 2023	SYSTEM	(\$27,202.00)				
					3	Aug 2, 2023	SYSTEM	\$36,984.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user jamesc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					3	Aug 2, 2023	SYSTEM	(\$36,984.00)				
					4	Aug 16, 2023	SYSTEM	\$36,984.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user jamesc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					4	Aug 16, 2023	SYSTEM	(\$36,984.00)				
					5	Sep 5, 2023	SYSTEM	\$2,036.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user jamesc4 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					5	Sep 5, 2023	SYSTEM	(\$2,036.80)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	3990 -	· Total						\$0.00				
	4010	REMOVAL FOR CLASS B PARTIAL DEPTH PAVT R	Overrun	Overrun	9	Nov 1, 2023	SYSTEM	(\$41,610.00)				
				Overrun - T	otal			(\$41,610.00)				
			Overrun - Tota	al				(\$41,610.00)				
	4010 -	· Total						(\$41,610.00)				
	4130	4 IN TEMPORARY PAVEMENT MARKING PAINT	Material		11	Dec 4, 2023	SYSTEM	\$1,390.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user jamesc4 overridding Paymen Estimate Exception 11 on the current Payment Estimate.			
					11	Dec 4, 2023	SYSTEM	(\$1,390.75)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	4130 -	· Total						\$0.00				
	4200	MGS GUARDRAIL	Construction Stockpile STMA		5	Sep 5, 2023	SYSTEM	\$34,665.75	Payment Estimate Item Adjustment generated Stockpile Transaction			
					6	Sep 19, 2023	SYSTEM	\$226,323.13	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				\$260,988.88				
			Construction	Stockpile STI	MA - Total			\$260,988.88				
			Construction Stockpile STMI		5	Sep 5, 2023	SYSTEM	\$78,030.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				\$78,030.00				
			Construction	Stockpile STI	VII - Total			\$78,030.00				
	4200 -	Total						\$339,018.88				
	4210	MGS BRIDGE APP. TRANS SEC	MGS BRIDGE	MGS BRIDGE Co	MGS BRIDGE Constr APP. TRANS SEC Stockp	Comptunation		5	Sep 5, 2023	SYSTEM	\$4,100.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile STMI			2020	Total					
		APP. TRANS SEC	Stockpile	- Total		2020		\$4,100.00				
		APP. TRANS SEC	Stockpile		VII - Total	2020		\$4,100.00 \$4,100.00				
	4210 -	APP. TRANS SEC (REG/NO CURB)	Stockpile STMI		MI - Total	2020						
		APP. TRANS SEC (REG/NO CURB)	Stockpile STMI Construction	Stockpile STI	VII - Total	Sep 5, 2023	SYSTEM	\$4,100.00 \$4,100.00 \$394.50	Payment Estimate Item Adjustment generated Stockpile Transaction			
	4210 -	APP. TRANS SEC (REG/NO CURB) Total MGS HEIGHT AND BLOCK	Stockpile STMI Construction Construction Stockpile STMI	Stockpile STI	5	Sep 5,	SYSTEM	\$4,100.00 \$4,100.00 \$394.50	Payment Estimate Item Adjustment generated Stockpile Transaction			
	4210 -	APP. TRANS SEC (REG/NO CURB) Total MGS HEIGHT AND BLOCK	Stockpile STMI Construction Construction Stockpile	Stockpile STI	5	Sep 5,	SYSTEM	\$4,100.00 \$4,100.00 \$394.50	Payment Estimate Item Adjustment generated Stockpile Transaction			
	4210 -	APP. TRANS SEC (REG/NO CURB) Total MGS HEIGHT AND BLOCK TRANSITION	Stockpile STMI Construction Construction Stockpile STMI	Stockpile STI	5	Sep 5,	SYSTEM	\$4,100.00 \$4,100.00 \$394.50	Payment Estimate Item Adjustment generated Stockpile Transaction			
	4210 - 4220	APP. TRANS SEC (REG/NO CURB) Total MGS HEIGHT AND BLOCK TRANSITION	Stockpile STMI Construction Construction Stockpile STMI Construction Construction Stockpile	Stockpile STI - Total Stockpile STI	5	Sep 5,	SYSTEM	\$4,100.00 \$4,100.00 \$394.50 \$394.50 \$394.50 \$394.50 \$33,620.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction			
	4210 - 4220	APP. TRANS SEC (REG/NO CURB) Total MGS HEIGHT AND BLOCK TRANSITION Total MGS END	Stockpile STMI Construction Construction Stockpile STMI Construction Construction	Stockpile STI	5 MI - Total	Sep 5, 2023		\$4,100.00 \$4,100.00 \$394.50 \$394.50 \$394.50				
	4210 - 4220	APP. TRANS SEC (REG/NO CURB) Total MGS HEIGHT AND BLOCK TRANSITION Total MGS END	Stockpile STMI Construction Construction Stockpile STMI Construction Construction Stockpile	Stockpile STI - Total Stockpile STI - Total	5 MI - Total 5	Sep 5, 2023		\$4,100.00 \$4,100.00 \$394.50 \$394.50 \$394.50 \$394.50 \$33,620.00				

Dec 6, 2023



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3283B	4240	TYPE A CRASHWORTHY END TERMINAL (MASH)	Stockpile		5	Sep 5, 2023	SYSTEM	\$78,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$78,750.00	
			Construction	Stockpile STI	VII - Total			\$78,750.00	
	4240 - Total							\$78,750.00	
	4250	TYPE D CRASHWORTHY END TERMINAL (MASH)	Stockpile STMI		3	Aug 2, 2023	SYSTEM	\$46,282.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$46,282.00	
			Construction	Stockpile STI	VII - Total			\$46,282.00	
	4250 -	Total						\$46,282.00	
J6S3283B	- Total							\$300,208.68	
Overall - T	otal							\$542,534.48	

MoDOT

Contract Adjustments for Contract - 230421-F06

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 25 of 25