

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 6, 2023

| Progress Estimate Number | Contract ID | 230519-C10 | Pay Period Start | August 16, 2023 | Original Contract Amount | \$2,143,392.55 |
|-----------------------------|---------------------|--|---------------------|-------------------|-----------------------------|----------------|
| 3 | Prime Contractor | Leavenworth Excavating & Equipment Company, Inc. | Pay Period End | September 1, 2023 | Net Change Order Amount | \$26,775.00 |
| | | | | | Current Contract Amount | \$2,170,167.55 |

| Approval Date | | By User |
|-------------------|--|---------|
| September 6, 2023 | Generated and Approved (and should be considered Draft) at the Project Office Level by | vegaj1 |
| September 6, 2023 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | sandis1 |
| September 6, 2023 | Reviewed and Approved at the Central Office Controllers Office Level by | ramses1 |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete |
|--------------------------|-------------------------|------------------------|---------------------------------------|
| May 1, 2024 | May 1, 2024 | | 17.62% |

| | Contract Informational Dat | tes | Milestones |
|------------------------|----------------------------|--------------------------------|----------------------------------|
| Date Description | Original Completion Date | Current Completion Date | No Milestones Exist for Contract |
| Acceptance Date | | | |
| Awarded Date | June 7, 2023 | June 7, 2023 | |
| Letting Date | May 19, 2023 | May 19, 2023 | |
| Notice to Proceed Date | July 10, 2023 | July 10, 2023 | |
| Open to Traffic Date | | | |
| Work Began Date | July 13, 2023 | July 13, 2023 | |

| Contract Total P | ay For Estimate No. 3 | | | | |
|-----------------------|----------------------------|---------------|--------------|--------------|--|
| | | This Estimate | Previous | To Date | |
| 230519-C10 | | | | | |
| | Total Posted Items Pay | \$256,838.70 | \$125,561.95 | \$382,400.65 | |
| | Gross Item Adjustments | (\$14,156.48) | \$119,351.40 | \$105,194.92 | |
| | Incentive | \$0.00 | \$0.00 | \$0.00 | |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 | |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 | |
| | · | | \$244,913.35 | \$487,595.57 | |
| Contract Total Page 1 | avable This Estimate: | \$242 682 22 | | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|--|------|---------------|--------------------------|-----------------------------|
| JKU0005 | 0010 | 2013000 | CLEARING AND GRUBBING | ACRE | \$30,000.000 | 0.18 | \$5,400.00 |
| | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | LS | \$78,200.000 | 0.2 | \$15,640.00 |
| | 0030 | 2031000 | CLASS A EXCAVATION | CUYD | \$5.000 | 5,328.46 | \$26,642.30 |
| | 0800 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | CUYD | \$50.000 | 75 | \$3,750.00 |
| | 0090 | 6096030A | FURNISHING TYPE 3 ROCK DITCH LINER | CUYD | \$63.000 | 20 | \$1,260.00 |
| | 0100 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | CUYD | \$14.000 | 75 | \$1,050.00 |
| | 0110 | 6096043 | PLACING TYPE 3 ROCK DITCH LINER | CUYD | \$45.000 | 20 | \$900.00 |
| | 0120 | 6113010 | FURNISHING TYPE 1 ROCK BLANKET | CUYD | \$51.000 | 1,001.75 | \$51,089.25 |
| | 0130 | 6113030 | PLACING TYPE 1 ROCK BLANKET | CUYD | \$12.000 | 1,001.75 | \$12,021.00 |
| | 0200 | 6175010A | RELOCATING TEMPORARY TRAFFIC BARRIER | LF | \$18.000 | 500 | \$9,000.00 |
| | 0210 | 6181000 | MOBILIZATION | LS | \$170,000.000 | 0.5 | \$85,000.00 |
| | 0220 | 6240104A | SEPARATION GEOTEXTILE | SQYD | \$2.750 | 2,250 | \$6,187.50 |
| | 0230 | 6249905 | MISC.GEOSYNTHETIC REINFORCEMENT | SQYD | \$4.000 | 3,600 | \$14,400.00 |
| | 0240 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | LS | \$9,600.000 | 0.2 | \$1,920.00 |
| | 0340 | 8051000A | SEEDING - COOL SEASON GRASSES | ACRE | \$1,750.000 | 0.225 | \$393.75 |

Revision 3/23/2023 Page 1 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 6, 2023

| Progress Estimate Number | Contract ID | 230519-C10 | Pay Period Start | August 16, 2023 | Original Contract Amount | \$2,143,392.55 |
|-----------------------------|---------------------|--|---------------------|-------------------|-----------------------------|----------------|
| 3 | Prime Contractor | Leavenworth Excavating & Equipment Company, Inc. | Pay Period End | September 1, 2023 | Net Change Order Amount | \$26,775.00 |
| | | | | | Current Contract Amount | \$2,170,167.55 |

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|--|------|-------------|--------------------------|-----------------------------|
| JKU0005 | 0350 | 8061004 | SEDIMENT TRAP ROCK | CUYD | \$360.000 | 1 | \$360.00 |
| | 0360 | 8061005 | ROCK DITCH CHECK | LF | \$82.000 | 15 | \$1,230.0 |
| | 0390 | 8061019 | SILT FENCE | LF | \$1.650 | 100 | \$165.0 |
| | 0400 | 8064140 | TYPE 3B EROSION CONTROL BLANKET | SQYD | \$1.600 | 1,089 | \$1,742.4 |
| | 0410 | 6061060 | MGS GUARDRAIL | LF | \$27.500 | 275 | \$7,562.5 |
| | 0420 | 6061074 | MGS HEIGHT AND BLOCK TRANSITION | EA | \$900.000 | 1 | \$900.0 |
| | 0430 | 6061080 | MGS END ANCHOR | EA | \$1,300.000 | 1 | \$1,300.0 |
| | 5001 | 6122019 | IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY) | EA | \$5,250.000 | 1 | \$5,250.0 |
| | 5003 | 6122030 | IMPACT ATTENUATOR (RELOCATION) | EA | \$3,675.000 | 1 | \$3,675.0 |
| Project JKU0 | 005 - Total | | | | | | \$256,838.7 |
| Overall - Tota | ıl | | | | | | \$256,838. |

Contract Adjustments This Estimate

| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|-------------------|-------------|---------------------------------------|--------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| JKU0005 | 0030 | CLASS A EXCAVATION | Price | | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | 5,328.46 | \$0.09 | \$468.90 |
| | 0040 | EMBANKMENT IN PLACE | Material | | | -1,300 | \$10.00 | (\$13,000.00 |
| | 0040 | EMBANKMENT IN PLACE | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user vegaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 1,300 | \$10.00 | \$13,000.00 |
| | 0800 | FURNISHING TYPE 2 ROCK DITCH LINER | Material | | | -75 | \$50.00 | (\$3,750.00) |
| | 0080 | FURNISHING TYPE 2 ROCK DITCH LINER | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user vegaj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | 75 | \$50.00 | \$3,750.00 |
| | 0090 | FURNISHING TYPE 3 ROCK DITCH LINER | Material | | | -20 | \$63.00 | (\$1,260.00) |
| | 0090 | FURNISHING TYPE 3 ROCK DITCH LINER | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user vegaj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | 20 | \$63.00 | \$1,260.00 |
| | 0120 | FURNISHING TYPE 1 ROCK BLANKET | Material | | | -1,488.9 | \$51.00 | (\$75,933.90) |
| | 0120 | FURNISHING TYPE 1 ROCK BLANKET | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user vegaj1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | 1,488.9 | \$51.00 | \$75,933.90 |
| | 0150 | CONSTRUCTION SIGNS | Material | | | -222 | \$12.00 | (\$2,664.00) |
| | 0150 | CONSTRUCTION SIGNS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user vegaj1 overridding Payment Estimate Exception 8 on | 222 | \$12.00 | \$2,664.00 |

Revision 3/23/2023 Page 2 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 6, 2023

August 16, 2023 Original Contract
Amount
September 1, Net Change Order
Amount
Current Contract
Amount **Progress Estimate Pay Period** \$2,143,392.55 Contract ID 230519-C10 Number Start Leavenworth Excavating & Equipment Company, Inc. Pay Period End Prime 3 \$26,775.00 Contractor \$2,170,167.55 Amount

| oject imber | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|----------------|-------------|---|---------------------------|----------------------------------|---|------------------------|---------------------------------------|-------------------|
| J0005 | | | | | the current Payment Estimate. | | | |
| | 0160 | CHANNELIZER (TRIM LINE) | Material | | | -30 | \$25.00 | (\$750.00) |
| | 0160 | CHANNELIZER (TRIM LINE) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user vegaj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | 30 | \$25.00 | \$750.00 |
| | 0170 | FLASHING ARROW PANEL | Material | | | -1 | \$2,500.00 | (\$2,500.00 |
| | 0170 | FLASHING ARROW PANEL | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user vegaj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | 1 | \$2,500.00 | \$2,500.00 |
| | 0180 | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | Material | | | -1 | \$3,995.00 | (\$3,995.00 |
| | 0180 | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user vegaj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | 1 | \$3,995.00 | \$3,995.00 |
| | 0190 | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED | Material | | | -500 | \$28.50 | (\$14,250.00 |
| | 0190 | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user vegaj1 overridding Payment Estimate Exception 12 on the current Payment Estimate. | 500 | \$28.50 | \$14,250.00 |
| | 0220 | SEPARATION GEOTEXTILE | Construction Stockpile | | Payment Estimate Item Adjustment generated Stockpile Transaction | | | (\$2,977.89 |
| | 0220 | SEPARATION GEOTEXTILE | Material | | | -4,000 | \$2.75 | (\$11,000.00 |
| | 0220 | SEPARATION GEOTEXTILE | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user vegaj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | 4,000 | \$2.75 | \$11,000.00 |
| | 0230 | MISC. | Construction Stockpile | | Payment Estimate Item Adjustment generated Stockpile Transaction | | | (\$5,585.78 |
| | 0230 | MISC. | Material | | | -4,300 | \$4.00 | (\$17,200.00 |
| | 0230 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user vegaj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. | 4,300 | \$4.00 | \$17,200.00 |
| | 0340 | SEEDING - COOL SEASON GRASSES | Material | | | -0.225 | \$1,750.00 | (\$393.75 |
| | 0340 | SEEDING - COOL SEASON GRASSES | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user vegaj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | 0.225 | \$1,750.00 | \$393.75 |

Revision 3/23/2023 Page 3 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 6, 2023

August 16, 2023 Original Contract
Amount
September 1, Net Change Order
Amount
Current Contract
Amount **Progress Estimate Pay Period** \$2,143,392.55 Contract ID 230519-C10 Number Start Pay Period End Prime Leavenworth Excavating & Equipment 3 \$26,775.00 Contractor Company, Inc. \$2,170,167.55 Amount

| Number No. Type Adjustment Type Adjustment Type Adjustment Type Adjustment Type Adjustment Type Adjustment Olife Price Adjustment Olife Price Olife | | | | | | | | | |
|--|---------|------|--------------------|----------|------------|---|------|------------|-------------------|
| SEDIMENT TRAP ROCK | | | Item Description | | Adjustment | Comments | | Adjustment | Adjustment amount |
| Benerated Material Payment Estimate Item Adjustment (0016) to user vegaj 1 overridding Payment Estimate. -15 \$82.00 \$1,230 | JKU0005 | 0350 | SEDIMENT TRAP ROCK | Material | | | -1 | \$360.00 | (\$360.00) |
| This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (D017) due to user vegal overridding Payment Estimate Exception 18 | | 0350 | SEDIMENT TRAP ROCK | Material | | generated Material Payment Estimate Item Adjustment (0016) due to user vegaj1 overridding Payment Estimate Exception 17 | 1 | \$360.00 | \$360.00 |
| generated Material Payment Estimate Item Adjustment (policy) due to user vegal overridding Payment Estimate Exception 18 on the current Payment Estimate. -100 \$1.65 \$165 | | 0360 | ROCK DITCH CHECK | Material | | | -15 | \$82.00 | (\$1,230.00) |
| District of the content of the con | | 0360 | ROCK DITCH CHECK | Material | | generated Material Payment Estimate Item Adjustment (0017) due to user vegaj1 overridding Payment Estimate Exception 18 | 15 | \$82.00 | \$1,230.00 |
| generated Material Payment Estimate Item Adjustment (2018) due to user vegaj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. 0410 MGS GUARDRAIL Construction Stockpile Payment Estimate Item Adjustment generated Stockpile Transaction 0410 MGS GUARDRAIL Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vegaj1 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vegaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on Stockpile Transaction 0420 MGS HEIGHT AND BLOCK TRANSITION Stockpile Payment Estimate Item Adjustment generated Stockpile Transaction 0430 MGS END ANCHOR Construction Stockpile Payment Estimate Item Adjustment generated Stockpile Transaction 5001 IMPACT ATTENUATOR 70 Material ARRAY) Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment User vegaj1 overridding Payment Estimate Item Adjustment User vegaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate. | | 0390 | SILT FENCE | Material | | | -100 | \$1.65 | (\$165.00) |
| Stockpile Stockpile Stockpile Transaction | | 0390 | SILT FENCE | Material | | generated Material Payment Estimate Item Adjustment (0018) due to user vegaj1 overridding Payment Estimate Exception 19 | 100 | \$1.65 | \$165.00 |
| MGS GUARDRAIL Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user vegaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. MGS HEIGHT AND BLOCK TRANSITION Stockpile Payment Estimate Item Adjustment generated Stockpile Transaction MGS END ANCHOR Construction Stockpile Payment Estimate Item Adjustment generated Stockpile Transaction MGS END ANCHOR Stockpile Payment Estimate Item Adjustment generated Stockpile Transaction MPH (SAND BARREL ARRAY) Material Material This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user vegaj1 overridding Payment Estimate Item Adjustment (0023) due to user vegaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | 0410 | MGS GUARDRAIL | | | | | | (\$4,641.71) |
| generated Material Payment Estimate Item Adjustment (0020) due to user vegaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 0420 MGS HEIGHT AND BLOCK TRANSITION Stockpile Payment Estimate Item Adjustment generated Stockpile Transaction 0430 MGS END ANCHOR Construction Stockpile Payment Estimate Item Adjustment generated Stockpile Transaction 10430 MGS END ANCHOR Construction Stockpile Payment Estimate Item Adjustment generated Stockpile Transaction 10430 MGS END ANCHOR Stockpile Transaction 10430 MGS END ANCHOR This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user vegaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | 0410 | MGS GUARDRAIL | Material | | | -275 | \$27.50 | (\$7,562.50) |
| TRANSITION Stockpile Stockpile Transaction MGS END ANCHOR Construction Stockpile MHACT ATTENUATOR 70 Material ARRAY) MPH (SAND BARREL ARRAY) MIMPACT ATTENUATOR 70 Material ARRAY) MATERIAL ARRAY) Material Stockpile Transaction Material Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vegaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | 0410 | MGS GUARDRAIL | Material | | generated Material Payment Estimate Item Adjustment (0020) due to user vegaj1 overridding Payment Estimate Exception 2 on | 275 | \$27.50 | \$7,562.50 |
| Stockpile Stockpile Stockpile Transaction 5001 IMPACT ATTENUATOR 70 Material ARRAY) 5001 IMPACT ATTENUATOR 70 Material ARRAY) 5001 IMPACT ATTENUATOR 70 Material ARRAY) Material Stockpile Transaction -1 \$5,250.00 (\$5,250 OF CARRAY) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vegaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | 0420 | | | | | | | (\$560.00) |
| MPH (SAND BARREL ARRAY) 5001 IMPACT ATTENUATOR 70 Material Generated Material Payment Estimate Item Adjustment (0023) due to user vegaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | 0430 | MGS END ANCHOR | | | | | | (\$860.00) |
| MPH (SAND BARREL ARRAY) Generated Material Payment Estimate Item Adjustment (0023) due to user vegaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | 5001 | MPH (SAND BARREL | Material | | | -1 | \$5,250.00 | (\$5,250.00) |
| Total (\$14,156 | | 5001 | MPH (SAND BARREL | Material | | generated Material Payment Estimate Item Adjustment (0023) due to user vegaj1 overridding Payment Estimate Exception 7 on | 1 | \$5,250.00 | \$5,250.00 |
| | Total | | | | | | | | (\$14,156.48) |

Revision 3/23/2023 Page 4 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | (| Contract Project Information | | | | | | |
|-------------------|----------------------------|--|----------------|--------|---|--|---|--|--|--|--|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | | Location of Work | | | | | | |
| JKU0005 | I-435-1(335) | 5 Slide repairs, culvert extension, guardrail replacement | I-435, I-29 | PLATTE | on Southbound I-435 at 53rd St., on I-29 between MO 273 and Route U | | | | | | | |
| Totals by J | Job Numbers | | | | | | | | | | | |
| JKU0005 | Posted It | m Adjustment | s Gross Ite | m Pav | This Estimate \$256,838.70 (\$14,156.48) \$242,682.22 | Previous \$125,561.95 \$119,351.40 \$244,913.35 | To Date \$382,400.65 \$105,194.92 \$487,595.57 | | | | | |
| | Incentive Disincent | | Si COS ILC | uy | \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 | | | | | |

Revision 3/23/2023 Page 5 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period | | | |
|--|---|---------------|------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project JKU0005, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0005, Item 6061060, Project Item Line Number 1410, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0005, Item 6061060, Project Item Line Number 1410, Material Set 606106096, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is nsufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 6096020, Project Item Line Number 080, Material Set 609602096, Material 0609PDDL - Paved Drainage Material for Ditch Liner, Acceptance ction Generic 0609PDDL is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 6096030A, Project Item Line lumber 0090, Material Set 6096030A96, Material 0609PDDL - Paved Drainage Material for Ditch Liner, acceptance Action Generic 0609PDDL is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 6113010, Project Item Line Number 120, Material Set 611301096, Material 0611EPM - Embankment Protection Material, Acceptance Action Beneric 0611EPM is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 6122019, Project Item Line Number 001, Material Set 612201996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance ction Generic 0616TMTC is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 6161005, Project Item Line Number 150, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance ction Generic 0616TMTC is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 6161025, Project Item Line Number 160, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance ction Generic 0616TMTC is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0005, Item 6161040, Project Item Line Number 170, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance action Generic 0616TMTC is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 6161098A, Project Item Line lumber 0180, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, cceptance Action Generic 0616TMTC is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 6173600D, Project Item Line lumber 0190, Material Set 6173600D96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, cceptance Action Generic 0617TCRCTF is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project JKU0005, Item 6240104A, Project Item Line Jumber 0220, Material Set 6240104A96, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 6249905, Project Item Line Number 230, Material Set 624990596, Material 3099XX - See Remarks for Description of Material, Acceptance ction Generic 3099XX is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 8051000A, Project Item Line lumber 0340, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 8051000A, Project Item Line lumber 0340, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 8061004, Project Item Line Number 350, Material Set 806100496, Material 0806TEC - Temporary Erosion Control, Acceptance Action Seneric 0806TEC is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 8061005, Project Item Line Number 360, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action seneric 0806TEC is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |
| stimate Exception Type: Insufficient Materials: Project JKU0005, Item 8061019, Project Item Line Number 330, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), acceptance Action Generic 1011GXT2 is insufficient. | Working with contractor/materials to get these exceptions cleared. Need to submit sample records. | vegaj1 | Overridden |

Revision 3/23/2023 Page 6 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | eport Generated date and can differ from the posted amo Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|---------------------------|--------------|--|
| 230519-C10 | JKU0005 | 0001 | 0010 | 2013000 | CLEARING AND GRUBBING | 3.00 | 0.00 | 3.00 | ACRE | 0.89 | \$30,000.00 | \$26,700.00 |
| | | 0001 | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 0.40 | \$78,200.00 | \$31,280.00 |
| | | 0001 | 0030 | 2031000 | CLASS A EXCAVATION | 64,624.00 | 0.00 | 64,624.00 | CUYD | 7,576.46 | \$5.00 | \$37,882.30 |
| | | 0001 | 0040 | 2035500 | EMBANKMENT IN PLACE | 34,545.00 | 0.00 | 34,545.00 | CUYD | 1,300.00 | \$10.00 | \$13,000.00 |
| | | 0001 | 0050 | 2063000 | CLASS 3 EXCAVATION | 84.00 | 0.00 | 84.00 | CUYD | 0.00 | \$60.00 | \$0.00 |
| | | 0001 | 0060 | 6044011 | PIPE COLLAR, TYPE A | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$2,100.00 | \$0.00 |
| | | 0001 | 0070 | 6054020 | OUTLET PIPES AND SPLASH PADS | 10.00 | 0.00 | 10.00 | EA | 0.00 | \$250.00 | \$0.00 |
| | | 0001 | 0080 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 945.00 | 0.00 | 945.00 | CUYD | 75.00 | \$50.00 | \$3,750.00 |
| | | 0001 | 0090 | 6096030A | FURNISHING TYPE 3 ROCK DITCH LINER | 135.00 | 0.00 | 135.00 | CUYD | 20.00 | \$63.00 | \$1,260.00 |
| | | 0001 | 0100 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | 945.00 | 0.00 | 945.00 | CUYD | 75.00 | \$14.00 | \$1,050.00 |
| | | 0001 | 0110 | 6096043 | PLACING TYPE 3 ROCK DITCH LINER | 135.00 | 0.00 | 135.00 | CUYD | 20.00 | \$45.00 | \$900.00 |
| | | 0001 | 0120 | 6113010 | FURNISHING TYPE 1 ROCK BLANKET | 9,291.00 | 0.00 | 9,291.00 | CUYD | 1,488.90 | \$51.00 | \$75,933.90 |
| | | 0001 | 0130 | 6113030 | PLACING TYPE 1 ROCK BLANKET | 9,291.00 | 0.00 | 9,291.00 | CUYD | 1,488.90 | \$12.00 | \$17,866.80 |
| | | 0001 | 0140 | 6123000A | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$2,500.00 | \$0.00 |
| | | 0001 | 0150 | 6161005 | CONSTRUCTION SIGNS | 286.00 | 0.00 | 286.00 | SQFT | 222.00 | \$12.00 | \$2,664.00 |
| | | 0001 | 0160 | 6161025 | CHANNELIZER (TRIM LINE) | 50.00 | 0.00 | 50.00 | EA | 30.00 | \$25.00 | \$750.00 |
| | | 0001 | 0170 | 6161040 | FLASHING ARROW PANEL | 2.00 | 0.00 | 2.00 | EA | 1.00 | \$2,500.00 | \$2,500.00 |
| | | 0001 | 0180 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$3,995.00 | \$3,995.00 |
| | | 0001 | 0190 | 6173600D | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED | 500.00 | 0.00 | 500.00 | LF | 500.00 | \$28.50 | \$14,250.00 |
| | | 0001 | 0200 | 6175010A | RELOCATING TEMPORARY TRAFFIC BARRIER | 1,500.00 | 0.00 | 1,500.00 | LF | 500.00 | \$18.00 | \$9,000.00 |
| | | 0001 | 0210 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 0.50 | \$170,000.00 | \$85,000.00 |
| | | 0001 | 0220 | 6240104A | SEPARATION GEOTEXTILE | 18,247.00 | 0.00 | 18,247.00 | SQYD | 4,000.00 | \$2.75 | \$11,000.00 |
| | | 0001 | 0230 | 6249905 | MISC.GEOSYNTHETIC REINFORCEMENT | 40,197.10 | 0.00 | 40,197.10 | SQYD | 4,300.00 | \$4.00 | \$17,200.00 |
| | | 0001 | 0240 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 0.40 | \$9,600.00 | \$3,840.00 |
| | | 0001 | 0250 | 7034041 | CLASS B-1 CONCRETE (CULVERTS) | 22.90 | 0.00 | 22.90 | CUYD | 0.00 | \$2,000.00 | \$0.00 |
| | | 0001 | 0260 | 7061030 | REINFORCING STEEL (CULVERTS) | 2,980.00 | 0.00 | 2,980.00 | LB | 0.00 | \$1.00 | \$0.00 |
| | | 0001 | 0270 | 7250318A | 18 IN. PIPE GROUP B | 18.00 | 0.00 | 18.00 | LF | 0.00 | \$125.00 | \$0.00 |
| | | 0001 | 0280 | 7250330A | 30 IN. PIPE GROUP B | 46.00 | 0.00 | 46.00 | LF | 0.00 | \$140.00 | \$0.00 |
| | | 0001 | 0290 | 7250336A | 36 IN. PIPE GROUP B | 13.00 | 0.00 | 13.00 | LF | 0.00 | \$200.00 | \$0.00 |
| | | 0001 | 0300 | 7320018A | 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,600.00 | \$0.00 |
| | | 0001 | 0310 | 7320024A | 24 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,700.00 | \$0.00 |
| | | 0001 | 0320 | 7320030A | 30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,950.00 | \$0.00 |
| | | 0001 | 0330 | 7320036A | 36 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$2,300.00 | \$0.00 |
| | | 0001 | 0340 | 8051000A | SEEDING - COOL SEASON GRASSES | 3.10 | 0.00 | 3.10 | ACRE | 0.22 | \$1,750.00 | \$393.75 |
| | | 0001 | 0350 | 8061004 | SEDIMENT TRAP ROCK | 9.00 | 0.00 | 9.00 | CUYD | 1.00 | \$360.00 | \$360.00 |
| | | 0001 | 0360 | 8061005 | ROCK DITCH CHECK | 220.00 | 0.00 | 220.00 | LF | 15.00 | \$82.00 | \$1,230.00 |
| | | 0001 | 0370 | 8061006 | ALTERNATE DITCH CHECK | 515.00 | 0.00 | 515.00 | LF | 0.00 | \$7.90 | \$0.00 |
| | | 0001 | 0380 | 8061016 | SEDIMENT REMOVAL | 140.00 | 0.00 | 140.00 | CUYD | 0.00 | \$6.00 | \$0.00 |
| | | 0001 | 0390 | 8061019 | SILT FENCE | 400.00 | 0.00 | 400.00 | LF | 100.00 | \$1.65 | \$165.00 |
| | | 0001 | 0400 | 8064140 | TYPE 3B EROSION CONTROL BLANKET | 15,004.00 | 0.00 | 15,004.00 | SQYD | 1,089.00 | \$1.60 | \$1,742.40 |
| | | 0010 | 0410 | 6061060 | MGS GUARDRAIL | 1,738.00 | 0.00 | 1,738.00 | LF | 275.00 | \$27.50 | \$7,562.50 |
| | | 0010 | 0420 | 6061074 | MGS HEIGHT AND BLOCK TRANSITION | 7.00 | 0.00 | 7.00 | EA | 1.00 | \$900.00 | \$900.00 |
| | | 0010 | 0430 | 6061080 | MGS END ANCHOR | 3.00 | 0.00 | 3.00 | EA | 1.00 | \$1,300.00 | \$1,300.00 |
| | | 0001 | 5001 | 6122019 | IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY) | 0.00 | 1.00 | 1.00 | EA | 1.00 | \$5,250.00 | \$5,250.00 |

Page 7 of 15 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|-------------|-------------|--------------|----------------------------------|-----------------|------------------------|------------------------------|------|------------------------------------|------------|--|
| 230519-C10 | JKU0005 | 0001 | 5002 | 6122020 | REPLACEMENT SAND BARREL | 0.00 | 10.00 | 10.00 | EA | 0.00 | \$1,050.00 | \$0.00 |
| | | 0001 | 5003 | 6122030 | IMPACT ATTENUATOR (RELOCATION) | 0.00 | 3.00 | 3.00 | EA | 1.00 | \$3,675.00 | \$3,675.00 |
| | Project J | (U0005 - To | tal Value | Posted to D | Date as of Report Generated Date | | | | | | | \$382,400.65 |
| 230519-C10 Ove | rall - Total | Value Post | ed to Dat | e as of Repo | ort Generated Date | | | | | | | \$382,400.65 |

Page 8 of 15 Revision 3/23/2023



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: JKU0005

| Line Number Code Description Date Date | nments |
|---|--------|
| Mile 0.133 Mile 0.15 Mile 0.16 Mile 0.18 Mile 0.18 | |
| Mile | |
| Silde repair located at mile marker (25.3. Mile 98.34 | |
| Mile 98.345 93.368 Mile 98.345 93.368 | |
| Mile 98.35 98.352 | |
| Mile 98.345 98.368 | |
| Mile Mile 98.35 98.352 | |
| | |
| 98.349 98.359 | |
| 0130 6113030 PLACING TYPE 1 ROCK BLANKET 9/1/23 9/5/23 1,001.75 CUYD Slide repair located at mile marker (MM) 25.8 Log Mile 98.349 9.3.59 | |
| 0200 6175010A RELOCATING TEMPORARY TRAFFIC BARRIER 9/1/23 9/5/23 500.00 LF Slide repair located mile marker 25.3 Log Mile Mile 0.086 0.142 | |
| 0210 6181000 MOBILIZATION 8/31/23 9/6/23 0.50 LS The slide repair located at mile marker (MM) 25.8. Also, Mile Mile Mile 0.099 to Log Mile 0.149. 98.336 98.357 | |
| 0220 6240104A SEPARATION GEOTEXTILE 9/1/23 9/5/23 2,250.00 SQYD Slide repair located at mile marker (MM) 25.8 Also, the slide repair located at mile marker (MM) 25.3 from log Mile Mile mile 0.133 to log mile 0.15.3 to log mile 0.16.5 slide repair located at mile marker (MM) 25.3 from log 98.34 98.364 | |
| 0230 6249905 MISC. GEOTEXTILE 9/1/23 9/5/23 3,600.00 SQYD Slide repair located at mile marker (MM) 25.8. Also, at the slide repair located at mile marker (MM) 25.3. Log Mile 98.34 98.364 | |
| 0240 6274000 CONTRACTOR FURNISHED SURVEYING AND STAKI 9/1/23 9/5/23 0.20 LS Slide repair located mile marker (MM) 25.3 Log Mile 0.038 0.141 | |
| 0340 8051000A SEEDING - COOL SEASON GRASSES 9/1/23 9/5/23 0.22 ACRE Slide repair located at mile marker (MM) 25.8 Log Mile 98.34 98.364 | |
| 0350 8061004 SEDIMENT TRAP ROCK 9/1/23 9/5/23 1.00 CUYD Slide repair located at mile marker (MM) 25.8 Log Mile 98.34 98.364 | |
| 0360 8061005 ROCK DITCH CHECK 9/1/23 9/5/23 15.00 LF Slide repair located at mile marker (MM) 25.8 Log Mile 98.34 98.364 | |
| 0390 8061019 SILT FENCE 9/1/23 9/5/23 100.00 LF Slide repair located at mile marker (MM) 25.8 Log Mile 98.34 98.364 | |
| 0400 8064140 TYPE 3B EROSION CONTROL BLANKET 9/1/23 9/5/23 1,089.00 SQYD Slide repair located at mile marker (MM) 25.8 Log Mile 98.34 98.364 | |
| 0410 6061060 MGS GUARDRAIL 9/1/23 9/5/23 275.00 LF Slide repair located at mile marker (MM) 25.8 Log Mile 98.334 98.373 | |
| 0420 6061074 MGS HEIGHT AND BLOCK TRANSITION 9/1/23 9/5/23 1.00 EA Slide repair located at mile marker 25.8 Log Mile 87.507 98.413 | |
| 0430 6061080 MGS END ANCHOR 9/1/23 9/5/23 1.00 EA Slide repair located mile marker (MM) 25.8 Log Mile 87.507 98.413 | |
| 5001 6122019 IMPACT ATTENUATOR 70 MPH (SAND BARREL 9/1/23 9/5/23 1.00 EA Initially installed at the slide repair located at mile marker 25.8 Initially installed at the slide repair located at mile marker 25.8 | |
| 5003 6122030 IMPACT ATTENUATOR (RELOCATION) 9/1/23 9/5/23 1.00 EA Relocated to the slide repair located at mile marker (MM) Log Mile 0.071 0.146 | |

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 9 of 15



| Majority Color C | | | | i | | | | | | | |
|---|---------|----------------|--------------|------------------|------------|---|----------------|----------|---------------|--|--|
| 2020 3 2020 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 3 2020 2020 2020 2020 2020 2020 2020 2020 2020 2020 20 | Project | Line | Description | | Adjustment | | | | Amount | Remarks | |
| Total | JKU0005 | 0030 | | Price FUEL | | 2 | | SYSTEM | \$197.82 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| | | | | | | 3 | | SYSTEM | \$468.90 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| Price FUEL - Total | | | | | - Total | | | | \$666.72 | | |
| | | | | Price FUEL - | | | | | | | |
| DATE PLACE | | 0020 | | | | | | | | | |
| PLACE | | | | | | • | | 0)/0==1/ | | | |
| 2023 3 Sep 6, SYSTEM \$13,000.00 This adjustment offsets the original system-generated Material Payment Edinate Image Ecopotion 1 on the current Payment Edinate Ecopotion 1 on the current Payment Edinate Image Ecopotion 1 on the current Payment Edinate Ecopotion 2 on the current Payment Edinate Ecopotion 1 on the current Payment Edinate Ecopotion 1 on the current Payment Edinate Ecopotion 2 on the current Payment Edinate Ecopotion 1 on the current P | | 0040 | | Material | | 2 | | SYSTEM | \$13,000.00 | Estimate Item Adjustment (0003) due to user vegaj1 overridding Payment | |
| 2023 Sep 6, SYSTEM \$13,000.000 | | | | | | 2 | | SYSTEM | (\$13,000.00) | | |
| Total | | | | | | 3 | | SYSTEM | \$13,000.00 | Estimate Item Adjustment (0002) due to user vegaj1 overridding Payment | |
| Material - Total | | | | | | 3 | | SYSTEM | (\$13,000.00) | | |
| Material - Total | | | | | - Total | | | | \$0.00 | | |
| Price FUEL | | | | Material - To | | | | | | | |
| Total S200.20 | | | | | iai – | 2 | Aug 16. | SYSTEM | | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| Price FUEL - Total | | | | | Total | | | | | , , , , , | |
| 1000 | | | | | | | | | | | |
| Name | | | | Price FUEL - | Total | | | | | | |
| ROCK DITCH LINER | | 0040 - | Total | | | | | | \$200.20 | | |
| Total S0.00 | | 0800 | ROCK DITCH | -1 | Material | | 3 | | SYSTEM | \$3,750.00 | Estimate Item Adjustment (0003) due to user vegaj1 overridding Payment |
| Material - Total S0.00 | | | | | | 3 | | SYSTEM | (\$3,750.00) | | |
| 1 | | | | | - Total | | | | \$0.00 | | |
| Sep 6, 2023 | | | | Material - Total | | | | | \$0.00 | | |
| 2023 Estimate Item Adjustment (0004) due to user vegaj1 overridding Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate. 3 | | 0080 - | Total | | | | | | \$0.00 | | |
| Total \$0.00 | | 0090 | TYPE 3 ROCK | Material | Material | | | SYSTEM | \$1,260.00 | Estimate Item Adjustment (0004) due to user vegaj1 overridding Payment | |
| Material - Total S0.00 | | | | | | 3 | | SYSTEM | (\$1,260.00) | | |
| Substitute Sub | | | | | | | | | \$0.00 | | |
| Sum | | | | Material Te | | | | | | | |
| PURNISHING TYPE 1 ROCK BLANKET Part of the part of | | 0000 | Total | material - 10 | .co. | | | | | | |
| BLANKET Aug 16, 2023 SYSTEM (\$24,844.65) 3 Sep 6, 2023 SYSTEM \$75,933.90 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. 3 Sep 6, 2023 SYSTEM \$75,933.90 Total | | | FURNISHING | Material | | 2 | | SYSTEM | | | |
| 3 Sep 6, 2023 SYSTEM \$75,933.90 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vegaj1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 Sep 6, 2023 SYSTEM (\$75,933.90) - Total | | | | | | 2 | | SYSTEM | (\$24,844.65) | | |
| 2023 Estimate Item Adjustment (0005) due to user vegaj1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 | | | | | | | 2023 | | , | | |
| Total So.00 Material - Total \$0.00 0120 - Total \$0.00 CONSTRUCTION SIGNS Material 1 Aug 2, 2023 SYSTEM \$2,664.00 1 Aug 2, 2023 SYSTEM (\$2,664.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 1 Aug 2, 2023 2 Aug 16, SYSTEM \$2,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vegaj1 overridding Payment | | | | | | 3 | | SYSTEM | \$75,933.90 | Estimate Item Adjustment (0005) due to user vegaj1 overridding Payment | |
| Material - Total \$0.00 | | | | | | 3 | | SYSTEM | (\$75,933.90) | | |
| Solid Construction Signs Material 1 Aug 2, 2023 System \$2,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 1 Aug 2, 2023 System \$2,664.00 This adjustment offsets the original system-generated Material Payment 2023 System \$2,664.00 This adjustment offsets the original system-generated Material Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user | | | | | - Total | | | | \$0.00 | | |
| Solid Construction Signs Material 1 Aug 2, 2023 System \$2,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 1 Aug 2, 2023 System \$2,664.00 This adjustment offsets the original system-generated Material Payment 2023 System \$2,664.00 This adjustment offsets the original system-generated Material Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user yegaj1 overridding Payment Stimate Item Adjustment (0005) due to user | | | | Material - To | tal | | | | \$0.00 | | |
| O150 CONSTRUCTION SIGNS Material 1 Aug 2, 2023 SYSTEM \$2,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 1 Aug 2, 2023 SYSTEM \$2,664.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 1 Aug 2, 2023 SYSTEM \$2,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vegaj1 overridding Payment | | 01 <u>20</u> - | Total | | | | | | \$0.00 | | |
| 1 Aug 2, 2023 2 Aug 16, 2023 2 Aug 16, 2023 3 SYSTEM \$2,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vegaj1 overridding Payment | | | CONSTRUCTION | Material | | 1 | | SYSTEM | | Estimate Item Adjustment (0001) due to user yostj1 overridding Payment | |
| 2 Aug 16, SYSTEM \$2,664.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vegaj1 overridding Payment | | | | | | 1 | Aug 2, 2023 | SYSTEM | (\$2,664.00) | | |
| | | | | | | 2 | Aug 16, | SYSTEM | \$2,664.00 | Estimate Item Adjustment (0005) due to user vegaj1 overridding Payment | |



| roject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | |
|--------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|-------------------------------|--|----------------|------------|---|--|
| U0005 | 0150 | CONSTRUCTION SIGNS | Material | | 2 | Aug 16, 2023 | SYSTEM | (\$2,664.00) | | | | | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | \$2,664.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vegaj1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$2,664.00) | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | |
| | 0150 - | · Total | | | | | | \$0.00 | | | | | |
| | 0160 | CHANNELIZER (TRIM LINE) | Material | | 1 | Aug 2, 2023 | SYSTEM | \$750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | |
| | | | | | 1 | Aug 2, 2023 | SYSTEM | (\$750.00) | | | | | |
| | | | | | 2 | Aug 16, 2023 | SYSTEM | \$750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vegaj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | |
| | | | | | 2 | Aug 16, 2023 | SYSTEM | (\$750.00) | | | | | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | \$750.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vegaj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$750.00) | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | |
| | 0160 - | · Total | | | | | | \$0.00 | | | | | |
| | 0170 | D FLASHING ARROW PANEL | Material | | 1 | Aug 2, 2023 | SYSTEM | \$2,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | | |
| | | | | | | | | | 1 | Aug 2, 2023 | SYSTEM | (\$2,500.00) | |
| | | | | | | | | 2 | Aug 16, 2023 | SYSTEM | \$2,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vegaj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | |
| | | | | | | | 2 | Aug 16, 2023 | SYSTEM | (\$2,500.00) | | | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | \$2,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vegaj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$2,500.00) | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | |
| | 0170 - | · Total | | | | | | \$0.00 | | | | | |
| | 0180 | CMS W/O COMMUNICATION INTERFACE, | Material | | 1 | Aug 2, 2023 | SYSTEM | \$3,995.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | |
| | | CONT F/ | | | 1 | Aug 2, 2023 | SYSTEM | (\$3,995.00) | | | | | |
| | | | | | 2 | Aug 16, 2023 | SYSTEM | \$3,995.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vegaj1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | | |
| | | | | | 2 | Aug 16, 2023 | SYSTEM | (\$3,995.00) | | | | | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | \$3,995.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vegaj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | | |
| | | | | : | | | | | | | | | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$3,995.00) | | | | | |
| | | | | - Total | 3 | | SYSTEM | (\$3,995.00) \$0.00 | | | | | |
| | | | Material - To | | 3 | | SYSTEM | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|---------|--------|--|-----------------------------------|-----------------------------|------------------|------------------------------------|-----------------|---|---|---|
| JKU0005 | 0190 | TEMPORARY TRAFFIC BARRIER, CONT. | Material | Туро | 1 | Aug 2, 2023 | SYSTEM | \$14,250.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | |
| | | FURN/RE | | | 1 | Aug 2, 2023 | SYSTEM | (\$14,250.00) | | |
| | | | | | 2 | Aug 16, 2023 | SYSTEM | \$14,250.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vegaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | |
| | | | | | 2 | Aug 16, 2023 | SYSTEM | (\$14,250.00) | | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | \$14,250.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vegaj1 overridding Payment Estimate Exception 12 on the current Payment Estimate. | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$14,250.00) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | tal | | | | \$0.00 | | |
| | 0190 - | · Total | | | | | | \$0.00 | | |
| | 0220 | SEPARATION GEOTEXTILE | Construction Stockpile | | 2 | Aug 16, 2023 | SYSTEM | (\$2,316.13) | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | Otockpiic | | 3 | Sep 6, 2023 | SYSTEM | (\$2,977.89) | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | | - Total | | | | (\$5,294.02) | | |
| | | | Construction | Stockpile - 1 | Γotal | | | (\$5,294.02) | | |
| | | | Construction Stockpile | | 2 | Aug 16, 2023 | SYSTEM | \$24,150.00 | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | STMI | - Total | | | | \$24,150.00 | | |
| | | | Construction | Stockpile S | ΓΜΙ - Tota | | | \$24,150.00 | | |
| | | | Material | Material | | 2 | Aug 16, 2023 | SYSTEM | \$4,812.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vegaj1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 2 | Aug 16, 2023 | SYSTEM | (\$4,812.50) | | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | \$11,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vegaj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$11,000.00) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | tal | | | | \$0.00 | | |
| | 0220 - | · Total | | | | | | \$18,855.98 | | |
| | 0230 | MISC. GEOTEXTILE | Construction Stockpile | | 2 | Aug 16, 2023 | SYSTEM | (\$1,086.12) | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$5,585.78) | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | | - Total | | | | (\$6,671.90) | | |
| | | | Construction | Stockpile - 1 | Total . | | | (\$6,671.90) | | |
| | | | Construction | | 2 | Aug 16, | SYSTEM | \$62,370.00 | Payment Estimate Item Adjustment generated Stockpile Transaction | |
| | | | Stockpile | | | 2023 | | | | |
| | | | | - Total | 2 | | | \$62,370.00 | | |
| | | | Stockpile | | | 2023 | | \$62,370.00 \$62,370.00 | | |
| | | | Stockpile STMI | | | 2023 | SYSTEM | | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user vegaj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | |
| | | | Stockpile STMI Construction | | ГМI - Tota | 2023 Aug 16, | SYSTEM | \$62,370.00 | Estimate Item Adjustment (0015) due to user vegaj1 overridding Payment | |
| | | | Stockpile STMI Construction | | ΓΜΙ - Total 2 | 2023 Aug 16, 2023 | | \$62,370.00 \$2,800.00 | Estimate Item Adjustment (0015) due to user vegaj1 overridding Payment | |
| | | | Stockpile STMI Construction | | FMI - Total 2 | Aug 16, 2023 Aug 16, 2023 Sep 6, | SYSTEM | \$62,370.00 \$2,800.00 (\$2,800.00) | Estimate Item Adjustment (0015) due to user vegaj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user vegaj1 overridding Payment | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-------------------------------------|-----------------------------------|-----------------------------|----------------|-----------------|---------------|---|--|
| JKU0005 | 0230 | MISC. GEOTEXTILE | Material - To | tal | | | | \$0.00 | |
| | 0230 - | Total | | | | | | \$55,698.10 | |
| | 0340 | SEEDING - COOL SEASON GRASSES | Material | | 3 | Sep 6, 2023 | SYSTEM | \$393.75 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user vegaj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$393.75) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0340 - | Total | | | | | | \$0.00 | |
| | 0350 | SEDIMENT TRAP ROCK | Material | | 3 | Sep 6, 2023 | SYSTEM | \$360.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user vegaj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$360.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0350 - | Total | | | | | | \$0.00 | |
| | 0360 | ROCK DITCH CHECK | Material | | 3 | Sep 6, 2023 | SYSTEM | \$1,230.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vegaj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$1,230.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0360 - | Total | | | | | | \$0.00 | |
| | 0390 | SILT FENCE | SILT FENCE Material | | 3 | Sep 6, 2023 | SYSTEM | \$165.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vegaj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$165.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0390 - | Total | | | | | | \$0.00 | |
| | 0410 | MGS GUARDRAIL | Construction Stockpile | | 3 | Sep 6, 2023 | SYSTEM | (\$4,641.71) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | (\$4,641.71) | |
| | | | Construction | Stockpile - 1 | | | | (\$4,641.71) | |
| | | | Construction Stockpile STMI | | 2 | Aug 16, 2023 | SYSTEM | \$29,335.63 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | Construction | - Total | TAU T | | | \$29,335.63 | |
| | | | Material | зоскрпе 3 | 3 | Sep 6, 2023 | SYSTEM | \$29,335.63 \$7,562.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vegaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$7,562.50) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | | | | | \$0.00 | |
| | 0410 - | · Total | | | | | | \$24,693.92 | |
| | 0420 | MGS HEIGHT AND BLOCK | Construction Stockpile | | 3 | Sep 6, 2023 | SYSTEM | (\$560.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | TRANSITION | | - Total | | | | (\$560.00) | |
| | | | Construction | Stockpile - 1 | Γotal | | | (\$560.00) | |
| | | | Construction Stockpile | | 2 | Aug 16, 2023 | SYSTEM | \$3,920.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | STMI | - Total | | | | \$3,920.00 | |
| | | | Construction | Stockpile S1 | ΓΜΙ - Total | | | \$3,920.00 | |
| | | | | | | | | | |





| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-------------|---------|---|---------------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| JKU0005 | 0420 - | Total | | | | | | \$3,360.00 | |
| | 0430 | MGS END ANCHOR | Construction Stockpile | | 3 | Sep 6, 2023 | SYSTEM | (\$860.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | (\$860.00) | |
| | | | Construction | Stockpile - 1 | Γotal | | | (\$860.00) | |
| | | | Construction Stockpile | | 2 | Aug 16, 2023 | SYSTEM | \$2,580.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | STMI | - Total | | | | \$2,580.00 | |
| | | | Construction | Stockpile S | TMI - Total | | | \$2,580.00 | |
| | 0430 - | Total | | | | | | \$1,720.00 | |
| | 5001 | IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY) | Material | Material | 3 | Sep 6, 2023 | SYSTEM | \$5,250.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vegaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 3 | Sep 6, 2023 | SYSTEM | (\$5,250.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 5001 - | Total | | | | | | \$0.00 | |
| JKU0005 | - Total | | | | | | | \$105,194.92 | |
| Overall - 1 | Total | | | | | | | \$105,194.92 | |

MoDOT

Contract Adjustments for Contract - 230519-C10

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 15 of 15