

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 2, 2023

Progress Estim 8	ate Number	Contract ID Prime Contractor	230519-F03 R. V. Wagner, Inc.		October 16, 2023 November 1, 2023		\$12,643,874.60 \$24,369.24 \$12,668,243.84
Approval Date							By User
November 2, 2023	ber 2, 2023 Generated and Approved (and should be considered Draft) at the Project						haungc1
November 2, 2023		Re	viewed and Approve	ed (and should be co	onsidered Draft) at	the Resident Engineer Level by	washas
November 3, 2023			Re	viewed and Approv	ed at the Central O	ffice Controllers Office Level by	ramses1
Original Compl	letion Date	Current Comp	oletion Date	Actual Completi	on Date	% of Current Contract Amou	int Complete
December 1	1, 2024	December	1, 2024			22.84%	
	044	Informational Date	_		Milantonas		

Contract Informational Dat	tes	Milestones
Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
June 7, 2023	June 7, 2023	
May 19, 2023	May 19, 2023	
July 10, 2023	July 10, 2023	
July 13, 2023	July 13, 2023	
	Original Completion Date  June 7, 2023  May 19, 2023  July 10, 2023	May 19, 2023 May 19, 2023 July 10, 2023 July 10, 2023

Contract Total Pay	For Estimate No. 8				
		This Estimate	Previous	To Date	
230519-F03					
	Total Posted Items Pay	\$118,102.57	\$2,774,824.34	\$2,892,926.91	
	Gross Item Adjustments	(\$41,642.53)	\$322,432.88	\$280,790.35	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$3,097,257.22	\$3,173,717.26	
<b>Contract Total Pay</b>	able This Estimate:	\$76,460.04			

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3540	0020	2022010	REMOVAL OF IMPROVEMENTS	LS	\$25,000.000	0.1	\$2,500.00
	0100	6169901	MISC.TRAFFIC CONTROL BRIDGE A8141	LS	\$29,000.000	0.3	\$8,700.00
	0130	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	EA	\$4,500.000	2	\$9,000.00
	0450	7040163	CONCRETE CRACK FILLER	SQYD	\$13.250	-4,133	(\$54,762.25)
	0470	7040163	CONCRETE CRACK FILLER	SQYD	\$13.250	6,110	\$80,957.50
Project Je	6 <mark>13540 - T</mark> o	tal					\$46,395.25
J6I3550	0510	2019919	MISC.VEGETATION REMOVAL AND TRIMMING	ACRE	\$13,800.000	0.05	\$690.00
	0520	2022010	REMOVAL OF IMPROVEMENTS	LS	\$144,300.000	0.225	\$32,467.50
	0530	2026040	BACKFILL	CUYD	\$230.000	1	\$230.00
	0560	2152000A	SHAPING SLOPES, CLASS II	100F	\$750.000	-168	(\$126,000.00)
	0570	2159910	MISC.SHAPING SLOPES, CLASS III (MODIFIED MATERIAL REQUIREMENTS)	100F	\$1,500.000	4	\$6,000.00
	0580	2169902	MISC.REMOVE LOOSE GROUT	EA	\$885.000	2	\$1,770.00
	0590	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$24.000	7	\$168.00
	0620	4136000	PCCP JOINT/CRACK SEALING	LF	\$15.400	74	\$1,139.60
	0660	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	CUYD	\$65.000	53.3	\$3,464.50
	0670	6096041	PLACING TYPE 1 ROCK DITCH LINER	CUYD	\$105.000	53.3	\$5,596.50
	0690	6099903	MISC.CONCRETE CURB	LF	\$168.000	16	\$2,688.00
	0720	6116010A	SLOPE PROTECTION	SQYD	\$120.000	93.6	\$11,232.00

Revision 3/23/2023 Page 1 of 21



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 2, 2023

Progre	ss Estima	te Number	Contract ID Prime Contractor	230519-F03 R. V. Wagner, Inc.	Pay Period Start Pay Period End	October 16, November		Original Contra Net Change Or Current Contra	der Amount	\$12,643,874.60 \$24,369.24 \$12,668,243.84	
Project Number	Line Number	Item Code		Item Descript	tion		Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J6I3550	0840	6169901	MISC.TRAFFIC CON	TROL BRIDGE A66	57		LS	\$46,000.000	0.025	\$1,150.00	
	0970	6169902	MISC.NTCIP COMPL (CONTRACTOR FUR				EA	\$4,500.000	4	\$18,000.00	
	0990	6178001	TRAFFIC BARRIER I	DELINEATOR, WHIT	ΓE		EA	\$46.000	16	\$736.00	
	1190	6240103A	PERMANENT EROS	ON CONTROL GEO	OTEXTILE		SQYD	\$5.000	103	\$515.00	
	1280	8051000A	SEEDING - COOL SE	ASON GRASSES			ACRE	\$5,400.000	0.7	\$3,780.00	
	1310	6061060	MGS GUARDRAIL				LF	\$31.000	775	\$24,025.00	
	1330	6061069	MGS BRIDGE APPRICURB)	OACH TRANSITION	SECTION (REGU	LAR/NO	EA	\$4,200.000	4	\$16,800.00	
	1350	6063014	TYPE A CRASHWOR	RTHY END TERMINA	AL (MASH)		EA	\$3,500.000	4	\$14,000.00	
	1540	7040104	HALF-SOLE REPAIR				SQFT	\$158.000	8.39	\$1,325.62	
	1570	7049903	MISC.BARRIER CUR	B REPAIR			LF	\$335.000	10	\$3,350.00	
	1580	7172054	OPEN CELL FOAM J	OINT SEAL			LF	\$130.000	256	\$33,280.00	
	1590	7173002	SILICONE EXPANSION	ON JOINT SEALAN	Т		LF	\$42.000	62	\$2,604.00	
	1910	7040113	CLEANING AND EPO	XY COATING			SQFT	\$10.800	157	\$1,695.60	

EΑ

\$1,100.000

10

\$11,000.00

\$71,707.32

\$118,102.57

Project J6l3550 - Total

Overall - Total

7123100 CLEANING AND COATING EXISTING BEARINGS

### Contract Adjustments This Estimate

1930

No Contract Adjustments Exist on Contract

		stments Exist on Contract tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3540	0130	MISC.	Overrun			-1	\$4,500.00	(\$4,500.00)
	0180	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-6,764	\$0.30	(\$2,029.20)
	0180	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user haungc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	6,764	\$0.30	\$2,029.20
	0190	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-3,404	\$0.30	(\$1,021.20)
	0190	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user haungc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	3,404	\$0.30	\$1,021.20
	0450	CONCRETE CRACK FILLER	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',13.25000 - 13.25000, 'is applied (if non-zero).	4,133	\$13.25	\$54,762.25
J6I3550	0560	SHAPING SLOPES, CLASS II	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',750.00000 - 750.00000, 'is applied (if non-zero).	2.3	\$750.00	\$1,725.00
	0590	TYPE 5 AGGREGATE FOR	Price		Reference Item Price Adjustment Index	7	\$0.11	\$0.80

Revision 3/23/2023 Page 2 of 21



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 2, 2023

Progress Estimate Number	Contract ID	230519-F03	Pay Period Start	October 16, 2023	Original Contract Amount	\$12,643,874.60
ο ο	Prime Contractor	R. V. Wagner, Inc.	Pay Period End	November 1, 2023	Net Change Order Amount	\$24,369.24
0					Current Contract Amount	\$12,668,243.84

	ne o.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
)		BASE (4 IN. THICK)		Type	Adjustment Type applied is FUEL		Office Price	
07	20	SLOPE PROTECTION	Material		, , , , ,	-330.8	\$120.00	(\$39,696.00
09	90	TRAFFIC BARRIER DELINEATOR, WHITE	Overrun			-2	\$46.00	(\$92.00
11	70	FLOWABLE BACKFILL	Material			-53	\$530.00	(\$28,090.00
12	80	SEEDING - COOL SEASON GRASSES	MaterialCredit			0.7	\$5,400.00	\$3,780.00
12	80	SEEDING - COOL SEASON GRASSES	Material			-1.4	\$5,400.00	(\$7,560.00
13	10	MGS GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$9,434.47
13	10	MGS GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$2,111.11
13	30	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$4,100.00
13	30	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$4,100.00
13	50	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$7,500.00
15	20	CLEANING AND EPOXY COATING	MaterialCredit			5	\$445.00	\$2,225.00
15	20	CLEANING AND EPOXY COATING	Material			-5	\$445.00	(\$2,225.00
15	20	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user haungc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	5	\$445.00	\$2,225.00
15	90	SILICONE EXPANSION JOINT SEALANT	Overrun			-6	\$42.00	(\$252.00
19	10	CLEANING AND EPOXY COATING	Material			-1,569	\$10.80	(\$16,945.20
19	10	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user haungc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	1,569	\$10.80	\$16,945.20
19	30	CLEANING AND COATING EXISTING BEARINGS	Material			-20	\$1,100.00	(\$22,000.00
19	30	CLEANING AND COATING EXISTING BEARINGS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	20	\$1,100.00	\$22,000.00
23	70	MISC.	MaterialCredit			1	\$3,300.00	\$3,300.00
23	70	MISC.	Material			-1	\$3,300.00	(\$3,300.00
23	70	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user haungc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	1	\$3,300.00	\$3,300.00

Revision 3/23/2023 Page 3 of 21



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J6I3540	NHPP 64-1(99)	8 Bridge rehabilitations	Various	ST LOUIS CITY	at various Locations w	at various Locations within St. Louis District					
J6I3550	NHPP 64-1(100)	25 Bridge rehabilitations and ADA	Various	ST CHARLES	at various locations in	St. Louis District					
Γotals by	Job Numbe	rs									
J6I3540		d Item Pay Item Adjustme	nts Gross It	em Pay	This Estimate \$46,395.25 \$50,262.25 <b>\$96,657.50</b>	Previous \$1,222,043.15 (\$54,922.25) \$1,167,120.90	To Date \$1,268,438.40 (\$4,660.00) \$1,263,778.40				
	Liquid	tive centive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J6I3550		d Item Pay Item Adjustme	nts Gross It	em Pay	This Estimate \$71,707.32 (\$91,904.78) (\$20,197.46)	Previous \$1,552,781.19 \$377,355.13 <b>\$1,930,136.32</b>	To Date \$1,624,488.51 \$285,450.35 <b>\$1,909,938.86</b>				
	Liquid	tive centive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 3/23/2023 Page 4 of 21



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

**Exceptions (Discrepancies) This Estimate Period** 

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3550, Item 6116010A, Project Item Line Number 0720, Material Set 6116010A96, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	past 28 day break	haungc1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J613540, Item 6205902A, Project Item Line Number 0180, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Certification received. awaiting entry	haungc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J613540, Item 6205902A, Project Item Line Number 0180, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Certification received. awaiting entry	haungc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J613540, Item 6205903A, Project Item Line Number 0190, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Certification received. awaiting entry	haungc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J613540, Item 6205903A, Project Item Line Number 0190, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Certification received. awaiting entry	haungc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3550, Item 6214600A, Project Item Line Number 1170, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient.	Past 28 day break	haungc1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6l3550, Item 7040113, Project Item Line Number 1520, Material Set 704011396, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Certification received. Inspector to associate sample with line item	haungc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3550, Item 7040113, Project Item Line Number 1910, Material Set 704011396, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Certification received. Inspector to associate sample with line item	haungc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3550, Item 7123100, Project Item Line Number 1930, Material Set 712310096, Material 1045PTOZ - High Solids Organic Zinc Paint, Acceptance Action Generic 1045PTOZ is insufficient.	Certification received. Inspector to associate sample with line item	haungc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J613550, Item 7123100, Project Item Line Number 1930, Material Set 712310096, Material 1045PTIZ - High Solids Inorganic Zinc Silicat Paint, Acceptance Action Generic 1045PTIZ is insufficient.	Certification received. Inspector to associate sample with line item	haungc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3550, Item 7129902, Project Item Line Number 2370, Material Set 7129902, Material 0712STDS - Drainage System on Structure, Acceptance Action Generic 0712STDS is insufficient.	Awaiting new line addition	haungc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J613550, Item 8051000A, Project Item Line Number 1280, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Awaiting certification from contractor	haungc1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J613550, Item 8051000A, Project Item Line Number 1280, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Awaiting certification from contractor	haungc1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230519-F03, Contract Project J6l3540, Project Item Line Number 0150, Contract Line Item Number 0150, Item 6178001, Minor Item.	Change order Forthcoming	haungc1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230519-F03, Contract Project J6I3550, Project Item Line Number 0990, Contract Line Item Number 0990, Item 6178001, Minor Item.	Change order Forthcoming	haungc1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230519-F03, Contract Project J6I3550, Project Item Line Number 1590, Contract Line Item Number 1590, Item 7173002, Minor Item.	Change order Forthcoming	haungc1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230519-F03, Contract Project J6I3540, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6169902, Minor Item.	Change order Forthcoming	haungc1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 230519-F03, Contract Project J6l3550, Project Item Line Number 1170, Contract Line Item Number 1170, Item 6214600A, Minor Item.	Change order Forthcoming	haungc1	Acknowledged

Revision 3/23/2023 Page 5 of 21



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230519-F03	J6I3540	0001	0010	2013000	CLEARING AND GRUBBING	2.00	0.00	2.00	ACRE	1.00	\$10,400.00	\$10,400.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.10	\$25,000.00	\$2,500.00
		0001	0030	2152000A	SHAPING SLOPES, CLASS II	36.00	0.00	36.00	100F	0.00	\$850.00	\$0.0
		0001	0040	2169902	MISC.REMOVE LOOSE GROUT	2.00	0.00	2.00	EA	0.00	\$950.00	\$0.0
		0001	0050	4011207	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	5.40	0.00	5.40	TONS	0.00	\$1,620.00	\$0.0
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	0.00	\$11,000.00	\$0.0
		0001	0070	6169901	MISC.TRAFFIC CONTROL BRIDGE A1501	1.00	0.00	1.00	LS	0.00	\$65,000.00	\$0.0
		0001	0080	6169901	MISC.TRAFFIC CONTROL BRIDGE A5584	1.00	0.00	1.00	LS	0.00	\$120,000.00	\$0.0
		0001	0090	6169901	MISC.TRAFFIC CONTROL BRIDGE A5585	1.00	0.00	1.00	LS	1.00	\$128,000.00	\$128,000.0
		0001	0100	6169901	MISC.TRAFFIC CONTROL BRIDGE A8141	1.00	0.00	1.00	LS	0.30	\$29,000.00	\$8,700.0
		0001	0110	6169901	MISC.TRAFFIC CONTROL BRIDGE L0815	1.00	0.00	1.00	LS	0.00	\$160,000.00	\$0.0
		0001	0120	6169901	MISC.TRAFFIC SIGNAL MAINTENANCE PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.0
		0001	0130	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	4.00	0.00	4.00	EA	5.00	\$4,500.00	\$22,500.0
		0001	0140	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	262.00	0.00	262.00	LF	0.00	\$200.00	\$0.0
		0001	0150	6178001	TRAFFIC BARRIER DELINEATOR, WHITE	170.00	0.00	170.00	EA	255.00	\$46.00	\$11,730.0
		0001	0160	6178002A	TRAFFIC BARRIER DELINEATOR, YELLOW	280.00	0.00	280.00	EA	280.00	\$54.00	\$15,120.0
		0001	0170	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$384,000.00	\$0.0
		0001	0171	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.25	\$328,675.00	\$82,168.7
		0001	0180	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	60,271.00	0.00	60,271.00	LF	6,764.00	\$0.30	\$2,029.2
		0001	0190	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	36,579.00	0.00	36,579.00	LF	3,404.00	\$0.30	\$1,021.2
		0001	0200	6206124A	MARKING PAINT, TYPE L BEADS  24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	1,383.00	0.00	1,383.00	LF	0.00	\$7.50	\$0.0
		0001	0210	6209902	PAINT, TYPE P BEADS  MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING,	3.00	0.00	3.00	EA	0.00	\$1,700.00	\$0.0
		0001	0220	6221001	LANE DROP ARROWS LT/RT  COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	45.00	0.00	45.00	SQYD	0.00	\$48.00	\$0.0
					SURFACING (3 IN. THICK OR LESS)							
		0001	0230	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1,000.00	\$0.0
		0001	0240	7040101	SUBSTRUCTURE REPAIR (FORMED)	18.00	0.00	18.00	SQFT	0.00	\$340.00	\$0.0
		0001	0250	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$6,500.00	\$0.0
		0001	0260	8025006	MULCHING	2.50	0.00	2.50	ACRE	0.00	\$3,000.00	\$0.0
		0001	0270	8051000A	SEEDING - COOL SEASON GRASSES	2.50	0.00	2.50	ACRE	0.00	\$3,000.00	\$0.0
		0010	0280	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$3,900.00	\$0.0
		0010	0290	6066640	GUARDRAIL DELINEATOR, WHITE	8.00	0.00	8.00	EA	0.00	\$22.00	\$0.0
		0010	0300	6066642	GUARDRAIL DELINEATOR, WHITE/RED	55.00	0.00	55.00	EA	0.00	\$27.00	\$0.0
		0010	0310	6066647A	GUARDRAIL DELINEATOR, YELLOW/RED	5.00	0.00	5.00	EA	0.00	\$27.00	\$0.0
		0050	0320	9109901	MISC.FIBER MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$1,600.00	\$0.0
		0050	0330	9109901	MISC.MODOT ITS ASSETS RELOCATION	1.00	0.00	1.00	LS	0.00	\$27,000.00	\$0.0
		0070	0340	7033013	PENETRATING CONCRETE SEALER	8,356.00	0.00	8,356.00	SY	0.00	\$7.60	\$0.0
		0070	0350	7040163	CONCRETE CRACK FILLER	15,684.00	0.00	15,684.00	SQYD	0.00	\$14.00	\$0.0
		0070	0360	7079902	MISC.Lighting Access Hole Covers	85.00	0.00	85.00	EA	0.00	\$440.00	\$0.0
		0071	0370	7033013	PENETRATING CONCRETE SEALER	8,356.00	0.00	8,356.00	SY	0.00	\$7.60	\$0.0
		0071	0380	7040163	CONCRETE CRACK FILLER	35,379.00	0.00	35,379.00	SQYD	0.00	\$14.00	\$0.0
		0071	0390	7079902	MISC.Lighting Access Hole Covers	22.00	0.00	22.00	EA	0.00	\$440.00	\$0.0
		0071	0400	6233000	EPOXY POLYMER WEARING SURFACE	26,570.00	0.00	26,570.00	SQYD	0.00	\$33.50	\$0.0
			0410	7040163	CONCRETE CRACK FILLER	588.00	0.00	588.00	SQYD	0.00	\$34.00	\$0.0
		0072	0410	7129901	MISC.Cleaning of Existing Drainage System	1.00	0.00	1.00	LS		\$34.00	\$0.0
		0072										
		0072	0430	7129902	MISC.Repairing Drain Connection	1.00	0.00	1.00	EA	0.00	\$9,300.00	\$0.0

Revision 3/23/2023 Page 6 of 21



### Total Paid / All Items / All Estimates (Including this Estimate)

Contract .CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
519-F03	J6I3540	0072	0440	7129903	MISC.Flushing Expansion Joint	173.00	0.00	173.00	LF	0.00	\$48.00	\$0.0
		0073	0450	7040163	CONCRETE CRACK FILLER	30,303.00	0.00	30,303.00	SQYD	30,303.00	\$13.25	\$401,514.
		0074	0460	7040163	CONCRETE CRACK FILLER	34,616.00	0.00	34,616.00	SQYD	33,696.00	\$13.25	\$446,472
		0075	0470	7040163	CONCRETE CRACK FILLER	15,660.00	0.00	15,660.00	SQYD	6,110.00	\$13.25	\$80,957.
		0076	0480	7040163	CONCRETE CRACK FILLER	29,512.00	0.00	29,512.00	SQYD	0.00	\$13.45	\$0
		0076	0490	7129901	MISC.Cleaning of Existing Drainage System	1.00	0.00	1.00	LS	0.00	\$210,000.00	\$0
		0001	5001	6189901	MISC.CONTRACT BOND PAYMENT	0.00	1.00	1.00	LS	1.00	\$55,325.00	\$55,325
	Project J	613540 - To	tal Value	Posted to D	ate as of Report Generated Date							\$1,268,438.
	J6I3550	0001	0500	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	0.10	\$8,500.00	\$850
		0001	0510	2019919	MISC.VEGETATION REMOVAL AND TRIMMING	1.80	0.00	1.80	ACRE	0.45	\$13,800.00	\$6,210
		0001	0520	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.42	\$144,300.00	\$61,327
		0001	0530	2026040	BACKFILL	12.00	0.00	12.00	CUYD	1.00	\$230.00	\$230
		0001	0540	2031000	CLASS A EXCAVATION	1,357.00	0.00	1,357.00	CUYD	1,317.00	\$170.00	\$223,890
		0001	0550	2036000	COMPACTING EMBANKMENT	100.00	0.00	100.00	CUYD	0.00	\$47.00	\$0
		0001	0560	2152000A	SHAPING SLOPES, CLASS II	192.00	0.00	192.00	100F	26.30	\$750.00	\$19,725
		0001	0570	2159910	MISC.SHAPING SLOPES, CLASS III (MODIFIED MATERIAL REQUIREMENTS)	19.00	0.00	19.00	100F	8.00	\$1,500.00	\$12,000
		0001	0580	2169902	MISC.REMOVE LOOSE GROUT	2.00	0.00	2.00	EA	2.00	\$885.00	\$1,770
		0001	0590	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	179.00	0.00	179.00	SQYD	7.00	\$24.00	\$168
		0001	0600	4011207	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	39.20	0.00	39.20	TONS	0.00	\$540.00	\$0
		0001	0610	4081027	PRIME-EMULSIFIED ASPHALT SS-1H	31.00	0.00	31.00	GAL	0.00	\$27.00	\$0
		0001	0620	4136000	PCCP JOINT/CRACK SEALING	6,374.00	0.00	6,374.00	LF	208.00	\$15.40	\$3,20
		0001	0630	6081010	CONCRETE CURB RAMP	12.00	0.00	12.00	SQYD	0.00	\$385.00	\$1
		0001	0640	6081012	TRUNCATED DOMES	40.00	0.00	40.00	SQFT	0.00	\$21.00	\$(
		0001	0650	6086004	CONCRETE SIDEWALK, 4 IN.	178.70	0.00	178.70	SQYD	0.00	\$163.00	\$1
		0001	0660	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	230.00	0.00	230.00	CUYD	116.30	\$65.00	\$7,55
		0001	0670	6096041	PLACING TYPE 1 ROCK DITCH LINER	230.00	0.00	230.00	CUYD	116.30	\$105.00	\$12,21
		0001	0680	6097000	ROCK LINING	12.00	0.00	12.00	CUYD	0.00	\$335.00	SI SI
		0001	0690	6099903	MISC.CONCRETE CURB	87.00	0.00	87.00	LF	16.00	\$168.00	\$2,688
		0001	0700	6113020	FURNISHING TYPE 2 ROCK BLANKET	1,315.00	0.00	1,315.00	CUYD	1,239.00	\$66.00	\$81,774
		0001	0710	6113040	PLACING TYPE 2 ROCK BLANKET	1,315.00	0.00	1,315.00	CUYD	1,239.00	\$121.00	\$149,919
		0001	0720	6116010A		391.00	0.00	391.00	SQYD	330.80	\$120.00	\$39,696
		0001	0730	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	0.00	\$11,000.00	\$0
		0001	0740	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	20.00	0.00	20.00	SQYD	0.00	\$378.00	\$(
					DEPTH PAVEMENT REPAIR							
		0001	0750	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	20.00	0.00	20.00	SQYD	0.00	\$8.00	\$1
		0001	0760	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	20.00	0.00	20.00	SQYD	0.00	\$12.00	\$1
		0001	0770	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	76.00	0.00	76.00	LF	0.00	\$6.50	\$1
		0001	0780	6169901	MISC.TRAFFIC CONTROL BRIDGE A4169	1.00	0.00	1.00	LS	0.50	\$34,000.00	\$17,00
		0001	0790	6169901	MISC.TRAFFIC CONTROL BRIDGE A5962	1.00	0.00	1.00	LS	0.50	\$59,000.00	\$29,500
		0001	0800	6169901	MISC.TRAFFIC CONTROL BRIDGE A5985	1.00	0.00	1.00	LS	0.50	\$40,000.00	\$20,00
		0001	0810	6169901	MISC.TRAFFIC CONTROL BRIDGE A6014/A6052	1.00	0.00	1.00	LS	0.00	\$83,000.00	\$1
		0001	0820	6169901	MISC.TRAFFIC CONTROL BRIDGE A6083/A6190	1.00	0.00	1.00	LS	0.00	\$91,000.00	\$
		0001	0830	6169901	MISC.TRAFFIC CONTROL BRIDGE A6475	1.00	0.00	1.00	LS	0.50	\$57,000.00	\$28,50
		0001	0840	6169901	MISC.TRAFFIC CONTROL BRIDGE A6657	1.00	0.00	1.00	LS	0.52	\$46,000.00	\$24,15
		0001	0850	6169901	MISC.TRAFFIC CONTROL BRIDGE A6752/A6753	1.00	0.00	1.00	LS	0.00	\$54,000.00	\$0
		0001	0860	6169901	MISC.TRAFFIC CONTROL BRIDGE A7046/A7122	1.00	0.00	1.00	LS	0.00	\$51,000.00	\$1

Revision 3/23/2023 Page 7 of 21



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
230519-F03	J6I3550	0001	0870	6169901	MISC.TRAFFIC CONTROL BRIDGE A7080/A7081	1.00	0.00	1.00	LS	0.00	\$23,000.00	\$0.00
		0001	0880	6169901	MISC.TRAFFIC CONTROL BRIDGE A7233	1.00	0.00	1.00	LS	0.00	\$34,000.00	\$0.00
		0001	0890	6169901	MISC.TRAFFIC CONTROL BRIDGE A7323	1.00	0.00	1.00	LS	0.50	\$49,000.00	\$24,500.0
		0001	0900	6169901	MISC.TRAFFIC CONTROL BRIDGE A8004/A8016	1.00	0.00	1.00	LS	0.00	\$33,000.00	\$0.0
		0001	0910	6169901	MISC.TRAFFIC CONTROL BRIDGE A8020	1.00	0.00	1.00	LS	0.00	\$28,000.00	\$0.0
		0001	0920	6169901	MISC.TRAFFIC CONTROL BRIDGE A8022	1.00	0.00	1.00	LS	0.00	\$15,000.00	\$0.0
		0001	0930	6169901	MISC.TRAFFIC CONTROL BRIDGE A8028/A8029	1.00	0.00	1.00	LS	0.00	\$25,000.00	\$0.0
		0001	0940	6169901	MISC.TRAFFIC CONTROL BRIDGE A8033	1.00	0.00	1.00	LS	0.00	\$25,000.00	\$0.0
		0001	0950	6169901	MISC.TRAFFIC CONTROL BRIDGE A8036	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.0
		0001	0960	6169901	MISC.TRAFFIC SIGNAL MAINTENANCE PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$43,000.00	\$0.0
		0001	0970	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	11.00	0.00	11.00	EA	4.00	\$4,500.00	\$18,000.0
		0001	0980	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	5.00	0.00	5.00	LF	0.00	\$670.00	\$0.0
		0001	0990	6178001	TRAFFIC BARRIER DELINEATOR, WHITE	14.00	0.00	14.00	EA	16.00	\$46.00	\$736.0
		0001	1000	6178004	TRAFFIC BARRIER DELINEATOR, WHITE/WHITE	10.00	0.00	10.00	EA	10.00	\$54.00	\$540.0
		0001	1010	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.20	\$904,000.00	\$180,800.0
		0001	1020	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	732.00	0.00	732.00	LF	0.00	\$27.00	\$0.0
		0001	1030	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	94.00	0.00	94.00	LF	0.00	\$27.00	\$0.0
		0001	1040	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	34.00	0.00	34.00	EA	0.00	\$324.00	\$0.0
		0001	1050	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	3.00	0.00	3.00	EA	0.00	\$270.00	\$0.0
		0001	1060	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	3.00	0.00	3.00	EA	0.00	\$540.00	\$0.0
		0001	1070	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	4.00	0.00	4.00	EA	0.00	\$540.00	\$0.0
		0001	1080	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	7.00	0.00	7.00	EA	0.00	\$60.00	\$0.0
		0001	1090	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	5,287.00	0.00	5,287.00	LF	0.00	\$1.10	\$0.0
		0001	1100	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,711.00	0.00	2,711.00	LF	0.00	\$1.10	\$0.0
		0001	1110	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	14,030.00	0.00	14,030.00	LF	0.00	\$1.10	\$0.0
		0001	1120	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	7,318.00	0.00	7,318.00	LF	0.00	\$1.10	\$0.0
		0001	1130	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	314.00	0.00	314.00	LF	0.00	\$6.50	\$0.0
		0001	1140	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	335.00	0.00	335.00	LF	0.00	\$6.50	\$0.0
		0001	1150	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, SYMBOL (BIKE)`	4.00	0.00	4.00	EA	0.00	\$540.00	\$0.0
		0001	1160	6209903	MISC.12 INCH WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	429.00	0.00	429.00	LF	0.00	\$11.00	\$0.0
		0001	1170	6214600A	FLOWABLE BACKFILL	20.00	0.00	20.00	CUYD	53.00	\$530.00	\$28,090.0
		0001	1180	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	312.00	0.00	312.00	SQYD	0.00	\$27.00	\$0.0
		0001	1190	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	2,382.00	0.00	2,382.00	SQYD	2,382.00	\$5.00	\$11,910.0
		0001	1200	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	86,400.00	0.00	86,400.00	LB	28,965.80	\$4.15	\$120,208.0
		0001	1210	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.20	\$15,000.00	\$3,000.0
		0001	1220	7040101	SUBSTRUCTURE REPAIR (FORMED)	18.00	0.00	18.00	SQFT	0.00	\$445.00	\$0.0
		0001	1230	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$4,300.00	\$0.0
		0001	1240	7172054	OPEN CELL FOAM JOINT SEAL	1,898.00	0.00	1,898.00	LF	432.00	\$130.00	\$56,160.0
		0001	1250	7173002	SILICONE EXPANSION JOINT SEALANT	605.00	0.00	605.00	LF	160.00	\$42.00	\$6,720.0
		0001	1260	7319902	MISC.REPLACE MANHOLE/INLET TOP	2.00	0.00	2.00	EA	0.00	\$2,300.00	\$0.0
		0001	1270	8025006	MULCHING	3.20	0.00	3.20	ACRE	0.00	\$5,400.00	\$0.0
		0001	1280	8051000A	SEEDING - COOL SEASON GRASSES	3.20	0.00	3.20	ACRE	1.40	\$5,400.00	\$7,560.0

Revision 3/23/2023 Page 8 of 21



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
30519-F03	J6I3550	0001	1290	8061005	ROCK DITCH CHECK	50.00	0.00	50.00	LF	0.00	\$19.50	\$0.0
		0001	1300	8061019	SILT FENCE	3,200.00	0.00	3,200.00	LF	800.00	\$9.00	\$7,200.0
		0010	1310	6061060	MGS GUARDRAIL	19,815.00	0.00	19,815.00	LF	1,925.00	\$31.00	\$59,675.0
		0010	1320	6061065	MGS GUARDRAIL, 6 FT. POSTS, 1 FT 6.75 IN. SPACING	200.00	0.00	200.00	LF	0.00	\$75.00	\$0.0
		0010	1330	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	30.00	0.00	30.00	EA	8.00	\$4,200.00	\$33,600.0
		0010	1340	6061080	MGS END ANCHOR	14.00	0.00	14.00	EA	0.00	\$1,600.00	\$0.0
		0010	1350	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	33.00	0.00	33.00	EA	8.00	\$3,500.00	\$28,000.0
		0020	1360	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	5.00	0.00	5.00	LF	0.00	\$48.60	\$0.0
		0020	1370	9014004	CONDUIT, 4 IN. RIGID, PUSHED	53.00	0.00	53.00	LF	0.00	\$54.00	\$0.0
		0020	1380	9014502	CONDUIT, 2 IN. RIGID, EXTERNAL ON STRUCTURE	586.00	0.00	586.00	LF	0.00	\$33.50	\$0.0
		0020	1390	9015010	TRENCHING TYPE I	560.00	0.00	560.00	LF	0.00	\$8.65	\$0.0
		0020	1400	9016110	PULL BOX, PREFORMED CLASS 1	3.00	0.00	3.00	EA	0.00	\$1,950.00	\$0.0
		0020	1410	9017008	CABLE, 8 AWG 1 CONDUCTOR	1,240.00	0.00	1,240.00	LF	0.00	\$1.10	\$0.0
		0020	1420	9017208	WIRE, 8 AWG, BARE NEUTRAL	620.00	0.00	620.00	LF	0.00	\$1.10	\$0.0
		0020	1430	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	590.00	0.00	590.00	LF	0.00	\$6.00	\$0.0
		0020	1440	9019902	MISC.LIGHT EMITTING DIODE WALL PACK	12.00	0.00	12.00	EA	0.00	\$720.00	\$0.0
		0030	1450	9028500	CABLE, LOOP DETECTOR, IN DUCT	3,350.00	0.00	3,350.00	LF	0.00	\$6.00	\$0.0
		0050	1460	9109901	MISC.FIBER MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$1,700.00	\$0.0
		0050	1470	9109903	MISC.MODOT ITS ASSETS RELOCATION	1,999.00	0.00	1,999.00	LF	0.00	\$19.45	\$0.
		0070	1480	2069901	MISC.DEWATERING	1.00	0.00	1.00	LS	0.00	\$6,500.00	\$0.
		0070	1490	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	594.00	0.00	594.00	SQYD	0.00	\$66.00	\$0.
		0070	1500	7029902	MISC.Pile Encasement	8.00	0.00	8.00	EA	8.00	\$8,270.00	\$66,160.
		0070	1510	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$158.00	\$0.
		0070	1520	7040113	CLEANING AND EPOXY COATING	5.00	0.00	5.00	SQFT	5.00	\$445.00	\$2,225.
		0071	1530	6233000	EPOXY POLYMER WEARING SURFACE	4,697.00	0.00	4,697.00	SQYD	0.00	\$41.00	\$0.
		0071	1540	7040104	HALF-SOLE REPAIR	75.00	0.00	75.00	SQFT	8.39	\$158.00	\$1,325.
		0071	1550	7040110	EPOXY PRESSURE INJECTING	250.00	0.00	250.00	LF	0.00	\$72.00	\$0.
		0071	1560	7040163	CONCRETE CRACK FILLER	711.00	0.00	711.00	SQYD	0.00	\$34.00	\$0.
		0071	1570	7049903	MISC.BARRIER CURB REPAIR	10.00	0.00	10.00	LF	10.00	\$335.00	\$3,350.
		0071	1580	7172054	OPEN CELL FOAM JOINT SEAL	264.00	0.00	264.00	LF	256.00	\$130.00	\$33,280.
		0071	1590	7173002	SILICONE EXPANSION JOINT SEALANT	56.00	0.00	56.00	LF	62.00	\$42.00	\$2,604.
		0072	1600	2069901	MISC.DEWATERING	1.00	0.00	1.00	LS	0.00	\$6,300.00	\$0.
		0072	1610	6233000	EPOXY POLYMER WEARING SURFACE	926.00	0.00	926.00	SQYD	0.00	\$47.80	\$0.
		0072	1620	7029902	MISC.Pile Encasement	18.00	0.00	18.00	EA	18.00	\$5,700.00	\$102,600.
		0072	1630	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$158.00	\$0.
		0072	1640	7040163	CONCRETE CRACK FILLER	253.00	0.00	253.00	SQYD	0.00	\$37.00	\$0.
		0072	1650	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC	1.00	0.00	1.00	LS	1.00	\$5,400.00	\$5,400.
			1000	7405004	PRIMER		0.00					
		0072	1660	7125961	GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	1.00	\$5,400.00	\$5,400.
		0072	1670	7173002	SILICONE EXPANSION JOINT SEALANT	49.00	0.00	49.00	LF	49.00	\$42.00	\$2,058.
		0073	1680	2169902	MISC.Removal of Raised Pavement Markers	20.00	0.00	20.00	EA	0.00	\$167.00	\$0.
		0073	1690	2169904	MISC.Pavement Patching	1.00	0.00	1.00	SQFT	0.00	\$325.00	\$0.
		0073	1700	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	3,336.00	0.00	3,336.00	SQYD	0.00	\$42.75	\$0.
		0073	1710	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$158.00	\$0.0
		0073	1720	7040163	CONCRETE CRACK FILLER	548.00	0.00	548.00	SQYD	0.00	\$35.00	\$0.0

Revision 3/23/2023 Page 9 of 21



### Total Paid / All Items / All Estimates (Including this Estimate)

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
0519-F03	J6I3550	0073	1730	7049901	MISC.CLEANING OF EXISTING DRAINAINAGE SYSTEM	1.00	0.00	1.00	LS	0.00	\$22,500.00	\$0.
		0074	1740	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	2,930.00	0.00	2,930.00	SQYD	0.00	\$44.50	\$0.
		0074	1750	7040163	CONCRETE CRACK FILLER	479.00	0.00	479.00	SQYD	0.00	\$31.60	\$0.
		0074	1760	7049901	MISC.CLEANING OF EXISTING DRAINAGE SYSTEM	1.00	0.00	1.00	LS	0.00	\$14,600.00	\$0.
		0074	1770	7049903	MISC.Barrier Curb Repair	25.00	0.00	25.00	LF	0.00	\$336.00	\$0.
		0075	1780	2169902	MISC.Removal of Raised Pavement Markers	12.00	0.00	12.00	EA	0.00	\$167.00	\$0.
		0075	1790	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	2,465.00	0.00	2,465.00	SQYD	0.00	\$43.00	\$0.
		0075	1800	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$158.00	\$0
		0075	1810	7040163	CONCRETE CRACK FILLER	410.00	0.00	410.00	SQYD	0.00	\$35.00	\$0
		0075	1820	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$12,000.00	\$0
		0075	1830	7173002	SILICONE EXPANSION JOINT SEALANT	41.00	0.00	41.00	LF	0.00	\$42.00	\$0
		0076	1840	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	2,807.00	0.00	2,807.00	SQYD	0.00	\$41.00	\$0
		0076	1850	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$158.00	\$0
		0076	1860	7040163	CONCRETE CRACK FILLER	468.00	0.00	468.00	SQYD	0.00	\$32.00	\$0
		0076	1870	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$12,000.00	\$0
		0076	1880	7173002	SILICONE EXPANSION JOINT SEALANT	41.00	0.00	41.00	LF	0.00	\$42.00	\$0
		0077	1890	6233000	EPOXY POLYMER WEARING SURFACE	1,057.00	0.00	1,057.00	SQYD	0.00	\$46.00	\$
		0077	1900	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$158.00	\$
		0077	1910	7040113	CLEANING AND EPOXY COATING	1,569.00	0.00	1,569.00	SQFT	1,569.00	\$10.80	\$16,94
		0077	1920	7040163	CONCRETE CRACK FILLER	222.00	0.00	222.00	SQYD	0.00	\$42.00	\$
		0077	1930	7123100	CLEANING AND COATING EXISTING BEARINGS	20.00	0.00	20.00	EA	20.00	\$1,100.00	\$22,000
		0077	1940	7173002	SILICONE EXPANSION JOINT SEALANT	80.00	0.00	80.00	LF	0.00	\$42.00	\$1
		0078	1950	2161503	REMOVAL OF EXISTING DECK REPAIR	25.00	0.00	25.00	SQFT	0.00	\$155.00	\$1
		0078	1960	6233000	EPOXY POLYMER WEARING SURFACE	1,155.00	0.00	1,155.00	SQYD	0.00	\$44.00	\$
		0078	1970	7040101	SUBSTRUCTURE REPAIR (FORMED)	5.00	0.00	5.00	SQFT	5.00	\$575.00	\$2,87
		0078	1980	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	5.00	0.00	5.00	SQFT	5.00	\$540.00	\$2,70
		0078	1990	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	2.00	\$158.00	\$31
		0078	2000	7040113	CLEANING AND EPOXY COATING	10.00	0.00	10.00	SQFT	0.00	\$540.00	\$
		0078	2010	7040163	CONCRETE CRACK FILLER	222.00	0.00	222.00	SQYD	0.00	\$41.00	\$
		0078	2020	7173002	SILICONE EXPANSION JOINT SEALANT	68.00	0.00	68.00	LF	0.00	\$42.00	\$
		0079	2030	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	1,481.00	0.00	1,481.00	SQYD	0.00	\$43.00	\$
		0079	2040	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$158.00	\$1
		0079	2050	7040113	CLEANING AND EPOXY COATING	1.00	0.00	1.00	SQFT	0.00	\$5,400.00	\$
		0079	2060	7040163	CONCRETE CRACK FILLER	331.00	0.00	331.00	SQYD	0.00	\$31.00	\$
		0079	2070	7173002	SILICONE EXPANSION JOINT SEALANT	31.00	0.00	31.00	LF	0.00	\$42.00	\$
		0080	2080	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	1,481.00	0.00	1,481.00	SQYD	0.00	\$43.00	\$
		0080	2090	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$158.00	\$
		0080	2100	7040163	CONCRETE CRACK FILLER	331.00	0.00	331.00	SQYD	0.00	\$31.00	\$
		0080	2110	7173002	SILICONE EXPANSION JOINT SEALANT	31.00	0.00	31.00	LF	0.00	\$42.00	\$
		0081	2120	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH	2,250.00	0.00	2,250.00	SQYD	0.00	\$45.00	\$
		0081	2130	7040163	HEALER SEALER CONCRETE CRACK FILLER	328.00	0.00	328.00	SQYD	0.00	\$36.00	\$
		0081	2140	7049903	MISC.Barrier Curb Repair	5.00	0.00	5.00	LF	0.00	\$336.00	\$
		0082	2150	6233000	EPOXY POLYMER WEARING SURFACE	1,130.00	0.00	1,130.00	SQYD	0.00	\$44.00	\$
		0082	2160	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	20.00	0.00	20.00	SQFT	0.00	\$540.00	\$I

Revision 3/23/2023 Page 10 of 21



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
19-F03	J6I3550	0082	2170	7040163	CONCRETE CRACK FILLER	862.00	0.00	862.00	SQYD	0.00	\$30.00	\$0
		0083	2180	6239905	MISC.EPOXY URETHANE POLYMER WEARING SURFACE WITH HEALER SEALER	1,030.00	0.00	1,030.00	SQYD	0.00	\$50.00	\$0
		0083	2190	7040163	CONCRETE CRACK FILLER	373.00	0.00	373.00	SQYD	0.00	\$33.00	\$0
		0083	2200	7172054	OPEN CELL FOAM JOINT SEAL	48.00	0.00	48.00	LF	0.00	\$130.00	\$0
		0084	2210	6233000	EPOXY POLYMER WEARING SURFACE	1,379.00	0.00	1,379.00	SQYD	0.00	\$44.00	\$0
		0084	2220	7040163	CONCRETE CRACK FILLER	324.00	0.00	324.00	SQYD	0.00	\$30.00	\$0
		0084	2230	7049901	MISC.CLEANING OF EXISTING DRAINAGE SYSTEM	1.00	0.00	1.00	LS	0.00	\$51,300.00	\$0
		0085	2240	2169904	MISC.PAVEMENT PATCHING	1.00	0.00	1.00	SQFT	0.00	\$325.00	\$0
		0085	2250	6233000	EPOXY POLYMER WEARING SURFACE	1,120.00	0.00	1,120.00	SQYD	0.00	\$44.00	\$0
		0085	2260	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$158.00	\$1
		0085	2270	7172054	OPEN CELL FOAM JOINT SEAL	90.00	0.00	90.00	LF	0.00	\$130.00	\$1
		0085	2280	7173002	SILICONE EXPANSION JOINT SEALANT	52.00	0.00	52.00	LF	52.00	\$42.00	\$2,18
		0086	2290	6233000	EPOXY POLYMER WEARING SURFACE	3,284.00	0.00	3,284.00	SQYD	0.00	\$39.00	\$
		0086	2300	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$158.00	\$
		0086	2310	7040110	EPOXY PRESSURE INJECTING	144.00	0.00	144.00	LF	0.00	\$75.00	\$
		0086	2320	7040113	CLEANING AND EPOXY COATING	233.00	0.00	233.00	SQFT	0.00	\$43.00	\$
		0086	2330	7040163	CONCRETE CRACK FILLER	372.00	0.00	372.00	SQYD	0.00	\$38.00	\$
		0086	2340	7049901	MISC.CLEANING OF EXISTING DRAINAGE SYSTEM	1.00	0.00	1.00	LS	0.00	\$29,700.00	\$
		0086	2350	7125101	SURFACE PREPARATION FOR OVERCOATING STRUCTURAL STEEL (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$34,500.00	\$
		0086	2360	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	0.00	1.00	LS	0.00	\$10,800.00	\$
		0086	2370	7129902	MISC.SLAB DRAIN EXTENSION	1.00	0.00	1.00	EA	1.00	\$3,300.00	\$3,30
		0086	2380	7173002	SILICONE EXPANSION JOINT SEALANT	100.00	0.00	100.00	LF	0.00	\$42.00	\$
		0087	2390	6233000	EPOXY POLYMER WEARING SURFACE	1,027.00	0.00	1,027.00	SQYD	0.00	\$46.00	\$
		0087	2400	7040163	CONCRETE CRACK FILLER	911.00	0.00	911.00	SQYD	0.00	\$29.00	5
		0088	2410	6233000	EPOXY POLYMER WEARING SURFACE	2,215.00	0.00	2,215.00	SQYD	0.00	\$41.00	5
		0088	2420	7040163	CONCRETE CRACK FILLER	343.00	0.00	343.00	SQYD	0.00	\$29.00	\$
		0089	2430	6233000	EPOXY POLYMER WEARING SURFACE	1,428.00	0.00	1,428.00	SQYD	0.00	\$65.00	\$
		0089	2440	7040163	CONCRETE CRACK FILLER	483.00	0.00	483.00	SQYD	0.00	\$39.00	\$
		0090	2450	6233000	EPOXY POLYMER WEARING SURFACE	1,033.00	0.00	1,033.00	SQYD	0.00	\$45.00	\$
		0090	2460	7040163	CONCRETE CRACK FILLER	256.00	0.00	256.00	SQYD	0.00	\$34.00	\$
		0091	2470	6233000	EPOXY POLYMER WEARING SURFACE	2,648.00	0.00	2,648.00	SQYD	0.00	\$38.00	\$
		0091	2480	7040163	CONCRETE CRACK FILLER	1,078.00	0.00	1,078.00	SQYD	0.00	\$26.00	\$
		0092	2490	6233000	EPOXY POLYMER WEARING SURFACE	613.00	0.00	613.00	SQYD	0.00	\$45.00	5
		0092	2500	7040163	CONCRETE CRACK FILLER	658.00	0.00	658.00	SQYD	0.00	\$25.00	5
		0093	2510	6233000	EPOXY POLYMER WEARING SURFACE	2,531.00	0.00	2,531.00	SQYD	0.00	\$42.00	5
		0093	2520	7040163	CONCRETE CRACK FILLER	1,132.00	0.00	1,132.00	SQYD	0.00	\$25.00	\$
		0094	2530	6233000	EPOXY POLYMER WEARING SURFACE	1,058.00	0.00	1,058.00	SQYD	0.00	\$58.00	\$
		0094	2540	7040163	CONCRETE CRACK FILLER	702.00	0.00	702.00	SQYD	0.00	\$25.00	\$
		0070	5101	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	0.00	1.00	1.00	LS	1.00	\$14,056.92	\$14,05
		0070	5102	7125961	GRAY EPOXY-MASTIC PRIMER	0.00	1.00	1.00	LS	1.00	\$6,638.00	\$6,63
		0070	5103	4136000	PCCP JOINT/CRACK SEALING	0.00	104.00	104.00	LF	0.00	\$35.33	\$
and the second		IOIOEEO T	tel Meles	Description 1	Date as of Report Generated Date							\$1,624,48

Revision 3/23/2023 Page 11 of 21



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6l3540

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2022010	REMOVAL OF IMPROVEMENTS	10/20/23	11/2/23	0.10	LS	Hwy N Bridge A7323 north side of bridge sidewalk removal					min excavator used rock hammer to break up walkway. Barricades used to block foot traffic.
0100	6169901	MISC.	10/30/23	11/1/23	0.10	LS	Hwy 47 southbound lane and shoulder, bridge A 8141					Tramar on site with automated flagman, signage, message boards, channelizers
			10/31/23	11/1/23	0.10	LS	southbound lane and shoulder of bridge A8141					two lanes are open. One southbound, one north bound. Channelizers were doubled. Message board messages changed, additional signage placed. men with stop paddles present. narrow lanes. speed a concern thru work zone. additional signage for lane shifts requested as well as covering the 40 mph zone signage.
			11/1/23	11/2/23	0.10	LS	J8(355) Bridge A 8141 southbound lane and shoulder closed					Tramar on site posted signage, cones, message boards, speed limit signs of 30 mph. 40 mph speed limit signs covered. traffic speed a concern, cones are knocked over and constantly monitored by Tramar. Tramar truck used to slow traffic down as they travel back and forth setting up cones. Trimline channelizer have been requested for tomorrow.
0130	6169902	MISC. TRAFFIC CONTROL DEVICES	11/1/23	11/2/23	2.00	EA	2 A8141	0		0		
0450	7040163	CONCRETE CRACK FILLER	10/16/23	11/2/23	-4,133.00	SQYD	Eastbound lane 3 A5852	N/A		N/A		
0470	7040163	CONCRETE CRACK FILLER	10/30/23	11/1/23	1,588.00	SQYD	A 8141 southbound lane and southbound shoulder, 1/2 of the bridge					Wagner on site with equipment. Bridge swept with skidloader w/broom, shot blasted, blasted with compressed air, then crack sealed.
			10/31/23				southbound lane and shoulder, Bridge A8141					JBISS40 Bridge AB141 Hwy 47 over the Missouri at Washington, MO 2 personnel on site. Traffic control set out beginning around 1000AM. Message board changed. Signage up. Cones doubled. However, traffic speed is a problem. Cones are being blown over and need trimines. Cones are being blown over and his characteristic swifting into work zones. Call to Brad and Nick at Wagner sout getting timines on site as well as reduced speed to 30 mph and covering up all 40 mph signage. Bride needs paddle stop signs at each end of bridge to slow traffic. No problem with traffic backing up at hospital or downtown areas. Wagner Construction 1 foreman, 1 operator, 1 driver/laborer, 4 laborers. Arrived around 1045. Deck swept, shot blasted, air compressor used on crassks, doet flooded with material and spread. Scupper were covered up to prevent material from flowing down below bridge. 2041 square yards; 175 gallons of material use; rate of application is 0.95 gal/100 sqf. 14 300 pounds of sand use; rate is 2.10 lbs/sy Tramar returned to site and monitored the work zone, making sure all the cones were properly set up and replacing those knocked out of the work zone or making sure all the cones were properly set up and replacing those knocked out of the work zone or channelizes will be brought out formorws. Spoke to Greg and Nick and advised that we needed reflective tabs placed on white and yellow string for delineation of the lanes of a night. Tabs were placed, took pictures.
			11/1/23	11/2/23	2,481.00	SQYD	Bridge A8141 south half of south bound lane and shoulder					Wagner construction swept, shotblasted, compressed air used on cracks, deck flooded. Shot blaster moved to ped bridge afterwards to prepare for crack sealing. Work began at the county line and progressed south to the end of bridge. Scuppers covered to project drainage down to the river bottom.  Reflective tabs placed after completion of crack sealing. Work began at 11 AM due to cold temperatures overnight. Finished at 300 PM

Project: J6l3550

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0510	2019919	MISC. MOWING	10/19/23	11/1/23	0.05	ACRE	NE, NW, SE, SW quadrants of bridge tree trimming					Cedar tree branches cut back enough to allow a person to walk down along the side of the bridge.
0520	2022010	REMOVAL OF IMPROVEMENTS	10/16/23	11/2/23	0.10	LS	Southeast quadrant A5962					Existing curb of 15 l.f. removed
			10/18/23	10/27/23	0.05	LS	West bound Hwy N over I-64					Concrete sidewalk broken up but not removed. Thick concrete with reinforced steel. Sidewalk closed and barricaded off to prevent people from using walkway.
			10/19/23	11/1/23	0.02	LS	Sidewalk on westbound Hwy N overpass of 64					Mini-excavator and rock hammer used to break up 6" concrete sidewalk
			10/30/23	11/1/23	0.02	LS	NW and SW quadrants of A7233	N/A		N/A		
			10/31/23	11/1/23	0.02	LS	NE and SE quadrants of A7233	N/A		N/A		
0530	2026040	BACKFILL	10/25/23	11/2/23	1.00	CUYD	A 5962 backfill on the slope protection slabs					Dirt excavated from the I-64 roadside ditch and moved to the slope protection slabs and backfilled.
0560	2152000A	SHAPING SLOPES, CLASS II	10/16/23	11/2/23	-170.00	100F	A5962 NW and SW quadrants	N/A		N/A		Quantity changed by CMH due to error made by Mike Yerion on 10/13/23
				11/2/23	2.00	100F	A5962 NW and SW quadrants	N/A		N/A		Quantity changed by CMH due to error made by Mike Yerion on 10/13/23
0570	2159910	MISC. SHAPING SLOPES	11/1/23	11/2/23	4.00	100F	NE quadrant, NW quadrant, SE quadrant, and SW quadrant of A7233	N/A		N/A		
0580	2169902	MISC. REMOVALS	10/20/23	11/2/23	2.00	EA		N/A		N/A		
0590	3040504	TYPE 5 AGGREGATE FOR BASE	11/1/23	11/2/23	7.00	SQYD	Sidewalk at east end of A7232	N/A		N/A		
0600	4011207	BIT. PAVEMENT MIXTURE PG70-22 (BP-1)	10/17/23	10/27/23	0.00	TONS	West bound hwy 94 bridge A 5985 approach slab					This is a repair to the existing pavement created by slab jacking contractor. No charge for MODoT.
0620	4136000	PCCP JOINT/CRACK SEALING	10/23/23	11/1/23	74.00	LF	A5962 NE, NW, SE,SW aprons at the quadrants of the bridge. Backer rod and silicone sealant used to seal joints where aprons had pulled away from the wing walls.					Joints sealed with backer rods and sealant. Pictures taken. Small cracks across the apron were also sealed to prevent water from undermining the apron.
0660	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	10/26/23	11/2/23	53.30	CUYD	Bridge A5962 under the east end of the bridge, along the east column of I-64					rock brought in and placed along the ditch paralleling I-64 and adjacent to the end east bridge columns.
0670	6096041	PLACING TYPE 1 ROCK DITCH LINER	10/26/23	11/2/23	53.30	CUYD	A 5962 under the east end of the bridge, along the east column of I-64					rock brought in and placed along the ditch paralleling I-64 and adjacent to the end east bridge columns.
0690	6099903	MISC. PAVED DRAINAGE	10/26/23	11/2/23	16.00	LF	southeast east quadrant of the bridge along pavement					curb repaired with concrete mix and finished. with rain predicted for the PM, concrete covered with plastic to prevent dimpling
0720	6116010A	SLOPE PROTECTION	10/23/23	11/1/23	93.60	SQYD	Slope protection poured under the A5962 bridge east end of bridge. Area is 45' X 8.5' and 46' X 10'					Cochran on site to provide quality control. Gonzalez on site to provide quality assurance. Concrete is from

Revision 3/23/2023 Page 12 of 21



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

0800	6169901							Log Mile	Log Mile	
										Kienstra, Cochran tested concrete at 5.2% air; Gonzalez tested concrete at 5.6%, slump is 2.5" with a temperature of 64 degrees.
0840		MISC.	10/17/23	10/27/23	0.00	LS	West bound Hwy 94 approach slab to A5985.			Traffic control provided for a repair to asphalt patch repair, caused during slab Jacking repair. No charge for MODoT as this is a repair due to a sub contractor.
	6169901	MISC.	10/18/23	10/27/23	0.02	LS	North bound Hwy DD at Dardenne Creek			Lane drop set up for Site Systems to seed/straw bridge site
0970	6169902	MISC. TRAFFIC CONTROL DEVICES	11/1/23	11/2/23	4.00	EA	2 A6752/A6753 2 A5962	0	0	
0990	6178001	TRAFFIC BARRIER DELINEATOR, WHITE	10/19/23	11/1/23	16.00	EA	on top of barrier walls north and south side of bridge			carpenter drilled holes and attached delineators near the locations of the old ones and added one each at the end of the barrier walls.
1190	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	10/26/23	11/2/23	103.00	SQYD	A5962 placed beneath ditch liner along I-64 parallel to 64, adjacent to columns, east end of bridge			placed beneath rock ditch liner, 180X8 sf. or 160 sq yds
1280	8051000A	SEEDING - COOL SEASON GRASSES	10/18/23	10/27/23	0.70	ACRE	DD at Dardenne Creek, east side of DD (A7233); Hwy Z at Dardenne creek (A 6475) placed along west side of Hwy Z. Note tack coat does not extend all the way down to creek as tall trees prevent spraying from water cannon.			Seed, straw, tack coat placed at DD; seed, straw placed along west side of road. tack coast stops 1/4 way down due to tall trees preventing water cannon from reaching straw.
1310	6061060	MGS GUARDRAIL	10/30/23	11/1/23	462.50	LF	87.5LF NW quadrant 375LF SW quadrant	N/A	N/A	
			10/31/23	11/1/23	212.50	LF	NE and SE quadrants of A7233	N/A	N/A	
			11/1/23	11/2/23	100.00	LF	SE quadrant of A7233	N/A	N/A	
1330	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	10/30/23	11/1/23	2.00	EA	1 NW quadrant 1 SW quadrant	N/A	N/A	
			10/31/23	11/1/23	2.00	EA	NE and SE quadrants of A7233	N/A	N/A	
1350	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	10/30/23	11/1/23	2.00	EA	1 NW quadrant 1 SW quadrant	N/A	N/A	
			10/31/23	11/1/23	1.00	EA	NE and SE quadrants of A7233	N/A	N/A	
			11/1/23	11/2/23	1.00	EA	SE quadrant of A7233	N/A	N/A	
1540	7040104	HALF-SOLE REPAIR	10/19/23	11/1/23	5.49	SQFT	West bound lanes, west end of bridge at expansion joints			Bad sections saw cut, cleaned out and repaired with approved materials
			10/20/23	11/2/23	1.80	SQFT	west bound DD lane 1, west end of bridge. Bridge A 5962			saw cut and filled with material. picture taken
			10/26/23	11/2/23	1.10	SQFT	A 5962 west end of bridge in shoulder of pavement			area cut out, and repaired with quick patch
1570	7049903	MISC.	10/25/23	11/2/23	10.00	LF	A 5962 concrete meidan barrier repair	N/A	N/A	Poured quick patch on median and around sign foundations that were cracked, broken and missing. took pictures
1580	7172054	OPEN CELL FOAM JOINT SEAL	10/16/23	11/2/23	100.00	LF	north and south approach slabs to bridge			1 foreman, 1 Operator, 3 laborers on site.
			10/18/23	10/27/23	42.00	LF	Eastbound DD, middle lane, north & south approach slabs, West bound, north approach slab, middle lane			1 foreman, 3 laborers removing and replacing cell foam with traffic control provided by Wagner. Eastbound lanes completed today.
			10/19/23	11/1/23	58.00	LF	west bound lanes			33 l.f. on the west end, north side of bridge, 25 l.f. on the east end, north side of bridge.
			10/20/23	11/2/23	56.00	LF	Bridge A 5962 West bound, Lanes 1 &2 (double left turn lanes), east end and west end of bridge			Joint cleaned out, material removed, material replaced and then sealed.
1590	7173002	SILICONE EXPANSION JOINT SEALANT	10/16/23	11/2/23	34.00	LF	Southeast and southwest quadrants			Removed the existing sealant and replaced with silicone expansion joint sealant
			10/19/23	11/1/23	14.00	LF	Southwest quadrant of bridge			Joint cleaned out with wire brush and sealant applied, then measured
			10/20/23	11/2/23	14.00	LF	northeast quadrant of A 5962			Joint cleaned out and silicone joint sealant added
1910	7040113	CLEANING AND EPOXY COATING	10/30/23	11/1/23	157.00	SQFT	A6475	N/A	N/A	Remainder of pay from completion.
1930	7123100	CLEANING AND COATING EXISTING BEARINGS	10/30/23	11/1/23	10.00	EA	A6475	N/A	N/A	Remainder of pay from completion.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 13 of 21



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
540	0130	MISC. TRAFFIC CONTROL	Overrun	Overrun	8	Nov 2, 2023	SYSTEM	(\$4,500.00)	
		DEVICES		Overrun - To	otal			(\$4,500.00)	
			Overrun - Tota	al				(\$4,500.00)	
	0130 -	Total						(\$4,500.00)	
	0150	TRAFFIC BARRIER DELINEATOR,	Overrun	Overrun	7	Oct 16, 2023	SYSTEM	(\$3,910.00)	
		WHITE		Overrun - T	otal			(\$3,910.00)	
			Overrun - Tota	al				(\$3,910.00)	
	0150 -	Total						(\$3,910.00)	
	0180	6 IN. WHITE HIGH BUILD WATERBORNE	Material		7	Oct 16, 2023	SYSTEM	\$2,029.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user leftrk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		PAINT			7	Oct 16, 2023	SYSTEM	(\$2,029.20)	
					8	Nov 2, 2023	SYSTEM	\$2,029.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user haungc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$2,029.20)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0180 -	Total						\$0.00	
	0190	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		7	Oct 16, 2023	SYSTEM	\$1,021.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user leftrk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		FAINT			7	Oct 16, 2023	SYSTEM	(\$1,021.20)	
					8	Nov 2, 2023	SYSTEM	\$1,021.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user haungc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$1,021.20)	
				- Total				\$0.00	
			Material - Tota	11				\$0.00	
	0190 -		:			0 5	OVOTEM	\$0.00	
	0280	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile STMI	- Total	4	Sep 5, 2023	SYSTEM	\$3,750.00 \$3,750.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)	Construction		/II - Total			\$3,750.00	
	0280 -	Total	- Constitution of	otoekpile o II	rotal			\$3,750.00	
	0450	CONCRETE CRACK FILLER	Material		6	Oct 3, 2023	SYSTEM	\$401,514.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user burnww2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Oct 3, 2023	SYSTEM	(\$401,514.75)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Overrun	Overrun	7	Oct 16, 2023	SYSTEM	(\$54,762.25)	
					8	Nov 2, 2023	SYSTEM	\$54,762.25	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',13.25000 - 13.25000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0450 -							\$0.00	
	0460	CONCRETE CRACK FILLER	Material		6	Oct 3, 2023	SYSTEM	\$54,762.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user burnww2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Oct 3, 2023	SYSTEM	(\$54,762.25)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3540	0460	CONCRETE CRACK FILLER	Material	- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0460 -	Total						\$0.00	
J6I3540 -	Total							(\$4,660.00)	
J6I3550	0540	CLASS A EXCAVATION	Price FUEL		3	Aug 16, 2023	SYSTEM	\$3.96	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Sep 5, 2023	SYSTEM	\$47.70	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Sep 18, 2023	SYSTEM	\$96.36	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$148.02	
			Price FUEL - 1	otal				\$148.02	
	0540 -	Total						\$148.02	
	0560	SHAPING SLOPES, CLASS	Overrun	Overrun	7	Oct 16, 2023	SYSTEM	(\$1,725.00)	
		II			8	Nov 2, 2023	SYSTEM	\$1,725.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',750.00000 - 750.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0560 -	Total						\$0.00	
	0570	MISC. SHAPING SLOPES	Material		6	Oct 3, 2023	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user burnww2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Oct 3, 2023	SYSTEM	(\$6,000.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0570 -	Total						\$0.00	
	0590	TYPE 5 AGGREGATE FOR BASE	Price FUEL		8	Nov 2, 2023	SYSTEM	\$0.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$0.80	
			Price FUEL - 1	Total				\$0.80	
	0590 -							\$0.80	
	0620	PCCP JOINT/CRACK SEALING	Material		5	Sep 18, 2023	SYSTEM	\$2,063.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burnww2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$2,063.60)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0620 -	Total						\$0.00	
	0720	SLOPE PROTECTION	Material		5	Sep 18, 2023	SYSTEM	\$28,464.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user burnww2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$28,464.00)	
					6	Oct 3, 2023	SYSTEM	\$28,464.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user burnww2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Oct 3, 2023	SYSTEM	(\$28,464.00)	
					7	Oct 16, 2023	SYSTEM	\$28,464.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user leftrk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$28,464.00)	
					8	Nov 2, 2023	SYSTEM	(\$39,696.00)	
				- Total				(\$39,696.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3550	0720	SLOPE PROTECTION	Material - Tota					(\$39,696.00)	
	0720 -	Total						(\$39,696.00)	
	0990	TRAFFIC BARRIER	Overrun	Overrun	8	Nov 2, 2023	SYSTEM	(\$92.00)	
		DELINEATOR, WHITE		Overrun - T	otal			(\$92.00)	
			Overrun - Tota	ı				(\$92.00)	
	0990 -	Total						(\$92.00)	
	1170	FLOWABLE BACKFILL	Material		3	Aug 16, 2023	SYSTEM	\$3,710.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burnww2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 16, 2023	SYSTEM	(\$3,710.00)	
					4	Sep 5, 2023	SYSTEM	\$8,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user burnww2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$8,480.00)	
					5	Sep 18, 2023	SYSTEM	\$30,210.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user burnww2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$30,210.00)	
					6	Oct 3, 2023	SYSTEM	\$30,210.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user burnww2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Oct 3, 2023	SYSTEM	(\$30,210.00)	
					7	Oct 16, 2023	SYSTEM	\$28,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leftrk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$28,090.00)	
					8	Nov 2, 2023	SYSTEM	(\$28,090.00)	
				- Total				(\$28,090.00)	
			Material - Tota	l				(\$28,090.00)	
			Overrun	Overrun	5	Sep 18, 2023	SYSTEM	(\$19,610.00)	
					7	Oct 16, 2023	SYSTEM	\$2,120.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',530.00000 - 530.00000, 'is applied (if non-zero).
				Overrun - T	otal			(\$17,490.00)	
			Overrun - Tota	ıl				(\$17,490.00)	
	1170 -	Total						(\$45,580.00)	
	1200	SLAB JACKING MATL HIGH	Material		2	Aug 2, 2023	SYSTEM	(\$16,288.75)	
		DENSITY POLYURETH		- Total				(\$16,288.75)	
			Material - Tota					(\$16,288.75)	
			MaterialCredit		3	Aug 16, 2023	SYSTEM	\$16,288.75	
				- Total				\$16,288.75	
			MaterialCredit	- Total				\$16,288.75	
	1200 -	Total						\$0.00	
	1240	OPEN CELL FOAM JOINT	Material		2	Aug 2, 2023	SYSTEM	(\$9,750.00)	
		SEAL		- Total				(\$9,750.00)	
			Material - Tota					(\$9,750.00)	
			MaterialCredit		3	Aug 16, 2023	SYSTEM	\$9,750.00	
				- Total				\$9,750.00	



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0 '	1240	OPEN CELL FOAM JOINT SEAL	MaterialCredit	- Total				\$9,750.00	
•	1240 -	Total						\$0.00	
	1280	SEEDING - COOL SEASON GRASSES	Material		6	Oct 3, 2023	SYSTEM	(\$3,780.00)	
		0.0.0020			7	Oct 16, 2023	SYSTEM	(\$3,780.00)	
					8	Nov 2, 2023	SYSTEM	(\$7,560.00)	
				- Total				(\$15,120.00)	
			Material - Tota	ıl	_		0)/0==1/	(\$15,120.00)	
			MaterialCredit		7	Oct 16, 2023	SYSTEM	\$3,780.00	
				- Total	8	Nov 2, 2023	SYSTEM	\$3,780.00 \$7,560.00	
			MaterialCredit						
	1280 -	Total	WateriarGredit	Total				\$7,560.00 (\$7,560.00)	
	1300	SILT FENCE	Material		1	Jul 17, 2023	SYSTEM	(\$4,500.00)	
				- Total				(\$4,500.00)	
			Material - Tota					(\$4,500.00)	
			MaterialCredit		2	Aug 2, 2023	SYSTEM	\$4,500.00	
				- Total				\$4,500.00	
			MaterialCredit	- Total				\$4,500.00	
1	1300 -	Total						\$0.00	
	1310	MGS GUARDRAIL	Construction Stockpile		6	Oct 2, 2023	SYSTEM	(\$17,132.14)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Nov 2, 2023	SYSTEM	(\$11,545.58)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$28,677.72)	
			Construction	Stockpile - To				(\$28,677.72)	
			Construction Stockpile STMI	Total	4	Sep 5, 2023	SYSTEM	\$295,194.25	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total	MI Total			\$295,194.25	
	1310 -	Total	Construction	Stockpile 511	vii - Totai			\$295,194.25 \$266,516.53	
	1320		Construction Stockpile		4	Sep 5, 2023	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
		FT. POSTS, 1 FT. - 6.75		- Total				\$8,510.00	
		5.70	Construction	Stockpile STI	MI - Total			\$8,510.00	
	1320 -	Total						\$8,510.00	
	1330	MGS BRIDGE APP. TRANS	Construction Stockpile		6	Oct 2, 2023	SYSTEM	(\$8,200.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		SEC (REG/NO CURB)			8	Nov 2, 2023	SYSTEM	(\$8,200.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$16,400.00)	
			Construction	Stockpile - To	otal			(\$16,400.00)	
			Construction Stockpile STMI		4	Sep 5, 2023	SYSTEM	\$61,500.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$61,500.00	
			Construction	Stockpile STI	MI - Total			\$61,500.00	
	1330 -							\$45,100.00	
	1340	MGS END ANCHOR	Construction Stockpile STMI		4	Sep 5, 2023	SYSTEM	\$11,480.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$11,480.00	



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
50	1340	MGS END ANCHOR	Construction 8	Stockpile STI	VII - Total			\$11,480.00	
	1340 -	Total						\$11,480.00	
	1350	TYPE A CRASHWORTHY	Construction Stockpile		6	Oct 2, 2023	SYSTEM	(\$7,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL (MASH)			8	Nov 2, 2023	SYSTEM	(\$7,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$15,000.00)	
			Construction S	Stockpile - To	otal			(\$15,000.00)	
			Construction Stockpile		4	Sep 5, 2023	SYSTEM	\$61,875.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$61,875.00	
			Construction S	Stockpile STI	MI - Total			\$61,875.00	
	1350 -	Total						\$46,875.00	
	1500	MISC. BEARING PILE	Material		3	Aug 16, 2023	SYSTEM	\$66,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user burnww2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Aug 16, 2023	SYSTEM	(\$66,160.00)	
					4	Sep 5, 2023	SYSTEM	\$66,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user burnww2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$66,160.00)	
					5	Sep 18, 2023	SYSTEM	\$66,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user burnww2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$66,160.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1500 -	Total						\$0.00	
	1520	CLEANING AND EPOXY	Material		7	Oct 16, 2023	SYSTEM	(\$2,225.00)	
		COATING			8	Nov 2, 2023	SYSTEM	\$2,225.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user haungc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$2,225.00)	
				- Total				(\$2,225.00)	
			Material - Tota					(\$2,225.00)	
			MaterialCredit		8	Nov 2, 2023	SYSTEM	\$2,225.00	
				- Total				\$2,225.00	
			MaterialCredit	- Total				\$2,225.00	
	1520 -	Total						\$0.00	
	1590	SILICONE EXPANSION	Overrun	Overrun	8	Nov 2, 2023	SYSTEM	(\$252.00)	
		JOINT SEALANT		Overrun - T	otal			(\$252.00)	
			Overrun - Tota					(\$252.00)	
	1590 -	Total						(\$252.00)	
	4000	MISC. BEARING	Material		2	Aug 2, 2023	SYSTEM	\$34,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user macekc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	1620	PILE							
	1620	PILE			2	Aug 2, 2023	SYSTEM	(\$34,200.00)	
	1620	PILE			3		SYSTEM	(\$34,200.00) \$91,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user burnww2 overridding Payment Estimate Exception 3 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
550	1620	MISC. BEARING PILE	Material		4	Sep 5, 2023	SYSTEM	\$102,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user burnww2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$102,600.00)	
					5	Sep 18, 2023	SYSTEM	\$102,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user burnww2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$102,600.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	1620 -	Total						\$0.00	
	1670	SILICONE EXPANSION JOINT SEALANT	Material		3	Aug 16, 2023	SYSTEM	\$2,058.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user burnww2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Aug 16, 2023	SYSTEM	(\$2,058.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	1670 -	Total						\$0.00	
	1910	CLEANING AND EPOXY COATING	Material		7	Oct 16, 2023	SYSTEM	\$15,249.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user leftrk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Oct 16, 2023	SYSTEM	(\$15,249.60)	
					8	Nov 2, 2023	SYSTEM	\$16,945.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user haungc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$16,945.20)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
		910 - Total							
	1910 -	TOtal						\$0.00	
	1910 - 1930	CLEANING AND COATING EXISTING	Material		7	Oct 16, 2023	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		CLEANING AND COATING	Material		7		SYSTEM SYSTEM		Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment
		CLEANING AND COATING EXISTING	Material			2023 Oct 16,		\$11,000.00	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment
		CLEANING AND COATING EXISTING	Material		7	2023 Oct 16, 2023 Nov 2,	SYSTEM	\$11,000.00 (\$11,000.00)	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment
		CLEANING AND COATING EXISTING	Material	- Total	7	2023 Oct 16, 2023 Nov 2, 2023	SYSTEM	\$11,000.00 (\$11,000.00) \$22,000.00	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment
	1930	CLEANING AND COATING EXISTING BEARINGS	Material  Material - Tota		7	2023 Oct 16, 2023 Nov 2, 2023	SYSTEM	\$11,000.00 (\$11,000.00) \$22,000.00 (\$22,000.00)	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment
	1930 -	CLEANING AND COATING EXISTING BEARINGS			7 8 8	2023 Oct 16, 2023 Nov 2, 2023	SYSTEM SYSTEM SYSTEM	\$11,000.00 (\$11,000.00) \$22,000.00 (\$22,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment
	1930 -	CLEANING AND COATING EXISTING BEARINGS  Total SUBSTRUCTURE REPAIR			7	2023 Oct 16, 2023 Nov 2, 2023 Nov 2, 2023 Sep 5, 2023	SYSTEM SYSTEM SYSTEM	\$11,000.00 (\$11,000.00) \$22,000.00 (\$22,000.00) \$0.00	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment
	1930 -	CLEANING AND COATING EXISTING BEARINGS  Total SUBSTRUCTURE	Material - Tota		7 8 8	2023 Oct 16, 2023 Nov 2, 2023 Nov 2, 2023 Sep 5,	SYSTEM SYSTEM SYSTEM	\$11,000.00 (\$11,000.00) \$22,000.00 (\$22,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment
	1930 -	CLEANING AND COATING EXISTING BEARINGS  Total SUBSTRUCTURE REPAIR	Material - Tota		7 8 8	2023 Oct 16, 2023 Nov 2, 2023 Nov 2, 2023 Sep 5, 2023 Sep 18,	SYSTEM SYSTEM SYSTEM	\$11,000.00 (\$11,000.00) \$22,000.00 (\$22,000.00) \$0.00 \$0.00 (\$2,700.00)	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment
	1930 -	CLEANING AND COATING EXISTING BEARINGS  Total SUBSTRUCTURE REPAIR	Material - Tota		7 8 8 8	2023 Oct 16, 2023 Nov 2, 2023 Nov 2, 2023 Sep 5, 2023 Sep 18, 2023 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$11,000.00  (\$11,000.00)  \$22,000.00  (\$22,000.00)  \$0.00  \$0.00  (\$2,700.00)	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment
	1930 -	CLEANING AND COATING EXISTING BEARINGS  Total SUBSTRUCTURE REPAIR	Material - Tota	ıl - Total	7 8 8 4 5 6	2023 Oct 16, 2023 Nov 2, 2023 Nov 2, 2023 Sep 5, 2023 Sep 18, 2023 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$11,000.00  (\$11,000.00)  \$22,000.00  (\$22,000.00)  \$0.00  \$0.00  (\$2,700.00)  (\$2,700.00)  (\$2,700.00)  (\$2,700.00)  (\$8,100.00)	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment
	1930 -	CLEANING AND COATING EXISTING BEARINGS  Total SUBSTRUCTURE REPAIR	Material - Tota	ıl - Total	7 8 8 8	2023 Oct 16, 2023 Nov 2, 2023 Nov 2, 2023 Sep 5, 2023 Sep 18, 2023 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$11,000.00  (\$11,000.00)  \$22,000.00  (\$22,000.00)  \$0.00  \$0.00  (\$2,700.00)  (\$2,700.00)  (\$2,700.00)	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment
	1930 -	CLEANING AND COATING EXISTING BEARINGS  Total SUBSTRUCTURE REPAIR	Material - Tota	ıl - Total	7 8 8 4 5 6	2023 Oct 16, 2023 Nov 2, 2023 Nov 2, 2023 Sep 5, 2023 Sep 18, 2023 Oct 3, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$11,000.00  (\$11,000.00)  \$22,000.00  (\$22,000.00)  \$0.00  \$0.00  (\$2,700.00)  (\$2,700.00)  (\$2,700.00)  (\$2,700.00)  (\$8,100.00)	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment
	1930 -	CLEANING AND COATING EXISTING BEARINGS  Total SUBSTRUCTURE REPAIR	Material - Tota	ıl - Total	7 8 8 8 5 6	2023 Oct 16, 2023 Nov 2, 2023 Nov 2, 2023 Sep 5, 2023 Sep 18, 2023 Oct 3, 2023 Oct 3, 2023 Oct 3, 2023	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$11,000.00  (\$11,000.00)  \$22,000.00  (\$22,000.00)  \$0.00  \$0.00  (\$2,700.00)  (\$2,700.00)  (\$2,700.00)  (\$8,100.00)  \$2,700.00  \$2,700.00	Estimate Item Adjustment (0006) due to user leftrk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haungc1 overridding Payment





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J613550	1980	SUBSTRUCTURE REPAIR (UNFORMED)	MaterialCredit - Total				\$8,100.00		
	1980 -	- Total						\$0.00	
	2370	MISC.	Material		7	Oct 16, 2023	SYSTEM	(\$3,300.00)	
					8	Nov 2, 2023	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user haungc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Nov 2, 2023	SYSTEM	(\$3,300.00)	
				- Total				(\$3,300.00)	
			Material - Total					(\$3,300.00)	
			MaterialCredit		8	Nov 2, 2023	SYSTEM	\$3,300.00	
				- Total				\$3,300.00	
			MaterialCredit - Total					\$3,300.00	
	2370 -	- Total						\$0.00	
	5102	GRAY EPOXY- MASTIC PRIMER			4	Sep 5, 2023	SYSTEM	\$6,638.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user burnww2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Sep 5, 2023	SYSTEM	(\$6,638.00)	
					5	Sep 18, 2023	SYSTEM	\$6,638.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user burnww2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	Sep 18, 2023	SYSTEM	(\$6,638.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5102 -	5102 - Total						\$0.00	
J6I3550 -	- Total							\$285,450.35	
Overall -	erall - Total								

# MoDOT

### Contract Adjustments for Contract - 230519-F03

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 21 of 21