

Pay Estimate Created Date: September 16, 2024

Progres	s Estimate Number	Contrac	t ID 231020-C01			Pay Period Start	September 2, 2024	Original Contract Ame	ount\$911,225.77			
8	Number	Prime Contrac	Superior Bo tor LLC	wen Aspha	lt Company,		September 15, 2024	Net Change Order Amount Current Contract Amo	\$0.00 punt \$911,225.77			
Approval Date				Ву								
September 16, 2024			Gen	erated and Approved (and should be considered Draft) at the Project Office Level by								
September 16, 2024		Reviewe	d and Approved (and should be considered Draft) at the Resident Engineer Level by ile									
September 17, 2024					Reviewed a	nd Approved at the 0	ntrollers Office Level by ram					
Original Com	Original Completion Date Current Completion					Completion Date % of Cu		urrent Contract Amount Complete				
October 2	15, 2024		October 15, 202	4	J	luly 15, 2024		96.38%				
Co	ontract Inform	national I	Dates				Milestones					
Date Description	Origir Completic		Current Completion Date	Date D	Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days			
Acceptance Date				Milestor Calenda		August 13, 2024	August 13, 2024	Milestone Complete	9			
Awarded Date	November 1	1, 2023	November 1, 2023									
Letting Date	October 20,	2023	October 20, 2023									
Notice to Proceed Date	December 4	4, 2023	December 4, 2023									
Open to Traffic Date	December 4	4, 2023	December 4, 2023									

Contract Total Pay For Estimate No. 8

June 3, 2024

June 3, 2024

Contract Total Payable This Estimate:	\$0.00			
		<mark>\$876,030.68</mark>	\$876,030.68	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Incentive	\$0.00	\$0.00	\$0.00	
Gross Item Adjustments	\$0.00	(\$2,184.06)	(\$2,184.06)	
Total Posted Items Pay	\$0.00	\$878,214.74	\$878,214.74	
231020-C01				
	This Estimate	Previous	To Date	

Contract Total Payable This Estimate: Items Paid This Estimate Period

No Data Available

Work Began

Date

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3P3108B	0060	ULTRATHIN BONDED WEARING SURFACE, TYPE B	Material			-45,157	\$8.00	(\$361,256.00)
	0060	ULTRATHIN BONDED WEARING SURFACE, TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	45,157	\$8.00	\$361,256.00
	0070	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material			-40.6	\$240.90	(\$9,780.54)
	0070	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on	40.6	\$240.90	\$9,780.54



Pay Estimate Created Date: September 16, 2024

F	Progres	s Estimate Number	Contract ID	231020-C01		Pay Period Start September 2, 2024	Original Co	ontract Amou	nt\$911,225.77
	8 Project Line Item		Prime Contractor	Superior Bov LLC	ven Asphalt C		Net Change Amount Current Co		\$0.00 nt \$911,225.77
Project Number		Item	Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3P3108B						the current Payment Estimate.			
	0080	CONCRE	TE SIDEWALK, 4 IN.	Material			-35.6	\$132.50	(\$4,717.00)
0	0080	CONCRE	TE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	35.6	\$132.50	\$4,717.00
	0090 MISC		MISC.	Material			-4	\$3,545.15	(\$14,180.60)
	0090		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	4	\$3,545.15	\$14,180.60
	0210	WATERBO	HITE HIGH BUILD RNE PAVEMENT G PAINT, TYPE L BEADS	Material			-259	\$0.30	(\$77.70)
	0210	WATERBO	HITE HIGH BUILD RNE PAVEMENT G PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	259	\$0.30	\$77.70
	0220	WATERBO	HITE STANDARD RNE PAVEMENT G PAINT, TYPE P BEADS	Material			-4,048	\$0.25	(\$1,012.00)
	0220	WATERBO	HITE STANDARD RNE PAVEMENT G PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	4,048	\$0.25	\$1,012.00
	0230	WATERBO	LOW STANDARD RNE PAVEMENT G PAINT, TYPE P BEADS	Material			-18,047	\$0.25	(\$4,511.75)
	0230	WATERBO	LOW STANDARD RNE PAVEMENT G PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	18,047	\$0.25	\$4,511.75
	0240	WATERBO	LOW STANDARD RNE PAVEMENT G PAINT, TYPE P BEADS	Material			-561	\$6.00	(\$3,366.00)
	0240 24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 0270 CABLE, LOOP DETECTOR IN DUCT		RNE PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	561	\$6.00	\$3,366.00
			Material			-6,270	\$5.25	(\$32,917.50)	
	0270	CABLE, LOOP DETECTOR, IN DUCT		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.	6,270	\$5.25	\$32,917.50
	0280	CABLE, LO	DOP DETECTOR, LEAD-IN	Material			-3,740	\$1.95	(\$7,293.00)



Pay Estimate Created Date: September 16, 2024

F	Progres 8	s Estimate Number	Contract ID Prime Contractor	231020-C01 Superior Bov LLC	ven Asphalt C	ompany,	Pay Period Start Pay Period En	September 2, 2024 d September 15, 2024	Net Change Amount	e Order	nt\$911,225.77 \$0.00 nt \$911,225.77
Project Number	Line No.	Item	Description	Adjustment Type					Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3P3108B	0290 BREAKAWAY ASSEMBLY (PERFORATED SQUARE		DOP DETECTOR, LEAD-IN	Material		genera Adj	ated Material Pay justment (0010) c ding Payment Es	the original system- ment Estimate Item due to user hessec2 timate Exception 20 Payment Estimate.	3,740	\$1.95	\$7,293.00
				Material					-3	\$388.00	(\$1,164.00)
	0290		WAY ASSEMBLY RATED SQUARE STEEL TUBE)	Material		genera Adj	ated Material Pay justment (0011) c ding Payment Es	the original system- ment Estimate Item due to user hessec2 timate Exception 21 Payment Estimate.	3	\$388.00	\$1,164.00
	0310	2.5 IN. PS	ST POST - 12 GA.	Material					-36	\$26.50	(\$954.00)
	0310	2.5 IN. PS	ST POST - 12 GA.	Material		genera Adj	ated Material Pay justment (0012) c ding Payment Es	the original system- ment Estimate Item due to user hessec2 timate Exception 22 Payment Estimate.	36	\$26.50	\$954.00
	0340		MISC.	Material					-1	\$200.00	(\$200.00)
	0340		MISC.	Material		genera Adj	ated Material Pay justment (0013) c ding Payment Es	the original system- ment Estimate Item due to user hessec2 timate Exception 23 Payment Estimate.	1	\$200.00	\$200.00
Total											\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J3P3108B		Pavement repair, resurface and ADA improvement	13	RAY	from Black Diamond Street to Walmart Avenue in Richmond						

Totals by Job Numbers

3P3108B	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$878,214.74	\$878,214.74
Gross Item Adjustments	\$0.00	(\$2,184.06)	(\$2,184.06)
Gross Item Pay	\$0.00	\$876,030.68	\$876,030.68
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 4133100, Project Item Line Number 0060, Material Set 413310096, Material 1015EAPEM1 - PEM-1 Anionic Polymer Mod Emulsion Membr, Acceptance Action Generic AspEmulsion is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 4133100, Project Item Line Number 0060, Material Set 413310096, Material 1015EACPEM1 - Cationic Polymer Mod Emulsion CPEM-1, Acceptance Action Generic AspEmulsion is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 5021108, Project Item Line Number 0070, Material Set 502110896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 5021108, Project Item Line Number 0070, Material Set 502110896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 5021108, Project Item Line Number 0070, Material Set 502110896, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 5021108, Project Item Line Number 0070, Material Set 502110896, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 5021108, Project Item Line Number 0070, Material Set 502110896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6086004, Project Item Line Number 0080, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6089902, Project Item Line Number 0090, Material Set 608990296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6205902A, Project Item Line Number 0210, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6205902A, Project Item Line Number 0210, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206000C, Project Item Line Number 0220, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206000C, Project Item Line Number 0220, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206001C, Project Item Line Number 0230, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206001C, Project Item Line Number 0230, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206125A, Project Item Line Number 0240, Material Set 6206125A96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206125A, Project Item Line Number 0240, Material Set 6206125A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206125A, Project Item Line Number 0240, Material Set 6206125A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 9028500, Project Item Line Number 0270, Material Set 902850096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 9028510, Project Item Line Number 0280, Material Set 902851096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 9031241, Project Item Line Number 0290, Material Set 903124196, Material 0903HSBA - Breakaway Assembly for Highway Signing, Acceptance Action Generic 0903HSBA is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 9031280, Project Item Line Number 0310, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 9039902, Project Item Line Number 0340, Material Set 9039902, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient.	Tests have passed but has yet been entered.	hessec2	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

No. No. Softwark A.07 B.07 <thb.07< th=""> B.07 B.07 <!--</th--><th>Contract CONTRACT</th><th>Project No.</th><th>Category</th><th>Line No.</th><th>ltem Code</th><th>Description</th><th>Bid Quantity</th><th>Net Change Order</th><th>Total Current Quantity</th><th>Unit</th><th>Total Posted Approved Qty</th><th>Unit Price</th><th>Total Value POSTED To Date (See report generated date)</th></thb.07<>	Contract CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0000000001001001000010000200 <t< td=""><td>020-C01</td><td>J3P3108B</td><td>0001</td><td>0010</td><td>2022010</td><td>REMOVAL OF IMPROVEMENTS</td><td>1.00</td><td>0.00</td><td>1.00</td><td>LS</td><td>1.00</td><td>\$20,913.35</td><td>\$20,913.3</td></t<>	020-C01	J3P3108B	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$20,913.35	\$20,913.3
100040041200100000000000000000000000000000000000			0001	0020	2079909	MISC.SIDEWALK	0.70	0.00	0.70	STA	0.70	\$5,485.71	\$3,840.0
0001 0050 01500 0			0001	0030	3109910	MISC.TYPE 5 AGGREGATE	62.70	0.00	62.70	TONS	0.00	\$157.90	\$0.0
No. SOU 413101 ULTRATHIN BONDED WEARING SURFACE. TYPE B 45.2510 SOU 45.070 </td <td></td> <td></td> <td>0001</td> <td>0040</td> <td>4011211</td> <td>BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)</td> <td>445.80</td> <td>0.00</td> <td>445.80</td> <td>TONS</td> <td>413.00</td> <td>\$272.00</td> <td>\$112,336.0</td>			0001	0040	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	445.80	0.00	445.80	TONS	413.00	\$272.00	\$112,336.0
No. SUM 001 000 0000 00000 CONCRETE SUEWALK, 4 IN. SUE SUM <td></td> <td></td> <td>0001</td> <td>0050</td> <td>4071005</td> <td>TACK COAT</td> <td>536.00</td> <td>0.00</td> <td>536.00</td> <td>GAL</td> <td>536.00</td> <td>\$3.50</td> <td>\$1,876.0</td>			0001	0050	4071005	TACK COAT	536.00	0.00	536.00	GAL	536.00	\$3.50	\$1,876.0
0001 00800 0000000 00000000 00000000 00000000 00000000 0000000 0000000 0000000 0000000 0000000 0000000 0000000 000000 000000 000000 000000 000000 000000 000000 000000 000000 000000 000000 00000 00000 </td <td></td> <td></td> <td>0001</td> <td>0060</td> <td>4133100</td> <td>ULTRATHIN BONDED WEARING SURFACE, TYPE B</td> <td>45,251.00</td> <td>0.00</td> <td>45,251.00</td> <td>SQYD</td> <td>45,157.00</td> <td>\$8.00</td> <td>\$361,256.0</td>			0001	0060	4133100	ULTRATHIN BONDED WEARING SURFACE, TYPE B	45,251.00	0.00	45,251.00	SQYD	45,157.00	\$8.00	\$361,256.0
0001 0009 00090 000900 000000000000000000000000000000000000			0001	0070	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	57.60	0.00	57.60	SQYD	40.60	\$240.90	\$9,780.5
Note F12000 TUCK OR TRALER MOUNTED ATTENUATOR (TMA) 2.00 0.00 2.00 F.A. 2.00 91.00.00 0001 010 616005 CONSTRUCTION SIGNS 1.091.00 0.00 7.00 5.00 5.00.00			0001	0080	6086004	CONCRETE SIDEWALK, 4 IN.	35.60	0.00	35.60	SQYD	35.60	\$132.50	\$4,717.0
0001 0110 01910 01910 0.001 1.991.00 0.001 1.991.00 9.001 9.000 9.001 9.000			0001	0090	6089902	MISC.ADA RAMP	4.00	0.00	4.00	EA	4.00	\$3,545.15	\$14,180.6
Internet			0001	0100	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.0
0001 0190 0190 0190 0190 0190 0100 <th< td=""><td></td><td></td><td>0001</td><td>0110</td><td>6161005</td><td>CONSTRUCTION SIGNS</td><td>1,091.00</td><td>0.00</td><td>1,091.00</td><td>SQFT</td><td>1,091.00</td><td>\$6.00</td><td>\$6,546.0</td></th<>			0001	0110	6161005	CONSTRUCTION SIGNS	1,091.00	0.00	1,091.00	SQFT	1,091.00	\$6.00	\$6,546.0
International International International International International International International 0001 0140 616109 Channegable Messade sign with Communication International International Internatinternational International			0001	0120	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$50.00	\$100.0
Over 0001 01000 0100 0100			0001	0130	6161025	CHANNELIZER (TRIM LINE)	300.00	0.00	300.00	EA	300.00	\$15.00	\$4,500.0
No. INTERPACE, CONTRACTOR FURNISHED. CONTRACTOR Interpace Contractor			0001	0140	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,100.00	\$2,200.0
0001 0170 6181000 MOBILIZATION 1.00 0.00 1.00 LS 1.00 \$90,000.00 0011 0180 620015 RREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. 405.00 0.00 406.00 LF 28.00 \$20.00 <td rowspan="4"></td> <td>0001</td> <td>0150</td> <td>6161099</td> <td>INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR</td> <td>2.00</td> <td>0.00</td> <td>2.00</td> <td>EA</td> <td>2.00</td> <td>\$2,500.00</td> <td>\$5,000.0</td>		0001	0150	6161099	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.0	
International Interna International International<		0001	0160	6169902	MISC.ADA COMPLINANT MOVEABLE SIDEWALK BARRICADE	4.00	0.00	4.00	EA	4.00	\$150.00	\$600.0	
Number Number<		0001	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$90,000.00	\$90,000.0	
Image: Content of the conten			0001	0180	6200015		405.00	0.00	405.00	LF	286.00	\$20.00	\$5,720.0
Inite <th< td=""><td></td><td></td><td>0001</td><td>0190</td><td>6200021</td><td></td><td>19.00</td><td>0.00</td><td>19.00</td><td>EA</td><td>19.00</td><td>\$300.00</td><td>\$5,700.</td></th<>			0001	0190	6200021		19.00	0.00	19.00	EA	19.00	\$300.00	\$5,700.
No. No. PAINT, TYPE L BEADS No. No. No. No. No. 0001 020 62060000 4.IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 5.060.0 0.00 5.060.0 0.1F 4.048.00 \$0.02 \$0.02 18.047.00 \$0.02 \$0.02 18.047.00 \$0.02 \$0.02 \$0.00 22.559.00 0.00 22.559.00 0.1F 18.047.00 \$0.02 \$0.02 \$0.00<			0001	0200	6200036		90.00	0.00	90.00	EA	90.00	\$125.00	\$11,250.
Image: Note of the paint, type peads Image: Note of the peads			0001	0210	6205902A		259.00	0.00	259.00	LF	259.00	\$0.30	\$77.
Normal NARKING PAINT, TYPE P BEADS Normal <td></td> <td></td> <td>0001</td> <td>0220</td> <td>6206000C</td> <td></td> <td>5,060.00</td> <td>0.00</td> <td>5,060.00</td> <td>LF</td> <td>4,048.00</td> <td>\$0.25</td> <td>\$1,012.</td>			0001	0220	6206000C		5,060.00	0.00	5,060.00	LF	4,048.00	\$0.25	\$1,012.
MARKING PAINT, TYPE P BEADS <t< td=""><td></td><td></td><td>0001</td><td>0230</td><td>6206001C</td><td></td><td>22,559.00</td><td>0.00</td><td>22,559.00</td><td>LF</td><td>18,047.00</td><td>\$0.25</td><td>\$4,511.</td></t<>			0001	0230	6206001C		22,559.00	0.00	22,559.00	LF	18,047.00	\$0.25	\$4,511.
Initial Initial SURFACING (3 IN. THICK OR LESS) Initial <th< td=""><td></td><td></td><td>0001</td><td>0240</td><td>6206125A</td><td></td><td>561.00</td><td>0.00</td><td>561.00</td><td>LF</td><td>561.00</td><td>\$6.00</td><td>\$3,366.0</td></th<>			0001	0240	6206125A		561.00	0.00	561.00	LF	561.00	\$6.00	\$3,366.0
Note <th< td=""><td></td><td></td><td>0001</td><td>0250</td><td>6221001</td><td></td><td>49,237.00</td><td>0.00</td><td>49,237.00</td><td>SQYD</td><td>49,061.00</td><td>\$3.30</td><td>\$161,901.</td></th<>			0001	0250	6221001		49,237.00	0.00	49,237.00	SQYD	49,061.00	\$3.30	\$161,901.
Occor Fine </td <td></td> <td></td> <td>0001</td> <td>0260</td> <td>6274000</td> <td>CONTRACTOR FURNISHED SURVEYING AND STAKING</td> <td>1.00</td> <td>0.00</td> <td>1.00</td> <td>LS</td> <td>0.00</td> <td>\$5,000.00</td> <td>\$0.0</td>			0001	0260	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.0
Occor Orice Definition			0030	0270	9028500	CABLE, LOOP DETECTOR, IN DUCT	6,270.00	0.00	6,270.00	LF	6,270.00	\$5.25	\$32,917.5
No. <td></td> <td></td> <td>0030</td> <td>0280</td> <td>9028510</td> <td>CABLE, LOOP DETECTOR, LEAD-IN</td> <td>3,740.00</td> <td>0.00</td> <td>3,740.00</td> <td>LF</td> <td>3,740.00</td> <td>\$1.95</td> <td>\$7,293.</td>			0030	0280	9028510	CABLE, LOOP DETECTOR, LEAD-IN	3,740.00	0.00	3,740.00	LF	3,740.00	\$1.95	\$7,293.
Norm <th< td=""><td></td><td></td><td>0040</td><td>0290</td><td>9031241</td><td></td><td>3.00</td><td>0.00</td><td>3.00</td><td>EA</td><td>3.00</td><td>\$388.00</td><td>\$1,164.</td></th<>			0040	0290	9031241		3.00	0.00	3.00	EA	3.00	\$388.00	\$1,164.
Note <th< td=""><td></td><td></td><td>0040</td><td>0300</td><td>9031272A</td><td>2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.</td><td>3.00</td><td>0.00</td><td>3.00</td><td>EA</td><td>3.00</td><td>\$111.00</td><td>\$333.</td></th<>			0040	0300	9031272A	2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	3.00	0.00	3.00	EA	3.00	\$111.00	\$333.
Odd Odd Odd Odd Odd Odd Odd Odd Odd SQFT SD00 SQ10 S\$1,1 Odd0 0340 903902 MISC.SIGN RELOCATION 1.00 0.00 1.00 EA 1.00 \$20.00			0040	0310	9031280	2.5 IN. PSST POST - 12 GA.	36.00	0.00	36.00	LF	36.00	\$26.50	\$954.
0040 0340 9039902 MISC.SIGN RELOCATION 1.00 0.00 1.00 EA 1.00 \$200.00			0040	0320	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	3.00	0.00	3.00	EA	3.00	\$273.00	\$819.
			0040	0040 0330 9035004A SH-FLAT SHEET				0.00	50.00	SQFT	50.00	\$23.00	\$1,150.
Project J3P3108B - Total Value Posted to Date as of Report Generated Date \$878,2			0040	0340	9039902	MISC.SIGN RELOCATION	1.00	0.00	1.00	EA	1.00	\$200.00	\$200.0
		Project J3	93108B - Te	otal Value	e Posted to D	Date as of Report Generated Date							\$878,214.



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable). No Data Available



Sep 18, 2024

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J3P3108B	0040	BIT. PAVEMENT MIXTURE	Other Item Adjustment	ACAD	3	Jul 1, 2024	hessec2	(\$332.98)	AC Adjustment Line No. 0040 Installed Quantity =											
		PG64-22 (BP-2)							413 tons X 4.3% (Virgin) X -18.75 (Diff) = \$-332.98											
				ACAD - Tota	al			(\$332.98)												
			Other Item	Adjustment -	Total			(\$332.98)												
	0040 -	Total						(\$332.98)												
	0050	TACK COAT	Material		3	Jul 1, 2024	SYSTEM	\$1,876.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					3	Jul 1, 2024	SYSTEM	(\$1,876.00)												
					4	Jul 16, 2024	SYSTEM	\$1,876.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					4	Jul 16, 2024	SYSTEM	(\$1,876.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0050 -	Total						\$0.00												
	0060	ULTRATHIN BONDED WEARING SURFACE,	Material		3	Jul 1, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
		TYPE B			3	Jul 1, 2024	SYSTEM	(\$361,256.00)												
					4	Jul 16, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
																4	Jul 16, 2024	SYSTEM	(\$361,256.00)	
											5	Aug 1, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					5	Aug 1, 2024	SYSTEM	(\$361,256.00)												
					6	Aug 16, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					6	Aug 16, 2024	SYSTEM	(\$361,256.00)												
					7	Sep 3, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					7	Sep 3, 2024	SYSTEM	(\$361,256.00)												
					8	Sep 16, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					8	Sep 16, 2024	SYSTEM	(\$361,256.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
			Other Item Adjustment	ACAD	3	Jul 1, 2024	hessec2	(\$1,851.08)	AC Adjustment Line No. 0050 Installed Quantity =											
									-18.75 (diff) X 1.98 T/CY X 0.75 Thick / 36 X 45,157 Sq Yd X 5.3% (Virgin) = \$-1,851.08.											
				ACAD - Tota	al			(\$1,851.08)												
			Other Item	Adjustment -	Total			(\$1,851.08)												
	0060 -	Total						(\$1,851.08)												
	0070	CONCRETE PAVEMENT (8 IN. NON-	Material		2	Jun 17, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3108B	0070	REINF)	Material		2	Jun 17, 2024	SYSTEM	(\$9,780.54)	
					3	Jul 1, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Jul 1, 2024	SYSTEM	(\$9,780.54)	
					4	Jul 16, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Jul 16, 2024	SYSTEM	(\$9,780.54)	
					5	Aug 1, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Aug 1, 2024	SYSTEM	(\$9,780.54)	
					6	Aug 16, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Aug 16, 2024	SYSTEM	(\$9,780.54)	
					7	Sep 3, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Sep 3, 2024	SYSTEM	(\$9,780.54)	
				8	Sep 16, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
				8	Sep 16, 2024	SYSTEM	(\$9,780.54)		
				- Total				\$0.00	
			Material - To					\$0.00 \$0.00	
	0070 -	Total	Material - To						
	0070 - 0080	Total CONCRETE SIDEWALK, 4 IN.			2	Jun 17, 2024	SYSTEM	\$0.00 \$0.00 \$4,717.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		CONCRETE SIDEWALK, 4			2		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
		CONCRETE SIDEWALK, 4				2024 Jun 17,		\$0.00 \$0.00 \$4,717.00	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
		CONCRETE SIDEWALK, 4			2	2024 Jun 17, 2024 Jul 1,	SYSTEM	\$0.00 \$0.00 \$4,717.00 (\$4,717.00)	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
		CONCRETE SIDEWALK, 4			2 3	2024 Jun 17, 2024 Jul 1, 2024 Jul 1,	SYSTEM SYSTEM	\$0.00 \$0.00 \$4,717.00 (\$4,717.00) \$4,717.00	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
		CONCRETE SIDEWALK, 4			2 3 3	2024 Jun 17, 2024 Jul 1, 2024 Jul 1, 2024 Jul 1, 2024 Jul 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00)	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
		CONCRETE SIDEWALK, 4			2 3 3 4	2024 Jun 17, 2024 Jul 1, 2024 Jul 1, 2024 Jul 16, 2024 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00) \$4,717.00	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
		CONCRETE SIDEWALK, 4			2 3 3 4 4	2024 Jun 17, 2024 Jul 1, 2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00)	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.
		CONCRETE SIDEWALK, 4			2 3 3 4 4 5	2024 Jun 17, 2024 Jul 1, 2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, Aug 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00) \$4,717.00	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.
		CONCRETE SIDEWALK, 4			2 3 3 4 4 5 5	2024 Jun 17, 2024 Jul 1, 2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024 Aug 1, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00)	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		CONCRETE SIDEWALK, 4			2 3 3 4 5 5 6	2024 Jun 17, 2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024 Aug 1, 2024 Aug 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00) \$4,717.00 (\$4,717.00) \$4,717.00	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks				
			Туре	Adjustment Type	Number	Date	Ву						
I3P3108B	0080	CONCRETE SIDEWALK, 4 IN.	Material		8	Sep 16, 2024	SYSTEM	\$4,717.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					8	Sep 16, 2024	SYSTEM	(\$4,717.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0080 -	Total						\$0.00					
	0090	MISC. CONCRETE	Material		2	Jun 17, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
					2	Jun 17, 2024	SYSTEM	(\$14,180.60)					
					3	Jul 1, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
					3	Jul 1, 2024	SYSTEM	(\$14,180.60)					
					4	Jul 16, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
						4	Jul 16, 2024	SYSTEM	(\$14,180.60)				
					5	Aug 1, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
						5	Aug 1, 2024	SYSTEM	(\$14,180.60)				
						6	Aug 16, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					6	Aug 16, 2024	SYSTEM	(\$14,180.60)					
								7 7	7	Sep 3, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
									7	Sep 3, 2024	SYSTEM	(\$14,180.60)	
					8	Sep 16, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
					8	Sep 16, 2024	SYSTEM	(\$14,180.60)					
				- Total				\$0.00					
			Material - T	otal				\$0.00					
	0090 -	Total						\$0.00					
	0180	PREF THERMO PVMT MARK,	Material		4	Jul 16, 2024	SYSTEM	\$5,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
		24 IN WHIT			4	Jul 16, 2024	SYSTEM	(\$5,720.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0180 -	Total						\$0.00					
	0190	PREF THERMO PVMT MARK, LT/RT ARROW	Material		4	Jul 16, 2024	SYSTEM	\$5,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
					4	Jul 16, 2024	SYSTEM	(\$5,700.00)					
				- Total				\$0.00					
			Material - To					\$0.00 \$0.00					



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks				
J3P3108B	0200	PREF	Material	Туре	4	Jul 16,	SYSTEM	\$11,250.00	This adjustment offsets the original system-generated Material Payment				
		THERMO PVMT MARK, 30" WHT MIDBL				2024			Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.				
					4	Jul 16, 2024	SYSTEM	(\$11,250.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0200 -	Total						\$0.00					
	0210	6 IN. WHITE HIGH BUILD WATERBORNE	Material		4	Jul 16, 2024	SYSTEM	\$77.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
		PAINT			4	Jul 16, 2024	SYSTEM	(\$77.70)					
					5	Aug 1, 2024	SYSTEM	\$77.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					5	Aug 1, 2024	SYSTEM	(\$77.70)					
					6	Aug 16, 2024	SYSTEM	\$77.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					6	Aug 16, 2024	SYSTEM	(\$77.70)					
						7	Sep 3, 2024	SYSTEM	\$77.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
					7	Sep 3, 2024	SYSTEM	(\$77.70)					
					8	Sep 16, 2024	SYSTEM	\$77.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					8	Sep 16, 2024	SYSTEM	(\$77.70)					
				- Total				\$0.00					
			Material - T	otal				\$0.00					
	0210 -	Total						\$0.00					
	0220	4 IN. WHITE WATERBORNE PAVEMENT MARKING			4	Jul 16, 2024	SYSTEM	\$1,012.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					4	Jul 16, 2024	SYSTEM	(\$1,012.00)					
					5	Aug 1, 2024	SYSTEM	\$1,012.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
					5	Aug 1, 2024	SYSTEM	(\$1,012.00)					
									6	Aug 16, 2024	SYSTEM	\$1,012.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Aug 16, 2024	SYSTEM	(\$1,012.00)					
					7	Sep 3, 2024	SYSTEM	\$1,012.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
					7	Sep 3, 2024	SYSTEM	(\$1,012.00)					
					8	Sep 16, 2024	SYSTEM	\$1,012.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
					8	Sep 16, 2024	SYSTEM	(\$1,012.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0220	- Total						\$0.00					



				0.1					-	
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J3P3108B	0230	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		4	Jul 16, 2024	SYSTEM	\$4,511.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
					4	Jul 16, 2024	SYSTEM	(\$4,511.75)		
					5	Aug 1, 2024	SYSTEM	\$4,511.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					5	Aug 1, 2024	SYSTEM	(\$4,511.75)		
					6	Aug 16, 2024	SYSTEM	\$4,511.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					6	Aug 16, 2024	SYSTEM	(\$4,511.75)		
					7	Sep 3, 2024	SYSTEM	\$4,511.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					7	Sep 3, 2024	SYSTEM	(\$4,511.75)		
					8	Sep 16, 2024	SYSTEM	\$4,511.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					8	Sep 16, 2024	SYSTEM	(\$4,511.75)		
				- Total				\$0.00		
			Material - T	otal				\$0.00		
	0230 ·	- Total						\$0.00		
	0240	24 IN. YELLOW WATERBORNE PAVEMENT MARKIN			4	Jul 16, 2024	SYSTEM	\$3,366.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					4	Jul 16, 2024	SYSTEM	(\$3,366.00)		
					5	Aug 1, 2024	SYSTEM	\$3,366.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					5	Aug 1, 2024	SYSTEM	(\$3,366.00)		
					6	Aug 16, 2024	SYSTEM	\$3,366.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
					6	Aug 16, 2024	SYSTEM	(\$3,366.00)		
					7	Sep 3, 2024	SYSTEM	\$3,366.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
						7	Sep 3, 2024	SYSTEM	(\$3,366.00)	
					8	Sep 16, 2024	SYSTEM	\$3,366.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					8	Sep 16, 2024	SYSTEM	(\$3,366.00)		
				- Total				\$0.00		
			Material - T	otal				\$0.00		
	0240	- Total		ıterial				\$0.00		
	0270	CABLE, LOOP DETECTOR, IN DUCT	ECTOR, IN		3	Jul 1, 2024	SYSTEM	\$12,474.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					3	Jul 1, 2024	SYSTEM	(\$12,474.00)		
					4	Jul 16, 2024	SYSTEM	\$32,917.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
					4	Jul 16,	SYSTEM	(\$32,917.50)		



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
12024000	0070			Туре		2024			
I3P3108B	0270	CABLE, LOOP DETECTOR, IN DUCT	Material			2024			
					5	Aug 1, 2024	SYSTEM	\$32,917.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Aug 1, 2024	SYSTEM	(\$32,917.50)	
					6	Aug 16, 2024	SYSTEM	\$32,917.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Aug 16, 2024	SYSTEM	(\$32,917.50)	
					7	Sep 3, 2024	SYSTEM	\$32,917.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Sep 3, 2024	SYSTEM	(\$32,917.50)	
					8	Sep 16, 2024	SYSTEM	\$32,917.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					8	Sep 16, 2024	SYSTEM	(\$32,917.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0270 -	Total						\$0.00	
	0280	CABLE, LOOP DETECTOR, LEAD-IN		/aterial	3	Jul 1, 2024	SYSTEM	\$3,238.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					3	Jul 1, 2024	SYSTEM	(\$3,238.95)	
					4	Jul 16, 2024	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hessec2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					4	Jul 16, 2024	SYSTEM	(\$7,293.00)	
					5	Aug 1, 2024	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					5	Aug 1, 2024	SYSTEM	(\$7,293.00)	
					6	Aug 16, 2024	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Aug 16, 2024	SYSTEM	(\$7,293.00)	
					7	Sep 3, 2024	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					7	Sep 3, 2024	SYSTEM	(\$7,293.00)	
					8	Sep 16, 2024	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					8	Sep 16, 2024	SYSTEM	(\$7,293.00)	
				- Total				\$0.00	
			Material - T	- Total				\$0.00	
	0280 -	Total						\$0.00	
	0290	BREAKAWAY ASSEMBLY (PERFORATED	Material	erial	2	Jun 17, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		SQUARE STEEL TUBE)			2	Jun 17, 2024	SYSTEM	(\$1,164.00)	
					3	Jul 1, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J3P3108B	0290	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Material		3	Jul 1, 2024	SYSTEM	(\$1,164.00)	
					4	Jul 16, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hessec2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					4	Jul 16, 2024	SYSTEM	(\$1,164.00)	
					5	Aug 1, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					5	Aug 1, 2024	SYSTEM	(\$1,164.00)	
					6	Aug 16, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					6	Aug 16, 2024	SYSTEM	(\$1,164.00)	
					7	Sep 3, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					7	Sep 3, 2024	SYSTEM	(\$1,164.00)	
					8	Sep 16, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					8	Sep 16, 2024	SYSTEM	(\$1,164.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0290 -	- Total						\$0.00	
	0310	2.5 IN. PSST POST - 12 GA.	Material	ial	2	Jun 17, 2024	SYSTEM	\$954.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					2	Jun 17, 2024	SYSTEM	(\$954.00)	
					0	Jul 1,	SYSTEM	\$954.00	This adjustment offsets the original system-generated Material Payment
					3	2024			Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3		SYSTEM	(\$954.00)	Estimate Item Adjustment (0009) due to user hessec2 overridding Payment
						2024 Jul 1,		(\$954.00) \$954.00	Estimate Item Adjustment (0009) due to user hessec2 overridding Payment
					3	2024 Jul 1, 2024 Jul 16,	SYSTEM	. ,	Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3	2024 Jul 1, 2024 Jul 16, 2024 Jul 16,	SYSTEM SYSTEM	\$954.00	Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3 4 4	2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1,	SYSTEM SYSTEM SYSTEM	\$954.00 (\$954.00)	Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hessec2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment
					3 4 4 5	2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024	SYSTEM SYSTEM SYSTEM SYSTEM	\$954.00 (\$954.00) \$954.00	Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hessec2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment
					3 4 4 5 5	2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024 Aug 1, 2024 Aug 1, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$954.00 (\$954.00) \$954.00 (\$954.00)	Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hessec2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate.
					3 4 4 5 5 6	2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024 Aug 1, 2024 Aug 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$954.00 (\$954.00) \$954.00 (\$954.00) \$954.00	Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hessec2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate.
					3 4 4 5 5 6 6	2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024 Aug 1, 2024 Aug 16, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$954.00 (\$954.00) \$954.00 (\$954.00) \$954.00 (\$954.00) (\$954.00)	Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hessec2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					3 4 5 5 6 6 7	2024 Jul 1, 2024 Jul 16, 2024 Aug 1, 2024 Aug 1, 2024 Aug 1, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$954.00 (\$954.00) \$954.00 (\$954.00) \$954.00 (\$954.00) \$954.00	Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hessec2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3108B	0310	2.5 IN. PSST POST - 12 GA.	Material	- Total				\$0.00	
			Material - To	otal				\$0.00	
	0310 - Total							\$0.00	
	0340	MISC.	Material		2	Jun 17, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					2	Jun 17, 2024	SYSTEM	(\$200.00)	
					3	Jul 1, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					3	Jul 1, 2024	SYSTEM	(\$200.00)	
					4	Jul 16, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hessec2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					4	Jul 16, 2024	SYSTEM	(\$200.00)	
					5	Aug 1, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	Aug 1, 2024	SYSTEM	(\$200.00)	
					6	Aug 16, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					6	Aug 16, 2024	SYSTEM	(\$200.00)	
					7	Sep 3, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					7	Sep 3, 2024	SYSTEM	(\$200.00)	
					8	Sep 16, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					8	Sep 16, 2024	SYSTEM	(\$200.00)	
				- Total				\$0.00	
			Material - To	aterial - Total					
	0340 -	Total						\$0.00	
J3P3108B	Total							(\$2,184.06)	
Overall - T	otal							(\$2,184.06)	



There are no contract adjustments to display for this contract.