

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2024

Progress Estimate Number	Contract ID	231020-C01	Pay Period Start	September 16, 2024	Original Contract Amo	unt\$911,225.77
9	Prime Contractor	Superior Bowen Asphalt Company, LLC	Pay Period En	d September 30, 2024	Net Change Order Amount Current Contract Amou	\$0.00 int \$911,225.77

Approval Date		By User
October 1, 2024	Generated and Approved (and should be considered Draft) at the Project Office Level by	hessec2
October 1, 2024	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	ilesb1
October 2, 2024	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
October 15, 2024	October 15, 2024	July 15, 2024	96.53%

С	ontract Informational	Dates	Milestones						
Date Description	Original Current Completion Date				Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Acceptance Date			Milestone - Calendar Time	August 13, 2024	August 13, 2024	Milestone Complete			
Awarded Date	November 1, 2023	November 1, 2023							
Letting Date	October 20, 2023	October 20, 2023							
Notice to Proceed Date	December 4, 2023	December 4, 2023							
Open to Traffic Date	December 4, 2023	December 4, 2023							
Work Began Date	June 3, 2024	June 3, 2024							

Contract Total P	ay For Estimate No. 9				
		This Estimate	Previous	To Date	
231020-C01					
	Total Posted Items Pay	\$1,381.00	\$878,214.74	\$879,595.74	
	Gross Item Adjustments	\$0.00	(\$2,184.06)	(\$2,184.06)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$876,030.68	\$877,411.68	
Contract Total Page 1	avable This Estimate:	\$1 381 00			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J3P3108B 0220 62060		6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.250	1,012	\$253.00			
	0230	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.250	4,512	\$1,128.00			
Project J3P3	3108B - Tot	al					\$1,381.00			
Overall - To	Overall - Total									

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item Adjustments Exist on Contract Line Item Adjustments This Estimate											
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
J3P3108B	0060	ULTRATHIN BONDED WEARING SURFACE, TYPE B	Material			-45,157	\$8.00	(\$361,256.00)			
	0060	ULTRATHIN BONDED WEARING SURFACE, TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	45,157	\$8.00	\$361,256.00			

Revision 3/23/2023 Page 1 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2024

Pay Period September 16, **Progress Estimate** Contract ID 231020-C01 Original Contract Amount \$911,225.77 2024 Number Start Pay Period End September 30, 2024 Prime Superior Bowen Asphalt Company, **Net Change Order** \$0.00 Contractor LLĊ Amount Current Contract Amount \$911,225.77

it \$911,225.77	ntract Amoun	Current Co										
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.	Project Number				
(\$9,780.54	\$240.90	-40.6			Material	CONCRETE PAVEMENT (8 IN. NON-REINF)	0070	3P3108B				
\$9,780.54	\$240.90	40.6	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.		Material	CONCRETE PAVEMENT (8 IN. NON-REINF)	0070					
(\$4,717.00	\$132.50	-35.6			Material	CONCRETE SIDEWALK, 4 IN.	0800					
\$4,717.00	\$132.50	35.6	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.		Material	CONCRETE SIDEWALK, 4 IN.	0800					
(\$14,180.60	\$3,545.15	-4			Material	MISC.	0090					
\$14,180.60	\$3,545.15	4	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.		Material	MISC.	0090					
(\$77.70	\$0.30	-259			Material	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	0210					
\$77.70	\$0.30	259	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.		Material	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	0210					
(\$1,265.00	\$0.25	-5,060			Material	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0220					
\$1,265.00	\$0.25	5,060	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.		Material	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0220					
(\$5,639.75	\$0.25	-22,559			Material	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0230					
\$5,639.75	\$0.25	22,559	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.		Material	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0230					
(\$3,366.00	\$6.00	-561			Material	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0240					
\$3,366.00	\$6.00	561	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.		Material	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0240					
(\$32,917.50	\$5.25	-6,270			Material	CABLE, LOOP DETECTOR, IN DUCT	0270					
\$32,917.50	\$5.25	6,270	This adjustment offsets the original system-		Material	CABLE, LOOP DETECTOR,	0270					

Revision 3/23/2023 Page 2 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2024

Prog	gress Estimate Number	Contract ID	231020-C01	Pay Period Start	September 16, 2024	Original Contract Amo	unt\$911,225.77
	9	Prime Contractor	Superior Bowen Asphalt Company, LLC	Pay Period End	September 30, 2024	Net Change Order Amount Current Contract Amou	\$0.00 ant \$911,225.77

nt \$911,225.77	ntract Amour	Current Co										
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.	Project Number				
			generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.			IN DUCT						
(\$7,293.00)	\$1.95	-3,740			Material	CABLE, LOOP DETECTOR, LEAD-IN	0280					
\$7,293.00	\$1.95	3,740	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.		Material	CABLE, LOOP DETECTOR, LEAD-IN	0280					
(\$1,164.00)	\$388.00	-3			Material	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	0290					
\$1,164.00	\$388.00	3	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.		Material	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	0290					
(\$954.00)	\$26.50	-36			Material	2.5 IN. PSST POST - 12 GA.	0310					
\$954.00	\$26.50	36	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.		Material	2.5 IN. PSST POST - 12 GA.	0310					
(\$200.00)	\$200.00	-1			Material	MISC.	0340					
\$200.00	\$200.00	1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.		Material	MISC.	0340					
\$0.00								Total				

Revision 3/23/2023 Page 3 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information	n				
Project Number											
J3P3108B	FAF 13-4(34)	Pavement repair, resurface and ADA improvement	13	RAY	from Black Diamond Stree	m Black Diamond Street to Walmart Avenue in Richmond					
Totals by Jo	b Number	's									
J3P3108B		l Item Pay Item Adjustme		Item Pay	This Estimate \$1,381.00 \$0.00 \$1,381.00	Previous \$878,214.74 (\$2,184.06) \$876,030.68	To Date \$879,595.74 (\$2,184.06) \$877,411.68				
		entive ated Damages			\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00				
	Other (Contract Adjus	tments		\$0.00	\$0.00	\$0.00				

Revision 3/23/2023 Page 4 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 4133100, Project Item Line Number 0060, Material Set 413310096, Material 1015EACPEM1 - Cationic Polymer Mod Emulsion CPEM-1, Acceptance Action Generic AspEmulsion is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 4133100, Project Item Line Number 0060, Material Set 413310096, Material 1015EAPEM1 - PEM-1 Anionic Polymer Mod Emulsion Membr, Acceptance Action Generic AspEmulsion is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 5021108, Project Item Line Number 0070, Material Set 502110896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 5021108, Project Item Line Number 0070, Material Set 502110896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 5021108, Project Item Line Number 0070, Material Set 502110896, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 5021108, Project Item Line Number 0070, Material Set 502110896, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 5021108, Project Item Line Number 0070, Material Set 502110896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6086004, Project Item Line Number 0080, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6089902, Project Item Line Number 0090, Material Set 608990296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6205902A, Project Item Line Number 0210, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6205902A, Project Item Line Number 0210, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206000C, Project Item Line Number 0220, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206000C, Project Item Line Number 0220, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206001C, Project Item Line Number 0230, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206001C, Project Item Line Number 0230, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206125A, Project Item Line Number 0240, Material Set 6206125A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206125A, Project Item Line Number 0240, Material Set 6206125A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 6206125A, Project Item Line Number 0240, Material Set 6206125A96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 9028500, Project Item Line Number 0270, Material Set 902850096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 9028510, Project Item Line Number 0280, Material Set 902851096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 9031241, Project Item Line Number 0290, Material Set 903124196, Material 0903HSBA - Breakaway Assembly for Highway Signing, Acceptance Action Generic 0903HSBA is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 9031280, Project Item Line Number 0310, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3108B, Item 9039902, Project Item Line Number 0340, Material Set 9039902, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient.	Tests have passed but has yet been Entered/Authorized.	hessec2	Overridden

Revision 3/23/2023 Page 5 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231020-C01	J3P3108B	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$20,913.35	\$20,913.35
		0001	0020	2079909	MISC.SIDEWALK	0.70	0.00	0.70	STA	0.70	\$5,485.71	\$3,840.00
		0001	0030	3109910	MISC.TYPE 5 AGGREGATE	62.70	0.00	62.70	TONS	0.00	\$157.90	\$0.00
		0001	0040	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	445.80	0.00	445.80	TONS	413.00	\$272.00	\$112,336.00
		0001	0050	4071005	TACK COAT	536.00	0.00	536.00	GAL	536.00	\$3.50	\$1,876.00
		0001	0060	4133100	ULTRATHIN BONDED WEARING SURFACE, TYPE B	45,251.00	0.00	45,251.00	SQYD	45,157.00	\$8.00	\$361,256.00
		0001	0070	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	57.60	0.00	57.60	SQYD	40.60	\$240.90	\$9,780.54
		0001	0800	6086004	CONCRETE SIDEWALK, 4 IN.	35.60	0.00	35.60	SQYD	35.60	\$132.50	\$4,717.00
		0001	0090	6089902	MISC.ADA RAMP	4.00	0.00	4.00	EA	4.00	\$3,545.15	\$14,180.60
		0001	0100	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.00
		0001	0110	6161005	CONSTRUCTION SIGNS	1,091.00	0.00	1,091.00	SQFT	1,091.00	\$6.00	\$6,546.00
		0001	0120	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$50.00	\$100.00
		0001	0130	6161025	CHANNELIZER (TRIM LINE)	300.00	0.00	300.00	EA	300.00	\$15.00	\$4,500.00
		0001	0140	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,100.00	\$2,200.00
		0001	0150	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0001	0160	6169902	MISC.ADA COMPLINANT MOVEABLE SIDEWALK BARRICADE	4.00	0.00	4.00	EA	4.00	\$150.00	\$600.00
		0001	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$90,000.00	\$90,000.00
		0001	0180	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	405.00	0.00	405.00	LF	286.00	\$20.00	\$5,720.00
		0001	0190	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	19.00	0.00	19.00	EA	19.00	\$300.00	\$5,700.00
		0001	0200	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	90.00	0.00	90.00	EA	90.00	\$125.00	\$11,250.00
		0001	0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	259.00	0.00	259.00	LF	259.00	\$0.30	\$77.70
		0001	0220	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,060.00	0.00	5,060.00	LF	5,060.00	\$0.25	\$1,265.00
		0001	0230	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	22,559.00	0.00	22,559.00	LF	22,559.00	\$0.25	\$5,639.75
		0001	0240	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	561.00	0.00	561.00	LF	561.00	\$6.00	\$3,366.00
		0001	0250	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	49,237.00	0.00	49,237.00	SQYD	49,061.00	\$3.30	\$161,901.30
		0001	0260	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0030	0270	9028500	CABLE, LOOP DETECTOR, IN DUCT	6,270.00	0.00	6,270.00	LF	6,270.00	\$5.25	\$32,917.50
		0030	0280	9028510	CABLE, LOOP DETECTOR, LEAD-IN	3,740.00	0.00	3,740.00	LF	3,740.00	\$1.95	\$7,293.00
		0040	0290	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	3.00	0.00	3.00	EA	3.00	\$388.00	\$1,164.00
		0040	0300	9031272A	2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	3.00	0.00	3.00	EA	3.00	\$111.00	\$333.00
		0040	0310	9031280	2.5 IN. PSST POST - 12 GA.	36.00	0.00	36.00	LF	36.00	\$26.50	\$954.00
		0040	0320	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	3.00	0.00	3.00	EA	3.00	\$273.00	\$819.00
		0040	0330	9035004A	SH-FLAT SHEET	50.00	0.00	50.00	SQFT	50.00	\$23.00	\$1,150.00
		0040	0340	9039902	MISC.SIGN RELOCATION	1.00	0.00	1.00	EA	1.00	\$200.00	\$200.00
					Date as of Report Generated Date							\$879,595.74
231020-C01 Ove	rall - Total V	alue Poste	d to Date	as of Repor	t Generated Date							\$879,595.74

Revision 3/23/2023 Page 6 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J3P3108B

Line Number	Item Code	Description		DWR Approval Date		Units	Location		Offset/ Distance		Offset/ Distance	Comments
0220	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	9/27/24	10/1/24	1,012.00	LF	Pay up to equal 100%	72.660		73.967		
0230	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	9/27/24	10/1/24	4,512.00	LF	Final payment to make it 100%	72.660		73.967		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 7 of 17



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J3P3108B	0040	BIT. PAVEMENT MIXTURE PG64-22 (BP-2)	Other Item Adjustment	ACAD	3	Jul 1, 2024	hessec2	(\$332.98)	AC Adjustment Line No. 0040 Installed Quantity =													
		. 00 . 12 (5. 2)							413 tons X 4.3% (Virgin) X -18.75 (Diff) = \$-332.98													
				ACAD - Tota				(\$332.98)														
			Other Item /	Adjustment -	Total			(\$332.98)														
		· Total			-			(\$332.98)														
	0050	TACK COAT	Material		3	Jul 1, 2024	SYSTEM	\$1,876.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					3	Jul 1, 2024	SYSTEM	(\$1,876.00)														
					4	Jul 16, 2024	SYSTEM	\$1,876.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					4	Jul 16, 2024	SYSTEM	(\$1,876.00)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
	0050 -	· Total						\$0.00														
	0060	ULTRATHIN BONDED WEARING	Material		3	Jul 1, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.													
		SURFACE, TYPE B			3	Jul 1, 2024	SYSTEM	(\$361,256.00)														
															4	Jul 16, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					4	Jul 16, 2024	SYSTEM	(\$361,256.00)														
					5	Aug 1, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					5	Aug 1, 2024	SYSTEM	(\$361,256.00)														
					6	Aug 16, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					6	Aug 16, 2024	SYSTEM	(\$361,256.00)														
					7	Sep 3, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
						7	Sep 3, 2024	SYSTEM	(\$361,256.00)													
																		8	Sep 16, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Sep 16, 2024	SYSTEM	(\$361,256.00)														
													9	Oct 1, 2024	SYSTEM	\$361,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					9	Oct 1, 2024	SYSTEM	(\$361,256.00)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
			Other Item Adjustment	ACAD	3	Jul 1, 2024	hessec2	(\$1,851.08)	AC Adjustment Line No. 0050 Installed Quantity =													
									-18.75 (diff) X 1.98 T/CY X 0.75 Thick / 36 X 45,157 Sq Yd X 5.3% (Virgin) = \$-1,851.08.													
				ACAD - Tota	al			(\$1,851.08)														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J3P3108B	0060	ULTRATHIN BONDED WEARING SURFACE, TYPE B	Other Item /	Adjustment -	Total			(\$1,851.08)														
	0060 -	Total						(\$1,851.08)														
	0070 CONCRETE PAVEMENT (8 IN. NON- REINF)	Material		2	Jun 17, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.														
				2	Jun 17, 2024	SYSTEM	(\$9,780.54)															
					3	Jul 1, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
					3	Jul 1, 2024	SYSTEM	(\$9,780.54)														
													4	Jul 16, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
									4	Jul 16, 2024	SYSTEM	(\$9,780.54)										
										5	Aug 1, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
							5	Aug 1, 2024	SYSTEM	(\$9,780.54)												
							6	Aug 16, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					6	Aug 16, 2024	SYSTEM	(\$9,780.54)														
					7	Sep 3, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
					7	Sep 3, 2024	SYSTEM	(\$9,780.54)														
					8	Sep 16, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
					8	Sep 16, 2024	SYSTEM	(\$9,780.54)														
									9	Oct 1, 2024	SYSTEM	\$9,780.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					9	Oct 1, 2024	SYSTEM	(\$9,780.54)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
	0070 -	Total						\$0.00														
	0800	CONCRETE SIDEWALK, 4 IN.	Material		2	Jun 17, 2024	SYSTEM	\$4,717.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.													
					3	3					3		2	Jun 17, 2024	SYSTEM	(\$4,717.00)						
																		3	3	Jul 1, 2024	SYSTEM	\$4,717.00
																		3	3	Jul 1, 2024	SYSTEM	(\$4,717.00)
													4	Jul 16, 2024	SYSTEM	\$4,717.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
															2	4	4					
					5	Aug 1, 2024	SYSTEM	\$4,717.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J3P3108B	0080	CONCRETE	Material						Estimate Exception 8 on the current Payment Estimate.															
		SIDEWALK, 4 IN.			5	Aug 1, 2024	SYSTEM	(\$4,717.00)																
					6	Aug 16, 2024	SYSTEM	\$4,717.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					6	Aug 16, 2024	SYSTEM	(\$4,717.00)																
					7	Sep 3, 2024	SYSTEM	\$4,717.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					7	Sep 3, 2024	SYSTEM	(\$4,717.00)																
					8	Sep 16, 2024	SYSTEM	\$4,717.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					8	Sep 16, 2024	SYSTEM	(\$4,717.00)																
					9	Oct 1, 2024	SYSTEM	\$4,717.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					9	Oct 1, 2024	SYSTEM	(\$4,717.00)																
				- Total				\$0.00																
			Material - To	otal				\$0.00																
	0080 -	Total						\$0.00																
	0090	MISC. CONCRETE	Material		2	Jun 17, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.															
								2	Jun 17, 2024	SYSTEM	(\$14,180.60)													
					3	Jul 1, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.															
					3	Jul 1, 2024	SYSTEM	(\$14,180.60)																
					4	Jul 16, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.															
					4	Jul 16, 2024	SYSTEM	(\$14,180.60)																
					5	Aug 1, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.															
					5	Aug 1, 2024	SYSTEM	(\$14,180.60)																
																				6	Aug 16, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
						6	Aug 16, 2024	SYSTEM	(\$14,180.60)															
											7	Sep 3, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
					7	Sep 3, 2024	SYSTEM	(\$14,180.60)																
			8 Sep 2024 8 Sep 2024 9 Oct			Sep 16, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.															
				Sep 16, 2024	SYSTEM	(\$14,180.60)																		
														9	Oct 1, 2024	SYSTEM	\$14,180.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
					9	Oct 1,	SYSTEM	(\$14,180.60)																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																				
3P3108B	0090	MISC.	Material			2024																							
		CONCRETE		- Total				\$0.00																					
			Material - To	otal				\$0.00																					
	0090 -	Total						\$0.00																					
	0180	PREF THERMO PVMT MARK, 24 IN WHIT	Material		4	Jul 16, 2024	SYSTEM	\$5,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.																				
		24 114 441 111			4	Jul 16, 2024	SYSTEM	(\$5,720.00)																					
				- Total				\$0.00																					
			Material - To	otal				\$0.00																					
	0180 -							\$0.00																					
	0190	PREF THERMO PVMT MARK, LT/RT ARROW	Material		4	Jul 16, 2024	SYSTEM	\$5,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.																				
					4	Jul 16, 2024	SYSTEM	(\$5,700.00)																					
				- Total				\$0.00																					
			Material - To	otal				\$0.00																					
	0190 -	Total						\$0.00																					
	0200	PREF THERMO PVMT MARK, 30" WHT	Material		4	Jul 16, 2024	SYSTEM	\$11,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.																				
		MIDBL			4	Jul 16, 2024	SYSTEM	(\$11,250.00)																					
				- Total				\$0.00																					
			Material - To	otal				\$0.00																					
	0200 -	Total																											
	0210	6 IN. WHITE HIGH BUILD WATERBORNE	BUILD ORNE		4	Jul 16, 2024	SYSTEM	\$77.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.																				
		PAINT			4	Jul 16, 2024	SYSTEM	(\$77.70)																					
					5	Aug 1, 2024	SYSTEM	\$77.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.																				
							5	Aug 1, 2024	SYSTEM	(\$77.70)																			
															6	Aug 16, 2024	SYSTEM	\$77.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.										
					6	Aug 16, 2024	SYSTEM	(\$77.70)																					
																				7	Sep 3, 2024	SYSTEM	\$77.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.					
						7	Sep 3, 2024	SYSTEM	(\$77.70)																				
																											8	Sep 16, 2024	SYSTEM
					8	Sep 16, 2024	SYSTEM	(\$77.70)																					
					9	Oct 1, 2024	SYSTEM	\$77.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.																				
					9	Oct 1, 2024	SYSTEM	(\$77.70)																					
				- Total				\$0.00																					
				Total																									
			Material - To					\$0.00																					



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J3P3108B	0220	4 IN. WHITE WATERBORNE PAVEMENT	Material		4	Jul 16, 2024	SYSTEM	\$1,012.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
		MARKING			4	Jul 16, 2024	SYSTEM	(\$1,012.00)		
					5	Aug 1, 2024	SYSTEM	\$1,012.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					5	Aug 1, 2024	SYSTEM	(\$1,012.00)		
					6	Aug 16, 2024	SYSTEM	\$1,012.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					6	Aug 16, 2024	SYSTEM	(\$1,012.00)		
					7	Sep 3, 2024	SYSTEM	\$1,012.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					7	Sep 3, 2024	SYSTEM	(\$1,012.00)		
					8	Sep 16, 2024	SYSTEM	\$1,012.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					8	Sep 16, 2024	SYSTEM	(\$1,012.00)		
					9	Oct 1, 2024	SYSTEM	\$1,265.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					9	Oct 1, 2024	SYSTEM	(\$1,265.00)		
			Matorial -T	Material - To	- Total				\$0.00	
			Material - To	otal				\$0.00		
		- Total						\$0.00		
	0230	4 IN. YELLOW WATERBORNE	Material		4	Jul 16, 2024	SYSTEM	\$4,511.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment	
		PAVEMENT							Estimate Exception 18 on the current Payment Estimate.	
					4	Jul 16, 2024	SYSTEM	(\$4,511.75)		
		PAVEMENT			5		SYSTEM	(\$4,511.75) \$4,511.75		
		PAVEMENT				2024 Aug 1,			Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment	
		PAVEMENT			5	2024 Aug 1, 2024 Aug 1,	SYSTEM	\$4,511.75	Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment	
		PAVEMENT			5	Aug 1, 2024 Aug 1, 2024 Aug 16,	SYSTEM SYSTEM	\$4,511.75 (\$4,511.75)	Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment	
		PAVEMENT			5 6	Aug 1, 2024 Aug 1, 2024 Aug 16, 2024 Aug 16,	SYSTEM SYSTEM	\$4,511.75 (\$4,511.75) \$4,511.75	Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment	
		PAVEMENT			5 5 6	Aug 1, 2024 Aug 1, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3,	SYSTEM SYSTEM SYSTEM	\$4,511.75 (\$4,511.75) \$4,511.75 (\$4,511.75)	Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment	
		PAVEMENT			5 5 6 6 7	2024 Aug 1, 2024 Aug 1, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,511.75 (\$4,511.75) \$4,511.75 (\$4,511.75) \$4,511.75	Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment	
		PAVEMENT			5 5 6 7 7	2024 Aug 1, 2024 Aug 1, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,511.75 (\$4,511.75) \$4,511.75 (\$4,511.75) \$4,511.75	Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment	
		PAVEMENT			5 5 6 7 7 8	2024 Aug 1, 2024 Aug 1, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,511.75 (\$4,511.75) \$4,511.75 (\$4,511.75) \$4,511.75 (\$4,511.75)	Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment	
		PAVEMENT			5 5 6 7 7 8	2024 Aug 1, 2024 Aug 1, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,511.75 (\$4,511.75) \$4,511.75 (\$4,511.75) \$4,511.75 (\$4,511.75) \$4,511.75	Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate.	
		PAVEMENT		- Total	5 5 6 7 7 8 8	2024 Aug 1, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 1,	SYSTEM	\$4,511.75 (\$4,511.75) \$4,511.75 (\$4,511.75) \$4,511.75 (\$4,511.75) \$4,511.75 (\$4,511.75)	Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate.	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3108B	0230 -	- Total						\$0.00	
	0240	24 IN. YELLOW WATERBORNE PAVEMENT MARKIN	Material		4	Jul 16, 2024	SYSTEM	\$3,366.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		IVIZITATIN			4	Jul 16, 2024	SYSTEM	(\$3,366.00)	
					5	Aug 1, 2024	SYSTEM	\$3,366.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					5	Aug 1, 2024	SYSTEM	(\$3,366.00)	
					6	Aug 16, 2024	SYSTEM	\$3,366.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					6	Aug 16, 2024	SYSTEM	(\$3,366.00)	
					7	Sep 3, 2024	SYSTEM	\$3,366.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Sep 3, 2024	SYSTEM	(\$3,366.00)	
					8	Sep 16, 2024	SYSTEM	\$3,366.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Sep 16, 2024	SYSTEM	(\$3,366.00)	
					9	Oct 1, 2024	SYSTEM	\$3,366.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					9	Oct 1, 2024	SYSTEM	(\$3,366.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0240 -	- Total	Material - 1	otal				\$0.00 \$0.00	
	0240 · 0270	CABLE, LOOP DETECTOR, IN DUCT	Material - 10	otal	3	Jul 1, 2024	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		CABLE, LOOP DETECTOR, IN		otal	3		SYSTEM	\$0.00	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment
		CABLE, LOOP DETECTOR, IN		otal		2024 Jul 1,		\$0.00 \$12,474.00	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment
		CABLE, LOOP DETECTOR, IN		otal	3	Jul 1, 2024 Jul 16,	SYSTEM	\$0.00 \$12,474.00 (\$12,474.00)	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment
		CABLE, LOOP DETECTOR, IN		otal	3	Jul 1, 2024 Jul 16, 2024 Jul 16,	SYSTEM SYSTEM	\$0.00 \$12,474.00 (\$12,474.00) \$32,917.50	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment
		CABLE, LOOP DETECTOR, IN		otal	3 4	Jul 16, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$12,474.00 (\$12,474.00) \$32,917.50	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment
		CABLE, LOOP DETECTOR, IN		otal	3 4 4 5	2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024 Aug 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$12,474.00 (\$12,474.00) \$32,917.50 (\$32,917.50) \$32,917.50	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment
		CABLE, LOOP DETECTOR, IN		otal	3 4 4 5	2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024 Aug 1, 2024 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$12,474.00 (\$12,474.00) \$32,917.50 (\$32,917.50) \$32,917.50	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment
		CABLE, LOOP DETECTOR, IN		otal	3 4 5 5 6	2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024 Aug 1, 2024 Aug 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$12,474.00 (\$12,474.00) \$32,917.50 (\$32,917.50) \$32,917.50 (\$32,917.50)	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment
		CABLE, LOOP DETECTOR, IN		otal	3 4 4 5 5 6 6 6	2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024 Aug 1, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$12,474.00 (\$12,474.00) \$32,917.50 (\$32,917.50) \$32,917.50 (\$32,917.50) (\$32,917.50)	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 19 on the current Payment Estimate.
		CABLE, LOOP DETECTOR, IN		otal	3 4 4 5 5 6 6 7 7	2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024 Aug 1, 2024 Aug 16, 2024 Sep 3, 2024 Sep 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$12,474.00 (\$12,474.00) \$32,917.50 (\$32,917.50) \$32,917.50 (\$32,917.50) (\$32,917.50) \$32,917.50	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 19 on the current Payment Estimate.
		CABLE, LOOP DETECTOR, IN		otal	3 4 5 5 6 6 7 7	2024 Jul 1, 2024 Jul 16, 2024 Jul 16, 2024 Aug 1, 2024 Aug 16, 2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$12,474.00 (\$12,474.00) \$32,917.50 (\$32,917.50) \$32,917.50 (\$32,917.50) \$32,917.50 (\$32,917.50) (\$32,917.50)	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 19 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J3P3108B	0270	CABLE, LOOP DETECTOR, IN	Material			2024			Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.														
		DUCT			9	Oct 1, 2024	SYSTEM	(\$32,917.50)															
				- Total				\$0.00															
			Material - To	otal				\$0.00															
	0270 -	Total						\$0.00															
	0280	CABLE, LOOP DETECTOR, LEAD-IN	Material		3	Jul 1, 2024	SYSTEM	\$3,238.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.														
					3	Jul 1, 2024	SYSTEM	(\$3,238.95)															
				4	Jul 16, 2024	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hessec2 overridding Payment Estimate Exception 24 on the current Payment Estimate.															
					4	Jul 16, 2024	SYSTEM	(\$7,293.00)															
				5	Aug 1, 2024	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.															
					5	Aug 1, 2024	SYSTEM	(\$7,293.00)															
					6	Aug 16, 2024	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
					6	Aug 16, 2024	SYSTEM	(\$7,293.00)															
					7	Sep 3, 2024	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
					7	Sep 3, 2024	SYSTEM	(\$7,293.00)															
					8	Sep 16, 2024	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
						8	Sep 16, 2024	SYSTEM	(\$7,293.00)														
					9	Oct 1, 2024	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
					9	Oct 1, 2024	SYSTEM	(\$7,293.00)															
				- Total				\$0.00															
			Material - To	otal				\$0.00															
	0280 -	Total						\$0.00															
	0290	BREAKAWAY ASSEMBLY (PERFORATED	Material		2	Jun 17, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.														
		SQUARE STEEL TUBE)				2	Jun 17, 2024	SYSTEM	(\$1,164.00)														
															3	Jul 1, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.				
												3	Jul 1, 2024	SYSTEM	(\$1,164.00)								
					4 Jul 16, 2024 (\$1,164.00)																		
			5	5	5	5	Aug 1, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
J3P3108B	0290	BREAKAWAY ASSEMBLY (PERFORATED	Material		6	Aug 16, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.																		
		SQUARE STEEL TUBE)			6	Aug 16, 2024	SYSTEM	(\$1,164.00)																			
					7	Sep 3, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.																		
					7	Sep 3, 2024	SYSTEM	(\$1,164.00)																			
					8	Sep 16, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.																		
					8	Sep 16, 2024	SYSTEM	(\$1,164.00)																			
					9	Oct 1, 2024	SYSTEM	\$1,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.																		
					9	Oct 1, 2024	SYSTEM	(\$1,164.00)																			
				- Total				\$0.00																			
			Material - To	otal				\$0.00																			
	0290 -	- Total						\$0.00																			
	0310	2.5 IN. PSST POST - 12 GA.	Material		2	Jun 17, 2024	SYSTEM	\$954.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.																		
					2	Jun 17, 2024	SYSTEM	(\$954.00)																			
					3	Jul 1, 2024	SYSTEM	\$954.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.																		
					3	Jul 1, 2024	SYSTEM	(\$954.00)																			
					4	Jul 16, 2024	SYSTEM	\$954.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hessec2 overridding Payment Estimate Exception 26 on the current Payment Estimate.																		
					4	Jul 16, 2024	SYSTEM	(\$954.00)																			
					5	Aug 1, 2024	SYSTEM	\$954.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.																		
					5	Aug 1, 2024	SYSTEM	(\$954.00)																			
					6	Aug 16, 2024	SYSTEM	\$954.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.																		
					6	Aug 16, 2024	SYSTEM	(\$954.00)																			
					7	Sep 3, 2024	SYSTEM	\$954.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.																		
					7	Sep 3, 2024	SYSTEM	(\$954.00)																			
							8	8	8	8	8 8 9	8					8	Sep 16, 2024	SYSTEM	\$954.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.						
													8	8	8	8	8	8	8				8	Sep 16, 2024	SYSTEM	(\$954.00)	
																							9	9	9	9	9
						Oct 1, 2024	SYSTEM	(\$954.00)																			
				- Total				\$0.00																			
			Material - To	otal				\$0.00																			





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3108B	0310 -	Total						\$0.00	
	0340	MISC.	Material		2	Jun 17, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					2	Jun 17, 2024	SYSTEM	(\$200.00)	
					3	Jul 1, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					3	Jul 1, 2024	SYSTEM	(\$200.00)	
					4	Jul 16, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hessec2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					4	Jul 16, 2024	SYSTEM	(\$200.00)	
					5	Aug 1, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	Aug 1, 2024	SYSTEM	(\$200.00)	
					6	Aug 16, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					6	Aug 16, 2024	SYSTEM	(\$200.00)	
					7	Sep 3, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					7	Sep 3, 2024	SYSTEM	(\$200.00)	
					8	Sep 16, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					8	Sep 16, 2024	SYSTEM	(\$200.00)	
					9	Oct 1, 2024	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					9	Oct 1, 2024	SYSTEM	(\$200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0340 -	Total						\$0.00	
J3P3108B -	- Total							(\$2,184.06)	
Overall - To	otal							(\$2,184.06)	

MoDOT

Contract Adjustments for Contract - 231020-C01

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 17 of 17